

Patrick Martino Site Vice President, Vogtle Unit 3 7825 River Road Waynesboro, Georgia 30830 706 848 6602 tel

September 6, 2023

ND-23-0696

10 CFR 50.73(a)(2)(iv)(A)

Docket No.: 52-025

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

Southern Nuclear Operating Company <u>Vogtle Electric Generating Plant (VEGP) – Unit 3</u> <u>Licensee Event Report 2023-005-00</u> <u>Automatic Reactor Protection System Actuation During Startup Testing Due to Inadequate</u> <u>Turbine Trip Logic</u>

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company is submitting the enclosed Licensee Event Report for VEGP Unit 3.

This letter contains no regulatory commitments. If you have questions regarding the enclosed information, please contact Will Garrett at (706) 848-7154.

Respectfully submitted,

Patrick A. Martino Site Vice President, Unit 3

PAM/NBC/sfr

Enclosure:

Unit 3 Licensee Event Report 2023-005-00

cc: Regional Administrator, Region II VPO Project Manager Senior Resident Inspector – Vogtle 3 & 4

Vogtle Electric Generating Plant - Unit 3

<u>Licensee Event Report 2023-005-00 - Automatic Reactor Protection System</u> <u>Actuation During Startup Testing Due to Inadequate Turbine Trip Logic</u>

Enclosure

Unit 3 Licensee Event Report 2023-005-00

(This enclosure consists of 3 pages, including this cover page)

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION							APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2023										
(03-14-2023) LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: <u>oira submission@orb.eop.gov</u> . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.									
1. Facility Name									050 2. Docket Number				3. Page				
Vogtle Electric Generating Plant, Unit 3								■ 052 00025				1 OF 2					
Automatic Reactor Protection System Actuation During Startup Testing Due to Inadequate Turbine Trip Logic																	
5. Event Date 6. LER Number 7. Report Date							8. Other Facilities Involved										
Month D	onth Day Year		Year	ear Sequential Number		sion D. Monti	¹ Month Day		Year	Facility Name			050			t Number	
07 0)9	2023	2023	- 005	- 00	0 09	06		2023	Facility Na	Facility Name			Docket Number			
9. Operating Mode 10. Power Level 045																	
I 11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: <i>(Check all that apply)</i>																	
10 CFR	Part 2	0	20.2	203(a)(2)(vi)	1	0 CFR Pa	art 50		50.73	s(a)(2)(ii)(A)	50.73(a)	(2)(viii)(A)		73.	1200(a)	
20.2201(b) 20.2203(a)(3)			203(a)(3)(i)) 50.36(c)(1)(i)(A)				50.73(a)(2)(ii)(B)			50.73(a)		73.	1200(b)			
20.2201(d) 20.2203(a)(3)(ii)				50.36(c)(1)(ii)(A)			50.73(a)(2)(iii)			50.73(a)] 73. [.]	1200(c)				
20,2203(a)(1)			20.2203(a)(4)			50.36(c)(2)			50.73(a)(2)(iv)(A)			50.73(a)	╞] 73. ⁻	1200(d)		
20,2203(a)(2)(i) 10				R Part 21	Part 21 50.46(a)(3)(ii)				50.73(a)(2)(v)(A)			10 CFR I] 73 .	1200(e)		
20.2203(a)(2)(i)			21.2(c)			50.69(a)			50.73(a)(2)(v)(B)			73.77(a)		73.	1200(f)		
20.2203(a)(2)(iii)						50.73(a)(2)(i)(A)			50.73(a)(2)(v)(C)			73.77(a)	╞	73.	1200(g)		
20.2203(a)(2)(iv)						50.73(a)(2)(i)(B)			50.73(a)(2)(v)(D)			73.77(a)(2)(ii)					
20.2203	B(a)(2)(v	/)				50.73(a)(2)(i)(C)			50.73(a)(2)(vii)								
OTHER (Specify here, in abstract, or NRC 366A).																	
	26 (1997) 					12. Licen	see Cont	act fo	r this L	ER							
Licensee Cont	act		41:0000	ng Mana									Phone Nu	nber (l 7068/	nclude 1871 <i>5</i>	area code)	
Will Garret	I. VEG	JP 304	+ Licens	13 Comple	ier ite One I	ine for eac	h Compo	nent l	Failure	Describer	d in fl	his Renort		000		~	
Cause System Component Manu			facturer	cturer Reportable to IRIS				Svet	System Compose		t Manufacture		er Reportable to IPIS				
Juuse	398								~~30	Jyst					. shoi		
	I	14.	Suppleme	ental Report I	Expected							1	Month		Day	Year	
No Yes (If ves. complete 15. Expected Submission Date)							\neg	15. Expected Submission Date									
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)																	
On July 9, 2023, at 1328 EDT with Vogtle Electric Generating Plant (VEGP) Unit 3 in Mode 1 at 45 percent power, the Reactor Protection System (RPS) automatically actuated during the 100 percent load rejection startup test activities. The operators responded timely by ensuring plant stability, with decay heat removal accomplished by steam generator power operated relief valves. The cause of the event was a turbine trip due to an erroneous high-level indication in a Moisture Separator Reheater (MSR) resulting from the steam pressure change that occurred following the planned load rejection. The corrective action for this event modified logic to prevent a turbine trip during the anticipated steam pressure change following a load rejection event, by accounting for erroneous high-2 MSR level indications during this condition. This event is reportable under 10 CFR 50.73(a)(2)(iv)(A) as an automatic actuation of the RPS. VEGP Units 1, 2, and 4 were unaffected by this event.																	

NRC FORM 366A U.S. NUCLEAR REGULATORY CO	MMISSION	APPROVED BY OMB:	NO. 3	3150-010)4	EXPIRES	3: O	8/31/2023				
(03-14-2023) LICENSEE EVENT REPORT (L CONTINUATION SHEET (See NUREG-1022, R.3 for instruction and guidance for completing http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr10	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: oira submission@omb.eep.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.											
	2. DOCKET NUMBER 3. LER NUMBER											
Vogtle Electric Generating Plant, Unit 3	050 052	00025		YEAR		SEQUENTIAL NUMBER		REV NO.				
				2023	-	005	-	00				
NARRATIVE					<u> </u>							
EVENT DESCRIPTION On July 9, 2023, at 1328 EDT with Vogtle Electric Generating Plant (VEGP) Unit 3 in Mode 1 at 45 percent power, the Reactor Protection System (RPS) [EIIS: JC] automatically actuated during the 100 percent load rejection test activities. The initiating event was a main turbine [EIIS: TA / TRB] trip due to a high-level indication in Moisture Separator Reheater (MSR) B [EIIS: SB / MSR]. During the performance of the 100 percent load rejection startup test, the turbine was in a Power/Load Unbalance condition. In this condition and as designed, the intercept valves (IVs) [EIIS: TA / V] initially fully closed to prevent turbine overspeed. The IVs cycled open and closed, by design, to control turbine speed based on lowering demand and to allow recovery from the load rejection by blowing down the reheated steam. As the IVs cycled, the pressure in the MSR shell decreased. Moisture removed from the high-pressure turbine exhaust via the MSR accumulated in the MSR Shell Drain Tank [EIIS: SN / TK] and prevented the MSR Shell Drain Tank pressure from correlating with pressure changes in the MSR shell. The differential pressure transmitters [EIIS: SB / PDT] that provide the MSR level indication responded to these pressure changes, resulting in an erroneous level indication that ultimately exceeded the high-2 setpoint, which led to the turbine trip. The turbine trip deenergized the Unit Auxiliary Transformers (UATs) [EIIS: EA / XFMR] which were powering the reactor coolant pumps [EIIS: AB / P], resulting in the reactor trip on low coolant flow. There were no structures, systems, or components that were inoperable at the beginning of the event that contributed to the event. This event is reportable under 10 CFR 50.73(a)(2)(iv)(A) as a condition that resulted in automatic actuation of the RPS. EVENT ANALYSIS												
The cause of this event was an inadequate turbine trip logic. The MSR pressure change conditions that occurred following the 100 percent load rejection test activities adversely impacted the differential pressure level instrument reading. The turbine trip logic did not account for these pressure change conditions. The turbine trip logic was modified to account for erroneous high MSR level indications while in the load rejection condition.												
SAFETY ASSESSMENT												
There were no safety consequences due to this event because the automatic actuation function of the RPS maintained the plant in a safe condition. The operators responded timely by ensuring plant stability and decay heat was removed by steam generator power operated relief valves [EIIS: SB / PCV]. All safety systems functioned as expected as a result of the event. VEGP Units 1, 2, and 4 were unaffected by this event.												
CORRECTIVE ACTION												
The turbine trip logic was modified by a software desig during load rejection conditions.	n change	to account for errone	eous ł	high-2	MS	R level indica	atio	าร				
PREVIOUS SIMILAR EVENTS												
None												