NRC FORM 591M (04-2022)



## U.S. NUCLEAR REGULATORY COMMISSION

## **Materials Inspection Report**

, a	****	Wateria	is inspection repor	•	
Licensee/Location Inspected:			2. NRC/Regional Office		
Kansas City Testing & Engineering, LLC 1141 Southwest Boulevard, Kansas City, KS 66103 and a Temporary Job Site at 101 Street NE and N Lister Avenue, Kansas City, MO			Region IV U. S. Nuclear Regulatory Commission 1600 E. Lamar Boulevard Arlington, TX 76011-4511		
Report Number(s) 2 3. Docket Number(s)		4. License Nu	ımbar(s)	I	5. Date(s) of Inspection
030-38242		15-29383-			3/12/2024
030-30242		10-2000-	0/12/2024		J/ 12/2024
Nuclear Regulatory	an examination of the activities or Commission (NRC) rules and regocedures and representative recor	ulations and t	he conditions of your license.	. The inspect	tion consisted of selective
1. Based o	on the inspection findings, no viola	tions were ide	ntified.		
2. Previous violation(s) closed.					
	this inspection, certain of your acti ssessed at Severity Level IV, in ac				ation of NRC requirements, and
identifi were s (Non-c 10 CFR protectio annually audit in correcte  B. The fol which (Violati 1.) 10 CF comp	plation(s), specifically described to ed, non-repetitive, corrective actionatisfied. Sited violation(s) was/were discussived violation(s) requires that the on program content and imply review the radiation protect June 2021, but didn't performed, the licensee established relowing violation(s) is/are being citemay be subject to posting in accordinations and Corrective Actions) FR 71.5(a) requires, in part, oly with the applicable requires 390 through 397, appropriational sites of the control of th	ed involving the licensee sleementation program an audit areminders to dance with 10 that a licenterements of the state of	ing taken, and the remaining taken, and the remaining the following requirement(s) and periodically (at least and contrary to this, the licent content and implement again until March 2023. To review the radiation process with NRC Enforcement Process 19.11.  See who transports licent the DOT regulations in 4	t annually) censee fail ntation. Th This issue totection p olicy. This fo	review the radiation ed to periodically (at least ne licensee conducted an was self-identified and self-rogram at least annually.  rm is a NOTICE OF VIOLATION,
49 C	FR 172.704(c)(2) requires, i	n part, that	a hazmat employee mu	ıst receive	recurrent training required
	1		f Corrective Actions		
actions is made in a	thin 30 days, the actions described by ccordance with the requirements of 1 hieved). I understand that no further w	0 CFR 2.201 (	corrective steps already taken,	corrective ste	ps which will be taken, date when fu
TITLE	PRINTED NAME			SIGNATURE	AND DATE
LICENSEE'S REPRESENTATIVE	Andrew Wilson, RSO		andwe B 1	Most	6/14/2024
NRC INSPECTOR	J. Dykert for D. Fiedorek and	Z. Sulaiman	JASON DYKERT	کے	Digitally signed by JASON DYKERT Date: 2024.06.14 09:18:33 -07'00'
BRANCH CHIEF	Lizette Roldán-Otero, PhD Ja	anine F. Kata	nic, PhD, CHP for	ANINE	Digitally signed by JANINE KATANIC
	_			ATANIC	Date: 2024 07 15

## **Materials Inspection Report (Continued)**

## (continued)

Contrary to the above, from May 5, 2022 through February 28, 2024, the licensee failed to ensure that two hazmat employees received recurrent training required by Subpart H to 49 CFR Part 172 at least once every three years. Specifically, two gauge users transported licensed material on public highways without having recurrent hazmat training: one user's hazmat refresher training expired on May 5, 2022, but they transported licensed material on public highways between November 28, 2023 and December 13, 2023; the second user's hazmat refresher training expired on February 24, 2024, but they licensed material on public highways on February 28, 2024. The licensee immediately provided recurrent hazmat training to the two individuals, and planned to provide recurrent hazmat training annually in-house and creating a computer program that will alert the RSO before additional training is required.

2.) License Condition 19 B of License Number 15-29383-01, Amendment 2, requires, in part, the licensee to conduct its program in accordance with the procedures contained in the license application dated April 30, 2020.

The licensee's Operating, Emergency, and Security Procedures submitted as part of the license application requires, in part, that portable nuclear gauges be signed out in a logbook at the storage location before being removed from the licensee's facility and taken to a temporary job site.

Contrary to the above, on on February 12, 2024, the licensee failed to conduct its program in accordance with the procedures contained in the license application dated April 30, 2020. Specifically, the licensee did not sign out a Troxler 3440P gauge in the logbook at the storage location before it was taken to a temporary job site. The licensee provided updated training to employees to fill out the utilization log, and re-posted a new paper log at the storage location.

NRC FORM 591M (04-2022)

 From:
 Jason Dykert

 To:
 Andrew Wilson

 Cc:
 Earlon Shirley

Subject: NRC Inspection Report 2024-001

Date: Wednesday, June 5, 2024 11:10:00 AM

Attachments: IR 030-38242-2024-001; KC Testing and Engineering; 591M, printed.pdf

Good afternoon Mr. Wilson,

As we discussed during the exit meeting today, two cited violations and one non-cited violation are documented in the attached report. Please review the corrective actions to ensure the violations do not recur, and sign and date the report and email it back to me.

After my branch chief signs the report, it will be a publicly available safety record available for review in the NRC's Agencywide Documents Access and Management System (ADAMS) online database.

Respectfully,

Jason Dykert Health Physicist Materials Inspection U.S. NRC - Region IV Phone: 817-200-1427