NRC FORM 592M			U.S. N	UCLEAR REGULATORY COMMISSION	
Materials Inspection Record					
1. Licensee Name: 2. Do		Docket Number(s):		3. License Number(s)	
University of Evansville 030		030-00707, 070-01045		13-09810-01, SNM-995	
4. Report Number(s):		5. Date(s) of Inspection:			
2023-001		12/13/23; in-office review through 07/11/24; exit 07/18/24			
6. Inspector(s):		7. Program Code(s): 8. Priority: 9. Inspection G		9. Inspection Guidance Used:	
Ryan Craffey		03620, 22120	5	IP 87140, 87141	
10. Licensee Contact Name(s): 11. L	Licensee E-mail Address:		12. Licensee	Telephone Number(s):	
John Stamm, PhD - RSO js3 Mark Davis, PhD - Future RSO md	84@evansville.ed I7@evansville.edu	812-488-2671 812-488-6423		-2671 -6423	
13. Inspection Type: Initial 14. Locations Inspected: Hybrid 15. Next Inspection Date (MM/DD/YYYY):					
✓ Routine ☐ Announced ✓ Main	n Office	d Office 12/13	12/13/2028 Vormal Extended		
Non-Routine 🖌 Unannounced 🗌 Temp	porary Job Site Ren	note		Reduced No change	
The University of Evansville, a private university in Evansville, Indiana, was authorized by NRC License No. 13-09810-01 and SNM-995 to use sealed sources of byproduct material and special nuclear material, respectively, for laboratory experiments and student instruction. At the time of the inspection, one AU (the RSO) used these sources every spring for a laboratory class in the Physics Department. The University also possessed a variety of historical check and reference sources and a Ni-63 ECD in secure storage, all pending disposal.					
The inspector toured the Koch Center for Engineering and Science in Evansville. All areas were adequately posted, as confirmed by independent surveys, and all licensed material was adequately secured. The inspector discussed the use of licensed material with the AU and observed demonstrations of leak test collection and analysis, performed annually prior to use (the material remained in secure storage otherwise). The inspector also reviewed a selection of records including leak test results and physical inventory records.					
While reviewing the licensee's inventiable with the words "radium," "Rate Po-210). During the period of in-office the inspector confirmed that the licer microcuries of Pb-210, Bi-210 and P containing 2-3 mg each of radium-22 previously been authorized on the U CFR 30.3(a) and 30.3(c)(2), respectite to the definition of byproduct material were met, the NRC exercised discretions of the second	tory of sources, th a-226," or "RaDEF" ce review, the licen nsee possessed a 20-210 in a berylliu 26. These represen Iniversity's byprodu ively. Since the RS al in 2005, and the stion not to cite the	e inspector found seve " (the historical name g nsee accounted for all h neutron reference sou m matrix, as well as tw nted non-exempt quan uct material license. Th SO was unaware that d other criteria in Enforc violation of 10 CFR 30	ral small s iven to a nistorical s rce nomin o survey tities of by is was no iscrete so ement Ma 0.3(c)(2).	sources from the 1960's to be mixture of Pb-210, Bi-210, and sources in its possession, and hally containing 100 meter check sources vproduct material, but had not ted as a SLIV violation of 10 purces of Ra-226 were added anual (Part II Section 3.9.2.A)	
The root cause of both violations was a lack of full understanding of licensing requirements. The use of historical names for Pb-210, Bi-210, and Po-210 was noted as a contributing factor to the violation of 10 CFR 30.3(a)					

Materials Inspection Record (Continued)

As corrective action, on April 5, 2024, the University submitted a request to add the previously unauthorized sources to its byproduct material license. Region III MLB approved the request on June 27, 2024 with the issuance of Amendment No. 22. A written response to the report will nevertheless be required to confirm the licensee's (specifically - the future RSO's) understanding that these sources are subject to all conditions of the byproduct materials license, including periodic leak tests and physical inventories.

During the previous routine inspection in 2018, the licensee was issued two SLIV violations for failing to perform leak tests and physical inventories as required by Conditions 12.D and 16 of its byproduct material license, respectively. The inspector reviewed the licensee's corrective actions and confirmed that it had performed physical inventories every six months since then, and although the ECD in storage (the subject of the LC 12.D violation) was not required to be leak tested again until 2028, the licensee was still aware of the requirement and still planned to test it then or prior to disposal, whichever came first. As such, the NRC considers both violations closed.

Signature and Date - Branch Chief

Digitally signed by RHEX EDWARDS Date: 2024.08.01 17:48:41 -05'00'