

## **Pre-Submittal Presentation - 1R25 PZR Nozzle RCV208 One-Cycle Justification - Relief Request 76**

April 22, 2025



# Agenda

- Introduction
- Background
  - Equipment Location
  - Flaw Identification
  - Design History
- ASME Section XI Code Requirements
- Proposed Alternative Pursuant to 10 CFR 50.55a(z)(1)
  - Flaw Removal and Evaluation
  - Welding
  - Basis for Alternatives
  - Duration of Proposed Alternative
  - Precedents
- Schedule
- Questions



## **Background - Equipment Location**







Original Nozzle  $\rightarrow$  Alloy 600 & Weld  $\rightarrow$  Alloy 82/182





Post-1987: Nozzle  $\rightarrow$  Alloy 600 & Weld  $\rightarrow$  Alloy 82/182







Post-1992: Nozzle  $\rightarrow$  Alloy 690 & Weld  $\rightarrow$  Alloy 82





7

## Background – Welding Issues

- During the installation of RC-1911, PZR Nozzle RCL023/RCV208 encountered weldability issues between the corrosion sleeve and the vessel wall.
- Water was detected during a PT exam, as the oil-based PT materials were unable to penetrate between the corrosion sleeve and the V208 nozzle bore.
- Visual examination of the corrosion sleeve attachment to the original Jgroove weld was conducted as part of weld troubleshooting issues.





## **Background – Flaw Identification**





Linear indication in corrosion sleeve to Pressurizer Bore seal weld. Estimated length based on nozzle and local geometry is approximately 0.5 - 0.75 inch in length.

The visual examination detected indications in the autogenous (seal) weld.



# **Code Requirements**

### ASME Code, Section XI, 2013 Edition

# IWA-4412 states "Defect removal shall be accomplished in accordance with the requirements of IWA-4420."

While seal weld is not pressure retaining, and no leakage present from RCS, relief requested due to age related flaws in the autogenous/original J-groove weld attached to the pressurizer shell

## **Flaw Removal**

Flaw removal required per IWA-4412/4420



# **Code Requirements**

#### ASME Code, Section XI, 2013 Edition

#### **Flaw Evaluation**

- IWB-3142.1(b) states "A component whose visual examination detects the relevant conditions described in the standards of Table IWB-3410-1 shall be unacceptable for continued service, unless such components..." are accepted by supplemental evaluation, accepted by corrective measures, or accepted by analytical evaluation.
- IWB-3420 states, "Each detected flaw or group of flaws shall be characterized by the rules of IWA-3300 to establish the dimensions of the flaws."
- IWA-3300 states, "Flaws detected by... inservice examinations shall be sized..."
- IWB-2420(b) states, "If a component is accepted for continued service in accordance with IWB-3132.3 or IWB-3142.4, the areas containing flaws or relevant conditions shall be reexamined during the next three inspection periods..."



# Proposed Alternative Pursuant to 10 CFR 50.55a(z)(1)

## Flaw Removal and Flaw Evaluation

- As an alternative to flaw removal to meet the applicable acceptance standards per IWA-4412/4420, flaws in the original internal J-groove weld/autogenous weld will remain in place
- As an alternative to performing the nondestructive examination (NDE) required to characterize a flaw under IWB-3420, analyze a maximum postulated flaw that bounds the range of flaw sizes that could exist in the original internal J-groove weld



## **Proposed Alternative Pursuant to 10 CFR** 50.55a(z)(1)

### Welding

- In lieu of NB-4620 post weld heat treatment requirements, install Alloy 52M welded pad in accordance with ASME Case N-638-10, ambient temperature gas tungsten arc weld (GTAW) temper bead technique.
- An alternative is proposed to N-638-10, Paragraph 4(a)(2), that requires the first three tempering layers are in place for 48-hour prior to performing NDE.
- APS proposes to perform the NDE after welding is complete versus 48 hours after the third tempering layer is complete.



# Proposed Alternative Pursuant to 10 CFR 50.55a(z)(1)

## **Basis for Alternatives**

- A review of previous analyses has been performed and confirmed that the As Left J-Groove Weld Analysis is acceptable for at least one operating cycle
- White paper supporting elimination of 48-hour hold in Code Case N-888-1
- Loose Parts analysis
- Corrosion analysis



## **Proposed Alternative Pursuant to 10 CFR** 50.55a(z)(1)

## **Duration of Proposed Alternative**

- Relief is requested for the duration of the Unit 1 Cycle 26 which concludes Fall 2026
- Separate relief request to be submitted for continued use of the nozzle for the life of the plant prior to the end of the cycle



## **Proposed Alternative Pursuant to 10 CFR** 50.55a(z)(1)

#### Precedents

- NRC approval via verbal authorization on November 6, 2020 (ML20314A028) for Peach Bottom Atomic Power Station, Unit 2. Safety Evaluation April 23, 2021 (ML21110A680)
- NRC verbal authorization on April 15, 2012, for Quad Cities, Unit 2 (ML12107A472). Safety Evaluation January 30, 2013 (ML13016A454)
- NRC approval via a verbal authorization on May 17, 2017, for Limerick, Unit 2 (ML17137A307). Safety Evaluation August 14, 2017 (ML17208A090)
- NRC verbal authorization on May 9, 2023 (ML23129A312) for Beaver Valley, Unit 2 (ML23118A381) and Letter from David Gudger (Constellation Energy Generation) to NRC dated March 24, 2023, ADAMS Accession No. ML23083B991
- PVGS Relief Request 70 verbal authorization (ML23303A011) and written authorization (ML24197A199) for 1 refueling cycle repair approval (U1 TE-101)
- PVGS Relief Request 73 verbal authorization (ML25104A042) for an additional refueling cycle (U1 TE-101)



## Schedule

- Proposed submittal date for RR-76
  - April 23, 2025
- Requested verbal authorization date
  - April 27, 2025
- Proposed submittal date for final one-cycle flaw analytical evaluation
  - 14-days after the end of the Unit 1 outage



