



Post Office Box 2000, Decatur, Alabama 35609-2000

July 14, 2025

10 CFR 50.73

ATTN: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555-0001

Browns Ferry Nuclear Plant, Unit 2  
Renewed Facility Operating License No. DPR-52  
NRC Docket No. 50-260

Subject: **Licensee Event Report 50-260/2025-002-00**

The enclosed Licensee Event Report provides details of the inoperability of the BFN Unit 2 Residual Heat Removal Suppression Pool Spray system for a period of time exceeding three years. The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B), as any operation or condition which was prohibited by the plant's Technical Specifications, and 10 CFR 50.73(a)(2)(v)(D), as any event or condition which could have prevented the fulfillment of the safety function of a system that is needed to mitigate the consequences of an accident.

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact David J. Renn, Nuclear Site Compliance Manager, at (256) 729-2636.

Respectfully,

A handwritten signature in black ink, appearing to read "DLAK", is written over a horizontal line.

Daniel A. Komm  
Site Vice President

Enclosure: Licensee Event Report 50-260/2025-002-00 – Residual Heat Removal  
Suppression Pool Spray Inoperable due to Missing U-bolt.

cc (w/ Enclosure):

NRC Regional Administrator - Region II  
NRC Senior Resident Inspector - Browns Ferry Nuclear Plant  
NRC Project Manager - Browns Ferry Nuclear Plant


**ENCLOSURE**

**Browns Ferry Nuclear Plant  
Unit 2**

**Licensee Event Report 50-260/2025-002-00**

---

**Residual Heat Removal Suppression Pool Spray Inoperable due to Missing U-bolt.  
See Enclosed**

NRC FORM 366 (04-02-2024)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 04/30/2027						
		<b>LICENSEE EVENT REPORT (LER)</b> (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form <a href="http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/">http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/</a> )										
1. Facility Name Browns Ferry Nuclear Plant (BFN), Unit 2				<input checked="" type="checkbox"/> 050 <input type="checkbox"/> 052		52. Docket Number 00260		3. Page 1 OF 6				
4. Title Residual Heat Removal Suppression Pool Spray Inoperable Due to Missing U-bolt												
5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved			
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	Docket Number		
05	16	2025	2025	- 002 -	00	07	14	2025	N/A	05000XXX		
										Facility Name	Docket Number	
										N/A	05000XXX	
9. Operating Mode 5						10. Power Level 0						
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)												
10 CFR Part 20		<input type="checkbox"/> 20.2203(a)(2)(vi)		10 CFR Part 50		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)		<input type="checkbox"/> 73.1200(a)		
<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)		<input type="checkbox"/> 73.1200(b)		
<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)		<input type="checkbox"/> 73.1200(c)		
<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.36(c)(2)		<input type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)		<input type="checkbox"/> 73.1200(d)		
<input type="checkbox"/> 20.2203(a)(2)(i)		10 CFR Part 21		<input type="checkbox"/> 50.46(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(v)(A)		10 CFR Part 73		<input type="checkbox"/> 73.1200(e)		
<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 21.21(c)		<input type="checkbox"/> 50.69(g)		<input type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.77(a)(1)		<input type="checkbox"/> 73.1200(f)		
<input type="checkbox"/> 20.2203(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> 73.77(a)(2)(i)		<input type="checkbox"/> 73.1200(g)		
<input type="checkbox"/> 20.2203(a)(2)(iv)				<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)		<input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)		<input type="checkbox"/> 73.77(a)(2)(ii)		<input type="checkbox"/> 73.1200(h)		
<input type="checkbox"/> 20.2203(a)(2)(v)				<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> 50.73(a)(2)(vii)						
<input type="checkbox"/> OTHER (Specify here, in abstract, or NRC 366A).												
12. Licensee Contact for this LER												
Licensee Contact Baruch Calkin, Compliance Engineer								Phone Number (Include area code) 256-278-1031				
13. Complete One Line for each Component Failure Described in this Report												
Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS			
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
4. Supplemental Report Expected)					15. Expected Submission Date					Month	Day	Year
<input checked="" type="checkbox"/> No										N/A	N/A	N/A
<input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date												
16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)												
<p>On March 20, 2025, at 0901 CDT, it was discovered that support 2-H-343 was missing a u-bolt, resulting in a lack of load on the support. This condition could have prevented the Unit 2 Residual Heat Removal (RHR) Loop I Suppression Pool Spray (SPS) valve from opening or closing, and resulted in the inoperability of the Unit 2 RHR Loop I SPS. On May 16, 2025, a Past Operability Evaluation determined that this condition had most likely existed for at least three years prior to discovery.</p> <p>The most likely cause of the event was a human performance error that was committed while performing maintenance on the Loop I SPS valve 2-FCV-074-0058 or its motor operator 2-MVOP-074-0058. Corrective actions for this event include re-installation of the missing u-bolt, and performance of a Notice of Indication evaluation on the support.</p>												

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: [oira\\_submission@omb.eop.gov](mailto:oira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>  Browns Ferry Nuclear Plant, Unit 2	<input checked="" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b>  00260	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2025	<b>SEQUENTIAL NUMBER</b> - 002	<b>REV NO.</b> - 00

**NARRATIVE****I. Plant Operating Conditions before the Event**

At the time of discovery, BFN Unit 2 was in Mode 5 at approximately 0 percent power.

**II. Description of Event****A. Event Summary**

On March 20, 2025, it was discovered that support 2-H-343 [SNB] was missing a u-bolt, resulting in a lack of load on the support. This condition could have prevented the Unit 2 Residual Heat Removal (RHR)[BO] system Loop I Suppression Pool Spray (SPS)[BT] valve [FCV] from opening or closing, and resulted in the inoperability of the Unit 2 RHR Loop I SPS. On May 16, 2025, a Past Operability Evaluation (POE) determined that this condition had most likely existed for at least three years prior to discovery.

The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(i)(B), as a condition that was prohibited by the plant's Technical Specifications (TS), and 10 CFR 50.73(a)(2)(v)(D), as any event or condition which could have prevented the fulfillment of the safety function of a system that is needed to mitigate the consequences of an accident.

**B. Status of structures, components, or systems (SSCs) that were inoperable at the start of the event and that contributed to the event**

There were no SSCs whose inoperability contributed to this event.

**C. Dates and approximate times of occurrences**

<u>DATE AND APPROXIMATE TIMES</u>	<u>OCCURRENCE</u>
March 20, 2025	Missing u-bolt discovered by Inservice Inspection (ISI) examiner.
March 24, 2025 1655 CDT	Work complete to install missing u-bolt under Work Order (WO) 125207651.
May 16, 2025	A POE determined that the Unit 2 RHR Loop I SPS had been inoperable for longer than its TS allowed outage time.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: [oira\\_submission@omb.eop.gov](mailto:oira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>  Browns Ferry Nuclear Plant, Unit 2	<input checked="" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b>  00260	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2025	<b>SEQUENTIAL NUMBER</b> - 002	<b>REV NO.</b> - 00

**NARRATIVE****D. Manufacturer and model number of each component that failed during the event**

No components failed during this event.

**E. Other systems or secondary functions affected**

No other systems or secondary functions were affected.

**F. Method of discovery of each component or system failure or procedural error**

During an ISI VT-3 examination of Support 2-H-343-IE, the examiner identified that the support was missing a u-bolt.

**G. The failure mode, mechanism, and effect of each failed component**

No components failed during this event.

**H. Operator actions**

There were no operator actions associated with this event.

**I. Automatically and manually initiated safety system responses**

There were no automatic or manual safety system responses associated with this event.

**III. Cause of the event**

The direct cause of the event was a u-bolt that was missing from Support 2-H-343-IE.

**A. Cause of each component or system failure or personnel error**

The most likely cause of the event was a human performance error that was committed on March 24, 2019, while performing maintenance on the Loop I SPS valve 2-FCV-074-0058 or its motor operator [MO] 2-MVOP-074-0058. Both scopes of work would have required removal of the u-bolt from the associated support to enable performance of maintenance.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: [oira\\_submission@omb.eop.gov](mailto:oira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>  Browns Ferry Nuclear Plant, Unit 2	<input checked="" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b>  00260	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2025	<b>SEQUENTIAL NUMBER</b> - 002	<b>REV NO.</b> - 00

**NARRATIVE****B. Cause(s) and circumstances for each human performance related root cause**

A review of work orders determined that both site maintenance personnel and vendors had work orders to remove the u-bolt. However, an in-depth review of WOs 118592493 and 119860080 determined that the configuration control forms were not filled out documenting the removal and reinstallation of the u-bolt.

**IV. Analysis of the event**

The safety function of the RHR SPS is to mitigate potential bypass leakage paths and maintain the primary containment peak pressure below the design limits in the event of a design basis accident. The three-year period where the Unit 2 RHR Loop I SPS was considered inoperable included several windows where the Unit 2 RHR Loop II SPS was concurrently inoperable. During this time, the SPS would have been incapable of performing its safety function to maintain the primary containment peak pressure below the design limits.

BFN, Unit 2 TS Limiting Condition for Operation (LCO) 3.6.2.4, RHR Suppression Pool Spray, requires that four RHR SPS subsystems shall be operable. TS LCO 3.6.2.4 Condition B requires, with two RHR SPS subsystems inoperable, that one RHR SPS subsystem be restored to OPERABLE status within seven days or in accordance with the Risk Informed Completion Time (RICT) Program, albeit the RICT Program was not implemented at BFN until May 2, 2023. A POE determined that this condition is likely to have existed prior to March 2022, which exceeded the 3.6.2.4.B.1 required completion time.

Additionally, TS LCO 3.8.1 Condition B requires, with one required Unit 1 and 2 Diesel Generator (DG)[DG] inoperable, that required feature(s) supported by the inoperable Unit 1 and 2 DG be declared inoperable when the redundant required feature(s) are inoperable. Therefore, the RHR B or D suppression pool spray loops would have been required by TS 3.8.1 to be declared inoperable any time the C or D DGs were inoperable for greater than 4 hours, which occurred on multiple occasions between March 2022 and the time of this event.

Finally, TS LCO 3.0.4 states that when an LCO is not met, entry into a Mode or other specified condition in the Applicability shall only be made when the associated actions to be entered permit continued operation in the Mode or other specified condition in the Applicability for an unlimited period of time. On March 21, 2023, BFN, Unit 2 entered a TS 3.6.2.4 Applicable Mode when TS 3.6.2.4 Required Actions were not met.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: [oira\\_submission@omb.eop.gov](mailto:oira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>  Browns Ferry Nuclear Plant, Unit 2	<input checked="checked" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b>  00260	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2025	<b>SEQUENTIAL NUMBER</b> - 002	<b>REV NO.</b> - 00

**NARRATIVE****V. Assessment of Safety Consequences**

The Unit 2 RHR Loop I SPS valve is normally closed. Lack of an installed u-bolt could result in the inability to open or close the valve. The valve disc could potentially have been in any position (open/mid position/closed). The desired position in the Probabilistic Risk Analysis (PRA) model is for this valve to remain closed to prevent a possible flow diversion during core cooling operations, where it could slowly deplete the Reactor Pressure Vessel inventory. However, the Loop I SPS isolation valve [ISV] 2-FCV-074-0057 is also a normally closed valve in the same flow path of the possible flow diversion. This event did not impact 2-FCV-074-0057. According to TVA Calculation NDN-000-074-2007-0025 R6, "Flow diversions due to multiple valve failures are generally considered too low of a probability to be considered (in the PRA model)." The increase in core damage frequency or large early release frequency due to this potential flow diversion is considered negligible.

This valve is also required to open for the SPS function, but the SPS flowrate is only 5 percent of the drywell spray flowrate and is considered too small to be used for containment pressure control during a core-damage event. Therefore, SPS is not credited for any sequence in the PRA model. Based on the above, TVA has concluded that sufficient systems were available to provide the required safety functions needed to protect the health and safety of the public.

**A. Availability of systems or components that could have performed the same function as the components and systems that failed during the event**

The three-year period where the Unit 2 RHR Loop I SPS was considered inoperable included several windows where the Unit 2 RHR Loop II SPS was concurrently inoperable.

**B. For events that occurred when the reactor was shut down, availability of systems or components needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident**

This event did not affect the operability of any other Unit 2 RHR subsystem. During the event, the RHR system was available to remove residual heat while the reactor was shut down.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: [oira\\_submission@omb.eop.gov](mailto:oira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>  Browns Ferry Nuclear Plant, Unit 2	<input checked="" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b>  00260	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2025	<b>SEQUENTIAL NUMBER</b> - 002	<b>REV NO.</b> - 00

**NARRATIVE****C. For failure that rendered a train of a safety system inoperable, estimate of the elapsed time from discovery of the failure until the train was returned to service**

The Unit 2 RHR Loop I SPS was found to be inoperable on March 20, 2025. It was returned to service approximately four days later on March 24, 2025.

**VI. Corrective Actions**

Corrective Actions are being managed by the TVA's Corrective Action Program (CAP) under Condition Report 2000493.

**A. Immediate Corrective Actions**

The u-bolt was replaced on support 2-H-343.

**B. Corrective Actions to Prevent Recurrence or to reduce the probability of similar events occurring in the future**

The corrective action for this event was to conduct a Notice of Indication evaluation of the support.

As an additional action, maintenance personnel will be provided a brief on the proper use of configuration control forms.

**VII. Previous Similar Events at the Same Site**

A review of the BFN CAP and Licensee Event Reports (LERs) for Units 1, 2, and 3 revealed no other instances within the past three years of SPS inoperability due to missing components.

**VIII. Additional Information**

There is no additional information.

**IX. Commitments**

There are no new commitments.