Union Electric Callaway Plant

Gentlemen:

PO Box 620 Fulton, MO 65251

May 1, 2000

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop P1-137 Washington, DC 20555-0001

ULNRC-4233

Ameren

ó

DOCKET NUMBER 50-483 CALLAWAY PLANT UNIT 1 UNION ELECTRIC CO. FACILITY OPERATING LICENSE NPF-30 LICENSEE EVENT REPORT 1999-003-01 Manual Reactor Trip Due To Heater Drain System Pipe <u>Rupture Caused By Flow Accelerated Corrosion</u> (Reference: ULNRC-4106, dated September 10, 1999)

The enclosed licensee event report is submitted in accordance with 10CFR50.73(a)(2)(iv) to report an event that resulted in an automatic actuation of an Engineered Safety Feature and a manual actuation of the Reactor Protection System. This revised licensee event report is submitted in order to clarify wording within the safety significance section which stated that no radioactive materials were released to the environment during this event. Although no unanticipated quantities of radioactive material were released, insignificant amounts of radioactive material normally present within the secondary coolant were released via the Atmospheric Steam Dumps and the Turbine Driven Auxiliary Feedwater Pump steam exhaust during this event.

R. D. Affolter Manager, Callaway Plant

RDA/mdhu

Enclosure



ULNRC-4233 May 1, 2000 Page 2

à

8 2

cc: Mr. Ellis W. Merschoff Regional Administrator
U.S. Nuclear Regulatory Commission Region IV
611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011-8064

> Senior Resident Inspector Callaway Resident Office U.S. Nuclear Regulatory Commission 8201 NRC Road Steedman, MO 65077

Mr. Jack N. Donohew (2 copies) Licensing Project Manager, Callaway Plant Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Mail Stop OWFN-4D3 Washington, DC 20555-2738

Manager, Electric Department Missouri Public Service Commission PO Box 360 Jefferson City, MO 65102

Records Center Institute of Nuclear Power Operations 700 Galleria Parkway Atlanta, GA 30339

r	<u>s</u>																										
					LIC	ENSE	CE E	VEN	T RE	PO	RT	C(L	EI	R)													
FACILIT	Y NAME (1)							<u> </u>	T	DOC	KET NU	JMBE	R (2)					PAG	GE (3)							
Calla	away	Plant	Unit	1							0	5	0	0	0	8	8 3 1 OF 0										
TITLE (4)	Man	ual Re	acto	or Trip D	ue To]	Heate	r Dra	in Sys	tem	Pip	e R	up	ture	C	aus	sed	by	Flow	J I.	I						
_		Accel	lerate	d Co	orrosion				-				-					-									
EVI	ENT DATE	5)		LE	R NUMBER (6)		REF	PORT DAT	ſE (7)					OTHE	R FA	ES IN	/OLV	ED (8)		<u> </u>							
MONTH	DAY	YEAR	YEAR	s	SEQUENTIAL NUMBER	REV. NO.	MONTH	DAY	YEAR			FACILIT	TY N/	AMES			DOCKET NUMBER(S)										
0 8	1 1	9 9	9 9	-	0 0 3 -	. 0 1	0 5	0 1	0 0								0										
OPE M	RATING 1 DDE (9) 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR : (Check one or more of the following) (11														ing) (11)												
POWER 20.2201(b) LEVEL (10) 1 0 0 20.2203(a)(1) 20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii)							20.2203(a 20.2203(a 20.2203(a 20.2203(a 50.36(c)(50.36(c)(J.2203(a)(2)(v) 50.73(a)(2)(i) 0.2203(a)(3)(i) 50.73(a)(2)(ii) 0.2203(a)(3)(ii) 50.73(a)(2)(iii) 0.2203(a)(4) X 50.73(a)(2)(iv) 50.73(a)(2)(iv) 0.36(c)(1) 50.73(a)(2)(vi) 0.36(c)(2) 50.73(a)(2)(vii)										50. 50. 73. 0T Ab: Te>	50.73(a)(2)(viii) 50.73(a)(2)(x) 73.71 OTHER (Specify in Abstract below or in Text, NRC Form 366A)								
NAME						L	ICENSEL	CONTAC	FOR THIS	LER (1)	2)						TE	LEPH	ONE NUM	BER							
J. D.	Schn	ack, S	Superv	/isin	g Enginee	ər, QA	Regul	atory	Suppo	ort				^{AR} 5		7 3	6	7	6 -	43	19						
CAUSE	COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) E SYSTEM COMPONENT MANUFAC- TURER REPORTABLE TO EPIX CAUSE SYSTEM COMPONENT MANUF TURE													NUFAC JRER		REPOF TO	TABLE EPIX										
Е	s	N	PS	Р		Y											l										
				SUP	PLEMENTAL RE	PORTEXPE	CTED (14)	<u> </u>				<u> </u>						Ц	MONTH	DAY	YEAR						
	6 (If <u>ye</u> s, c	omplete EX	PECTED	UBMIS	SSION DATE)					EXPECT SUBMISSI DATE (1						ED ON 5)		1	<u> </u>	<u> </u>							
	•						· ·						•						_	<u> </u>	<u> </u>						
ABSTRA At a a pi Sepa reac manu syst for The degr Acce repl	cr (Limit) pprox pe ru rator tor v ally ems c compo locat ee el lerat aced	o 1400 spa cimate apture c Rehe vas ma initi operat cion c bow. ced Cc with	ces, ie. ap aly 09 a occu ater anual tated ted pe s loca of the Root prros: Chror	proxima PI7 JT7 fir Ly t ST d ated ≥ pi = ca ion nium	ately fifteen single on Augus ed in a s est stage tripped a No person lesign. d in the ipe ruptu ause anal (FAC) w: n - Moly)	⇒space typew st l1, six in e rehe. and fa nnel w Some : vicin ure wa lysis ith an bdenum	vritten lines 1999 ch dr ater st cl ere i non-s ity c s det indic abnc pipi	<pre>sylfe) sylfe ain drain drain .osure .njure safet of the cermin cates ormal ing.</pre>	h the line] n tank e of t y rela e pipe ned to that ly hig Addit	plan locat can the I ring ated e ruj o be the gh we cion	nt ted d t th eq otu im fa fa al	ope he n S uis uis med ilu: ra pip	rat two "61 tea even men iat re te inq	ting een 3" f am] ent nt f cely was .] y ir	f and the feet of	at ne edw. ola ilu dow: att: e r oec	100 "D" ate tio all res nst rib upt	pe Mc r h sa we rea ute ute	arcen pistu neate alve fety are of am of ad to ad pi	t pow re r. T s was rela bserv a 45 Flow ping	rer, The ted red was						
peri abno FAC	ormeo rmal progi	wear am gu	rates rates	ions 3 ob ines	s with s: oserved. s for det	Less termin	oper ons l ing i	earne. .nsped	g cond ed fro ction	n ti poir	ons his hts	ev ev	ent	igui z wi	il]	10: L b	ns i	wit nco	n no orpor	othe ated	r into						

.

FACILITY NAME (1)	DO	СКЕТ	NUM	IBER	(2)						L	ER N	UMB	ER (6	5)		P	3)				
									YE	AR		SEC N	QUEN UMBE	TIAL R		R N	EV 0.					
Callaway Plant Unit 1	0	5	0	0	0	4	8	3	9	9	-	0	0	3	-	0	1	0	2	OF	0	5

TEXT (If more space is required, use additional NRC Form 366A's)(17)

DESCRIPTION OF EVENT:

.

At approximately 0917 on August 11, 1999, a pipe rupture occurred in a six inch drain line located between the "D" Moisture Separator Reheater (MSR) first stage reheater drain tank and the "6B" feedwater heater. At the time of the event the plant was operating in Mode 1 at 100 percent power with no safety related components out of service.

Heater drain system alarms and an approximate 20 Megawatt decrease in electrical generation initially alerted the Control Room staff to an abnormality in the extraction steam/heater drain system. Subsequently, the Control Room began receiving reports of a steam leak within the Turbine Building. The Reactor Operator also noticed reactor power was increasing with a maximum observed power level of 100.78% (3591.8 MW thermal). The Control Room staff reduced reactor power and began making preparations to isolate one train of the high pressure feedwater heaters based on preliminary reports and indications. Additional reports indicated the steam leak was substantial and the source of the leak could not be determined. Based on this information, at 0925 the Control Room Supervisor directed the Reactor Operator to manually trip the reactor and the appropriate Emergency Operating Procedure was entered. The reactor trip initiated a main turbine trip which closed the turbine stop valves. Additionally, as a result of the reactor trip, a Feedwater Isolation Signal (FWIS) was generated which isolated the main feedwater system and automatically started the three Auxiliary Feedwater pumps to supply the steam generators.

In order to ensure isolation of the ruptured line, fast closure of the Main Steamline Isolation Valves was manually initiated with all valves closing properly. Personnel accountability by assembly was initiated. This was performed as a precautionary measure for ascertaining the safety of plant personnel.

The Control Room staff transitioned from the Emergency Operating Procedures to normal plant shutdown procedures and subsequently secured both motor driven auxiliary feedwater pumps. The plant was stabilized with the turbine driven auxiliary feedwater pump supplying the steam generators with the Main Steam Line atmospheric steam dump valves controlling steam generator pressure.

All safety related systems and components operated per design during this event. Operational abnormalities were observed for the following non-safety related systems and components following the rupture of the heater drain line:

1) Steam escaping from the ruptured pipe contacted fire detectors in the immediate area resulting in the actuation of a fire protection system preaction deluge valve. Although the deluge valve actuated, a discharge did not occur through the sprinkler heads since the fusible links on the sprinkler heads had not melted. However, the "A" diesel driven and motor driven fire pumps did automatically start as a result of the system pressure decrease from the deluge valve actuation.

FACILITY NAME (1)	DO	CKET	r NUN	ABER	(2)						l	ER NUMBER (6)							P	3)		
										YEAR			SEQUENTIAL NUMBER				EV O.					
Callaway Plant Unit 1	o	5	0	0	0	4	8	3	9	9	-	0	0	3	_	0	1	0	3	OF	0	5

TEXT (If more space is required, use additional NRC Form 366A's)(17)

2) The plant computer failed approximately 5 minutes into the event due to the failure of one of the computer's uninterruptible power supplies which was located in the vicinity of the pipe rupture.

3) The five non-safety process radiation monitors listed below experienced failures during this event due to the failure of an uninterruptible power supply (UPS) which was located in the vicinity of the pipe rupture.

Main Steam Line Atmospheric Steam Dump Valve "A" discharge monitor Unit Vent discharge monitors "A" and "B" Radwaste Building discharge monitors "A" and "B"

4) The in-service Condenser Air Removal Exhaust Fan tripped following the pipe rupture due to a high differential pressure on the suction filter resulting from the high humidity environment within the Turbine Building.

BASIS FOR REPORTABILITY:

These events are reportable per 10CFR50.73(a)(2)(iv) as an event or condition that resulted in a manual or automatic actuation of an engineered safety feature, including the reactor protection system.

CONDITION AT TIME OF EVENT:

Mode 1, Power Operations - 100% power

ROOT CAUSE:

The ruptured pipe was determined to be schedule 40, 0.280 inch wall thickness, SA106 Grade B carbon steel pipe. The normal operating conditions for this section of pipe was 410 degrees Fahrenheit, 283 psig. The location of the pipe rupture was determined to be immediately downstream of a 45 degree elbow in the heater drain line. The direct cause of the pipe rupture was preliminarily attributed to Flow Accelerated Corrosion (FAC) with an abnormally high wear rate. This was an unanticipated location for a catastrophic failure since the 45 degree elbow was considered to be the limiting FAC susceptible component in this location. Previous inspections had not revealed abnormal wear rates within this elbow.

Independent consultant services were acquired to assist in the root cause determination. Analysis has determined the FAC wear rate appears to have been accelerated by water droplet impingement on the piping immediately downstream of the 45 degree elbow. The cause of the impingement was attributed to a combination of the system's low steam quality (approximately 4%) and the piping configuration upstream of the 45 degree elbow. The upstream piping configuration consisted of a 100 foot horizontal section of pipe that allowed the water/steam mixture to separate, followed by 90 degree and 45 degree elbows. As the flow entered the 45 degree elbow, it encountered weld backing rings that forced some water droplets back into the steam flowpath. As the steam exited the 45 degree elbow, the water droplets were then impinged upon the side wall of the downstream piping.

FACILITY NAME (1)	E (1) DOCKET NUM										i	ER N	IUMB	ER (6	5)	Γ	P	3)				
									YE	YEAR		SEQU		uential Imber		R	EV O.					
Callaway Plant Unit 1		ا ⊾	ما	0	١		.	2		_			_ ا	2						OF		5
Callaway Plant Unit 1	0	5	0	0	0	4	8	3	9	9	-	0	0	3	-	0		1	1 0	1 0 4	1 0 4 OF	1 0 4 OF 0

TEXT (If more space is required, use additional NRC Form 366A's)(17)

A causal factor associated with this event is the manner in which the FAC inspection program provided guidance for inspecting downstream piping when performing fitting inspections. The program did not consider downstream piping inspections as mandatory, although it is a common practice. However, this downstream piping was not inspected when the upstream 45 degree elbow was inspected during previous refueling outages. Had this piping been previously inspected, it is probable an abnormal wear rate would have been detected. (Note: This section of pipe had been previously added to the scope of inspections for the plant's tenth refueling outage scheduled for the fall of 1999.)

A second causal factor associated with this event is the industry experience-based perception that the upstream 45 degree elbow would be the most susceptible component for failure due to FAC. This causal factor contributed to the decisions made during previous refueling outages to not inspect the downstream piping associated with this elbow.

CORRECTIVE ACTIONS:

1) Mechanical, electrical, instrumentation, and civil/structural inspections were performed to assess collateral damage to structures and components within the surrounding area of the pipe rupture.

2) The ruptured section of carbon steel piping was replaced with A335 Gr. P22 Chromium - Molybdenum piping.

3) Engineering performed evaluations to determine other locations with similar operating conditions/configurations which may be susceptible to the same failure mechanisms. As a result, 42 additional points within other sections of the heater drain system were identified as requiring inspections to verify piping integrity. These inspections were performed with no other abnormal wear conditions identified.

4) A review of components within the FAC program was performed in order to identify other locations in which downstream piping was not inspected during fitting inspections. Twenty-one inspection sites meeting these criteria were identified. As a result, these components have been added to the scope of inspections scheduled for the plant's tenth refueling outage in the fall of 1999.

5) Procedures governing the FAC program will be revised to include lessons learned from this event, including selection criteria guidelines for determining inspection points.

6) Information regarding this event has been provided for industry notification through the Checworks Users Group (CHUG), which is an industry funded users group that addresses FAC. In addition, utility engineering personnel have worked closely with the designers of the Checworks FAC modeling program in providing feedback regarding the specific details of this anomaly. General information regarding this event has also been provided to the Institute of Nuclear Power Operations (INPO) for industry distribution.

FACILITY NAME (1)	DO	СКЕТ	NUM	IBER	(2)						l	LER NUMBER (6)							P,	(3)		
										YEAR			QUEN	Jential Mber		R	RÉV NO.		÷			
Callaway Plant Unit 1	0	5	0	0	0	4	8	3	9	9	-	0	0	3	-	0	1	0	5	OF	0	5

TEXT (If more space is required, use additional NRC Form 366A's)(17)

SAFETY SIGNIFICANCE:

No personnel injuries occurred as a result of this event. However, this event was significant with respect to the safety of plant personnel due to the potential for personnel injury resulting from the piping failure. This event was not significant with respect to the health and safety of the general public since all safety systems functioned per design during this event. Additionally, the radioactive material released to the environment as a result of this event was an insignificant fraction of the regulatory limits.

PREVIOUS OCCURRENCES:

There have been no previous occurrences of pipe ruptures due to FAC at Callaway.

FOOTNOTES:

The system and component codes listed below are from IEEE Standard 805-1984 and IEEE Standard 803A-1984, respectively.

System SN, Component PSP