

Point Beach 2

Initiating Events



Significance: Dec 31, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

UNPLANNED REACTOR VESSEL LEVEL DECREASE DURING COUPLING OF REACTOR COOLANT PUMP.

The inspectors identified a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," for an inadequate procedure which resulted in an inadvertent decrease in reactor coolant system inventory during reactor coolant pump coupling while in cold shutdown. The finding was of very low safety significance because residual heat removal was not impacted and the amount of water that could have been drained from the reactor coolant system was limited by system configuration and alignment.

Inspection Report# : [2000017\(pdf\)](#)

Significance: N/A Nov 02, 2001

Identified By: NRC

Item Type: FIN Finding

SUPPLEMENTAL INSPECTION FOR WHITE PERFORMANCE INDICATOR

This supplemental inspection was performed to assess the licensee's evaluation of the Unplanned Scrams per 7,000 Critical Hours Performance Indicator (PI) for Unit 2 which transitioned from Green to White in the second quarter of 2001. The evaluation was determined to be acceptable.

The licensee utilized a structured approach to evaluate the circumstances of the individual plant trips and the collective significance of the four trips to identify potential common causes. The inspector determined that corrective actions for each of the plant trips contributing to the White PI corresponded with the root and contributing causes identified by the root cause evaluations. The corrective actions were either completed or being tracked for completion. In two of the four trips, the corrective action and root cause program established a process for performing assessment reviews to assess the effectiveness of corrective actions. Due to the licensee's acceptable performance in addressing the root and contributing causes of the individual plant trips which contributed to exceeding the licensee response threshold for Unplanned Scrams, the White PI associated with this issue will only be considered in assessing plant performance for a total of four quarters, in accordance with the guidance in IMC 0305, "Operating Reactor Assessment Program."

Inspection Report# : [2001016\(pdf\)](#)

Mitigating Systems



Significance: Jun 30, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

AFW SYSTEM INCORRECTLY RETURNED TO MAINTENANCE RULE (a)(2) STATUS WITHOUT MEETING THE REQUIREMENTS IN THE LICENSEE'S (a)(1) ACTION PLAN

A Non-Cited Violation [of 10 CFR 50.65] was identified for the licensee erroneously returning the auxiliary feedwater system to (a)(2) status prior to meeting licensee established (a)(1) performance goals in December 2000. The licensee's inaccurate monitoring of system unavailability against established (a)(1) unavailability goals was determined to be the cause of the error. Since no actual loss of the safety function of the auxiliary feedwater system occurred, this issue was evaluated as having very low safety significance.

Inspection Report# : [2001010\(pdf\)](#)



Significance: Jun 30, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

USE OF THE STEAM GENERATOR BLOWDOWN ISOLATION INTERLOCK DEFEAT SWITCH COULD RESULT IN LOSS OF SAFETY FUNCTION

Code of Federal Regulations 10 CFR Part 50, Appendix B, Criterion III, "Design Control," requires, in part, that measures be established to assure that the design basis specified in the licensee application be correctly translated into procedures and instructions. Contrary to this requirements, the licensee modified steam generator blowdown isolation circuitry to allow defeating the blowdown isolation function during surveillance testing without considering the design basis requirements of the auxiliary feedwater system to provide the heat removal equivalent feedwater flow, 200 gpm, to each unit necessary for post-accident decay heat removal. This issue has been included in the licensee's corrective action program as CR 01-

0108.

Inspection Report# : [2001010\(pdf\)](#)G**Significance:** May 08, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

FAILURE TO PROVIDE DIRECT READINGS OF STEAM GENERATOR 'B' PRESSURE PARAMETER WHICH WAS NECESSARY TO PERFORM SAFE SHUTDOWN FUNCTIONS

10 CFR Part 50, Appendix R, Section III.L.2.d, requires the process monitoring function be capable of providing direct readings of the process variables necessary to perform and control safe shutdown functions. Contrary to the above, the licensee failed to provide direct readings of steam generator 'B' pressure parameter which was necessary to perform safe shutdown functions.

Inspection Report# : [2001008\(pdf\)](#)G**Significance:** May 08, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

FAILURE TO INSTALL THE FIRE STOPS IN A CONFIGURATION WHICH WOULD PREVENT PROPAGATION OF FIRE FROM ONE REDUNDANT TRAIN TO ANOTHER

10 CFR Part 50, Appendix R, Section III.G.2.b, requires separation of cables and equipment and associated non-safety circuits of redundant trains by a horizontal distance of more than 20 feet with no intervening combustibles or fire hazards. An exemption to this requirement was granted by the NRC, dated July 3, 1985, which stated that the approved alternative was to install fire stops in the intervening cable trays. Contrary to the above, the licensee failed to install the fire stops in the Unit 1 motor control center room in a configuration which would prevent propagation of fire from one redundant train of charging pump cables to another.

Inspection Report# : [2001008\(pdf\)](#)G**Significance:** May 08, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

REDUNDANT INSTRUMENT CABLES WERE LOCATED WITHIN 20 FEET OF EACH OTHER IN THE UNITS 1 AND 2 CONTAINMENTS

10 CFR Part 50, Appendix R, Section III.G.2.d, requires separation of cables and equipment and associated non-safety circuits of redundant trains by a horizontal distance of more than 20 feet with no intervening combustibles or fire hazards inside non-inerted containment. Contrary to the above, redundant cables for several temperature elements and steam generator level instruments were located within 20 feet of each other in the Units 1 and 2 containments.

Inspection Report# : [2001008\(pdf\)](#)G**Significance:** May 08, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

POSTULATED FIRE COULD LEAD TO LOSS OF REDUNDANT TRAINS OF CHARGING PUMPS

10 CFR Part 50, Appendix R, Section III.L.2.b, requires the reactor coolant makeup function be capable of maintaining the reactor coolant level within the level indication in the pressurizer for pressurized water reactors. Contrary to the above, in eight fire zones, the cables associated with volume control tank and reactor water storage tank outlet valves were routed in the same fire areas. There would be insufficient time to take manual actions to prevent failure of charging pumps credited for maintaining reactor coolant level.

Inspection Report# : [2001008\(pdf\)](#)G**Significance:** May 08, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

REPLACEMENT OF CHARGING PUMP CONTROL POWER FUSE OUTSIDE APPENDIX R DESIGN BASIS

10 CFR Part 50, Appendix R, Section III.G.1, requires that fire protection features be provided for systems important to safe shutdown so that one train of systems necessary to achieve and maintain hot shutdown conditions is free of fire damage. Contrary to the above, the licensee failed to provide redundant fusing to protect the control cable associated with the credited charging pump which was necessary for hot shutdown condition and was not free of fire damage.

Inspection Report# : [2001008\(pdf\)](#)

Significance: N/A Mar 31, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

TECHNICAL SPECIFICATION REQUIREMENTS FOR TESTING RPS ACTUATION SYSTEM LOGIC NOT SATISFIED

Technical Specification Table 15.4.1-1, "Minimum Frequencies for Checks, Calibrations, and Test of Instrument Channels," Item 44, "Reactor Protection System and Emergency Safety Feature Actuation System Logic," required monthly testing of Reactor Protection System trips which includes the power range low power trip and the intermediate range high flux trip logics. Contrary to this requirement, a surveillance test requirement was missed when the licensee failed to test the power range low power and the intermediate range high flux trips within 24 hours after reducing power below 10 percent after having operated in excess of 10 percent power for greater than the monthly surveillance test frequency. This issue was entered in the licensee's corrective action program as CR 01-0118.

Inspection Report# : [2001007\(pdf\)](#)

Significance: N/A Mar 31, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO COMPLY WITH LIMITING CONDITION FOR OPERATION ACTION STATEMENT TO START REDUNDNT STANDBY

Technical Specification 15.3.7.B.1.g required redundant standby emergency power supplies to be started within 24 hours before or after the normal power supply or emergency power supply to Unit 1 A06/B04 or Unit 2 A05/B03 safeguards busses being taken out-of-service. Contrary to this requirement, the licensee identified that the standby emergency power supply to the Unit 2 A05/B03 was out-of- service for 37 hours without the redundant standby emergency power supply being started. This issue was entered in the licensee's corrective action program as CR 00-3475.

Inspection Report# : [2001007\(pdf\)](#)

Significance: N/A Feb 12, 2001

Identified By: NRC

Item Type: FIN Finding

16 VALVES ON UNIT 2 SI SYSTEM WERE LOCKED CLOSED INSTEAD OF JUST CLOSED.

The inspectors identified that 16 valves in the Unit 2 safety injection system were locked closed instead of just closed as required by plant procedure. The failure to maintain valve position in accordance with applicable plant procedure did not affect the operability, availability, or reliability of the safety injection system and was not evaluated using the Significance Determination Process. However, the inspectors determined that the extent of the status control errors, the repetitive nature of locked valve problems, and the failure of previously identified corrective actions constituted extenuating circumstances in accordance with Manual Chapter 0609.

Inspection Report# : [2001003\(pdf\)](#)



Significance: Feb 12, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

INADEQUATE CONTROL OF CABLE SPREADING ROOM HIGH ENERGY LINE BREAK BARRIER.

The licensee's quality assurance organization identified that a 4½-inch pipe built into and penetrating a wall of the cable spreading room, used for temporary running of cables into the room, was being controlled as a fire barrier impairment but not as a high-energy line break barrier impairment. The pipe had not been included in the licensee's procedure on high energy line break barriers. The failure to include the 4½" pipe in Administrative Procedure NP 8.4.16, "PBNP [Point Beach Nuclear Plant] High Energy Line Break Barriers," was considered a violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," requirements.

Inspection Report# : [2001003\(pdf\)](#)



Significance: Dec 31, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE PROCEDURE FOR BYPASSING ALARMS FOR HEAT TRACE CIRCUITS FOR SAFETY-RELATED EQUIPMENT.

The inspectors identified a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," for an inadequate procedure that specified actions that inappropriately de-energized heat trace circuits for safety-related equipment when the intent was only to bypass alarms. The finding was of very low safety significance because safety-related equipment was not actually rendered inoperable.

Inspection Report# : [2000017\(pdf\)](#)



Significance: Nov 09, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE PROCEDURE FOR PRESSURE TEST OF RESIDUAL HEAT REMOVAL VALVE.

On October 11, 2000, the inspectors identified a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," for an inadequate procedure that did not require verification of appropriate automatic overpressure protection on hydrostatic pressure

test equipment during valve seat leakage testing on Train "B" of the Unit 2 residual heat removal system. This finding was of very low safety significance because procedurally required manual overpressure protection was available during testing and Train "A" of the Unit 2 residual heat removal system was operable.

Inspection Report# : [2000014\(pdf\)](#)

Significance: N/A Aug 22, 2000

Identified By: NRC

Item Type: FIN Finding

SAFETY INJECTION VALVES NOT LOCKED AS REQUIRED BY PLANT PROCEDURE.

The inspectors identified that 24 valves in the Unit 2 safety injection system were not locked as required by plant procedure. The failure to lock the valves in accordance with plant procedure did not affect the operability, availability, or reliability of the safety injection system and was not evaluated using the Significance Determination Process. However, the inspectors determined that the extent of the status control errors and repetitive nature of the locked valve problems constituted extenuating circumstances in accordance with Manual Chapter 0609. This finding was assigned to Unit 2.

Inspection Report# : [2000009\(pdf\)](#)



Significance: G Nov 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO TAKE TIMELY CORRECTIVE ACTION REGARDING INADEQUATE CONTROL OF MAINTENANCE ACTIVITIES DURING COLD WEATHER CONDITIONS

The inspectors identified a Non-Cited Violation (10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action"), in that the licensee failed to take corrective action prior to the onset of freezing temperatures in the fall of 2001 for previously identified problems with the plant's freeze protection system. The finding was considered to be more than minor because the freeze protection system helps to protect safety-related components from freezing and the system's failure could have a credible impact on safety. Because there was no actual failure of safety-related components associated with the mitigating systems cornerstone, the finding is considered to be of very low significance

Inspection Report# : [2001014\(pdf\)](#)



Significance: G Sep 30, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

NO PROCEDURES TO PREVENT EXCESSIVE FOULING OF SERVICE WATER STRAINERS

The inspectors identified a Non-Cited Violation (10 CFR Part 50, Appendix B, Criterion V), in that, the licensee failed to provide adequate written instruction to prevent excessive fouling of the service water header strainers. As a result, a condition adverse to quality was self-revealed on September 20, 2001, when auxiliary operators identified, while taking logs, that both the north and south header strainers were excessively fouled. The excessive fouling resulted in the service water system being in a configuration that was beyond design basis analyses. The Non-Cited Violation was considered of low risk significance since, for the plant and environmental conditions at the time of discovery, no actual loss of safety function occurred or would have occurred.

Inspection Report# : [2001013\(pdf\)](#)

Significance: N/A Sep 28, 2001

Identified By: NRC

Item Type: FIN Finding

HUMAN PERFORMANCE CROSS-CUTTING ISSUE DUE TO WEAKNESSES IN FIRE PROTECTION ENGINEERING AREA

The inspectors identified a number of issues which, collectively, indicated that human performance weaknesses existed in the fire protection engineering area.

Inspection Report# : [2001012\(pdf\)](#)

Significance: N/A Sep 28, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

INSUFFICIENT EMERGENCY LIGHTING TO SUPPORT SAFE SHUTDOWN

The inspectors identified that there was insufficient emergency lighting to support performance of required safe shutdown actions. Specifically, there was insufficient emergency lighting in the Unit 1 and Unit 2 façade areas to support performing confirmatory actions to fail air to the Unit 1 and Unit 2 main steam isolation valves so as to ensure these valves would not spuriously reopen. The failure to have adequate emergency lighting is a violation of 10 CFR Part 50, Appendix R, Section III.J. The finding was greater than minor because a delay in performing safe shutdown actions could occur due to the lack of emergency lighting. The finding was determined to be No Color because the finding did not involve the impairment or degradation of a fire protection defense-in-depth element. Because the finding was of very low safety significance, and the finding was captured in the licensee's corrective action system, this finding is being treated as a NCV consistent with Section VI.A.1 of the NRC Enforcement Policy.

Inspection Report# : [2001012\(pdf\)](#)

G

Significance: Sep 28, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

AUXILIARY FEEDWATER PUMP ROOM HALON SYSTEM INADEQUATE

The inspectors identified that the automatic fire suppression system for the auxiliary feedwater pump room was not adequate. The installed fire suppression system was only designed for surface fires and was not designed to provide the necessary soak time for deep-seated fires. However, deep-seated fire hazards had been introduced to the room. The failure to have an adequate automatic suppression system is a violation of 10 CFR Part 50, Appendix R, Section III.G.2. The finding was determined to be greater than minor because the finding involved automatic suppression, a fire protection defense-in-depth element. The finding was determined to be of very low safety significance (Green) because the inspectors were not able to postulate a fire scenario which could sustain a deep-seated fire and damage redundant trains of equipment. Because the finding was of very low safety significance, and the finding was captured in the licensee's corrective action system, this finding is being treated as a NCV consistent with Section VI.A.1 of the NRC Enforcement Policy.

Inspection Report# : [2001012\(pdf\)](#)**Significance:** N/A Sep 28, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

INSUFFICIENT APPENDIX R FUEL OIL SUPPLY

The inspectors identified that the licensee had failed to maintain a 72-hour fuel supply on-site for generator G-05 relied upon for safe shutdown in the event of a fire. The failure to maintain a 72-hour supply of fuel is a violation of 10 CFR Part 50, Appendix R, Section III.L.3. The finding was greater than minor because the capability to achieve and maintain cold shutdown conditions for 72 hours was not provided. The finding was determined to be No Color because the finding did not involve the impairment or degradation of a fire protection defense-in-depth element. Because the finding was of very low safety significance, and the finding was captured in the licensee's corrective action system, this finding is being treated as a NCV consistent with Section VI.A.1 of the NRC Enforcement Policy.

Inspection Report# : [2001012\(pdf\)](#)

G

Significance: Sep 28, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

POSSIBLE SPURIOUS OPENING OF POWER-OPERATED RELIEF VALVE DURING FIRES

10 CFR Part 50, Appendix R, Section III.G.1.a required, in part, that one train of systems necessary to achieve and maintain hot shutdown conditions be free of fire damage. As discussed in LER 50-266/1999-006-00; 50-301/1999-006-00, hot shutdown conditions would not have been able to be maintained during the ensuing plant transient which would have resulted from a stuck open pressurizer PORV (power-operated relief valve).

Inspection Report# : [2001012\(pdf\)](#)

G

Significance: Aug 07, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

INEFFECTIVE CORRECTIVE ACTIONS FOR FAILURE TO FOLLOW TECHNICAL SPECIFICATIONS CONCERNING COMMON CAUSE FAILURE TESTING OF EMERGENCY DIESEL GENERATORS

The inspectors identified that the licensee failed to take effective corrective action to preclude repetition of the failure to comply with Technical Specification limiting condition for operation requirements directing testing of redundant standby emergency diesel generator power supplies within 24 hours. A Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," was identified. The finding was of very low safety significance because, in both cases of Technical Specification non-compliance, the redundant standby emergency diesel generators were tested satisfactorily, indicating that no actual loss of safety function occurred.

Inspection Report# : [2001011\(pdf\)](#)**Significance:** N/A May 05, 2000

Identified By: NRC

Item Type: FIN Finding

INADEQUATE OPERABILITY DETERMINATIONS.

The inspectors identified that operability determinations lacked sufficient engineering basis to support continuing operability calls. The licensee was able to show current system operability, given the plant conditions at the time of the inspection.

Inspection Report# : [2000006\(pdf\)](#)

G

Significance: May 05, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

ERRORS IN CALCULATIONS FOR SERVICE WATER TESTING ACCEPTANCE CRITERIA.

The inspectors identified errors in the calculations providing the uncertainty values for determining the service water inservice testing acceptance criteria. The errors resulted in the lower inservice testing acceptance criteria being below the required design minimum flow. The risk significance of this was low because, at the time of the inspection, all six pumps had flow rates above the minimum acceptance criteria. This issue was considered the first example of a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control."

Inspection Report# : [2000006\(pdf\)](#)

G

Significance: May 05, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

ERRORS IN SERVICE WATER TEMPERATURE UNCERTAINTY VALUES.

The inspectors identified errors in the service water temperature uncertainty values. This resulted in the control room temperature indications being non-conservatively low. The risk significance of this was low because, at the time of the inspection, lake temperatures were below the design basis maximum. This was the second example of a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control."

Inspection Report# : [2000006\(pdf\)](#)

G

Significance: May 05, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

ERROR IN CALCULATION PUMP NET POSITIVE SUCTION HEAD.

The inspectors identified a fundamental error in calculating pump net positive suction head which basically concluded that the pumps would have adequate suction even if the intake was completely uncovered. The risk significance of this was low because, at the time of the inspection, forebay level was sufficiently high to ensure the pumps were operable. This was the third example of a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control."

Inspection Report# : [2000006\(pdf\)](#)

Barrier Integrity

G

Significance: Nov 09, 2000

Identified By: Licensee

Item Type: NCV NonCited Violation

INADEQUATE PROCEDURE FOR SHIELDING PLACEMENT IN FRONT OF CONTROL ROOM WINDOWS.

An operating procedure did not provide for timely placement of portable shielding in front of control room windows to ensure accident doses to operator would remain below NRC limits. This was contrary to Criterion V, "Instructions, Procedures, and Drawings," of Appendix B of 10 CFR Part 50, requires that activities affecting quality be prescribed by documented instructions, procedures, or drawings.

Inspection Report# : [2000014\(pdf\)](#)

Emergency Preparedness

Significance: N/A Nov 03, 2000

Identified By: NRC

Item Type: FIN Finding

SUPPLEMENTAL INSPECTION OF WHITE PERFORMANCE INDICATOR.

The licensee's initial evaluations and corrective actions associated with the White alert and notification system (ANS) performance indicator (PI) were not adequate. Following the initial NRC onsite inspection and a parallel review by the licensee's quality assurance staff, the licensee performed a comprehensive root cause evaluation of ANS performance. The inspector determined that this evaluation was thorough and effectively identified the root causes of the siren system performance issues. In addition, the licensee fully determined the technical issue that resulted in siren test failures. As a root cause, the licensee concluded that the siren upgrade project was performed outside of the licensee's normal procurement process, which would have provided additional quality assurance, software testing and verification, and project oversight. In addition, the staff did not consistently use the licensee's corrective action system to document system failures. The licensee attributed these failures to a "mindset" among the emergency preparedness staff that resulted in the staff using internal processes instead of normal plant processes. In terms of

corrective actions, the inspector found that the licensee's final planned corrective actions appeared to address the root causes identified in its evaluation. However, the licensee had not yet defined what measures would be implemented to ensure that the effectiveness of these corrective measures were reviewed, nor had the licensee completed its extent of condition review.

Inspection Report# : [2000012\(pdf\)](#)

Occupational Radiation Safety



Significance: Mar 31, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

WORKER ENTERED A HIGH RADIATION AREA WITHOUT GETTING RADIATION PROTECTION DEPARTMENT APPROVAL OR BRIEF

Technical Specification Section 15.6.11., Radiation Protection Program, required that an individual entering a high radiation area be under the control of a radiation work permit that includes specification of the radiation dose rates in the immediate work area and other appropriate radiation protection equipment and measures. Contrary to this requirement, during resin transfer operations on February 27, 2001, a laundry decontamination worker entered a high radiation area without getting radiation protection department approval or a brief as required by Radiation Work Permit (RWP) 01-005, Revision 0. This issue was entered in the licensee's corrective action program as CR 01-0611.

Inspection Report# : [2001007\(pdf\)](#)

Public Radiation Safety

Physical Protection

Miscellaneous

Significance: N/A Mar 30, 2001

Identified By: NRC

Item Type: FIN Finding

EFFECTIVE CORRECTIVE ACTION PROGRAM.

The team concluded that the licensee was generally effective at identifying problems and putting them into the corrective action program. There was strong management emphasis on plant staff to identify problems and, overall, a very responsive plant staff. Since 1997, there had been an average of 4200 condition reports written each year. With the large number of condition reports and associated corrective actions, a dated software platform for the corrective action program, and the press of routine and emergent work activities, there was indication of timeliness and quality problems with some aspects of the corrective action program. Examples were identified by the inspectors, consistent with what the licensee had identified, of protracted resolution of problems with the freeze protection system and with discrepancies between the locked status of valves in the plant and the designation as locked in equipment checklists. Examples were also identified where corrective actions for some problems had been incorporated with the resolution of other related problems which were then incorporated with the resolution of yet other problems (that is, by closing corrective action documents to other documents and so on), creating the potential for dilution of the effectiveness of corrective actions for some of the original problems and for unintended extension of due dates for older items. Although there had been some expressed dissatisfaction with some aspects of the corrective action program, the inspectors identified no impediments to a safety conscious work environment.

Inspection Report# : [2001006\(pdf\)](#)

Significance: N/A Dec 31, 2000

Identified By: NRC

Item Type: FIN Finding

CROSS-CUTTING ISSUE FOR PROCEDURE INADEQUACIES.

The inspectors determined that a negative performance trend had developed in several cornerstone areas with procedure inadequacy being the common element based on two examples identified during this reporting period and two previously identified examples of inadequate procedures. All four examples related to the licensee development, technical review, and approval of procedures. While the risk of the individual examples was very low, the licensee had failed to ensure that procedures were correct prior to being approved for use. These findings collectively indicated a problem with the licensee's human performance in the area of procedure development, technical review, and approval.

Inspection Report# : [2000017\(pdf\)](#)

Significance: N/A Sep 30, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE EMERGENCY OPERATING PROCEDURE FOR TERMINATING CONTAINMENT SPRAY.

A Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified during the review of Licensee Event Report 50-266/2000-005-00, "Termination Criteria for Containment Spray in Emergency Operating Procedure Non-Conservative with Safety Analysis Assumptions." This report described a discrepancy with an Emergency Operating Procedure which had the potential to allow operators to prematurely secure containment spray prior to reaching the analyzed draw down level of the refueling water storage tank. The corrective actions were being tracked in the licensee's corrective action program.

Inspection Report# : [2000013\(pdf\)](#)

Significance: N/A May 05, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

NUMEROUS ERRORS IDENTIFIED IN CALCULATIONS.

The inspectors identified errors in the majority of calculations reviewed. These errors, along with those discussed above, indicated that a human performance issue might exist, relating to the depth and adequacy of engineering reviews. The errors constitute a fourth example of a Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control."

Inspection Report# : [2000006\(pdf\)](#)

Last modified : March 27, 2002