

Cooper

Initiating Events



Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to maintain Technical Specification Bases consistent with the USAR

The licensee failed to maintain Technical Specification Bases consistent with the USAR as required by Technical Specification 5.5.10(c). Specifically, the licensee failed to ensure that the Technical Specification Bases were maintained consistent with the Updated Final Safety Analysis Report with respect to offsite power supplying power to the 4160 volt buses. This resulted in the failure to enter Technical Specification 3.8.1.A, "One offsite circuit inoperable," that required the performance of Surveillance Requirement 3.8.1.1 within one hour on March 13, 2002. The licensee documented this issue in their corrective action process as Notification 10110178. The inspectors also determined that this noncited violation had crosscutting aspects associated with problem identification and resolution. This issue was determined to have an actual impact on safety, in that part of the safety function of a qualified offsite power source was unavailable. However, the condition was of very low safety significance because it was identified and corrected in approximately 2 hours (less than the Technical Specification allowed outage time) and the critical busses remained energized without the need for emergency power.

Inspection Report# : [2001008\(pdf\)](#)



Significance: G Dec 18, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to develop a procedure for combating emergencies and other significant events required by Regulatory Guide 1.33, Appendix A, Section 6.0

On September 7, 2001, a lightning storm caused the loss of one of the two offsite power circuits, as well as, intermittent degraded voltage on the other. No emergency or abnormal procedure was available to address degraded voltage or partial loss-of-offsite power conditions. The failure to have a procedure for combating emergencies and other significant events, specifically the loss or degradation of offsite power sources, was a violation of Technical Specification 5.4.1, which requires that procedures for combating emergencies be established in accordance with Regulatory Guide 1.33, Appendix A, Section 6.0. This violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notification 10111895. This issue was more than minor because it involved a credible impact on safety, in that, no procedure had been established for operators to combat the partial loss or degradation of one or both offsite power sources. The lack of a procedure for the operators could cause or increase the likelihood of an initiating event due to a loss-of-offsite power. The issue was evaluated by the team using the significance determination process and determined to be of very low safety significance (Green), since the reactor did not scram, and the critical busses remained energized without the need for emergency power.

Inspection Report# : [2001010\(pdf\)](#)



Significance: G Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Licensee's Technical Specification bases Control program failed to ensure that the Technical Specification Bases were maintained consistent with the Updated Final Safety Analysis Report

The licensee's Technical Specification Bases Control program failed to contain provisions to ensure that the Technical Specification Bases were maintained consistent with the Updated Final Safety Analysis Report with respect to the

offsite power sources supplying power to the essential switchgear. The licensee documented this issue in their corrective action process as Notification 10110178. This issue was considered to have an actual impact on safety, in that part of the safety functions of both off-site power sources was impacted. The issue was evaluated by the inspectors, through discussion with a senior reactor analyst, to be of very low risk significance. All events resulting in the abnormal electrical distribution configuration lasted less than 12 hours, and the critical busses remained energized without the need for emergency power (Section 1R04.1).

Inspection Report# : [2001006\(pdf\)](#)

Significance: G Oct 05, 2002

Identified By: NRC

Item Type: FIN Finding

Green finding regarding an inadequate modification package which inadvertently de-energized control room equipment.

The unplanned loss of power to four effluent radiation monitors during the installation of a service water radiation monitoring system modification was considered to be a self-revealing finding. The modification package required lifting an energized lead to de-energize a portion of the old service water radiation monitoring system; however, due to errors made by design engineering, this step unintentionally de-energized four other effluent radiation monitors which were required to be operable per the Technical Requirements Manual. The finding was considered more than minor since the modification package required lifting energized leads in control room panels which could reasonably be viewed as a precursor to a significant event if not adequately controlled. The finding was characterized as having very low safety significance since the loss of the effluent monitors did not result in a release in excess of allowable limits.

Inspection Report# : [2002003\(pdf\)](#)

Significance: G Jun 22, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate measures to assure that accurate and conservative values were used to establish second level undervoltage relay setpoint.

The measures established by the licensee for the translation of design requirements were not adequate to assure that the values used to establish the second level undervoltage relay setpoint were accurate and conservative with respect to the technical specifications. In addition, the measures for promptly identifying and correcting the adverse condition were not adequate as demonstrated by the length of time this condition has existed (since 1987). The failure to accurately translate design requirements was a violation of Criterion III of Appendix B to 10 CFR Part 50, and the untimely corrective actions was a violation of Criterion XVI of Appendix B to 10 CFR Part 50. This violation is noncited in accordance with Section VI.A of NRC's Enforcement Policy, and is in the licensee's corrective action program (Notification 10092429). (Section 1R21.5.b.1.) The finding was of very low safety significance because, although the calculated values were not conservative and were not consistent with the technical specification values, there were administrative procedures in place to prevent exceeding the correct analytical limit. Additionally, there was no actual loss of safety function.

Inspection Report# : [2001005\(pdf\)](#)

Significance: N/A Apr 03, 2001

Identified By: NRC

Item Type: URI Unresolved item

Potential Unreviewed Safety Question Related to Off-Site A/C Sources

IR 05000298-00-15; 12/31/2000-03/31/2001; Nebraska Public Power District; Cooper Nuclear Station. Integrated Resident/Regional Report; Safety Eval. Prog., Heat Sink Perf., Personnel Perf. During Nonroutine Plant Evolutions, Postmaintenance Testing, and Physical Security Plan. The inspectors identified that the 161 kV Auburn, Nebraska, line has never been analyzed and accepted as a General Design Criteria 17 qualified offsite ac power source. The original design basis had the power source transferred from the 345 kV/161 kV startup station service transformer to the 69 kV emergency transformer upon a loss of the 345 kV source. This issue is considered to be an unresolved item awaiting additional technical evaluation by the licensee and the NRC (1R02).

Inspection Report# : [2000015\(pdf\)](#)**Significance:** Mar 31, 2001

Identified By: NRC

Item Type: FIN Finding

Plant operators failed to properly control plant transients during a normal reactor shutdown.

IR 05000298-00-15; 12/31/2000-03/31/2001; Nebraska Public Power District; Cooper Nuclear Station. Integrated Resident/Regional Report; Safety Eval. Prog., Heat Sink Perf., Personnel Perf. During Nonroutine Plant Evolutions, Postmaintenance Testing, and Physical Security Plan. Plant operators failed to properly control plant transients during a normal reactor shutdown. Improper operator actions, to control reactor vessel level, could have produced a loss of feed initiating event (Section 1R14). The inspectors determined the event was of very low safety significance using the guidance of Inspection Manual Chapter 0609. The inspectors noted that Reactor Feed Pump A remained available, other emergency core cooling system equipment was capable of injecting, and that the length of the transient was only slightly more than an hour.

Inspection Report# : [2000015\(pdf\)](#)**Significance:** May 13, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO FOLLOW MAINTENANCE PROCEDURES

IR05000298-00-06; on 04/02-5/13/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Rule and Health Physics. On two occasions, maintenance personnel failed to follow maintenance procedures when working on a control rod drive flow control valve. Maintenance workers failed to perform a specified step of a work order. As a result, the control rod subsequently operated at approximately 3 times normal rod speed. Planners also deleted a postmaintenance test that would have verified the rod's speed. The planners did not follow maintenance procedures that required work order revision approval for such changes. Both examples were in violation of Technical Specification 5.4.1(a) that requires written procedures to be established, implemented, and maintained. The licensee documented these issues in their corrective action process as Resolved Condition Report 2000-0046 and Resolved Condition Report 2000-0061, respectively. This noncited violation was characterized as a "green" finding using the significance determination process. The increased control rod speed had very low significance because reactor engineers demonstrated that excess margins were available to thermal limits during all times that the control rod was able to be moved.

Inspection Report# : [2000006\(pdf\)](#)**Significance:** May 13, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INAPPROPRIATE USE OF TECHNICAL SPECIFICATION LCO

IR05000298-00-06; on 04/02-5/13/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Rule and Health Physics. Licensed operators armed and withdrew Control Rod 42-19, after determining that the rod was inoperable, in violation of Technical Specification 3.1.3. The rod had exhibited excessive rod speed during a reactor startup. Technical Specification 3.1.3 requires that an inoperable control rod be fully inserted and disarmed. Operators inappropriately applied the permissive of Technical Specification 3.0.5 to manipulate the control rod for troubleshooting and rod speed adjustment. Technical Specification 3.0.5 permits testing of equipment solely to determine operability following corrective maintenance. The licensee documented these issues in their corrective action process as Resolved Condition Report 2000-0046 and Resolved Condition Report 2000-0061, respectively. This noncited violation was characterized as a "green" finding using the significance determination process. The increased control rod speed had very low safety significance because reactor engineers demonstrated that excess margins were available to thermal limits during all times that the control rod was able to be moved.

Inspection Report# : [2000006\(pdf\)](#)

Significance:  Apr 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

APPENDIX R LIGHTING INADEQUATE

The inspectors identified a failure to provide required emergency lighting for the access and egress route to the service water pumps. The vestibule area outside the service water pump room did not have an emergency light. This issue had low safety significance. Operations personnel could have taken compensatory measures to gain access to the room without lighting

Inspection Report# : [2000004\(pdf\)](#)

Significance:  Nov 20, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

MAINTENANCE WORKERS FAILED TO PROPERLY IMPLEMENT A MAINTENANCE PROCEDURE, RESULTING IN THE UNPLANNED LOSS AND SWITCHING OF A VITAL BUS (SECTION 1R03)

Maintenance workers failed to properly implement a maintenance procedure, resulting in the unplanned loss and switching of a vital bus. The inspectors concluded that worker failure to properly implement a maintenance procedure, resulting in the unplanned loss of a vital bus, was a violation. This loss of the vital bus was characterized as having low safety significance based upon the significance determination process review for reactor safety. Deenergizing the essential bus made the equipment powered from this bus unavailable for mitigation of an accident. However, redundant equipment was continuously operable from another essential bus, and the deenergized bus automatically transferred and reenergized within approximately 2 seconds. We are treating this violation as a noncited violation, consistent with the Interim Enforcement Policy for pilot plants. Operations personnel documented this in their corrective action process as Significant Condition Report 99-0746.

Inspection Report# : [1999014\(pdf\)](#)

Mitigating Systems

Significance:  Jul 12, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to adequately document environmental qualification of safety-related equipment

The licensee failed to identify and correct deficient documentation supporting environmental qualification of safety-related equipment in the steam tunnel and acceptable voltage applications for Buchanan 0241 terminal blocks. These findings were determined to be two examples of a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notifications 10163954 and 10167990. This finding also had crosscutting aspects associated with problem identification and resolution. This finding was determined to have a credible impact on safety because there was no assurance that the equipment would perform its design function during accident conditions since it was not operating in a previously tested or analyzed configuration. This noncited violation was characterized under the significance determination process as having very low safety significance based on the performance of an acceptable analysis that demonstrated the affected equipment was environmentally qualified.

Inspection Report# : [2002002\(pdf\)](#)

Significance:  Jul 12, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to apply required design control measures for a change to the service water system

The licensee failed to conduct required design control measures prior to implementing a design change in the service water system, in which a coating previously not evaluated was applied to the internal surface of several pipe riser columns. This was identified as a violation of Criterion III of Appendix B to 10 CFR Part 50, "Design Control." This finding is characterized under the significance determination process as having very low safety significance because there was no loss of function in the service water system. Because of the very low safety significance and because the licensee included the item in their corrective action program as Notification 10156239, this violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy.

Inspection Report# : [2002002\(pdf\)](#)

Significance: May 25, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate procedure for diesel fuel oil day tank low level alarms

Technical Specification 5.4.1(a) requires that the licensee establish, implement, and maintain written procedures recommended in Regulatory Guide 1.33, Revision 2, Appendix A, February 1978. Appendix A recommends procedures for abnormal, off normal, or alarm conditions. The inspectors concluded that the guidance contained in the alarm response procedure for a diesel generator fuel oil day tank low level alarm was inadequate. Specifically, the procedure directed operators to perform incorrect actions under a postulated condition that could have resulted in both diesel generators being inoperable. This was determined to be a violation of Technical Specification 5.4.1(a). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue was entered into the licensee's corrective action program as Notification 10163642. This finding was considered to have a potential impact on safety since the inadequate procedure could result in the failure of both diesel generators following a loss of one diesel fuel oil transfer pump. This finding was characterized by the significance determination process as having very low safety significance since credit for recovery was given, based on fuel consumption rates and adequate procedures to monitor fuel consumption if both diesels were running.

Inspection Report# : [2002008\(pdf\)](#)

Significance: N/A May 03, 2002

Identified By: NRC

Item Type: FIN Finding

Implementation of an improper validation process for biennial written requalification examinations

IR 05000298-02-06; Nebraska Public Power District; on April 29-May 3, 2002; Cooper Nuclear Station; supplemental inspection for a "White" inspection finding applicable to the mitigating systems cornerstone in the reactor safety strategic performance area. The inspection was conducted by two regional specialist inspectors. No findings were identified. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000. The U.S. Nuclear Regulatory Commission (NRC) performed this supplemental inspection to assess the licensee's evaluation associated with a compromise in the integrity of written requalification examinations and a failure of the corrective action process to adequately evaluate the requalification examinations for the effects of the compromise. This performance issue was previously characterized as having low to moderate risk significance ("White") in NRC Inspection Report 50-298/01-12. During this supplemental inspection, performed in accordance with Inspection Procedure 95001, the inspectors determined that the licensee performed a comprehensive root cause evaluation, determined the extent of condition, and developed appropriate corrective actions. The licensee identified the primary root cause of the examination compromise issue to be requalification examination program procedure inadequacies and examination process problems. The licensee also identified two additional contributing causes for this event, which involved a failure to take appropriate corrective actions when the compromise was originally identified in July 2000 and involved changes made to the examination validation process by a new training staff. The inspectors determined that the extent of condition involved only the year 2000 requalification examinations and did not extend to prior years. To assure that the licensed operating staff was qualified and that their corrective actions were effective, the inspectors noted that the licensee conducted their biennial written requalification examinations in January 2002 rather than July 2002. The examinations were developed in accordance with NUREG-1021, "Operating Licensing Examination Standards for Power Reactors." The method by which the licensee validated the examinations maintained the integrity of the examinations. Given the licensee's acceptable performance in addressing the requalification examination issue, the White finding associated with this issue

will only be considered in assessing plant performance for a total of four quarters in accordance with the guidance in Inspection Manual Chapter 0305, "Operating Reactor Assessment Program." With the exception of corrective actions involving training procedure revisions, all corrective actions had been implemented. These training procedures are routinely reviewed during inspections performed as a part of the baseline inspection program.

Inspection Report# : [2002006\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Noncompliance of safety relief valves with 10 CFR 50.49 requirements

The licensee failed to maintain the safety relief valve solenoids in an environmentally qualified condition. The solenoid-operated pilot valve terminal boards and connections were not maintained consistent with the tested configuration. Specifically, conformal coating did not completely cover the electrical connections and the installation of insulated lugs deviated from the tested configuration. This was determined to be a violation of 10 CFR Part 50.49(f). This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10123606. This issue was considered to have a credible impact on safety in that, if the equipment is not in a previously tested configuration, there is no assurance that the equipment will perform its design function during accident conditions. This noncited violation was characterized under the significance determination process as having very low safety significance because the safety relief valve solenoids were later tested to demonstrate they would perform their design function during accident conditions.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to identify and correct a condition adverse to quality

The licensee failed to identify and correct a condition adverse to quality. On October 3 and 23, 2001, the licensee identified two other areas in the service water system SW-F11 function that exceeded ASME B31.1 minimum pipe wall thickness requirements prior to being replaced. The licensee failed to implement effective corrective actions, resulting in the SW-F11 function exceeding ASME minimum pipe wall thickness. This was determined to be a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10144722. This issue was considered to have a credible impact on safety in that the failure of the service water piping boundary would potentially cause a serious degradation of the ultimate heat sink capability. This noncited violation was characterized under the significance determination process as having very low safety significance, because the licensee had replaced all segments of piping that contained pin hole leaks and those areas where minimum pipe wall thickness exceeded the performance criteria did not exceed the design allowable stresses.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform an operability evaluation and/or declare equipment inoperable

The licensee failed to perform an operability evaluation and/or declare equipment inoperable after identifying that the reactor equipment cooling system was not analyzed for a loss of coolant accident. This was determined to be a violation of Technical Specification 5.4.1(a). This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notification 10147885. The inspectors also considered this noncited violation had crosscutting aspects associated with problem identification and resolution. This issue was determined to have a credible impact on safety because the reactor equipment cooling system was not evaluated as being able to perform its cooling functions, including support for

emergency core cooling systems, during accident conditions. This noncited violation was characterized under the significance determination process as having very low safety significance because the licensee subsequently performed an operability evaluation that demonstrated the system could perform all its design basis functions.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to evaluate piping in accordance with 10 CFR 50.55 (a)(3)

The licensee failed to adequately evaluate localized areas of erosion and corrosion of the service water system in accordance with 10 CFR Part 55a(a)(3). Specifically, the licensee used an alternative method, not approved for use as required by 10 CFR 50.55a(a)(3), to evaluate localized areas of wall thinning of the service water system piping. This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notification 10140024. This issue was determined to have a credible impact on safety in that the failure to properly evaluate piping, in accordance with approved methods, could result in piping being below minimum code acceptable thickness. This noncited violation was characterized under the significance determination process as having very low safety significance. The licensee replaced all segments of piping that were potentially outside code requirements during the refueling outage starting in November 2001. Those segments of piping not replaced were subsequently evaluated to meet code requirements using an approved method.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to implement effective corrective actions

The inspectors determined the licensee failed to implement effective corrective actions after identifying that changes in river temperatures adversely affected service water pump impeller clearances. The ineffective corrective actions resulted in Service Water Pump D failing on December 26, 2002. The failure to identify and correct this significant condition adverse to quality is a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notification 10132527. This issue also had crosscutting aspects associated with problem identification and resolution. This issue was determined to have an actual impact on safety in that the failure to properly maintain the appropriate impeller clearances resulted in pump failure. This NCV was characterized under the significance determination process as having very low safety significance. The service water system is a two-train system, with each train containing two full capacity pumps. Therefore, the loss of a single pump did not disable the design function of the service water system.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Jan 03, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to follow procedure resulting in a fire

The licensee failed to ensure that combustible material was removed or protected from hot work resulting in a fire on November 26, 2001, located in the reactor building on the torus area floor. This was determined to be a violation of Technical Specification 5.4.1.d. This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10126869. This issue was determined to have a credible impact on safety because an actual fire inside the reactor building occurred. This noncited violation was characterized under the significance determination process as having very low safety significance because the fire was quickly identified and extinguished, and the fire did not, and could not affect any equipment necessary for maintaining safe shutdown conditions. Specifically, the reactor cavity was

flooded to greater than 23 feet, the spent fuel pool gates were open, a division of shutdown cooling was operable, and emergency core cooling system instrumentation was not affected.

Inspection Report# : [2001007\(pdf\)](#)

Significance: G Jan 03, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Licensee personnel inappropriately removed seismic restraint/pipe support from an operable and running service water piping system

On November 15, 2001, the licensee identified that personnel had inappropriately removed a seismic restraint/pipe support (SW-H138) from an operable and running service water piping system. This was determined to be a violation of Technical Specification 5.4.1(a). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10123800. The safety significance of this violation was determined to be very low. Although the operators declared the service water system inoperable, the removal of the support hanger did not affect the service water system from performing its function to maintain the plant in a safe shutdown condition. Specifically, the reactor cavity was flooded to greater than 23 feet, the spent fuel pool gates were open, a division of shutdown cooling was operable, and emergency core cooling system instrumentation was not affected. Additionally, the section of piping affected was immediately isolated following discovery of the missing hanger until repairs were performed.

Inspection Report# : [2001007\(pdf\)](#)

Significance: G Jan 03, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Licensee personnel inappropriately racked out the Residual Heat Removal Pump B breaker

On November 9, 2001, the licensee identified that, during performance of a tagout, personnel inappropriately racked out the Residual Heat Removal Pump B breaker. This was determined to be a violation of Technical Specification 5.4.1 (a). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10122626. The safety significance of this violation was determined to be very low. Residual Heat Removal Pump B was not in use when the breaker was removed and did not affect the ability to maintain the plant in a safe shutdown condition. Specifically, the reactor cavity was flooded to greater than 23 feet, the spent fuel pool gates were open, a division of shutdown cooling was operable, and emergency core cooling system instrumentation was not affected. Additionally, the removal of the wrong breaker was immediately identified by the licensee and it was returned to service within 1 hour.

Inspection Report# : [2001007\(pdf\)](#)

Significance: G Jan 03, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to identify and correct 10 CFR 50.49 requirements associated with safety-relief valve cables

The licensee failed to identify and correct a condition adverse to quality. Power cables to the safety-relief valve solenoid valves were not maintained in conformance with 10 CFR 50.49 requirements from 1995 through October of 2001. The licensee had several opportunities to identify and correct this condition from April 2000 to October 2001. This was determined to be a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10092693. This finding was more than minor because, if left uncorrected, it would have posed a more significant issue. This noncited violation was characterized under the significance determination process as having very low safety significance because the safety-relief valves were later determined to have been qualified.

Inspection Report# : [2001007\(pdf\)](#)

Significance: N/A Dec 18, 2001

Identified By: NRC

Item Type: FIN Finding

Numerous examples of inadequate corrective actions and improper implementation of the corrective action program demonstrated a continued trend of inadequate problem identification and resolution.

Numerous examples of inadequate corrective actions and improper implementation of the corrective action program demonstrated continued inadequate problem identification and resolution. This was primarily due to a general lack of understanding and ownership of site-wide programs and procedures associated with the identification and resolution of problems. Each of the program areas discussed below include violations of NRC requirements that were determined to be more than minor but of very low safety significance (Green) using the significance determination process. The licensee documented this issue in their corrective action process as Notification 10112315, which is being addressed in Significant Condition Report 2001-0938, "Continued Difficulty in Implementing the Corrective Action Program." For example: The team identified that during the implementation of the corrective action program issues were improperly characterized and classified resulting in those issues being inappropriately removed from the corrective action program. This resulted in ineffective and untimely corrective actions since the items were either closed or awaiting resolution. This issue is described in this report and involves both the mitigating systems and barrier integrity cornerstones of reactor safety. Numerous concerns with scaffolds constructed near operable safety-related equipment were identified. The licensee had not constructed scaffolding in accordance with plant procedures and the required scaffolding engineering evaluations for nonconforming items had not been performed. Previous similar findings associated with improper scaffolding had been identified in NRC Inspection Report 50-298/00-04. Despite corrective actions involving new procedures and training, similar problems continued. The licensee had not effectively corrected problems with personnel recognizing when and how to perform adequate operability determinations and evaluations. A noncited violation was identified, which involved examples from both the mitigating system and barrier integrity cornerstones. This cross-cutting issue was documented in the previous NRC problem identification and resolution inspection and other similar findings associated with this cross-cutting issue are noted in NRC Inspection Reports 50-298/00-10, 50-298/00-13, 50-298/00-14, and 50-298/01-02.

Inspection Report# : [2001010\(pdf\)](#)

Significance: G Dec 18, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Ineffective corrective actions related to the scaffold control program

The licensee failed to correct a previously identified problem in the construction and control of scaffolding in accordance with Procedure 7.0.7, "Scaffolding Construction and Control." During a plant walkdown with operators, the team identified numerous examples where scaffolding was constructed in close proximity or attached to operable safety-related equipment, which did not satisfy requirements contained in Procedure 7.0.7. Many of these nonconformances identified by the team had not been evaluated by engineering, as required by Procedure 7.0.7. The licensee subsequently performed additional walkdowns and a total of 47 scaffolding configuration nonconformances were identified. Each nonconformance was evaluated by engineering and, although no operability issues were identified, 11 nonconformances had to be corrected. This 10 CFR Part 50, Appendix B, Criterion XVI, corrective action violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy. The issue was placed in the licensee's problem identification and resolution program as Notification 10111303. The issue of inadequate implementation of the scaffolding construction and control program was more than minor because it involved a credible impact on safety, in that, numerous scaffolding configuration discrepancies were identified with construction of scaffolding on and in close proximity to operable safety-related systems, structures, or components. The team concluded that this issue was of very low safety significance (Green) using the significance determination process because an actual impact on safety systems did not occur.

Inspection Report# : [2001010\(pdf\)](#)

Significance: G Dec 18, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to properly classify issues in the licensee's Problem Identification and Resolution program that resulted in ineffective corrective actions

Issues had not been classified properly in accordance with Licensee Procedure 0.5.CLSS, "Classification of Problem Identification Reports (PIRs)." Some of these issues were inappropriately removed from the problem identification and resolution program when they should have remained. The improper classification contributed to a lack of prompt corrective actions. These examples were contrary to 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action." This issue was placed in the licensee's problem identification and resolution program as Notification 10113236. This violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy (Section 4OA2.b). Two examples included: Reactor building equipment cooling flow control valves located downstream of the drywell fan coil units were changed from a throttled to fully open position in December 1995. In October 2000, the licensee identified that the procedure change for the valve positions had an inadequate engineering review and that estimated actual flow through the cooling coils was significantly greater than rated flow for the coolers. The issue was downgraded and removed from the corrective action program in November 2000, and reclassified as an "OTHER NAIT" work item with approval from the licensee's condition review group. According to Procedure 0.5.CLSS, Revision 1, a classification of "OTHER" applied to any condition that requires correction by a process outside of the corrective action program that does not represent an actual or potential condition or significant condition adverse to quality (significant condition report or resolve condition report level of classification). After questions were raised by the team, the licensee subsequently estimated the flow rates and determined analytically that the high flow condition was acceptable. The licensee documented this issue in their corrective action process as Notification 10114113. This issue of conducting changes to the facility without adequate engineering documentation was more than minor because it involved a credible impact on safety, in that, the procedure change permitted plant operation with flow in excess of rated capacity without an evaluation of the impact the increased erosion would have on primary containment integrity. This issue was evaluated using the significance determination process and was determined to be of very low safety significance (Green) because the finding did not represent an actual open pathway in the physical integrity of reactor containment. On August 21, 2001, emergency transformer secondary voltage exceeded 4600 volts (4615 volts). Emergency transformer secondary voltage is normally maintained between 4435 and 4575 volts to ensure that under full load conditions, emergency bus voltage can be maintained near its nominal voltage of 4160 volts. Operators referred to Station Operating Procedure 2.2.17, "Emergency Station Service Transformer (ESST)," but they failed to recognize that secondary voltage exceeded the operability limit of 4600 volts listed in the procedure and subsequently failed to declare the emergency station service transformer inoperable. Notification 10105501 was written, but was subsequently removed from the corrective action program by being classified as a "Department Disposition" item. The team concluded that the licensee should have placed this deficiency in the corrective action program as a "Resolve Condition Report - Apparent Cause" in accordance with Procedure 0.5.CLSS, Revision 5. The licensee documented this issue in their corrective action process as Notification 10112753. Had the transformer been loaded during this overvoltage condition, it could have affected the function of a safety-related power supply; therefore, this issue was more than minor because it involved a credible impact on safety. This condition could have a credible impact on the availability and reliability of the onsite electrical power system. The condition was determined to be of very low safety significance (Green) since operators never placed the emergency station service transformer in service.

Inspection Report# : [2001010\(pdf\)](#)



Significance: G Dec 18, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failures to follow required procedures were identified when operability determinations were not performed or issues were not considered for their impact on the plant.

Two examples of a failure to follow procedure were identified, which involved failure to perform operability evaluations, as required by Procedure 0.5.OPS, "Operations Review of Problem Identification Reports/Operability Determinations/ Evaluations," Revision 7. Failure to follow Procedure 0.5 OPS was a violation of Technical Specification 5.4.1.a. This violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy (Section 4OA2.a). Two examples included: On August 28, 2001, operators placed the electrical distribution system in a configuration that rendered both offsite power circuits inoperable, but did not declare them inoperable or enter a limiting condition for operation, as required by their technical specifications. The team determined that this configuration would not allow both offsite circuits to auto-transfer to both critical buses, as described in the Updated Safety Analysis Report. The licensee failed to evaluate operability for a degraded condition

that affected the function of an offsite power circuit. This issue was documented as Notification 10109209. This issue was considered to have an actual impact on safety, in that, part of the safety functions of both offsite power sources was impacted. The issue was evaluated using the significance determination process by the team and a senior reactor analyst, to be of very low safety significance (Green). The abnormal electrical distribution configuration lasted less than 12 hours, and the critical buses remained energized without the need for emergency power. On September 7, 2001, the licensee lost both offsite power sources because of lightning strikes. On September 13, 2001, line crews conducting tests in the 345 kV switchyard found a failed relay, which improperly allowed the T2 auto-transformer to isolate. The licensee failed to recognize that the switchyard did not operate as designed and, therefore, failed to evaluate the failed relay's impact on operability. The licensee documented this deficiency in Notification 10109324. This issue was considered to have an actual impact on safety, in that, a defective relay caused the fault on a non-qualified offsite power source to trip a qualified source. The team and a senior reactor analyst reviewed the loss-of-offsite power initiators and accidents. The issue was evaluated using the significance determination process by the team and a senior reactor analyst, to be of very low safety significance (Green), since this issue did not significantly increase the likelihood of a loss-of-offsite power/loss-of-coolant accident scenario.

Inspection Report# : [2001010\(pdf\)](#)



Significance: G Dec 18, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Ineffective corrective actions related to operability determinations/evaluations

The licensee failed to correct a previously identified problem associated with conducting adequate operability determinations/evaluations. The NRC problem identification and resolution inspection (50-298/00-10), conducted August 2000, identified multiple examples of a failure to perform operability determinations and evaluations, as required by Administrative Procedure 0.5 OPS, "Operations Review of Problem Identification Reports/Operability Determinations/Evaluations." Subsequently, a substantive cross-cutting finding of inadequate human performance was identified in NRC Inspection Report 50-298/00-13, associated with failure to implement the problem identification program in the area of operability determinations/evaluations. Numerous additional noncited violations associated with inadequate operability determinations/ evaluations were identified in NRC Inspection Reports 50-298/00-14 and 50-298/01-02. These repeat findings from past inspections combined with two additional examples associated with reactor building equipment cooling flow and an unrecognized overvoltage condition on the emergency station service transformer collectively reflect inadequate corrective actions and a continued programmatic problem. This 10 CFR Part 50, Appendix B, Criterion XVI, corrective action violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy. The licensee wrote Notification 10112315 to address this violation. This issue was more than minor because it involved a credible impact on safety, in that, failing to recognize when degraded structures, systems, or components require an operability determination or evaluation could result in continued operation of the facility when plant technical specifications would require a shutdown. This issue was determined to have very low risk significance (Green) because the systems remained operable in the examples identified or each specific example had been previously addressed by the NRC's significant determination process at this level.

Inspection Report# : [2001010\(pdf\)](#)



Significance: W Dec 03, 2001

Identified By: NRC

Item Type: VIO Violation

Licensed operator requalification written examination compromise involving a violation of 10 CFR 55.49

Final SDP letter sent on March 26, 2002 The licensee had compromised their 2000 Biennial Requalification Written Examinations. This constitutes a violation of 10 CFR Part 55.49 for engaging in activities, which compromised the integrity of an examination. The finding was evaluated as having low to moderate safety significance because after identification of the compromise, the corrective action process (compensatory actions) failed to adequately evaluate the requalification examinations for the effects of the compromise. Had the licensee performed a detailed question analysis and regraded the requalification examinations by removing those questions where compromise was indicated, at least two licensed operators would have failed instead of receiving their original passing grade. Subsequently, at least two operators were returned to licensed duties without completion of the required retraining and testing for having failed

the examination. 5/29/02 Supplemental Inspection (95001) NRC Report 50-298/02-06 The U.S. Nuclear Regulatory Commission (NRC) performed this supplemental inspection to assess the licensee's evaluation associated with a compromise in the integrity of written requalification examinations and a failure of the corrective action process to adequately evaluate the requalification examinations for the effects of the compromise. This performance issue was previously characterized as having low to moderate risk significance ("White") in NRC Inspection Report 50-298/01-12. During this supplemental inspection, performed in accordance with Inspection Procedure 95001, the inspectors determined that the licensee performed a comprehensive root cause evaluation, determined the extent of condition, and developed appropriate corrective actions. The licensee identified the primary root cause of the examination compromise issue to be requalification examination program procedure inadequacies and examination process problems. The licensee also identified two additional contributing causes for this event which involved a failure to take appropriate corrective actions when the compromise was originally identified in July 2000 and involved changes made to the examination validation process by a new training staff. The inspectors determined that the extent of condition involved only the year 2000 re-qualification examinations and did not extend to prior years. To assure that the licensed operating staff was qualified and that their corrective actions were effective, the inspectors noted that the licensee conducted their biennial written requalification examinations in January 2002 rather than July 2002. The examinations were developed in accordance with NUREG-1021, Operating Licensing Examination Standards for Power Reactors. The method by which the licensee validated the examinations maintained the integrity of the examinations. Given the licensee's acceptable performance in addressing the requalification examination issue, the white finding associated with this issue will only be considered in assessing plant performance for a total of four quarters in accordance with the guidance in IMC 0305, "Operating Reactor Assessment Program." With the exception of corrective actions involving training procedure revisions, all corrective actions had been implemented. These training procedures are routinely reviewed during inspections performed as a part of the baseline inspection program.

Inspection Report# : [2001012\(pdf\)](#)



Significance: G Oct 19, 2001

Identified By: NRC

Item Type: FIN Finding

Two of seven simulator operating test crew failures occurred during the 2000 annual requalification operating test.

During the 2000 Annual Operator Requalification Operating Test, two out of seven total crews failed the dynamic simulator portion of their operating test. The safety significance of this finding was very low because the overall crew failure rate was less than 34 percent, the crews were not performing licensed duties, and the failed crews were appropriately retrained and retested prior to being returned to licensed duties.

Inspection Report# : [2001012\(pdf\)](#)



Significance: G Oct 04, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

Inappropriate corrective actions of the primary containment isolation valve function exceeded the licensee's established goal for repeat maintenance preventable functional failures

Green. The licensee failed to demonstrate that performance of radwaste primary containment isolation valves was being effectively controlled through the performance of appropriate preventive maintenance in that repetitive failures of the valves occurred that were not prevented by preventive or corrective maintenance. This was determined to be a violation of 10 CFR 50.65 (a)(2). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action program as Notification 10095968. This issue was determined to have a credible impact on safety because the failure of these valves to operate properly affected the ability to isolate primary containment. This noncited violation was characterized under the significance determination process as having very low safety significance because there was no occurrence in which the inboard and outboard primary containment isolation valves failed concurrently. Therefore, no actual open pathway affecting the physical integrity of the primary containment was present (Section 1R12.1).

Inspection Report# : [2001006\(pdf\)](#)

Significance:  Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Loose bolts on the Division 1 diesel generator jacket water heat exchanger

Technical Specification 5.4.1(a) requires that the licensee establish, implement, and maintain written procedures recommended in Regulatory Guide 1.33, Revision 2, Appendix A, February 1978. Appendix A recommends procedures for performing maintenance. On September 11, 2001, the licensee identified that 7 out of 12 bolts were loose on the Division 1 diesel generator jacket water heat exchanger. The licensee's root cause evaluation determined the failure to establish an adequate maintenance procedure resulted in the condition. This is being treated as a noncited violation. The licensee entered this issue into the corrective action process as Resolve Condition Report 2001-0868.

Inspection Report# : [2001006\(pdf\)](#)

Significance:  Oct 05, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Noncited violation of License Condition 2.C.(4) for failure to maintain operability of a fire suppression system.

The licensee failed to identify and correct degraded spray shields associated with sprinkler heads on Sprinkler System 29 in the cable expansion room which provides fire protection for cable trays containing redundant divisions of safety-related cables. The spray shields were identified as having holes in them which would result in decreasing the effectiveness of the shields. This was a violation of License Condition 2.C.(4). This finding had crosscutting aspects associated with problem identification and resolution since the licensee had multiple opportunities to identify and correct this condition but failed to do so. This finding was more than minor since failure of this system during a fire would have adversely impacted the availability, reliability, and capability of systems that respond to an initiating event. The finding was characterized under the significance determination process as having very low safety significance since the alternate shutdown capability was unaffected and due to the low fire ignition frequency for the cable expansion room. Because of the very low safety significance and because the licensee entered the item in their corrective action program as Notification 10190964, this violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy.

Inspection Report# : [2002003\(pdf\)](#)

Significance:  Oct 05, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

A noncited violation for failure to correct a procedure deficiency which affected the operability of the high pressure coolant injection system.

The licensee failed to take corrective actions for a surveillance test procedure that rendered the high pressure coolant injection system and the reactor core isolation cooling system concurrently inoperable. The procedural error was identified by the licensee in 1998 but no action was taken due to an incorrect conclusion that the procedure did not actually render the high pressure core injection system inoperable. When this question was addressed again in 2002, the licensee concluded that the system was, in fact, inoperable. This configuration was allowed by Technical Specifications; however, operators failed to recognize it as an entry condition into a shutdown action statement. No violation of the action statement was identified but the failure to recognize its entry condition was considered a condition adverse to quality. Therefore, this was considered to be a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This finding also had crosscutting aspects associated with problem identification and resolution. This finding was characterized under the significance determination process as having very low safety significance because the high pressure core injection system could have performed its safety function even though it was considered inoperable per Technical Specifications. The finding was more than minor since the procedural error had an adverse impact on the availability and capability of a mitigating system. Because of the very low safety significance and because the licensee included the item in their corrective action program as Notification 10193745, this violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy.

Inspection Report# : [2002003\(pdf\)](#)

Significance:  Oct 05, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

A noncited violation for failure to take corrective actions to prevent instrument line snubber clogging which caused a failure of the reactor core isolation cooling system.

The licensee failed to take corrective actions to prevent clogging of instrument line snubbers which resulted in the inadvertent isolation of the reactor core isolation cooling system on May 14, 2002. This was an apparent violation of 10 CFR Part 50, Appendix B, Criterion XVI. This finding also had crosscutting aspects associated with problem identification and resolution. This finding was characterized under the significance determination process as having very low safety significance based on the results of a Phase 3 analysis. The finding was more than minor since it had an adverse impact on the availability, reliability, and capability of a mitigating system. Because of the very low safety significance and because the licensee included the item in their corrective action program as Resolve Condition Report 2002-0895, this violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy.

Inspection Report# : [2002003\(pdf\)](#)

Significance:  Jul 10, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate procedures to ensure emergency core cooling systems filled with water.

The licensee failed to have adequate surveillance procedures in accordance with Technical Specification 5.4.1(a) to satisfy Technical Specification Surveillance Requirement 3.5.1.1, which verifies that all emergency core cooling systems (ECCS) are full of water. This noncited violation was evaluated under the risk significance determination process as being Green. The issue was determined to have a credible impact on safety because the potential existed for a system void not being properly evaluated. Also, extenuating circumstances were involved related to the degraded condition of the pressure maintenance system used to keep the residual heat removal (RHR) Loop A system filled with water. This issue was characterized as having very low safety significance because no systems were identified as being degraded by voiding (Section 1R22.1).

Inspection Report# : [2001002\(pdf\)](#)

Significance:  Jun 22, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to properly account for the static head in Calculation NEDC 92-050AT, "CM-PS-270 Setpoint Calculation," Revision 0.

The failure to properly account for the static head in Calculation NEDC 92-050AT, "CM-PS-270 Setpoint Calculation," Revision 0, resulted in the licensee adjusting Switch CM-PS-270, residual heat removal system, loop A keep fill system. The incorrect setting could have allowed a void in the keep fill line from being detected by the operators. This failure was a violation of Criterion III of Appendix B to 10 CFR Part 50. This violation is noncited in accordance with Section VI.A of NRC's Enforcement Policy, and is in the licensee's corrective action program (Notification 10089082). (Section 1R21.5.b.2.) The finding was of very low safety significance because there was no evidence that voids existed and, therefore, there was no actual loss of safety function.

Inspection Report# : [2001005\(pdf\)](#)

Significance:  Apr 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to install detectors as documented in the safety evaluation report which was not in accordance with 10 CFR 50.48(b).

IR 05000298/01-03; on 04/02-06/2001, onsite and 04/09-13/01, in-office; Cooper Nuclear Station; Triennial Fire Protection Inspection The team identified a noncited violation in three areas (control room, diesel generator room, and the 1001-foot elevation of the reactor building) in which the licensee failed to install detectors as documented in the safety evaluation report which was not in accordance with 10 CFR 50.48(b). This violation was entered into the licensee's corrective action program as Notification 10078580, 10078607, and 10078606. This finding was determined to be of very low safety significance due to the number of mitigating systems remaining.

Inspection Report# : [2001003\(pdf\)](#)



Significance:  Apr 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform calculations to ensure that the locations and conditions of fire areas did not require as much water as is discharged by nominal 1/2-inch orifice sprinkler . . .

IR 05000298/01-03; on 04/02-06/2001, onsite and 04/09-13/01, in-office; Cooper Nuclear Station; Triennial Fire Protection Inspection. The team identified that on October 20, 1985, the licensee implemented modification design change MDC 85-48 in which they replaced 1/2-inch diameter sprinkler heads with 1/4-inch diameter sprinkler heads in the reactor recirculation pump motor generator set lube oil pump area (958-foot elevation of the reactor building) and in the reactor recirculation pump motor generator lube oil pump area (976 foot elevation of the reactor building). The licensee failed to perform calculations to ensure that the reduction in the diameter of the sprinkler heads did not adversely affect the suppression requirements in these fire areas, as required by the National Fire Protection Association Code 13. This was not in accordance with 10 CFR 50.48(b). This violation was entered into the licensee's corrective action program as Notification 10073757. This finding was determined to be of very low safety significance, because there were no safe shutdown systems in the areas that could be affected by a postulated fire.

Inspection Report# : [2001003\(pdf\)](#)



Significance:  Apr 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide adequate emergency lighting to perform operator actions for safe shutdown.

IR 05000298/01-03; on 04/02-06/2001, onsite and 04/09-13/01, in-office; Cooper Nuclear Station; Triennial Fire Protection Inspection Green. The team identified a noncited violation in Fire Zone 7A (control room basement) in that emergency lighting was not aligned properly to adequately perform safe shutdown operator actions in accordance with Section III.J of Appendix R to 10 CFR Part 50. This violation was entered into the licensee's corrective action program as Notification 10076810. This finding was of very low safety significance because the operators would have available dedicated hand held lights that would assist them in performing required actions.

Inspection Report# : [2001003\(pdf\)](#)



Significance:  Apr 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide 20 feet separation between redundant service water equipment.

IR 05000298/01-03; on 04/02-06/2001, onsite and 04/09-13/01, in-office; Cooper Nuclear Station; Triennial Fire Protection Inspection Cornerstone: Mitigating Systems The team identified a noncited violation in Fire Zone 20A (service water pump room) in which equipment required for safe shutdown of the plant following a fire was not separated by 20 feet horizontal distance, and there were intervening combustibles (Rubatex insulation) that were not part of an exemption, nor included in the licensee's engineering evaluation. This was not in accordance with Section III.G.2(b) of Appendix R. This violation was entered into the licensee's corrective action program as Notification 10075408 and 10076323. This finding was of very low safety significance because the area-wide fire suppression and detection systems were not degraded, and the increase in combustible loading of the Rubatex insulation did not substantially increase the severity of a postulated fire in the fire area.

Inspection Report# : [2001003\(pdf\)](#)

Significance: Mar 31, 2001

Identified By: NRC

Item Type: FIN Finding

Testing of the residual heat removal heat exchangers may have resulted in an inaccurate estimation of their performance under design-basis conditions.

IR 05000298-00-15; 12/31/2000-03/31/2001; Nebraska Public Power District; Cooper Nuclear Station. Integrated Resident/Regional Report; Safety Eval. Prog., Heat Sink Perf., Personnel Perf. During Nonroutine Plant Evolutions, Postmaintenance Testing, and Physical Security Plan. Three elements for the testing of the residual heat removal heat exchangers may have resulted in an inaccurate estimation of their performance under design-basis conditions. The testing was often conducted under dynamic rather than stabilized thermal conditions, the testing was not conducted during the worst season for biological growth (and the design basis temperatures), and the testing was conducted after a flush of the heat exchanger that may have had the effect of improving the thermal performance (Section 1R07). The risk associated with the three anomalies in the testing of the residual heat removal heat exchangers was determined to be of very low safety significance because the cumulative effect was likely to be less than the available thermal performance margin. Additional factors that mitigated this concern were a recent change-out of valves in the service water system that reduced the standby leakage flow through the residual heat removal heat exchangers and a recently-initiated practice of running normal flow through the heat exchangers weekly for 30 minutes, both of which should have the effect of reducing the buildup of slime and scale.

Inspection Report# : [2000015\(pdf\)](#)

Significance: Mar 31, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to document and maintain a design standard for surge suppression varistors in the Division 2 Emergency Diesel control circuit.

IR 05000298-00-15; 12/31/2000-03/31/2001; Nebraska Public Power District; Cooper Nuclear Station. Integrated Resident/Regional Report; Safety Eval. Prog., Heat Sink Perf., Personnel Perf. During Nonroutine Plant Evolutions, Postmaintenance Testing, and Physical Security Plan. The inspectors identified a noncited violation for the failure to document and maintain a design standard, for surge suppression varistors in the Division 2 emergency diesel control circuit. The use of incorrect values for these components caused the generator to frequently trip during the shutdown process, and thereby be unavailable for immediate restart (Section 1R19). The noncited violation was of very low safety significance because this condition only affected one diesel, and the condition only affected its ability to do a hot restart immediately after a previous run. The time that a diesel is in this condition, compared to the standby condition, is very small. Therefore the probability of an actual demand for the diesel during these conditions was very low.

Inspection Report# : [2000015\(pdf\)](#)

Significance: Jan 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform operability determination and/or declare equipment inoperable

IR 05000298-00-14, on 11/5-12/30/2000, Nebraska Public Power District, Cooper Nuclear Station Integrated Resident/Regional Report. The inspectors determined that operations personnel did not perform an operability assessment for a safety-related service water pump, or declare the pump inoperable, when the functionality of the pump was questioned. The failure to perform an operability determination, as required by station procedure, is in violation of Technical Specification 5.4.1(a), for failure to follow Regulatory Guide 1.33, Appendix A, recommended procedures. This noncited violation was determined to have very low safety significance because the nature of the failure was determined, through subsequent testing, to not affect the safety function of the service water pump (Section 1R14).

Inspection Report# : [2000014\(pdf\)](#)

Significance:  Jan 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to properly implement a surveillance test procedure

IR 05000298-00-14, on 11/5-12/30/2000, Nebraska Public Power District, Cooper Nuclear Station Integrated Resident/Regional Report. This inspection report covers a 7-week period of inspection by the resident inspectors. While performing undervoltage testing on Division 1 4160V Essential Bus 1F, technicians failed to follow a procedural step, resulting in an unplanned plant transient. An inadvertent undervoltage signal caused the following loads to trip: Reactor Recirculation Pump A, Service Water Pump A, Control Rod Drive Pump A, and selected nonessential 480 volt motor control centers. The failure to implement a surveillance procedure is in violation of Technical Specification 5.4.1 (a), for failure to follow Regulatory Guide 1.33, Appendix A, recommended procedures. This noncited violation was determined to have very low safety significance based upon a significance determination process analysis of the equipment lost, performed by the regional senior reactor analyst. The event lasted only 4 to 5 minutes, with one train of emergency core cooling systems remaining operable for the entire period (Section 1R22).

Inspection Report# : [2000014\(pdf\)](#)

Significance:  Jan 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to maintain design control for service water system

IR 05000298-00-14, on 11/5-12/30/2000, Nebraska Public Power District, Cooper Nuclear Station Integrated Resident/Regional Report. This inspection report covers a 7-week period of inspection by the resident inspectors. The inspectors identified a lack of design control for service water pump bolting standards after operators reported finding loose foundation nuts. Conflicting information regarding the use of washers for the service water pump foundation bolts was provided in design documents. This is in violation of Criterion III of 10 CFR Part 50, Appendix B, for improper design control. This noncited violation was determined to have very low safety significance because there would be no loss of service water function, based upon the remaining foundation bolts being properly fastened and the licensee's seismic analysis for the loose bolts (Section 1R04).

Inspection Report# : [2000014\(pdf\)](#)

Significance:  Dec 14, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Implement Design Requirements

Cooper Nuclear Station NRC Inspection Report 50-298/00-07 This special inspection report covered the activities associated with inspection and assessment of environmental qualification issues. Plant personnel failed to identify problems with the environmental qualifications program until they were specifically characterized by the NRC. Plant personnel also failed to identify problems with equipment that did not meet program requirements during field walkdowns. In addition, plant personnel failed to enter self-identified deficiencies, in the environmental qualifications program, into the corrective action program. These failures to properly identify problems and enter them into the corrective actions process constituted an apparent violation of 10 CFR Part 50, Appendix B, Criterion XVI (Section 02.04) This item was originally opened as an apparent violation but later closed per letter from Nebraska Public Power District dated November 8, 2001, Reference #NLS2001104, and reopened and closed as a noncited violation. This apparent violation was closed by letter from Nebraska Public Power District to NRC dated November 8, 2001, Reference #NLS2001104. It was opened and closed as an NCV by same letter.

Inspection Report# : [2000007\(pdf\)](#)

Significance: SL-IV Dec 14, 2000

Identified By: NRC

Item Type: VIO Violation

Failure to Maintain Environmental Qualifications of Safety-Related Equipment

Cooper Nuclear Station NRC Inspection Report 50-298/00-07 This special inspection report covered the activities associated with inspection and assessment of environmental qualification issues. The failures to environmentally qualify, maintain the qualification of, and document qualifications in an auditable form, for equipment important to safety, constituted an apparent violation of 10 CFR 50.49 (Section 2.02). This item was originally opened as an apparent violation in IR 00-07. It was later closed per letter from Nebraska Public Power District dated November 8, 2001, Reference #NLS2001104 and reopened as a violation, Severity Level IV.

Inspection Report# : [2000007\(pdf\)](#)

Significance: Nov 04, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO ESTABLISH, IMPLEMENT, AND MAINTAIN PROCEDURES FOR THE OFF-SITE AC POWER CIRCUITS

IR 05000298-00-13; on 9/24-11/04/2000; Nebraska Public Power District; Cooper Nuclear Station, Integrated Resident & Regional Report. Maintenance Rule Effectiveness. On August 24, 2000, engineering and maintenance personnel performed a temporary modification in the 345/161Kv switchyard. The licensee provided temporary power to auxiliary circuits for control power to off-site ac circuit breakers. The inspectors identified that the licensee had not established procedures for the operation and maintenance of off-site access circuits. The failure to establish, implement, and maintain Regulatory Guide 1.33, Appendix A, recommended procedures, was a violation of Technical Specification 5.4.1(a). This noncited violation was determined to have very low safety significance because the minimum required number of offsite circuits remained available at all times (Section 1R23).

Inspection Report# : [2000013\(pdf\)](#)

Significance: Nov 04, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PERFORM OPERABILITY DETERMINATION AND/OR DECLARE EQUIPMENT INOPERABLE

IR 05000298-00-13; on 9/24-11/04/2000; Nebraska Public Power District; Cooper Nuclear Station, Integrated Resident & Regional Report. Maintenance Rule Effectiveness. The inspectors determined that operations personnel did not declare that safety-related equipment was inoperable, under degraded or nonconforming conditions, on three separate occasions. The separate conditions were the loss of an off-site ac power circuit, a potentially generic problem with the closing mechanism of safety-related Magne-Blast circuit breakers, and the apparent excessive leakage from the reactor equipment cooling system. The failure to perform operability determinations was considered a violation of Technical Specification 5.4.1(a), for failure to follow Regulatory Guide 1.33, Appendix A, recommended procedures. This noncited violation was determined to have very low safety significance because the minimum required number of offsite circuits remained available for the first example, and subsequent evaluations determined there was not a loss of safety function for the other two examples (Section 1R15).

Inspection Report# : [2000013\(pdf\)](#)

Significance: Aug 25, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Follow Procedures

Eleven examples of failure to follow required procedures were identified. The majority involved failure to perform operability evaluations as required by Procedure 0.5.OPS and parent Procedure 0.5, "Conduct of Problem Identification and Resolution Process." One example was for not performing an operability determination for the "D" diesel-driven fire water pump associated with the failure of an engine cooling system raw water solenoid valve to stroke during a surveillance test. Failure to follow Procedure 0.5 OPS was a violation of Technical Specification 4.5.1.a. This violation is being treated as a Non-Cited Violation in accordance with Section VI.A of the NRC Enforcement Policy. This issue was entered into the licensee's corrective action program as Problem Identification Report 4-11393 (50-298/0010-01)

(Section 4OA2.1.b). This issue was characterized as a green finding using the Significance Determination Process. It was determined to have very low risk significance because the system remained operable in the examples identified or the specific example had been previously addressed by the Significance Determination Process at this level.

Inspection Report# : [2000010\(pdf\)](#)

Significance: G Aug 25, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Establish an Adequate Procedure

The licensee failed to establish an adequate work control procedure because it did not contain the requirement to establish a basis for deferring corrective maintenance on Valve HPCI-MOV-MO19 for degraded conditions (i.e., degraded grease in motor-operator valve motor actuators) beyond the next refueling outage. Generic Letter 96-07, "Periodic Evaluation of Motor Operated Valves," provided evaluation guidance for degraded grease and the impact on motor operated valve operability. However, no technical evaluation or justification was performed for deferral of the corrective maintenance. The issue was placed into the licensee's corrective action program as Problem Identification Report 4-11043. This violation of 10 CFR Part 50, Appendix B, Criterion V, is being treated as a Non-Cited Violation consistent with Section VI.A of the NRC Enforcement Policy (50-298/0010-02) (Section 4OA2.2.b). This issue was characterized as a green finding using the Significance Determination Process. It was determined to have a very low risk significance because alternate means for safe shutdown and cooldown were available for the degraded deferred components and the valve passed its last refueling outage surveillance tests.

Inspection Report# : [2000010\(pdf\)](#)

Significance: N/A Aug 12, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO ATTAIN PRIOR COMMISSION APPROVAL FOR A PROCEDURE REVISION INVOLVING AN UNREVIEWED SAFETY QUESTION

IR05000298-00-11; on 06/25-08/12/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Risk Assessments and Emergent Work Evaluation, Surveillance Testing. On July 2, 2000, engineering and operations personnel revised a surveillance procedure to raise the drywell temperature limit from 148° F to 150° F. The licensee's basis for raising the limit was that the instrument inaccuracy was already accounted for in the calculated net positive suction head margin for emergency core cooling systems. However, the inspectors determined that adequate margin did not exist in these calculations. As a result, during the licensee's review of the procedure change, the licensee failed to identify that the change involved an unreviewed safety question and therefore required Commission approval. The failure to obtain Commission approval prior to raising the drywell temperature limit was a violation of 10 CFR 50.59. This violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy and is in the licensee's corrective action program as Problem Identification Report 4-10381.

Inspection Report# : [2000011\(pdf\)](#)

Significance: G May 13, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO ENTER APPROPRIATE LCO FOR SWBP CONDITION

IR05000298-00-06; on 04/02-5/13/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Rule and Health Physics. The inspectors determined that a maintenance procedure was inadequate to address the seismic qualification of service water system piping when an idle section of piping was removed. Procedure 7.2.57.1, "Pipe Support Removal and Re-installation," provided guidance for the removal of snubbers, hangers, and other such equipment. However, the procedure did not address the impact from removal of the piping itself. As a result, operations personnel determined that residual heat removal service water booster pump system components were operable when seismic reviews to support operability had not been completed. This was in violation of Technical Specification 5.4.1(a) that requires written procedures to be established, implemented, and

maintained. The licensee documented these issues in their corrective action process as Resolved Condition Report (RCR) 2000-0108. This noncited violation was characterized as a "green" finding using the significance determination process. This issue was determined to be of very low significance because, while the repairs affected the operability of one system loop, redundant safety capability was still available from the other loop. Also, operators and engineers determined that previous repairs were all conducted within the most restrictive Technical Specification allowed outage times.

Inspection Report# : [2000006\(pdf\)](#)

Significance: May 09, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO CONSIDER SEISMIC EFFECTS ON SERVICE WATER PIPE OPERABILITY

IR05000298-00-05; on 04/17-4/20/00; Nebraska Public Power District, Cooper Nuclear Station. Supplemental Engineering Inspection. During calculations to evaluate the effects of wall thinning on service water piping, the engineers failed to include seismic considerations as required by design requirements. This was a violation of 10 CFR Part 50, Appendix B, Criterion III. We are treating this as noncited in accordance with the NRC Enforcement Policy. The inspectors noted that the probability of a seismic event was very low. As a result, the lack of evaluating seismic stresses imposed very low risk significance. The licensee replaced the affected piping during the refueling outage.

Inspection Report# : [2000005\(pdf\)](#)

Significance: May 09, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE CORRECTIVE ACTION FOR A DESIGN CALCULATION ERROR

IR05000298-00-05; on 04/17-4/20/00; Nebraska Public Power District, Cooper Nuclear Station. Supplemental Engineering Inspection. During review for replacement of a high pressure core injection steam isolation valve completed on December 23, 1997, licensee engineers found that an inaccurate, nonconservative valve actuator weight had been used in the existing pipe stress calculation. This was a violation of 10 CFR Part 50, Appendix B, Criterion XVI, for failing to implement measures to promptly identify and correct other possible examples of this error. We are treating this violation as noncited in accordance with the NRC Enforcement Policy. This violation was included in the licensee's corrective action program as Problem Identification Report 4-08665. This issue was determined to be of low safety significance by the Safety Determination Process because allowable pipe stresses were not exceeded and the pipe remained fully operable. Specifically, licensee engineers failed to scope this issue to determine if this nonconservative weight had been used in other pipe stress calculations for other actuators of the same type.

Inspection Report# : [2000005\(pdf\)](#)

Significance: Apr 17, 2000

Identified By: NRC

Item Type: FIN Finding

POOR ENGINEERING CORRECTIVE ACTION

IR05000298-00-05; on 04/17-4/20/00; Nebraska Public Power District, Cooper Nuclear Station. Supplemental Engineering Inspection. This focused inspection was performed by the NRC to assess a licensee engineering self-assessment performed during September and October 1999. The inspection is being documented as a supplemental inspection; however, no "white" issue characterization caused the inspection. In 1995, the licensee relocated and reorganized the engineering staff. The licensee completed an engineering self-assessment and a follow up self-assessment in 1996 in order to evaluate the effectiveness of the engineering organization, staff, and processes. In 1998 the licensee implemented a strategy for achieving engineering excellence. Included in this strategy was an action to perform a self-assessment in 1999, again reviewing the effectiveness of the engineering organization, staff, and processes, and measuring progress made. In letters from the licensee to the NRC dated October 7, 1998, and May 19, 1999, the licensee outlined commitments in order to improve engineering performance and documented the licensee's understanding of the NRC's plans for monitoring licensee engineering performance. One of the NRC's plans was to

evaluate the licensee's 1999 assessment. That evaluation is contained in this report. This inspection was performed using portions of Inspection Procedures 95001 and 71152. During this inspection, the inspectors determined that licensee engineering management generally understood the causes of poor engineering performance. The 1999 licensee self-assessment failed, however, to emphasize the effects of the engineering backlog and failed to emphasize design issues associated with the 250/125 volt dc system. The inspectors also determined that the causes of poor engineering performance were not fully corrected; however, planned corrective actions were reasonable and improvements had been made.

Inspection Report# : [2000005\(pdf\)](#)

Significance: G Apr 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

RHR CROSS-CONNECTION RESULTED IN AN UNCONTROLLED VESSEL DRAINING

The cross-connecting of residual heat removal loops produced an uncontrolled vessel level transient that was self-terminated when the nonoperating loop was filled. The inspectors determined that an inadequate equipment control release allowed a cross-connect valve between the two residual heat removal loops to be opened. The inspectors concluded this was a noncited violation of Technical Specification 5.4.1(a). This issue had low safety significance. Since the secured loop vent and drain valves were closed at the time, the transient lasted only 2 to 3 minutes, resulting in approximately 2500 gallons of water being lost from the refueling cavity. This resulted in only a minor decrease in refueling cavity level and no increase in adverse radiological conditions.

Inspection Report# : [2000004\(pdf\)](#)

Significance: G Apr 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

SCAFFOLD BLOCKING CONTAINMENT VALVE

Maintenance personnel constructed a scaffolding in the auxiliary building that blocked the operation of a secondary containment isolation valve. Operations and maintenance personnel determined that the valve was obstructed for a period of 4-5 days and that the valve would not have closed as required on a containment isolation signal. The inspectors concluded this was a noncited violation of Technical Specification 5.4.1(a). This issue had low safety significance. A redundant valve, in series with the obstructed valve, remained operable

Inspection Report# : [2000004\(pdf\)](#)

Significance: G Apr 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

LEAKING TORUS VACUUM BREAKERS

On March 6, 2000, operations and licensing personnel reported to the NRC that the torus vacuum breakers failed a leak test surveillance. Proper mitigation of a loss-of-coolant accident requires that the vacuum breakers do not permit excessive communication between the drywell and the suppression chamber. Inadequate maintenance procedures for the refurbishment of the valves in the last refueling outage led to the excessive leakage. The inspectors concluded this was a noncited violation of Technical Specification 5.4.1(a). This issue had low safety significance. Engineering personnel provided analyses and documentation that showed that, while the leakage was above administrative limits, it remained within design limits for the plant

Inspection Report# : [2000004\(pdf\)](#)

Significance: G Apr 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

MOV-53-A OPERABILITY EVALUATION

The inspectors identified a noncited violation of Technical Specification 5.4.1(a) for failure to perform an operability evaluation on a reactor recirculation pump discharge valve. The Reactor Recirculation Pump A Discharge Valve exhibited degraded performance during a forced outage in January, and subsequently failed to operate on March 4, 2000. The valve is required to close on a loss-of-coolant accident signal to prevent the short cycling of a subloop for low pressure coolant injection. This issue had low safety significance. The other subloop, and the low pressure core spray system, remained operable.

Inspection Report# : [2000004\(pdf\)](#)

Significance: G Apr 01, 2000

Identified By: NRC

Item Type: FIN Finding

CONTROL ROOM PERSONNEL UNAWARE OF HEIGHTENED CONFIGURATION RISK AND ASSOCIATED CONTINGENCY PLANS

On March 20, 2000, the inspectors questioned control room personnel about outage risk, configuration control, and contingency plans. The control room personnel were unaware that configuration risk was in the orange, or second highest, band. The operators also were unaware of specific contingency plans that they were responsible to implement. This issue had low safety significance. While a potential existed for improper configuration management, the lack of operator awareness did not result in any actual impact to the plant.

Inspection Report# : [2000004\(pdf\)](#)

Significance: G Feb 19, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INOPERABILITY OF FAST OPEN FEATURE OF TURBINE BYPASSES

Technical Specification 3.7.7 requires that the fast open feature be enabled prior to exceeding 25 percent of rated thermal power. However, the fast open feature was inoperable whenever the reactor was operated between 25 and 33 percent. The cause of the inoperable fast open feature for the turbine bypass valves was a design error made during original construction of the facility that was not identified prior to the implementation of Improved Technical Specifications in August of 1998. Engineers inappropriately designed the turbine bypass valve controller resulting in the blocking of the fast open feature of the valves until approximately 33 percent rated thermal power. The turbine bypass valve fast open feature is required to prevent exceeding minimum critical power ratio limits for certain transients while the reactor is operating between 25 and 30 percent of rated thermal power. However, the plant is infrequently operated in this region, resulting in a low probability of occurrence for these transients. Reactor engineering personnel also provided corollary data and vendor information to demonstrate that there was still considerable margin to safety limits. As a result, this issue was characterized as having very low safety significance based upon the significance determination process. Licensing personnel documented that personnel had failed to identify this deficiency in the corrective action process as Significant Condition Report 2000-0024

Inspection Report# : [2000001\(pdf\)](#)

Significance: G Feb 19, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PERFORM SAFETY FUNCTION DETERMINATION PROGRAM IN ACCORDANCE WITH TECHNICAL SPECIFICATION 5.5.11.

Plant personnel failed to perform required evaluations because licensed operators inappropriately declared the reactor equipment cooling system operable following the discovery of a system leak greater than design allowances. On December 30, 1999, the NRC granted a Notification of Enforcement Discretion indicating its intention to exercise discretion not to enforce compliance with Technical Specification 3.7.3, "Reactor Equipment Cooling System." This discretion only related to the noncompliance with Technical Specification 3.7.3 resulting from continued operation of the plant with excessive reactor equipment cooling system leakage.

Inspection Report# : [2000001\(pdf\)](#)**G****Significance:** Feb 19, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE SURVEILLANCE TESTING FOR TURBINE BYPASSES

Although technicians tested that the fast open feature would function when the reactor was near rated thermal power, the functional testing did not include a verification that the permissive enabled the fast open feature at 25 percent rated thermal power. This was in noncompliance with Technical Specification Surveillance Requirement 3.7.7.2. The turbine bypass valve fast opening feature is required to prevent exceeding minimum critical power ratio limits for certain transients while the reactor is operating between 25 and 30 percent of rated thermal power. However, the plant is infrequently operated in this region, resulting in a low probability of occurrence for these transients. Reactor engineering personnel also provided corollary data and vendor information to demonstrate that there was still considerable margin to safety limits. As a result, this issue was characterized as having very low safety significance based upon the significance determination process. Licensing personnel documented the procedure inadequacy in their corrective action process as Significant Condition Report 2000-0024

Inspection Report# : [2000001\(pdf\)](#)**G****Significance:** Jan 01, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE PROCEDURES TO ENSURE EQ PANEL CLOSURE

Green. Operations and maintenance procedures were inadequate to ensure proper closure of environmentally qualified equipment panels. This issue was characterized as having low safety significance based upon the significance determination process. Various electrical and equipment control panels throughout the facility require closure and proper fastening to ensure environmental qualification (EQ). The inspectors found a number of EQ designated panels for high pressure coolant injection (HPCI) subsystems not properly fastened. Subsequent review by engineers provided evidence that the identified panels provided environmental qualification only for high radiation. As a result, they were not required to be sealed. The inspectors and engineers also determined, however, that the existing procedures did not differentiate between EQ actions for high radiation panels and actions for other harsh environment panels. Plant staff did not find any inoperable equipment in the HPCI panels. The lack of procedural control over EQ panel configuration created a possibility, however, that workers would not properly restore panels that require a seal from steam intrusion. The inspectors concluded that operating and maintenance procedures did not ensure personnel knew when to address EQ requirements. The inadequacy of these procedures is considered a violation of Technical Specification 5.4.1(a). This violation is being treated as a non-cited violation, consistent with the Interim Enforcement Policy for pilot plants. Licensing personnel documented this in their corrective action process as Repetitive Condition Report 99-0824 (Section 1R04.)

Inspection Report# : [1999016\(pdf\)](#)**G****Significance:** Nov 20, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

A LICENSED OPERATOR FAILED TO PROPERLY IMPLEMENT A SURVEILLANCE PROCEDURE, RESULTING IN THE UNPLANNED WITHDRAWL OF A CONTROL ROD (SECTION 1R22).

A licensed operator failed to properly implement a surveillance procedure, resulting in the unplanned withdrawal of a control rod and a reactivity transient. This issue was characterized as having low safety significance based upon the significance determination process review for events. The operator action of withdrawing the control rod, instead of inserting it, caused reactor power to exceed steady state licensed thermal power for a period of approximately 3 minutes. Reactor engineers verified that no thermal limits were exceeded and that design basis transient analysis permits brief operation at the power level attained during this transient. The inspectors concluded that the operator failed to properly insert the control rod as specified in Procedure 6.CRD.301, "Withdrawn Control Rod Operability IST

Test," Revision 6. We are treating this violation as a noncited violation, consistent with the Interim Enforcement Policy for pilot plants. Operations personnel documented this in their corrective action process as Repetitive Condition Report (RCR) 99-0824.

Inspection Report# : [1999014\(pdf\)](#)

Significance: Oct 29, 1999

Identified By: NRC

Item Type: FIN Finding

Reactor Equipment Cooling System Leak was Considered to be Potentially Significant.

A leak from the reactor equipment cooling system was found to be the result of leaking tubes in a room cooler in the northeast quadrant of the secondary containment building. This was considered to be potentially significant because the reactor equipment cooling system is required to be capable of providing cooling for 30 days without makeup water. This issue was considered GREEN in the significance determination process since it did not represent an actual loss of safety function of a system, of a single train for more than the technical specification allowable outage time, or of a single train of non-technical specification equipment designated as risk-significant under 10 CFR 50.65 for more than 24 hours.

Inspection Report# : [1999011\(pdf\)](#)

Significance: Sep 10, 1999

Identified By: NRC

Item Type: FIN Finding

Logic Testing Problems with Residual Heat Removal System Contacts

A narrowly focused approach in response to Generic Letter 96-01 involving surveillance issues associated with logic testing led to a recent noncited violation (50-298/9904-04) for inadequate corrective actions. Subsequent to the noncited violation, a condition, described in Licensee Event Report 99-005, addressed related circumstances associated with surveillance testing of the residual heat removal logic contacts. The corrective actions associated with the residual heat removal logic testing identified another example of the previously documented noncited violation. In using the cornerstone significance determination process, this issue was determined to have very low risk significance because the system remained operable, although degraded (Section 1R22).

Inspection Report# : [1999003\(pdf\)](#)

Significance: Sep 10, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

UNTIMELY CORRECTIVE ACTIONS FOR THE RHR SYSTEM

Green: In using the cornerstone significance determination process, this issue was determined to have very low risk significance because the system remained operable, although degraded. The residual heat removal heat exchanger operator workaround conditions involving the operation of the heat exchanger outlet valves (including the service water side) had existed for several years. Long-term corrective actions to restore the system's ability to maintain temperature control during shutdown cooling mode of operation, according to the system's original design, had not been developed and implemented. Failure to establish prompt corrective actions for conditions adverse to quality was a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation (50-298/9903-01), consistent with the Interim Enforcement Policy for pilot plants (Section 1R07).

Inspection Report# : [1999003\(pdf\)](#)

G**Significance:** Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to follow equipment control procedure

Technical Specification 5.4.1(a) requires that the licensee establish, implement, and maintain written procedures recommended in Regulatory Guide 1.33, Revision 2, Appendix A, February 1978. Appendix A recommends procedures for Equipment Controls. On January 28, 2002, the licensee identified that, during performance of troubleshooting activities on the reactor building ventilation system, personnel inappropriately lifted an electrical lead, resulting in a loss of secondary containment pressure control. This resulted in an unplanned entry into LCO 3.6.4.1(A) for the loss of secondary containment. This is being treated as a noncited violation. The licensee entered this issue into their corrective action process as Notification 10139333. The safety significance of this violation was determined to be very low. The lifted wire was replaced and secondary containment pressure control was re-established after approximately 10 minutes. The standby gas treatment system was also available for secondary containment pressure control if needed.

Inspection Report# : [2001008\(pdf\)](#)**G****Significance:** Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to follow surveillance test procedure

Technical Specification 5.4.1(a) requires that the licensee establish, implement, and maintain written procedures recommended in Regulatory Guide 1.33, Revision 2, Appendix A, February 1978. Appendix A recommends procedures for surveillance tests. On February 11, 2002, personnel failed to follow Surveillance Procedure 6.CRD.201, "North and South Shutdown Volume Vent and Drain Valve Cycling," resulting in both shutdown vent and drain lines failing to close. This condition resulted in an unplanned entry into LCO 3.1.8(B), "One or more shutdown volume vent or drain valves inoperable." This is being treated as a noncited violation. The licensee entered this issue into their corrective action process as Notification 10141525. The safety significance of this violation was determined to be very low. The function of these valves is to provide primary containment isolation during a scram. This condition was present for approximately 10 minutes (less than the Technical Specification allowed outage time) before being identified and corrected.

Inspection Report# : [2001008\(pdf\)](#)**G****Significance:** Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to monitor performance of Maintenance Rule components

The licensee failed to demonstrate that performance of the feedwater check valves was being effectively controlled through the performance of appropriate preventive maintenance in that repetitive preventive maintenance preventable failures of the valves occurred from July 1996 to February 19, 2002. Following these failures, the licensee failed to consider placing the feedwater check valves into (a)(1) status. This was determined to be a violation of 10 CFR 50.65 (a)(2). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue was entered into the licensee's corrective action program as Notification 10122802. This issue was considered to have a credible impact on safety, in that the failure of these valves caused a higher than normal containment leakage. This noncited violation was characterized under the significance determination process as having very low safety significance. The finding was a Type A finding in accordance with the significance determination process in Table 2 of Inspection Manual Chapter 0609-H, "Containment Integrity Significance Determination Process." Type A findings are findings that affect core damage frequency. Type A findings with a delta core damage frequency less than 10-7/yr associated with large early release frequency sequences in plants with Mark I containments are considered to be Green, based on low core damage frequency and large early release frequency, as documented in Table 1 of Inspection Manual Chapter 0609-H, "Containment Integrity Significance Determination Process".

Inspection Report# : [2001008\(pdf\)](#)

Significance:  Jan 03, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to identify and correct design control deficiencies associated with the reactor feedwater check valves

The licensee failed to implement effective corrective actions resulting in repetitive failures of reactor feedwater check valves to pass local leak rate testing requirements from 1983 through November of 2001. This was determined to be a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Significant Condition Report 2001-1161. This issue was considered to have a credible impact on safety, in that the failure of these valves caused a higher than normal containment leakage. This noncited violation was characterized under the significance determination process as having very low safety significance. The finding was a Type B finding in accordance with the significance determination process because these valve failures did not affect core damage frequency. Type B findings related to containment isolation valves in plants with Mark I containments and are considered to be Green, based on Table 3 of Inspection Manual Chapter 0609-H, "Containment Integrity Significance Determination Process."

Inspection Report# : [2001007\(pdf\)](#)

Significance:  Jan 03, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Ineffective corrective actions resulting in repetitive scaffold construction nonconformances

The licensee failed to implement effective corrective actions, resulting in repetitive scaffold construction nonconformances potentially affecting the operation of equipment important to safety. Examples included scaffolding built in the proximity of and over safety-related equipment, as well as scaffold components that could have interfered with the safety function of plant components. This violation of 10 CFR Part 50, Appendix B, Criterion XVI, is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10127237. This issue was considered to have a credible impact on safety, in that the failure to properly construct scaffolds could affect the operation of equipment important to safety. This noncited violation was characterized under the significance determination process as having very low safety significance because the failure to construct scaffolds in accordance with the procedural requirements did not result in any equipment failure or loss of safety function.

Inspection Report# : [2001007\(pdf\)](#)

Significance:  Jan 03, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to follow procedure resulting in disabling the suppression chamber vacuum relief valves

On November 2, 2001, the licensee identified that personnel inadvertently placed the Suppression Chamber Vacuum Relief Valves PC-AO-243 and PC-AO-244 operating switches to close while performing a tagout of another system for maintenance. This was determined to be a violation of Technical Specification 5.4.1(a). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10120889. This issue was considered to have a credible impact on safety, in that the suppression chamber vacuum relief function was disabled. This event was characterized as having very low safety significance because licensed operators identified that the switches were in the incorrect position and corrected the condition within approximately 3 hours. This was within the Technical Specification allowed outage time.

Inspection Report# : [2001007\(pdf\)](#)

Significance:  Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Exceeded Licensed Thermal Power

Cooper Nuclear Station License DPR-46, Section 2.C.1, states "The licensee is authorized to operate the facility at steady state reactor core power levels not in excess of 2381 megawatts (thermal)." From 12 p.m. through 8:55 p.m., on August 25, 2001, the licensee averaged between 2381 and 2384 megawatts thermal, due to a mispositioned reactor water cleanup filter bypass valve. This is being treated as a noncited violation. The licensee entered the issue into the corrective actions process as Notification 10106705.

Inspection Report# : [2001006\(pdf\)](#)

Significance: G Jul 10, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide administrative controls for opening primary containment isolation valves

The licensee failed to provide administrative controls, as required by Technical Specification 3.6.1.3, from May 8-10, 2001, to ensure that primary containment Isolation Valves RW-AOV-AO-82, 83, 94, and 95 could be isolated. This issue was determined to have a credible impact on safety because administrative controls were insufficient to ensure that primary containment could be isolated rapidly. This noncited violation was characterized under the risk significance determination process as having very low safety significance because the valves never failed to close when they were administratively opened and this condition lasted for less than 3 days (Section 1R04.2).

Inspection Report# : [2001002\(pdf\)](#)

Significance: G Jul 10, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform operability determination and/or declare equipment inoperable

The licensee failed to declare equipment inoperable following multiple failures of primary containment isolation Valves RW-AOV-AO82, -83, -94, and -95 to pass surveillance testing requirements. This was a violation of Technical Specification 5.4.1(a). This issue was determined to have a credible impact on safety because the failure of these valves affected the ability to isolate primary containment. This noncited violation was characterized under the risk significance determination process as having very low safety significance because both the inboard and outboard primary containment isolation valves had never failed at the same time. Therefore, no actual open pathway affecting the physical integrity of the primary containment was present (Section 1R04.1).

Inspection Report# : [2001002\(pdf\)](#)

Significance: G Aug 12, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO INITIATE ACTIONS WITHIN ONE HOUR AS REQUIRED BY TECHNICAL SPECIFICATION LIMITING CONDITION FOR OPERATION 3.0.3

IR05000298-00-11; on 06/25-08/12/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Risk Assessments and Emergent Work Evaluation, Surveillance Testing. On June 28, 2000, operations personnel declared the drywell floor drain sump flow monitoring system inoperable to perform a surveillance test. Operators did not recognize that the drywell atmospheric monitoring system had previously been declared inoperable on June 23 due to a failed sample pump. As a result, all reactor coolant system leak detection instrumentation required by Technical Specification 3.4.5, "RCS Leakage Detection Instrumentation," was inoperable for 1 hour and 9 minutes. Because the operators did not recognize this condition, the requirements of Technical Specification 3.0.3 to initiate actions within 1 hour to shut down the plant was not satisfied. This was determined to be a violation and is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy. It is in the licensee's corrective action program as Significant Condition Report 2000-0701.

Inspection Report# : [2000011\(pdf\)](#)

**Significance:** Oct 09, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to use a gauge that provided adequate repeatability for low pressure testing of the primary containment drywell airlock.

Green. 10 CFR Part 50, Appendix B, Criteria XI, requires that licensees have available and use adequate test instrumentation. The failure to use a gauge that provided adequate repeatability for low pressure testing of the primary containment drywell airlock is a violation. We are treating this violation as noncited, consistent with the Interim Enforcement Policy for pilot plants. The licensee placed this issue in the corrective action program as Problem Identification Report 4-04709. Since the subsequent airlock leak test at accident pressure proved that the airlock continuously met the Technical Specification 3.6.1.2 requirements for operability, the inspectors concluded that this problem had minimal risk significance.

Inspection Report# : [1999013\(pdf\)](#)

Emergency Preparedness

Significance: N/A May 28, 2002

Identified By: NRC

Item Type: FIN Finding

Summary of Assessment for a Supplemental Inspection (95002)

IR 05000298-02-05, on 04/15-18/2002, Nebraska Public Power District, Cooper Nuclear Station. Supplemental inspection for a degraded emergency preparedness cornerstone in the reactor safety strategic performance area resulting from multiple White inspection findings. This supplemental inspection was primarily performed by the NRC to assess the licensee's evaluations of the following inspection findings: (1) the licensee failed to implement planning standard 10 CFR 50.47(b)(5), resulting in an untimely notification to state and local response organizations following declaration of an Alert on June 25, 2001; (2) the licensee failed to meet emergency planning standard 10 CFR 50.47(b)(2), resulting in untimely activation of the emergency response facilities following declaration of an Alert on June 25, 2001. These performance issues were characterized as having low to moderate risk significance (White). This inspection was also performed to evaluate followup corrective actions for a previous finding documented in NRC Inspection Report 50-298/01-04. This finding was for a performance weakness that was repeated during an April 11, 2001, drill, resulting in a violation of 10 CFR Part 50, Appendix E, Paragraph IV.F.2.g. During this supplemental inspection, the inspectors evaluated the extent of the condition for both of the 10 CFR 50.47 findings. They found that other problems, with a similar root cause, could exist beyond the original case due to the licensee's weaknesses in identification and resolution of problems. The licensee determined that the root cause of the Emergency Preparedness Program implementation breakdown was "Overall inadequate program implementation and maintenance of the Emergency Plan." The licensee's root cause evaluation did not fully identify and assess all contributing causes that resulted in the breakdown of the Emergency Preparedness Program. An extensive list of corrective actions was developed to address the Emergency Preparedness Program issues. However, these corrective actions were not supported by a thorough assessment that would ensure the licensee had a detailed understanding of the underlying problems. The inspectors concluded that the licensee did not provide adequate assurance that all causes of the programmatic breakdown were identified and evaluated or that the developed corrective actions would prevent recurrence of future emergency preparedness problems. The licensee had detailed an extensive list of corrective actions in their Emergency Preparedness Improvement Plan Schedule. Most of these actions were complete. However, licensee performance in simulator drills and on a call-out drill was not indicative of a program that had undergone extensive and effective corrective actions. As a result of these concerns, both of the 10 CFR 50.47 White issues will remain open. The inspectors also reviewed the corrective actions for a previous finding, "Corrective actions implemented to prevent recurrence of a dose assessment performance weakness identified during the August 29, 2000, biennial exercise were not fully effective in that they were narrowly focused and failed to prevent recurrence of the performance weakness (Inspection Report 50-298/2001-04)." The inspectors concluded that actions after an NRC supplemental inspection (NRC Supplemental Inspection Report 50-298/2001-011) corrected the specific aspects of problems identified during that inspection. However, other Emergency Preparedness Program problems were missed when the licensee failed to

conduct a thorough root cause evaluation and identify deficiencies similar to those identified during the inspection. The inspectors concluded that this finding involved similar aspects of problem identification and resolution to the other emergency preparedness findings. Since these problems are of a similar nature, and the expected resolution is common, this finding will also remain open.

Inspection Report# : [2002005\(pdf\)](#)



Significance: W Oct 01, 2001

Identified By: NRC

Item Type: VIO Violation

Failure to correct a risk-significant EP performance weakness

(NOTE: The Degraded Cornerstone Inspection (IR 50-298/2002-05) held this violation open pending further review of corrective actions. The original date was June 27, 2001. The event date was modified so that this item would continue to be indicated as an open White finding.) Corrective actions implemented to prevent recurrence of a dose assessment performance weakness identified during the August 29, 2000, biennial exercise were not fully effective in that they were narrowly focused. The dose assessment team failed to recognize a degraded core condition and to revise its dose projections for the degraded condition. As a result, protective action recommendations were not upgraded. Corrective actions for the performance weakness concentrated on procedural inconsistencies that contributed to the failure and did not sufficiently recognize the need for additional personnel training. As a result, the performance weakness was repeated during an April 11, 2001, drill. This was an apparent violation of 10 CFR Part 50, Appendix E, Paragraph IV.F.2.g. This finding had greater than minor significance because the failure to use a degraded core in dose calculations had a credible impact on safety, in that it resulted in incorrect protective action recommendations which could have caused offsite populations to receive unnecessary radiation dose. It had been preliminarily determined to have low to moderate safety significance (White) using the Emergency Preparedness Significance Determination Process because it represented a failure to correct a performance weakness associated with a risk-significant emergency preparedness planning standard. This violation was entered into the licensee's corrective action program as RCR 2001-0331. The final determination for a white finding and notice of violation were issued for EA-01-154 on August 13, 2001.

Inspection Report# : [2001004\(pdf\)](#)



Significance: W Oct 01, 2001

Identified By: NRC

Item Type: VIO Violation

Failure to Meet Planning Standard 10 CFR 50.47(b)(2)

(NOTE: The Degraded Cornerstone Inspection (IR 50-298/2002-05) held this violation open pending further review of corrective actions. The original date was July 25, 2001. The event date was modified so that this item would continue to be indicated as an open White finding.) The licensee failed to activate the emergency response facilities within approximately one hour following declaration of an Alert on June 25, 2001. This was a violation of 10 CFR 50.54(q) and 10 CFR 50.47(b)(2). This violation was evaluated under the risk significance determination process as having low to moderate safety significance based on the following: (1) the finding is a violation of 10 CFR 50.54(q); and (2) this finding was a failure to meet nonrisk significant planning standard 10 CFR 50.47(b)(2) (Section 4OA3.2) Final SDP letter issued March 1, 2002.

Inspection Report# : [2001009\(pdf\)](#)



Significance: W Oct 01, 2001

Identified By: NRC

Item Type: VIO Violation

Failure to Perform Timely Offsite Notification during Alert

(NOTE: The Degraded Cornerstone Inspection (IR 50-298/2002-05) held this violation open pending further review of corrective actions. The original date was July 25, 2001. The event date was modified so that this item would continue to be indicated as an open White finding.) The licensee failed to notify state and local governmental agencies within 15 minutes of declaring an Alert on June 25, 2001. This was a violation of 10 CFR 50.54(q) and the licensee's emergency

plan. This violation was evaluated under the risk significance determination process as having low to moderate safety significance based on the following: (1) the failure to notify state and local governmental agencies in a timely manner, following declaration of an Alert, during an actual event on June 25, 2001; and (2) this finding represents a failure to implement the risk significant planning standard 10 CFR 50.47(b)(5) (Section 4OA3.1). Final SDP letter sent March 1, 2002.

Inspection Report# : [2001009\(pdf\)](#)

Significance: Sep 06, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Reduction in the effectiveness of the emergency plan without Commission approval

Apparent Violation Documented in Inspection Report 2001-09: The licensee failed to maintain an adequate emergency operations facility to support emergency response since September 14, 1991. This is an apparent violation of 10 CFR 50.54(q) and 10 CFR 50.47(b)(8). This apparent violation was evaluated under the risk significance determination process as having low to moderate safety significance based on the following: (1) the finding is an apparent violation of 10 CFR 50.54(q); and (2) this finding was a failure to meet nonrisk significant planning standard 10 CFR 50.47(b)(8) (Section 4OA3.3). Final Determination documented in a letter dated March 1, 2002: In February 1992, the licensee reduced the effectiveness of its emergency plan without Commission approval when it revised System Operating Procedure 2.2.90, "12.5 kV System," to restrict the backup power source to supply only the EOF communication system when in operating Modes 1, 2, and 3. As a result, the EOF filtered ventilation system, and other equipment, would not be available in the event of a loss of offsite power during operating Modes 1, 2, and 3. This is a violation of 10 CFR 50.54(q). This issue was determined to have a credible impact on safety because the ability to perform required emergency response functions from the EOF could be impacted during accidents involving a loss of offsite power, resulting in a delay in actions necessary to protect the public. This noncited violation was characterized using the SDP as having very low safety significance because it did not result in the failure of the licensee to meet an emergency planning standard contained in 10 CFR 50.47(b).

Inspection Report# : [2001009\(pdf\)](#)

Significance: Oct 11, 2000

Identified By: NRC

Item Type: FIN Finding

Failure of exercise critique process to identify a risk-significant planning standard problem

IR 05000298-00-16, on 8/28-31/2000, Nebraska Public Power District, Cooper Nuclear Station. Exercise Evaluation.

The inspection was conducted by regional inspectors and resident inspectors. This inspection identified one finding.

Cornerstone: Emergency Preparedness The formal exercise critique process failed to identify a dose assessment performance problem which caused the issuance of incorrect protective action recommendations for offsite populations. There were three opportunities for protective action recommendations, and only one was performed correctly. During its initial critique, the licensee assessed that three protective action recommendation opportunities had been successfully completed. The issue was preliminarily determined to have low to moderate safety significance because the issue involved a failure of the licensee's critique process to identify a risk-significant emergency preparedness planning standard problem.

Inspection Report# : [2000016\(pdf\)](#)

Occupational Radiation Safety

Significance: Apr 15, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Two examples of the failure to inform workers of the radiological conditions in their work area

The NRC determined that on November 27, 2001, three workers were not informed of the contamination levels, airborne radiological conditions, and the potential for creating an airborne area prior to the start of their task. One of these individuals received an unplanned intake of radioactive material resulting in a dose of 15 millirem. Contamination levels were as high as 480 millirad per hour (fixed) and 10 millirad per hour (loose surface). Airborne radiological conditions were 0.5 derived air concentration. The failure to inform workers of the radiological conditions in their work area is a 10 CFR 19.12 violation. This violation is being treated as a noncited violation consistent with Section VI.A.1 of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Notification 10127287. The safety significance of this finding was determined to be very low by the Occupational Radiation Safety Significance Determination Process. The failure to inform workers of the radiological conditions in their work area has a credible impact on safety, and the occurrence involved a worker's unplanned dose that could have been significantly greater if radiological conditions had been greater. However, there was no overexposure or substantial potential for an overexposure, and the ability to assess dose was not compromised.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to conduct a radiation survey

10 CFR 20.1501(a) states, in part, that each licensee shall make or cause to be made surveys that are reasonable to evaluate the magnitude and extent of radiation levels and the potential radiological hazards. On November 18, 2001, the licensee identified that radiation protection personnel failed to survey a high radiation area in the "A" side of the condenser prior to two workers entering the condenser. Radiation levels were as high as 450 millirem per hour. This violation is being identified as a noncited violation and is in the licensee's corrective action program, reference Notification 10124470. The safety significance of this violation was determined to be very low by the occupational radiation safety significance determination process because there was no overexposure or substantial potential for an overexposure and the ability to assess dose was not compromised.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to follow temporary shielding procedure requirements

Technical Specification 5.4.1.(a) requires procedures for the ALARA Program. Procedure 3.14, "Temporary Shielding," Revision 10, is used, in part, to implement this requirement. Section 3.5.3 of this procedure stated to "Install shielding in accordance with the Temporary Shielding Request (TSR)." TSR 01-107 authorized shielding to be installed on "B" RHR piping. On December 1, 2001, the licensee identified that temporary shielding was installed on main steam piping rather than the "B" RHR piping. The estimated additional exposure for installing and removing the shielding from the main steam pipe was approximately 20 millirem. This violation is being treated as a noncited violation and is in the licensee's corrective action program, reference Notification 10127279. The safety significance of this violation was determined to be very low by the occupational radiation safety significance determination process because there was no overexposure or substantial potential for an overexposure and the ability to assess dose was not compromised.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to follow radiation work permit requirements

Technical Specification 5.4.1.(a) requires procedures for the radiation work permit system. Procedure 9.RADOP.1, "Radiation Protection at Cooper Nuclear Station," Revision 2, is used, in part, to implement this requirement. Section

3.7.4 of this procedure states that each individual is responsible for abiding by all the instructions on the RWP. Worker instructions associated with RWP 2001-1082, Revision 0, states, in part, "Contact RP prior to each entry." On November 27, 2001, the licensee identified that a worker performed work on "B" steam jet air ejector without contacting radiation protection personnel. This worker received an unplanned intake of radioactive material that resulted in a dose of 18 millirem. This violation is being treated as a noncited violation and is in the licensee's corrective action program, reference Notification 10126269. The safety significance of this violation was determined to be very low by the occupational radiation safety significance determination process because there was no overexposure or substantial potential for an overexposure and the ability to assess dose was not compromised.

Inspection Report# : [2001008\(pdf\)](#)

Significance: G Jan 03, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

The licensee failed to lock and control items hanging in the spent fuel pool

The licensee failed to lock and control items hanging in the spent fuel pool that would create a high radiation area if removed. Specifically, on October 26, 2001, two items were found with underwater on contact radiation levels of 40 and 120 Rem per hour and, on November 29, 2001, another item was found with contact radiation levels of 200 Rem per hour. Licensee personnel assumed that these contact dose rates would have resulted in a high radiation area if the components had been removed from the pool. These occurrences were determined to be a violation of Technical Specification 5.4.1(a). This violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy. This issue has been entered into the licensee's corrective action process as Notification 10127300. The safety significance of this violation was determined to be very low by the occupational radiation safety significance determination process because there was no actual overexposure or substantial potential for an overexposure, and the ability to assess dose was not compromised.

Inspection Report# : [2001007\(pdf\)](#)

Significance: N/A Jul 10, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform an ALARA review.

On May 22, 2001, the inspector identified that the as low as reasonably achievable (ALARA) committee had not reviewed job Package RE19AL-23, "Resolution of EQ Splice Issues," before the job exceeded 5 person-rem. The failure to review a job package before job dose exceeds 5 person-rem is a violation of Technical Specification 5.4.1. This violation is in the licensee's corrective action program as Notification 10086481. The significance of this violation was determined to be more than minor because the failure to perform an appropriate ALARA Committee review could have a credible impact on safety. This violation did not affect the Occupational Radiation Safety cornerstone, since there were no unplanned or unintended doses that resulted from actions contrary to Technical Specifications. However, the issue was determined to be greater than minor (Section 2OS2).

Inspection Report# : [2001002\(pdf\)](#)

Significance: G Jul 10, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to prevent unauthorized entry to a locked high radiation area.

On May 23, 2001, the inspector determined that the door used to control access to the steam jet air ejector room, a locked high radiation area, would not prevent unauthorized entry. The failure to prevent unauthorized entry to a locked high radiation area is a violation of Technical Specification 5.7.2. This violation is in the licensee's corrective action program as Notification 100866582. The safety significance of this violation was determined to be very low by the Occupational Radiation Safety Significance Determination Process because there was no overexposure or substantial potential for an overexposure, and the ability to assess dose was not compromised. This violation was more than minor because the failure to prevent unauthorized entry to a locked high radiation area has a credible impact on safety and the potential for unplanned or unintended dose (Section 2OS2).

Inspection Report# : [2001002\(pdf\)](#)

Significance: May 13, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO FOLLOW ALARA PROCEDURES

IR05000298-00-06; on 04/02-5/13/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Maintenance Rule and Health Physics. A radiation worker and a radiation protection technician failed to follow the requirements of their radiation work permits. Specifically, the radiation worker failed to rinse equipment being removed from the reactor cavity pool to reduce the possible spread of contamination and radioactive particles, and the radiation protection technician failed to perform air sampling during the installation of the reactor cavity/fuel pool shield plugs to monitor the radiological airborne work conditions. The licensee documented the above occurrences in Problem Identification Reports 4-07254 and 4-08306, respectively. This noncited violation was characterized as a "green" finding using the occupational radiation safety significance determination process. This issue was determined to be of very low significance because these incidents did not result in an overexposure or have a significant potential to cause an overexposure.

Inspection Report# : [2000006\(pdf\)](#)

Significance: Mar 24, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

VIOLATION OF 10 CFR 20.1501(a)/FAILURE TO EVALUATE THE DOSE GRADIENT BETWEEN CHEST AND HEAD TO DETERMINE IF DOSIMETRY IS LOCATED CORRECTLY

The inspectors identified a noncited violation of 10 CFR 20.1501(a) because the licensee failed to evaluate the dose gradient between the chest and head to determine if dosimetry was located correctly to measure the dose to the part of the body receiving the highest exposure. The failure to perform this survey could have resulted in an unplanned and unmonitored radiation dose. However, because the incident did not result in an overexposure or have a significant potential to cause an overexposure, the Occupational Radiation Safety Significance Determination Process indicated that the violation had a low risk significance. This violation is in the licensee's corrective action program as Problem Identification Report 4-07142.

Inspection Report# : [2000003\(pdf\)](#)

Significance: Sep 10, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PERFORM RADIOLOGICAL SURVEY

Green: In using the cornerstone significance determination process, this issue was determined to have very low risk significance because there was no unintended exposure or substantial potential for one and the ability to assess dose was not compromised. During withdrawal of the transverse incore probe from the reactor core, radiation levels exceeded the 5000 millirems per hour limit of the survey meter in use. As a result, on May 24, 1997, the extent of the radiation levels was unknown. The failure to perform an adequate radiological survey was a violation of 10 CFR Part 20, Section 1501. This violation is being treated as a noncited violation (50-298/9903-02), consistent the Interim Enforcement Policy for pilot plants (Section 2OS4).

Inspection Report# : [1999003\(pdf\)](#)

Significance: Jul 17, 1999

Identified By: Licensee

Item Type: FIN Finding

INSPECTORS REVIEWED THE LICENSEE'S ACTIONS FOLLOWING A JUNE 4, 1999, SPILL OF FLOW-

LEVEL RADIOACTIVE CONDENSATE DEMINERALIZER RESIN TO ASSESS SIGNIFICANCE.

Green. On June 4, 1999, approximately 5,000 gallons of water with 3 to 4 cubic feet of condensate demineralizer resin spilled onto the radioactive waste building basement floor. The inspectors determined that no significant radiation exposure nor potential overexposure had occurred. The inspectors determined that, because no significant radiation exposure nor potential overexposure had occurred, the spill remained within the licensee's response band (green). Operators documented the event in Problem Identification Report 4-02417 (Section 4OA3).

Inspection Report# : [1999006\(pdf\)](#)

Public Radiation Safety

Significance: Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to properly classify and manifest radioactive waste shipments

On August 21, 2001, the inspector identified that the licensee had incorrect shipping manifests and had under reported isotopic and total shipment radioactivity. The licensee had utilized nonconservative 3-year average waste stream analysis scaling factors for each waste stream to classify all radioactive waste shipments. Various isotopic scaling factors were low by a factor of between 10 and 100. The failure to properly classify and manifest radioactive waste shipments in 1999, 2000, and 2001 was a violation of 10 CFR Part 20, Appendix G. This violation is being treated as a noncited violation consistent with Section VI.A.1 of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Notification 10106415. The safety significance of this violation was determined to be very low by the Public Radiation Safety Significance Determination Process because radiation limits were not exceeded, and there was no breach of package during transit, certificate of compliance problem, low level burial ground access problem, or failure to make notifications or provide emergency information. The violation was more than minor because there was a credible impact on safety due to incorrect shipping manifests and underreported isotopic and shipment activities, and the issue involved an occurrence in the licensee's radioactive material transportation program (Section 2PS2).

Inspection Report# : [2001006\(pdf\)](#)

Significance: Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

The licensee identified that the 10 CFR Part 61 annual waste stream sampling and analysis had not been completed in 1998 in accordance with radiation protection procedural requirements

Technical Specification 5.4.1.a requires that procedures be established, implemented, and maintained for activities recommended in Regulatory Guide 1.33, Revision 2, Appendix A, February 1978. On September 21, 2000, the licensee identified that the 10 CFR Part 61 annual waste stream sampling and analysis had not been completed in 1998 in accordance with radiation protection procedural requirements. This event is described in the licensee's corrective action program, reference Problem Identification Report 4-11611. This is being treated as a noncited violation.

Inspection Report# : [2001006\(pdf\)](#)

Significance: Oct 04, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

Radioactive waste and material shipping containers were defective and repaired by radiation protection without procedural, material, or quality guidance

49 CFR 173.28(c)(2) states, in part, that reconditioning of a nonbulk packaging is restoring the packaging by repair or replacement of components to a condition such that it conforms in all respects with the requirements of this subchapter.

On September 8, 2000, the licensee identified that radioactive waste and material shipping containers were defective and repaired by radiation protection without procedural, material, or quality guidance. This event is described in the licensee's corrective action program, reference Problem Identification Report 4-11390. This is being treated as a noncited violation.

Inspection Report# : [2001006\(pdf\)](#)

Significance: Oct 04, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

The licensee identified that decay heat calculations were not being performed as required by the certificate of compliance for Type B packages

10 CFR 71.12(c)(2) states, in part, that the general license applies to a licensee who complies with the terms and conditions of the license, certificate, or other approval as applicable. On September 21, 2000, the licensee identified that decay heat calculations were not being performed as required by the certificate of compliance for Type B packages. This event is described in the licensee's corrective action program, reference Problem Identification Report 4-11571. This is being treated as a noncited violation.

Inspection Report# : [2001006\(pdf\)](#)

Significance: Aug 26, 1999

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO CARRY OUT A COMPREHENSIVE SYSTEM OF PLANNED AND PERIODIC AUDITS OF 10 CFR PART 71 REQUIREMENTS (SECTION 4OA1)

The inspector identified a violation for failure to carry out a comprehensive system of planned and periodic audits of the radioactive material packaging and transportation programs in accordance with 10 CFR 71.137. The failure to review all aspects of the radioactive material processing and shipping program could cause programmatic problems to be missed which could ultimately result in unnecessary exposure to radiation workers and members of the public. This violation is being treated as a noncited violation (NCV), consistent with Appendix F of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Problem Identification Report (Serial Number) 4-03782 (Section 4OA1).

Inspection Report# : [1999009\(pdf\)](#)

Physical Protection

Significance: Jul 12, 2002

Identified By: NRC

Item Type: FIN Finding

Inconsistent implementation of fitness-for-duty requirements

The licensee failed to identify and correct deficient documentation supporting environmental qualification of safety-related equipment in the steam tunnel and acceptable voltage applications for Buchanan 0241 terminal blocks. These findings were determined to be two examples of a violation of 10 CFR Part 50, Appendix B, Criterion XVI. This violation is being treated as a noncited violation, consistent with Section VI.A of the NRC Enforcement Policy. The licensee documented this issue in their corrective action process as Notifications 10163954 and 10167990. This finding also had crosscutting aspects associated with problem identification and resolution. This finding was determined to have a credible impact on safety because there was no assurance that the equipment would perform its design function during accident conditions since it was not operating in a previously tested or analyzed configuration. This noncited violation was characterized under the significance determination process as having very low safety significance based on the performance of an acceptable analysis that demonstrated the affected equipment was environmentally qualified.

Inspection Report# : [2002002\(pdf\)](#)

Significance: Oct 05, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

A noncited violation of 10CFR73.55(d)(3) for failure to detect prohibited contraband during a security search prior to the material entering the protected area.

The failure of the security search to detect and control a box of ammunition as it entered the protected area was considered to be a self-revealing noncited violation of 10 CFR 73.55(d)(3). This finding was characterized by the significance determination process as having very low safety significance since there were not more than two similar findings in the past four quarters. It was considered more than minor because it represented a failure to meet the requirements of 10 CFR 73.55(d) and the licensee's security plan. Because of the very low safety significance and because the licensee entered this finding into their corrective action program as Notification 10181426, this violation is being treated as a noncited violation consistent with Section VI.A of the NRC Enforcement Policy.

Inspection Report# : [2002003\(pdf\)](#)

Significance: Mar 31, 2001

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide adequate compensatory measures following degradation of a segment of the perimeter detection system.

IR 05000298-00-15; 12/31/2000-03/31/2001; Nebraska Public Power District; Cooper Nuclear Station. Integrated Resident/Regional Report; Safety Eval. Prog., Heat Sink Perf., Personnel Perf. During Nonroutine Plant Evolutions, Postmaintenance Testing, and Physical Security Plan. Section 9.2.B of the licensee's physical security plan and paragraph 6.5 of licensee's security procedure 2.14 require that upon degradation of a portion of the perimeter detection system, an observer or armed guard with view of the degraded coverage area, will be positioned within 10 minutes. On November 6, 2000, the licensee identified that an observer or armed guard was not posted at a degraded segment of the perimeter detection system until 48 minutes following degradation, as described in the licensee's corrective action program, reference Problem Identification Report 4-12402. This issue was determined to be greater than minor in nature because the condition, if left uncorrected, would become a more significant safety concern. The issue was further determined to be of very low safety significance (Green) by the significance determination process because there were not greater than two similar findings in the last four quarters.

Inspection Report# : [2000015\(pdf\)](#)

Miscellaneous

Significance: N/A Aug 22, 2002

Identified By: NRC

Item Type: FIN Finding

Summary of Assessment for Supplemental Inspection (95003)

On April 1, 2002, Cooper Nuclear Station entered the Repetitive Degraded Cornerstone Column of the Action Matrix. Upon entry into this column of the Action Matrix, and with oversight by the NRC, Nebraska Public Power District was required to develop a comprehensive improvement plan. The purposes of this inspection were to determine the breadth and depth of the performance deficiencies and to assess the adequacy of the licensee's improvement plan (The Strategic Improvement Plan, Revision 1). The inspectors found that Cooper Nuclear Station is being operated safely; however, a number of long-standing performance problems exist. Of greatest concern is the failure of Cooper Nuclear Station to correct recurring performance issues. For example, the improvement plan did not include actions to correct recurring equipment problems and was not comprehensive in addressing problems with the corrective action program. Nebraska Public Power District has been unsuccessful in efforts to improve performance with focused improvement plans. The inability to effectively correct problems has resulted in recurring problems with the reliability of safety systems,

personnel errors, implementation of the emergency plan, and the quality of engineering, training, and maintenance activities. The development of the improvement plan lacked the requisite coordination between problem characterization and the corrective actions specified to correct the problem. The team found performance problem areas which were not effectively addressed by the improvement plan and one area which was missed in its entirety. Also, the improvement plan actions were not prioritized and integrated. The performance problem areas that were identified as not being effectively addressed included equipment reliability; adequacy of operability determinations; plant modification packages; management of component parts; use of industry operating experience information; effective use of performance problem trend codes; use of departmental performance indicators; conflicting departmental and station priorities, policies, and goals; effective implementation of engineering programs; entering self-assessment findings and observations into the corrective action program; coordination and integration among site organizations; procedure change requests; and conflicting departmental and station priorities, policies, and goals. The level of detail of documents reviewed by the team was frequently not sufficient to assess the effectiveness of planned actions. The improvement plan, in general, did not include adequate performance measures to evaluate the effectiveness of the actions plans. In addition, the improvement plan had not been assessed for the resources needed for successful implementation of the planned actions.

Inspection Report# : [2002007\(pdf\)](#)



Significance: G Apr 15, 2002

Identified By: Licensee

Item Type: NCV NonCited Violation

Failure to fully implement the physical security plan

License Condition 2.C(3) of the Cooper Nuclear Station Facility Operating License requires that the licensee fully implement and maintain in effect all provisions of the Commission-approved physical security plan. The licensee's physical security plan states that prior to entering the protected area, all personnel will be searched in accordance with 10 CFR 73.55(d). 10 CFR 73.55(d)(1) requires, in part, that the search function for detection of firearms, explosives, and incendiary devices must be accomplished through the use of both firearms and explosive detection equipment capable of detecting those devices. On February 27 and March 5, 2002, the search function for detection of firearms failed, resulting in a test weapon being successfully passed through the licensee's access control point into the protected area. The licensee initiated prompt corrective actions. This is being treated as a noncited violation. The licensee entered these issues into their corrective action process as Notifications 10145888 and 10144779. This noncited violation was characterized under the significance determination process as having very low safety significance because there have not been greater than two similar findings in the past four quarters.

Inspection Report# : [2001008\(pdf\)](#)



Significance: G Dec 18, 2001

Identified By: Licensee

Item Type: NCV NonCited Violation

Five examples of failure to follow corrective action program procedures for performing operability determinations and evaluations

The following findings of very low safety significance were identified by the licensee and are violations of NRC requirements and meet the criteria of Section VI.A of the NRC Enforcement Policy, NUREG-1600, for being dispositioned as a noncited violation. On July 23, 2001, crimps improperly installed...on August 7, 2001, numerous EQ deficiencies...on August 9, 2001, examples where operability determinations were not performed...on August 7, 2001, primary containment isolation switches did not meet Reg Guide 1.97 requirements...on August 23, 2001, main steam isolation valve limit switches did not have qualification packages to account for actual ambient temperature.

Inspection Report# : [2001010\(pdf\)](#)

Significance: N/A Dec 18, 2001

Identified By: NRC

Item Type: FIN Finding

PI&R Inspection Findings

The team identified that the licensee had an acceptable process to identify, prioritize, evaluate, and correct problems.

Station personnel identified problems and placed them into the problem identification and resolution program, with some exceptions noted. The team, however, identified a number of implementation problems. Numerous examples were identified where the licensee had improperly characterized and classified issues, which resulted in them being effectively removed from the problem identification and resolution program, two of these examples were found to be more than minor. Management meetings were conducted to review issues and determine the process to follow for resolution; however, these meetings were observed by the team to be less than fully effective. A number of other implementation problems involving documentation, engineering justification for changes to the facility, and the development of issue resolution dates were identified. Corrective actions from previously identified problems, such as conducting operability determinations/evaluations and the scaffolding program were not effective as evidenced by continuing problems in these two areas. Quality assurance audits and assessments were found to be critical of the problem identification and resolution program. However, the issues identified by these audits were not being corrected effectively, as evidenced by repeat findings in similar areas. Most station personnel interviewed stated they had no reservations raising safety issues to management. However, a review of the licensee's employee concerns program and a small number of interviews revealed some isolated instances where personnel were reluctant to raise issues.

Inspection Report# : [2001010\(pdf\)](#)

Significance: N/A Nov 04, 2000

Identified By: NRC

Item Type: FIN Finding

SUBSTANTIVE FINDING OF A CROSS-CUTTING HUMAN PERFORMANCE ISSUE FOR OPERABILITY DETERMINATIONS

IR 05000298-00-13; on 9/24-11/04/2000; Nebraska Public Power District; Cooper Nuclear Station, Integrated Resident & Regional Report. Maintenance Rule Effectiveness. The inspectors identified a trend with human performance, in determining operability of safety-related equipment, being the common element. This trend was evidenced by the following: • Ten months prior to this inspection, operations personnel failed to perform an operability determination for a reactor recirculation valve degraded condition (NCV 50-298/0004-02). • During the last 3 months, three additional examples of failures to perform operability determinations were identified (NCV 50-298/0013-01). The causal relationship of these errors was that operations personnel lacked a questioning attitude toward degraded or nonconforming conditions. Each of these individual findings could directly impact safety, based upon failures to recognize the potential loss of safety function(s) for safety-related equipment. The inspectors considered this performance trend to be a substantive cross-cutting issue, not captured in individual issues, indicating a performance trend. The significance determination process does not address such human performance issues. Therefore, this finding is considered to have no color (Section 4OA4).

Inspection Report# : [2000013\(pdf\)](#)



Significance: G Aug 25, 2000

Identified By: NRC

Item Type: VIO Violation

Failure to Take Prompt Corrective Actions

The licensee did not take timely corrective actions for restoration of environmentally qualified electrical and controls equipment control panels for the high pressure coolant injection system, which were not properly secured. Furthermore, the licensee did not implement measures through maintenance procedure revisions and corrective actions to address environmental qualification aspects of maintenance on safety-related equipment. This issue had previously been identified as a Non-Cited Violation in NRC Inspection Report 50-298/9916-01, yet actions to revise maintenance procedures and restore compliance had not been promptly taken and continued to be uncorrected 9 months after initial identification. No formally reviewed and approved analysis had been performed to justify not correcting the discrepant condition, which could affect equipment operability. Nonconformance conditions are required to be promptly corrected or sufficient interim compensatory measures established, or technical evaluations performed to justify the existing condition. The failure to establish prompt corrective actions for conditions adverse to quality was a violation of 10 CFR Part 50, Appendix B, Criterion XVI (50-298/0010-03) (Section 4OA2.3.b). This issue was characterized as a green finding using the significance determination process. The issue was determined to have very low risk significance because of redundant systems and the actual impact on the affected equipment was low.

Inspection Report# : [2000010\(pdf\)](#)



Significance: Jun 24, 2000

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO FOLLOW EQUIPMENT CONTROL AND TAGGING PROCEDURE

IR05000298-00-08; on 05/14-06/24/00; Nebraska Public Power District, Cooper Nuclear Station. Integrated Resident & Regional Report; Resident Inspection and Security. Maintenance workers failed to follow an administrative procedure for equipment control and tagging. The workers operated the drywell personnel airlock while a danger tag was hanging on it. Through interviews conducted with maintenance personnel, the inspectors found that workers did not have an adequate understanding of the controls and restrictions associated with equipment tagging. The inspectors considered this to be a crosscutting human performance issue. The failure to follow the procedure for equipment tagging was a violation of Technical Specification 5.4.1 (a). This violation is being treated as a noncited violation in accordance with Section VI.A of the NRC Enforcement Policy and is in the licensee's corrective action program as Problem Identification Report 4-09638. This noncited violation was characterized as a green finding using the significance determination process. It was determined to have very low risk significance because at least one drywell personnel airlock door remained operable at all times.

Inspection Report# : [2000008\(pdf\)](#)

Significance: N/A Sep 10, 1999

Identified By: NRC

Item Type: FIN Finding

CORRECTIVE ACTION PROGRAM ADEQUATE

PIM NRC FIN OTHER No Color 9/10/99 71152 Corrective action program adequate The corrective action program was generally implemented adequately across all cornerstones, with very low risk significance examples of untimely corrective actions. The licensee's self-assessments were appropriately focused on substantive performance improvement areas. Licensee management identified improving ownership, accountability, and support as a site-wide improvement area and was developing improvement plans at the end of the inspection.

Inspection Report# : [1999003\(pdf\)](#)

Last modified : December 02, 2002