

Comanche Peak 1

1Q/2003 Plant Inspection Findings

Initiating Events

Significance:  Oct 07, 2002

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

Inadequate Procedure to Test Lockout Relay in 345 kV Switchyard Resulted in Loss of Shutdown Cooling

An inadequate maintenance procedure for testing the lockout relays on the East bus in the 345 kV switchyard resulted in the loss of residual heat removal shutdown cooling. The procedure failed to state that actuation of a relay would cause loss of power to both Unit 1 safety related 6.9 kV buses. A self-revealing non-cited violation of Technical Specification 5.4.1.a was identified. The finding is greater than minor in that it was associated with the procedure quality attribute of the initiating events cornerstone and affected the cornerstone objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during a shutdown. The finding is of very low safety significance because reactor cavity level was greater than 23 feet above the reactor vessel flange and residual heat removal cooling was recovered within 8 minutes.

Inspection Report# : [2002005\(pdf\)](#)

Mitigating Systems

Significance:  Dec 06, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to test interlock circuits for residual heat removal system cross-tie valves

The inspectors identified one finding, which was a violation of NRC regulatory requirements. The inspectors found that the licensee had failed to fully and routinely test the control circuits for the residual heat removal system cross-tie valves (two per unit), which are opened from the control room to provide suction to the charging and safety injection pumps during intermediate pressure cold leg recirculation following a loss-of-coolant accident. During the inspection, to address the inspectors' concerns, the licensee performed special tests, which revealed that a limit switch for one interlock for a Unit 1 valve failed to close as required, and wiring connections for another interlock on a Unit 2 valve were loose. The licensee determined that the remaining parts of the degraded interlock circuits were intact, and concluded that these as-found conditions would not have prevented the operator from opening the valves for the recirculation mode. Despite the problems encountered, the system and its trains would have performed their safety function with the proper valve line up. The inspectors concluded that failure to routinely test these circuits and detect these failures was a noncited violation of 10 CFR Part 50, Appendix B, Criterion XI, Test Control. Criterion XI requires a licensee establish a test program to assure identification and performance of all testing required to demonstrate that systems and components will perform satisfactorily in service. The inspectors considered the finding greater than minor because the lack of testing affected the reliability of a mitigating system. The inspectors considered the risk significance to be green because there was not an actual loss of a train of risk significant equipment. This violation is being treated as a noncited violation consistent with Section VI.A.1 of the NRC Enforcement Policy (50-445;446/0208-01). This violation is in the licensee's corrective action program as SmartForms 2002-004158, 2002-

004227, and 2002-004228.

Inspection Report# : [2002008\(pdf\)](#)

G

Significance: Oct 05, 2002

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

Inadequate Low Temperature Overpressure Protection (LTOP) surveillance procedure resulted in Train B RHR Being Inoperable

An inadequate calibration procedure for the low temperature overpressure protection (LTOP) temperature channel resulted in Train B residual heat removal system being inoperable while Technical Specification 3.9.6 required both trains to be operable. The procedure failed to state that the performance of the surveillance would interlock closed the reactor coolant system hot leg to Train B residual heat removal pump suction Valve 1-8702B. This self-revealing, noncited violation of Technical Specification 5.4.1.a. was first documented in NRC Inspection Report 50-445/02-05; 50-446/02-05 as an unresolved item (URI 50-445/0205-01) pending a Phase 2 analysis. This finding is greater than minor because it was associated with the mitigating systems attribute of equipment availability and affected the cornerstone objective to ensure the availability of a mitigating system. This violation degraded the safety of a shutdown reactor, and in accordance with Inspection Manual Chapter 0609, Appendix G, the shutdown safety function of the core heat removal guidelines was not met. Since the finding degraded the ability to recover decay heat removal once it was lost, a Phase 2 analysis was required. Because the Phase 2 shutdown risk tool is currently in draft, the analyst completed a Phase 3 analysis. This analysis resulted in the significance of this violation being very low (GREEN). This was primarily due to: (1) the operators having two methods to realign Train B RHR to the decay heat removal mode and both were achievable within 10 minutes; and (2) the available water in the RWST provided 9 hours of inventory and the water in the cavity increased the time to boil.

Inspection Report# : [2002006\(pdf\)](#)

Barrier Integrity

G

Significance: Nov 01, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Two Examples of Failure to Identify and Correct Steam Generator Tube Flaws

Inspectors identified a non-cited violation of 10 CFR Part 50, Appendix B, Criterion XVI for two examples of failure to perform adequate steam generator eddy-current examination in the 2002 refueling outage (1RF09). The inadequate examinations resulted in analyst failure to properly characterize two steam generator tube flaws until the licensee took corrective actions in response to questions from the NRC inspectors. This finding is greater than minor because it degraded the ability to meet the cornerstone objective of reactor coolant system pressure boundary. The failure to identify the flaws could have resulted in flawed tubes that might have developed leaks if left in service. The significance of this finding is very low because the in situ tests demonstrated that the tubes would have met the design basis requirements for withstanding analyzed transients, and prior to returning the plant to operation the licensee removed the flawed tubes from service.

Inspection Report# : [2002009\(pdf\)](#)

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Significance:  Dec 13, 2002

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

Failure to properly classify a radioactive material shipment package as Surface Contaminated Object-II.

A self-revealing non-cited violation of 49 CFR 173.421 was identified because the licensee failed to properly classify a shipment package as Surface Contaminated Object (SCO)-II, Schedule 8. On May 1, 2002, box number 300125 included in Radioactive Material Shipment 2002-0039 was classified by the licensee as limited quantity based on a maximum exterior surface dose rate of 0.4 millirem per hour measured prior to shipment. However, on May 9, 2002, receipt surveys performed by Westinghouse personnel showed that the maximum dose rate on the exterior surface of the box was 2.4 millirem per hour, which exceeded the 0.5 millirem per hour limit for a limited quantity package. The team determined that this issue was self-revealing rather than licensee identified because the issue was identified during receipt surveys by the recipient of the radioactive materials shipment. The failure to properly classify box number 300125 as SCO-II was a performance deficiency. The finding was determined to be more than minor because it was associated with one of the Public Radiation Safety cornerstone attributes (Transportation Program) and affected the associated cornerstone objective. Using the Public Radiation Safety Significance Determination Process, the team determined the finding had very low safety significance because radiation limits for SCO-II were not exceeded, the package was not breached during transit, no certificate-of-compliance problem was involved, there was no low level burial ground nonconformance, and the licensee did not fail to make notifications. This violation is being treated as a non-cited violation consistent with Section VI.A.1 of the NRC Enforcement Policy. This violation is in the licensee's corrective action program as Smart Form SMF-2002-001873.

Inspection Report# : [2002010\(pdf\)](#)

Significance:  Dec 13, 2002

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

Failure to control detectable licensed radioactive material.

A self-revealing non-cited violation of Technical Specification 5.4.1a was identified because the licensee did not prevent the release of detectable licensed radioactive material from the radiologically controlled area. Specifically, Procedure RPI-213, "Survey and Release of Material and Personnel," Revision 8, Section 4.2.1, states, in part, that the criteria for unconditional release from an Radiologically Controlled Area is no detectable activity. However, on November 12, 2002, a contract worker was discovered with radioactive material on his lanyard during an in-processing whole body count at another licensee's facility. The individual last worked at Comanche Peak Steam Electric Station. The team determined that this example was self-revealing rather than licensee identified because the example was found by another licensee. The failure to properly control detectable licensed radioactive material is a performance deficiency. The finding was more than minor because it was associated with one of the Public Radiation Safety cornerstone attributes (Material Release Program) and affected the associated cornerstone objective. Using the Public Radiation Safety Significance Determination Process, the team determined the finding had very low safety significance because there were not more than 5 occurrences and the exposure associated with each item was less than 5 millirem. This violation is being treated as a non-cited violation consistent with Section VI.A.1 of the NRC Enforcement Policy.

This violation is in the licensee's corrective action program as Smart Form SMF-2002-3975.
Inspection Report# : [2002010\(pdf\)](#)

Significance: N/A Apr 25, 2002

Identified By: NRC

Item Type: FIN Finding

Supplemental Inspection Results

A supplemental inspection was performed by the NRC to assess the licensee's evaluation of the control of radioactive material. A finding previously characterized as having low to moderate safety significance (White) was documented in the Final Significance Determination for NRC Inspection Report 50-445/01-07; 50-446/01-07. During this supplemental inspection performed in accordance with Inspection Procedure 95001, the inspector determined that the licensee performed a thorough, broad-based evaluation of the causes of the radioactive material control issue and correctly identified the extent of the conditions that led to the control problems. The licensee's evaluation identified 17 root causes. Corrective actions included: (1) conducting a pre-outage stand-down with all station work groups to discuss the past associated problems and the importance for control of radioactive material; (2) procedural revisions that clarified radioactive material control expectations and identification programs; (3) improved Radiation Worker Training lesson plans that stressed the need for and the controls in-place for handling radioactive material; and, (4) increased staffing for monitoring and controlling the release of radioactive material during outages. An effectiveness evaluation of radiation protection activities, to include the control of radioactive material, will be documented in Nuclear Oversight Department Evaluation 2002-015, at the completion of refueling outage 2RFO6. Because of the licensee's acceptable performance in addressing the control of radioactive material, the White finding associated with this issue will only be considered in assessing plant performance for a total of four quarters, in accordance with the guidance in IMC 0305, "Operating Reactor Assessment Program."

Inspection Report# : [2002007\(pdf\)](#)

Physical Protection

Miscellaneous

Last modified : May 30, 2003