

Grand Gulf 1

2Q/2003 Plant Inspection Findings

Initiating Events

Significance:  Dec 27, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to prescribe instructions for tightening a reactor recirculation system flange allows unquantifiable torquing of bolts which construct part of the reactor coolant system boundary.

A noncited violation of 10 CFR 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified for failure to establish appropriate instructions for restoration of a reactor recirculation Loop B decontamination flange which resulted in improper torquing of flange bolting and degrading a reactor coolant system pressure boundary. This issue was documented in the licensee's corrective action program as CR-GGN-2002-1988. The noncited violation is greater than minor because it was related to the initiating events cornerstone objective of limiting the likelihood of an initiating event in the form of a loss of coolant from the flanged pressure boundary. The finding was of very low safety significance because although the bolts were improperly torqued and would have been exposed to reactor coolant system pressure, the bolts were replaced by the licensee prior to taking the reactor coolant system to operating pressure due to inspector intervention.

Inspection Report# : [2002005\(pdf\)](#)

Mitigating Systems

Significance:  Jun 28, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Apply Adequate Design Control Measures Lead to Increased Agastat Relay Failure Rate

The inspectors identified a noncited violation of Criterion III of Appendix B to 10 CFR Part 50 for failure to assure adequate design controls were in place such that Agastat® General Purpose relays would be replaced prior to exceeding their design basis life. As a result, 15 out of 17 failed relays in an 18 month period had exceeded their design basis lives; including 4 relays having one or more contacts that would not perform their safety actuation. This finding is greater than minor because, if the condition were left uncorrected it would become a more significant safety concern. Specifically, the affected safety-related systems would have a lower reliability and availability since the failure rate of relays used beyond their service life is significantly higher than those relays that are within their service life. A Significance Determination Process, Phase 3 analysis was performed by the Senior Reactor Analyst in Region IV. It considered the impact of the 4 relays that failed to initiate functions. The 4 relays impacted standby service water to the control room air conditioning system and five containment/drywell isolation valves. The analysis was based on a set of core damage sequences that would initiate from normal operations, but only progress given a loss-of-offsite-power or a loss-of-coolant-accident. The core damage sequence would continue only if the loss of control room air conditioning progressed to a point that control room instrumentation began to fail as a result of high temperatures and operators were required to evacuate the control room. Finally, for core damage to occur, operators would have had to fail to properly shutdown the reactor from the alternate shutdown panel. The analysis indicated that, given this core damage sequence,

the estimated change in core damage probability was 7.0×10^{-8} , and the change in large early release probability was 1.4×10^{-8} . The conclusion of this analysis characterized the performance deficiency as an issue of very low safety significance. The licensee implemented an aggressive campaign to replace the affected relays.
Inspection Report# : [2003002\(pdf\)](#)

Significance:  May 09, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to provide procedural instructions for restoring the instrument air system following a loss of instrument air.

The team identified a noncited violation of Technical Specification 5.4.1 for failure of Grand Gulf Nuclear Station to provide an adequate procedure for restoring the instrument air system following a loss of instrument air. The procedure failed to provide instructions on how to provide seal air and control air to the instrument air compressor from a temporary source. This failure resulted in operation of the unit one instrument air compressor in an abnormal configuration which caused damage to its inlet valve and the licensee's inability to restore instrument air header pressure with that compressor. This issue was documented in the licensee's corrective action program as condition report 2003-1347. This finding was evaluated using the Significance Determination Process and determined to be of very low safety significance. The finding is greater than minor because it affected the mitigating systems cornerstone objective as described in NRC Manual Chapter 0612 involving the ability to ensure the availability, reliability, and capability of systems that respond to initiating events. The finding was of very low safety significance because although the recovery of instrument air was delayed, all mitigating safety system functions remained available.
Inspection Report# : [2003007\(pdf\)](#)

Significance:  Mar 13, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Determine Cause of Single Relay Contact Failure-to-Transition

A noncited violation of Criterion XVI of Appendix B to 10 CFR Part 50 was identified for the failure to adequately identify the cause of relay contact failures-to-transition, a significant condition adverse to quality, and corrective actions to prevent recurrence. This finding is greater than minor because, if the condition were left uncorrected, it would become a more significant safety concern. Specifically, the failure to understand the failure mechanism behind the failure mode mentioned above would impede the licensee's ability to control that failure mechanism and could lead to additional failures of safety-related equipment to actuate when called upon. The finding was determined to be of very low risk significance since no other failures of this type have been experienced since the discovery of the initial five failures

Inspection Report# : [2003006\(pdf\)](#)

Significance:  Jan 24, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to energize required heat tracing at two fire hose stations located in the emergency diesel generator breeze way during prolonged freezing periods.

A noncited violation of Technical Specification 5.4.1.a was identified for failure to provide an adequate administrative procedure for establishing freeze protection measures in the form of heat tracing to fire hose stations located in the emergency diesel generator breezeway. On January 24, 2003, during prolonged freezing temperatures, two fire hose station's heat trace was found unplugged and de-energized. This issue was documented in the licensee's corrective action program as Condition Report CR-GGN-2003-0227. This finding was evaluated using the Significance

Determination Process and determined to be of very low safety significance. The finding is greater than minor because it affected the mitigating systems cornerstone objective as described in NRC Manual Chapter 0612 involving protection against external factors such as fire. The finding was of very low safety significance because, although the fire hose station's heat trace was not energized, it had not frozen and was restored in a timely manner due to inspector intervention.

Inspection Report# : [2002006\(pdf\)](#)



Significance: Dec 27, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate corrective actions associated with operating the residual heat removal system heat exchanger outlet valve (E12-F003A) beyond its optimum throttling range leads to excessive system vibratio

A noncited violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," was identified for inadequate corrective actions which resulted in operating the residual heat removal system heat exchanger outlet Valve (E12-F003A) beyond its optimum throttling range causing small bore piping failures. This issue was documented in the licensee's corrective action program as CR-GGN-2002-1779. This self-revealing noncited violation is greater than minor because it affected the mitigating systems cornerstone objective of equipment reliability, in that operation of this valve beyond its optimum throttling capability would lead to system small bore piping failures. The finding was of very low safety significance because all other emergency core cooling systems remained available.

Inspection Report# : [2002005\(pdf\)](#)



Significance: Dec 27, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate design controls associated with adding a permanent pressure locking modification to a residual heat removal system valve resulted in low stress high cycle fatigue whenever the residual heat

A noncited violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," was identified for inadequate design controls which resulted in a pressure locking design modification being completed without provisions for adequate piping supports resulting in a small bore piping failure. This issue was documented in the licensee's corrective action program as CR-GGN-2002-1779. This self-revealing noncited violation is greater than minor because it affected the Mitigating Systems Cornerstone objective of equipment reliability, in that the inadequate design of the pressure locking piping modification allowed cyclic stress to cause a failure of a small bore piping socket weld. The finding was of very low safety significance because all other emergency core cooling systems remained available.

Inspection Report# : [2002005\(pdf\)](#)



Significance: Oct 04, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Performance of maintenance using an inadequate procedure leads to isolation of the reactor core cooling isolation system

Performance of maintenance using an inadequate procedure leads to isolation of the reactor core cooling isolation system. The licensee failed to establish appropriate instructions for the circumstances when backfilling the reactor core isolation cooling high steam flow transmitter. This resulted in technicians improperly backfilling the detector. This caused the detector to isolate steam to the reactor core isolation cooling turbine, rendering the system inoperable. This violation of Technical Specification 5.4.1 is noncited in accordance with Section VI.A of the NRC's Enforcement Policy, and is in the licensee's corrective action program (CR-GGN-2002-0947). The finding was of very low safety significance because although the reactor core isolation cooling system was inoperable, all other remaining mitigating

systems remained operable and the duration of the system inoperability was short.

Inspection Report# : [2002004\(pdf\)](#)

Significance:  Sep 17, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate alternative shutdown procedure

A noncited violation of Technical Specification 5.4.1.a was identified for the failure to provide an adequate procedure for a control room fire. Technical Specification 5.4.1.a, requires the licensee to establish procedures for implementation of activities recommended in Regulatory Guide 1.33, which lists procedures for combating a fire in the control room and forced evacuation of the control room. The licensee's Alternative Shutdown Procedure 05-1-02-II-1, "Shutdown from the Remote Shutdown Panel," Revision 25, was inadequate, because it did not instruct operators to verify that a flow diversion pathway was closed, which could render the credited reactor vessel injection source unable to perform its safety function. In the event of a fire in the control room requiring control room evacuation and remote shutdown, this pathway could have diverted coolant to containment spray and away from the reactor vessel through a spuriously opened containment spray valve. Operators would not normally check the valve position on their own and would not have adequate indication from the remote shutdown panel to identify the potential flow diversion path. The licensee entered this finding into their corrective action program as Condition Report CR-GGN-2002-01460. The issue was of greater than minor significance because it impacted the mitigating systems cornerstone and affected the ability of the low pressure coolant injection system to provide adequate core cooling to prevent core damage. Using the Phase 2 Significant Determination Process, this finding was determined to be of very low safety significance, due to the extremely low fire ignition frequency in conjunction with the low probability that fire would cause the spurious opening of the containment spray valve (Section 1R05.3).

Inspection Report# : [2002007\(pdf\)](#)

Significance:  Sep 17, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to protect radio repeaters

A noncited violation of Grand Gulf Nuclear Station, License Condition 2.C(41), which requires the licensee to implement and maintain the provisions of their NRC-approved fire protection program, was identified. The licensee failed to meet the fire protection program requirement to protect radio repeaters from exposure to fire damage in six fire areas; therefore, in the event of a fire in any one of these fire areas, radio communications necessary to support safe shutdown could be lost. The licensee entered this finding into their corrective action program as Condition Report CR-GGN-2002-1472. The issue was of greater than minor significance because it impacted the mitigating systems cornerstone objective. Specifically, ineffective fire brigade communications can hamper the brigade's ability to fight a fire, thereby, potentially endangering mitigating systems. A Phase 1 Significant Determination Process evaluation determined that the issue has very low safety significance (Green) because the problem only impacts the effectiveness of the fire brigade while other fire protection features, such as fire barriers and physical separation, remain available (Section 1R05.4).

Inspection Report# : [2002007\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Physical Protection

Significance:  Feb 15, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

A visitor without unescorted access was found alone without a required escort in a temporary shelter erected in the protected area for inspections of the standby service water system basins.

A noncited violation of Section 2.E of the Grand Gulf Nuclear Station (GGNS) facility operating license was identified for failure to comply with Section 6.2, "Access Controls," of the GGNS Security Plan. On February 15, 2003, a GGNS employee, performing access control escort duties, failed to control the access of a visiting contractor who was not authorized by the licensee to enter or remain in the protected area without an escort. This issue was documented in the licensee's corrective action program as Condition Report CR-GGN-2003-0544. This finding was evaluated using the Significance Determination Process and determined to be of very low safety significance. The finding is greater than minor because it affected the physical protection cornerstone objective as described in NRC Manual Chapter 0612 involving unescorted visitor access controls. The finding was of very low safety significance because, although the unescorted visitor was found alone, the individual had no intentions of malevolent acts and there had not been two similar findings in the previous four quarters.

Inspection Report# : [2002006\(pdf\)](#)

Significance: N/A Dec 06, 2002

Identified By: NRC

Item Type: FIN Finding

Verification of Compliance With Interim Compensatory Measures Order

On February 25, 2002, the NRC imposed by Order, Interim Compensatory Measures to enhance physical security. The inspectors determined that, overall, the licensee appropriately incorporated the Interim Compensatory Measures into the site protective strategy and access authorization program; developed and implemented relevant procedures; ensured that the emergency plan could be implemented; and established and effectively coordinated interface agreements with offsite organizations.

Inspection Report# : [2002008\(pdf\)](#)

Miscellaneous

Last modified : September 04, 2003