

Robinson 2

3Q/2003 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Jun 14, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Adequately Implement a Safety Injection and Containment Vessel Spray System Operating Procedure

Green. A failure to adequately implement an operating procedure resulted in the mispositioning of a vent valve in the safety injection (SI) system. A non-cited violation of Technical Specification 5.4.1 was identified. This finding is greater than minor and had credible impact on safety. The finding had the potential for affecting the mitigating systems cornerstone equipment, including, loss of reactor water storage tank level, flooding of the SI pump room and subsequent loss of SI and containment spray pumps due to flooding. The finding is of very low safety significance (Green) because any significant leakage would have caused the auxiliary building sump level to increase, alerting the control room. Further, the pipe cap downstream of the mispositioned valve had not exhibited any leakage.

Inspection Report# : [2003004\(pdf\)](#)

Significance:  Jun 14, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Follow Load Rejection Abnormal Operating Procedure

Green. A failure to follow an abnormal operating procedure resulted in an improper increase in turbine load for the purpose of temperature control. A non-cited violation of Technical Specification (TS) 5.4.1 was identified for failure to follow Abnormal Operating Procedure (AOP)-15, Secondary Load Rejection. The procedure requires, under specific conditions, the operators to either insert control rods or borate the reactor coolant system for the purposes of temperature control. However, subsequent to receipt of a turbine runback, increasing turbine load was used for temperature control. This finding affected mitigating systems cornerstone equipment. The finding had a credible impact on safety and is greater than minor because the turbine load action was non-conservative. The finding was determined to be of very low safety significance (Green) because TS limits were not exceeded and the power increase from the turbine load increase following the runbacks was very small and did not approach reactor protection system setpoints.

Inspection Report# : [2003004\(pdf\)](#)

Significance:  Dec 31, 2002

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to adequately implement procedure OPS-NGGC-1301, Equipment Clearances

Green. A failure to adequately implement an equipment clearance procedure resulted in an extended unavailability and inoperability of the B motor driven auxiliary feedwater (MDAFW) pump. A non-cited violation of Technical Specification (TS) 5.4.1 was identified. This finding is greater than minor as the clearance error extended the total unavailability and inoperability of the B MDAFW pump beyond that originally planned. The finding is of very low safety significance as the total inoperability of the B MDAFW pump did not exceed TS allowed outage time and both the A MDAFW train and the steam driven auxiliary feedwater pump were operable.

Inspection Report# : [2002004\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Significance:  Aug 22, 2003

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

FAILURE TO COMPLY WITH DOT REQUIREMENTS FOR NON-FIXED, EXTERNAL RADIOACTIVE CONTAMINATION LIMITS FOR A SPENT FUEL SHIPMENT PACKAGE

Green. A self-revealing non-cited violation of 10 CFR 71.5(a), 10 CFR 71.87(i) and 49 CFR 173.443(b) was identified because the licensee transported a shipment of spent fuel, as exclusive use, to the Harris plant with levels of removable radioactive contamination which were approximately two times the Department of Transportation (DOT) regulatory limit. This finding is greater than minor because it was associated with the transportation packaging attribute of the Public Radiation Safety Cornerstone and adversely effected the cornerstone objective to ensure adequate protection of the public health and safety from exposure to radioactive materials released into the public domain. The finding is of very low safety significance because the location of the contamination was inaccessible to the public during transport and the contamination found was less than 5 times the regulatory limit.

Inspection Report# : [2003010\(pdf\)](#)

Public Radiation Safety

Physical Protection

Miscellaneous

Last modified : December 01, 2003