

Ginna

4Q/2003 Plant Inspection Findings

Initiating Events

Significance:  Dec 31, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO IMPLEMENT PROCEDURES FOR SEVERE WEATHER

Green. The inspectors identified that although the Ginna site was experiencing high winds, control room operators did not implement the site adverse weather plan contained in procedures EPIP 1-17, "Planning for Adverse Weather," and ER-SC-1, "Adverse Weather Plan," until prompted by the inspector. Following implementation of ER-SC-1, operators manually tripped the reactor as required by Abnormal Operating Procedure AP-RCS.2, "Loss of Reactor Coolant Pump Flow," when an offsite power supply was lost because of storm-related damage. The failure to implement EPIP 1-17 and ER-SC-1 is a violation of Technical Specification 5.4.1.

This finding is associated with the "Protection Against External Factors" attribute of the initiating events cornerstone. This finding is greater than minor because it affected the objective of limiting the likelihood of those events that upset plant stability during power operation in that the severe weather caused a reactor trip. Since operators responded appropriately to the loss of the 751 line, the finding is of very low safety significance because it did not contribute to the likelihood of a primary or secondary system LOCA initiator, or to both the likelihood of a reactor trip and the likelihood that mitigation equipment or functions would not be available. Additionally, the finding did not increase the likelihood of a fire or internal/external flood. (Section 1R01)

Inspection Report# : [2003007\(pdf\)](#)

Mitigating Systems

Significance:  Dec 31, 2003

Identified By: NRC

Item Type: FIN Finding

FAILURE TO PROPERLY SEQUENCE WORK ACTIVITIES DURING SURVEILLANCE TESTING

Green. The inspectors identified that RG&E had performed maintenance on four main steam safety valves prior to performing required surveillance testing. This practice may mask the as-found condition of the valves, and affect the results of the surveillance tests.

This finding is greater than minor, because it is associated with the "Equipment Performance" (reliability) attribute of the mitigating systems cornerstone, and it would adversely affect the cornerstone objective because failure to conduct as-found testing may mask any valve degradation. This could adversely impact the reliability of the steam generator overpressure protection system to prevent undesirable consequences. The finding is of very low safety significance because it was not a design or qualification deficiency, it did not represent a loss of safety function, and was not potentially risk significant due to seismic, flood, fire, or weather related initiating event. Further, the finding is of very low safety significance since the issue involved inadequate testing, and did not degrade the ability of the main steam

safety valves to perform their intended function for the next operating cycle. (Section 1R19)

Inspection Report# : [2003007\(pdf\)](#)

Significance:  Dec 31, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO CORRECTLY ASSESS RISK OF MAINTENANCE ACTIVITIES

Green. The inspectors identified a non-cited violation of 10 CFR 50.65 (a)(4) when RG&E personnel installed an incorrect version of the risk analysis program on the plant intranet server. The program incorrectly modeled the impact of removing emergency diesel generators from service. RG&E personnel installed the correct version of the software when the error was identified by the inspectors.

After management review, this finding was determined to be greater than minor, because the plant risk analysis assessments, which RG&E schedulers and operations personnel had performed on several occasions, were incorrect, and in one case on November 18, 2003, unbeknownst to Ginna personnel, the plant was in an elevated risk condition. If left uncorrected, this finding could become a more significant safety concern since with the incorrect software installed, operators could not correctly assess the impact on plant risk of maintenance on mitigating systems. The safety significance of the finding was very low, because the plant was not in a high risk condition at any time during the period that the wrong program was installed. (Section 1R13)

Inspection Report# : [2003007\(pdf\)](#)

Significance:  Dec 31, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

AUXILIARY FEEDWATER FLOWPATH INOPERABLE DURING MODE CHANGES, DUE TO PERSONNEL ERROR, RESULTED IN CONDITION PROHIBITED BY TECHNICAL SPECIFICATIONS

Green. A self-revealing non-cited violation of Ginna Station Technical Specification (TS) Limiting Condition for Operation (LCO) 3.0.4 was identified when plant operators conducted PT-16Q-T after transition to Mode 2 from Mode 4 and found that flow could not be achieved from the turbine driven auxiliary feedwater (TDAFW) pump to the "B" steam generator. The line had been isolated through a sequence of lineup and testing, which was conducted prior to the Mode change that did not properly restore the system to the required line-up for the Mode change. The flow path was immediately restored by RG&E personnel when the deficiency was discovered. Procedures will be revised to minimize the possibility of event recurrence.

This finding, associated with the "Configuration Control" attribute of the mitigating systems cornerstone, is greater than minor because it affected the objective of ensuring the reliability and capability of systems to prevent undesirable consequences in that the TDAFW system was inoperable for three days. The finding is of very low safety significance because it was not a design or qualification deficiency, it did not represent a loss of safety function (the remaining diverse trains of AFW remained operable), and was not potentially risk significant due to seismic, flood, fire, or weather related initiating events. Further, the exposure time was less than the LCO action time of seven days. (Section 4OA3)

Inspection Report# : [2003007\(pdf\)](#)

Significance:  Oct 28, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PROMPTLY IDENTIFY AND TAKE ACTIONS TO ADDRESS A CONDITION ADVERSE

TO QUALITY CONCERNING CONTAINMENT SUMP SCREEN BYPASS FLOWPATHS

Green. The inspectors identified a non-cited violation of 10 CFR Part 50, Appendix B, Criterion XVI, Corrective Actions, for RG&E's failure to promptly identify and take actions to address a condition adverse to quality. Specifically, RG&E did not promptly identify and correct several longstanding containment sump screen bypass flowpaths that had the potential to adversely impact emergency core cooling systems (ECCS) during containment recirculation.

The finding was more than minor because it affected the Mitigating Systems cornerstone objective of ensuring the availability, reliability, and capability of ECCS to respond to initiating events (loss-of-coolant accidents (LOCAs)) to prevent undesirable conditions. The finding was associated with the design control and human performance attributes. The finding was considered to be of very low safety significance, because ECCS remained operable and there was no loss of safety function. Specifically, the finding did not represent an actual loss of ECCS function or of a single train that mitigates internal or external event (e.g., seismic, fire, flooding, or severe weather) core damage accident sequences. (Section 40A3.1)

Inspection Report# : [2003012\(pdf\)](#)

G

Significance: Oct 28, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PROMPTLY IDENTIFY AND TAKE ACTIONS TO ADDRESS A CONDITION ADVERSE TO QUALITY CONCERNING CONTAINMENT SUMP DEBRIS

Green. The inspectors identified a non-cited violation of 10 CFR Part 50, Appendix B, Criterion XVI, Corrective Actions, for RG&E's failure to promptly identify and take actions to address a condition adverse to quality. Specifically, RG&E did not promptly identify and correct containment sump debris that had the potential to adversely impact ECCS during containment recirculation.

The finding was more than minor because it affected the Mitigating Systems cornerstone objective of ensuring the availability, reliability, and capability of ECCS to respond to initiating events (LOCAs) to prevent undesirable conditions. The finding was associated with the procedure quality and human performance attributes. The finding was considered to be of very low safety significance, because ECCS remained operable and there was no loss of safety function. Specifically, the finding did not represent an actual loss of ECCS function or of a single train that mitigates internal or external event (e.g., seismic, fire, floodnig, or severe weather) core damage accident sequences.

Inspection Report# : [2003012\(pdf\)](#)

G

Significance: Sep 27, 2003

Identified By: NRC

Item Type: FIN Finding

RG&E did not have procedures to address potential high temperature conditions in the relay room.

The inspectors identified that RG&E did not have compensatory measures in place to prevent the air temperature in the relay room from exceeding the maximum values described in the plant Updated Final Safety Analysis Report (UFSAR). High air temperatures in the relay room would degrade the performance of safety-related components located in that room.

Inspection Report# : [2003006\(pdf\)](#)

G

Significance: Sep 27, 2003

Identified By: NRC

Item Type: FIN Finding

The RG&E vendor manual control program did not ensure information regarding maintenance of the lube oil circulation pump for the "A" motor driven AFW pump was supplied to maintenance personnel.

The RG&E vendor manual control program was inadequate in that it did not ensure maintenance personnel were provided with the information needed to properly rebuild the lubricating oil circulation pump for the "A" motor driven auxiliary feedwater pump. As a result, the pump was not properly assembled during maintenance activities.

Inspection Report# : [2003006\(pdf\)](#)

Significance:  Sep 27, 2003

Identified By: Self Disclosing

Item Type: NCV NonCited Violation

Operators did not shutoff the "B" AFW Pump when the AFW system coss-tie valves are opened resulting in damage to the "B" AFW pump.

A self-revealing non-cited violation of Technical Specification 5.4.1.a was identified due to the operating crew not correctly implementing procedures ES-0.1 "Reactor Trip Response." This resulted in a period of inoperability for the "B" motor driven auxiliary feedwater pump.

A contributing cause of this finding is related to the Human Performance cross-cutting area. Inadequate placekeeping in the procedure by the operating crew resulted in the omission of the step to shutdown the "B" motor driven auxiliary feedwater pump.

Inspection Report# : [2003006\(pdf\)](#)

Significance:  Apr 17, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Maintain the Ventilation over the SI and CS Pumps in Accordance with the Design Basis

The inspectors identified a non-cited violation of 10 CFR 50, Appendix B, Criterion III, for failure to support the ventilation ductwork over the safety injection (SI) and containment spray (CS) pumps, as assumed in the seismic design evaluation. In addition, the required supports were not included on the design drawings associated with the ventilation for the SI and CS pumps.

The finding is greater than minor because it affects the design control attribute of the mitigating system cornerstone objective to maintain the reliability of mitigating system equipment. The finding adversely impacts the reliability of the SI pumps and CS pumps to remain functional subsequent to a postulated seismic event, since the seismic class I ductwork and supports were not installed and configured consistent with the design analysis. The finding is of very low safety significance because it involved a qualification deficiency that did not result in a loss of function and the affected pumps remained operable.

Inspection Report# : [2003002\(pdf\)](#)

Significance:  Mar 29, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Mitigation procedures for a control room fire were not accurate

The inspectors identified a non-cited violation of Technical Specification 5.4.1.d; which requires, in part, that procedures be established, implemented, and maintained covering the fire protection program. Contrary to the above, RG&E did not maintain procedures that described how the Control Room Emergency Air Treatment System (CREATS) should be operated if a fire occurred in the control room.

Inspection Report# : [2003003\(pdf\)](#)

Significance:  Mar 29, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Intermittent control room roof leakage not identified and repaired

The inspectors identified that ongoing water leakage through the control room roof had not been entered into the RG&E corrective action program. The roof had been leaking intermittently since the last time it had been repaired in 2000. A Green non-cited violation was identified for a failure of RG&E to identify and correct a degraded condition as required by 10 CFR 50 Appendix B Criterion XVI.

Inspection Report# : [2003003\(pdf\)](#)

Significance: N/A Mar 29, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Three SRO licensed operator certifications were not renewed by RG&E

The inspectors identified a non-cited violation in which three senior reactor operator (SRO) licenses had expired without the appropriate renewal forms being submitted. Two of these individuals improperly fulfilled Technical Specification positions that required an SRO license from October 2, 2002, to October 11, 2002.

Inspection Report# : [2003003\(pdf\)](#)

Barrier Integrity

Significance:  Sep 27, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Personnel did not properly sequence work activities and contrary to procedure requirements, allowed work to be performed on the spent fuel pool ventilation system when irradiated fuel was being moved.

While observing maintenance activities on the spent fuel pool system charcoal filtration system, the inspectors identified that contrary to requirements in the applicable maintenance procedure, RG&E personnel were working on the system when spent fuel was being moved in the spent fuel pool. The failure to correctly implement the maintenance procedure was a violation of Technical Specification (TS) 5.4.1.a which states, in part, that procedures shall be established, implemented and maintained.

Inspection Report# : [2003006\(pdf\)](#)

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Physical Protection

Miscellaneous

Significance:  Mar 29, 2003

Identified By: NRC

Item Type: FIN Finding

RG&E did not have procedures that described when Self Contained Breathing Apparatus should be used by control room personnel.

The inspectors identified that RG&E did not provide control room operators with guidance regarding when they should use the self contained breathing apparatus (SCBA) located in the control room. Chapter 6.4.2.2.2 of the Ginna UFSAR and Licensee Event Report (LER) 2002-002 indicate operators would use the SCBAs if toxic gas or airborne particulate activity was detected in the control room.

Inspection Report# : [2003003\(pdf\)](#)

Last modified : March 02, 2004