

## Calvert Cliffs 2

### 1Q/2006 Plant Inspection Findings

---

#### Initiating Events

**G****Significance:** Jun 28, 2003

Identified By: Self-Revealing

Item Type: FIN Finding

**Troubleshooting Human Performance Error Results in a Reactor Trip**

The inspectors identified a finding because the work practices during a turbine governor valve control circuit troubleshooting activity were inadequate and resulted in a reactor trip.

This finding is greater than minor because it affected an attribute and the objective of the Initiating Events Cornerstone in that the work practices inadequacies resulted in a perturbation in plant stability by causing a reactor trip. The finding is of very low safety significance in accordance with Phase 1 of the reactor safety SDP because, although it caused a reactor trip, it did not increase the likelihood of a primary or secondary system loss of coolant accident initiator, did not contribute to a combination of a reactor trip and loss of mitigation equipment functions, and did not increase the likelihood of a fire or internal/external flood.

Inspection Report# : [2003003\(pdf\)](#)

---

#### Mitigating Systems

**G****Significance:** Nov 18, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

**Failure to identify and correct unavailability problems for the turbine drive AFW pump.**

The NRC identified a Green non-cited violation (NCV) of Technical Specification (TS) 5.4.1 due to an inadequate procedure for installation and adjustment of packing for the 22 turbine-driven auxiliary feedwater (TDAFW) pump, which led to premature pump shutdown during a quarterly surveillance test. During the test, operators secured the pump when they noticed a burning smell and observed smoke coming from the pump's inboard packing gland. Investigation found the inboard packing gland had lost adequate leak off flow along its inner diameter. The licensee entered the deficiency with the pump overhaul procedure into their corrective action (CA) program for resolution.

This finding was greater than minor because it adversely affected the availability of a safety-related TDAFW pump which affected the equipment performance attribute of the Mitigating Systems Cornerstone because the pump was unavailable until the degraded packing had been replaced and the pump was satisfactorily retested. The finding was determined to be of very low safety significance (Green) in accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," because an engineering analysis determined that the pump would have remained operable, and was capable of performing its intended safety function. (Section 40A2.2)

Inspection Report# : [2005007\(pdf\)](#)**G****Significance:** Oct 16, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

**Maintenance Rule Failure to Monitor Safety-Related Power Supply System**

The inspectors identified a non-cited violation (NCV) of 10 CFR 50.65(a)(2) for failure to establish adequate measures to demonstrate that performance of Unit 2 safety-related power supplies were effectively monitored in the maintenance rule program. The licensee failed to adequately identify, evaluate, and track the failures of these power supplies in accordance with the requirements of their maintenance rule program. Specifically, when reviewing relevant power supply failures, the inspectors identified that the power supply failure associated with the 22 feedwater steam generator level transmitter, which occurred on September 16, 2005, was not properly classified as a maintenance rule functional failure. The licensee's failure to classify this as a maintenance rule functional failure resulted in the system being placed in a 50.65 (a)(1) category on October 16, 2005, after this deficiency was identified by the inspectors, instead of on September 16, 2005, when the failure occurred. A condition report was generated by the licensee to document this as well as a condition report generated to place the safety-related power supplies in an (a)(1) status.

The finding is greater than minor because it is associated with the equipment performance attribute and affected the Mitigating Systems

Cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). Specifically, the licensee did not demonstrate effective control of the performance or condition of the safety-related power supplies by failing to put the affected structure, system, component (SSC) in a 50.65 (a)(1) category. The finding is of very low safety significance because no loss of safety-related equipment actually occurred, and the affected safety-related equipment was capable of performing its intended safety function. The inspectors identified that a contributing cause to the finding was related to the cross-cutting area of human performance. Plant personnel did not properly evaluate and classify the 22 feedwater steam generator level transmitter 2LT1124C power supply failure as a maintenance rule functional failure. This inadequate classification contributed to the system not being placed in a 50.65 (a)(1) category. (Section 1R12)

Inspection Report# : [2005005\(pdf\)](#)

G

**Significance:** Sep 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

#### **Inadequate Procedures for Offsite Power Availability**

The inspectors identified an NCV of Technical Specification 5.4.1.a. "..., written procedures shall be established, implemented,..." for the failure to provide an adequate procedure for the operation of the electrical system. Specifically, Operating Procedure OI-27-B, 13.8kV System, provides steps for placing voltage regulators under manual control which makes the associated offsite source to the affected 4 kV busses inoperable. The procedure did not state this, and as a result, when the voltage regulators were placed in manual the associated offsite source was not declared inoperable when it should have been.

This finding is greater than minor because it is associated with the cornerstone attribute Procedure Quality and affects the objective of the Mitigating Systems Cornerstone to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. This finding was determined to be a finding of very low safety significance because the finding did not represent an actual loss of a safety function and was not potentially risk significant due to an external initiating event. (Section 4OA2)

Inspection Report# : [2005004\(pdf\)](#)

---

## Barrier Integrity

---

## Emergency Preparedness

---

## Occupational Radiation Safety

G

**Significance:** Mar 31, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

#### **Failure to properly control access to a high radiation area**

Green. A self-revealing non-cited violation (NCV) associated with the alternate access control requirements established in accordance with 10 CFR 20.1601 (c), was identified. Specifically, the licensee failed to control and properly post a high radiation area with dose rates greater than 1,000 millirems per hour. On January 18, 2006, a nondestructive examination (NDE) worker's electronic personnel dosimeter unexpectedly alarmed when the worker was exposed to unanticipated radiation levels of up to approximately 3,000 millirems per hour. The area was not adequately surveyed by a radiation protection technician to establish the dose rate levels in the area and to properly post the area, and the worker was not made aware of the actual dose rate levels prior to entry into the area while wearing an alarming electronic personnel dosimeter. The licensee determined that the worker received less than ten millirems. This performance deficiency was entered into the licensee's corrective action program for resolution. The inspectors determined that a contributing cause of this finding was related to the cross-cutting area of human performance in that access to a high radiation area was not properly controlled.

This finding is more than minor because it is associated with the Occupational Radiation Safety attribute of exposure control and affected the cornerstone objective in that not controlling the locked high radiation area could increase personal exposure. Using the Occupational Radiation Safety Significance Determination Process, the inspectors determined that the finding was of very low safety significance (Green) because it did not involve: (1) as low as is reasonably achievable planning and controls, (2) an overexposure, (3) a substantial potential for overexposure, or (4) an impaired ability to assess dose. (Section 2OS1)

Inspection Report# : [2006002\(pdf\)](#)

---

## Public Radiation Safety

---

## Physical Protection

[Physical Protection](#) information not publicly available.

---

## Miscellaneous

**Significance:** N/A Nov 18, 2005

Identified By: NRC

Item Type: FIN Finding

### Identification and Resolution of Problems

The team determined that Constellation's Calvert Cliffs (CC) Units 1 and 2 Nuclear Power Plants were effective at identifying problems and entering them into the corrective action program (CAP). Relatively few deficiencies were identified by external organizations (including NRC) that had not been previously identified by the licensee. Audits and self-assessments were generally thorough. Once entered into the CAP, issues were screened and prioritized in a timely manner using established criteria. Items entered into the CAP were also properly evaluated commensurate with their safety significance. The causal evaluations for equipment and performance issues were complete, and proposed corrective actions that addressed the identified causes. Corrective actions were generally effective and typically implemented in a timely manner. On the basis of interviews conducted during the inspection, workers at the station felt free to raise safety issues and were willing to enter them into the corrective action program. However, an ineffective maintenance procedure adversely impacted the availability of an auxiliary feedwater pump.

Inspection Report# : [2005007\(pdf\)](#)

Last modified : May 25, 2006