

Oyster Creek 2Q/2006 Plant Inspection Findings

Initiating Events

G**Significance:** Jun 30, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Failure to Follow Procedures Results in a Hydrogen Detonation in Augmented Offgas System

A self-revealing finding was identified regarding inadequate procedure adherence when operators did not properly implement an alarm response procedure which contributed to a hydrogen detonation and the isolation of the offgas and augmented offgas (AOG) and systems on February 13, 2006. This finding was determined to be a non-cited violation of technical specification 6.8.1a, "Procedures and Programs." AmerGen's corrective actions involved providing training to operations personnel on this event and communicating expectations regarding procedure usage.

The finding was more than minor because it was associated with the human performance attribute of the initiating events cornerstone and affected the cornerstone objective to limit the likelihood of those events that upset plant stability during shutdown as well as power operations. The inspectors conducted a significance determination process (SDP) Phase 1 screening in accordance with Inspector Manual Chapter (IMC) 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations." The finding was of very low safety significance (Green) because the finding did not contribute to both the likelihood of a reactor trip and the likelihood that mitigation equipment would not be available. The performance deficiency has a human performance cross-cutting aspect. (Section 40A3)

Inspection Report# : [2006003\(pdf\)](#)**G****Significance:** Apr 24, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Identify That a Main Steam Isolation Valve Did Not Close Within TS Surveillance Acceptance Criteria

The inspectors identified a Green NCV of 10CFR50, Appendix B, Criterion XVI, "Corrective Action," for the failure to identify that the "A" outboard main steam isolation valve (MSIV) did not stroke closed within the allowable time specified in the surveillance test procedure in February 2006. As a result of not recognizing that the valve did not meet stroke time acceptance criteria, the plant was started up with an inoperable MSIV. This was found by the inspectors during a review of data from a test performed in May 2006 during a forced outage. In May 2006, the same valve again failed to stroke closed in the allowable time; however, the station operators recognized the problem this time. The valve closing mechanism was adjusted before the plant was started up in May 2006. The failure to identify the failure in February 2006 was entered into the licensee's CAP.

The finding is more than minor and is similar to an example described in NRC Inspection Manual Chapter (IMC) 0612, Appendix E, because when the closure time for the February 2006 test was calculated correctly, a Technical Specification (TS) limit was exceeded. The finding is associated with the equipment performance attribute of the Initiating Events cornerstone; in that, the fast closure of the MSIV challenged the reactor vessel integrity and increased the potential for a loss of coolant accident. The finding was determined to be of very low safety significance (Green) because the finding would neither result in exceeding the TS limit for identified reactor coolant system leakage nor would the finding have affected other mitigation systems resulting in a total loss of their safety function. The finding has a cross-cutting aspect in the area of human performance due to inattention to detail by the personnel performing the surveillance test procedure. (Section 40A2.1.b)

Inspection Report# : [2006006\(pdf\)](#)**G****Significance:** Mar 31, 2006

Identified By: Self-Revealing

Item Type: FIN Finding

Untimely Corrective Actions Causes Unplanned Power Reduction Due to 'A' Feedwater Packing Leakage

A self-revealing finding was identified regarding untimely corrective actions when packing on the 'A' feedwater regulating valve failed on February 10, 2006, and resulted in an upset of plant stability. This finding was determined not to be a violation of NRC requirements. AmerGen's corrective actions involved repairing the valve and replacing the packing.

This finding was more than minor because it was associated with the equipment performance attribute of the initiating events cornerstone and affected the cornerstone objective to limit the likelihood of those events that challenge plant stability during power operation. In accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Operations," the inspectors conducted a Phase 1 SDP screening and determined the finding to be of very low safety significance (Green). The finding was of very low safety significance because the issue does not contribute to both the likelihood of a reactor trip and unavailability of mitigating equipment. The performance deficiency had a problem identification and resolution cross-cutting aspect. (Section 1R12)

Inspection Report# : [2006002\(pdf\)](#)

G**Significance:** Sep 23, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Failure to Follow Procedures

A self-revealing non-cited violation (NCV) of Technical Specification 6.8.1 was identified for failure to follow an abnormal operating procedure that resulted in the loss of the No. 1 North Intake Service Water Pump, the No.1 Emergency Service Water system and the associated containment spray heat exchangers. The licensee took immediate corrective actions which included the issuance of standing orders to reinforce management's expectations and provided interim guidance related to the shortcomings of the shift crew's performance.

This finding is greater than minor because the failure to follow the abnormal procedure impacted the control room's ability to adequately monitor intake levels and impacted prompt operator response actions due to decreasing intake level. This finding is associated with the cornerstone objectives of Initiating Events, Mitigating Systems and Containment Barriers Cornerstones. The attributes affected are protection against external factors such as loss of heat sink, equipment performance in availability and reliability, human performance in human error (pre-event), containment structure system and component and barrier performance. The cause of the finding is related to the cross-cutting element of human performance (personnel). (Section 2.0)

Inspection Report# : [2005011\(pdf\)](#)

Mitigating Systems

G**Significance:** Jun 30, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Inadequate Scaffold Disassembly Results in Core Spray Booster Pump Unavailability

A self-revealing finding was identified regarding an inadequate disassembly of scaffold which resulted in the unavailability of the 'B' core spray booster pump on June 27, 2006. During disassembly of a scaffold, a scaffold coupler fell and damaged the 'B' core spray booster pump's trico oiler reservoir. This finding was determine to be a non-cited violation of technical specification 6.8.1a, "Procedures and Programs." AmerGen's corrective actions included communicating this event to maintenance personnel and enhancing the pre-job walkdown checklist to identify potential hazards.

The finding was more than minor because it was associated with the human performance attribute of the mitigating systems cornerstone and affected the objective to maintain the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. In accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the inspectors conducted a Phase I SDP screening and determined the finding to be of very low safety significance (Green). The finding was of very low safety significance because the issue was not a design or qualification deficiency that resulted in a loss of function, did not result in an actual loss of safety function for a single train of equipment for greater than allowed by technical specifications, did not result in an actual loss of safety function of one or more non-technical specification trains of equipment considered risk significant in the maintenance rule program for greater than 24 hours, and was not screened as potentially risk significant from external events. The performance deficiency has a human performance cross-cutting aspect. (Section 1R12)

Inspection Report# : [2006003\(pdf\)](#)**G****Significance:** Mar 31, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

'D' ESW Pump Start Failure

A self-revealing finding was identified regarding inadequate procedure quality when the 'D' emergency service water (ESW) pump did not start on December 19, 2005. A preventive maintenance procedure was not adequate to identify a degraded condition associated with a contact in the pump's circuit breaker prior to placing the breaker in service. This finding was determined to be a non-cited violation of 10 CFR 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings." AmerGen's corrective actions included revising the procedure to ensure that resistance checks are performed on the contacts which could impact proper operation of the ESW pump breakers.

The finding was more than minor because it was associated with the procedure quality attribute of the mitigating systems cornerstone and affected the objective to maintain the reliability of systems that respond to initiating events to prevent undesirable consequences. In accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the inspectors conducted a Phase I SDP screening and determined the finding to be of very low safety significance (Green). The finding was of very low safety significance because the issue was not a design or qualification deficiency that resulted in a loss of function, did not result in an actual loss of safety function for a single train of equipment for greater than allowed by technical specifications, did not result in an actual loss of safety function of non-technical specification equipment considered risk significant in the maintenance rule program for greater than 24 hours, and was not screened as potentially risk significant from external events. The performance deficiency had a human performance cross-cutting aspect. (Section 1R12)

Inspection Report# : [2006002\(pdf\)](#)

G**Significance:** Dec 31, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Maintenance Rule Reactor Building Floor Drain System (a)(2) Demonstration Invalidated

The inspectors identified that AmerGen did not identify and properly account for one repetitive maintenance preventable function failure (RMPFF) of the reactor building floor and equipment drain system. This resulted in AmerGen not demonstrating the effectiveness of preventative maintenance and the 10 CFR50.65(a)(2), "Requirements for Monitoring the Effectiveness of Maintenance at Nuclear Power Plants," demonstration became invalid. This finding was of very low safety significance (Green) and determined to be a violation of 10 CFR 50.65(a)(2), "Requirements for Monitoring the Effectiveness of Maintenance at Nuclear Power Plants." AmerGen's corrective actions included performing a maintenance rule (a)(1) determination and creating a preventive maintenance task to replace the isolation valve actuator and solenoid.

The finding was more than minor because it was associated with the equipment performance attribute of the mitigating systems cornerstone and affected the objective to maintain the reliability of systems that respond to initiating events to prevent undesirable consequences. In accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the inspectors conducted a Phase I SDP screening and determined the finding to be of very low safety significance (Green). The finding was of very low safety significance (Green). The finding was of very low safety significance because the issue was not a design or qualification deficiency that resulted in a loss of function, did not result in an actual loss of safety function of a single train of equipment for greater than allowed by technical specifications, did not result in an actual loss of safety function of equipment considered risk significant in the maintenance rule program for greater than 24 hours, and was not screened as potentially risk significant from external events. The performance deficiency had a problem identification and resolution cross-cutting aspect.

Inspection Report# : [2005005\(pdf\)](#)**G****Significance:** Nov 04, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Provide Protection in Accordance with 10 CFR Part 50, Appendix R, Section III.G.2.

The team identified a non-cited violation of 10 CFR Part 50, Appendix R, Section III.G.2. AmerGen Energy included unapproved manual actions in their fire safe shutdown analyses and safe shutdown procedure to operate equipment necessary for achieving and maintaining hot shutdown. Several of these manual actions did not meet the requirements of Appendix R, Section III.G.2 and the NRC had not granted exemptions to allow these actions. In accordance with the guidance provided in inspection procedure 71111.05T, "Fire Protection," (issue dated: 02/18/05) this finding is greater than minor. The finding is of very low safety significance because the manual actions are reasonable and are expected to meet the criteria outlined in Enclosure 2 of inspection procedure 71111.05T.

Inspection Report# : [2005008\(pdf\)](#)

Barrier Integrity

G**Significance:** Jun 30, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Untimely Corrective Actions for the Standby Gas Treatment System

A self-revealing finding occurred when AmerGen did not take timely corrective actions for a non-conforming condition on the standby gas treatment (SBGT) system between March 2005 and May 2006. Specifically, sand and debris were identified in the SBGT system '1' due to a hole in the system ductwork. This finding was determined to be a non-cited violation (NCV) of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action." AmerGen's corrective actions included a permanent modification which involved installing an aluminum sleeve inside the ductwork to correct the condition.

The finding was more than minor because it was associated with the barrier performance attribute of the barrier integrity cornerstone and affected the cornerstone objective to provide reasonable assurance that physical design barriers protect the public from radio nuclide releases caused by accidents or events. In accordance with IMC 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the inspectors conducted a Phase I SDP screening and determined the finding to be of very low safety significance (Green). The finding was of very low safety significance (Green) because the finding only represents a degradation of the radiological barrier function provided for the SBGT system. The performance deficiency has a problem identification and resolution cross-cutting aspect. (Section 1R12)

Inspection Report# : [2006003\(pdf\)](#)**G****Significance:** Sep 30, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Failure to Maintain Primary Containment Penetration Integrity

A self-revealing non-cited violation (NCV) of Technical Specification (TS) 3.5.A.3 was identified for AmerGen's failure to maintain primary containment penetration integrity. On July 12, 2005, while conducting a primary containment isolation valve surveillance for the nitrogen supply system, the operators failed to adequately evaluate an unexpected indication on the drywell makeup flow recorder. Without pursuing other potential causes, AmerGen concluded that the nitrogen supply system inboard containment isolation valve was leaking by its closed seat and declared the inboard containment isolation valve inoperable. However, on July 13, 2005, AmerGen found that the local leak rate test (LLRT) connection cap located between the two isolation valves was missing. This condition resulted in the outboard containment isolation valve being rendered functionally operable. Amergen's failure to adequately access the plant indications resulted in the primary containment penetration not being properly isolated for a period of time greater than the TS action statement (after discovery).

This finding is considered more than minor because it was associated with the configuration control attribute of the barrier integrity cornerstone and affected the cornerstone objective to provide reasonable assurance that containment will protect the public from radionuclide releases caused by accidents or events. The condition of concern is a failure of the inboard valve to isolate during a design basis accident. This violation has been determined to have a very low safety significance since there was not an actual open pathway in the physical integrity of reactor containment. This finding is related to the cross-cutting area of Human Performance. (Section 1R22)

Inspection Report# : [2005004\(pdf\)](#)

Emergency Preparedness

Significance: N/A Jun 12, 2006

Identified By: NRC

Item Type: FIN Finding

NRC Emergency Preparedness 95002 Supplemental Inspection

The NRC performed this supplemental inspection, in accordance with Inspection Procedure 95002, to assess the licensee's evaluation and corrective actions associated with two White findings. This inspection also included an independent extent of condition and extent of cause review of issues related to the White findings. The two findings, which were in the EP Cornerstone, placed the performance of Oyster Creek into the Degraded Cornerstone Column of the NRC's Action matrix for the third quarter 2005. The first White finding involved an inaccurate EAL threshold value used for making a GE declaration. That White finding was evaluated and closed in Supplemental Inspection Report 05000219/2005007.

The second White finding involved operators not recognizing during an actual event that plant parameters met the EAL thresholds for declaring a UE and a subsequent Alert. In consideration of the NRC work already completed in the above listed prior inspection, this supplemental inspection primarily focused on the second White finding, and the combined assessment of the two White findings that resulted in the Degraded EP Cornerstone.

August 2005 Event Analysis and Corrective Actions (Second White Finding)

AmerGen determined that the root cause of the event was that operations senior management failed to consistently reinforce strict compliance with human performance and EP fundamentals. AmerGen also identified several causal factors and contributing causes associated with EP and issued corrective actions to prevent recurrence. The completed corrective actions associated with the EP deficiencies appeared to be effective.

However, the human performance issues related to procedural compliance were determined to be a primary causal factor that led to the performance problems identified during the August 2005 event response. The inspectors determined, despite the corrective actions taken and the time available for the actions to become effective, that licensed operators continued to demonstrate weaknesses associated with understanding of management expectations and site requirements for procedural use and adherence. The inspectors based this conclusion on information obtained during interviews with multiple licensed operators and on review of NRC-identified procedural usage issues during recent operating events. (Section 02.03)

As a result, the White finding associated with the August 2005 event will remain open pending completion of an additional follow-up NRC inspection to review additional AmerGen corrective actions to improve the licensed operators' knowledge of and adherence to procedural usage requirements.

Summary of Combined Review

The inspectors performed a collective assessment of the July 2004 event and the August 2005 event to determine if a commonality existed between the two events. For the first event, a process was not used; whereas for the second event, the procedure was used, but not strictly followed. Though somewhat similar, AmerGen determined the causes for the events were different; therefore, no additional corrective actions were necessary. The team reviewed the two events, discussed the root causes with AmerGen personnel, and concluded that AmerGen's collective evaluation for the multiple performance issues was adequate.

Inspection Report# : [2006010\(pdf\)](#)



Significance: G Sep 23, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Untimely State/Local Notification of UE

A self-revealing NCV of 10 CFR 50.47(b)(2) was identified in which state and local agencies were not notified within 15 minutes after declaring a

UE. The licensee immediately re-trained shift managers in the offsite notification process and proper completion of the notification form.

This finding is greater than minor because it affects the RO performance (actual event response) attribute of the EP cornerstone. Failure to notify offsite agencies in a timely manner impacts the EP cornerstone objective of ensuring that the licensee is capable of implementing adequate measures to protect the public health and safety during an emergency. Timely offsite notifications enable state and local agencies to make decisions for taking initial offsite response measures that could affect the general public. This finding is of very low safety significance because it was a failure to implement a Risk Significant Planning Standard during an actual event associated with the notification of a UE. The cause of this finding is related to the cross-cutting element of human performance (personnel). (Section 3.1)

Inspection Report# : [2005011\(pdf\)](#)

W

Significance: Sep 23, 2005

Identified By: NRC

Item Type: VIO Violation

EAL Matrix Not Reviewed For Declaring an Alert

An NRC-identified notice of violation (NOV) of 10 CFR 50.47(b)(4) was identified. This NOV, which has low to moderate safety significance, occurred because the Oyster Creek E-Plan EAL matrix was not properly utilized to determine if a plant parameter met the EAL threshold for declaring an emergency classification. This resulted in not recognizing during an actual event, that plant parameters met the EAL thresholds for declaring a UE and a subsequent Alert. Immediate corrective actions were taken in which shift crews were retrained on the implementation of E-Plan requirements.

The finding is greater than minor because it is associated with the EP cornerstone attribute of response organization (RO) performance (actual event response). It affects the cornerstone objective of ensuring the capability to implement measures to protect the health and safety of the public during an emergency. The licensee did not use the Oyster Creek E-Plan EAL matrix when plant parameters met the EAL thresholds for declaring a UE and a subsequent Alert. As a consequence, both the onsite and offsite EROs were not activated during actual Alert conditions. Had the event degraded further, the onsite ERO would not have been readily available to assist in the mitigation of the event and the offsite agencies could have been prevented from taking initial offsite response measures. This finding is of low to moderate safety significance because it constituted a failure to implement a Risk Significant Planning Standard during an actual event in which plant conditions met an Alert. The cause of the finding is related to the cross-cutting element of human performance (personnel).

Inspection Report# : [2005011\(pdf\)](#)

Occupational Radiation Safety

G

Significance: Mar 31, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate Administrative Control of High Radiation Area Keys

The inspectors identified that AmerGen did not properly implement administrative controls for locked high radiation area (HRA) access keys maintained under the control of operations personnel. This finding was determined to be a non-cited violation of technical specification 6.13.2, "High Radiation Area." As of the end of this inspection period, AmerGen was determining the appropriate corrective actions for this issue.

The finding was more than minor because it was associated with the program and process attribute of the occupational radiation safety cornerstone and affected the objective to ensure the adequate protection of the worker health and safety from exposure to radiation from radioactive material during routine civilian nuclear reactor operation. The finding was evaluated using IMC 0609, Appendix C, "Occupational Radiation Safety Significance Determination Process," because it was an exposure control issue. The inspectors determined the finding to be of very low safety significance (Green) because it did not involve an As Low As Reasonably Achievable (ALARA) finding, it did not involve an overexposure, there was no substantial potential for an overexposure, and the ability to assess dose was not compromised. The performance deficiency had a problem identification and resolution cross-cutting aspect. (Section 2OS1)

Inspection Report# : [2006002\(pdf\)](#)

Public Radiation Safety

G

Significance: Apr 24, 2006

Identified By: NRC

Item Type: FIN Finding

Failure to Take Timely Corrective Actions to Ensure the Availability and Reliability of the Augmented Off-Gas System

The inspectors identified a Green Finding for the failure to take timely actions to correct known deficiencies associated with the augmented off-gas (AOG) system, which impacted the system's reliability and availability since October 2003. In 2003, Oyster Creek performed a Common Cause Analysis (CCA) due to multiple equipment issues and system trips of the AOG system. The CCA recommended four system enhancements and also that routine preventive maintenance was necessary to address some of the deficiencies which had contributed to system unavailability. The preventative maintenance tasks were developed; however, none of the recommended system enhancements were completed. From 2003 to September 2005, the "B" train of AOG system was unavailable due to the degraded condition of the recombiner bed. When "B" train was returned to service in October 2005, it operated intermittently until February 13, 2006, when a hydrogen detonation rendered the "B" train unavailable. Oyster Creek completed a second CCA which identified the same enhancements that had been recommended in 2003. A system improvement plan was prepared to address how the plant was going to resolve the issues in the upcoming years. This performance deficiency was entered into the licensee's CAP.

The finding is more than minor because it is associated with the plant equipment attribute of the Public Radiation Safety cornerstone and affected the objective to ensure adequate protection of public health and safety from exposure of radioactive materials released into the public domain as a result of routine civilian nuclear plant operation. The finding was determined to be of very low safety significance (Green) because there was no radiological release associated with the event. The finding has a cross-cutting aspect in the area of problem identification and resolution due to the failure to take timely corrective actions to minimize the unavailability and unreliability of the AOG system. (Section 40A2.3.b)

Inspection Report# : [2006006\(pdf\)](#)

G

Significance: Mar 31, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Unauthorized Unmonitored Effluent Discharge to the Environment

A self-revealing finding was identified regarding inadequate procedure adherence when work activities on the main condenser during a forced maintenance outage resulted in an unauthorized, unmonitored effluent discharge to the environment between January 31 and February 2, 2006. This finding was determined to be a non-cited violation of technical specification 6.8.1a, "Procedures and Programs." As of the end of this inspection period, AmerGen was determining the appropriate corrective actions for this issue.

The finding was more than minor because it was associated with the program and process attribute of the public radiation safety cornerstone and affected the objective to ensure adequate protection of public health and safety from exposure to radioactive materials released into the public domain as a result of routine civilian nuclear reactor operation. This finding was evaluated using IMC 0609, Appendix D, "Public Radiation Safety Significance Determination Process," because it was a radioactive effluent release program issue. The inspectors determined the finding to be of very low safety significance (Green) because AmerGen was able to assess the dose from the release of the radioactive effluent and the radiological release associated with the event was not greater than 10 CFR 50 Appendix I, "Numerical Guides for Design Objectives for Operation to Meet the Criterion 'As Low As Is Reasonably Achievable' for Radioactive Material in Light -Water-Cooled Nuclear Power Reactor Effluents" or 10 CFR 20.1301(d), "Dose Limits for Individual Members of the Public," regulatory limits. The performance deficiency had a human performance cross-cutting aspect. (Section 1R20)

Inspection Report# : [2006002\(pdf\)](#)

Physical Protection

[Physical Protection](#) information not publicly available.

Miscellaneous

Significance: N/A Apr 24, 2006

Identified By: NRC

Item Type: FIN Finding

Identification and Resolution of Problems

The team concluded that the implementation of the corrective action program (CAP) at Oyster Creek was generally adequate, and improving compared to documented inspection results since the last team inspection of the corrective action program in May 2004. The team determined that Oyster Creek had a low threshold for identifying problems and entering them in the CAP; however, the station did not always recognize that individual problems could be indicative of a larger performance issue. In addition, the station did not consistently use trend data to identify potential problems, as evidenced by two examples where opportunities to prevent failures existed but were not acted upon. Once entered into the system, items were screened and prioritized in a timely manner using established criteria. Items entered into the CAP were properly evaluated commensurate with their safety significance. However, documentation supporting conclusions in several causal evaluations and the operability determinations was weak. Corrective actions were typically implemented in a timely manner. Licensee audits and self-assessments were generally critical at identifying problems. On the basis of interviews conducted during the inspection, workers at the site expressed freedom to enter safety concerns into the CAP.

There was one Green NCV and one Green Finding identified by the inspectors during this inspection. The NCV was associated with the failure to identify that a main steam isolation valve (MSIV) closed too fast during a surveillance test; as a result the plant was started up with an MSIV exhibiting a closure time outside the specified acceptance criteria. The Finding was associated with a failure to take timely corrective actions for repetitive deficiencies in the augmented off-gas system, impacting the system's reliability and availability.

Inspection Report# : [2006006\(pdf\)](#)

G

Significance: Sep 23, 2005

Identified By: NRC

Item Type: FIN Finding

Inadequate Root Cause Analysis

The inspectors identified a green finding for ineffective corrective actions in that the root cause analysis team did not correctly identify the amount of time Alert conditions existed during the August 6, 2005, event. AmerGen initiated some of their immediate corrective actions and their analysis of the significance of this event based on the Alert lasting for five minutes when it actually lasted for approximately 45 minutes. The licensee confirmed the error, revised the root cause analysis report and entered this issue into their corrective action program.

The finding was more than minor because if left uncorrected, it could have resulted in a more significant safety concern. Specifically, failure to accurately identify information pertaining to operating events can lead to deficiencies in corrective actions. Because this finding does not involve a violation of regulatory requirements, this finding is not suitable for SDP evaluation, but has been reviewed by NRC management and is determined to be a finding of very low safety significance. The cause of the finding is related to the cross-cutting element of problem identification and resolution. Section 4.0

Inspection Report# : [2005011\(pdf\)](#)

Last modified : August 25, 2006