

Oconee 2

2Q/2006 Plant Inspection Findings

Initiating Events



Significance: Sep 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Implement an Inspection Program for the Main Steam Lines

A NRC-identified non-cited violation of 10 CFR 50 Appendix B, Criterion X, Inspection, was identified for the failure to develop and implement an inspection program for monitoring the main steam line in the Unit 1, 2 and 3 East Penetration Rooms. The finding was considered to be a performance deficiency in that the licensee had committed to perform inspections of the steam lines to support the acceptability of Duke's design and analysis for the main steam lines, but the inspections were not being performed. The finding was considered to be more than minor because it impacted the Reactor Safety Initiating Events Cornerstone in that failure to perform the inspections could lead to failure to identify degrading main steam line conditions, which would cause an increase in the likelihood of an initiating event. The finding was screened as having very low safety significance under the Initiating Events Cornerstone, in that it did not contribute to both the likelihood of a reactor trip and the likelihood that mitigation equipment or functions would not be available. This finding involved the cross-cutting aspect of Problem Identification and Resolution. (Section 1R22.3)

Inspection Report# : [2005004\(pdf\)](#)

Mitigating Systems



Significance: Jun 30, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to promptly correct long-standing east penetration room blowout panel-related deficiencies that precluded flood mitigation in the auxiliary building.

NCV of 10 CFR Part 50, Appendix B, Criteria XVI, Corrective Action, for failure to promptly identify and correct a significant condition adverse to quality. Specifically, as a result of inappropriate east penetration room blowout panel modifications (identified as a violation in 2002), in conjunction with the inappropriate addition of floor curbing and the inadequate strength of internal doors and block walls (all identified in DEC's corrective action program in 2001), Units 1, 2, and 3 continue to be operated outside their licensing basis with respect to HELB-related flood mitigation in the auxiliary building.

Inspection Report# : [2006014\(pdf\)](#)

Significance: SL-IV Jun 30, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to report east penetration room blowout pante-related deficiencies would prevent fulfillment of the HPI system safety function.

NCV of 10 CFR 50.73, Part (v) was identified for the failure to report that east penetration room blowout panel-related deficiencies would prevent the fulfillment of the HPI system safety function to mitigate the consequences of a HELB (i.e., to shutdown the reactor and maintain it in a cold shutdown condition).

Inspection Report# : [2006014\(pdf\)](#)



Significance: Jun 30, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Perform Adequate Examinations of Letdown Filter Supports.

The inspectors identified a finding involving a non-cited violation of 10 CFR Part 50.55a(g)(4)ii for failure to perform a visual (VT-3) examination of the letdown filter housing supports as required by Section XI of the ASME Code. The examinations were performed with a remote camera and the required examination coverage was not obtained as required by Section XI of the ASME Code. The limited remote VT-3 examinations found no indications that the structural integrity of the supports was unacceptable for service. The licensee entered this issue into the Corrective Action Program.

This finding was of more than minor significance because the incomplete examination of the letdown filter housing supports, if left uncorrected, could become a more significant structural support concern. In addition, a failure to examine the letdown filter supports as required by the ASME Code is related to the "Equipment Performance" attribute of the "Initiating Events" cornerstone and affects the cornerstone objective of limiting the

likelihood of those events that upset plant stability and challenge critical safety functions during shutdown, as well as power operations. This finding was evaluated using Phase 1 of the NRC IMC 0609, "Significance Determination Process (SDP)." This finding was of very low safety significance because the worst case degradation of the letdown filter supports would result in a detectable and isolable RCS leak that would not impair the mitigating function of the high pressure injection (HPI) system. (Section 1R08)

Inspection Report# : [2006003\(pdf\)](#)

Significance:  Jun 30, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Failure To Maintain Containment Electrical Penetration Enclosures.

The inspectors identified a non-cited violation of 10 CFR 50 Appendix B, Criterion XVI for failure to identify a condition adverse to quality in that East and West Penetration Room containment electrical penetration enclosures had not been maintained, such that a number of enclosures allowed the introduction of dirt and debris inconsistent with conditions under which these penetrations were environmentally qualified.

The finding was considered to be a performance deficiency in that the licensee failed to maintain the containment electrical penetration covers such that debris was allowed to accumulate in a number of enclosures; thereby, jeopardizing the environmental qualification of safety-related circuits. This finding was considered to be more than minor because it affected the mitigating systems cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events in that, the degraded penetration covers, if left uncorrected could allow the environmental qualification of safety-related circuits to degrade such that they would fail following a high energy line break (HELB) in the east penetration rooms. Using the phase 1 screening worksheet of Manual Chapter 0609, Appendix A, the finding was determined to be of very low safety significance, as it did not result in a loss of operability of any equipment needed to mitigate the effects of a HELB.

This finding has a cross-cutting aspect in the area of problem identification and resolution, as the licensee did not appropriately identify the degraded penetration covers consistent with their corrective action program. (Section 40A5.1)

Inspection Report# : [2006003\(pdf\)](#)

Significance:  Mar 17, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

Non-Conservative EOP Procedure Setpoint for Operator Action to accomplish BWST to RBES swap over on Low BWST Level

The team identified a Green, non-cited violation (NCV) of Technical Specification 5.4.1.b for a non-conservative operator action setpoint in the Emergency Operating Procedures. Specifically, the 6 foot level setpoint for operator action to complete the BWST to Reactor Building Emergency Sump (RBES) swap over by closing the BWST suction valves did not include enough margin to preclude degradation or damage to the pumps due to vortex formation in the BWST in all cases. When the NRC notified the licensee of this condition, the licensee entered it into the corrective action program. This finding is greater than minor because it is associated with the procedure quality attribute of the Mitigating Systems cornerstone and affected the cornerstone objective of ensuring reliable, available, and capable systems that respond to initiating events to prevent undesirable consequences. This finding is of very low safety significance because no actual loss of safety function occurred and operators have been trained to identify loss of pump suction. This finding has been entered into the licensee's corrective action program as PIP O-06-01374. (Section 1R21.2.1.1)

Inspection Report# : [2006006\(pdf\)](#)

Significance:  Dec 31, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Inadequate Procedures for Testing the SSF Diesel Generator With the CCW Supply Secured

A Green self-revealing non-cited violation was identified for failure to have adequate procedures for testing the Standby Shutdown Facility (SSF) diesel generator as required by Technical Specification (TS) 5.4.1. The licensee's existing test procedures did not establish the appropriate plant conditions with the Unit 2 condenser cooling water (CCW) system shut down such that the water supply to the SSF auxiliary service water (ASW) and station ASW heated above 90 degrees F rendering both unavailable for all three units. The licensee entered this finding into their corrective action program under Problem Investigation Process report (PIP) O-05-7479. This finding was considered to be of more than minor significance because it affected the Mitigating Systems Cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences, as the elevated temperature of the SSF ASW and station ASW supply resulted in the unavailability of these systems. This issue was determined to be of very low safety significance based on the screening criteria found in MC 0609, Appendix A, Phase 1 SDP worksheet. More specifically, the total additional unavailability of the SSF (one day) as result of overheating the supply did not exceed the TS allowed outage time. (Section 1R12)

Inspection Report# : [2005005\(pdf\)](#)

G**Significance:** Dec 31, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Identify Unmitigated/Unprotected Feedwater Line Terminal Ends

A NRC-identified non-cited violation of 10 CFR 50 Appendix B, Criterion XVI was identified for the failure to identify a condition adverse to quality, in that feedwater terminal ends had not been identified; and therefore, actions to mitigate the effects from a terminal end line break had not been implemented. The licensee entered this finding into their corrective action program under PIP O-06-00138. This finding was considered to be more than minor because an unprotected terminal end line break would impact the Reactor Safety Cornerstone for Mitigating Systems associated with the availability, reliability and function of systems needed to respond to a high energy line break (HELB). This issue was determined to be of very low safety significance based on a very low initiating event frequency being calculated as a result of the limited number of welds and feet of pipe under consideration. In addition, the large early release frequency impact was below the threshold, because of the size of break required to damage the containment penetration was an even lower probability event. This finding involved the crosscutting aspect of Problem Identification and Resolution. (Section 40A5.2)

Inspection Report# : [2005005\(pdf\)](#)**G****Significance:** Sep 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Performing Licensed Duties While Medically Unqualified

A NRC-identified non-cited violation of 10 CFR 50.74 was identified for failure to make a notification of a change in operator or senior operator status regarding information for one licensed operator concerning his medical qualification. Specifically, the operator failed to meet the American Nuclear Standards Institute /American Nuclear Society (ANSI/ANS-3.4, "Medical Certification and Monitoring of Personnel Requiring Operator Licenses for Nuclear Power Plants," 1983 Standard for a blood pressure (BP) limitation. This impacted the NRC's ability to perform its regulatory function, in that the NRC was not able to make a licensing decision with regards to a potential restriction to ensure compliance with ANSI/ANS-3.4. Consequently, an operator stood several watches in a Technical Specification license position with his BP greater than the ANSI/ANS limits. This finding is of very low safety significance because there was no evidence that the operator endangered plant operations as a result of hypertension while performing licensed duties since the original issuance of his license. However, the regulatory significance was important because pertinent information was not provided to the NRC when the operator knowingly discontinued taking his medication. Subsequently, this impacted a licensing decision for the individual. (Section 1R11.2)

Inspection Report# : [2005004\(pdf\)](#)**G****Significance:** Sep 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Develop and Implement a Cleanliness Inspection Program for the Containment Electrical Penetrations

A NRC-identified non-cited violation of 10 CFR 50 Appendix B, Criterion X, Inspection, was identified for the failure to develop and implement an inspection program for inspection and cleaning of the containment electrical penetrations located in the East and West Penetration Rooms of Units 1, 2, and 3. The finding was considered to be a performance deficiency in that the licensee had failed to develop an inspection program for their containment electrical penetrations to ensure cleanliness of the electrical connections. The inspectors concluded that if left uncorrected (no inspection) debris and rust accumulation could lead to failure of the electrical circuits during a high energy line break as a result of grounds and shorts. Therefore, failure to perform cleanliness inspections was considered to be more than minor because it could impact the Reactor Safety Mitigating Systems Cornerstone objective for reliability of a mitigating system/train (i.e., circuits needed to mitigate a high energy line break. The finding was screened as very low safety significance in the Phase 1 review under the Mitigating Systems Cornerstone, in that failure to perform an electrical penetration inspection was not considered to be a design deficiency, was not considered to represent a loss of safety system function, was not considered to represent an actual loss of safety function of a single train, and did not involve seismic, flooding or severe weather. This finding involved the cross-cutting aspect of Problem Identification and Resolution. (Section 1R22.2)

Inspection Report# : [2005004\(pdf\)](#)**G****Significance:** Sep 30, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Untimely Corrective Actions for Repairs to a Unit 2 East Penetration Room Floor Seal

A NRC-identified non-cited violation of 10 CFR 50 Appendix B, Section XVI, Corrective Action, for inadequate corrective actions related to the lack of timeliness of repairs to a Unit 2 East Penetration Room floor seal. The failure to promptly repair the damaged floor seal was considered to be a performance deficiency. The finding was considered to be more than minor because if left uncorrected, additional seal area could fail and it would affect the Mitigating System Cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events, in that the high pressure injection (HPI) pumps could be flooded following a high energy line break in the East Penetration Room. However, in the seal's current level of degradation, the inspectors concluded that the deficiency would not by itself result in the loss of function of the HPI pumps, because flooding would be limited by the size of the degraded/failed seal. Consequently, the finding was determined to be of very low safety significance, as it was screened out under the Mitigating Systems Cornerstone in the SDP Phase 1 Screening Worksheet with the determination that there was no loss of safety function. This finding involved the cross-cutting aspect of Problem Identification and Resolution. (Section 40A2.6)

Inspection Report# : [2005004\(pdf\)](#)

Significance: N/A Jan 23, 2004

Identified By: NRC

Item Type: VIO Violation

Failure to Obtain Prior NRC Approval to a Change to the Facility Involving Unreviewed Safety Questions on High Energy Line Break Analysis

The inspectors identified an apparent violation of 10 CFR 50.59 (a)(1) (1999 version of 10 CFR) which states, in part, that the licensee may make changes in the facility as described in the safety analysis report without prior Commission approval, provided the proposed change does not involve an unreviewed safety question (USQ). 10 CFR 50.59 (a)(2) states, in part, that a proposed change involves an USQ if the probability of occurrence or malfunction of equipment important to safety previously evaluated in the safety analysis report may be increased, or if it may create an accident different from any previously evaluated.

On May 17, 2001, the licensee made a change to the facility, as described in the Updated Final Safety Analysis Report, Section 3.6.1.3, associated with the High Energy Line Break (HELB) analysis, which involved unreviewed safety questions, and failed to obtain prior NRC approval. The UFSAR Section was changed to increase the maximum initiation time following HELB of Emergency Feedwater from 15 to 30 minutes and of High Pressure Injection from 1 hour to 8 hours (based on referenced reports and analysis). The analysis discussed an increased cycling of pressurizer Safety Relief Valves on steam and water, boiler condenser mode of decay heat removal, and an unapproved computer code for application to HELB, but failed to recognize that such changes may increase the probability of occurrence or the consequences of a malfunction of equipment important to safety or may create an accident different from any previously evaluated. In addition, the change resulted in more than a minimal increase in risk.

Based on the results of the inspection, a pre-decisional enforcement conference was held on March 2, 2004, in the NRC's Region II Office in Atlanta, Georgia, with the licensee staff to discuss the apparent violation, its significance, root causes, and corrective actions. Based on the information developed during the inspection, and the information presented at the conference, the NRC determined that a violation of NRC requirements occurred. On April 8, 2004, the NRC issued a Notice of Violation (NOV) and proposed imposition of a \$60,000 Civil Penalty (ADAMS accession number ML040990355). The violation involves a failure to adhere to the requirements of 10 CFR 50.59, in that Duke Energy Corporation made changes to the Oconee facility as described in Section 3.6.1.3 of the UFSAR and referenced analyses that involved unreviewed safety questions (USQs) without obtaining prior NRC approval.

Inspection Report# : [2004005\(pdf\)](#)

Inspection Report# : [2004007\(pdf\)](#)

Inspection Report# : [2005002\(pdf\)](#)

Inspection Report# : [2005005\(pdf\)](#)

Barrier Integrity



Significance: G Sep 30, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Inadequate QC Inspection Results in the Improper Installation of Thermal Overloads on the Unit 1 and 2, B Train, CROABF

A self revealing, non-cited violation (NCV) of 10 CFR 50 Appendix B, Criterion X, Inspection, was identified for an inadequate quality control (QC) inspection associated with the installation of the thermal overloads on the Unit 1 and 2 Control Room Outside Air Booster Fan (CROABF) Train B. The finding was considered to be a performance deficiency because the licensee failed to conduct an adequate QC inspection of the installation of the S4.4 overload relay heater elements on the safety-related B CROABF. The licensee's failure to correctly install the thermal overloads on the Unit 1 and 2, B Train, CROABF was considered to be more than minor because it affected the Barrier Integrity Cornerstone attribute of maintaining control room habitability. Similar to NCV 05000269/2005002-02, this finding represented a similar degradation of the barrier function of the control room against smoke and/or a toxic atmosphere; thereby, requiring a Phase 3 evaluation be performed. However, since the exposure time associated with this CROABF finding is shorter than that used in the Phase 3 evaluation of NCV 05000269/2005002-02, it too is considered to be of very low safety significance. This finding involved the cross-cutting aspect of human performance. (Section 40A3.3)

Inspection Report# : [2005004\(pdf\)](#)

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

G**Significance:** Dec 31, 2005

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Ensure Adequacy of Measurements of Particulate Effluents Released from Unit Vent

An NRC-identified NCV of 10 CFR 20.1302(a) was identified for failure to ensure surveys of particulate radioactive materials in effluents released to unrestricted areas by the unit vents were adequate to demonstrate compliance with dose limits for individual members of the public. The failure to conduct appropriate evaluations to assure representative sample collection from the Unit 1, 2, and 3 unit vent exhaust streams when sampled through the tee connections on the sample line to 1,2,3-RIA-43 and the elbow connections on the associated Selected Licensee Commitment required unit vent particulate sampler lines could result in inaccurate measurement of airborne particulate radionuclides in effluent samples, potentially leading to effluent releases exceeding allowed concentrations or dose limits to members of the public. This finding was entered into the licensee's corrective action program as PIPs O-04-7084 and O-05-4874. The licensee has approved and scheduled installation of a design modification for the monitors that will remove the non-conforming bends and replace them with bends of radius greater than or equal to five times the size of the diameter of the sample lines. This finding is greater than minor because it is associated with the program and process attribute of the Public Radiation Safety Cornerstone and affects the cornerstone objective of assuring adequate protection of public health and safety from exposure to radioactive materials released into the public domain as a result of routine civilian nuclear reactor operation. This finding which involved radioactive material control was assessed using the Public Radiation Safety SDP. Since the finding did not result in the failure to assess dose, due to the licensee having other means by which dose from particulate releases could be assessed, and because the licensee did not exceed the limits in 10 CFR 50 Appendix I or 10 CFR 20.1301(d), it was determined to be of very low safety significance. The cause of the finding is related to the cross-cutting element of Problem Identification and Resolution. (Section 2PS1)

Inspection Report# : [2005005\(pdf\)](#)G**Significance:** Dec 31, 2005

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Failure to Adequately Survey and Maintain Control of Licensed Material (Section 2PS3)

A self-revealing non-cited violation of 10 CFR 20.1501(a) and 10 CFR 20.1802 was identified for an inadequate survey of contaminated equipment and failure to control and maintain constant surveillance of licensed material when free-released contaminated equipment was subsequently shipped to two locations as "clean" material without appropriate radiological controls. One of the locations was a non-licensed individual possessing neither the training nor equipment necessary to identify and control the contaminated material. The licensee entered the finding into the corrective action program as PIP O-04-8873. The corrective actions associated with this PIP included sending a radiological response team to one of the locations to identify, contain, and decontaminate any contaminated equipment and performing a detailed root cause analysis of the event. The finding is greater than minor because it is associated with the human performance attribute of the Public Radiation Safety Cornerstone and affects the cornerstone objective of assuring adequate protection of public health and safety from exposure to radioactive materials released into the public domain as a result of routine civilian nuclear reactor operation. The failure to conduct adequate surveys resulted in the free-release of contaminated equipment, potentially leading to exceeding the dose limits to members of the public through loss of control of licensed material. This finding which involved radioactive material control was assessed using the Public Radiation Safety SDP. Since the finding neither resulted in an exposure to the public in excess of five millirem nor involved greater than five occurrences, it was determined to be of very low safety significance. The cause of this finding is related to the cross-cutting element of Human Performance. (Section 2PS3)

Inspection Report# : [2005005\(pdf\)](#)

Physical Protection

[Physical Protection](#) information not publicly available.

Miscellaneous

Significance: N/A Jul 01, 2005

Identified By: NRC

Item Type: FIN Finding

Biennial PI&R Inspection

The inspectors concluded that, in general, problems were properly identified, evaluated, and corrected. The licensee was effective at identifying problems and entering them into the corrective action program (CAP) for resolution; however, several minor plant material condition deficiencies were identified during plant system walkdowns that had gone undetected by licensee personnel. The licensee maintained a low threshold for identifying problems as evidenced by the continued large number of Problem Investigation Process reports (PIPs) entered annually into the CAP. Generally, the licensee properly prioritized issues and examined issues; although several minor problems were noted where lower significance issues were mis-categorized or the investigations lacked thoroughness. Formal root cause evaluations for significant problems were thorough and detailed. Corrective actions specified for problems were generally adequate; although, several minor problems were noted where corrective actions were not complete or not comprehensive. Audits and self-assessments were effective in identifying deficiencies in the CAP. Personnel at the site felt free to raise safety concerns to management and to resolve issues via the CAP.

Inspection Report# : [2005008\(pdf\)](#)

Last modified : August 25, 2006