

Hope Creek 1

2Q/2007 Plant Inspection Findings

Initiating Events

Significance:  Jun 29, 2007

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

FAILURE TO FOLLOW TEST PROCEDURE RESULTS IN REACTOR SCRAM

A self-revealing non-cited violation of 10 CFR 50, Appendix B, Criterion V, “Instructions, Procedures, and Drawings,” occurred when technicians did not follow a procedure during undervoltage relay testing on the normal supply breaker for the 10A401 4 kV bus. This resulted in a momentary loss of power to the 10A401 4kV vital bus that caused the loss of two reactor feed pumps (RFPs) and required the manual insertion of all control rods (scram). PSEG’s corrective actions included changing the procedure guidance for the sequence of breaker testing and adding independent verification steps for the removal of test equipment.

The finding was greater than minor because it affected the human performance attribute of the Initiating Events cornerstone and impacted the cornerstone objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during plant operations. Specifically, failure to follow surveillance test procedures resulted in the momentary loss of power to the 10A401 vital bus and a reactor scram. The inspectors determined the finding was of very low safety significance (Green). The finding had a cross-cutting aspect in the area of human performance because personnel did not follow procedures (H.4.b). Specifically, maintenance technicians failed to remove test equipment in accordance with the test procedure.

Inspection Report# : [2007003](#) (*pdf*)

Significance:  Sep 30, 2006

Identified By: Self-Revealing

Item Type: FIN Finding

INADVERTENT INSTRUMENT AIR COMPRESSOR TRIP

A self-revealing finding was identified when an operations work control supervisor caused an inadvertent trip of the 10K107 instrument air compressor. During a tagging operation on the 00K107 air compressor, the supervisor verified that a key would fit properly in the 00K107 air compressor uninterruptible power supply (UPS) by testing it in the in-service 10K107 air compressor UPS. When the supervisor removed the key, the 10K107 air compressor tripped resulting in an instrument air system transient. PSEG stopped all work activities to brief crews on the transient, proper use of human performance tools, and site procedures.

This performance deficiency is more than minor because it is associated with the configuration control and human performance attributes of the Initiating Events Cornerstone and affected the cornerstone’s objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during power operations. The inspectors completed a Phase 1 screening of the finding using Appendix A of Inspection Manual Chapter 0609, “Determining the Significance of Reactor Inspection Findings for At-Power Situations,” and determined that a more detailed Phase 2 evaluation was required to assess the safety significance because the finding contributed to both the likelihood of a reactor trip and the likelihood that mitigation equipment would not be available. The finding was determined to be of very low safety significance based upon a Significance Determination Process Phase 2 evaluation. The performance deficiency had cross-cutting aspect in the area of human performance related to the work practices component in that the individual did not use human performance error prevention techniques and proceeded in the face of uncertainty.

Inspection Report# : [2006004](#) (*pdf*)

Mitigating Systems

G**Significance:** Jun 29, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

FAILURE TO PERFORM A RISK ASSESSMENT WHEN REQUIRED BY 10 CFR 50.65(a)(4)

The inspectors identified a non-cited violation of 10 CFR Part 50.65(a)(4) when PSEG did not assess and manage the increase in risk for corrective maintenance activities on the 'C' SSW pump following an emergent failure of a 'B' SSW ventilation supply fan. PSEG updated the risk assessment, implemented appropriate risk management actions, repaired and restored the 'B' SSW fan to service, and created notification 20326624 to address the inadequate risk assessment.

The finding was greater than minor because PSEG's risk assessment had errors or incorrect assumptions that changed the outcome of the plant risk assessment. Specifically, PSEG's risk assessment did not consider the emergent failure of the 'B' SSW supply fan risk prior to performing planned maintenance on the 'C' SSW pump. The inspectors determined that the finding was of very low safety significance (Green) because the incremental core damage probability deficit was in the low E-8 range. The finding had a cross-cutting aspect in the area of human performance because PSEG did not appropriately plan work activities by incorporating risk insights (H.3.a). Specifically, PSEG did not adjust the work schedule to ensure overall plant risk was minimized because PSEG did not evaluate the change in plant risk caused by the emergent failure of the 'B' SSW ventilation supply fan.

Inspection Report# : [2007003](#) (*pdf*)**G****Significance:** Dec 31, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

UNPLANNED TRIP OF THE 'B' CONTROL ROOM CHILLER AND VENTILATION TRAIN

A self-revealing non-cited violation of 10 CFR 50 Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified when maintenance personnel lifted an energized lead (wire) that inadvertently tripped the 'B' control room chiller during maintenance on the 'B' control area battery room exhaust fan. PSEG's corrective actions included revising the maintenance planning development procedure and conducting a review of other relay replacement preventative maintenance procedures to identify weaknesses similar to those discovered during the investigation of this issue.

The inspectors determined the failure to provide appropriate procedures, drawings, or instructions for the replacement of a relay constituted a performance deficiency and a finding. The finding is more than minor because it is associated with the procedure quality attribute of the mitigating systems cornerstone and affected the cornerstone's objective to ensure the availability of systems that respond to initiating events to prevent undesirable consequences. The inspectors conducted a Phase 1 SDP screening and determined the issue to be of very low safety significance (Green). The finding has a cross-cutting aspect in the area of human performance because personnel proceeded in the face of uncertainty or unexpected circumstances by deciding to lift two leads without understanding the effect that action would have on safety-related equipment.

Inspection Report# : [2006005](#) (*pdf*)**G****Significance:** Dec 31, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

MISPOSITIONED VALVE RESULTS IN REDUCED COOLING FLOW TO THE 'C' EMERGENCY DIESEL GENERATOR

A self-revealing non-cited violation of 10 CFR 50 Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified when the safety auxiliaries cooling system (SACS) throttle valve to the 'C' emergency diesel generator (EDG) was found out of its required position on August 11, 2006. PSEG's corrective actions included performing a flow balance on the EDG to correct SACS valve positions and implementing a modification to the SACS to increase available cooling flow to the EDGs. The finding is self-revealing, rather than licensee-identified, because the inspectors communicated concerns of unusually high lube oil temperatures during summer conditions to PSEG personnel that were not confirmed by PSEG for several months due to repetitive deferrals of corrective action orders to evaluate the condition. PSEG had surveillance test data that demonstrated that all of the EDGs were exhibiting higher than normal lube oil temperatures during summer months and thus could reasonably have discovered the

configuration control error before high summer temperatures challenged the capability of the EDG.

The inspectors determined that positioning equipment contrary to PSEG's configuration control and safety tagging procedures was a performance deficiency and a finding. The finding is more than minor because it is associated with the configuration control attribute of the mitigating systems cornerstone and affected the cornerstone's objective to ensure the capability of systems that respond to initiating events to prevent undesirable consequences. The inspectors conducted a Phase 1 SDP screening and determined the issue to be of very low safety significance (Green). The finding had a cross-cutting aspect in the area of human performance because self and peer checks were not used effectively to verify the correct position of the SACS throttle valve following maintenance activities.

Inspection Report# : [2006005](#) (*pdf*)

Significance:  Dec 31, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

HIGH TEMPERATURE CONDITION ON 'B' EMERGENCY DIESEL GENERATOR NOT FULLY IDENTIFIED IN A TIMELY MANNER

The inspectors identified a non-cited violation of 10 CFR 50 Appendix B, Criterion XVI, "Corrective Action," when lube oil temperature exceeded the procedural limit of 170 degrees F on the 'B' EDG during a surveillance test on July 31, 2006. PSEG determined that a throttle valve in the SACS was not in the required position, which caused a reduction of cooling flow to the EDG lube oil cooler. The finding is NRC-identified because the inspectors communicated concerns of unusually high lube oil temperatures during summer conditions to PSEG personnel that were not confirmed by PSEG for several months due to repetitive deferrals of corrective action orders to identify the condition. PSEG's corrective actions included performing a flow balance on the EDG to correct SACS valve positions and implementing a modification to SACS to increase available cooling flow to the EDGs.

The finding is more than minor because it is associated with the configuration control attribute of the mitigating systems cornerstone and affected the cornerstone's objective to ensure the capability of systems that respond to initiating events to prevent undesirable consequences. The inspectors conducted a Phase 1 SDP screening and determined the issue to be of very low safety significance (Green). The finding has a cross-cutting aspect in the area of problem identification and resolution because PSEG did not promptly identify deficiencies that caused higher than expected temperatures in EDG lube oil systems.

Inspection Report# : [2006005](#) (*pdf*)

Significance:  Dec 08, 2006

Identified By: NRC

Item Type: NCV NonCited Violation

INADEQUATE STRAINER DIFFERENTIAL PRESSURE DESIGN CONTROL TO ENSURE ADEQUATE SERVICE WATER FLOW

The team identified a non-cited violation of 10CFR50, Appendix B, Criterion III, "Design Control," for a failure to correctly translate the design basis into procedures in that measures were not established to verify the adequacy of the service water (SW) cooling water design flow. Specifically, the SW abnormal operating procedure allowed for continued SW pump operation (up to 12 hours) without declaring the pump inoperable, when SW strainer differential pressure exceeded the SW system hydraulic calculation assumptions. Operation in this condition did not ensure the design basis minimum flowrate would be provided to the safety auxiliaries cooling system, which in turn cools the emergency diesel generators and other safety-related equipment, under the most limiting conditions. PSEG performed a review of past operability, and initiated a notification to change the SW abnormal operating procedure to declare the SW pump inoperable when a SW strainer differential pressure exceeds the appropriate setpoint.

The finding is more than minor because it is associated with the design control attribute of the mitigating systems cornerstone and affected the cornerstone's objective to ensure the availability and reliability of systems that respond to initiating events to prevent undesirable consequences. The finding also is associated with the initiating events cornerstone because unavailability of one service water pump increases the likelihood of loss of service water events. In accordance with NRC Inspection Manual Chapter 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the team conducted a Phase 1 SDP screening and determined a more detailed Phase 2 SDP evaluation was required to assess the safety significance because the finding affected two cornerstones. The finding was determined to be of very low safety significance (Green) based upon the Phase 2 SDP

evaluation. The finding has a cross-cutting aspect in the area of human performance because the SW abnormal operating procedure was inappropriately revised in May 2006 to remove acceptance criteria for pump operability with elevated strainer differential pressure.

Inspection Report# : [2006015](#) (*pdf*)

Significance:  Dec 08, 2006

Identified By: NRC

Item Type: FIN Finding

INADEQUATE CONTAINMENT VENT VALVE BACKUP PNEUMATIC SUPPLY

The team identified a finding for the failure to correctly translate the design basis of the containment ventilation backup nitrogen bottles into procedures. Specifically, the operator rounds log was revised to allow the two backup nitrogen bottles, which operate containment vent valve 1GSHV-4964, to decrease to 200 psig each. The nitrogen capacity calculation assumed a minimum of 800 psig per bottle to ensure sufficient nitrogen to stroke the containment vent valve as needed in beyond design basis events. Operation below 800 psig did not ensure the containment vent valve could be used according to emergency operating procedures to protect containment against overpressurization. PSEG raised the minimum backup nitrogen bottle pressure to 800 psig per bottle, performed a review of past bottle pressures, and initiated a notification to change the operator rounds log to allow a minimum of 800 psig per bottle.

This finding is more than minor because it is associated with the design control attribute of the mitigating systems cornerstone, and affected the cornerstone's objective to ensure the availability and reliability of the containment vent to respond to initiating events to prevent undesirable consequences. In accordance with NRC Inspection Manual Chapter 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," the inspectors conducted a Phase 1 SDP screening and determined the finding was of very low safety significance (Green) since it did not result in a loss of safety system function because the vent valve local hand-jack was available to open the containment vent. There were no violations of NRC requirements because the containment vent function is not covered by Technical Specifications, is not a part of Hope Creek's licensing basis, and is only credited in beyond design basis events.

Inspection Report# : [2006015](#) (*pdf*)

Significance:  Sep 30, 2006

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

'A' CORE SPRAY MINIMUM FLOW CHECK VALVE FAILURE

A self-revealing, non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," was identified when the 'A' core spray pump minimum flow check valve remained open, resulting in 56 hours of unplanned unavailability of the 'A' core spray loop. PSEG did not implement corrective actions developed following a similar condition on the 'C' core spray check valve on November 12, 2004. PSEG's corrective actions included repairing the check valve, updating the check valve maintenance procedure, and creation of periodic preventative maintenance tasks to internally inspect the core spray pump minimum flow check valve.

This performance deficiency is more than minor because it is associated with the equipment performance attribute of the Mitigating Systems Cornerstone and affected the cornerstone's objective to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. The inspectors determined the finding to be of very low safety significance (Green), based on a Phase 1 SDP screening. The performance deficiency had a cross-cutting aspect in the area of problem identification and resolution in the corrective action program component in that the appropriate corrective actions to address the missing pin on the 'C' core spray minimum flow check valve were not implemented in a timely manner to prevent a similar failure in the 'A' core spray minimum flow check valve.

Inspection Report# : [2006004](#) (*pdf*)

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Physical Protection

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the [cover letters](#) to security inspection reports may be viewed.

Miscellaneous

Significance:  Mar 23, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

FITNESS-FOR-DUTY (FFD) COLLECTION PERSONNEL COLLECTING FFD SAMPLES FROM CO-WORKERS

The NRC identified a non-cited violation of 10 CFR 26, Appendix A, subpart B, 2.3 (1) when the inspectors observed PSEG's fitness-for-duty (FFD) collection technicians and security officers perform urine and breath collection on co-workers on March 21, 2007. PSEG implemented immediate corrective actions by stopping the practice of collection personnel performing urine and breath collections on other collection technicians, enhancing the station FFD procedures, and by conducting FFD testing of the affected individuals.

The performance deficiency was determined to be more than minor because, if left uncorrected, it would affect the integrity of the FFD program. The finding was determined to be of very low safety significance (Green) using the Physical Protection Significance Determination Process. The finding had a cross-cutting aspect in the area of Human Performance in that PSEG did not have FFD adequate procedures that ensured that the regulatory requirements prohibiting collectors from collecting samples from co-workers were followed.

Inspection Report# : [2007007](#) (*pdf*)

Significance:  Mar 23, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

FITNESS-FOR-DUTY (FFD) COLLECTORS LEAVING FFD SPECIMENS UNATTENDED

The NRC identified a non-cited violation of 10 CFR 26, Appendix A, Subpart B, 2.4 (g) (20) when the inspectors observed PSEG's fitness-for-duty (FFD) collection technicians leaving split FFD urine specimens in unsealed aliquot tubes and sealed specimen containers in unattended work areas on March 21, 2007. The licensee implemented immediate corrective measures by capping and sealing FFD aliquot specimens, requiring that FFD donors witness the transfer of their FFD urine specimen to a laboratory technician through a chain-of-custody form, and by sampling an additional 25 percent of PSEG employees for a FFD test.

The performance deficiency was determined to be more than minor because, if left uncorrected, it could affect the integrity of the FFD program. The inspector determined that the finding was of very low safety significance (Green)

using the Physical Protection Significance Determination Process. The finding had a cross-cutting aspect in the area of Human Performance in that PSEG failed to effectively communicate expectations regarding procedural compliance and personnel did not follow procedures.

Inspection Report# : [2007007](#) (*pdf*)

Last modified : August 24, 2007