

Susquehanna 1

4Q/2007 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Jun 30, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Take Timely Corrective Actions for an "E" Emergency Diesel Generator Jacket Water Leak

The inspectors identified a non-cited violation (NCV) of Title 10 of the Code of Federal Regulations (CFR), Part 50, Appendix B, Criterion XVI, "Corrective Action," when PPL did not correct a condition adverse to quality, associated with a jacket water supply header leak on the "E" emergency diesel generator (EDG) 3R (right) engine cylinder. Inspectors identified that PPL had several opportunities to correct this leak before the condition impacted safety system reliability and availability. PPL identified the jacket water leak during a diesel generator surveillance test on December 2, 2005 and entered this condition into the corrective action system. Although, the leak was small and did not originally impact system operability or reliability, PPL rescheduled, delayed, and deferred the repair work for this gasket connection until the condition resulted in a leak of approximately 12 gallons per hour during a March 28, 2007 surveillance test. Due to the rate of jacket water coolant inventory loss, PPL shutdown the engine and declared the "E" emergency diesel inoperable. PPL repaired the leak and entered the issue into the corrective action program.

This finding is greater than minor because it is associated with the equipment performance attribute of the Mitigating Systems cornerstone and negatively affected the cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. This finding is related to the Problem Identification and Resolution cross-cutting area (Corrective Action) because PPL did not take actions to correct the jacket water leak in a timely manner, commensurate with the issue's safety significance. (P.1(d)) (Section 1R19)

Inspection Report# : [2007003](#) (*pdf*)

Significance:  Jun 29, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

Inoperable Pumphouse Ventilation lineup Corrective Actions

The inspectors identified a non cited violation (NCV) of 10CFR 50 Appendix B, Criterion III Design Control because PPL failed to ensure that the design basis for the Residual Heat Removal System (RHR) was correctly translated into specifications and procedures. In 1990 PPL identified a single point vulnerability that could result in a complete loss of RHR to one of the units during a design basis event. PPL corrected this vulnerability by establishing alternate ventilation by opening a door. In 2002 PPL sealed the door disabling this strategy and reintroducing the same single point vulnerability. In November 2005, PPL identified that the modification had made the ventilation procedure unusable. PPL's assessment of the condition report incorrectly concluded that the ventilation procedure was not part of the design basis and immediate corrective actions were not performed. Following the team's identification of the issue PPL took immediate corrective actions to establish a new ventilation path. The issue had a crosscutting aspect in the area of problem identification and resolution related to corrective actions.

The finding was more than minor because it is associated with the design control attribute of the Mitigating Systems cornerstone and affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. The team conducted a Phase 3 SDP and determined the finding to be of very low safety significance.

Inspection Report# : [2007007](#) (*pdf*)

G**Significance:** Jun 29, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

E EDG Procedure Violation Human Performance

The inspectors identified a non cited violation of Susquehanna Steam Electric Station (SSES) Technical Specification 5.4.1, Administrative Controls, Procedures, for failure to use procedures required by Regulatory Guide 1.33. PPL operators did not follow the procedure adherence requirements when aligning the E emergency diesel generator (EDG) for standby operation prior to removing the C EDG from service for planned maintenance. The field supervisor concurred that not following procedure adherence requirements was an acceptable practice in this instance. Both the station procedure review and management expectations confirmed that the administrative procedure required strict procedure adherence during this evolution. SSES entered this issue into the corrective action program for resolution. The finding is more than minor because it affected the human performance attribute of the mitigating systems cornerstone and affected the cornerstone objective to ensure the availability and reliability of systems that respond to initiating events to prevent undesirable consequences. The finding was determined to be of very low safety significance (Green) because it did not result in a loss of system safety function. This finding has a cross cutting aspect in the area of human performance because SSES did not effectively communicate expectations regarding procedural compliance and because personnel did not follow procedures.

Inspection Report# : [2007007](#) (*pdf*)**G****Significance:** Mar 31, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

Reactor Building Floor and Equipment Drains not Fully Scoped into the Maintenance Rule

The inspectors identified a non-cited violation of 10 CFR Part 50.65 (b)(2) because PPL did not scope an accident and transient mitigation function of the Reactor Building (RB) equipment floor drain system (EFDS) into the Maintenance Rule monitoring program. The RB EFDS is relied upon to mitigate internal flooding events and failure of the system to function could prevent safety-related structures, systems and components from fulfilling their safety-related functions. PPL entered this issue into the condition reporting system.

The finding was more than minor because the RB EFDS's performance is associated with the Equipment Performance attribute of the Mitigating Systems cornerstone and adversely affected the cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences because on January 10, 2007, the RCIC room floor drain isolation valve operator and position indication were found inoperable. This finding was of very low safety significance because the finding did not contribute to an actual loss of mitigation equipment functions, and did not increase the likelihood of a fire or flooding event. A contributing cause of this finding was related to the Corrective Action aspect of the Problem Identification and Resolution cross-cutting area in that PPL's corrective action did not result in all the required functions of the EFDS being scoped into the Maintenance Rule program. Specifically, PPL's corrective actions for NCV 05000387/2004004-02 were not commensurate with the significance and complexity of the issue. (Section 1R12)

Inspection Report# : [2007002](#) (*pdf*)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

G

Significance: Jun 30, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

Violation of 10 CFR 71.5 for Inadequately Secured Transport of Condensate Pump Motors (Class 7 Material)

An NRC-identified finding having very low safety significance was identified due to a deficiency in the radioactive material control program. On March 20, 2007, Susquehanna shipped two condensate pump motors in a sealand container as Class 7 material, surface contaminated objects, to a vendor, in Memphis, TN. Upon receipt at the vendor on March 22, 2007, it was identified that there had been a breach of the package during transit, in that several holes were in the side wall of the container due to inadequate blocking and bracing of the load.

Code of Federal Regulations 10 CFR 71.5 requires that each licensee who transports licensed material shall comply with the applicable requirements of the Department of Transportation (DOT) regulations in 49 CFR Parts 171 through 180. 49 CFR 173.448 requires that each shipment of Class 7 materials must be secured to prevent shifting during normal transportation conditions. 49 CFR 173.410 requires that each package used for the shipment of Class 7 materials be designed so that the package will be capable of withstanding the effects of any acceleration, vibration or vibration resonance that may arise under normal conditions of transport without any deterioration in the integrity of the package. Contrary to these requirements, PPL failed to properly block and brace the contents of a sealand container, resulting in the loss of package integrity. This finding has a cross-cutting aspect in the area of human performance (work practices) because the contracted vendor did not have established instructions for proper loading and bracing of the shipment and PPL did not ensure adequate supervisory and management oversight of the work activities. (H.4.c) (Section 2PS2.1)

Inspection Report# : [2007003](#) (*pdf*)

G

Significance: Jun 30, 2007

Identified By: NRC

Item Type: NCV NonCited Violation

Violation of 10 CFR 71.5 for Inadequately Accounting for Activity in a Shipment of Irradiated Fuel Channels

A self-revealing finding having very low safety significance was identified due to a deficiency in the radioactive material control program. On June 22, 2007, while preparing to load fuel channels in a disposal liner, Susquehanna identified that a liner of irradiated fuel channels previously shipped to the Barnwell Disposal facility in South Carolina contained an incorrect fuel channel for that shipment.

Code of Federal Regulations 10 CFR 71.5 requires that each licensee who transports licensed material shall comply with the applicable requirements of the DOT regulations in 49 CFR Parts 171 through 180. 49 CFR 172.203(d)(3) requires that the shipping papers for Class 7 materials include the activity contained in the shipment. Contrary to these requirements, PPL failed to properly account for the activity contained in a shipment due to the inclusion of the wrong item in the shipment. This finding has a cross-cutting aspect in the area of human performance (work practices) because the contracted vendor did not follow established instructions for proper loading of the shipment and the licensee did not ensure adequate supervisory and management oversight of the work activities. (H.4.c) (Section 2PS2.2)

Inspection Report# : [2007003](#) (*pdf*)

Physical Protection

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the [cover letters](#) to security inspection reports may be viewed.

Miscellaneous

