

# Arkansas Nuclear 2

## 3Q/2009 Plant Inspection Findings

---

### Initiating Events

**Significance:**  Sep 23, 2009

Identified By: Self-Revealing

Item Type: FIN Finding

#### **FAILURE TO IMPLEMENT TROUBLESHOOTING PROCEDURE DURING TROUBLESHOOTING ACTIVITIES**

Green. The inspectors documented a self-revealing finding for failure to follow Procedure EN MA 125, "Troubleshooting," Revision 3. Specifically, the procedure was not implemented, as work conditions dictated, and failed to prevent maintenance from blowing a fuse while performing troubleshooting activities in the steam generator blow down tank level switch circuitry.

The performance deficiency was determined to be more than minor because it was associated with the configuration control attribute of the Initiating Events Cornerstone and affected the objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during power operations, and is therefore a finding. Using Inspection Manual Chapter 0609, Phase 1 Worksheets, the finding was determined to be of very low safety significance because the finding did not contribute to both, the likelihood of a reactor trip and the likelihood that mitigation equipment or functions would not have been available. It was determined that the finding had a crosscutting aspect in the area of human performance associated with work practices [H.4(b)], in that the licensee failed to define and effectively communicate expectations regarding procedural compliance.

Inspection Report# : [2009004](#) (*pdf*)

**Significance:**  Jun 30, 2009

Identified By: NRC

Item Type: FIN Finding

#### **Failure to Follow Procedure to Obtain OSRC Review Prior to Restart**

The inspector identified a finding for failure of operations personnel to follow procedures to obtain an Operational Safety Review Committee review and approval prior to restart of the unit where the cause of the trip had not been positively identified. Specifically, on December 13, 2008, and again on December 23, 2008, Unit 1 was restarted without an Operational Safety Review Committee review and approval as required by the Post Transient Review procedure (OP-1015.037), Attachment B. In both cases, the cause of the trip was identified as probable. The licensee entered this issue into their corrective action program as condition report CR-ANO-C-2009-01217.

The performance deficiency was greater than minor because it could be reasonably viewed as a precursor to a significant event, as evidenced by the December 20, 2008 manual reactor trip. Using Manual Chapter 0609.04, "Phase 1 – Initial Screening and Characterization of Findings," this finding affects the initiating events cornerstone and is determined to have very low safety significance by NRC management review because it did not contribute to both the likelihood of a reactor trip and the likelihood that mitigation equipment or functions would not be available. The finding was determined to have a crosscutting aspect in the area of Human Performance associated with Decision-Making [H.1(b)], in that the licensee made non-conservative assumptions in the decisions to restart the unit after each trip. The licensee failed to conduct sufficient effectiveness reviews to verify the validity of the underlying assumptions.

Inspection Report# : [2009008](#) (*pdf*)

**Significance:**  Mar 24, 2009

Identified By: NRC

Item Type: FIN Finding

### **Failure to Follow Procedure for Flow Accelerated Corrosion Program**

The inspectors documented a self-revealing finding for the failure to properly implement the flow accelerated corrosion control program. Consequently, a nonsafety related extraction steam drain line failed because of flow accelerated corrosion. Engineers had identified the line as being vulnerable to flow accelerated corrosion but did not monitor it. Engineers also failed to integrate relevant industry operating experience into the program. Operators had to reduce Unit 2 power and take the turbine off line in response to the event. The licensee entered this issue into their corrective action program as Condition Report ANO 2-2009-0319.

The performance deficiency was more than minor because it affected the equipment performance attribute of the Initiating Events Cornerstone, and it directly affected the cornerstone objective to limit the likelihood of those events that upset plant stability during power operations. Using Inspection Manual Chapter 0609, "Significance Determination Process," Phase 1 Worksheet, this finding was determined to have very low safety significance because it did not contribute to both the likelihood of a reactor trip and the likelihood that mitigation equipment or functions would not be available. The finding had a crosscutting aspect in the area of Problem Identification and Resolution associated with Operating Experience [P.2(b)], in that licensee personnel failed to implement and institutionalize operating experience through changes to station processes and procedures.

Inspection Report# : [2009002](#) (*pdf*)

---

## **Mitigating Systems**

**Significance:**  Sep 23, 2009

Identified By: NRC

Item Type: NCV NonCited Violation

### **FAILURE TO MAINTAIN SEISMIC DESIGN BASES CONTROL**

Green. The inspectors identified a noncited violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for the failure to assure that applicable design basis for applicable structures, systems, and components were correctly translated into specifications, procedures, and instructions. Specifically, the licensee approved a nonconservative engineering calculation which led to operating procedure changes that allowed the removal of safety related, motor operated valve actuator rigid seismic restraints in the support of maintenance without verifying conformance to meet seismic design basis requirements. The issue was entered into the licensee's corrective action program as Condition Report ANO C 2009 0710.

The performance deficiency was determined to be more than minor because it was associated with the protection against external events attribute of the Mitigating Systems Cornerstone, and affected the associated cornerstone objective to ensure availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences, and is therefore a finding. Specifically, the engineering calculation used to support removal of rigid seismic restraints and maintain operability only analyzed the deadweight of the motor operated valve actuator, not any dynamic seismic loading. Using NRC Manual Chapter 0609, "Significance Determination Process," Phase 1 Worksheets, Mitigating Systems Cornerstone, the finding was determined to have very low safety significance because it did not represent an actual loss of safety function and did not screen as potentially risk significant due to a seismic initiating event. This finding did not have a crosscutting aspect because the engineering calculation used to determine the acceptability of removal of motor operated valve actuator seismic restraints to support maintenance and maintain system operability was made in 1994 and was not indicative of current plant performance.

Inspection Report# : [2009004](#) (*pdf*)

**Significance:**  Sep 23, 2009

Identified By: NRC

Item Type: NCV NonCited Violation

### **FAILURE TO ENSURE THAT CONDITIONS ADVERSE TO QUALITY ARE APPROPRIATELY ENTERED INTO THE CORRECTION ACTION PROGRAM**

Green. The inspectors identified a noncited violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," for the licensee's failure to have adequate measures established to assure that, when a condition adverse to quality was identified, it was appropriately entered into the stations corrective action program. Specifically, the licensee's staff has repeatedly failed to enter conditions adverse to quality, identified during investigation of issues, into the corrective action program. The licensee entered this issue into their corrective action program as Condition Reports ANO C 2009 1544 and ANO C 2008 1536.

The performance deficiency was determined to be more than minor because, if left uncorrected, station personnel's failure to enter conditions adverse to quality into the station corrective action program would result in the licensee's failure to recognize that risk-significant equipment is in a degraded condition and, as such, may not be able to perform its specified safety function, and is therefore a finding. Using Inspection Manual Chapter 0609, "Significance Determination Process," Phase 1 Worksheets, this finding was determined to have a very low safety significance because the finding (1) was not a qualification deficiency confirmed not to result in loss of operability; (2) did not lead to an actual loss of system safety function; (3) did not result in the loss of safety function of a single train for greater than its technical specification allowed outage time; (4) did not represent an actual loss of safety function of one or more nontechnical specification trains of equipment designated as risk-significant per 10 CFR 50.65, for greater than 24 hours; and (5) it did not screen as potentially risk significant due to a seismic, flooding, or severe weather initiating event. This finding had a crosscutting aspect in the area of problem identification and resolution associated with the corrective action program [P.1(a)], in that licensee personnel failed to implement a corrective action program with a low threshold for identifying issues. This also includes identifying such issues completely, accurately, and in a timely manner commensurate with their safety significance.

Inspection Report# : [2009004](#) (pdf)



**Significance:** Dec 31, 2008

Identified By: NRC

Item Type: NCV NonCited Violation

**Failure to Perform an Adequate Risk Assessment when Disabling a Station High Energy Line Break Barrier**

The inspectors identified a noncited violation of 10 CFR 50.65(a)(4), "Requirements for Monitoring the Effectiveness of Maintenance at Nuclear Power Plants," associated with the licensee's failure to perform an adequate risk assessment for planned maintenance. Specifically, the licensee inappropriately assumed that disassembly of Door 340, a high-energy line break barrier, constituted normal plant ingress and egress. As such, this assumption resulted in an inadequate risk assessment, which failed to adequately evaluate the proposed condition of Door 340 and provide appropriate risk management actions for this condition. This issue was entered into the licensee's corrective action program as Condition Report ANO-2-2008-2231.

The finding was more than minor because it was similar to the nonminor considerations of Maintenance Rule Example 7.e in NRC Manual Chapter 0612, Appendix E, "Examples of Minor Issues," in that the licensee's risk assessment contained incorrect assumptions that changed the outcome of the assessment and required additional risk management activities. The inspectors evaluated this finding using NRC Manual Chapter 0609, Appendix K, "Maintenance Risk Assessment and Risk Management Significance Determination Process" because the finding is a maintenance risk assessment issue. Flowchart 1, "Assessment of Risk Deficit," requires the inspectors to determine the risk deficit associated with this issue. This finding was determined to be of very low safety significance because the incremental core damage probability deficit was less than  $1 \times 10^{-6}$ . This finding had a crosscutting aspect in the area of Human Performance associated with Decision Making [H.1(b)], in that the licensee's engineering staff failed to use conservative assumptions and failed to verify the validity of the underlying assumptions used when evaluating the potential effects of disabling a high energy line break barrier for maintenance in accordance with 10 CFR 50.65(a)(4).

Inspection Report# : [2008005](#) (pdf)

**Significance:** **G** Sep 23, 2009

Identified By: NRC

Item Type: NCV NonCited Violation

**FAILURE TO ADEQUATELY IMPLEMENT FOREIGN MATERIAL EXCLUSION CONTROLS**

Green. The inspectors identified a noncited violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," associated with the licensee's failure to adequately implement Procedure EN MA 118, "Foreign Material Exclusion," Revision 5. Specifically, on multiple occasions during Refueling Outage 2R20, licensee personnel failed to implement appropriate foreign material exclusion controls in areas designated as Zone 1 foreign material exclusion areas in accordance with Procedure EN MA 118. This issue was entered into the licensee's corrective action program as Condition Report ANO 2-2009-2843.

The performance deficiency was more than minor because it affected the human performance attribute of the Barrier Integrity Cornerstone and directly affected the cornerstone objective of providing reasonable assurance that physical barriers protect the public from radionuclide releases caused by accidents or events, and is therefore a finding. Furthermore, the significant programmatic deficiencies that were identified associated with this issue could lead to worse errors if left uncorrected. Specifically, station personnel's continued failure to implement appropriate foreign material exclusion controls would result in the introduction of foreign material into critical areas, such as the spent fuel pool or the reactor cavity, which in turn would result in degradation and adverse impacts on materials and systems associated with these areas. Using Inspection Manual Chapter 0609, "Significance Determination Process," Phase 1 Worksheets, this finding was determined to have a very low safety significance because the finding was only associated with the fuel barrier. This finding had a crosscutting aspect in the area of human performance associated with work practices [H.4(b)], in that the licensee failed to define and effectively communicate expectations regarding procedural compliance which resulted in a failure to follow procedure by workers.

Inspection Report# : [2009004](#) (*pdf*)

**Significance:** **G** Jun 23, 2009

Identified By: NRC

Item Type: NCV NonCited Violation

**Failure to Appropriately Identify and Implement Adequate Corrective Actions to Correct a Condition Adverse to Quality Associated with the Material Control System**

The inspectors identified a noncited violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," associated with the licensee's failure to adequately identify and implement adequate corrective actions in response to the identification of defective material. Specifically, in 1997 the licensee identified that two check valves, which had been installed in the postaccident monitoring system, had a defective design that prevented them from seating all of the way. However, the stations material control system was not updated with this information and this model valve was subsequently issued for use in the high pressure safety injection pressurization system which resulted in leakage due to the valves failure to completely seat. The licensee entered this issue into their corrective action program as Condition Report CR ANO 2 2009 1012.

The performance deficiency was more than minor because it affected the design control attribute of the Barrier Integrity Cornerstone and it directly affected the cornerstone objective to provide reasonable assurance that the physical design barriers protect the public from radionuclide releases caused by accidents or events. Using Inspection Manual Chapter 0609, "Significance Determination Process," Phase 1 Worksheet, this finding was determined to have very low safety significance because the finding did not represent a degradation of the barrier functions of the control room or auxiliary building; did not represent an actual open pathway in the physical integrity of reactor containment; and did not involve an actual reduction in the function of hydrogen ignitors in the reactor containment. The finding was determined to have a crosscutting aspect in the area of Problem Identification and Resolution associated with the Corrective Action Program [P.1(c)], in that the licensee failed to thoroughly evaluate problems such that the resolutions address causes and extent of conditions, as necessary. This is indicative of current plant performance because the licensee continues to inadequately evaluate issues and develop appropriate resolutions.

Inspection Report# : [2009003](#) (*pdf*)

---

# Emergency Preparedness

---

## Occupational Radiation Safety

---

### Public Radiation Safety

**Significance:**  Sep 23, 2009

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

#### **FAILURE TO CONTROL ACCESS TO A HIGH RADIATION AREA WITH DOSE RATES IN EXCESS OF 1.0 R/HR**

Green. The inspector reviewed a self-revealing noncited violation of Technical Specification 6.7.2 for failure to control a high radiation area with dose rates in excess of 1.0 R/hr. On September 12, 2009, a radiological barrier was removed by a work crew exposing an area with dose rates in excess of 1.0 R/hr without radiation protection personnel authorization. Radiation protection personnel did not fully understand that the work crew was intending to remove the secondary handhole barrier on the Unit 2 steam generator A to clean the area in preparation for installing the strongback. The dose rate one foot within the handhole was 2.9 R/hr. Radiation protection was made aware of the situation when reviewing the cause for one member of the work crew receiving a dose rate alarm. The issue was documented as Condition Report ANO-2-2009-02609.

The failure to control a high radiation area with dose rates in excess of 1.0 R/hr is a performance deficiency. The finding was greater than minor because it was associated with the Occupational Radiation Safety cornerstone attribute (exposure control) of program and process and affected the cornerstone objective, in that, the failure to properly control a high radiation area with dose rates in excess of 1.0 R/hr had the potential to increase personnel dose. This finding was evaluated using the Occupational Radiation Safety Significance Determination Process and determined to be of very low safety significance because it did not involve: (1) ALARA planning or work control issue, (2) an overexposure, (3) a substantial potential for overexposure, or (4) an impaired ability to assess dose. Additionally, this finding had human performance crosscutting aspects associated with work control in that the work planning did not appropriately plan work activities by incorporating risk insights and radiological safety [H.3(a)].

Inspection Report# : [2009004](#) (*pdf*)

---

### Physical Protection

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the [cover letters](#) to security inspection reports may be viewed.

---

### Miscellaneous

Last modified : December 10, 2009