

# Byron 2

## 1Q/2011 Plant Inspection Findings

---

### Initiating Events

**Significance:**  Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

#### **WATER INTRUSION LEADS TO LOSS OF ANNUNCIATORS (SECTION 1R15.b)**

The inspectors identified a finding of very low safety significance and associated NCV of Byron Operating License Condition 2.C(6) for Unit 1 and 2.E for Unit 2 for the licensee failing to provide an adequate floor drain system as required by the Fire Protection Program. Specifically, the floor drain system in the Upper Cable Spreading Room (UCSR) was not adequate to prevent firefighting water from entering the Control Room through the floor openings and affecting equipments. The licensee entered this issue into the CAP as IR 1046794 and subsequently sealed the UCSR floor.

The finding is greater than minor because it was associated with the protection against external factors attribute of the Initiating Events cornerstone and affected the cornerstone objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during shutdown as well as power operations. The finding is of very low significance because safety equipment functions remained available to control room personnel. This finding was related to the cross-cutting area of Problem Identification and Resolution and its associated component for Corrective Action Program (P.1(d)) because the licensee failed to take appropriate corrective actions to address safety issues and adverse trends in a timely manner, commensurate with their safety significance and complexity. (Section 1R15.b)

Inspection Report# : [2010003](#) (*pdf*)

---

### Mitigating Systems

**Significance:**  Mar 31, 2011

Identified By: NRC

Item Type: NCV NonCited Violation

#### **INADEQUATE INSTRUCTIONS FOR MEASURING ECCS VOIDS**

An NRC-identified finding of very low safety significance and an associated NCV of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified by the inspectors when licensee personnel failed to establish instructions for measuring pipe voids detected during surveillances of the emergency core cooling systems for gas accumulation. Specifically, instructions to measure the size of gas voids detected during venting at each safety injection and residual heat removal system vent location were not provided so that the effect of the void on system operability could be evaluated. The licensee entered this issue into their corrective action program and initiated procedure revisions to provide additional guidance for recording data to size voids identified during venting operations.

The performance deficiency was determined to be more than minor because if left uncorrected it would have the potential to lead to a more significant safety concern. The finding screened as having very low safety significance because it did not result in a loss of operability or functionality. Specifically, a qualitative assessment of the voids detected by venting since the implementation of the licensee's resolution of Generic Letter 2008 01 established reasonable assurance that these voids did not result in a loss of operability. The inspectors did not identify a cross-cutting aspect that represented the underlying cause of this performance deficiency. Therefore, no cross-cutting aspect was assigned to this finding.

Inspection Report# : [2011002](#) (*pdf*)

**Significance:** **W** Feb 07, 2011

Identified By: NRC

Item Type: VIO Violation

**Self-Revealing Failure of the 2A Diesel Generator Upper Lube Oil Cooler**

A finding of low to moderate safety significance (White) and a violation of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was self-revealed when the 2A Diesel Generator (D/G) was required to be shutdown during routine monthly surveillance testing on November 17, 2010, when a flange connection on a spool piece connected to the upper lube oil cooler failed, resulting in a significant oil leak. The cause of the failure was that Work Order 1206254, "Clean Tube Side of Lube Oil Coolers," did not contain appropriate acceptance criteria to ensure proper reassembly of the spool piece for the upper lube oil cooler following maintenance on January 17, 2010. Specifically, the work order package did not contain a final torque verification to ensure that the spool piece flange bolts were torqued to required values, which resulted in the leak. The licensee entered this issue into the correction action program as Issue Report (IR) 1141591, properly re-installed the spool piece, and returned the 2A D/G to service on November 21, 2010.

The inspectors determined that this finding was more than minor, because it was associated with the Human Performance attribute of the Mitigating Systems cornerstone and impacted the cornerstone objective of ensuring the availability of systems that respond to initiating events to prevent undesirable consequences. The NRC assessed this finding through a Phase 3 Risk Evaluation of the Significance Determination Process and made a preliminary determination that it was an issue of low to moderate safety significance (White). The cause of this finding was related to the Work Practices component of the Human Performance cross-cutting area since licensee personnel proceeded in the face of uncertainty or unexpected circumstances during the upper lube oil cooler maintenance activity (H.4(a)). (Section 1R12)

Final Significance Determination issued in report 2011-012 on March 14, 2011.

Inspection Report# : [2011011](#) (*pdf*)

Inspection Report# : [2011012](#) (*pdf*)

**Significance:** **G** Dec 31, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

**Inadequate Instructions for the Inspection of the River Screen House and Essential Service Water Cooling Tower**

A finding of very low safety significance and an associated NCV of 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified by the inspectors when licensee personnel failed to establish specific instructions for inspecting the River Screen House and Essential Service Water Cooling Tower. Specifically, the procedure that provided guidance for inspecting these structures lacked specific instructions on how to detect concrete degradation, erosion, corrosion and biological fouling. The licensee entered this issue into their corrective action program and initiated procedure revisions to provide further direction for identifying and documenting the degradation of these structures and related components.

The performance deficiency was determined to be more than minor because if left uncorrected it would have the potential to lead to a more significant safety concern. The finding screened as of very low safety significance because it was a qualification deficiency confirmed not to result in a loss of operability or functionality. Specifically, a qualitative assessment of historic surveillance reports found the documented results acceptable. The inspectors determined that this finding did not represent current licensee performance and therefore no cross-cutting aspect was assigned. (Section 1R07.1)

Inspection Report# : [2010005](#) (*pdf*)

**Significance:** **G** Dec 03, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

**Failure to Provide Adequate Guidance in Safe-Shutdown Procedures**

A finding of very low safety-significance and associated NCV of Technical Specification 5.4.1.c for Units 1 and 2

was identified by the inspectors for the licensee's failure to provide adequate guidance in safe shutdown procedures. Specifically, the licensee failed to provide adequate guidance to reenergize the 4 kiloVolt (kV) buses, which were required to power safe shutdown components to achieve hot shutdown in the event of a fire in Fire Zone 11.3-0. The licensee subsequently entered the issue into their corrective action program and initiated actions, which included recommendations to revise safe shutdown procedures to provide guidance for recovery actions to reenergize the required affected busses.

The inspectors determined that this finding was more than minor because the failure to provide adequate procedural guidance to reenergize the 4 kV buses could have potentially compromised the ability to safely shutdown the plant in the event of a fire in Fire Zone 11.3-0. This finding was of very low safety significance (Green) based on a Phase III significance determination analysis. The finding did not have a cross-cutting aspect because it was not reflective of current performance. (Section 1R05.1R05.6.b(1))

Inspection Report# : [2010006](#) (pdf)

**Significance:**  Dec 03, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **Failure to Periodically Test 125 Vdc Molded Case Circuit Breakers**

. A finding of very low safety significance and associated NCV of the Byron Station facility operating licensee conditions for fire protection was identified by the inspectors for the licensee's failure to periodically test samples of molded case circuit breakers (MCCBs) at the 125 Volt direct current (Vdc) level. The licensee subsequently entered the issue into their corrective action program and verified that sufficient design margin existed such that breaker coordination would not be adversely affected.

The inspectors determined that this finding was more than minor because the failure to test the MCCBs would result in a failure to detect excessive set-point drift which impacted breaker coordination. This finding was of very low safety significance (Green) because the licensee verified that sufficient design margin existed such that breaker coordination would not be adversely affected. In addition, no failures of 125 Vdc MCCBs to trip due to set-point drift had been identified. The finding did not have a cross-cutting aspect because it was not reflective of current performance. (Section 1R05.1R05.6.b(2))

Inspection Report# : [2010006](#) (pdf)

**Significance:**  Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **INADEQUATE EVALUATION OF SHIM PACK FOR THE UPPER STEAM GENERATOR LATERAL SUPPORTS**

The inspectors identified a finding of very low safety significance and associated Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," for the inadequate design evaluation of the shim packs for the Upper Steam Generator Lateral Supports. Specifically, the licensee's calculations failed to demonstrate that the stresses in the shims and the concrete met the acceptance criteria. The licensee entered the issue into the corrective action program (CAP) as Issue Report (IR) XXXXXX to perform/revise the design basis calculations.

The finding was determined to be more than minor because it was associated with the Mitigating Systems cornerstone attributes of Design Control and Equipment Performance and affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. The finding is of very low safety significance because it was a design qualification deficiency confirmed not to result in the loss of operability or functionality. This finding does not have a cross-cutting aspect due to its age. (Section 1R15.b)

Inspection Report# : [2010003](#) (pdf)

**Significance:**  Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

## **LOOSE DEBRIS INSIDE OF UNIT CONTAINMENT AT THE START OF THE REFUELING OUTAGE**

The inspectors identified a finding of very low safety significance and associated Non-Cited Violation of 10 CFR 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," for the licensee's failure to follow procedure BAP 1450-1, "Access to Containment." Specifically, the inspectors determined that the licensee brought loose debris items into Unit 2 containment prior to Mode 5 and did not perform an engineering evaluation required by procedure. The licensee entered this issue into the CAP as IR 1058304 and completed an evaluation to verify that the containment sump was not adversely affected.

The finding is more than minor because, if left uncorrected, the issue could have become a more significant safety concern. The inspectors evaluated the finding using IMC 0609, "Significance Determination Process," Attachment 0609.04, "Phase 1 – Initial Screening and Characterization of Finding," dated January 10, 2008, for the Mitigating Systems Cornerstone. Since this finding was not a design or qualification deficiency, did not result in loss of system or train safety function, and was not safety significant due to external events, this issue is screened as very low safety significance. This finding is related to the Work Control component of the Human Performance cross cutting area for the licensee's failure to coordinate work activities and the need for work groups to coordinate with each other. (H.3 (b)) (Section 1R20.b)

Inspection Report# : [2010003](#) (pdf)

**Significance:**  Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **FAILURE TO APPROPRIATELY ANALYZE THE DEGRADED VOLTAGE TIMER SETTINGS**

A finding of very low safety significance and associated Non-Cited Violation of 10 CFR Part 50, Appendix B, Criterion III, Design Control, was identified by the inspectors for the licensee's failure to have an appropriate analysis for the second level undervoltage (degraded voltage) relay timer settings. Specifically, Byron's analysis EC 377631, "Evaluation and Technical Basis for the AP System Second Level Undervoltage (Degraded Voltage) Time Delay Settings," dated February 3, 2010, failed to demonstrate the ability of the permanently connected safety-related loads to continue to operate for 5 minutes and 40 seconds without sustaining damage during a worst case, non-accident degraded voltage condition. The licensee entered this issue into their corrective action program as IR 1071667.

The performance deficiency was determined to be more than minor because the finding affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. Specifically, there was reasonable doubt as to whether the permanently connected safety-related loads would remain operable during a worst case, non-accident degraded voltage condition for the duration of the time delay chosen. This finding is of very low safety significance (Green), because the design deficiency was confirmed not to result in loss of operability or functionality. After consulting with the Office of Nuclear Reactor Regulation (NRR), the inspectors identified a cross-cutting aspect associated with this finding in the area of human performance, decision making because the licensee did not use conservative assumptions based on NRC approved changes to the licensing basis in choosing the worst case degraded voltage condition in their February 2010 analysis. Specifically, in their February 2010 analysis, the licensee chose 75 percent of nominal voltage as their lower limit of degraded voltage (based on a not formally approved manual action), opposed to the worst possible degraded voltage of approximately 66 percent of nominal (first level undervoltage setpoint). (IMC 0310, Section 06.01.a. (2))

Inspection Report# : [2010003](#) (pdf)

**Significance:**  Jun 30, 2010

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

### **0B FIRE PUMP DISCHARGE VALVE DISCOVERED CLOSED (SECTION 1R12)**

A self-revealed finding of very low safety significance and associated Non-Cited Violation of Byron Operating License Condition 2.C(6) for Unit 1 and 2.E for Unit 2 for the licensees failure to identify the separation of the 0B Fire Pump discharge valve, 0FP018B, valve stem and valve disk. As a result, the mitigating functions associated with the 0B Diesel driven fire pump would not be assured. The licensee entered this issue into the Corrective Action Program (CAP) as Issue Report (IR) 1063395 and repaired the valve.

The issue is more than minor because it affected the Mitigating Systems Cornerstone attribute of Protecting Against External Events and affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. Based on a Phase 3 significance

evaluation, the finding is determined to be of very low safety significance. The primary cause for this finding was related to the cross-cutting area of Problem Identification and Resolution and its associated component for Corrective Action Program (P.1(c)) because licensee personnel failed to identify the discharge valve's functionality was impacted by its degraded state. (Section 1R12.b)

Inspection Report# : [2010003](#) (pdf)

**Significance:** SL-IV Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

**FAILURE TO REPORT AN AUTOMATIC RPS AND AUXILIARY FEEDWATER ACTUATION WHILE SHUTDOWN THUS IMPACTING THE REGULATORY PROCESS.**

A Severity Level IV, NCV of 10 CFR 50.72(b)(3)(iv)(A) was identified by the inspectors for the licensee's failure to recognize that a valid Unit 2 automatic Reactor Protection System (RPS) and Auxiliary Feedwater (AF) actuation while shutdown were reportable conditions. Consequently, the licensee failed to make an eight hour report as required by 10 CFR 50.72. This issue was documented in the licensee's Corrective Action Program as IR 1060177 and the licensee subsequently reported the event.

This finding was evaluated under Traditional Enforcement because it had the potential for impacting the NRC's ability to perform its regulatory function. However, this violation was of very low safety significance because immediate NRC follow-up action was not required. The NRC has characterized this violation as a Severity Level IV NCV in accordance with Section IV.A.3 and Supplement 1 of the NRC Enforcement Policy. The cause of this finding was directly related to the cross-cutting area of Problem Identification and Resolution (P.1(c)) because the licensee did not thoroughly evaluate and classify a condition adverse to quality for reportability. (Section 4OA3).

The performance deficiency associated with this traditional enforcement case is item 2010-003-07.

Inspection Report# : [2010003](#) (pdf)

**Significance:**  Jun 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

**FAILURE TO REPORT AN AUTOMATIC RPS AND AUXILIARY FEEDWATER ACTUATION WHILE SHUTDOWN .**

A Green Finding and associated NCV of 10 CFR 50.72(b)(3)(iv)(A) was identified by the inspectors for the licensee's failure to recognize that a valid Unit 2 automatic Reactor Protection System (RPS) and Auxiliary Feedwater (AF) actuation while shut down were reportable conditions. Consequently, the licensee failed to make an 8 hour report as required by 10 CFR 50.72. This issue was documented in the licensee's CAP as IR 1060177 and the licensee subsequently reported the event.

This finding was of very low safety significance (Green) because immediate NRC follow-up action was not required. The cause of this finding was directly related to the cross-cutting area of Problem Identification and Resolution (P.1(c)) because the licensee did not thoroughly evaluate and classify a condition adverse to quality for reportability. (Section 4OA3).

The traditional enforcement issue associated with this finding is tracked as item 2010-003-06.

Inspection Report# : [2010003](#) (pdf)

---

## Barrier Integrity

**Significance:**  Mar 31, 2011

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

**SELF-REVEALED LOW FLOW TO REACTOR CONTAINMENT FAN COOLER**

A self-revealed finding of very low safety significance was identified on January 21, 2011, when licensee personnel

failed to ensure that surveillance procedures for measuring essential service water flow through reactor containment fan coolers was adequate. As a result, during routine surveillance testing, measured essential service water flow through the reactor containment fan coolers was less than technical specification requirements.

The inspectors concluded that the finding was more than minor because it was associated with the Configuration Control attribute of the Barrier Integrity Cornerstone and affected the cornerstone objective of providing reasonable assurance that physical barriers, including the containment, protect the public from radionuclide releases caused by accidents and events. Specifically, the finding was determined to adversely impact the required technical specification required flow rate of essential service water through the reactor containment fan coolers. The inspectors evaluated the finding using IMC 0609.04, "Phase 1 – Initial Screening and Characterization of Findings," and based on a "No" answer to all of the questions in the Barrier Integrity column of Table 4a, determined the finding to be of very low safety significance. This finding had a cross-cutting aspect in the area of Human Performance, Resources (H.2(c)) because the licensee had repeatedly modified the surveillance procedure without ensuring adequate operational margin to the technical specification limit. The licensee entered this issue into the corrective action program and initiated actions to revise the surveillance procedure to raise the as-left essential service water system flow rate.

Inspection Report# : [2011002](#) (pdf)

**Significance:**  Mar 31, 2011

Identified By: NRC

Item Type: NCV NonCited Violation

#### **FAILURE TO EVALUATE THE EFFECTS OF DYNAMIC LOADS AT THE CS DISCHARGE PIPING**

An NRC-identified finding of very low safety significance and an associated NCV of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," was identified by the inspectors when licensee personnel failed to evaluate the effects of dynamic loads at the containment spray discharge piping. The inspectors were concerned because portions of the containment spray discharge piping were normally voided by design and neither the structural design nor operation of the system addressed the dynamic loads that would result when the voided piping was rapidly filled following system initiation. The licensee entered this issue into the corrective action program and, at the time of the inspection, planned to include an evaluation of dynamic loads into the design basis of containment spray.

The performance deficiency was determined to be more than minor because it was associated with the Structures, Systems, Components, and Barrier Performance attribute of the Barrier Integrity Cornerstone and adversely affected the cornerstone objective of providing reasonable assurance that physical design barriers protect the public from radionuclide releases caused by accidents or events. The finding screened as having very low safety significance because it did not affect either core damage frequency or large early release frequency. The inspectors determined that this finding had a cross-cutting aspect in the area of Problem Identification and Resolution, Operating Experience, because the licensee did not thoroughly evaluate external operating experience.

Inspection Report# : [2011002](#) (pdf)

**Significance:**  Sep 30, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

#### **FAILURE TO PERFORM ADEQUATE EVALUATION FOR CRANE UPGRADE**

A finding of very low safety significance and an associated Non-Cited Violation (NCV) of Title 10 Code of Federal Regulations (CFR), Part 50, Appendix B, Criterion III, "Design Control" was identified by the inspectors for the licensee's failure to perform adequate evaluations to upgrade the single failure proof crane. Specifically, the inspectors identified six examples where the licensee failed to perform adequate evaluations in accordance with American Society of Mechanical Engineers (ASME) NOG-1-2004, requirements. The licensee documented the conditions in Issue Report (IR) 1099897, and IR 1100062 and initiated actions for calculation revisions and field modifications.

The Fuel Handling Building (FHB) crane is designed to Seismic Category I requirements and the licensee used compliance with ASME NOG-1-2004, as the design basis for their crane upgrade to a single failure proof crane. The inspectors determined that the failure to perform adequate evaluations was contrary to ASME NOG-1-2004 requirements and was a performance deficiency. The finding was more than minor as it was associated with the Barrier Integrity cornerstone, because a fuel handling building crane heavy load drop can damage the Spent Fuel Pool (SFP) Cooling System or spent fuel cladding. The inspectors evaluated the finding using Inspection Manual Chapter

(IMC) 0609.04, “Phase 1 - Initial Screening and Characterization of Findings,” and based on a “No” answer to all of the questions in the Barrier Integrity column of Table 4a, determined the finding to be of very low safety significance (Green). This finding has a cross-cutting aspect in the area of Human Performance, Resources because the licensee did not provide adequate oversight of work activities, including contractors, such that design documentation was accurate to support nuclear safety. H.2(c) (Section 4OA5)

Inspection Report# : [2010004](#) (pdf)

---

## Emergency Preparedness

---

## Occupational Radiation Safety

**Significance:**  Mar 31, 2011

Identified By: NRC

Item Type: NCV NonCited Violation

### **OUT-OF-DATE/EXPIRED RESPIRATOR CARTRIDGES**

An NRC-identified finding of very low safety significance and an associated NCV of TS 5.4.1 was identified by the inspectors when out of date respirator cartridges were found available for use. Radiation protection procedures that cover respiratory protection program did not require cartridges to be replaced after the manufacturer specified shelf-life had expired. The manufacturer of the respirator canister recognized that it was possible that chemical cartridges, which were more than a year old, might lose some of their efficiency in their ability to absorb contaminants. The manufacturer prescribed an expiration date of 3 years from the date of the canister manufacture and this date was stamped on to the canister label.

The regulatory authority for respiratory protection is the Occupational Safety and Health Administration (OSHA). The regulations are defined in 29 CFR 1910.134 titled “Respiratory Protection.” Title 29 CFR 1910.134(d)(3)(iii) provides requirements for the protection against gases and vapors. These requirements include that air purifying respirators be equipped with an End-of-Service Life Indicator (ESLI) or the employer implements a change schedule for canisters and cartridges that is based on objective information or data that will ensure that canisters and cartridges are changed before the end of their service life. The employer shall describe in the respirator program the information and data relied upon and the basis for the canister and cartridge change schedule and the basis for reliance on the data.

The inspectors reviewed the guidance in IMC 0612, Appendix E, Examples of Minor Issues, but did not identify any examples similar to the performance deficiency. However, in accordance with IMC 0612, the inspectors determined that the finding was more than minor because if left uncorrected the performance deficiency would have the potential to lead to a more significant safety concern. Specifically, cartridges that were beyond the recommended shelf-life could lose some of their efficiency in their ability to absorb contaminants and result in additional radiation doses to the users. The finding was assessed using the Occupational Radiation SDP and was determined to be of very low safety significance because these problems were not as-low-as-is-reasonably-achievable (ALARA) planning issues, there were no overexposures, nor substantial potential for overexposures and the licensee’s ability to assess dose was not compromised. Corrective actions planned by the licensee included replacing the expired cartridges and adding guidance to procedures for checking expiration dates during routine inventories. The inspectors determined that the cause of this incident involved a cross-cutting component in the human performance area for inadequate resources. Specifically, the licensee did not have complete, accurate and up-to-date procedures.

Inspection Report# : [2011002](#) (pdf)

---

## Public Radiation Safety

---

# Physical Protection

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the [cover letters](#) to security inspection reports may be viewed.

---

## Miscellaneous

**Significance:** SL-IV Dec 31, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **Inadequate Procedures for Implementing FSAR Required Annulus Cooling (Section 40A5.2.b.1)**

The inspectors identified a Severity Level IV NCV of very low safety significance of 10 CFR 72.150, "Instruction, Procedures, and Drawings." Specifically, the licensee failed to have procedures in place to ensure that the design basis peak fuel cladding limit would not be exceeded during canister loading operations. The licensee entered this issue into their corrective action program and revised the procedure to provide monitoring criteria.

The violation was determined to be of more than minor significance using IMC 0612, "Power Reactor Inspection Reports," Appendix E, "Examples of Minor Issues," Example 2c, in that the procedures failed to incorporate thermal acceptance criteria established by the Holtec Final Safety Analysis Report and that the failure to incorporate thermal acceptance criteria was repetitive. Although the violation contributed to the likelihood of peak fuel cladding temperatures exceeding the safety limit, subsequent analysis by the licensee determined that fuel cladding temperature limits were not exceeded. The violation screened as having very low safety significance. (Section 40A5.2)

Inspection Report# : [2010005](#) (*pdf*)

**Significance:** SL-IV Dec 31, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **Inadequate Procedural Guidance for Heavy Loads Operations (Section 40A5.2.b.2)**

The inspectors identified a Severity Level IV NCV of very low safety significance of 10 CFR 72.150, "Instructions, Procedures, and Drawings." Specifically, the licensee failed to have procedures in place to ensure that heavy loads were operated safely in the Fuel Handling Building. The licensee entered this issue into their corrective action program and revised the procedure to provide monitoring criteria.

The violation was determined to be of more than minor significance because if left uncorrected, it could lead to a more significant safety concern. Consistent with the guidance in Section 2.6.D of the NRC Enforcement Manual, if a violation does not fit an example in the Enforcement Policy Violation Examples, it should be assigned a severity level: (1) commensurate with its safety significance; and (2) informed by similar violations addressed in the Violation Examples. The violation screened as having very low safety significance. (Section 40A5.2)

Inspection Report# : [2010005](#) (*pdf*)

**Significance:** SL-IV Sep 17, 2010

Identified By: NRC

Item Type: NCV NonCited Violation

### **Inadequate procedures for Implementing FSAR Required Annulus Cooling.**

The inspectors identified a Severity Level IV NCV of 10 CFR 72.150, "Instructions, Procedures, and Drawings." Specifically, the licensee failed to have procedures in place to ensure that the design basis peak fuel cladding temperature limit would not be exceeded during vacuum drying operations. The licensee entered this issue into its corrective action program and revised the procedure to provide monitoring criteria.

The violation was determined to be of more than minor significance because, if left uncorrected, it could lead to a more safety significant event. Although the violation contributed to the likelihood of peak fuel cladding temperatures exceeding the safety limit, subsequent analysis by the licensee and the NRC determined that fuel cladding temperature limits were not exceeded during this event; therefore, the violation screened as having very low safety significance.

(Section 4OA5.2)

Inspection Report# : [2010007](#) (*pdf*)

Last modified : June 07, 2011