

Sequoyah 2

2Q/2012 Plant Inspection Findings

Initiating Events

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Implement Procedures for Tornado Watch/Warning

The inspectors identified a noncited violation of Units 1 & 2 Technical Specification of 6.8.1.a for the licensee's failure to adequately implement procedure AOP-N.02, "Tornado Watch/Warning," Revision 28. On March 2, 2012, the licensee entered AOP-N.02 due to a tornado watch/warning and failed to secure or remove loose material in the Switchyard/Transformer Yard as required by the procedure. This issue was entered into the licensee's corrective action program as Problem Evaluation Report (PER) 515684.

Inspection Report# : [2012002](#) (*pdf*)

Mitigating Systems

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to Meet Fire Drill Training Requirements

The inspectors identified a noncited violation of facility operating license DPR-77 condition 2.C.(16) and facility operating license DPR-79 condition 2.C.(13) for failure to implement and maintain in effect all provisions of the approved fire protection program. Specifically, Sequoyah's Fire Protection Report Part II, Section 9.3.b.2 – Fire Drills requires a minimum of one drill per shift every calendar quarter, a minimum on one unannounced drill per shift per year, at least one drill per shift per year is performed on a "backshift" for each fire brigade, and fire brigade members including leaders shall participate in at least two drills per year. The inspectors

identified multiple examples of the licensee's failure to meet these requirements in calendar years 2010 and 2011. This issue was entered into the licensee's corrective action program as Problem Evaluation Report (PER) 513378, 512736, and 527875.

Inspection Report# : [2012002](#) (*pdf*)

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: FIN Finding

Failure to Follow Corrective Action Program Procedures

The inspectors identified a finding for the licensee's failure to meet the requirements of corrective action program procedure NPG-SPP-03.1.7, PER Actions, Revision 2. Specifically, the licensee failed to ensure that the corrective action plan and associated actions addressed the required action and schedule associated with PER 432510, which documented the need to address a condition involving water accumulation in manhole locations containing electrical cable runs. This issue was

entered into the licensee's corrective action program as Problem Evaluation Report (PER) 433761, 432510, and 505259.
Inspection Report# : [2012002](#) (*pdf*)

G

Significance: Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Change to Fire Protection Program Which Adversely Affected Safe Shutdown Without Prior NRC Approval

The inspectors identified a non-cited violation of Sequoyah operating license conditions 2.C. (16) and 2.C. (13) for Units 1 and 2 respectively, for a change made to the Sequoyah fire protection program which was determined to adversely affect safe shutdown (SSD), without prior NRC approval. Specifically, in lieu of protecting the cables and equipment to ensure that one train of equipment required for SSD was free of fire damage, the licensee made a change to the Sequoyah fire protection program in 2002 that added new operator manual actions (OMAs) to achieve SSD, without prior NRC approval. The evaluation performed in 2002 for the new OMAs was not adequate to support the conclusion that adding the OMAs did not adversely affect post-fire SSD because the evaluation only addressed OMA feasibility and did not address defense-in-depth. The licensee entered this issue in the corrective action program as problem evaluation report 324757 to track resolution.

Inspection Report# : [2012002](#) (*pdf*)

G

Significance: Dec 31, 2011

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Failure to Follow Procedure for Loss of Power Diesel Generator Start Instrumentation Surveillance Testing

A self-revealing non-cited violation of Unit 2 Technical Specification (TS) 6.8.1.a was identified for the licensee's failure to follow station procedures during the performance of a surveillance testing activity. While performing degraded voltage/load shed relay testing associated with the 2B 6.9kV shutdown board, the use of improper test equipment and the incorrect connection of test equipment resulted in a control power circuit fuse being blown, which caused inoperability of an emergency diesel generator and a motor driven auxiliary feedwater train. This issue was entered into the licensee's corrective action program as Problem Evaluation Report (PER) 415324.

Inspection Report# : [2011005](#) (*pdf*)

G

Significance: Dec 31, 2011

Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Nuclear Instrumentation System Channel Calibration Error

A self-revealing non-cited violation of Unit 2 TS 3.0.3 was identified for the licensee's failure to place the unit in Mode 3 within seven hours when a Limiting Condition for Operation (LCO) was not met in Modes 1 and 2. The requirements of LCO 3.3.1, "Reactor Trip System Instrumentation," associated with the power range neutron flux function in Modes 1 and 2 were not met for a period of approximately 24 hours. This was the result of an error made during the performance of a channel calibration activity, which caused one channel to be left in an inoperable condition. This issue was entered into the licensee's corrective action program as PER 397142.

Inspection Report# : [2011005](#) (*pdf*)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Security

Although the Security Cornerstone is included in the Reactor Oversight Process assessment program, the Commission has decided that specific information related to findings and performance indicators pertaining to the Security Cornerstone will not be publicly available to ensure that security information is not provided to a possible adversary. Other than the fact that a finding or performance indicator is Green or Greater-Than-Green, security related information will not be displayed on the public web page. Therefore, the [cover letters](#) to security inspection reports may be viewed.

Miscellaneous

Significance: SL-IV Sep 30, 2011

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to report system actuation

The inspectors identified a non-cited violation of 10 CFR 50.73, "Licensee Event Report System," for the licensee's failure to report an invalid system actuation. On May 5, 2011, a containment ventilation isolation (CVI) signal was inadvertently generated on Unit 2 while performing surveillance testing. This system actuation was not reported to the NRC as required by 10 CFR 50.73(a)(2)(iv) within 60 days of discovery of the event. This issue was entered into the licensee's corrective action program as PER 417453, and was reported to the NRC as EN #47249 on September 8, 2011.

This violation was determined to be applicable to traditional enforcement because of its potential to impact the ability of the NRC to perform its regulatory oversight function, and was therefore evaluated in accordance with the NRC Enforcement Policy. This issue was determined to be a Severity Level IV violation in accordance with Section 6.9.d.9 of the NRC Enforcement Policy. No cross-cutting aspect was assigned since traditional enforcement violations for which there are no associated ROP findings are not screened for cross-cutting aspects. (Section 1R15)

Inspection Report# : [2011004](#) (*pdf*)

Last modified : September 12, 2012