

Oconee 3

4Q/2012 Plant Inspection Findings

Initiating Events

Mitigating Systems

Significance:  Sep 30, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to maintain accurate pre-fire plans

An NRC-identified non-cited violation of the Oconee Units 1, 2, and 3 renewed facility operating licenses, condition 3.D. was identified for the licensee's failure to maintain accurate pre-fire plans in areas that contain safety related equipment. Discrepancies such as failure to identify compressed gas cylinder and chemical storage areas, fire extinguisher locations, and physical building characteristics were identified in 79 fire zone pre-fire plans. The licensee modified the pre-fire plans to correct the deficiencies. This violation was entered into the licensee's corrective action program (CAP) as PIP O-12-10817.

The performance deficiency (PD) was more than minor because it was associated with the Mitigating Systems Cornerstone Attribute of Protection Against External Events (Fire) and adversely affected the cornerstone objective in that inaccurate pre-fire plans could impact the fire brigade's ability to effectively fight a fire. The inspectors determined that the finding was of very low safety significance (Green) because an alternate means of safe shutdown was available, the fire brigade consisted of plant personnel familiar with the plant layout and associated hazards, and appropriate firefighting equipment was available in each area. The cause of the PD was directly related to the aspect of complete, accurate, and up-to-date procedures of the Resources Component in the cross cutting area of Human Performance because the licensee failed to ensure that other personnel were assigned the responsibility to maintain the pre-fire plans. [H.2(c)] (1R05)

Inspection Report# : [2012004](#) (pdf)

Significance:  Jun 30, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to perform a calculation to determine site PMP ponding levels in a timely manner

An NRC-identified non-cited violation (NCV) of 10 CFR 50, Appendix B, Criterion XVI, Corrective Action, was identified for the licensee's failure to implement corrective actions for a condition adverse to quality. The licensee did not develop a calculation to determine the maximum on-site water level resulting from a Probable Maximum Precipitation (PMP) event in a timely manner. Corrective actions included development of a calculation bounding the expected water level resulting from a PMP event. This violation is in the licensee's corrective action program (CAP) as PIP O-12-7994.

The performance deficiency (PD) was more than minor because it was associated with the Mitigating Systems Cornerstone attribute of Design Control and adversely impacted the cornerstone objective because there was reasonable doubt that plant equipment was adequately protected from the increased water level and therefore had the potential to result in a loss of systems that respond to initiating events to prevent undesirable consequences. The finding was determined to be of very low safety significance (Green) because the licensee subsequently demonstrated that the water entering the plant structures would not have resulted in the loss of safety-related or risk-significant equipment. This finding does not have a cross-cutting aspect because the performance deficiency was not indicative of

Inspection Report# : [2012003](#) (pdf)

Significance:  Jun 30, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Failure to follow the engineering change process

An NRC-identified non-cited violation of 10 CFR 50, Appendix B, Criterion V, Instructions, Procedures and Drawings, was identified for the licensee's failure to follow EDM 601, Engineering Change Manual, during the design and construction of the Protected Service Water (PSW) ductbank / manhole structure. As a result, rainwater accumulation during a Probable Maximum Precipitation (PMP) event could enter the Auxiliary Building (AB). Corrective actions included sealing penetrations, installation of an isolation valve, revising procedures, and conducting training. This violation is in the licensee's CAP as PIPs O-12-1317, O-12-1876, O-12-1906 and O-12-2443.

The performance deficiency was determined to be more than minor because it was associated with the Mitigating Systems cornerstone attribute of Protection Against External Factors - Flooding and adversely affected the cornerstone objective in that water from a PMP event could enter the AB and adversely impact safety-related and / or risk-significant equipment. The licensee was required to perform extensive modeling and calculations to determine what the impact from a PMP event would be on the SSC's located in the lower elevations of the AB. The finding was of very low safety significance due to the high likelihood that the source of the water leaking into the AB would be correctly identified and isolated prior to the loss of safety-related equipment due to the flood. The cause of the finding was directly related to the aspect of ensuring supervisory oversight of work activities such that nuclear safety is supported of the Work Practices component in the cross-cutting area of Human Performance because the licensee failed to ensure that the appropriate level of supervisory and management oversight was applied during design, modification and construction of Manhole 7. [H.4(c)] (Section 1R01)

Inspection Report# : [2012003](#) (pdf)

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: FIN Finding

Failure to Adequately Test Safety-Significant Medium Voltage Cables

An NRC-Identified finding was identified for the licensee's failure to develop an adequate procedure for performing cable degradation testing on medium voltage cables. Consequently, a degraded condition of one of the conductors from CT-5 to the standby buses was not addressed for approximately 18 months and subsequently failed accruing approximately 30 days of unavailability to replace the cable.

The performance deficiency (PD) was determined to be more than minor as it affected the Mitigating Systems cornerstone attribute of equipment performance in that failure to identify the degraded condition resulted in unplanned unavailability of the CT-5 power path. The finding was of very low safety significance because the "Y" phase cable from CT-5 was capable of performing its function from June 2010 until December 22, 2011. The cause of this finding was directly related to the implementation of operating experience aspect of the Operating Experience component of the Problem Identification and Resolution cross-cutting area, in that, the licensee failed to incorporate industry guidance to establish test acceptance criteria for degradation of power cables insulation. [P.2(b)]

Inspection Report# : [2012002](#) (pdf)

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: NCV NonCited Violation

Inadequate Procedure for Installation of Safety-related Control Cables

An NRC-Identified non-cited violation (NCV) of 10 CFR 50, Appendix B, Criterion V, Instructions, Procedures, and

Drawings, was identified for the licensee's failure to develop adequate procedures governing the installation of safety related control cables. The work package did not contain the maximum tension limits and the specified testing method was inadequate to demonstrate that control cables had not been damaged during the cable pull. The licensee revised TI/0/A/3000/030, PSW Cable Pulling in Duct Banks Using Mechanical Device, and re-tested the control cable ensure its functional integrity.

The performance deficiency was determined to be more than minor because it was associated with the Design Control attribute of the Mitigating Systems Cornerstone and adversely affected the cornerstone objective in that it could represent an indeterminate functional condition for proper control functions for safety-related equipment operation in the PSW and the SSF. The finding was of very low safety significance because it did not result in the loss of any system safety function. The cause of the finding directly involved the cross-cutting aspect of appropriate planning of work activities in the Work Control component of the Human Performance area, in that the licensee failed to implement procedures which established planned contingencies, compensatory actions, and abort criteria. [H.3(a)]

Inspection Report# : [2012002](#) (*pdf*)

Significance:  Mar 31, 2012

Identified By: NRC

Item Type: FIN Finding

Failure to Ensure UFSAR described Flood Protection Measures In Place

An NRC-Identified finding was identified for the licensee's failure to ensure the Oconee UFSAR-described Auxiliary Building (AB) flood protection measures were maintained. Penetrations were not included in a surveillance program to verify below-grade penetrations would not allow flooding of the AB existed below the design basis 796.5 foot mean sea level (msl) elevation.

The performance deficiency was more than minor because if left uncorrected, it could lead to a more significant safety concern, in that, other onsite activities such as excavation work exterior to the AB walls could provide a pathway for flood waters to enter the AB through the uncontrolled penetrations causing the loss of accident mitigation systems. The finding was of very low safety significance because an actual loss of operability or functionality did not occur. The cause of the finding was directly related to the appropriate corrective actions aspect of the Corrective Action Program component in the area of Problem Identification and Resolution because the licensee failed to correct the O-310 K series to identify that all external AB walls as flood barriers. [P.1(d)]

Inspection Report# : [2012002](#) (*pdf*)

Barrier Integrity

Emergency Preparedness

Occupational Radiation Safety

Public Radiation Safety

Security

Although the Security Cornerstone is included in the Reactor Oversight Process assessment program, the Commission has decided that specific information related to findings and performance indicators pertaining to the Security Cornerstone will not be publicly available to ensure that security information is not provided to a possible adversary. Other than the fact that a finding or performance indicator is Green or Greater-Than-Green, security related information will not be displayed on the public web page. Therefore, the [cover letters](#) to security inspection reports may be viewed.

Miscellaneous

Last modified : February 28, 2013