



Home > Nuclear Reactors > Operating Reactors > Reactor Oversight Process > Plant Summaries > Limerick 2 > Quarterly Plant Inspection Findings

Limerick 2 – Quarterly Plant Inspection Findings

3Q/2017 – Plant Inspection Findings

On this page:

- Initiating Events
- Mitigating Systems
- Barrier Integrity
- Emergency Preparedness
- Occupational Radiation Safety
- Public Radiation Safety
- Security

Initiating Events

Mitigating Systems

Significance: G Mar 31, 2017

Identified By: NRC

Item Type: NCV Non-Cited Violation

Inadequate Work Instructions for Staging of Equipment and Routing of Temporary Power Cables

The inspectors identified a Green NCV of 10 Code of Federal Regulations (CFR) 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," for Exelon's failure to establish instructions appropriate to the circumstances to properly stage equipment and route temporary power cables. Specifically, during cell replacement of the Class 1E '2A2' 125/250 volts direct current (Vdc) safeguards battery, a portable battery charger was staged adjacent to operable '2A1' battery cells and not restrained to prevent potential tipping and shorting of exposed battery cell terminals and a non-safety related extension cord was routed in near contact with exposed safety related cables in an open cable tray. Exelon moved the portable battery charger, removed and rerouted extension cords, and entered the issues into the corrective action program as issue report (IR) 3980217; IR 3980203; and IR 3983203.

This finding is more than minor because it adversely affected the configuration control attribute of the mitigating systems cornerstone to ensure the availability and reliability of systems that respond to initiating events to prevent undesirable consequences (i.e. core damage). Specifically, the portable battery charger was adjacent to the '2A1' battery rack and oriented such that it was susceptible to tipping over and causing electrical shorting, and a non-safety related temporary power cable connected to a non-safety related power source was routed in near contact with safety related cables in an open cable tray which introduced a potential to damage and disable safety related equipment. Using IMC 0609, Appendix A, Exhibit 2, the inspectors determined that this finding was of very low safety significance (Green). Specifically, the finding did not represent a loss of system or function and did not represent the loss of a single train for greater than technical specification allowed outage times or greater than 24 hours. The inspectors determined that this finding has a cross-cutting aspect in the area of Human Performance, Training, because Exelon did not provide sufficient training to maintain a knowledgeable workforce and instill nuclear safety values associated with the staging

of material and equipment. [H.9] (Section 1R04)

Inspection Report# : 2017001 (*pdf*)

Significance: G Dec 31, 2016

Identified By: Self-Revealing

Item Type: NCV Non-Cited Violation

Control Structure Chiller Unit Trip Caused by Failure to Implement Procedures

A self-revealing Green NCV of LGS Units 1 and 2 technical specification 6.8.1 was identified when Exelon did not properly implement a surveillance procedure. Specifically, operators secured cooling water to the operating 'A' control structure chilled water system (CSCWS) chiller unit which resulted in the unit automatically tripping to prevent damage. Operators restored cooling water flow in accordance with procedures. Exelon entered the issue into the corrective action program as IR 2720374.

This finding is more than minor because it is associated with the human performance attribute of the mitigating systems cornerstone to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences. Specifically, the loss of cooling water to the 'A' CSCWS chiller unit resulted in a trip of the unit on high condenser pressure and rendered the chiller unavailable. Using IMC 0609, Appendix A, Exhibit 2, the inspectors determined that this finding was of very low safety significance (Green). Specifically, the finding did not represent a loss of system or function and did not represent the loss of a single train for greater than technical specification allowed outage times or greater than 24 hours. The inspectors determined that this finding has a cross-cutting aspect in the area of Human Performance, Avoid Complacency, because operators did not recognize and plan for the possibility of mistakes and inherent risk and did not use appropriate error reduction tools. [H.12] (Section 4OA2)

Inspection Report# : 2016004 (*pdf*)

Barrier Integrity

Significance: G Jul 31, 2017

Identified By: Self-Revealing

Item Type: NCV Non-Cited Violation

Inadequate Design Control of the Drywell Unit Cooler Condensate Flow Rate Monitoring System

A self-revealing Green NCV of 10 Code of Federal Regulations (CFR) Part 50, Appendix B, Criterion III, 'Design Control,' occurred when Exelon failed to verify or check the adequacy of design of a new Unit 2 drywell unit cooler condensate flow rate monitoring system. Specifically, the design did not identify that the low conductivity of the drain fluid affected the ability of the flow elements to accurately detect drain flow. In addition to this, LGS staff did not assure adequate post modification acceptance testing in accordance with CC-AA-107-1001, 'Post Modification Acceptance Testing.' This inadequately designed and tested modification also resulted in a violation of technical specification (TS) 3.4.3.1, 'Leakage Detection Systems,' because the system was inoperable and unavailable to perform its function following the Unit 2 April 2015 refueling outage, and the TS 3.4.3.1 action statement was not met until the system was declared inoperable on December 10, 2015. In response to this issue, Exelon initiated a condition report, IR 2598308, performed an apparent cause investigation, and replaced the Rosemount drywell unit cooler condensate flow rate monitoring system with a modified version of the previously used system.

The inspectors determined that the failure to verify the adequacy of the newly installed Rosemount drywell unit cooler condensate flow rate monitoring was within Exelons ability to foresee and correct and should have been prevented and therefore was a performance deficiency. This issue is more than minor because it adversely affected the design control

attribute of the barrier integrity cornerstone to provide reasonable assurance that physical design barriers protect the public from radionuclide releases caused by accidents or events. Specifically, the Unit 2 drywell unit cooler condensate flow rate monitoring system was inoperable and unavailable to perform its function as part of the reactor coolant leakage detection system following
Inspection Report# : 2017002 (*pdf*)

Emergency Preparedness
Occupational Radiation Safety
Public Radiation Safety
Security

The security cornerstone is an important component of the ROP, which includes various security inspection activities the NRC uses to verify licensee compliance with Commission regulations and thus ensure public health and safety. The Commission determined in the staff requirements memorandum (SRM) for SECY-04-0191, "Withholding Sensitive Unclassified Information Concerning Nuclear Power Reactors from Public Disclosure," dated November 9, 2004, that specific information related to findings and performance indicators associated with the security cornerstone will not be publicly available to ensure that security-related information is not provided to a possible adversary. Security inspection report cover letters will be available on the NRC Web site; however, security-related information on the details of inspection finding(s) will not be displayed.

Miscellaneous

Current data as of : November 29, 2017

Page Last Reviewed/Updated Monday, November 06, 2017