

May 2, 2005

Mr. William Levis  
Senior Vice President and Chief Nuclear Officer  
PSEG Nuclear, LLC - N09  
P. O. Box 236  
Hancocks Bridge, NJ 08038

SUBJECT: SALEM AND HOPE CREEK NUCLEAR GENERATING STATIONS - NRC  
PROBLEM IDENTIFICATION AND RESOLUTION INSPECTION REPORT  
05000272/2005007, 05000311/2005007, AND 05000354/2005006

Dear Mr. Levis:

On March 18, 2005, the NRC completed a team inspection at your Salem Unit 1 & 2 and Hope Creek reactor facilities. The enclosed report documents the inspection findings which were discussed on March 18, 2005, with Mr. Joyce and other members of your staff during an exit meeting.

This inspection was an examination of activities conducted under your license as they relate to the identification and resolution of problems, compliance with the Commission's rules and regulations, and with the conditions of your license. Within these areas, the inspection involved examination of selected procedures and representative records, observation of activities, and interviews with personnel. This inspection was conducted primarily for the purpose of assessing the problem identification and resolution (PI&R) program at Salem, but was expanded to include site-wide PI&R activities, including Hope Creek. This expanded scope was consistent with the implementation of the Reactor Oversight Process Action Matrix Deviation Memorandum for Salem/Hope Creek dated August 23, 2004.

On the basis of the samples selected for review, the team concluded that, in general, problems were adequately identified, evaluated and corrected. However, the team noted several examples of inconsistent implementation of your corrective action program. The team identified weaknesses in each of the three fundamental areas: problem identification, evaluation, and the effectiveness of corrective actions. The team identified six Green findings. Four of these findings were determined to be violations of NRC requirements. However, because of their very low safety significance and because they were entered into your corrective action program, the NRC is treating these findings as non-cited violations, in accordance with Section VI.A.1 of the NRC's Enforcement Policy. If you contest these non-cited violations, you should provide a response with the basis for your denial within 30 days of the date of this inspection report, to the U. S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, Region I; the Director, Office of Enforcement, U. S. Nuclear Regulatory Commission, Washington DC 20555-0001; and the NRC Resident Inspector at the Salem and Hope Creek facilities.

Mr. William Levis

2

In addition, several issues of minor significance were identified by the team and entered into the corrective action program by your staff. These items involved conditions adverse to quality that had not been entered into the corrective action program, had narrowly focused problem evaluations, or corrective actions that were either ineffective or not implemented. None of these minor deficiencies resulted in a challenge to system operability or reliability.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

**/RA/**

Marvin D. Sykes, Chief  
Performance Evaluation Branch  
Division of Reactor Safety

Docket Nos. 50-272, 50-311, 50-354  
License Nos. DPR-70, DPR-75, NPF-57

Enclosure: Inspection Report 50-272/05-007, 50-311/05-007, 50-354/05-006  
w/Attachment: Supplemental Information

cc w/encl:

T. Joyce, Site Vice President - Salem  
G. Barnes, Site Vice President  
M. Gallagher, Vice President, Engineering and Technical Support  
W. F. Sperry, Director Business Support  
C. Perino, Director - Regulatory Assurance  
C. J. Fricker, Salem Plant Manager  
M. Massaro, Hope Creek Plant Manager  
J. J. Keenan, Esquire  
M. Wetterhahn, Esquire  
F. Pompper, Chief of Police and Emergency Management Coordinator  
J. Lipoti, Ph.D., State of New Jersey, Ass't Director Radiation Protection & Release Prevention  
K. Tosch - Chief, Bureau of Nuclear Engineering, NJ Dept. of Environmental Protection  
H. Otto, Ph.D., DNREC Division of Water Resources, State of Delaware  
Consumer Advocate, Office of Consumer Advocate  
N. Cohen, Coordinator - Unplug Salem Campaign  
W. Costanzo, Technical Advisor - Jersey Shore Nuclear Watch  
E. Zobian, Coordinator - Jersey Shore Anti Nuclear Alliance

Mr. William Levis

3

Distribution w/encl:

- S. Collins, RA
- J. Wiggins, DRA
- E. Cobey, DRP
- S. Barber, DRP
- D. Orr, DRP - NRC Resident Inspector
- K. Venuto, DRP - Resident OA
- S. Lee, RI OEDO
- R. Laufer, NRR
- D. Collins, PM, NRR
- R. Ennis, PM, NRR (backup)
- Region I Docket Room (with concurrences)
- ROPreports@nrc.gov
- W. Lanning, DRS
- M. Sykes, DRS

DOCUMENT NAME: E:\Filenet\ML051230026.wpd

**SISP Review Complete: BDW (Reviewer's Initials)**

After declaring this document "An Official Agency Record" it **will** be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP	RI/DRS	RI/DRP	RI/DRS	
NAME	BWelling (BDW)	WSchmidt (WAC for)	ECobey (EWC)	MSykes (MDS)	
DATE	05/02/05	05/02/05	05/02/05	05/02/05	05/ /05

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION

REGION I

Docket Nos: 50-272, 50-311, 50-354

License Nos: DPR-70, DPR-75, NPF-57

Report No: 05000272/2005007, 05000311/2005007, 05000354/2005006

Licensee: PSEG Nuclear LLC

Facility: Salem Nuclear Generating Station, Unit 1 and 2  
Hope Creek Nuclear Generating Station

Location: P.O. Box 236  
Hancocks Bridge, NJ 08038

Dates: February 28 - March 18, 2005

Inspectors: B. Welling, Senior Reactor Inspector (Team Leader)  
J. Schoppy, Senior Reactor Inspector  
D. Florek, Senior Project Engineer  
K. Young, Reactor Inspector  
G. Malone, Resident Inspector, Salem  
J. Benjamin, Reactor Inspector  
J. Lilliendahl, Reactor Inspector

Approved by: Marvin D. Sykes, Chief  
Performance Evaluation Branch  
Division of Reactor Safety

Enclosure

## SUMMARY OF FINDINGS

IR 05000272/2005007, IR 05000311/2005007, IR 05000354/2005006; 2/28/2005 - 3/18/2005; Salem Units 1 and 2 and Hope Creek; biennial baseline inspection of the identification and resolution of problems; problem identification and resolution.

This inspection was conducted by six region-based inspectors and a resident inspector. The inspection identified six Green findings, four of which were non-cited violations. The significance of most findings is indicated by their color (Green, White, Yellow, Red) using Inspection Manual Chapter (IMC) 0609, "Significance Determination Process (SDP)." Findings for which the SDP does not apply may be "Green" or be assigned a severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

### Identification and Resolution of Problems

The team determined that, in general, problems were adequately identified, evaluated and corrected. However, the team noted that PSEG's implementation of their corrective action program was inconsistent. The team identified weaknesses in each of the three fundamental areas: problem identification, evaluation, and the effectiveness of corrective actions. The team identified six findings in which PSEG did not properly evaluate and correct conditions adverse to quality. Several staff interviews were conducted during the inspection. The team identified no new safety conscious work environment issues.

#### A. NRC Identified and Self-Revealing Findings

##### Cornerstone: Mitigating Systems

- Green. (Hope Creek) The team identified a non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," because PSEG did not identify a condition adverse to quality in August 2004, related to open torque switch bypass settings for a core spray injection valve that did not stroke open during in-service testing and, as a result, did not establish appropriate corrective action.

The finding was more than minor because it was associated with the Mitigating Systems cornerstone attribute for equipment performance and it affected the objective of ensuring the availability and reliability of the core spray system. The finding was of very low safety significance (Green) based upon Inspection Manual Chapter 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," Phase 1 analysis, because it was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The performance deficiency had a problem identification and resolution (evaluation) cross cutting aspect. Engineering incorrectly evaluated documented data on the open torque switch bypass setting

for the valve and as a result did not identify that the settings were outside of range established in the site's procedures. (Section 4OA2.b.2.1)

- Green. (Hope Creek) The team identified a finding of very low safety significance because on at least seven occasions neither loop of service water was available to supply emergency makeup to the safety auxiliaries cooling system (SACS). The Hope Creek Updated Final Safety Analysis Report indicates that a safety-related makeup supply from service water is available.

This finding was more than minor because it was associated with the Mitigating Systems cornerstone attribute for equipment performance and it affected the objective to ensure the availability and reliability of the SACS system. The finding was of very low safety significance (Green), based on a Phase 1 significance determination process (SDP) because it was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The issue was similarly of very low risk in the Initiating Events cornerstone because the finding did not increase the likelihood of a loss of SACS event because the trains are not normally cross-connected and an inventory loss on one train would not reasonably be expected to impact the redundant train concurrently. The performance deficiency had a problem identification and resolution (evaluation) cross cutting aspect. Hope Creek did not fully evaluate the impact of this condition on the SACS system. (Section 4OA2.b.2.2)

- Green. (Salem) The team identified a finding of very low safety significance because PSEG did not properly follow its procedural guideline for conducting an apparent cause evaluation (ACE) in response to a component cooling water configuration control problem that caused the 11 residual heat removal heat exchanger to be inoperable.

This finding is more than minor because it is associated with the Mitigating Systems cornerstone's configuration control attribute and affected the cornerstone's objective to ensure the availability and reliability of systems that respond to initiating events. This finding was of very low safety significance (Green) based on a Phase 1 SDP, because it was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The performance deficiency had a human performance cross cutting aspect. The individuals performing the ACE did not follow the site procedural guidelines for the conduct of the ACE. (Section 4OA2.b.2.3)

- Green. (Salem) The team identified a non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," for ineffective and untimely corrective action associated with the 1C1 125VDC battery charger. NRC inspection report 05000272, 05000311/2004004, documented several previous battery charger failures, but timely corrective actions were not implemented to eliminate the identified defective condition for all battery chargers of identical design and like

vintage. Consequently, the failure of another battery charger occurred on November 16, 2004.

This finding was more than minor because it was associated with the equipment performance attribute, and it affected the Mitigating Systems cornerstone objective to ensure the capability and reliability of systems that respond to initiating events. The finding was of very low safety significance based upon a Phase 1 SDP, because the finding was not a design deficiency, it did not result in an actual loss of safety function, and it did not screen as potentially risk significant for externally initiating events (seismic, flooding, or severe weather). The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect. (Section 4OA2.c.2.1)

- Green. (Salem) The team identified non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," for failure to implement timely and effective corrective actions following repetitive failures of the control area chillers due to a deficient temperature control system.

The finding was more than minor because it was associated with the equipment performance attribute of the Mitigating Systems cornerstone. This finding affected the cornerstone objective, in that it reduced the availability and reliability of a system that responds to initiating events. The finding was determined to be of very low safety significance (Green) based upon a SDP Phase 1 analysis, because it was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect. (Section 4OA2.c.2.2)

- Green. (Hope Creek) The team identified a non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," for PSEG's failure to take adequate corrective action to address recurring challenges to standby service water (SW) pumps due to silting and debris in the out of service strainers.

The finding was more than minor because it affected the Mitigating Systems cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events. The finding was associated with the attribute of equipment performance (SW system availability and reliability). This issue also impacted the Initiating Events cornerstone because unavailability of one train of SW increased the likelihood of a loss of service water (LOSW) event. The finding was determined to be of very low safety significance based upon a SDP Phase 2 analysis. The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect. (Section 4OA2.c.2.3)

## B. Licensee-Identified Violations

None.

## Report Details

### **4. OTHER ACTIVITIES (OA)**

#### 4OA2 Problem Identification and Resolution

##### a. Effectiveness of Problem Identification

##### (1) Inspection Scope

The team reviewed PSEG's corrective action program procedures, attended the daily initial screening and management review meetings, and attended a corrective action review board (CARB) meeting to understand the threshold for identifying problems and to assess management involvement with the corrective action process. The team noted that problems were identified through the initiation of notifications (NOTFs).

Several NOTFs were reviewed to determine whether PSEG was appropriately identifying, characterizing, and entering problems into the corrective action process. The team selected NOTFs to cover the seven cornerstones of safety in the NRC Reactor Oversight Process (ROP). The team reviewed NOTFs initiated subsequent to the last NRC problem identification inspection that was completed in March 2003. In addition, the team considered risk insights from the station probabilistic risk assessments to focus the NOTF sample selection and system walkdowns on risk significant components. Attachment 1 lists the NOTFs selected for review.

The team reviewed items from PSEG's maintenance, operations, engineering, and oversight processes to verify that PSEG appropriately considered problems for entry into the corrective action program. Specifically, the team reviewed a sample of control room deficiency and operator work-around lists, maintenance orders, operability determinations, engineering system health reports, quality assessment reports, and departmental self-assessments. The team reviewed these documents to ensure that underlying problems associated with each issue were appropriately evaluated and resolved. The team also conducted walkdowns of control room panels and selected plant equipment to independently assess whether problems were being adequately identified and addressed.

On August 23, 2004, the NRC's Executive Director for Operations approved a deviation from the NRC's Action Matrix to provide a greater level of oversight for the Salem and Hope Creek stations than would typically be called for in the Action Matrix. One provision of the deviation memorandum provided for the enhancement of existing reactor oversight process (ROP) baseline inspections. In accordance with this deviation, the Salem inspection team was augmented with additional inspectors and the scope of the review was expanded to include site-wide PI&R issues and additional NOTFs.

##### (2) Findings and Observations

No findings of significance were identified.

Enclosure

The team determined that, in general, PSEG adequately identified discrepant conditions and initiated NOTFs where appropriate. However, the team identified several examples where PSEG did not enter conditions adverse to quality into the corrective action system and did not identify and correct other minor deficiencies in a timely manner. During the plant walkdowns, the team observed several minor deficiencies that had not been previously identified and entered into the corrective action program. PSEG initiated numerous NOTFs and corrected some minor deficiencies on the spot. In some cases, these items reflected an acceptance of minor equipment deficiencies or poor implementation of program guidance (scaffold and transient combustible material control). Some examples included:

- C An improper pressure regulator reading on the Salem 13AF21 flow control valve (20228787).
- C Six inches of standing water in the fresh water and fire protection water supply to auxiliary feedwater (AFW) trench on 88' elevation of the Salem Unit 2 turbine building (20228636).
- C A leak at the wall penetration where A SW loop exits the Hope Creek reactor building (20226813).

The team also found that the use of equipment malfunction information system (EMIS) tags was inconsistent. During plant walkdowns, the team identified several EMIS tags hanging that should have been removed following corrective maintenance. EMIS tags left hanging after work completion potentially mask the degraded condition should it recur. Alternately, the team noted several examples where previously identified deficiencies did not have EMIS tags applied. These EMIS tag deficiencies represent a recurring corrective action program (CAP) weakness based upon previous NRC PI&R inspection observations at Salem and Hope Creek.

The team identified that PSEG had several hundred NOTFs that were not reviewed by a supervisor. Although these items had been screened in a timely manner, the delays in supervisory review may give the impression to plant staff that the issue is insignificant. PSEG wrote NOTF 20227808 to address this item.

The team independently evaluated the problem identification deficiencies noted above for potential significance. The team determined that none of the individual issues were of more than minor significance based upon the guidance in Inspection Manual Chapter (IMC) 0612, Appendix E, "Examples of Minor Issues." However, these NRC identified issues indicated weaknesses in PSEG problem identification.

Quality Assessment (QA) audits, and self-assessments identified adverse conditions and negative trends. They were generally self-critical and consistent with the team's findings.

b. Prioritization and Evaluation of Issues

(1) Inspection Scope

The team reviewed the NOTFs listed in Attachment 1 to determine whether PSEG adequately prioritized, evaluated, and resolved problems. The review focused on the appropriateness of the assigned significance, the timeliness of resolutions, and the scope and depth of the root or apparent cause analyses. A portion of the items chosen for review were age-dependent, and accordingly, the scope of review was expanded to five years. In this area, the team reviewed problems in the service water system and auxiliary feedwater system. The team also considered risk insights from PSEG's probabilistic risk assessment to help focus the sample to the 1) component cooling water, 2) 4 KV AC power, and 3) safety injection systems.

The team also selected NOTFs associated with previous NRC non-cited violations (NCVs) and findings to determine whether PSEG had evaluated and resolved problems related to applicable regulatory requirements and standards. The team reviewed PSEG's evaluation of industry operating experience (OE) information for applicability to their facility. The team also reviewed PSEG's assessment of equipment operability, reportability requirements, and the potential extent of the problem.

(2) Findings and Observations

In general, PSEG adequately prioritized and evaluated the issues and concerns entered into the CAP. However, the team identified three Green findings related to incomplete or ineffective evaluations of problems.

Plant personnel were generally effective at classifying and performing operability evaluations and making reportability determinations for discrepant conditions. Yet, the team identified two instances in which PSEG did not adequately perform operability reviews or did not do so in a timely manner. These involved air found in residual heat removal (RHR) piping at Hope Creek (20228105), and the operability of the Hope Creek control room emergency filtration boundary during fire damper testing (20227644). The team also noted several weaknesses in PSEG's prioritization and evaluation of degraded conditions.

The team observed that the initial screening committee team did not always evaluate such factors as potential risk and uncertainty. This was particularly evident when assigning priority for an issue involving the potential for nitrogen voiding in Salem ECCS piping (20227725). In addition, the management screening committee did not assign follow up action commensurate with the potential safety significance during their initial review of this issue.

The team identified that Salem engineering and operations did not fully evaluate a condition adverse to quality involving ongoing nitrogen leakage from the No. 11 safety injection (SI) accumulator. In particular, PSEG did not assess where the nitrogen was going and did not fully evaluate the potential for nitrogen voiding of Salem ECCS piping or ECCS pump cavitation. The team noted that a senior reactor operator's operability evaluation on August 21, 2004, stated "11 SI accumulator pressure is still within tech

spec. No operability concern.” On March 9, 2005, PSEG initiated NOTF 20227725 to evaluate this issue. On March 18, PSEG management determined that an apparent cause evaluation (70045518) was needed to determine potential leakage paths, areas of potential nitrogen migration, methods of detection, if voids exist, and the leakage rate. The team concluded that this issue will be treated as an unresolved item (URI). An unresolved item is an issue requiring further information to determine if it is acceptable, if it is a finding, or if it constitutes a deviation or violation of NRC requirements. In this case, additional NRC inspection will be required to review PSEG’s evaluation of the issue. **(URI 05000272/2005007-01)**

During reviews of apparent cause evaluations, the team identified several narrowly focused evaluations that appeared to address the symptoms of equipment problems rather than the underlying causes. This was evident in evaluations for Salem control area chiller trips (20230185), and multiple failures of an auxiliary feedwater pump steam admission valve, 1MS132 (20207415). The narrowly focused evaluations sometimes led to repetitive problems. In certain instances, the licensee did not perform extent of condition evaluations, as in the case of a Hope Creek core spray injection valve issue (20227627). In other cases, the evaluations were incomplete. For example, engineering erroneously excluded five relief valves from an ‘A’ SACS loop inventory loss evaluation (20226834), and engineering did not evaluate missing packing in a leaking auxiliary feedwater pump motor bearing thermocouple (20190639).

For NRC non-cited violations (NCVs), the team noted instances in which PSEG did not evaluate or address the performance deficiencies associated with these NCVs. For example:

- Evaluation 70037473 for NCV 50-272/04-02-02 did not address why the inservice testing program did not evaluate the degrading condition of the 12 SW 65 valve; and
- Evaluation 70038387 for NCV 50-272/04-03-10 did not address the inadequate maintenance procedures that led to an inadvertent safety injection signal actuation.

The team noted that root cause evaluations were generally complete. The root cause methodology was typically identified in the evaluations.

The team independently evaluated the CAP deficiencies noted above for potential significance. The team determined that none of the individual issues were findings of more than minor significance based upon the guidance in IMC 0612, Appendix E, “Examples of Minor Issues.” However, these issues represented examples where the corrective actions for identified conditions were not adequately prioritized and evaluated.

#### .1 Core Spray Motor-Operated Valve Deficiency

Introduction. The team identified a Green non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, “Corrective Action,” because PSEG did not identify a condition adverse to quality in August 2004, related to open torque switch bypass settings for a core spray

injection valve that did not stroke open during in-service testing and, as a result, did not establish appropriate corrective action.

Description. On August 21, 2004, Hope Creek operators initiated NOTF 20201072 to document that the train A core spray outboard injection valve (MOV BE-HV-F004A) did not stroke open during an in-service test. Operators determined that the valve remained operable because the valve is normally open and remains open during an accident, the valve has no safety function to close, and the valve stroked open successfully in two subsequent attempts. Engineering's assessment of the valve response was a loose wire or dirty contact and initiated WO 60047832 to inspect the limit switch compartment in November 2005. On February 1, 2005, operators initiated NOTF 20222530 to document that the A core spray outboard injection valve again failed to stroke open during a in-service test. Operators declared the valve inoperable and maintenance worked the valve using WO 60047832.

The team determined that, in response NOTF 20201072, engineering incorrectly evaluated the open torque switch bypass (OTSB) setting for the valve and as a result did not identify an incorrect setting and thereby did not establish the appropriate corrective action to ensure that the valve would stroke open when demanded. The valve has both an automatic and manual OTSB bypass circuit that bypasses the OTSB if needed during an accident. The team concluded that since 1993 the OTSB setting for this valve had been set at 6% and this setting was outside of the range (15% - 50%) permitted by PSEG procedures. In response to NOTF 20201072 Engineering reviewed the diagnostic VOTES test performed in 2002 for the valve and did not recognize that the documented OTSB setting (12% of the open stroke) was outside of the range specified by PSEG procedures. As a result, engineering's assessment that the valve response was due to a loose wire or dirty contact was incorrect and the corrective action to inspect the limit switch compartment in November 2005 was insufficient to correct the OTSB setting. In response to NOTF 20222530, engineering recognized that not only was the documented OTSB setting in the VOTES test performed in 2002 out of specification it was also documented in error and was actually set at 6% of open stroke. The VOTES testing in 1993 (WO 921023100) showed the OTSB setting at 6% of open stroke. As a result, PSEG took corrective action and adjusted the setting to 24% of the open stroke. The team noted that this repeat failure resulted in approximately 24 hours of additional unplanned unavailability of the A core spray subsystem.

Analysis. The performance deficiency is that PSEG did not identify an out of specification OTSB setting in August 2004 and, as a result, did not develop appropriate corrective action as required by PSEG corrective action program. The finding was more than minor because it was associated with the Mitigating Systems cornerstone attribute for equipment performance and it affected the objective to ensure the availability and reliability of the core spray system. The finding was of very low safety significance (Green) based upon Inspection Manual Chapter 0609, Appendix A, "Significance Determination of Reactor Inspection Findings for At-Power Situations," Phase 1 analysis, because it was not a design deficiency, did not result in an actual loss of safety function of a single train of core spray for greater than its TS allowed outage time, and

did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather).

A contributing cause of this finding relates to the evaluation subcategory of the cross cutting area of problem identification and resolution. Engineering incorrectly evaluated documented data on the open torque switch bypass (OTSB) setting for the valve and as a result did not identify that the settings were outside of range established in the site's procedures.

Enforcement. 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," requires, in part, that measures shall be established to assure that conditions adverse to quality, such as failures, malfunctions, deficiencies, deviations, defective material and equipment, and non-conformances are promptly identified and corrected. Contrary to the above, in August 2004, PSEG did not identify that the open torque switch bypass (OTSB) setting for a core spray injection valve was out of the required range in plant procedures and, as a result, PSEG did not establish corrective actions to restore the OTSB settings to within the required range. However, because the finding was of very low safety significance and has been entered into the CAP (NOTF 20227627 and order 70045369), this violation is being treated as a NCV, consistent with section VI.A of the NRC Enforcement Policy. **(NCV 05000354/2005006-02)**

## .2 Service Water Emergency Makeup Unavailability

Introduction. The team identified a Green finding because on at least seven occasions neither loop of service water was available to supply emergency makeup to the safety auxiliaries cooling system. The Hope Creek Updated Final Safety Analysis Report indicates that a safety-related makeup supply from service water is available for emergency use.

Description. The Hope Creek Updated Final Safety Analysis Report (UFSAR) Section 9.2.2.2 indicates that a safety-related makeup supply from service water (SW) is available, so that makeup water to the safety auxiliaries cooling system (SACS) can be provided during emergency conditions.

In June 2001, PSEG assumed mitigation capability credit for this design feature in evaluating the safety significance of excessive leakage from the A SACS loop (NRC Inspection Report 50-354/01-07, Section 4OA3.1). Credit was given for operators' ability to recover the A SACS loop. In addition, in January 2004, engineering credited this safety feature in evaluating the continued operability of the A SACS loop (70035939).

The team identified at least seven instances since April 2000 when both loops of SW emergency makeup to SACS were unavailable for significant periods of time (the longest from 1/13/04 through 4/7/04). PSEG could not produce an engineering evaluation to support the unavailability times, and there was no clear process in place to ensure that SW makeup capability is available. Operations initiated NOTF 20227046 to evaluate this condition.

Analysis. The unavailability of both service water makeup supplies to the SACS is a performance deficiency since the unavailability of both supplies is not consistent with the UFSAR and was reasonably within PSEG's ability to appropriately identify and correct. This issue was more than minor because it was associated with Mitigating Systems cornerstone attribute for equipment performance and it affected the objective to ensure the availability and reliability of the SACS system. The issue was of very low safety significance (Green) using the Phase 1 SDP worksheet for at power situations for the Mitigating Systems cornerstone because the finding was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The issue did not increase the likelihood of a loss of SACS event because the trains are not normally cross-connected and an inventory loss on one train would not reasonably be expected to impact the redundant train concurrently. The performance deficiency had a problem identification and resolution (evaluation) cross cutting aspect. Hope Creek did not fully evaluate the impact of this condition on the SACS system.

Enforcement. None (**FIN 05000354/2005006-03**)

### .3 Component Cooling Water System Configuration Control

Introduction. The team identified a Green finding because PSEG did not properly follow their procedural guideline for conducting an apparent cause evaluation in response to a component cooling water configuration control problem that caused the unplanned inoperability of the 11 residual heat removal heat exchanger.

Description. On November 23, 2004, during testing, component cooling water (CCW) flow through the 11 residual heat removal (RHR) heat exchanger was determined to be 3050 gpm. This flow rate was below both the required testing range of 4620 to 4780 gpm and the 4000 gpm minimum UFSAR limit required for accident cooling. Operators adjusted the 11 RHR CCW manual outlet valve (11CC15) to bring the flow up to 4700 gpm per site procedures to restore the operability of the heat exchanger. PSEG entered this configuration control problem into its corrective action program (NOTF 20212591) and specified that an apparent cause evaluation be performed to determine the cause of the configuration control problem and recommend corrective actions.

PSEG's apparent cause evaluation (ACE) (70043024) concluded that the cause was indeterminate. One possible cause identified by PSEG was internal looseness within the valve or valve operator. But this was viewed by PSEG to be rare and unlikely with this relatively new valve that had seen little wear. A corrective action from the ACE was to check for internal looseness within the 11CC15 valve or valve operator. On December 8, 2004, PSEG observed no signs of looseness during surveillance testing.

On March 15, 2004, the team identified that PSEG did not perform an adequate ACE of this problem. PSEG did not follow the site procedural guideline for conducting an ACE, as per (NC.CA-TM.ZZ-0005, Rev. 16). Specific examples in the ACE guideline that were not performed or fully implemented included:

Enclosure

- The evaluators did not verify that equipment was quarantined, as necessary, as specified in step 4.2.1 of the procedure.
- The evaluators did not collect available data (facts) to determine what happened (including the extent of condition), how it happened, and why it happened, per step 4.2.2 of the procedure.
- The evaluators did not conduct interviews or discuss the problem with operators and personnel who could have changed the position of the 11CC15 valve, per the guideline.
- The evaluators did not determine the inappropriate actions, equipment failure modes and apparent cause(s) using the facts obtained and a Cause and Effect Analysis or other suitable method, per the guideline.

In addition, PSEG had not considered recurring instances of Unit 1 low CCW flow conditions identified during surveillance testing since December 15, 2003 (NOTFs 20135502, 20202226, and 20210439) as part of the ACE evaluation. As a result, the inspectors concluded that had PSEG performed the steps above, PSEG could have obtained information to determine if the improper configuration was due to human or equipment error.

Analysis. The inspectors determined that PSEG's failure to conduct its ACE of the CCW configuration control problem in accordance with its procedure was a performance deficiency. The evaluators did not use substantial attributes of the site guideline or information from prior similar situations for performing an apparent cause evaluation. This finding was reasonably within PSEG's ability to foresee and prevent. The finding was more than minor because it was associated with the Mitigating Systems cornerstone configuration control attribute and affected the cornerstone objective to ensure the availability, reliability and capability of systems that respond to initiating events. The finding was of very low safety significance (Green) based upon Phase 1 SDP per IMC 0609, Appendix A, "Determination of Significance of Reactor Inspector Findings for At-Power Situations." This finding was of very low safety significance (Green), because it was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather).

A contributing cause of this finding is related to the organizational subcategory of the human performance cross cutting area. The individuals performing the ACE did not follow the site procedural guidelines for the conduct of the ACE.

Enforcement. None. **(FIN 50000272/2005007-04)**

c. Effectiveness of Corrective Actions

(1) Inspection Scope

The team reviewed PSEG's corrective actions to determine whether the actions taken appropriately addressed the identified causes of the problems. The team also reviewed PSEG's timeliness in implementing corrective actions and their effectiveness in preventing recurrence of significant conditions adverse to quality. Furthermore, the team assessed the backlog of corrective actions to determine if any, individually or collectively, represented an increased risk due to the delay in implementation.

(2) Findings and Observations

There were three Green findings identified during this inspection that involved ineffective or untimely corrective actions. In addition, the team noted some weaknesses in PSEG's implementation of CAP program guidance with respect to resolution of degraded conditions, documentation of actions, and completion of identified corrective actions. Examples included:

- C PSEG closed out corrective actions associated with two AFW vent valves without completing the identified actions (20227347).
- C PSEG had not effectively resolved several longstanding equipment deficiencies that potentially caused unnecessary operator burdens such as spent fuel pool (SFP) cooling pump trips, SACS automatic isolation valve (HV2522A-F) repeat work due to a design deficiency, and Hope Creek SW system ultrasonic flow instrumentation issues.
- C PSEG closed out a corrective action for a root cause evaluation (Foreign Material Exclusion, NOTF 20163339, activity 0460) without completing the identified action.
- C Condition Report 70032452 identified that the 15 containment fan cooler unit bearing was overpacked with grease resulting in higher than normal bearing temperatures, a repetitive problem, yet the evaluation contained no corrective actions.

The team reviewed several instances in which PSEG (both Quality Assessment and the line organization) initiated NOTFs which identified ineffective or untimely corrective actions; however, PSEG did not follow through to ensure that the additional corrective actions to address the original issue were actually completed. Examples included the unauthorized temporary modification on AFW pumps (20135512, 20156974, 20228908), a Salem operator burden involving a high pressure condition on the SW system (70037183, 20186028, 70037127), an industrial safety concern at the Hope Creek SW intake (20136274, 20189242, 20227360), and incomplete closure of corrective actions from a March 2003 root cause evaluation (20136006) related to a Hope Creek power transient. In this last case, several deficiencies raised by QA were not addressed.

The team independently evaluated the CAP deficiencies noted above for potential significance. The team determined that none of the individual issues were findings of more than minor significance based upon the guidance in IMC 0612, Appendix E,

“Examples of Minor Issues.” However, these issues represented examples where the corrective actions for identified conditions were not effective.

.1 Untimely Problem Resolution for Repeat Failures of 125VDC Battery Chargers

Introduction. A Green non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, “Corrective Action,” was identified when PSEG found a blown fuse and an associated charred transducer card during periodic inspection of the 1C1 125VDC battery charger. This was a repeat occurrence of several battery charger failures as documented in NRC Inspection Report (IR) 05000272, 05000311/2004004, issued November 9, 2004.

Description. On November 16, 2004, PSEG technicians identified a blown fuse and a charred transducer card during periodic inspection of the 1C1 125VDC battery charger. The periodic inspection was established as a result of previous similar failures of these battery chargers.

As stated in NRC IR 05000272, 05000311/2004-004, the voltage transducers had been installed in the early 1990's. The transducer card failure typically caused a one amp fuse, AXF2-1, to blow, thus causing the battery charger to operate at reduced capacity, because the fuse also supplies a portion of the battery charger firing circuits. The reduced capacity caused the battery charger not to meet its Technical Specification (TS) requirement.

The battery chargers are safety related. Salem Units 1 and 2 each have a primary and a back-up battery charger associated with all three vital DC buses per unit. There are a total of twelve battery charger units at Salem.

On October 13, 2004, PSEG initiated NOTF 20207005 which identified a lack of timeliness in correcting multiple failures of 125VDC battery charger transducers. The NOTF indicated that on June 14, 2004, PSEG engineers received Plant Health Prioritization Committee approval to initiate a design change package (DCP) for removal of the unused transducers on all battery chargers because of the number of previous failures. However, it was not until another failure on July 30, 2004, that the minor modification package was written but not issued. The NRC reviewed this issue and determined that PSEG had not implemented timely corrective actions to eliminate the identified defective condition for all battery chargers of identical design and like vintage.

On November 16, 2004, PSEG technicians identified another blown fuse and a charred transducer card during periodic inspection of the 1C1 battery charger. PSEG still had not implemented the DCP to abandon the transducer cards in place. The team verified that work orders to remove and spare wires with all battery charger transducer cards were ultimately completed by the end of December 2004. The team determined that this was another example of failure to implement timely corrective actions for this issue.

Analysis. The performance deficiency associated with the 1C1 battery charger failure has problem identification and resolution cross cutting aspects. Specifically, PSEG did not implement a long term resolution for a number of transducer card failures in a timely

Enclosure

manner. Traditional enforcement does not apply because the issue did not have any actual safety consequences or potential for impacting the NRC's regulatory function, and it was not the result of any willful violation of NRC requirements. This issue was more than minor because it was associated with the equipment performance attribute, and it affected the Mitigating Systems cornerstone objective to ensure the reliability of systems to respond to initiating events. The team considered this issue a potential loss of a DC bus initiating event for the Initiating Events cornerstone and determined that the failure mechanism, potential reduced charging capacity, did not increase the likelihood of a loss of a DC bus. This finding was of very low safety significance (Green) using the Phase 1 SDP worksheet for at power situations because the finding was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect.

Enforcement. 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," requires that in the case of significant conditions adverse to quality, measures shall assure that the cause of the condition is determined and corrective actions taken to preclude repetition. Contrary to the above, on November 16, 2004, PSEG did not preclude repetition of a failed safety-related battery charger due to a defective transducer card, a significant condition adverse to quality, when the 1C1 battery charger was found with a blown fuse and charred transducer card. PSEG NOTFs documented several battery charger failures for identical reasons. However, because the finding is of very low safety significance and had been entered into the corrective action program (20211713), this violation is being treated as an NCV, consistent with section VI.A of the NRC Enforcement Policy. **(NCV 05000272, 05000311/2005007-05)**

## .2 Deficient Control Area Chiller Controls

Introduction. A Green non-cited violation of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," was identified for the failure to correct a condition adverse to quality involving repetitive control area chiller failures.

Description. PSEG identified that an obsolete and inaccurate temperature control system has led to control area chiller trips, extended equipment outages, and equipment damage. The calibration drift associated with these controls has led to spurious freeze protection trips and fatigue failure of internal compressor components including cotter pins and unloader forks. The deficient control circuit caused unloader devices to cycle more frequently than expected resulting in component failures.

On January 21, 2003, an instrument and controls (I&C) technician found a temperature control switch out of calibration for the 23 chiller unit. An evaluation was performed under order 70029166 which identified a history of calibration drifts and resultant chiller unit trips. The chiller units tripped on a freeze protection logic that is affected by the temperature drift. The evaluation identified that the temperature control circuit which affects unit startup, loading and protective trips, is obsolete and does not have an accuracy acceptable for its intended use. The evaluation identified sixteen prior

examples of NOTFs written to identify calibration drifts and unit trips since October 11, 2000. The evaluation recommended redesigning the controller to reduce inaccuracy and address obsolescence.

On December 9, 2003, the 23 chiller unit tripped on a freeze protection feature, and condition report 70035495 was generated to evaluate the condition. The evaluation determined that the chiller trip was likely due to temperature drift of the control circuit. A walkdown performed by PSEG on December 30, 2003, found all three control room chillers for Unit 2 running very lightly loaded which should occur only during heavy loading in the summer months. This was another indication that the control circuits were not operating correctly. The evaluation referenced prior chiller failures and industry operating experience from which corrective actions have not been implemented. The evaluation documented a corrective action to prevent recurrence (CAPR) to develop a modification to replace the problematic temperature control circuit with a more reliable temperature switch. The projected date of installation of the minor modification is September, 2006.

On December 29, 2004, the 21 chiller failed to pumpdown while shutting the unit down for maintenance. The evaluation (70044081) identified that a suction valve had broken into small pieces which subsequently became lodged in the discharge valve seating surface, creating a refrigerant leak path from the discharge to the suction side of the compressor. The evaluation concluded that the temperature control system was leading to the equipment damage and is scheduled to be corrected by minor modification 88074528 that is also found in condition report 70035495 above.

Analysis. The performance deficiency involved a failure to correct an identified deficiency with control area chiller temperature control systems that resulted in the failure of 21 control area chiller. The 21 chiller was inoperable for 222 hours. Traditional enforcement does not apply because the issue does not have any actual safety consequences or potential for impacting the NRC's regulatory function and is not the result of any willful violation of NRC requirements. This finding was more than minor because it was associated with the equipment performance attribute of the Mitigating Systems cornerstone and affected the objective to maintain the availability of mitigating systems. The finding was of very low safety significance (Green) based on a Phase 1 screening in Appendix A of Inspection Manual Chapter 0609, "Significance Determination of Reactor Inspection Findings for At-Power Situations," because the finding was not a design deficiency, did not result in an actual loss of safety function, and did not screen as potentially risk significant due to external initiating events (seismic, flooding, or severe weather). The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect.

Enforcement. 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," requires that measures shall be established to assure that conditions adverse to quality, such as failures, malfunctions, deficiencies, deviations, defective material and equipment, and nonconformances be promptly identified and corrected. Contrary to the above, on December 29, 2004, PSEG's failure to correct a deficient chiller temperature control system that was identified in January 2003, led to a failure of the 21 control area chiller.

Enclosure

Because this finding is of very low safety significance and has been entered into the corrective action program in NOTF 20230185, this violation is being treated as a NCV, consistent with section VI.A of the NRC Enforcement Policy. **(NCV 05000311/2005007-06)**

### .3 Silting Challenges to Standby Service Water Pumps

Introduction. The team identified a Green, non-cited violation of 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," because of inadequate corrective action for recurring challenges to standby SW pumps due to silting and debris in the out of service strainers.

Description. In February 2002, NRC inspectors identified a non-cited violation for ineffective corrective actions for malfunctions regarding standby SW pump performance due to intake silt accumulation (see NRC Inspection Report 50-354/02-02, Section 1R07.1). The inspectors had determined that PSEG had not implemented effective measures to ensure that the standby SW pump and traveling screens would perform properly under emergent SW pump start conditions. Based on historical data and engineering judgment, engineering recommended that operators rotate all idle SW traveling screens at least once every seven days to minimize the accumulation of silt in idle SW bays(70023083).

The team reviewed a sample of operator logs and NOTFs for the period March 2004 through March 2005 to assess the effectiveness of PSEG's corrective actions associated with challenges to standby SW pumps. The team noted the recommended actions had been discontinued and several additional instances had occurred which rendered the associated SW pump inoperable.

- C On April 13, 2004, operators placed D SW pump in service and observed high SW strainer DP (off scale high) and a reduced SW flow. Operators declared the pump inoperable, and initiated NOTF 20185599. The pump had been out of service for ten days. The team noted that operators did not enter their SW abnormal procedure, HC.OP-AB.COOL-0001, and attempt to clear the strainer high DP condition per their operator training. Operators left the D SW pump in manual control until April 15 when they restarted the pump under an operations/engineering troubleshooting plan with the pump discharge valve in the lockout position. After approximately one minute, they opened the discharge valve and noted that the high strainer DP condition cleared. The pump was unavailable for approximately 53 hours. The team noted no documentation of any actions taken to determine the cause of the high strainer DP.
- C On April 15, 2004, a control room operator initiated NOTF 20186090 to suggest implementing a SW pump swap weekly ("a routine implemented years earlier in response to SW pump problems") in order to mitigate the effects of silt settling out within the standby pump piping and strainer.

- C On April 26, 2004, mechanics found an excessive amount of mud on the C SW strainer drum when they opened the strainer for a routine inspection (30085305). Maintenance initiated NOTF 20187632, which stated: "The as-found condition gives the appearance that a reverse flow path could be occurring in the strainer with the pump out of service." There was no documentation of any actions taken to determine the cause of the excessive mud in the strainer or to evaluate a potential reverse flow path into the strainer.
- C Based on the two occurrences with elevated silt level in out of service strainers, engineering implemented a weekly pump swap using HC.OP-DL.ZZ-0016 on May 18, 2004. Engineering determined that no further actions were required and closed NOTF 20186090 to trend.
- C On June 5, 2004, operators initiated NOTF 20192262 to document a sustained high DP and low SW flow condition on the C SW strainer during a return to service post maintenance test. The C SW pump had been out of service for eight days. The team noted that operators did not enter their SW abnormal procedure. The pump was unavailable for approximately 15.5 additional hours. Operators also initiated NOTF 20192208 to document a concern that SW intake structure silting may soon affect system operability. In response to this concern, engineering performed an operability determination (70039631) and determined that all four SW trains were operable but degraded as a result of the high silt levels in front of the SW intake structure. Engineering mandated a 5-day pump swap to mitigate silt accumulation in the standby SW pump bays until the SW intake was desilted. Maintenance completed desilting operations by August 4, 2004, and engineering closed out the associated condition resolution operability determination (CROD).
- C On October 29, PSEG initiated NOTF 20208989, "High Silt Levels in Service Water Intake," based on questions from the NRC Senior Resident Inspector. On November 21, PSEG initiated NOTF 20212421, "Excessive Mud Found in C SSW Pump Bay."
- C On December 11, a control room operator initiated NOTF 20215238, "Possible Back Flow in C SW Strainer," based on indications of strainer DP with the strainer and pump in standby. Engineering attributed the questioned DP to a clogged instrument tap.
- C On January 26, 2005, operations initiated NOTF 20221348, "Service Water Grassing Event," when the B SW strainer experienced a high DP condition (from 80 psid to over 200 psid) following a routine pump swap. Operators entered their abnormal procedure, and cleared the condition. On February 1, the initial screening committee closed this NOTF to trend. The team noted: (1) the B SW pump had been in standby for seven days; (2) operators did not appear to follow the guidance in HC.OP-AB.COOL-0001 for sustained high strainer DP; (3) HC.OP-AB.COOL-0001 does not define "sustained" which allows for individual operator interpretation; and (4) except during this pump start, there were no

reported grass attacks during the period January 25 - 27. This represented an additional 25 minutes of SW pump unavailability.

- C On February 22, operations initiated NOTF 20225325 for a February 20 event involving a B SW strainer high DP condition following a routine pump swap. The operators entered their abnormal procedure and the equipment operator reported a small amount of grass on the A and B SW screens. Engineering documented that the condition is common during elevated grassing conditions. The team noted: (1) the B SW pump had been in standby for approximately ten days; (2) operators did not initiate a NOTF for the condition until prompted by the NRC Resident Inspector; and (3) based on a log review, except during this pump start, there were no reported grass attacks during the period February 19 - 22.
- C On February 23, operations initiated NOTF 20225588 for a series of alarms that came in after they placed the C SW pump in service following a routine pump swap. The pump had been in standby for approximately 14 days.
- C On March 1, based on a limited review of the NOTFs associated with silting and SW pump start issues, the team questioned whether there was a common cause associated with the issues and if previous corrective actions for the February 2002 NCV were effective. On March 8, engineering informed the team that they had completed their review of this concern and determined that three of the issues documented above were attributed to ineffective corrective actions for the standby pump silting concern, but that all issues since their CROD in July 2004 have been due to grassing only.
- C On March 9, operations initiated NOTF 20227726 for a B SW strainer high DP condition following a routine pump swap. Engineering documented that the B strainer high DP condition was attributable to grassing conditions and that the issue should be closed to trend with no actions required. The team noted: (1) the B SW pump had been in standby for approximately eight days; and (2) based on a log review, except during this pump start, there were no reported grass attacks shortly before or after the B SW pump start.

In summary, the team determined that (1) operators and engineers did not demonstrate a questioning attitude (except as noted above) and were quick to accept an easy answer (must be grassing), (2) operators did not consistently follow their abnormal procedure, (3) engineering has not investigated a potential backleakage concern compounding the impact to the C SW strainer when in standby, and (4) PSEG corrective action for the silting impact on standby SW strainers has been inadequate and ineffective in addressing this recurring challenge to SW system reliability and availability.

Analysis. The team considered PSEG's failure to take timely and adequate corrective actions for the recurring challenges to standby SW pumps a performance deficiency. Given the repeated nature of the adverse condition and previous NRC NCV on this issue, the deficiency was reasonably within PSEG's ability to appropriately evaluate and correct prior to February 2005. Traditional enforcement does not apply because the

issue did not have any actual safety consequences or potential for impacting the NRC's regulatory function and was not the result of any willful violation of NRC requirements. This issue was more than minor because it was associated with Mitigating Systems cornerstone attribute for equipment performance and it affected the objective to ensure the availability and reliability of the SW system. This issue also impacted the Initiating Events cornerstone because unavailability of one train of SW increased the likelihood of a loss of service water event. The inspectors completed a SDP Phase 1 screening of the finding and determined that a more detailed Phase 2 evaluation was required to assess the safety significance because the finding affected two cornerstones (Initiating Events and Mitigating Systems).

The Region I SRA conducted a Phase 2 evaluation, using the LOSW worksheet from Revision I of the Hope Creek Risk Informed Inspection Notebook, concluding that the finding was of very low safety significance (Green) relative to internal events core damage frequency increase (Î CDF). The internal event Î CDF was estimated to be 1 in 60,000,000 years of reactor operation. The dominant core damage sequence was a non-recovered LOSW with a failure to vent the containment. The SDP Phase 2 evaluation used the following assumptions:

- An exposure time of less than 3 days was used in the analysis. The D SW pump was unavailable for approximately 53 hours (4/13-15/2004). The C SW pump was unavailable for approximately 15.5 additional hours due to this condition on June 5, 2004. The B SW pump was unavailable for approximately 0.4 additional hours due to this condition on January 26, 2005.

No fault exposure was assumed for the many times that SW pumps were kept in standby longer than seven days. Based on operators' past success in clearing the strainer high DP condition when they implemented their abnormal operating procedure actions,

- Operator recovery credit of 90% (10% chance of failure), based on the actual ability to recover the D, C, and B SW strainers.
- The SW system was considered to be a multi-train normally cross-tied support system. Therefore, the initiating event likelihood was increased by one order of magnitude for the associated special initiator.

The performance deficiency had a problem identification and resolution (corrective actions) cross cutting aspect.

Enforcement. 10 CFR 50, Appendix B, Criterion XVI, "Corrective Action," requires that measures be established to assure that conditions adverse to quality, such as failures, malfunctions, deficiencies, deviations, defective material and equipment, and nonconformances are promptly identified and corrected. Contrary to the above, from February 2002, PSEG failed to take corrective action to determine the nature of the recurring challenges to standby SW pump strainers, and correct this condition in a timely manner to prevent subsequent strainer challenges and SW pump unavailability.

Enclosure

However, because the finding was of very low safety significance and has been entered into the CAP (NOTF 20228274), this violation is being treated as a NCV, consistent with section VI.A of the NRC Enforcement Policy. **(NCV 05000354/2005006-07)**

d. Assessment of Safety Conscious Work Environment

(1) Inspection Scope

Team members interviewed plant staff, observed various activities throughout the plant, and attended a cross section of meetings to determine if conditions existed that would result in personnel being hesitant to raise safety concerns to their management and/or the NRC.

(2) Findings and Observations

No findings of significance were identified.

4OA6 Meetings, Including Exit

The team presented the inspection results to Mr. Joyce and other members of PSEG management on March 18, 2005. PSEG management acknowledged the results presented. No proprietary information was identified during the inspection.

**ATTACHMENT 1****SUPPLEMENTAL INFORMATION****KEY POINTS OF CONTACT**Licensee Personnel

G. Barnes	Hope Creek Site Vice President
J. Barstow	Corrective Action Program Manager
K. Braendle	System Engineer (CCW)
D. Buirch	Superintendent, Fire Protection
K. Fleischer	Electrical/I&C Design Engineering Supervisor
C. Fricker	Salem Plant Manager
R. Henriksen	Corrective Action Program Supervisor
F. Hummel	System Engineer
S. Jones	Employee Concerns Manager
T. Joyce	Salem Site Vice President
T. Lake	SCWE Supervisor
M. Massaro	Hope Creek Plant Manager
C. Perino	Regulatory Assurance Director
G. Reed	Nuclear Quality Assurance Supervisor
D. Romashko	Nuclear Quality Assurance Manager
G. Sosson	Salem System Engineering Manager
B. Thomas	Senior Licensing Engineer
E. Villar	Senior Licensing Engineer
K. Wolf	System Engineer, Fire Protection

**LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED**Opened

05000272/2005007-01	URI	Potential for nitrogen voiding of ECCS piping or ECCS pump cavitation. (Section 4OA2.b.2.1)
---------------------	-----	---

Opened/Closed

05000354/2005006-02	NCV	Core spray injection valve found with an improper open torque switch bypass setting. (Section 4OA2.b.2.1)
---------------------	-----	---

05000354/2005006-03	FIN	Longstanding reliability and unavailability of the SW emergency makeup supply to SACS. (Section 4OA2.b.2.2)
---------------------	-----	---

05000272/2005007-04	FIN	Component cooling water configuration control deficiency. (Section 4OA2.b.2.3)
05000272, 311/2005007-05	NCV	Untimely problem resolution for repeat failures of 125VDC battery chargers. (Section 4OA2.c.2.1)
05000311/2005007-06	NCV	Deficient control area chiller controls. (Section 4OA2.c.2.2)
05000354/2005006-07	NCV	Repeated challenges to standby service water pumps due to silting and debris in the standby SW strainers. (Section 4OA2.c.2.3)

### LIST OF DOCUMENTS REVIEWED

#### Audits, QA Reports, and Self-Assessments

Salem 2005 Problem Identification & Resolution Inspection Preparations, 2/21/2005  
 Corrective Action Program GAP Analysis Report, 6/11/2004  
 QA Report 2003-0027 - Corrective Action Management Meeting Effectiveness, 2/5/2003  
 QA Report 2003-0058 - Quality of Apparent Cause Evaluations, 3/28/2003  
 QA Report 2003-0070 - Corrective Action Review Board, 6/17/2003  
 QA Report 2003-0076 - SL2 Evaluation Order 70029590, 4/7/2003  
 QA Report 2003-0092 - Evaluation of SL2 20133890, 4/21/2003  
 QA Report 2003-0156 - Transient Combustibles and Live Fire Training, July 3, 2003  
 QA Report 2003-0176 - Corrective Action and Self-Assessment Program Implementation, 7/15/2003  
 QA Report 2003-0191 - SL2 Evaluation of SPV Issues, 7/2/2003  
 QA Report 2003-0211 - Evaluation of SL2 20148028, 7/30/2003  
 QA Report 2003-0220 - Fire Protection Triennial Assessment, October 6, 2003  
 QA Report 2003-0226 - Status of Training Improvement Plans, 8/28/2003  
 QA Report 2003-0283 - Reactivity Management  
 QA Report 2004-0019 - Self-Assessment of QA Procedures, 1/30/2004  
 QA Report 2004-0030 - Power Transient SL1 Corrective Actions, 2/8/2004  
 QA Report 2004-0034 - Self-Assessment Program Implementation, 3/23/2004  
 QA Report 2004-0039 - Post Maintenance Testing, 3/31/2004  
 QA Report 2004-0041 - Corrective Action Program Effectiveness, 3/30/2004  
 QA Report 2004-0088 - Training Effectiveness, Conduct of Training, 6/21/2004  
 QA Report 2004-0105 - Hope Creek Pre-SSDI Self-Assessment, 6/25/2004  
 QA Report 2004-0111 - Departmental Performance Indicators, 10/1/2004  
 QA Report 2004-0147 - Operational Fire Protection Program, October 14, 2004  
 QA Report 2004-0150 - Closure of Corrective Action Program and Work Management Business Plan Items, 9/21/2004  
 QA Report 2004-0161 - Corrective Action Program, 10/29/2004  
 QA Report 2004-0235 - Effectiveness Review for QA Focused Self-Assessment 2004-0102, 12/17/2004

Engineering Programs Self-Assessment Checklist, Fire Protection Program, Salem and Hope Creek Generating Stations  
Engineering Self-Assessment, Page 9, 20160891 - SL2, Evaluation Not Created for TS 3.03 Entry  
Salem Operations Observation Cards, dated 11/13-17/04 & 1/10-14/05  
Salem Operations PAOWF Human Performance and Departmental Cards Analysis, 7/1/04 - 9/30/04 (3rd Quarter)  
Salem Operations PAOWF Human Performance and Departmental Cards Analysis, 10/1/04 - 12/31/04 (4th Quarter)  
Quality Assessment Focused Self-Assessment 2003-0176, Corrective Action and Self-Assessment Program Implementation, dated 7/15/03  
Quality Assessment Monitoring Feedback 2003-0211, Evaluation of SL2 20148028 (Radiation Protection), dated 7/30/03  
QA Assessment Monitoring Feedback 2003-0331, Station ALARA Committee Meeting, dated 11/12/03  
Quality Assessment Monitoring Feedback 2004-0063, 1R16 Containment Work Activities, dated 4/9/04  
QA Assessment Report 2004-0170, Chemistry Rounds and Logs, dated 12/17/04  
QA Assessment Report 2004-0167, Flood and Adverse Weather Protection, dated 12/29/04  
QA Assessment Report 2004-0084, Process Control Program for Processing and Packaging of Radioactive Wastes, dated 6/22/04  
Quality Assessment Report 2004-0034, Self-Assessment Program Implementation, dated 3/23/04  
Quality Assessment Report 2003-0283, Reactivity Management, dated 10/21/03  
Quality Assessment Report 2004-0041, Corrective Action Program Effectiveness, dated 3/30/04  
Quality Assessment Report 2004-0161, Corrective Action Program, dated 10/29/04  
Ongoing Self-Assessment Report 80054140 - 0020, Radiation Protection Assessment of Corrective Actions, dated 2/28/03  
Radiation Protection Self-Assessment Report 80054140 - 040, Radiation Protection - Instruments, dated 7/11/03  
Ongoing Self-Assessment Report 80054140/0060, Chemistry Radiological Work Practices, dated 6/30/2003  
Ongoing Self-Assessment Report 80062122/0030, RP Work Practices of Maintenance, dated 2/13/04  
Radiation Protection Focused Self-Assessment Report 80066418060, RP Contamination Control/Green Sticker Program, dated 8/29/04  
Radiation Protection Self-Assessment Report 800664180100, In Processing Training, dated 1/31/05  
Salem Operations Focused Self-Assessment, Reactivity Management, dated 11/22/04  
Salem Operations Focused Self-Assessment, Operator Rounds, dated 3/14/04  
Salem Operations Focused Self-Assessment, Industrial Safety, dated 12/20/04  
Salem Operations Focused Self-Assessment, Procedure Quality and procedure Use & Adherence, dated 4/20/03

Calculations

EG-0048, Rev. 0 Evaluation of SACS System Capabilities Following a Design Basis Earthquake  
 ES-15.004(Q), Load Flow & Motor Starting Calculation, Rev. 2  
 ES-15.012, Bus Transfer, Rev. 2  
 SC-PB-0002, Hope Creek 4KV Vital Bus Degraded Grid Voltage Relay Setpoint/Accuracy, Rev. 1  
 S-C-4KV-JDC-959, Degraded Vital Bus Undervoltage Setpoint, Rev. 5  
 SC-4KV001-01, Salem Unit 1 & 2 4160 Line Feed/Vital Bus Voltage Indication, Rev. 5  
 S-1-CC-MDC-1817 Component Cooling Heat Exchanger Operability

Completed Surveillances

Inservice Testing - 11 Auxiliary Feedwater Pump (S1.OP-ST.AF-0001), dated 2/2/05  
 Inservice Testing - 23 Auxiliary Feedwater Pump (S2.OP-ST.AF-0003), dated 01/28/05  
 Inservice Testing - 14 Service Water Pump (S1.OP-ST.SW-0004), dated 12/25/04  
 Inservice Testing - 23 Service Water Pump (S2.OP-ST.SW-0003), dated 01/25/05  
 Inservice Testing - 11 Safety Injection Pump (S1.OP-ST.SJ-0001), dated 12/9/04  
 Inservice Testing - 22 Safety Injection Pump (S2.OP-ST.SJ-0002), dated 1/16/05  
 1A Diesel Generator Surveillance Test (S1.OP-ST.DG-0001), dated 2/2/05  
 2C Diesel Generator Surveillance Test (S2.OP-ST.DG-0003), dated 2/17/05  
 Feedwater System Valves - Cold Shutdown - IST (HC.OP-IS.AE-0102), dated 10/13/04  
 Feedwater System Valves - IST (HC.OP-IS.AE-0101), dated 1/14/05  
 Containment Atmosphere Control System Valves - IST (HC.OP-IS.GS-0101), dated 1/7/05  
 Service Water Screen Wash Subsystem A Valves - IST (HC.OP-IS.EP-0101), dated 3/4/05  
 Service Water Screen Wash Subsystem B Valves - IST (HC.OP-IS.EP-0102), dated 1/02/05  
 Emergency Diesel Generator A Operability Test - Monthly (HC.OP-ST.KJ-0001), dated 2/28/05  
 Emergency Diesel Generator B Operability Test - Monthly (HC.OP-ST.KJ-0002), dated 2/18/05  
 Emergency Diesel Generator C Operability Test - Monthly (HC.OP-ST.KJ-0003), dated 2/3/05  
 Emergency Diesel Generator D Operability Test - Monthly (HC.OP-ST.KJ-0004), dated 2/22/05  
 A SACS Pump - AP210 - IST (HC.OP-IS.EG-0001), dated 2/27/05  
 B SACS Pump - BP210 - IST (HC.OP-IS.EG-0002), dated 2/18/05  
 C SACS Pump - CP210 - IST (HC.OP-IS.EG-0003), dated 2/5/05  
 D SACS Pump - DP210 - IST (HC.OP-IS.EG-0004), dated 1/16/05  
 A Service Water Pump - AP502 - IST (HC.OP-IS.EA-0001), dated 3/4/05  
 B Service Water Pump - BP502 - IST (HC.OP-IS.EA-0002), dated 12/19/04  
 C Service Water Pump - CP502 - IST (HC.OP-IS.EA-0003), dated 2/4/05  
 D Service Water Pump - AP502 - IST (HC.OP-IS.EA-0004), dated 1/3/05

Design Change Packages (DCPs)

80023523  
 80030039  
 80072683  
 80073762  
 80074401

Drawings

205231 A 8761 Component Cooling Water P&ID Sheet 1, Rev 64, 6/29/2004  
 205231 A 8761 Component Cooling Water P&ID Sheet 2, Rev 44, 12/2/1997  
 205231 A 8761 Component Cooling Water P&ID Sheet 3, Rev 43, 3/25/1997  
 203000 S 8789-51, Salem No. 1 & No. 2 Units Generators and Main Transformers, One Line Control, Rev. 51  
 203000-SIMP-1, Salem 500KV- 4KV, Electrical Distribution-Simplified One Line, Rev. 1  
 203001 A 8789-29, Salem Unit 1, 4160V, Group Buses One Line, Rev. 29  
 203002 A 8789-34, Salem Unit 1, 4160V, Vital Buses One Line, Rev. 34  
 203061 A 8789-33, Salem Unit 2, 4160V, Vital Buses One Line, Rev. 33  
 203062 A 8789-27, Salem Unit 2, 4160V, Group Buses One Line, Rev. 27  
 Hope Creek Generating Station Service Water (—10-1, Sh. 2), Rev. 36

Evaluations/Analyses

Root Cause Analysis, Salem 500kV Failure/Bus Transfer Event, Rev. 1  
 Root Cause Analysis, Salem 500kV 1-5 Breaker Failure, Rev. 1  
 S-C-4KV-EEE-1972, Assessment of Salem Transfer Capability (as a result of 7/29/03 failure)  
 S-C-4KV-EEE-1795, Establishment of New Lower Voltage Limit for Vital Buses at Salem Stations, Rev. 1

Non-Cited Violations

50-272 & 311/03-03-02	50-272/03-08-03	50-311/04-03-07
50-272/03-03-03	50-272/03-09-02	50-272/04-03-09
50-272/03-05-01	50-272/03-09-03	50-272/04-03-11
50-272/03-05-04	50-272/04-02-02	50-272/04-04-01
50-272/03-05-07	50-272/04-03-01	50-272 & 311/04-04-03
50-272/03-08-01	50-311/04-03-03	50-272 & 311/04-06-01
50-272/03-08-02		

Procedures

HC.MD-PM.EA-0002, Rev. 13, Service Water Intake Bay Silt Survey and Silt Removal  
 HC.OP-AB.COOL-0001, Rev. 5, Station Service Water  
 HC.OP-AB.COOL-0002, Rev. 0, Safety/Turbine Auxiliaries Cooling System  
 NC.CA-TM.ZZ-0003(Z), Rev. 2, Root Cause Evaluation Guideline  
 NC.CA-TM.ZZ-0004(Z), Rev.3, Root Cause Evaluation Template  
 NC.CA-TM.ZZ-0005(Z), Rev. 5, Apparent Cause Evaluation Guideline  
 NC.CA-TM.ZZ-0006(Z), Rev. 17, Corrective Action Review Board Process  
 NC.CA-TM.ZZ-0007(Z), Rev. 0, Effectiveness Review Process  
 NC.CA-TM.ZZ-0008(Z), Rev. 0, Common Cause Evaluation Guideline  
 NC.CA-DG.ZZ-0101(Z), Rev. 5, Operational Challenges Desk Guide  
 NC.LR-AP.ZZ-0054(Q), Rev. 2, Operating Experience (OE) Program  
 NC.NA-AP.ZZ-0016(Q), Rev. 5, Monitoring the Effectiveness of Maintenance  
 NC.PF-AP.ZZ-0082(Z), Rev. 9, Review, Prioritization and Approval Process

NC.QA-AP.ZZ-0077(Z), Rev. 1, Self-Assessment Process  
 NC.QA-AP.ZZ-0002(Q), Rev. 9, QA/NSB Document Review  
 NC.QA-AP.ZZ-0004(Z), Rev 1, Differing Professional Opinion Resolution  
 NC.QA-AP.ZZ-0020(Q), Rev 15, QA Inspection Program  
 NC.QA-AP.ZZ-0021(Q), Rev. 1, QA Processing of Part 21 Notifications  
 NC.QA-AP.ZZ-0026(Q), Rev. 21, QA Audits  
 NC.QA-AP.ZZ-0030(Q), Rev. 0, Nuclear Review Board  
 NC.QA-AP.ZZ-0031(Q), Rev. 11, Onsite Independent Review Program  
 NC.QA-AP.ZZ-0032(Q), Rev. 5, Independent Inspector Certification Program  
 NC.QA-AP.ZZ-0034(Q), Rev. 0, QA Performance Based Inspection Program  
 NC.QA-DG.ZZ-0015(Z), Rev. 8, QA Issue Identification and Escalation  
 NC.QA-PO.ZZ-0001(Q), Rev. 1, QA Operational Philosophy  
 NC.QA-PS.ZZ-0001(Q), Rev. 3, QA Standards Matrix  
 NC.QN-AP.ZZ-0003(Q), Rev. 9, Revisions to the Quality Assurance Program  
 NC.WM-AP.ZZ-0000(Q), Rev. 10, Notification Process  
 NC.WM-AP.ZZ-0001 (Q), Rev. 11, Work Management Process  
 NC.WM-AP.ZZ-0002(Q), Rev. 10, Corrective Action Process  
 S1.OP-AB-LOOP-0001(Q), Rev. 16, Loss of Off-Site Power  
 S2.OP-AB-LOOP-0001(Q), Rev. 16, Loss of Off-Site Power  
 S1.OP-DL.ZZ-0003(Q), Rev. 44, Control Room Log - Modes 1 - 4  
 S2.OP-DL.ZZ-0003(Q), Rev. 56, Control Room Log - Modes 1 - 4  
 S1.OP-SO.4KV-0009(Z), Rev. 14, 1CW 4KV Bus Operation  
 S2.OP-SO.4KV-0009(Z), Rev. 11, 2CW 4KV Bus Operation  
 S2.MD-PM.AF-0002, Rev. 6, Motor Driven Ingersoll-Rand Auxiliary Feedwater Pump  
 Disassembly, Inspection and Reassembly  
 S1.OP-SO.SW-0001, Rev. 21, Service Water Pump Operation  
 S1.OP-AR.ZZ-0002, Rev. 25, Overhead Annunciators Window B  
 SH.OP-DL.ZZ-0027, Rev. 5, Temporary Reading Log & Log Supplements  
 SH.OP-AP.ZZ-0103(Q), Rev. 9, Component Configuration Control  
 SH.OP-AP.ZZ-0108(Q), Rev. 16, Operability Assessment and Equipment Control Program  
 SH.MD-DG.ZZ-0023, Rev. 3, Scaffold Erection, Modification and Dismantling Desk Top Guide  
 SH.MD-AP.ZZ-0023, Rev. 6, Scaffold Program  
 SH.MD-DG.ZZ-0007 (Z), Rev. 10, Maintenance Standards  
 SC.MD-PM.CC-0001 (Q), Rev. 10, Component Cooling Pump Internal Inspection and Thrust  
 Bearing Replacement

System Health Reports and Trending Data

Hope Creek Fuel Pool Cooling and Cleanup  
 Hope Creek Main Turbine and Auxiliary Systems  
 Hope Creek Control Room HVAC System  
 Hope Creek Control Rod Drive  
 Hope Creek Emergency Diesel Generators  
 Hope Creek Service Water (EA/EP), 9/1/04 TO 12/31/04, 4th Quarter 2004  
 Hope Creek Safety and Turbine Auxiliary Cooling System (STACS) - EG, 9/1/04 to 12/31/04  
 Salem 1 Auxiliary Feedwater System Health Report, 4th Quarter 2004  
 Salem 2 Auxiliary Feedwater System Health Report, 4th Quarter 2004

Salem 1 Service Water System, 4th Quarter 2004  
 Salem 2 Service Water System, 4th Quarter 2004  
 Salem 1 Safety Injection System, 10/01/04 to 12/31/04, 4th Quarter 2004  
 Salem 2 Safety Injection System, 10/01/04 to 12/31/04, 4th Quarter 2004  
 Salem 1 Chemical Volume Control, 4th Quarter 2004  
 Salem 2 Chemical Volume Control, 4th Quarter 2004  
 A, B, C, D Service Water Intake Bay Silt Survey Trending Data, 10/4/99 - 1/6/05  
 Salem 1, Component Cooling System, 4th qtr 2004, 12/31/2004  
 Salem 2, Component Cooling System, 4th qtr 2004, 12/31/2004  
 Salem 1 Fire Protection, 3rd Quarter 2004  
 Salem 2 Fire Protection, 3rd Quarter 2004  
 Salem 1 Fire Protection, 4th Quarter 2004  
 Salem 2 Fire Protection, 4th Quarter 2004  
 Salem 1 4kV System, 4th Quarter 2004  
 Salem 2 4kV System, 4th Quarter 2004  
 Hope Creek Fire Protection, 3rd Quarter 2004  
 Hope Creek Fire Protection, 4th Quarter 2004  
 Fire Protection Program Health Report, Period January 2004, June 2004

#### Orders and Evaluations

30041485	60037927	60047339	70022265	70031177	70035275
30081483	60037998	60047739	70023083	70031258	70035290
30085284	60038730	60048023	70023178	70031383	70035401
30087034	60038786	60048115	70026802	70031413	70035833
30087318	60039114	60048470	70028106	70031659	70035939
30087982	60040064	60048505	70028208	70032029	70036089
30097091	60040217	60048542	70028374	70032167	70036112
30098912	60040428	60048543	70028618	70032409	70036161
30115623	60040561	60048545	70029006	70032506	70036324
40008840	60041629	60048546	70029127	70032562	70036363
50079049	60041857	60048547	70029285	70032825	70036365
50082303	60041858	60048548	70029347	70032901	70036752
60011031	60041860	60048549	70029458	70033182	70036864
60021746	60042218	60048550	70029591	70033197	70036969
60024088	60042219	60048551	70029594	70033329	70037109
60024588	60042220	60048552	70029882	70033492	70037127
60031896	60042286	60048553	70029887	70033539	70037183
60031943	60042438	60048554	70029891	70033628	70037412
60032555	60042574	60048848	70029950	70033834	70037479
60032556	60043979	60048965	70030002	70033930	70037484
60032602	60043980	60048966	70030230	70034002	70037510
60032603	60045248	60049227	70030231	70034140	70037623
60033270	60045249	60049764	70030270	70034737	70037721
60034448	60045302	60049923	70030699	70034872	70037733
60035369	60046575	60050219	70031070	70034881	70038071
60035510	60047317	60051353	70031155	70034963	70038091

70038121	70039159	70040282	70041320	70042850	80025150
70038387	70039170	70040328	70041415	70042942	80040533
70038524	70039231	70040561	70041544	70042988	80053229
70038615	70039288	70040699	70041885	70043313	80056707
70038629	70039353	70040740	70041889	70043729	80064179
70038638	70039456	70040813	70041902	70044011	80068351
70038689	70039623	70040846	70041909	70044027	80070162
70038783	70039645	70040875	70042201	70044165	80074401
70038854	70039907	70040926	70042251	70044199	80075390
70038861	70039928	70041083	70042446	70044322	80078632
70038902	70040074	70041104	70042603	70044467	80079060
70039073	70040192	70041180	70042621	70044768	971013150
70039109	70040264	70041212	70042687	70045403	

Notifications Reviewed/Written for this Inspection

20037582	20127342	20133910	20143070	20151760	20162554
20038256	20127482	20133913	20143144	20152770	20162801
20058661	20127664	20133969	20144107	20153108	20163198
20071232	20127791	20133970	20144403	20153410	20163339
20075010	20128060	20133992	20144552	20153925	20163393
20075728	20128124	20134003	20144554	20153983	20163394
20077752	20128140	20134077	20144707	20154543	20163396
20078996	20128256	20134622	20144712	20155083	20163522
20079170	20128369	20134944	20145129	20156271	20163704
20079562	20129057	20135446	20145133	20156362	20164070
20079565	20129243	20135502	20146136	20156551	20164497
20082985	20129246	20135512	20146321	20156866	20164730
20085848	20129312	20135513	20146656	20156974	20165852
20085945	20129726	20135661	20146800	20157376	20165871
20085946	20129858	20135822	20146880	20157540	20166315
20086171	20129967	20136006	20147066	20158261	20166529
20087812	20130136	20136177	20147394	20158321	20167104
20090303	20130309	20136434	20147747	20158465	20167758
20090944	20130775	20136602	20148028	20158632	20168094
20091651	20130862	20137093	20148160	20159382	20168428
20095182	20131346	20137129	20149496	20160269	20168854
20101701	20131588	20137354	20149641	20160842	20169114
20111289	20131677	20137681	20150507	20160891	20169418
20111857	20131787	20138903	20150604	20160918	20169671
20115009	20132950	20138938	20150887	20160931	20169733
20116804	20133267	20139115	20150909	20160985	20170614
20124539	20133397	20139118	20151331	20161194	20170863
20125291	20133597	20139130	20151332	20161377	20171132
20126306	20133726	20140724	20151421	20161614	20171232
20126830	20133890	20141215	20151723	20161639	20171701
20127255	20133904	20142575	20151724	20162366	20171756

20172444	20182573	20189921	20199527	20206875	20215013
20172488	20182916	20189942	20199601	20206898	20215621
20172576	20182927	20190529	20199758	20207005	20215657
20172623	20183682	20190639	20199939	20207105	20215678
20172798	20183687	20191128	20200927	20207107	20215739
20172875	20184393	20191172	20200938	20207271	20215776
20172983	20184477	20191494	20201072	20207415	20216001
20172987	20184593	20191499	20201645	20208058	20216016
20173622	20184629	20191519	20201671	20208470	20216070
20173835	20184708	20192149	20201689	20208504	20216430
20174146	20184959	20192262	20201692	20208505	20216430
20174354	20185039	20192275	20201701	20208506	20216455
20174423	20185175	20192287	20201845	20208513	20216473
20175144	20185191	20192702	20201970	20208580	20216509
20175150	20185302	20192703	20201994	20208892	20217015
20175469	20185370	20192784	20202108	20208989	20217444
20175605	20185551	20192888	20202171	20209050	20217469
20176214	20185568	20193201	20202226	20209101	20217645
20176331	20185599	20193264	20202483	20209102	20217647
20176935	20185837	20193380	20202771	20209103	20217843
20177014	20185911	20194799	20202888	20209289	20218297
20177031	20185960	20195100	20203026	20209300	20218653
20177063	20185968	20195339	20203031	20209352	20218671
20177444	20186003	20195340	20203116	20209363	20219003
20177461	20186028	20195458	20203214	20209492	20219079
20177503	20186241	20195459	20203324	20209663	20219290
20177624	20186359	20195472	20203525	20209735	20219527
20177734	20186608	20195473	20203538	20209772	20219920
20178650	20186810	20195474	20203566	20209825	20219926
20178662	20186985	20195723	20203664	20209894	20220141
20179066	20186988	20195987	20203669	20210310	20220177
20180001	20187103	20196046	20203749	20210439	20220309
20180082	20187261	20196070	20203766	20210676	20220839
20180233	20187271	20196154	20203896	20210742	20220965
20180270	20187414	20196327	20203897	20210849	20221325
20180381	20187588	20196637	20204120	20211263	20221348
20180499	20187615	20196790	20204207	20211551	20221480
20180752	20187632	20197579	20204270	20211713	20221545
20180763	20187692	20197796	20204359	20211810	20221821
20180856	20187870	20198146	20204395	20212421	20221864
20181019	20187886	20199092	20204546	20212514	20221867
20181022	20188571	20199193	20204952	20212648	20223109
20181302	20188691	20199287	20205138	20212968	20223251
20181337	20188892	20199300	20205895	20213045	20223305
20181784	20189073	20199332	20206335	20213564	20223395
20181900	20189105	20199339	20206339	20213779	20223470
20182164	20189242	20199497	20206786	20214154	20223544

A-10

20223562	20226537*	20226795	20227197*	20227802*	20228755*
20223623	20226538*	20226813*	20227198*	20227822*	20228756*
20223854	20226540*	20226815*	20227216*	20227905*	20228787*
20223995	20226593*	20226818*	20227245*	20227906*	20228794*
20224131	20226594*	20226827*	20227248*	20228036*	20228851*
20224479	20226595*	20226834*	20227292*	20228037*	20228852*
20224489	20226596*	20226843*	20227340*	20228070*	20228853*
20224549	20226598*	20226844*	20227342*	20228101*	20228854*
20224695	20226602*	20226846*	20227347*	20228105*	20228855*
20225325	20226605*	20226847*	20227351*	20228274	20228856*
20225588	20226617*	20226848*	20227352*	20228379*	20228858*
20225726	20226644*	20226849*	20227353*	20228380*	20228859*
20225756	20226654*	20226881*	20227360*	20228394*	20228860*
20225895	20226676	20226912*	20227363*	20228486*	20228871*
20225900	20226702*	20226913*	20227364*	20228521*	20228872*
20226040	20226709*	20226933*	20227451*	20228607*	20228873*
20226265*	20226720*	20226951*	20227489*	20228609*	20228874*
20226348	20226722*	20226956*	20227541*	20228636*	20228875*
20226422*	20226731*	20226984*	20227564*	20228638*	20228876*
20226423*	20226756*	20226985*	20227626*	20228725*	20228877*
20226424*	20226759*	20227009*	20227627*	20228739*	20228908*
20226429*	20226760*	20227046*	20227644*	20228740*	20228922*
20226445*	20226766*	20227062*	20227705*	20228751*	20228938*
20226453*	20226767*	20227063*	20227722*	20228752*	20228939*
20226454*	20226768*	20227182*	20227725*	20228753*	20229015*
20226512*	20226786*	20227183*	20227726	20228754*	
20226536*	20226789*				

\* indicates Notifications written as a result of the team's inspection activities

Miscellaneous

- NRC Information Notice 2002-08: Pump shaft damage due to excessive hardness of shaft sleeve generator tubes
- NRC Information Notice 2002-12: Submerged Safety-Related Electrical Cables
- NRC Information Notice 2003-02: Recent experience with reactor coolant system leakage and boric acid corrosion
- NRC Information Notice 2004-07: Plugging of safety injection pump lubrication oil coolers with lakeweed
- NRC Information Notice 2004-01: Auxiliary Feedwater Pump Recirculation Line Orifice Fouling
- NRC Information Notice 1997-40, Potential Nitrogen Accumulation Resulting From Backleakage From Safety Injection Tanks, dated 6/26/97
- Hope Creek Expert Panel Meeting Minutes (HCEP 05-001), dated 2/28/05
- Temporary Modification Summary Salem Unit 1, dated 8/23/04
- Salem CROD Status Log
- Salem Unit 1 and 2 Forced Outage Plan
- Hope Creek Top Risk Significant Systems and Top Ten Operator Actions

Salem Top Risk Significant Systems and Top Ten Operator Actions  
 PSEG Nuclear, LLC, Corrective Action Program Performance Indicators, December 2004  
 PSEG Metrics for Improving the Work Environment, Quarterly Report, 1/31/2005  
 Salem Mrule (a)(1) Goals With Outstanding Corrective Actions Corrective Action Status, 1/7/05  
 Hope Creek Maintenance Rule (a)(1) List  
 Replace 1EAFE-2218B & 1EAFIT-2218B With Panametrics DF868 Ultrasonic Flowmeter (TM 03-032), Rev. 2  
 Salem Unit 1 Control Room Narrative Log, dated 11/1-30/04 & 12/23/04 - 2/15/05  
 Salem Operability Determination 04-009; 11,12,21 & 22 Nuclear Service Water Headers High Operating Pressure, Rev. 5  
 Risk-Informed Inspection Notebook For Salem Generating Station, Rev. 1  
 Risk-Informed Inspection Notebook For Hope Creek Generating Station, Rev. 1  
 Employee Concerns Program Report 2003-2004

**LIST OF ACRONYMS USED**

AFW	Auxiliary Feedwater
CAP	Corrective Action Program
CAPR	Corrective Action to Prevent Recurrence
CARB	Corrective Action Review Board
CCW	Component Cooling Water
CDF	Core Damage Frequency
CDP	Core Damage Probability
CFR	Code of Federal Regulations
CR	Condition Report
CRDM	Control Rod Drive Mechanism
CROD	Condition Resolution Operability Determination
DC	Direct Current
DCP	Design Change Package
ECCS	Emergency Core Cooling System
EDG	Emergency Diesel Generator
EMIS	Equipment Malfunction Information System
HCGS	Hope Creek Generating Station
IMC	Inspection Manual Chapter
IPE	Individual Plant Examination
IST	Inservice Test
LCO	Limiting Condition for Operation
LERF	Large Early Release Frequency
LOSW	Loss of Service Water
MOV	Motor-Operated valve
NCV	Non-Cited Violation
NOTF	Notification (PSEG input into their CAP)
OE	Operating Experience
OTSB	Open Torque Switch Bypass
PHPC	Plant Health Prioritization Committee
PI&R	Problem Identification and Resolution

PRA	Probabilistic Risk Assessment
PSEG	Public Service Enterprise Group, LLC
PSID	Pounds per Square Inch Differential
QA	Quality Assessment
RCIC	Reactor Core Isolation Cooling
RHR	Residual Heat Removal
ROP	Reactor Oversight Process
SACS	Safety Auxiliaries Cooling System
SCWE	Safety Conscious Work Environment
SDP	Significant Determination Process
SFP	Spent Fuel Pool
SI	Safety Injection
SL	Significance Level
SPAR	Standardized Plant Analysis Risk
SRA	Senior Reactor Analyst
SSW	Station Service Water
ST	Surveillance Test
SW	Service Water
TS	Technical Specification
UFSAR	Updated Final Safety Analysis Report
URI	Unresolved Item
VDC	Volts Direct Current