Official Transcript of Proceedings

NUCLEAR REGULATORY COMMISSION

Title: Advisory Committee on Reactor Safeguards

Plant License Renewal Subcommittee

Docket Number: (not applicable)

Location: Rockville, Maryland

Date: Tuesday, October 3, 2006

Work Order No.: NRC-1271 Pages 1-232

NEAL R. GROSS AND CO., INC. Court Reporters and Transcribers 1323 Rhode Island Avenue, N.W. Washington, D.C. 20005 (202) 234-4433

	1
1	UNITED STATES OF AMERICA
2	NUCLEAR REGULATORY COMMISSION
3	+ + + +
4	ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS)
5	MEETING OF PLANT LICENSE RENEWAL SUBCOMMITTEE
6	+ + + +
7	TUESDAY,
8	OCTOBER 3, 2006
9	+ + + +
10	The meeting was convened in Room T-2B3 of
11	Two White Flint North, 11545 Rockville Pike,
12	Rockville, Maryland, at 1:30 p.m., Dr. Otto Maynard,
13	Chairman, presiding.
14	MEMBERS PRESENT:
15	OTTO MAYNARD Chair
16	GRAHAM B. WALLIS Member
17	WILLIAM J. SHACK Member
18	SAID ABDEL-KHALIK Member
19	J. SAM ARMIJO Member
20	MARIO BONACA Member
21	OTTO L. MAYNARD Member
22	JOHN D. SIEBER Member
23	
24	
25	

		2
1	ACRS STAFF PRESENT:	
2	LOUISE LUND	
3	FRANK GILLESPIE	
4	HANS ASHER	
5	RICK SKELSKEY	
6	DONNIE ASHLEY	
7	MICHAEL MODES	
8	JIM DAVIS	
9	KEN CHANG	
10	MIKE HESSLER	
11		
12	ALSO PRESENT:	
13	MIKE GALLAGHER	
14	PETE TAMBURNO	
15	AHMED OUAOU	
16	TERRY SCHUSTER	
17	FRED POLASKI	
18	PAUL GUNTER	
19	RICHARD WEBSTER	
20		
21		
22		
23		
24		
25		

	3	
1	C-O-N-T-E-N-T-S	
2	AGENDA ITEM PAGE	
3	Opening Remarks 4	
4	Staff Introduction 6	
5	Oyster Creek License Renewal Application	
6	Michael Gallagher 8	
7	Fred Polaski	
8	Tom Quintenz	
9	SER Overview	
10	Donnie Ashley	
11	Michael Modes	
12	Aging Managment Program Review	
13	and Audits	
14	Confirmatory Analysis of Drywell	
15	Hans Asher	
16	Public Comments	
17	Adjourn	
18		
19		
20		
21		
22		
23		
24		
25		

P-R-O-C-E-E-D-I-N-G-S

1:32 P.M.

CHAIRMAN MAYNARD: This meeting will now come to order. This is a meeting of the Advisory Committee on Reactor Safeguards, Plant License Renewal Subcommittee. I am Otto Maynard, Chairman for this subcommittee meeting. ACRS members in attendance are Graham Wallis, William Schack, Mario Bonaca, Jack Sieber, Said Abdel-Khalik and Sam Armijo. Our ACRS consultant, John Barton is also present. Cayetano Santos with the ACRS staff, is a designated official for this meeting.

The purpose of this meeting is to discuss the license renewal application for the Oyster Creek Generating Station, the Associated Draft Safety Evaluation Report and other related documents. The Subcommittee will gather information, analyze relevant issues and facts and formulate proposed positions and actions as appropriate for deliberation by the full committee. The rules for participation in today's meeting were announced in the Federal Register on October 2nd, 2006. ACRS meetings are conducted in accordance with the Federal Advisory Committee Act. They are normally open to the public and provide opportunities for oral or written statements from

members of the public to be considered as part of the Committee's information gathering process. I would like to emphasize that these comments should be limited to issues associated with the Oyster Creek Generating Station License Renewal Application.

hear We will presentations from representatives of the Office of Nuclear Reactor Regulation, the Region 1 office, and the Amergen Energy Company. We have also received requests for time to make oral statements at today's meeting. Paul Gunter of the Nuclear Information Resource Richard Webster of the Rutgers Service and ${\tt Mr.}$ Environmental Law Clinic will make their statements following the formal presentation by the Applicant and staff.

If anyone else in the audience would like to make a statement, please notify Mr. Cayetano Santos during the break and we will try to accommodate your request during the public comment portion of the agenda. We have received one written comment from a member of the public regarding today's meeting. This comment was provided by e-mail from Mr. Bill Hering, dated October 3rd, 2006. Copies have been distributed to the subcommittee. A transcript of the meeting is being kept and will be made available as stated in the

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

Federal Register notice. Therefore, we request that participants in this meeting use the microphones located throughout the meeting room when addressing the subcommittee.

Participants should first identify themselves and speak with sufficient clarity and volume so that they can be readily heard. Due to the number of people, we do have an overflow room next door. The audience can see the slides in that room. So if seating is not available in here, next door there should be some seating. Also due to a large number of people, I request to turn your cell phones off or at least put them on vibrate or your pagers on vibrate to minimize disturbance in the meeting.

I will now proceed with the meeting, and I call upon Ms. Louise Lund of the Office of Nuclear Reactor Regulation to begin.

MS. LUND: Okay, thank you. Good afternoon. My name is Louise Lund. I'm the Branch Chief of License Renewal Branch A in the Division of License Renewal. Beside me is also Frank Gillespie, our Director for the Division of License Renewal. The staff has conducted a very detailed and thorough review of the Oyster Creek Generating Station License Renewal Application which was submitted in July of

2005. Mr. Donnie Ashley, here to my right, is the Project Manager for this review. He will lead the staff's presentation this afternoon on the Draft Safety Evaluation Report. In addition, we have Mr. Michael Modes, who is our team leader for the Region 1 inspections that were conducted at Oyster Creek.

We also have several members of the NRR technical staff here in the audience to provide additional information and answer your questions. As result of the review, five open items identified which will be discussed in the This also resulted -- our review presentation. resulted in the issuance of 108 formal requests for additional information. I know the ACRS has been interested in the number of questions that have come out in the reviews in the past. We believe part of that reduction is as a result of the generic aging This application was lessons learned report. submitted using the draft GALL report that was issued back in January 2005. However, it was reconciled with a September 2005 version of the GALL report.

The GALL has certainly helped with the review by providing a roadmap. The staff at Oyster Creek provided excellent support for onsite audits and inspections that were conducted and also the

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

headquarters review through the conference calls and numerous meetings that we've had. And would you like to make some opening remarks?

MR. GILLESPIE: Only what we tried to do and you're going to see when Donnie comes on is we're going to try to conserve the Committee's time so that we can kind of focus on questions and answers. We do have a large number of slides but we're going to try to go through them on the staff presentation very quickly and not duplicate what you're going to hear from the licensee. So we'll make some adjustments because we know, at least in this case there's a number of technical issues. This is the one plant that's the first one to have us focus on this containment shell question which is also a topic of litigation.

So you'll also find the staff being very careful and trying to be careful of their words at his point relative to saying anything too definitive about specific findings because this is not the final SE. This is the SE with open items. So with that, I'm going to turn it over to Mike Gallagher from Exelon.

MR. GALLAGHER: Okay, good afternoon. My name is Mike Gallagher and I am the Vice President of License Renewal Projects for Amergen and Exelon. For

your information Amergen is an Exelon company so therefore, you'll hear both names today. Here with us today we have Tim Rausch, our Site Vice President and we also have a host of support personnel to answer any questions that may come up. Presenting with me today is Fred Polaski, our License Renewal Manager, tom Quintenz, from Oyster Creek and John Hufnagel, our Project Licensing Engineer. Next slide, Slide 3 shows our agenda for Note that early in our presentation we will be discussing the drywell corrosion issue. Fred? MR. POLASKI: Thank you. My name is Fred Polaski, I'm Exelon's Manager for License Renewal. Oyster Creek is a BWR2 with a Mark 1 containment located in Lacey Township, Ocean County, New Jersey. Barnegat Bay is the ultimate heat sink for the plant. Onsite spent fuel storage is provided in the fuel pool and drycast storage. Current capacity enables onsite storage to the current operating term with full core offload capability. We are currently planning an expansion of the interim spent fuel storage facility to accommodate additional fuel storage through the year 2020. MEMBER WALLACE: Is cold water involved, salt water?

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 MR. POLASKI: Yes, we do have salt water 2 as the --3 MEMBER WALLACE: (Microphone is not on, 4 inaudible). 5 MR. POLASKI: The GALL does address salt water environments, yes. Yes. Yes, okay, all right. 6 7 An expansion of the spent fuel storage facility beyond 8 2020 could be pursued if it's warranted. The Oyster 9 Creek PRA was updated in 2004. Our core damage 10 frequency and large early release frequency are shown 11 here on the slide. Next slide, please. 12 This is an overhead picture of the Oyster Just to give you a point of reference, 13 14 north is to the top of the slide. The plant is 15 located west of Route 9. The Barnegat Bay is the body of water on the right of the slide. East of Barnegat 16 17 Bay is the Island Beach State Park and east of that would be the Atlantic Ocean. Water intake is provided 18 19 by the Forked River at the top of the slide and 20 discharges by Oyster Creek to the Barnegat Bay. 21 It's a very funny river. MEMBER WALLACE: 22 It goes in a circle. Does it have an end or a 23 beginning? 24 POLASKI: That's not the original 25 There was a lot of changes made when this river.

1 plant was built to the original -- to the flow of the 2 river. 3 MEMBER WALLACE: Where does it come in 4 from that land? Where is the fresh water? Back 5 there? Up there is the fresh water. So it's somehow 6 7 MR. POLASKI: Actually, there's three branches to the Forked River. This is the north 8 9 branch, this is the middle branch and the lower 10 branch, this other branch is through here and so the original flow of this would have been down here, so 11 12 this one the intake canal was drastically modified during construction. 13 14 MEMBER WALLACE: Now, there's some sort of 15 flushing of all this by tides; is that how it works? 16 MR. POLASKI: And actually, the flow 17 through the plant is greater typically than the flow down the river, so any of the flow coming down the 18 19 Forked River then, flow comes through this way into 20 the plant and back out through Oyster Creek. 21 And the last thing I'd like to point out 22 on the slide is the Forked River combustion turbines 23 which we'll be discussing later in the presentation, 24 are the station blockout owner of AC power source and

they're located adjacent to the switch yard for the

plant.

CHAIRMAN MAYNARD: And you'll be getting into your agreement on the aging management program for that in your presentation.

MR. POLASKI: Yeah, we're going to talk about that later. Slide 6. Oyster Creek is currently operating in the 20 th operating cycle, a plant transition at 24-month cycles in 1991 and the plant is currently operating in end of cycle coast down. Oyster Creek is in the regulatory response column of the NRC Regulatory Oversight Program with one white finding in emergency preparedness. This finding was due to an event in August 2005 when plant operators did not recognize that plant parameters met the threshold for declaring an emergency action level.

In addition, a substantive cross-cutting issue in the area of human performance was identified by the NRC staff and communicated in the recent mid-cycle performance review. One of the examples cited was the white finding in emergency preparedness. The station has completed a thorough root cause analysis of these issues and has continued to implement corrective actions to improve performance in this area.

MEMBER SIEBER: This was a failure to

1	report or reporting the wrong action level?
2	MR. POLASKI: It was a failure to respond
3	to plant conditions when the action level occurred.
4	MEMBER SIEBER: Gotcha.
5	MR. POLASKI: And actually the
6	declaration was made but it was made much too late for
7	the
8	MEMBER SIEBER: Gotcha, understand.
9	MR. POLASKI: Slide 7. Oyster Creek is one
10	of the 15 power reactors that were issued a
11	provisional operating license. This provisional
12	operating license was issued in 1969. Oyster Creek's
13	licensed thermo-power is 1,930 megawatts thermal. New
14	power uprates have been incorporated at the plant and
15	none are currently planned. Design electrical rating
16	is 650 megawatts electric. The ownership of the plant
17	was transferred from GPU to Amergen in 2000 and the
18	current license expires April 9, 2009.
19	MEMBER BONACA: Before you go forth, you
20	mentioned the emergency plan finding. That will be
21	essentially finding on a cornerstone.
22	MR. POLASKI: Yes.
23	MEMBER BONACA: So where is the cross-
24	cutting issue? Mean, what other items have been
25	brought up that combine together with this cornerstone

1	issue?
2	MR. POLASKI: The cross-cutting issue
3	dealt with procedural compliance and procedural
4	adherence.
5	MEMBER BONACA: Yes, okay. And so you
6	have other examples of problems with procedural
7	adherence.
8	MR. POLASKI: Yeah, there were other green
9	findings in that quarter that were in the procedure
LO	adherence hearing.
L1	MEMBER BONACA: In the procedural, okay,
L2	thank you.
L3	MR. POLASKI: If there's no other
L4	questions, I'm going to now turn it back to Mike
L5	Gallagher to discuss the drywell corrosion issues.
L6	MR. GALLAGHER: Okay, I will now give you
L7	a brief history of the drywell corrosion at Oyster
L8	Creek. The corrective actions that were implemented
L9	and how we insured the corrective actions were
20	effective. The presentation will describe how we
21	arrived at our overall conclusions which are the
22	corrective actions to mitigate drywell shell corrosion
23	have been effective, the drywell shell corrosion was
24	arrested in the sand bed region and continues to be

very low in the upper drywell elevations. The service

1	life of the drywell shell extends beyond the year 2029
2	with margin. And also we have effective aging
3	management programs to insure continued safe
4	operation.
5	MEMBER WALLACE: Now, you said it was
6	arrested in the sandbed region. Is this because
7	you've excavated the whole sandbed area and you
8	checked the whole thing all around?
9	MR. GALLAGHER: Yeah.
10	MEMBER WALLACE: And how often do you do
11	that?
12	MR. GALLAGHER: I think the rest of my
13	presentation will touch on all those details.
14	MEMBER WALLACE: Will go into that, okay.
15	MR. GALLAGHER: We can go through that.
16	CHAIRMAN MAYNARD: One other thing I'd
17	like to make sure you touch on in your presentation is
18	one of the observations from the inspection report
19	were found some water. It was emptied without
20	analysis and I think a number of the members have some
21	questions, so if you can work that into your
22	discussion, too.
23	MR. GALLAGHER: Okay, we will. Okay, just
24	to go through some background first, and I think this
25	will help us all. Slide 9, this is a cross section of
J	I and the state of

1	the drywell. Early in plant life during refueling
2	outages, water leaked through defects in the reactor
3	water and the reactor cavity liner which I depicted in
4	cross-hatched blue into the air gap which is depicted
5	in red between the drywell shell in the reactor
6	building, down to the sandbed region which is depicted
7	in the cross hatch purple.
8	MEMBER SHACK: Now, is that really an air
9	gap or is that filled with this Firebar D?
10	MR. GALLAGHER: There is Firebar D in that
11	gap and then during the first operational or static
12	test it actually presses and compresses that Firebar
13	D. There an air gap in there.
14	MEMBER SHACK: I see, so the concrete is
15	cast against it. It compresses and then you're left
16	with a gap.
17	MR. GALLAGHER: That's correct.
18	MEMBER SHACK: And roughly what's the
19	dimensions?
20	MR. GALLAGHER: Pete Tamburno?
21	MR. TAMBURNO: I'm Pete Tamburno, Senior
22	Mechanical Engineer Oyster Creek. That gap is
23	approximately three inches.
24	MEMBER WALLACE: How does the gap get
25	created now, the concrete shrinks or something?

1	MR. GALLAGHER: No. Pete, can you go into
2	that in detail?
3	MR. TAMBURNO: The gap was created by
4	first erecting the drywell vessel. Then they applied
5	this Firebar D to the drywell, and then they poured
6	the concrete around it.
7	MEMBER WALLACE: And they what happened
8	to the stuff that was in between? It disappeared
9	somewhere?
10	MR. TAMBURNO: No, it's still there.
11	CHAIRMAN MAYNARD: When you do your
12	pressure test, is that when
13	MR. GALLAGHER: Yes, Ahmed, could you
14	MEMBER WALLACE: So the gap is full of
15	something.
16	MR. GALLAGHER: It was a foam. It was
17	foam and then during the hydrostatic test of the
18	drywell, you know, it compresses and then there's a
19	gap.
20	MEMBER WALLACE: Okay.
21	MR. GALLAGHER: So I think what Pete's
22	referring to the whole gap, the whole gap
23	MEMBER WALLACE: It's the whole gap or
24	MR. GALLAGHER: Yes.
25	MEMBER WALLACE: it's the air plus this

1	other stuff?
2	MR. GALLAGHER: It's the air plus the
3	Firebar, yeah.
4	MEMBER WALLACE: What do you call that
5	stuff?
6	MR. GALLAGHER: Firebar D.
7	MEMBER WALLACE: Firebar D.
8	MR. GALLAGHER: It's the type of material.
9	MEMBER WALLACE: Fire resistant, is that
10	what it is?
11	MR. GALLAGHER: It was a construction
12	material.
13	MEMBER BONACA: Just a question still
14	regarding configuration. So you're saying that
15	your postulation is that there are cracks in the liner
16	of the cavity and water will come through that down
17	this gap. Now, doesn't it defeat the design purpose
18	of the refueling seal to have those cracks?
19	MR. GALLAGHER: Yes, perhaps if I can go
20	to the next two slides, it will show closer cross
21	sections of this area and I'll answer that question
22	directly.
23	MEMBER BONACA: That is a specific
24	question regarding the design. I thought that the
25	design of the seal was in fact, to prevent any water

1	penetration.
2	MR. GALLAGHER: Yeah.
3	MEMBER BONACA: And it seems to me that
4	the existence of these cracks in the liner by
5	definition, they're defeating the design purpose of
6	the seal, but anyway, so whenever you get there.
7	MR. GALLAGHER: I'll get there, I can get
8	there right now.
9	MEMBER ARMIJO: Just to add one thing to
10	your list of questions, when you talk about the
11	leakage, would you address the issue of moisture geing
12	absorbed in that Firebar D and/or chemicals that leach
13	out of that material ultimately getting down into the
14	sandbar region and what that what your views are
15	concerning the chemistry and the corrosion you saw?
16	MR. GALLAGHER: Let me continue with the
17	background and we will get into that question also.
18	MEMBER WALLACE: What makes the bubbles in
19	the foam?
20	MR. GALLAGHER: Excuse me?
21	MEMBER WALLACE: What makes the bubbles in
22	the foam in the Firebar D? Is it some kind of gaseous
23	release by a chemical reaction or something? What
24	makes the bubbles in the foam?
25	MEMBER SIEBER: There are no bubbles in

1	the
2	MEMBER WALLACE: The foam must have
3	bubbles if it's a foam.
4	MR. GALLAGHER: I'm not aware of any
5	bubbles in the foam.
6	MEMBER WALLACE: It's a foam, you said it
7	was a foam.
8	MR. GALLAGHER: It's a Ahmed, can you
9	answer that?
10	MR. OUAOU: It's
11	CHAIRMAN MAYNARD: Excuse me, could you
12	state your name, please?
13	MR. OUAOU: Ahmed Ouaou with the Oyster
14	Creek License Renewal Team. The Firebarrier, the
15	Firebar D material was put in place to prevent the
16	concrete from it being in contact with the shell and
17	later on that material was compressed with 40 psi
18	pressure and heat it to a temperature of 140 degrees
19	Fahrenheit to create a one-inch gap that's required
20	for seismic movements, for movements of the
21	containment shell. That was basically its purpose.
22	It's a non a compressible material
23	beyond the one-inch
24	MEMBER WALLACE: I'm trying to find out
25	what it is, chemically and so on. Is it completely

1	neutral in terms of corrosion properties or what is
2	it?
3	MR. OUAOU: It has some chlorides.
4	MEMBER WALLACE: Chlorides.
5	MR. OUAOU: Yeah, the chlorides, however,
6	are not in the area of corrosiveness to the steel.
7	MR. GALLAGHER: Yes, specifically, your
8	question about the water, when the water did wash down
9	from this area, it does pick up it did pick up some
10	of these contaminants. The water now that we've had
11	showed that the water met the criteria for you know,
12	non-aggressive to concrete and you know
13	MEMBER SHACK: Or steel.
14	MR. GALLAGHER: Or steel, yes. So the
15	I think we have some data on that matter, Pete, about
16	the chloride level is less than 1,000.
17	MR. TAMBURNO: Yeah, the sand was tested
18	and the ph limit for the leachate was 8.46. The
19	MEMBER SHACK: I thought that was a test
20	on the sand. Is that the sand after it's been
21	penetrated with the stuff or that's the acceptance
22	criteria for the sand that you're about to put in the
23	sand bag?
24	MR. TAMBURNO: No, the results of the
25	tests I'm giving you is the tests on the sand after

1 that was removed, and the chlorides are 45 parts per 2 billion and sulfates are 17 parts per billion. 3 MEMBER WALLACE: In that water that was 4 tested? 5 MR. GALLAGHER: Yes, in the leachate that came from the sand. 6 7 MEMBER WALLACE: Does the NRC know what 8 Firebar D is and what it's made out of and what's its 9 properties are? MEMBER SIEBER: Yeah, they do because it's 10 in the SER. 11 Hans Ashar is coming up to talk 12 MS. LUND: 13 about --14 ASHER: Yeah, we're aware of the 15 particular type of insulation between the concrete 16 shield wall and steel and with the water coming out of 17 the refueling cavity in some places when a accumulation in the same pocket area, it is 18 19 contaminated that sand with corrosive 20 environment in the early days and afterwards, I 21 believe Oyster Creek owners at that time had done a 22 number of analysis that I recall. I don't remember all 23 the numbers but I have seen the chemical composition 24 and all those things. I have it in my folders but I 25 was not ready to talk about because I didn't know it

1	would come up at this time because they were taking
2	out the sand, but if you
3	MEMBER WALLACE: The Firebar is still
4	there, though, isn't it?
5	MR. ASHER: Yes, the Firebar is still
6	there.
7	MR. GALLAGHER: And I think when we go
8	later through the presentation, we'll talk about, you
9	know, our program that monitors the corrosion in the
10	upper drywell and the results of that which are good.
11	So I think that addresses the issue, what's actually
12	going on up there.
13	MEMBER BONACA: I don't want you to forget
14	about my question.
15	MR. GALLAGHER: We're doing that right
16	now. If we could go to
17	MEMBER SIEBER: Well, we still don't have
18	the answer to Dr. Wallace's question as what the
19	material is. Is it a foam, is it a fiber?
20	CHAIRMAN MAYNARD: I'd like to go ahead
21	and let the licensee go on. We can come back to that
22	if we've got it from somebody here' who's looking
23	after it.
24	MR. GALLAGHER: Yeah, and we can get that
25	specific information, also at a break.
ļ	

1	Okay, so let me just continue with the
2	overhead. We'll get to your question. So attached to
3	the sandbed region are five drains designed to remove
4	any water from this region. The sandbed drains were
5	clogged and thus, prevented the sand from remaining
6	dry.
7	MEMBER WALLACE: Say that again.
8	MR. GALLAGHER: The sandbed drains were
9	clogged and thus, prevented the sand from remaining
10	dry. This is, I'm talking about the you know, the
11	initiation of the event.
12	CHAIRMAN MAYNARD: And this was back in
13	the `80s.
14	MR. GALLAGHER: This is in pre-mid-`80s.
15	So what I'm going through here now is, you know, the
16	complete history, so we're starting from the
17	identification of the problem. So I'm describing the
18	background and identification of the problem and then
19	we'll go through all the facets to our current aging
20	management.
21	MEMBER WALLACE: You say there were some
22	regions which were much more corroded than others.
23	MR. GALLAGHER: That's true.
24	MEMBER WALLACE: That's going to be part
25	of our investigation, I think, as to how extensive is

1 this corrosion, how extensive -- how well, if this is 2 something, tell us of the details of it all the way 3 around and help us. 4 MR. GALLAGHER: And we'll be getting into 5 that, yes. 6 MEMBER WALLACE: Okay. 7 MR. GALLAGHER: Yes, sir. So, as I said, 8 this wet sand was in contact with the drywell shell exterior and caused general corrosion of the shell in 9 the sandbed region. To a lesser extent, there was 10 also corrosion identified in the upper region of the 11 drywell as you had just questioned with the Firebar. 12 The detection of water draining from the sandbed 13 14 drains and potential for drywell shell corrosion was recognized and pursued in the mid-1980s. 15 So that's 16 the period of time we're talking about right now. Well, I don't mean to go 17 MEMBER WALLACE: on forever but to get corrosion, you need oxygen as 18 19 well as water and the worst condition which 20 something that is damp and has air there. If it's 21 totally immersed, sometimes it's better off. 22 MR. GALLAGHER: That's true. 23 MEMBER WALLACE: Well, you have a 24 condition where you've got air and water, so

partly drained water and there's some sort of

1 interface where things are really going on; is that 2 what you had there, something like that? 3 MR. GALLAGHER: Well, there is an air gap 4 there and so there is -- there was air or there is 5 If I go to Slide 10 and this will be hitting into your questions. Slide 10 is a close-up of the 6 7 cross-section of the sandbed. Your questions will be 8 answered in the next slide, but this shows the sandbed 9 area and the drain. The air gap is also shown and 10 that's the red at the top of the slide. MEMBER WALLACE: I understand. 11 sandbed is the blue and the red or -- it doesn't make 12 sense. Where is the sandbed in this picture? 13 14 is the torus? 15 MR. GALLAGHER: This might be a little bit 16 better figure for you. That is the sandbed area that 17 he's pointing to. 18 MEMBER WALLACE: Okay. 19 MR. GALLAGHER: The cross hatch is the 20 shell itself. MEMBER WALLACE: Yeah, I thought it was. 21 22 So what's this blue and red stuff? 23 MR. GALLAGHER: All right, on that slide 24 it didn't turn out well in this overhead because I 25 think the projector is --

1	MEMBER WALLACE: So it's labeled sandbed
2	but it isn't sandbed.
3	MR. GALLAGHER: Go back to that.
4	MEMBER WALLACE: It's something inside.
5	MR. GALLAGHER: Let me explain to you.
6	This light these lines are too light. This is
7	projected
8	MEMBER WALLACE: Yes, the sandbed is in
9	there.
10	MR. GALLAGHER: This is the sandbed there.
11	MEMBER WALLACE: And what's that red and
12	blue stuff and why is that highlighted?
13	MR. GALLAGHER: The orange or
14	MEMBER WALLACE: Red on my slide.
15	MR. GALLAGHER: The orange, down here that
16	is the concrete in the inside of the containment.
17	There's actually it's a sawtooth arrangement in
18	that the you know, the curb is higher and then
19	lower a threat to the drywell. So the blue is
20	supposed to show you the top of the curb on the inside
21	of the drywell.
22	MEMBER WALLACE: This is just a different
23	piece of concrete.
24	MR. GALLAGHER: Yes. Well, it's the same
25	form but it's it looks like a sawtooth pattern.

1	The sandbed area is to the right of that, and that's
2	the white area, okay. The green is supposed to be
3	that's one of the down comers going to the torus. And
4	then the air gap is the red depicted at the top. It's
5	the same red on the previous slide and that goes all
6	the way around obviously, and so it connects to the
7	sandbed area.
8	MEMBER WALLACE: And you're going to tell
9	us just where the corrosion is in here?
10	MR. GALLAGHER: Yes, yeah.
11	MEMBER WALLACE: Can you point it out now?
12	MR. GALLAGHER: The corrosion is
13	MEMBER SHACK: You're better off with the
14	next slide.
15	MR. GALLAGHER: The next slide is about
16	the refueling seal.
17	MEMBER SHACK: You have the line drawing
18	of this area.
19	MR. GALLAGHER: Okay, where you see the
20	shell
21	MEMBER WALLACE: Where's the corrosion?
22	Up there?
23	MR. GALLAGHER: The corrosion is in this
24	area here.
25	MEMBER WALLACE: And not below that.

1	MR. GALLAGHER: Well, it's all of this
2	area.
3	MEMBER SHACK: It tapers off.
4	MEMBER WALLACE: It doesn't go beyond
5	that. It's just how do you know what happens when
6	it goes into the concrete there?
7	MR. GALLAGHER: Into which area?
8	MEMBER WALLACE: The bottom, the very
9	bottom. In there, what happens in there?
10	MR. GALLAGHER: And we'll be talking about
11	that also.
12	MEMBER WALLACE: Oh, you're going to tell
13	us all these things.
14	MR. GALLAGHER: Yes, that's right.
15	MEMBER WALLACE: Good.
16	MEMBER SHACK: Just while we have this
17	drawing up, now, my understanding is you didn't have
18	a galvanized plate the way some people do to cover the
19	sandbed but is that a galvanized or is that some sort
20	of plate I see there in the drawing?
21	MR. GALLAGHER: This here, no, that's the
22	down comer.
23	MEMBER SHACK: That's the down comer.
24	MR. GALLAGHER: Yes.
25	MEMBER SHACK: And you don't have the

1	galvanized. Yours is open to the
2	MR. GALLAGHER: Ahmed, any galvanized
3	plate?
4	MR. OUAOU: We do have a cover plate
5	around the vent header at the top of the sandbed
6	region.
7	MR. GALLAGHER: At the top.
8	MR. OUAOU: There was one included in the
9	design.
10	MEMBER SHACK: There wasn't?
11	MR. OUAOU: There was.
12	MEMBER SHACK: There was.
13	MR. OUAOU: Yes.
14	MEMBER ARMIJO: Just one last question;
15	you said you had five drains. Were all of the drains
16	plugged or was just a couple of them so that you
17	MR. GALLAGHER: They were all plugged.
18	MEMBER ARMIJO: You have to assume that
19	the corrosion was generalized around the lower part of
20	this.
21	MR. GALLAGHER: That's correct.
22	MEMBER WALLACE: There's a filter on top
23	of the drain pipe or something like that to prevent
24	the sand washing away?
25	MR. GALLAGHER: There is a filter, and

1 Ahmed, the filter? 2 That's what plugged? MEMBER WALLACE: 3 MR. GALLAGHER: The filter. 4 MR. OUAOU: As Mike mentioned previously, 5 the drain itself was full of sand as part of the design to avoid --6 7 MEMBER WALLACE: It was filled with sand. It was filled with sand to 8 MR. OUAOU: 9 avoid draining the sand from the sandbed region but as a result of water intrusion in the area, you have 10 fines that mixed with the sand. You don't have the 11 12 drainage and that was why it was plugged. MR. GALLAGHER: Okay, so to get to your 13 14 question on the next slide, which is Slide 12, excuse 15 me, Slide 11, this is the reactor cavity seal area. And this -- this shows a cross section of that. 16 slide is useful to show the water leakage path. 17 And basically as we indicated, the water leakage was 18 19 through defects in the reactor cavity liner and worked 20 its way into the trough area. Again, this projector 21 is light but I think your slides are a little better. 22 The water worked its way -- or leaked into 23 this trough area and some of this trough area there 24 was low spots originally in the trough area and so the

water which leaked through here, leaked down and

1	spilled over into the air gap.
2	MEMBER BONACA: Now, two questions. One,
3	how sure are you that that's the source of water since
4	this is being contested? You've tested this water?
5	MR. GALLAGHER: We're very sure that
6	that's the source of the water. Other
7	MEMBER BONACA: That's an issue.
8	MR. GALLAGHER: Other during the
9	corrective action, early on, there was other sources
10	that were pursued such as the refueling seal and
11	things like that and it was determined that the
12	majority was through this other
13	MEMBER BONACA: And then the question I
14	had was, the seal is supposed to be preventing water
15	penetration but if you have cracks in the liner you
16	are defeating the design objective. And the question
17	I'm raising is because whatever you do to control
18	corrosion, to do whatever you can do to monitor, you
19	still are defeating the design objective and fitting
20	water through that gap. I mean, is that an initiative
21	to try to fix those cracks or replace the liner?
22	MR. GALLAGHER: Absolutely, what we
23	MEMBER BONACA: Otherwise the root cause
24	of all this is not going to go away. And I mean, the
25	goal objective of inspecting those bellows and seals

1	is defeated by definition. Simply you have cracks and
2	they're allowing water to come down.
3	MR. GALLAGHER: When we go into our
4	program and talk about what we've done in the past and
5	what we're committing to do for the future, we put
6	strippable coating on the reactor cavity liner before
7	we fill it with water during refilling outages. And
8	that's been very, very effective to eliminate the
9	water from this air gap.
10	MEMBER BONACA: You still have been
11	getting water in these containers.
12	MR. GALLAGHER: Okay, we can talk about
13	the containers now, if that's
14	MEMBER BONACA: No, that's okay, you're
15	going to talk about it later.
16	MEMBER SHACK: Well, let me go over this
17	strippable coating now. You have put this I mean,
18	every time you fill this with water, that's part of
19	your procedure is to apply the strippable coating
20	first?
21	MR. GALLAGHER: We have made a commitment
22	that going forward, every time we fill the reactor
23	cavity, we will put strippable coating.
24	MEMBER SHACK: You haven't done that every
25	time since the problem started?
I	

	31
1	MR. GALLAGHER: We've done it, I think,
2	every time except two outages. And
3	MEMBER SIEBER: The answer is, no, they
4	haven't done it every time.
5	MEMBER BONACA: That's right.
6	MEMBER ARMIJO: Was that just oversight or
7	error or was it a
8	MEMBER SHACK: A procedural failure?
9	MR. GALLAGHER: Pete, can you answer that
10	question?
11	MR. TAMBURNO: This is Pete Tamburno,
12	Senior Mechanical Engineer. There were two outages
13	during the time frame that GPU owned the plant that
14	the strippable coating was not put on and I believe it
15	was during a time when the plant was announced to be
16	decommissioned.
17	MR. GALLAGHER: But, you know, for
18	clarity, we have made a commitment and we put that in
19	our license renewal application that we will put the
20	strippable coating on.
21	MEMBER SHACK: Now, when you
22	MEMBER BONACA: Yeah, go ahead.
23	MEMBER SHACK: When you have the
24	strippable coating in place and you're I trust
25	you're still monitoring for leakage, do you get any

leakage with the strippable coating in place? You're 1 2 still getting leakage? 3 MEMBER BONACA: Yes, they do. 4 MR. GALLAGHER: We have had -- when we 5 went through our commitments on this -- the current commitments, current licensing basis commitments, we 6 7 couldn't find any current documentation on 8 monitoring of the water leakage. We've talked with 9 people that have been in the sandbed and they have 10 said that, you know, there is no water in the sandbed when they go in there to do the visual inspections on 11 12 the coating. So we believe that our corrective actions have been effective, which I'll go in to tell 13 14 you what we've done comprehensively to insure that the 15 water is going down the trough drain and not into the air gap. 16 I'd like for us to let 17 CHAIRMAN MAYNARD: the licensee go ahead, I think trying to give a 18 19 history and --20 MR. GALLAGHER: Yeah, we have a pretty 21 good presentation. 22 CHAIRMAN MAYNARD: We can come back to 23 these -- anything that is not answered, we can come 24 back to but I want to leave time for us to do that. 25 MR. GALLAGHER: And I think we'll hit on

	all your issues.
2	Okay, if we can skip through Slide 12,
3	Slide 12 is basically the words that I just talked to.
4	Okay, going to Slide 13, okay, so just to frame this
5	again, where I'm at is we've discovered the problem
6	and now we're determining what the problem is and the
7	extent of it. So in the 1986 time frame, the initial
8	corrosion monitoring program was initiated utilizing
9	ultrasonic thickness measurements in order to
10	determined
11	MEMBER WALLACE: Taken from the sandbed
12	side?
13	MR. GALLAGHER: This is comprehensively
14	for the drywell.
15	MEMBER WALLACE: On the sandbed side.
16	MR. GALLAGHER: From inside the drywell.
17	MEMBER WALLACE: From inside not from the
18	sandbed side, from inside.
19	MR. GALLAGHER: This is a comprehensive
20	program to look for to evaluate the
21	MEMBER WALLACE: It's taken from inside.
22	MR. GALLAGHER: So in order to determine
23	the
24	MEMBER SHACK: But when you take that from
25	inside, you're going through the concrete and you look

1	for a reflection off the inside wall and outside wall?
2	MR. GALLAGHER: No, the inside is just the
3	liner itself. The concrete is on the outside.
4	MEMBER WALLACE: There's concrete there,
5	isn't there?
6	MEMBER BONACA: He's not talking about the
7	bottom.
8	MR. GALLAGHER: Yeah, I'm talking the
9	accessible shells
LO	MEMBER SHACK: The portion of the sandbed
L1	region.
L2	MEMBER WALLACE: Well, you said concrete
L3	on there, so how do you do take it when you've got
L4	concrete on top of the steel?
L5	MR. GALLAGHER: If I can, what I'm trying
L6	to describe here first is, our monitoring.
L7	MEMBER WALLACE: This seems to be
L8	important as to how good are the measurements.
L9	MR. GALLAGHER: That's right, that's
20	right. And
21	MEMBER WALLACE: You show there's concrete
22	on top of the steel in that region?
23	MR. GALLAGHER: What I'm talking about now
24	is to determine the appropriate monitoring locations
25	to measure the

1	MEMBER SHACK: What you're saying is
2	you've taken a thousand measurements in the sandbed
3	region and we're asking
4	MR. GALLAGHER: I didn't say that.
5	MEMBER WALLACE: We're asking how you did
6	it.
7	MR. GALLAGHER: I didn't say that. If I
8	can describe
9	MEMBER SHACK: The UT is in the sandbed
10	region at least some of the one thousand.
11	MR. GALLAGHER: These one thousand
12	measurements were throughout the drywell in order to
13	determine
14	MEMBER WALLACE: That's misleading then.
15	They're not in the sandbed region. What did you do in
16	the sandbed region?
17	MR. GALLAGHER: It says approximately a
18	thousand UT measurements were taken to identify the
19	finished location
20	MEMBER WALLACE: How does measuring
21	somewhere else measure what's happening in the
22	sandbed?
23	MR. GALLAGHER: in the sandbed region
24	and the upper elevations of the drywell. What we're
25	trying to say, we comprehensively took measurements

1	throughout the dry well to identify the extent of the
2	problem, okay.
3	MEMBER WALLACE: We're asking you how you
4	did it in the sandbed.
5	MR. GALLAGHER: Okay, so in the sandbed
6	region, let me turn that over to Pete and you can go
7	into the specifics on that.
8	MR. TAMBURNO: Okay, this is in the early
9	`80s before we had access to the sandbed. At that
10	time, we did not have access to get into the sandbed
11	so we did a sweep, 360 degrees on drywell vessel
12	inside the drywell, that was accessible. We did not
13	look at portions underneath the concrete, only the
14	portions of the vessel that were accessible. There's
15	a
16	MEMBER WALLACE: So you've got no
17	measurements in the sandbed region?
18	MR. TAMBURNO: No, no, there are portions
19	of the sandbed which are accessible from the inside.
20	MEMBER WALLACE: Some parts.
21	MR. TAMBURNO: Yes, sir.
22	MEMBER WALLACE: But there are other parts
23	that are not.
24	MR. TAMBURNO: There are other parts that
25	are not accessible.
	I and the second

1	MEMBER WALLACE: I presume we knew nothing
2	about what was happening there.
3	MR. TAMBURNO: Well, shortly after we
4	reported that information to the NRC, they questioned
5	about what about underneath the concrete, at which
6	point we removed a portion of the concrete in two
7	sections and investigated the vessel in those two
8	portions. Our conclusions were that the information
9	on the accessible regions were representative of the
10	corrosion when we looked at the portions of the vessel
11	that were underneath the concrete.
12	MEMBER WALLACE: That's where you found
13	the minimum thickness that we're going to hear about?
14	MR. TAMBURNO: Yes, sir.
15	MEMBER WALLACE: And how big was the
16	minimum thickness?
17	MR. TAMBURNO: At that time, there were
18	the numbers varied anywhere between 1.1 which is what
19	the vessel was originally delivered and to 0.5 inches
20	thickness.
21	MEMBER WALLACE: 0.5 inches thickness.
22	That's the thinnest I've heard yet.
23	MR. TAMBURNO: Excuse me, excuse me,
24	that's incorrect, 0.85, I'm very sorry.
25	MEMBER WALLACE: Why did I see .603 in the

report?

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. TAMBURNO: At the time that we did our original investigation, we did not see the .603. was later on when we gained access to the outside of the drywell by removing the sand.

MEMBER WALLACE: I'm asking all this because I'm not sure from what I've read, what the thinnest part of this drywell is, how thin it is, how extensive it is. I don't get that from the report. I get these numbers thrown out. We measured 0.85 then we found .603 but how big is it and what about the places where you didn't measure? All that stuff, I don't know. Are you going to clarify all that? MEMBER BONACA: The .8 is referenced as an

average.

Yeah, there's actually two MR. GALLAGHER: criterion we -- if I can briefly, there's different plates in the drywell and shell, as you know. there's a different minimum thickness for each one. Sandbed, just talking sandbed, there's actually two criterion. Okay, one is for the minimum average. Okay, and that number is 0.736. And the other is for a minimum local, which is .49. So the measurements need -- you know, the criterion is to meet those. all the areas of the sandbed, we meet those criterion.

1 MEMBER WALLACE: In all areas. So you've 2 got how many measurements around to make sure that you 3 cover all areas? So specifically, what 4 MR. GALLAGHER: 5 we're talking about here is there was an investigation that was done to identify the areas to monitor for 6 7 corrosion, okay. When I say these thousand points, 8 it's throughout the drywell. Basically the bottom 9 line is to get to your question, is that these were 10 used to identify the thinnest areas, biased to the We then set up -- there's 19 11 thinnest areas. 12 monitoring locations that are on the interior of the sandbed area that are like a grid, you know, and those 13 14 are to determine the data points and they are 360 15 degrees around there. 16 thev representative of are 17 condition of the sandbed. Those particular points, there's a grid that's established. It's a 49-point 18 19 Those 49 points in each of the 19 locations 20 were taken and they were bounced off this criteria of 21 the minimum general being the .736 and then the 22 minimum local being the .49. 23 MEMBER ARMIJO: Do you have a little

24

1	region that you could show
2	MEMBER WALLACE: That would help a lot.
3	MEMBER ARMIJO: You know, that would save
4	a lot of questions, because I think that's our all
5	of us have looked for this information.
6	MEMBER WALLACE: Right.
7	MR. GALLAGHER: We can easily we don't
8	have that in an overhead. We can provide that. But
9	these 19 locations are throughout the 360 degree of
10	the sandbed region.
11	MEMBER WALLACE: Now in the torus, you've
12	got pits. I mean, how would you find pits if you're
13	only just looking in a few places here? You don't
14	find pits in the drywell? You find pits in the torus.
15	MR. GALLAGHER: The torus?
16	MEMBER WALLACE: You could have a pit in
17	the drywell, couldn't we here, that's bigger than
18	these average of thicknesses?
19	MR. GALLAGHER: So is your question about
20	the torus or about the
21	MEMBER WALLACE: Well, I find there are
22	pits in the torus because you could see the torus.
23	MR. GALLAGHER: Right.
24	MEMBER WALLACE: We found pits. I just
25	want to be somehow assured that there aren't pits in

1	the drywell, which wouldn't show up in these random
2	measurements.
3	MR. GALLAGHER: Let me turn that question
4	over to Ahmed.
5	MR. OUAOU: Ahmed with Exelon. The
6	corrosion sandbed region after we removed sand and
7	cleaned up the sandbed region, we noted that the
8	corrosion is primarily general corrosion. There were
9	some
10	MEMBER WALLACE: But you were able to look
11	up the whole region.
12	MR. OUAOU: Absolutely.
13	MEMBER WALLACE: You didn't see pits.
14	MR. OUAOU: Well, there were localized
15	areas and that's what this local criteria for
16	acceptable thickness is for.
17	MEMBER WALLACE: You looked at part of the
18	drywell and there was general corrosion.
19	MR. OUAOU: We looked at the entire
20	surface of
21	MEMBER WALLACE: Entire surface.
22	MR. OUAOU: of the sandbed region and
23	the
24	MR. GALLAGHER: From the exterior.
25	MR. OUAOU: From the exterior after the
l	

1 sand was removed in `92 which I believe is going to 2 come up in some slides but the corrosion is general 3 corrosion, not pitting. 4 MEMBER WALLACE: You see, it would help 5 really if you ask yourself the questions instead of us asking the questions. We asked these questions, this 6 7 is how we answered them instead of us sort of having 8 to drag it out of you. It would help. 9 MR. GALLAGHER: Okay. 10 MEMBER WALLACE: Maybe you could do that later on in your presentation. 11 12 We will. MR. GALLAGHER: MEMBER WALLACE: 13 Okay. Okay, so at this point, in 14 MR. GALLAGHER: 15 the program, I'm telling you about how many UT points were developed in order to determine which monitoring 16 points should be monitored. We also took core samples 17 of the drywell shell to confirm these UT measurements. 18 These core samples also confirmed that the degradation 19 20 was general corrosion. At this point, in response to 21 an NRC staff concern regarding whether the inspection 22 locations represented the condition of the entire 23 drywell, in 1990 Oyster Creek prepared a new random UT 24 inspection plan designed to address the concern.

Inspection results using the new random

inspection plan confirmed the previous locations were representative of the thinnest locations in the drywell. One location at elevation 60 foot 10 inches which is in the upper drywell, was also added to the program to expand the monitoring of the thinnest locations. The NRC staff accepted this program in an SER dated November 1st, 1995. Next slide.

At this point, I'm talking to you about the corrective actions. Corrective actions were then developed and implemented in order to address the ongoing shell corrosion. First, the containment pressure analysis was revised to establish additional shell thickness margin for the upper drywell. The original primary containment design pressure of 62 psig --

MEMBER WALLACE: I'm sorry, I have another question because in reading these, I see that the basic approach was a buckling evaluation. Buckling to me means collapse by having a vacuum in the vessel.

And yet, this is talking here about containment peak pressure. It seems that the concern is that it would collapse due to a vacuum rather than it would burst due to a pressure.

MR. GALLAGHER: Yeah, the upper drywell actually the controlling mechanism is membrane

1	stressors. Below it it's buckling, in the sandbed
2	region below it's buckling. So we had to
3	MEMBER WALLACE: Don't you have vacuum
4	breakers or something to prevent this kind of a vacuum
5	forming in the drywell?
6	MR. GALLAGHER: Ahmed?
7	MR. OUAOU: The cause of buckling in this
8	case is the refueling water. During outages, the
9	cavity is full of water. It's actually the dead load
LO	that's imposed on the shell and not the vacuum.
11	MEMBER WALLACE: No, it's not a vacuum
12	inside.
L3	MR. OUAOU: We do have vacuum breakers but
L4	that's not the type of buckling.
15	MEMBER WALLACE: So it's not a vacuum,
L6	it's a dead load of water.
L7	MR. OUAOU: That's right. It's a dead
18	
	load of water plus the dead load of whatever else is
19	attached to the containment.
20	MR. GALLAGHER: Okay, so as I said, the
21	original analysis had a design pressure of 62 psig and
22	it was generic to a GE Mark 1 containment design and
23	included a 10-pound margin. Analyses were then
24	performed to re-evaluate the drywell design pressure
25	for the Oyster Creek drywell. Analysis demonstrated
	•

that following worst case design basis, loss of coolant accident, the peak drywell pressure would not exceed 38.1 pounds.

Additional margin was added to establish a design pressure of 44 pounds and this change was approved as 165 to the Amendment Oyster technical specifications in September of 1993. revised containment pressure was later utilized to determine the minimum acceptable drywell thickness and establish additional shell thickness margins for an area above the sandbed region. A detailed analysis was performed to determine the minimum acceptable drywell, shell thickness. The results of the analysis show that the minimum general thickness required to satisfy the ASME code above the sandbed region is controlled by membrane stresses, as I said, and buckling controls the minimum drywell shell thickness in the sandbed region.

The analysis used 0.736 inches general thickness in the sandbed region which satisfied the ASME stress requirements for all design based load combinations and applicable ASME safety factors. All actual general thickness measurements have met this criterion as I've said before. The focus of the remaining corrective actions to prevent water

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

intrusion into the sandbed region, and to eliminate the ongoing corrosion. Activities such as applying sealing tape and strippable coating to the reactor cavity liner during refueling outages and improving the reactor cavity trough drain were performed. sandbed region drains were cleared to improve draining at this time. Originally the sandbed region was inaccessible. Access to the sandbed region was gained by creating access ports through the surrounding The sand was then permanently concrete structure. sandbed region since this was removed from the acceptable by to be the containment analysis. The corrective actions also included the removal of corrosion from the drywell exterior surface and the application of a protective epoxy coating on the drywell exterior surface. MEMBER WALLACE: So there's no sand there now. MR. GALLAGHER: Excuse me? MEMBER WALLACE: There's no sand there now. MR. GALLAGHER: There's no sand there now. MEMBER WALLACE: So the function of the sand is no longer being performed.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. GALLAGHER: Ahmed, if you could
2	explain the original function and why that was
3	acceptable to remove.
4	MR. OUAOU: The BWR Mark 1 containments
5	had a sandbed region to transition from the embedded
6	region into the cantilevered portion free-standing
7	region basically to reduce the stresses. It's a
8	cushion. And the analysis that was done in 1991 and
9	`92 time frame, concluded that it's not required. The
10	shell by itself can handle the stresses. And for that
11	reason, it was removed.
12	MEMBER ARMIJO: A quick question, are the
13	access ports to the sandbed region still open that you
14	can go in there and inspect?
15	MR. GALLAGHER: Pete, if you can just
16	describe the access ports.
17	MR. TAMBURNO: The access ports are man
18	ways in the concrete. They're approximately six feet
19	long and we've installed boron bags when we're at
20	operation. When we do our coating inspection we
21	remove the bags and we send a man through the man way
22	to do the inspections.
23	MEMBER ARMIJO: So is there one or many?
24	MR. GALLAGHER: There's 10.
25	MEMBER ARMIJO: So you can do a 360-degree
ļ	

visual inspection.
MR. GALLAGHER: Yes, sir. Again, I'm
talking about corrective actions here in the early
`90s. The corrective actions also included the
removal of corrosion from the drywell exterior surface
and the application of protective epoxy coating on the
drywell exterior surface in the sandbed region. The
concrete surface below the sandbed was shaped and
coated with an epoxy coating to
MEMBER WALLACE: Well, if it was 1.1
inches originally and it went down to .75 or
something, there must have been about half an inch of
rust on there.
MR. GALLAGHER: Yeah, the 1. minimum is .8
inches is where we are not.
MEMBER WALLACE: But the rust is bigger
than the original steel, so there's
MR. GALLAGHER: There was corrosion
products there.
MEMBER WALLACE: A large amount.
MR. GALLAGHER: Which probably contributed
to the clogging in the sand. The concrete surface
below the sand I'm talking about now, that was shaped
and coated with an epoxy coating to assure that any

inadvertent leakage would flow towards each of the

1	five sandbed drains. The drywell shell at the
2	juncture, and this gets to some of your questions
3	about the embed, of the concrete floor was sealed with
4	silicon to prevent
5	MEMBER WALLACE: When you took the rust
6	off, did you get a smooth surface or did you have to
7	sandblast it or something to get a smooth surface that
8	you could coat? Was it kind of pockmarked or how was
9	it?
10	MR. GALLAGHER: Pete, can you answer the
11	question?
12	MR. TAMBURNO: This is Pete Tamburno
13	again. The area was not smooth. There was pockmarks.
14	Certain areas were more had more general corrosion
15	and some areas were better.
16	MEMBER WALLACE: So you cleaned off the
17	smoothed it off?
18	MR. TAMBURNO: Yes, we cleaned off all the
19	corrosion by-products using hand tools and we also
20	inspected
21	MEMBER WALLACE: That's grinding is it?
22	MR. TAMBURNO: No, sir, we used hand
23	tools.
24	MEMBER WALLACE: Brushes?
25	MR. TAMBURNO: Brushes and that type of
ı	

1	thing and that was required because for the coating
2	application. We also did some inspection we did
3	inspections of all the areas that were noted to be
4	deep.
5	MEMBER ARMIJO: Did you keep photographic
6	documentation of the area after it was all cleaned up
7	so somebody could actually look at those pictures?
8	MR. GALLAGHER: Pete, photographic
9	documentation?
10	MR. TAMBURNO: Yes, we have some
11	photographs of the condition of the coating. We have
12	a video which we have presented to the NRC and we do
13	have some pictures from our most recent inspection
14	which was 2004.
15	CHAIRMAN MAYNARD: I think you were asking
16	a question about pictures of corrosion.
17	MEMBER ARMIJO: Yeah.
18	CHAIRMAN MAYNARD: You said pictures of
19	the coating.
20	MEMBER ARMIJO: Yeah, I just want to say,
21	when they did the cleanup and everything was all nice
22	and
23	MR. GALLAGHER: Precoating?
24	MEMBER ARMIJO: Yeah, precoating, they
25	document that and then

1	MR. GALLAGHER: Precoating, Pete?
2	MR. TAMBURNO: We do have a few pictures
3	of the vessel after cleaning of the corrosion
4	byproducts but before coating.
5	MEMBER ARMIJO: Okay, so there's some.
6	MR. GALLAGHER: So the embed area is what
7	we're talking about now. As I said
8	MEMBER WALLACE: This is what you used to
9	convince the NRC that using some sort of average was
10	okay and that the pock marks weren't too deep and all
11	that kind of stuff? These photographs are what you
12	used?
13	MR. GALLAGHER: Well, there was some data
14	from the outside, Pete, the exploratory data from the
15	outside?
16	MR. TAMBURNO: We took the inspection
17	after we removed the corrosion byproducts, we
18	performed a visual inspection of 100 percent of the
19	sandbed region and then we inspected through UT
20	measurements, the thinnest we found. We then
21	evaluated those thinnest areas in a calculation and
22	compared them to the results of the GE analysis.
23	MR. GALLAGHER: So the embed, the drywell
24	shell at the juncture of the concrete floor was sealed
25	with a silicone to prevent water intrusion going

1	forward into the embedded drywell shell. The
2	potential for corrosion of the inaccessible embedded
3	shell prior to this corrective action has also been
4	assessed. The water that was in the sandbed region is
5	not aggressive to concrete. Therefore, our assessment
6	is that the corrosion of the inaccessible embed shell
7	is not significant, since it is protected by the high
8	alkalinity in concrete.
9	MEMBER WALLACE: Well, it was corrosive to
10	steel. So once it got in there, it's going to eat its
11	way in further, isn't it?
12	MR. GALLAGHER: Ahmed.
13	MR. OUAOU: The embedded shell is
14	protected by the alkaline environment in concrete and
15	that
16	MEMBER WALLACE: And that counteracts the
17	corrosive activities of the water?
18	MR. OUAOU: That does not counteract the
19	corrosivity of water. The water was not corrosive.
20	In order for water to be
21	MEMBER WALLACE: I think it was corrosive
22	because the shell corroded.
23	MR. GALLAGHER: Yeah, we're talking about
24	the area at the concrete interface and below.
25	MEMBER WALLACE: It's the bottom of

1	MR. GALLAGHER: Yeah, and yeah, but
2	MEMBER WALLACE: Explain why this
3	corrosion couldn't go any further.
4	MR. GALLAGHER: Right, where it was
5	corroded was above that area where the wet sand was in
6	contact with
7	MEMBER WALLACE: You're convincing us it
8	didn't go any further.
9	MR. GALLAGHER: That's correct, not
10	significantly.
11	MEMBER WALLACE: You're convincing us not
12	significantly or no?
13	MR. GALLAGHER: No.
14	MEMBER WALLACE: It doesn't go
15	MR. GALLAGHER: That the corrosion would
16	not be significant.
17	MEMBER WALLACE: Verbal arguments or
18	something else?
19	MR. GALLAGHER: This is consistent with
20	the GALL of embedded
21	MEMBER WALLACE: GALL says it doesn't
22	corrode?
23	MR. GALLAGHER: Embedded seal in concrete.
24	If you meet certain criteria of the water not being
25	aggressive to the concrete, it does.

1 CHAIRMAN MAYNARD: Okay. 2 TAMBURNO: Can I just to make a comment, certainly the embedded portion -- do you have 3 4 the slide with the embedded shell, John, please? 5 MR. GALLAGHER: We have a cross-section of that area, showing the embed and a skirt, the drywell 6 7 skirt that's below it. MR. TAMBURNO: What this slide shows is 8 9 the sandbed, the area where we applied seal after 1992 and that shows, you know, the portion of the shell 10 11 that's embedded in the concrete and then you have a 12 for the skirt which is a support shell Certainly, we really can't say that 13 construction. 14 there's no corrosion in the embedded shell. 15 What we maintain is that the could be corrosion. corrosion should be less than in the sandbed region 16 17 because of the protection that the alkaline environment provides for the steel. 18 19 But in the case of the embedded shell, if 20 you look at the elevation 8 foot 3 and the bottom of 21 the sandbed is 8 foot 11, the corrosion should be 22 limited to that area, and of course, the skirt could 23 have some corrosion, but the skirt is not relied upon 24 as a support after the concrete was poured.

MEMBER SIEBER:

25

So this skirt goes 360

degrees around solid, so moisture would have to drill through that skirt to go under --

That's one of the points MR. GALLAGHER: we were trying to make is that the skirt does provide a barrier and if you look at the plate thicknesses, the plate thickness above, you know, where the skirt is and in sandbed regions is the 1.159 and then below that is where -- it's the thinner skirt, so we think that the -- because of, you know, the concrete as we described, that the corrosion in that area would be less significant than the corrosion that was experienced in the sandbed region and then we did the analysis assuming that plate was at thickness of .736. So we feel that's covered.

MEMBER ARMIJO: Just one thing; when you inspected that area right down where, you know, if you could install a seal, the silicone seal, you must have looked at it and was the corrosion worse or equivalent in that region right close to the concrete or was it less?

MR. GALLAGHER: Yes, Pete can answer that question.

MR. TAMBURNO: We did inspect that area during the repair activities in there and the corrosion in that area was no worse than -- than the

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	worst areas above it.
2	MEMBER WALLACE: That doesn't say very
3	much.
4	MR. TAMBURNO: So it was no better.
5	MEMBER WALLACE: It was no better, right?
6	MR. GALLAGHER: Yeah, so it was the same.
7	But there you would expect it to be similar because
8	the sand, the wet sand there was sand throughout so
9	the sand was contacting that. What we're saying is
10	below that interface, it would be less the
11	corrosion should be less significant because of the
12	concrete that's embedded in it.
13	MEMBER ARMIJO: And that's a debate,
14	right? That's an ongoing debate.
15	MR. GALLAGHER: Well, we think we're
16	consistent with the guidance that's in the GALL and
17	MEMBER WALLACE: You replaced the seal,
18	did you?
19	MR. GALLAGHER: We put that seal in.
20	MEMBER WALLACE: You put it in afterwards.
21	MR. GALLAGHER: Yes, this is the
22	corrective action.
23	MEMBER WALLACE: Okay.
24	CHAIRMAN MAYNARD: I'd like to move on
25	with the presentation.
ļ	

1 MR. GALLAGHER: Yes, sir. 2 MEMBER SIEBER: I'd like to ask, beyond, in our package the last slide you have is Slide 28. 3 4 You're referring to backup slides which should be made 5 part of the record. So -- okay. MR. GALLAGHER: Yeah, any slide we show, 6 7 we'll put in. MEMBER SIEBER: Okay, we'll I'd like to 8 have copies of this. 9 Yeah, I want to remind 10 CHAIRMAN MAYNARD: 11 everybody, we still have the staff's presentation 12 after this and we also have public comment time. want to make sure we get a chance to get through this 13 14 and we'll see where we need to come back to. 15 MEMBER WALLACE: I'm sorry, Mr. Chairman, 16 I'm responsible for this. I want to really know 17 what's going on though, I'm afraid, so I have to ask these questions, because the presentation doesn't tell 18 19 me unless I ask them, but I'll try to be brief. 20 GALLAGHER: Okay, so leaving the MR. 21 embed, the drywell shell in the sandbed region was 22 The coating that was applied was then coated. 23 application of a three-coat epoxy coating system 24 consisting of one coat of primer and two coats of

epoxy coating. Each coat was visually examined and

dry film thickness measurements were taken to assure the proper coating thickness was achieved. The coating is a two-part 100 percent solid epoxy coating which is less susceptible to the degradation and moist environments. The coating was tested to qualify for emersion surface coating applications such as tank linings. The surrounding environment has stable temperature conditions resulting in lower thermal stresses being applied to the coating and therefore, provides close to an ideal service environment which will result if a very long service life.

MR. BARTON: Do you have any idea how long that coating would be good for, the epoxy coating?

 $$\operatorname{MR}.$$ GALLAGHER: We can have Ahmed answer that question.

MR. OUAOU: There were some estimates done by our engineering and it varied from 10 years to 20 years. Recently we spent a lot of time talking to the vendor about the qualification of the coating and the feedback we're getting is that there is no guarantee for that coating, whether it is 20 years, 15 years, whatever. However, you can rely on your inspections to give you an indication whether you're approaching the end life of the coating. So the rigor inspection is the gauge as to when we think that coating is to

1	get replaced or repaired.
2	MR. BARTON: And the inspections are how
3	frequent, every 10 years?
4	MR. OUAOU: The inspection, we inspect
5	every fueling outage. We look at it basically every
6	refueling outage.
7	MR. OUAOU: Every other refueling outage.
8	MR. GALLAGHER: Our current program, and
9	I'll go into this, our current program which we do
10	there's 10 bays. We do two of the 10 bays every other
11	refueling outage and going forward, we're going to
12	insure we do 100 percent of the bays every 10 years.
13	MEMBER SIEBER: And what's your cycle
14	length, two years?
15	MR. GALLAGHER: Two-year refueling.
16	MEMBER ARMIJO: So it's every four years
17	you inspect two out of 10 bays?
18	MR. GALLAGHER: That's the current
19	program. Going forward, it will be a minimum of three
20	every other outage to insure that we cover the you
21	know, 10 bays.
22	CHAIRMAN MAYNARD: Do you have a criteria
23	that when you find degradation that you expand or you
24	increase your frequency or expand the number you look
25	at?
ļ	1

1	MR. GALLAGHER: Yes, Ahmed?
2	MR. OUAOU: Yes, in the future, we'll be
3	performing the ASME IEE inspections for the coating.
4	Which requires that if you perform an automatic
5	inspection, you look at the coating and you find
6	defects, you have to assess the other areas that you
7	looked at if you're doing a sampling. So if we do
8	find degradations, we would look at other areas in
9	accordance with our corrective action process.
LO	CHAIRMAN MAYNARD: And you have a criteria
L1	as to what constitutes degradation?
L2	MR. GALLAGHER: Yes, in the inspection
L3	program.
L4	MR. OUAOU: This is Ahmed. We do have
L5	criteria. We're using the criteria right out of the
L6	WE that's looking for blistering and flaking and
L7	cracking, et cetera, degradation of the coating.
L8	MEMBER WALLACE: This slide would benefit
L9	from numbers. If the first bullet said .74 and the
20	second bullet said .69 or something, it would help.
21	MEMBER SIEBER: Yeah, it sure would.
22	MEMBER WALLACE: Can you tell us what
23	those numbers are, what the shell thickness needs to
24	be and what it is? Are you going to tell us the
25	numbers?
J	I

1	MR. GALLAGHER: I told I said there's
2	various limits throughout for each plate and
3	specifically for the sandbed region, the minimum
4	thickness was .736 inches and the minimum that's
5	the minimum general. The minimum local is .49 inches
6	and we need those criteria. There's every plate
7	has a
8	MEMBER WALLACE: By how much do you meet
9	them?
LO	MR. GALLAGHER: The margins?
L1	MEMBER WALLACE: Yeah.
L2	MR. GALLAGHER: Pete, if you can answer
L3	the margin question.
L4	MR. OUAOU: This is Ahmed. Let me try to
L5	answer the question. I think giving you a number
L6	would be not easy and the reason for that is, is that
L7	there is a cylindrical region has a different
L8	thickness in the sphere than the sandbed regions.
L9	MEMBER WALLACE: Let's just talk about the
20	sandbed.
21	MR. OUAOU: The sandbed region, the
22	original thickness is 1.154 inches. The UT
23	measurements indicate that we have minimum of .80
24	inches and
25	MEMBER WALLACE: Average, yeah.

1 MR. OUAOU: Average, and the required for 2 stress to meet ASME requirements is .736. 3 remind you that those type of measurements are in two 4 bays. It does not reflect the entire sandbed region. 5 MEMBER WALLACE: Okay. MEMBER ARMIJO: You guys could really help 6 7 You submit good information in some of your On page 5 of your June 2th submittal, you 8 documents. 9 have a very good chart showing all the numbers for all the regions of the design thickness, minimum measured 10 thickness, required thickness and margin. You know, 11 12 maybe you've got a chart like that in your backup slides but it would save a lot of time if we just had 13 14 those numbers. 15 Yeah, we're sorry, we MR. GALLAGHER: 16 didn't present the numbers on the graph. We had, you 17 know, provided all those to the staff and they reviewed those in detail. So we were trying to just 18 19 give a summary. 20 I'm really puzzled when MEMBER WALLACE: I read the document though, because here it says, "The 21 assumed 22 that analysis conservatively the 23 thickness in the entire sandbed region has been 24 reduced uniformly to a thickness of .736 inches.

MR. GALLAGHER:

That's correct.

1	MEMBER WALLACE: Well, that's less than
2	the .80 inches you said.
3	MR. GALLAGHER: Right, that's
4	MEMBER WALLACE: Since we're just
5	teetering on the edge of what you need to make that
6	thing pass the code.
7	MR. GALLAGHER: The .736 is what the
8	analysis was run at so that's the minimum and the .8
9	is the lowest point we have. And so that's 64 mils
10	MEMBER WALLACE: The words say that you
11	assumed it had been reduced to this thickness.
12	MR. GALLAGHER: What was the input to the
13	analysis to come up with
14	MEMBER SHACK: That's sort of a limit to
15	find out how low they could go.
16	MR. GALLAGHER: That's correct.
17	MEMBER WALLACE: That's what it means.
18	MR. GALLAGHER: That's what it means.
19	MEMBER SHACK: You start with the 44
20	MEMBER WALLACE: What I assumed it meant
21	was that you measured .8 and you assumed to be
22	conservative, that it really could be .736. That's
23	not what you mean by this statement.
24	MEMBER SHACK: No, it means with a 44 psi
25	design pressure, he needs .736.
ļ	

1	MR. GALLAGHER: Right, right.
2	MEMBER WALLACE: That's what it means,
3	okay. It was confusing to me.
4	MR. GALLAGHER: And then the other point
5	I was trying to make about, you know, most of the
6	locations are well above that .8 and many of them are
7	close to the original plate thickness.
8	Again, I apologize for not providing that
9	table, but
10	MEMBER WALLACE: It's very strange that
11	you assume the answer. You assume .736 and then do
12	a study. I think you deduce .736 from the study.
13	MR. GALLAGHER: That was an input to the
14	analysis.
15	MEMBER WALLACE: And it showed everything
16	was okay?
17	MR. GALLAGHER: And then we showed that we
18	had the proper safety margins.
19	MEMBER WALLACE: But it doesn't down that
20	.70 might be okay, too, mightn't it?
21	MR. GALLAGHER: It could be, could be.
22	MEMBER WALLACE: Well, why didn't you vary
23	the thing and see where you get into trouble? Well,
24	you did. That's the .49 is that?
25	MR. GALLAGHER: .49 is a local minimum.

1	MEMBER WALLACE: Okay, how thin does it
2	have to be before we get into real trouble?
3	MR. GALLAGHER: How low can we go below
4	.736 average?
5	MEMBER WALLACE: Yes, yes.
6	MR. GALLAGHER: We have not analyzed that.
7	MEMBER WALLACE: You don't know? It might
8	be .735 or something. I mean, these are obvious
9	things to do.
10	MEMBER SHACK: No, no, he has to go back
11	and redo his design pressure calculations again, but
12	for 44 psi he can go to 736.
13	MEMBER WALLACE: He doesn't say that. He
14	said he assumed the answer and then said it was okay.
15	That's different from deducing it.
16	MR. GALLAGHER: It's probably poorly
17	worded, but the that's
18	MEMBER WALLACE: .736 was deduced from the
19	design pressure?
20	MR. GALLAGHER: That's the way we did the
21	analysis and Ahmed, he can
22	MR. OUAOU: If I may, this is Ahmed. I'd
23	like to explain how that .736 came about.
24	Essentially, the time that the analysis was done, the
25	measured thickness was .80 and because at that time

1	this is back in `81, sand has not been totally
2	removed, there was an estimate as to how much
3	corrosion we're going to have between now and when the
4	analysis run
5	MEMBER WALLACE: Yes.
6	MR. OUAOU: and somebody came up with
7	the idea, well, if we use .736 we ought to be
8	conservative.
9	MEMBER WALLACE: Yes.
10	MR. OUAOU: And that value was used to
11	come up with stresses and that satisfied ASME
12	requirements.
13	MEMBER WALLACE: So you did not deduce it
14	from a design pressure. You assumed it and found it
15	was okay.
16	MR. OUAOU: Well, yeah.
17	MEMBER WALLACE: So it may be that .65 is
18	okay. You just don't know.
19	MR. GALLAGHER: The minimum thickness
20	could be lower.
21	MEMBER WALLACE: I'm really puzzled. You
22	would really reassure the public if you would say,
23	"We've done the analysis and we show that this would
24	be good all the way down to .4". That would be great.
25	MEMBER SHACK: You mean with a 44 psi

1	design pressure I could go lower is what you're
2	saying.
3	MR. OUAOU: Not in the sandbed region, we
4	just said in sandbed region buckling controls so you
5	reduce the pressure to 44 or whatever number, that
6	will not change that. If the pressure had control,
7	that's true, but since the buckling controls
8	MEMBER SHACK: Okay, that controls the
9	thickness of
LO	MR. OUAOU: Exactly, exactly.
L1	MR. GALLAGHER: That's the way the
L2	analysis was done. We could you know, we could
L3	continue to do an analysis
L4	MEMBER WALLACE: The bottom line, they've
L5	got to get this straight, because this is your case,
L6	isn't it? You say we assume .736 to be conservative
L7	and we do an analysis at the reduced pressure for the
L8	containment.
L9	MR. GALLAGHER: Right, but like Ahmed said
20	it
21	MEMBER WALLACE: And then we show that
22	it's okay.
23	MR. GALLAGHER: Right, but like Ahmed said
24	the
25	MEMBER WALLACE: You have no idea how far

1	you are from it being not okay.
2	MR. GALLAGHER: Well, we know where we are
3	as far as the measurements we have and we have 64 mils
4	of margin to that .736.
5	MEMBER WALLACE: Well, when you do that
6	analysis, you come up with some critical stress or
7	something, X. And that's less than Y where it has to
8	be.
9	MR. GALLAGHER: Uh-huh.
10	MEMBER WALLACE: You must know something
11	about how different those are.
12	MR. GALLAGHER: We have the safety
13	factors, Ahmed?
14	MR. OUAOU: With that stress analysis and
15	as far as the sandbed region, the .736 is minimum
16	because using that thickness, using that thickness
17	stress limits you get in shell are those allowed by
18	the
19	MEMBER WALLACE: Now, they're just on the
20	borderline.
21	MR. OUAOU: They're very close.
22	MEMBER WALLACE: Okay, so you just
23	happened to hit the borderline.
24	MR. OUAOU: With the applicable safety
25	factors, exactly.

1	MEMBER WALLACE: That would help if you
2	had said that in the beginning. Okay.
3	MEMBER ABDEL-KHALIK: What is the
4	certainty band on the .8 inch measured value?
5	MR. GALLAGHER: Pete?
6	MR. TAMBURNO: Whenever we take the data,
7	we do make some uncertainty calculations based on the
8	number of data points. Typically, the uncertainties
9	on those numbers are somewhere approximately between
10	plus or minus 10 mils.
11	MEMBER ABDEL-KHALIK: Is this a 95 percent
12	confidence level?
13	MR. TAMBURNO: Yes, sir, with 95 percent
14	confidence.
15	MEMBER WALLACE: Would it be true to say
16	you have no margin then? You had .8 and then you
17	said, "Well, to be sure we'll assume it could be .736,
18	and when we calculate that, the stresses are found to
19	be right on the borderline of acceptability." That
20	means there's no margin except in this .736 being less
21	than .8. There's no margin in the calculated stress.
22	MR. GALLAGHER: The margin that we're
23	saying we have is 64 mils.
24	MEMBER WALLACE: Say that again, 64 mils?
25	MR. GALLAGHER: 64 mils.

1	MEMBER SHACK: The difference between .8
2	and 736.
3	MEMBER SIEBER: You arrived at that by
4	assuming a future corrosion rate.
5	MEMBER WALLACE: Well, that's what I said,
6	if you have these slides that talk about thickness
7	with margin, unless you tell us what the margin is, we
8	don't know anything at all.
9	MR. GALLAGHER: Right.
10	MEMBER WALLACE: That's why I'm being so
11	insistent about that.
12	MR. GALLAGHER: At this point in the
13	presentation, we're talking about the corrective
14	actions.
15	MEMBER WALLACE: Yeah, I know, but
16	MR. GALLAGHER: And what I'm saying is
17	going forward in the sandbed region, we've determined
18	that the corrosion was arrested and so and we put
19	the coating on. So the visual inspections we
20	performed on the coating verified that no ongoing
21	corrosion is taking place. So we are, you know, flat-
22	lined in the sandbed region as far as corrosion and
23	just, you know
24	MEMBER WALLACE: I have to decide whether
25	or not deducing stresses which are on the borderline

1	of acceptability is okay? Is that what I'm asked to
2	decide?
3	MR. GALLAGHER: I guess I don't understand
4	your concern because
5	MEMBER WALLACE: Well, I understand it
6	very well.
7	MR. GALLAGHER: The as with any
8	analysis, you have you determined what the minimum
9	and there will be safety factors with that. So with
10	the appropriate safety factors, we're saying we need
11	to be above .736. We've said that
12	MEMBER WALLACE: You just make it, right?
13	MR. GALLAGHER: Well, there's 64 mils of
14	margin and the corrosion has been arrested.
15	MEMBER WALLACE: 64 mils of margin, that's
16	pretty
17	MR. GALLAGHER: The corrosion has been
18	arrested and it's coated
19	MEMBER WALLACE: Because it's .8, okay.
20	MR. GALLAGHER: And it's coated.
21	MEMBER WALLACE: Well, I thought you were
22	saying .8 might not be really accurate, so we'd assume
23	it's .736. Okay.
24	CHAIRMAN MAYNARD: Well, the code has some
25	conservatism in it, too, does it not?
	I and the second

1 MR. GALLAGHER: Yes, the safety factors 2 that we have in there. 3 MEMBER BONACA: Yeah, the concern I have 4 is not the specifically but at some point you'll 5 address it too, I imagine. You made other commitments regarding corrective actions and mitigative actions 6 7 and so on as a -- and then, you know, at the same time 8 as you make these commitments in writing and that are 9 reported in the SER, you had water in jugs out there 10 and you didn't even test it as you were supposed to 11 Could you tell us about that? I mean, I'm still do. left with this question, 12 are we talking hypothetical things or are we talking about what's 13 happening out there? How can we trust a program that 14 15 you claim was in place since 1990s and then it wasn't in place when the inspection occurred? 16 17 MR. GALLAGHER: Yeah, do you want me to address that issue right now? 18 19 CHAIRMAN MAYNARD: Might as well, yes. 20 MR. GALLAGHER: Okay, so as far as the water in the bottles, let's step back and talk about 21 22 that for a minute. First of all, our overall program 23 which I haven't got into yet on the initial aging 24 management program, relied on monitoring UT's in the

drywell area for the corrosion rate, to determine the

corrosion rate and we determined these corrosion rates were very low and then our ongoing coding inspections. So we have, you know, fulfilled our commitments associated with managing the aging and the drywell.

Now, the water monitoring, we should have been performed more rigorous water monitoring and one of the things we identified when we were developing our commitments for implementation for the license application, was that we had not renewal rigorously performing the water monitoring. of this year, when we did a walk-down of the torus rim from those sandbed drains, as we described there's five sandbed drains. There's tubing that goes from those sandbed drains to these water jugs, they're like five-gallon water jugs. There was some water in there. We believe that water is very old and we believe that if there was any active leak, which we verified at the time that there was no active leak, the tubing was dry and that type of thing, if there was an active leak, incidental observation would have identified that as a concern and then we would have taken corrective action.

MEMBER BONACA: But you have no --

MR. BARTON: But you're telling us that nobody observed water that's been there for a long

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

time in the torus area that's collecting water from the sand pocket drains, right, and nobody paid attention to that or said, "Why is there water in here"? I mean, you're saying it's old water. So for a long time nobody gave a hoot about this commitment.

MEMBER BONACA: And what bothers me is here you have, you know, the shell is down to minimum margin, okay, and I grant it from you. I'm not going to question this point. And so you would want to see most aggressive actions to preserve the margin which means delivering only commitments which says if there is water, we're going to remove it within three months and so on and so forth.

Furthermore, I mean, you don't have record of whether or not used a strippable tape. So you're still not dealing with the source of the whole problem which is these cracks up there in the refueling cavities. So I'm saying, since you haven't done it yet, why am I to believe that you'll do it in the future once we -- once you get to the operating license for 20 more years? I mean, that's an important issue.

MR. BARTON: And also, isn't it standard practice if you see water someplace in a container on the floor or something that you sample it and see

1 where the hell the source is from before you throw it 2 away? That would have been 3 MR. GALLAGHER: 4 helpful. In this case --5 MR. BARTON: Would have been helpful? Ιt should have been required. I mean, what kind of 6 7 practices do we got at this site these days where you 8 have something like that and people get rid of it and 9 nobody cares about what it is or where it came from. That doesn't tell me a hell of a lot about what's 10 going on at this site cultural-wise. 11 12 MR. GALLAGHER: Yeah, the thought process behind removing the water was to determine if there 13 14 was actively leakage going on. As far as commitments, 15 I can give you to Tim Rausch, he's our Site Vice President and later on in our presentation, we do have 16 17 how we've, you know, tracked commitments, what we do now, and how we insure they get done. 18 19 MR. RAUSCH: Yes, good afternoon. 20 Rausch, Site Vice President. In response to the 21 question regarding the commitments and the integrity 22 of meeting those commitments, there was a period of 23 time in a transition of the station, in terms of 24 ownership and the commitments were not rigorously 25 upheld during that period of time.

1	MR. BARTON: They weren't what?
2	MR. RAUSCH: They were not followed
3	through on.
4	MR. BARTON: You make a commitment to the
5	NRC. You've got a commitment tracking system and you
6	ignored it.
7	MR. RAUSCH: Yes, the commitment tracking
8	system for the particular commitment regarding the
9	water into the bottles and the monitoring of that was
10	a deficiency on our part in terms of the performance
11	and we acknowledge that in the exit of that AMP
12	exit that was conducted several weeks ago. So the
13	commitment that we have going forward is this company
14	has a formal commitment tracking system. It's
15	automated with backup barriers to insure that those
16	commitments are, in fact
17	MR. BARTON: Is that a brand new system?
18	MR. RAUSCH: Well, it's not brand new but
19	it is an excellent system that is being implemented.
20	MR. BARTON: What happened to the old GPU
21	commitment tracking system? Did you throw that out?
22	MR. RAUSCH: No, sir.
23	MR. BARTON: Well, wasn't it in that
24	commitment system was well?
25	MR. GALLAGHER: This if I can answer
ļ	

1 that, Mr. Barton, the specific commitment was in 2 correspondence. 3 MR. BARTON: Right. MR. GALLAGHER: And we have not found any 4 5 specific implementation document that implemented that commitment from after it was made by GPU in the early 6 7 `90s. BARTON: So nobody took that 8 MR. 9 correspondence from the NRC and put it in the 10 commitment tracking system. MR. GALLAGHER: That's what it looks like 11 12 and now, we know that it was done and it was done by the project personnel assigned to that and it was done 13 14 for a long period of time. I think it was one of 15 those things that was owned by, you know, high ownership and they just did it but it was not embedded 16 17 in any, you know, rigorous process. Right now, we have it as a specific preventative maintenance task 18 specifically scheduled and it will get done and it's 19 been done five times to date and there's been no water 20 21 detected in those drains. 22 Well, I mean but, you MEMBER BONACA: 23 know, the commitments report in the SER were in response from you on June 20 th of this year and the 24

findings from the inspections that defeat those

1 commitments were in September. 2 MR. GALLAGHER: The inspection actually 3 was in March and we had, ourself, identified this 4 water issue in the bottles. 5 MEMBER BONACA: All right, I didn't --And it was during the 6 MR. GALLAGHER: 7 inspection in March also and the inspection exit was 8 not until September. 9 MEMBER BONACA: All right. 10 CHAIRMAN MAYNARD: I know the questions are important. I would like for you to go ahead and 11 12 get through your presentation. We also have the staff to question on a number of these things as to why do 13 14 they find some of these things acceptable and if need 15 be, we can bring the licensee back up here and --16 MEMBER WALLACE: Let me tell you what I'm 17 thinking. I've asked myself the question, are these folks ready to go forward to the full committee. 18 19 don't always do that. This is a subcommittee, right? 20 CHAIRMAN MAYNARD: Right. 21 MEMBER WALLACE: We don't always recommend 22 that they are ready to go forward. It's not as if the 23 schedule has to be always met. So you have to develop 24 some credibility. So I guess that's what I'm after

here is getting enough credibility to go forward.

1	That's why I'm asking these questions.
2	CHAIRMAN MAYNARD: And I fully understand.
3	MEMBER WALLACE: If I don't have it, I'm
4	going to have to say, I'm going to have to have
5	another meeting or something. So that's why I'm
6	asking.
7	CHAIRMAN MAYNARD: I fully understand that
8	and that may be one of the options, you know. Again,
9	we won't end this meeting until we've either got the
10	questions answered or that we
11	MEMBER WALLACE: Yeah, you want to see
12	more of what they have to say.
13	CHAIRMAN MAYNARD: Right, or we may very
14	well determine that we need another subcommittee
15	meeting before trying to go to the full committee. I
16	would not recommend going to the full committee until
17	we've
18	MEMBER WALLACE: I've looked at the rest
19	of the slides. I think they can move quickly.
20	CHAIRMAN MAYNARD: Yeah, if we can get
21	through theirs and also the staff's and hear the
22	public, then I think we'll be in a better position to
23	make some of those determinations.
24	MR. RAUSCH: Mr. Chairman, may I just
25	finish the comment in terms of the commitment. The

company of Exelon/Amergen understands how the commitment was met at this time and it has taken corrective actions to insure that doesn't happen again in terms of addressing the question of how can we feel confident going forward that we won't have a similar occurrence. Thank you.

MR. GALLAGHER: Okay. I believe we're on Slide 15 now, which --

MEMBER SIEBER: Before you escape from this slide, I do have a question. You talk about taking UT measurements, thickness measurements of the shell. And it was stated that the corrosion of the shell was not uniform and, therefore, when you take individual point measurements, even in a grid or the thousand measurements that you talked about on the previous slide, there is some probability that there is a thinner place than what you've measured. And so, just assume that here's the minimum can't thickness I can tolerate to withstand the pressure of the -- the accident pressure. You have to have some margin that's statistically based between your minimum measured thickness and the minimum or the minimum allowed thickness for the pressure. Have you done that work and has the staff reviewed it?

MR. GALLAGHER: Pete?

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. TAMBURNO: Yes, we've done that work.
2	We've taken the data for the upper regions and applied
3	a 95 percent confidence intervals on the data and also
4	in the sandbeds.
5	MEMBER ABDEL-KHALIK: How about the
6	embedded region?
7	MR. TAMBURNO: The embedded region has not
8	been inspected.
9	MEMBER ABDEL-KHALIK: So do you have
LO	confidence that the thickness in that region will be
L1	greater than .8 inches?
L2	MR. OUAOU: This is Ahmed with Exelon. We
L3	have confidence that the corrosion incentive bed
L4	region and the embedded region it will not be greater
L5	than the sandbed region itself. And since we use the
L6	same analysis and the same minimum thickness, we
L7	believe that balance the potential of having corrosion
L8	in the embedded region. And
L9	MEMBER ABDEL-KHALIK: Where does your
20	confidence come from?
21	MR. OUAOU: We have consulted with
22	corrosion experts. We looked at the environment that
23	the embedded shell is going to be subjected to. Based
24	on that, our consultants indicated that the corrosion
25	in the embedded shell will not be greater, should not

be greater than the sandbed region area.

MEMBER SHACK: Well, that's certainly true from when you had active ongoing corrosion in the sandbed. You know, I'd fully accept that argument that it would be less. Now, that you've arrested the corrosion in the sandbed, what's your assurance of the environment within there. That really comes down to the integrity of the silicon seal.

MR. OUAOU: And in response to that question, we agree with you. The fact that the seal itself now protects the embedded shell. We inspect the seal with we inspect the coating mixture of that it is not cracked or it is not damaged such that any potential moisture will get in the embedded shell.

MEMBER SHACK: And there's no other access path for water to that embedded region.

MR. OUAOU: No.

MEMBER WALLACE: This 95 percent confidence seems to me an important issue. If you do a statistical analysis, it should be part of your presentation. It's a good piece of evidence and it should be there. We shouldn't have to drag it out of you and it should be explained fully so we know what it was. Is it a confidence that the thickness is bigger than .736 where there's 95 percent probability

and blah, blah, or is it bigger than .72 or what it is? Give us the numbers, otherwise it's all vague.

MEMBER ARMIJO: Well, I'd like to add that your Table 1 in your June 20th letter to the NRC shows that in the embedded region you have almost three times as much margin for the lower sphere even if you assume that that region which you couldn't inspect, corroded down to .8 inches. And you know, again, beating a dead horse on this table, but this table is very informative. I got a lot out of it. I wish we could all have had it in the presentation.

MR. GALLAGHER: Okay, a point well-taken.
We'll -- I again apologize for not having that in there.

Okay, if we could move onto Slide 15 then, which at this point in the presentation we've put the corrective actions in place and then after the corrective actions were implemented, the effectiveness was then determined. And we took UT thickness measurements in 1992 and again, in 1994 in the sandbed region and confirmed that the corrosion in the sandbed region had been arrested. UT measurements were also taken in 1996. However, there were some anomalies in this data. In some cases, the values were greater than previously measured.

We investigated this and determined that the most likely contributor is attributed to not removing a protective grease coating prior to taking the measurements. Corrective actions are in place to prevent this from happening in the future. These sandbed UT measurements will be performed in the refueling outage that begins this month.

Also at this time to verify effectiveness, we did the coating inspections of the applied coating to the sandbed region and that was visually examined and determined to be acceptable. Ιf we go to Slide 16, so now we're at the stage of our initial aging management program. And the initial aging management program established that was primarily consisted drywell of the upper UT measurements and the sandbed region inspections. The UT measurements in the sandbed region were discontinued because the corrosion was determined to be arrested and since the sandbed region was now accessible, the visual inspections of the coating were determined to be a more effective inspection.

Every other refueling outage, the upper elevation UT measurements have been performed. These measurements are verified to be greater than the

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

minimum required plate thickness and a corrosion rate is projected to verify the acceptability of continued operation. The results indicate that there's no ongoing corrosion at the two elevations and that the corrosion rate for the other three elevations are less than one mil per year. The service life of the drywell extends well beyond 2029 with margin. MEMBER WALLACE: Is this all based on some sort of statistics or just measurements? MR. GALLAGHER: Pete? MR. TAMBURNO: It's based on the 95 percent confidence intervals around the curve fit of the data. MR. GALLAGHER: Since the exterior surface of the supper drywell is not accessible, these UT's were continued. Additionally since the exterior surface of the drywell shell above the sandbed region is not epoxy coated, the corrosion rates identified are the leading indicators of corrosion overall in the drywell. The coating applied to the sandbed region of the drywell shell exterior has also been visually examined, two of the 10 bays have been examined every

other refueling outage. Some of the bays have been

examined multiple times because those bays contain the

thinnest shell locations.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

A total of five of the 10 bays have been inspected to date. All coding inspection results have been satisfactory. When we get into our future program I'll show you that we are going to look at those other five bays and then again all 10 bays every 10 years. Next slide.

As part of the preparation of the license renewal application and subsequent NRC review, the drywell shell aging management program has been enhanced. The following are the key elements of our aging management program. Amergen will continue to apply the strippable coating on the reactor liner, reactor cavity liner each refueling outage prior to filling the reactor cavity with water. We will also insure that the reactor cavity trough drains are clear. These actions will eliminate water intrusion into the sandbed region.

Sandbed drain leakage monitoring is performed quarterly during non-outage periods and will be performed daily during the refueling outage when the reactor cavity is filled with water. These are the more rigorous inspections that I'm telling you we have now through our preventative maintenance tasks. Corrective actions will be taken if further water leakage is identified. The upper drywell shell UT's

1 will continue to be taken every other refueling 2 outage. Again, these measurements are the leading 3 indicator of -- for corrosion, overall corrosion in 4 the drywell. 5 Amergen will perform periodic confirmatory UT inspections of the drywell shell in the sandbed 6 7 region. The UT measurements will be taken prior to entering the period of extended operation and then 8 9 after four years. After confirming that the sandbed 10 region corrosion continues to be arrested, 11 frequency would then be extended to 10 years The NRC will be notified within 48 hours 12 thereafter. of any unexpected results and corrective actions will 13 14 be taken. 15 If the coating fails right MEMBER SIEBER: after you do an inspection, how long will it take for 16 corrosion to take you below min wall, four years, or 17 have you done that? 18 19 MR. GALLAGHER: Pete, did you get the 20 question? 21 MR. TAMBURNO: This is Pete Tamburno. At 22 the current projected corrosion rates that we've seen 23 in the upper regions, a four-year -- it would take 24 much longer than four years. 25 MEMBER SIEBER: Even uncoated?

	91
1	MR. TAMBURNO: Yes, sir.
2	MEMBER BONACA: How do you justify 10
3	years?
4	MR. GALLAGHER: The 10-year inspection
5	rule for the coating?
6	MEMBER BONACA: Yeah.
7	MR. GALLAGHER: Ahmed?
8	MR. OUAOU: The 10-year inspection of the
9	coating is based on ISI ASME Section 11 but I think
10	one thing that's important to mention is that we are
11	actually doing or staggering the inspections during
12	refueling outages such that we've been looking at
13	three, I believe
14	MR. GALLAGHER: Right, a minimum of three
15	bays every other outage.
16	MR. OUAOU: minimum of three bays every
17	other outage.
18	MR. GALLAGHER: For the sandbed region
19	coating prior to the period of extended operation
20	Amergen will perform a visual inspections of epoxy
21	coating of the five bays that have yet to be
22	inspected.
23	MEMBER SHACK: I hate to interrupt. How
24	extensive is this inspection going to be before you
25	enter the period of extended operation? You look at

1	all the bays?
2	MR. GALLAGHER: There's five bays that we
3	have not yet inspected. We were going to look at all
4	five of those and with our inspection program.
5	MR. BARTON: This outage?
6	MR. GALLAGHER: We are doing them this
7	outage. The commitment is prior to the period of
8	extended operation.
9	MR. BARTON: So not much time.
10	MR. GALLAGHER: We have to start this
11	month.
12	MEMBER BONACA: So, really, I mean, you
13	have some substance there. I mean, you don't know
14	what you're going to find.
15	MR. GALLAGHER: We've based on the
16	inspections we've done before, the coating has been
17	you know, satisfactory. In addition, as I said, we'll
18	inspect 100 percent of the epoxy coating every 10
19	years during the period of extended operation. So
20	Slide 18.
21	So our overall conclusions on the drywell
22	corrosion at Oyster Creek are, the corrective actions
23	to mitigate the drywell shell corrosion have been
24	effective, the drywell shell corrosion was arrested in

the sandbed region and continues to be very low in the

1	upper drywell elevations. The service life of the
2	drywell shell extends beyond the year 2029 with
3	margin. And we have an effective aging management
4	program to insure continued safe operation.
5	MR. BARTON: This every 10 years is only
6	going to get you one inspection during your extended
7	period of operation.
8	MR. GALLAGHER: For which
9	MR. BARTON: In drywell region, drywell
10	coating visual every 10 years, it gets done in 2009,
11	are you going to do in 2019, 2029, you're done, you
12	weren't going to do one anyhow. So you're going to do
13	one of them in 20 years.
14	MR. GALLAGHER: Are you talking about the
15	coating inspection, sir?
16	MR. BARTON: That's what is says here.
17	MR. GALLAGHER: Okay, what we're doing is,
18	Ahmed had mentioned, we are staggering the
19	inspections, so every other outage, we're going to do
20	at least three bays.
21	MR. BARTON: And every 10 years, you're
22	going to have done
23	MR. GALLAGHER: 100 percent, yes.
24	MR. BARTON: 360 degrees.
25	MR. GALLAGHER: That's correct. So we'll

1 do it twice in the period of extended operation. 2 MR. BARTON: I gotcha now. 3 MR. GALLAGHER: Okay. MEMBER WALLACE: I think it's flexible. 4 5 If you found some problem with the three bays, you might then go back and inspect some more bays. 6 7 MR. GALLAGHER: That's correct. If we 8 find a problem, we would have to do an extended 9 condition and we would increase our inspections. 10 CHAIRMAN MAYNARD: That's what I'd asked about earlier is criteria for if we find something, 11 12 expand and more frequent --MR. GALLAGHER: We've also -- I've just 13 14 given you some of the key issues -- key commitments in 15 our aging management program. There's also other ones particularly if we did find water say in the water 16 drains, we would do further inspections of the 17 coatings from those bays. So there's other features 18 19 in our program you know, to insure that issues that 20 are not expected are pursued and evaluated. This slide, Slide 19, shows the five open 21 22 items from the Draft Safety Evaluation Report and to 23 close the first item we are committing to additional 24 inspection locations at the two plate transitions on 25 the shell and so this will be a total of four.

1 one inspection for each of these transition plates. 2 We are going to increase that to four locations at 3 each of these two plate transitions and we will be 4 submitting additional correspondence on this issue. 5 Based on discussions with the NRC staff, we believe no additional information is needed from 6 7 Amergen on the other four items. So that concludes 8 the drywell corrosion. Are there any more questions 9 on the drywell corrosion before we go onto the rest of the presentation. I'll ask the Chairman if --10 CHAIRMAN MAYNARD: We may have some more 11 12 What I'd like to do is get through the questions. We'll have a number of questions for 13 presentation. 14 the staff, and I'm -- as long as Amergen is staying 15 here, then after the presentations, if we have 16 additional questions at that time, we can come back to 17 some issues. Okay. All right, so I'll 18 MR. GALLAGHER: 19 now turn it over to Fred Polaski who will discuss some 20 of the key historical equipment issues and how they're 21 addressed and the results of our license renewal 22 application. MR. POLASKI: Thank you, Mike. 23 I'd like 24 to briefly discuss the history and status of other 25 equipment problems significant plant that have

occurred at Oyster Creek. All of these issues are well-understood and ongoing activities monitor these issues as part of the Oyster Creek Corrective Action First of all, what I'd like to talk about is the core shroud. In 1994, a significant circumferential crack was identified in the H4 weld. Ten tie rods were installed to provide full structural repair for the horizontal welds. Since then inspections have not detected any significant indications or cracking in the shroud.

In 1978 a crack was identified in one of In the upper sparger there the core spray spargers. was a 180-degree crack around the circumference of the A mechanical clamp was installed. subsequent refueling outages multiple indications were observed and nine additional clamps were installed for And of these 10 four of them were on a total of 10. they're all all of the boxes clamped. Т and Subsequent inspections and testing indicated there really are only two confirmed indications that result in leakage through the dispargers. The root cause was determined high residual to be stress from installation of dispargers.

In 1991 a crack was observed in the top guide of the reactor vessel. Subsequent inspections

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	identified further cracking and in 1996, a 100 percent
2	UT examination was performed of the top guide and
3	confirmed that there's six cracks in the top guide.
4	Metal samples confirmed that the reason for the
5	cracking was a radiation assisted stress corrosion
6	cracking. These cracks are monitored during refueling
7	outages and no new growth has been observed since the
8	year 2000.
9	MEMBER SHACK: And your water chemistry
10	is?
11	MR. POLASKI: The chemistry is good and
12	it's hydrogen water chemistry since 1992.
13	MEMBER SHACK: With noble metal or just
14	MR. POLASKI: Noble metals in 2002.
15	MEMBER ARMIJO: Do you attribute the lack
16	of new IGSCC cracks to the water chemistry?
17	MR. POLASKI: Water chemistry is a major
18	influence on IGSCC cracking. With the proper water
19	chemistry you shouldn't have any IGSCC. And getting
20	ahead a little bit but I'll cover this, that the
21	hydrogen water chemistry implemented at Oyster Creek
22	is greater than 99 percent availability during the
23	last cycle. The injection rates are such that they
24	obtain a molar ratio of four to one. BWR VIP
25	recommends at least three to one, so four to one is
	II

1	even better than that.
2	MR. BARTON: So you're telling me there
3	isn't even enough hydrogen to even protect the upper
4	core components because this is where this is, right?
5	MR. POLASKI: Yeah, but these cracks were
6	found back in 1991.
7	MR. BARTON: Right.
8	MR. POLASKI: And we didn't start hydrogen
9	water chemistry till 1992.
LO	MR. BARTON: But you found there was
L1	initially one and then you found some more?
L2	MR. POLASKI: Found some more.
L3	MR. BARTON: Still in `91?
L4	MR. POLASKI: Well, up through `96 was
L5	when they confirmed that there were six. Some of them
L6	could have been there earlier.
L7	MEMBER SHACK: This could be inspection
L8	transients, yeah.
L9	MR. POLASKI: Yeah, I mean, initially it
20	was visual inspections where you happen to be able to
21	see them. In `96 it was 100 percent UT examination
22	that confirmed there was only six.
23	MEMBER SHACK: All right.
24	MR. POLASKI: And during outages, they go
25	hack in and look at some of the gracks every outage

1	and no additional growth in the last you know,
2	since 2000.
3	MEMBER ARMIJO: Do you have a noble metal
4	monitoring system?
5	MR. POLASKI: Noble metals are injected in
6	2002. There is a hydrogen water chemistry monitoring
7	system.
8	MEMBER ARMIJO: So you measure potential
9	and
10	MR. POLASKI: Yeah, you measure potential
11	to keep your minus or less than minus 230 millivolts.
12	The next thing I wanted to discuss was CRD
13	stub tubes. Two of them were found to be leaking in
14	2000. They were repaired by and this was observed
15	during the hydrostatic tests at the end of the
16	refueling outage. They were repaired by performing a
17	roll expansion of the CRD housing. They're inspected
18	every outage when the drywall is accessible and no
19	subsequent leaks have been observed.
20	MEMBER SHACK: Just my own curiosity and
21	how reliable is your ECP measuring system? What's its
22	online availability?
23	MR. POLASKI: I'm going to ask Marsha or
24	Terry Schuster to answer that.
25	MR. SCHUSTER: Terry Schuster, Chemistry

and Environmental Manager for Oyster Creek Station.

The ECP probes are continually available in the Bravo recirculation loop. Our measured millivolt reading is minus 400 millivolts for the ECP probes and that is lower than the expected minimal value of minus 230 millivolts and that has been consistently the case for the entire cycle.

MEMBER SHACK: This is copper, copper oxide?

MR. SCHUSTER: I'm sorry, I don't know the makeup of the probe but it is available and it measures good results continually.

The other reactor vessel and MR. POLASKI: thermo component I just wanted to briefly discuss was the steam dryer. I know that's been an issue in previous license renewal applications. Oyster Creek inspections have identified some minor cracking. However, it's not been extensive and been repaired. The Oyster Creek steam dryers are a different design than the one at Quad Cities and Dresden. It's a more robust design. There have been no power uprates performed at Oyster Creek and none are intended so we don't have any of the flow problems and vibration problems that they had at Quad Cities and we don't believe it's going to be an issue for license renewal.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 MEMBER SIEBER: Is it in scope? 2 MR. POLASKI: Yes, it's in scope. And we 3 will be implementing the BWR VIP inspections on it but 4 don't expect any problems with it right now. and I already talked about 5 other thing is too, chemistry in noble metals. 6 hydrogen water 7 implementing inspection procedures for the reactor vessel internals are all done in accordance with the 8 9 BWR VIP program, so we're following that program. The next thing I wanted to talk about, a 10 11 total different subject, medium voltage electrical 12 There have been a history of failures of cables. these cables in wetted environments at Oyster Creek. 13 14 Most was determined to be susceptible cables due to 15 design insulation type and manufacturing issues. 16 Presently replacement cables that we're using are Okenite EPRI cables which are designed for wetted 17 environment conditions. We've had no failures of 18 19 these type cables since they've been installed. 20 And in the refueling outage later this 21 fall, the four known susceptible cables are going to 22 be replaced with Okenite EPRI cables. MR. BARTON: And this cable can withstand 23 24 a wet environment, the new one? 25 The new ones, let me just MR. POLASKI:

1 double-check, Dan Barnes or Debby, are these in wetted 2 environments? Yes, the answer is that these four are 3 in wetted environments. 4 MEMBER BONACA: They're qualified for it. 5 MR. POLASKI: Pardon? The replacements are 6 MEMBER BONACA: 7 qualified for wetted environment. 8 MR. POLASKI: Yes, they're designed for 9 wetted environments. 10 We've performed continuing testing of cables and we have two types of testing we do. For 11 accessible shielded cables, we do online partial 12 discharge testing. And for cables that are either 13 14 unshielded or not accessible to be tested while 15 they're online, we do step voltage and power factor testing when the lines can be determinated. 16 17 CHAIRMAN MAYNARD: I noticed, it looked like for your inaccessible or underground medium 18 committing to 19 voltage cable, you were 20 methodology that hasn't been approved yet but you anticipate it being approved before the period of 21 22 extended operation. 23 MR. POLASKI: What we committed to in the 24 application was an aging management program that's consistent with the GALL program. We have a vendor

1	that we've been using for several years to do testing
2	and that methodology has been submitted to IEEE and is
3	going through reviews right now. We believe it's
4	going to be an acceptable method to go forward in the
5	period of extended operation and we've used it and it
6	has indicated degradation of cables and that's been
7	confirmed in one or two cases when the cables have
8	been replaced.
9	CHAIRMAN MAYNARD: I'll save the rest of
10	mine for the staff when they get to acceptability.
11	MR. BARTON: Has there been any work done
12	on site to either minimize or eliminate the water
13	intrusion into the conduct system?
14	MR. POLASKI: Well, one thing that has
15	been done is some of the cables have been rerouted so
16	they're not in locations that would be susceptible to
17	water and that's really about the only thing you can
18	do where you've got cable that's in conduit
19	underground. I mean, there's no way to prevent water
20	from getting into that conduit.
21	MR. BARTON: So you have rerouted some of
22	those.
23	MR. POLASKI: We have rerouted some of
24	those, but not all of them.
25	MR. BARTON: Do you intend to reroute the

1 rest of them or are you going to rely on the Okenite 2 cable? MR. POLASKI: Right now, the plan is to 3 4 rely on mainly the Okenite and the ongoing testing 5 where we should be able to detect any degradation, I mean, because this cable testing is designed to look 6 7 for water issues and detect it, see it coming and be 8 able to replace it in time before it would fail. 9 Or it bows, okay, thank you. MR. BARTON: 10 MR. POLASKI: Any other questions on that? The next topic, I'd like to discuss is 11 Okay. underground piping. There have been leaks in 12 underground piping at Oyster Creek due to salt water 13 14 corrosion from the inside of the pipe after failure of 15 the internal coatings. We've not have any failures from age-related degradation of the external coatings 16 17 of this piping. MR. BARTON: Wait a minute, hasn't there 18 19 been any failures of water piping from coatings 20 deteriorated during installation? MR. POLASKI: There was one with a problem 21 22 with installation problem of the coating but none of 23 that's been age related where it's degraded over time. 24 that one was fully investigated and it 25 installation problem determined to be an that

1	occurred.
2	MR. BARTON: And hopefully that's the only
3	installation problem that that piping coating was
4	damaged, all right.
5	MR. POLASKI: The only way to determine if
6	there's any other ones is to dig it all up and look.
7	MR. BARTON: I know you can't do that, I
8	understand that.
9	MR. POLASKI: That probably would cause
10	more problems than if you'd just leave it alone.
11	MR. BARTON: I understand that. In your
12	underground piping program, though, is the diesel
13	transfer piping from the main storage tank to the
14	diesel generator building included in that program,
15	because I couldn't find reference that that was or
16	that fire protection piping was included?
17	MR. POLASKI: I'm going to ask Pete
18	Tamburno to answer that question.
19	MR. BARTON: The one that had a leak in it
20	years ago.
21	MR. TAMBURNO: This is Pete Tamburno.
22	We're replacing the diesel fuel transfer line
23	presently. Right now, the project is about 70 percent
24	due and 70 percent complete and it should be done

by the end of the year. The fire protection system

has been added to the program and will be inspected as part of our license renewal commitments.

MR. POLASKI: Thank you, Pete. wanted to continue on was the site has an existing ongoing underground piping program that was in place before we started to prepare the license renewal application, where they've looked at all the underground piping and which is the most significant and risk impact to the plant. They have replaced 50 percent of the underground safety-related emergency service water piping and the remainder will be replaced prior to entering the period of extended The non-safety related service water operation. piping is being replaced with a phased plan as part of this underground piping program.

at the plant that enhanced as part of the license renewal process to inspect all the in-scope buried piping before we enter the period of extended operation. In summary, we believe that our existing aging management programs have been successful in managing aging for these issue and will be continued into the period of extended operation and will be successful for the next 20 years.

Slide 21. Our license renewal application

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

was submitted July 22nd, 2005. In the time period preparing that license when were application, I realized in my work with NEI licensure task force and interfacing with the NRC that the NRC was revising the Standard Review Plan in the GALL report and that the new versions of that would be issued in September 2005 and would be used by the staff for their review of the application. And I was concerned that if we prepare the application using rev 0 of the GALL and standard review plan, which were approved in 2001, that there would be a large number of differences identified during the review by the staff.

So we discussed this issue with the staff and obtained their concurrence that for preparation of the Oyster Creek application, we would use the draft revision 1 of the GALL and the Standard Review Plan which were issued in January of 2005 and the NRC expected that there would be few changes between the draft and the final versions of rev 1. We also, in preparation of the application, used NEI 95-10, the guidance document and we used the latest revision on that. Ultimately, we're using rev 6, which was issued in June of 2005.

This approach worked well for us and for

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

the NRC. After rev 1 was issued, we performed a reconciliation of the final version versus the draft. changes looked for and additions to management programs. We looked at the GALL line items to determine if there were any of those that changed from the ones we'd used for Oyster Creek, any had been deleted or whether there was any new line items that we would have used if it had been available when we prepared the application.

The result of that, we identified that four new inspections or enhancements to existing inspections were needed. There was five new exceptions to programs which we reconciled and actually two of the exceptions we had identified in the application was eliminated because of the update to the application. So overall, very few changes were needed as a result of going to the new version of GALL and Standard Review Plan.

The last thing I'd like to mention in this area is that the NRC's schedule and process for review of our application consists of two audits on site but the License Renewal Group, one for aging management programs and one for aging management reviews. During the first audit in October of 2005, it was recognized by the NRC and Amergen that the backup information

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

that we had available for review by the NRC was not in a format that facilitated an efficient review by the staff. We made a decision then we would prepare basis document notebooks similar to those used by other applicants to support the future reviews and the audits were held successfully in January and February of 2006.

We identified for Oyster Creek Slide 22. in our application 57 aging management programs, 50 of those that align with the GALL programs and seven were plant specific. Of the GALL programs, 32 were 14 required existing programs, of which some enhancements and we had 18 new programs. I'd like to mention about that 18 just a little bit that it's a lot larger number than you would typically see, I think, in recent applications, the reason being is that our Forked River Combustion Turbines which are alternate AC power supply with station blackout were in scope of the rule. We prepared aging management programs specifically for them that were separate and different than the corresponding programs to the For example, in the cooling water aging plant. management program we have one for the Oyster Creek We have a different one for Forked River Combustion Turbine.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. BARTON: Why was that separate and
2	submitted late?
3	MR. POLASKI: I was going to get to the
4	point of late. I'll get to that in just a minute when
5	I get into combustion turbines. The reason we did it
6	separate, I'll get to that whole thing in a minute,
7	yeah.
8	MR. BARTON: Okay, that's fine.
9	MR. POLASKI: So 11 with Forked River and
10	one also dealt with our meteorological tower and the
11	reasons I'll get to in a second.
12	MR. BARTON: Okay.
13	MS. POLASKI: And seven plant specific,
14	four existing and three new, again one with the Forked
15	River Combustion Turbines.
16	MEMBER SIEBER: Who is going to do the
17	programs for the combustion turbine?
18	MR. BARTON: He's going to get to that
19	later.
20	MR. POLASKI: I'm going to get Slide
21	23, the next slide.
22	MEMBER SIEBER: First Energy, right, how
23	are you going to make First Energy do it?
24	MR. POLASKI: Okay, so for everybody's
25	understanding, Forked River Combustion Turbines are

two peaking combustion turbines rated at 30 megawatts each. They were installed by GPU in 1989 in the Oyster Creek Substation. As a result of having to comply with the station blackout rule, in 1992, these were credited as the alternate AC power supply.

Breakers were installed and transmission conductors will be able to tie those into the plant. I will note that only one of the two is needed to meet the station blackout design.

MEMBER SIEBER: Is one of the two committed to the SBO or are they both committed?

MR. POLASKI: They're both committed to station blackout but they have to make sure that one is always available and one would be provided during station blackout conditions.

MEMBER SIEBER: Okay. In reality, even though they're 38 megawatts, I think our transformer limitation is something like four megawatts we could take off of those. So we only really need and could only use one of them. They are currently owned and operated by First Energy. So that -- you know, the question is, how are we going to maintain them? They are covered by the Maintenance Rule and surveillance testing programs and as part of the station blackout design, we monitor reliability of the those.

1 On Slide 24 --2 BARTON: That means you've got a 3 systems engineer that makes sure everything First 4 Energy does is in accordance with your maintenance 5 rule? MR. POLASKI: That is correct. 6 7 MEMBER SIEBER: Or doesn't do. 8 MR. BARTON: Or doesn't do, yeah. 9 MR. POLASKI: Well, it does to it. The 10 reliability is greater than 99 percent. In fact, I 11 think the number is like 99.92 percent for the last 12 So that reliability has been very good on 100 starts. this and that formed our basis for our initial aging 13 14 management strategy. The licensure application 15 included these and credited the reliability monitoring as I said, but after discussions with the NRC, we 16 17 elected to establish multiple GALL based management programs to manage specific long-lived 18 19 passive components similar like we would do in the 20 plant. 21 Now, so what does that program mean? In 22

some areas, the civil structural inspections, we will continue to do that by Amergen as part of the structural monitoring program. Electrical testing will be done by Amergen personnel because it's non-

23

24

1	intrusive. You can do it with equipment online or
2	it's visual. The mechanical inspections, in large
3	part, are going to be performed by First Energy and we
4	are currently working with them to build those into
5	their ongoing maintenance practices.
6	MEMBER SIEBER: If you have a loss of the
7	grid, which has happened
8	MR. POLASKI: Yes.
9	MEMBER SIEBER: And you use one of the
10	combustion turbines as a station blackout combustion
11	turbine, it will be running at around 10 percent load.
12	MR. POLASKI: Yes.
13	MEMBER SIEBER: Is this stable at 10
14	percent?
15	MR. POLASKI: I'm going to ask Rick
16	Skelskey from the station to answer that question.
17	MEMBER SIEBER: Usually their more stable
18	with a bigger load.
19	MR. POLASKI: I understand.
20	MR. SKELSKEY: Rick Skelskey, Engineering
21	Manager Oyster Creek. So at 10 percent where it's
22	about 20 percent load, it is stable at that and
23	actually does run very well at those loads. And we
24	test that every refueling outage. We bring
25	combustion turbines on to the plant and assume the

1 loads through our transformer. 2 MEMBER SIEBER: So you've tried. Yes, we do them. 3 MR. SKELSKEY: We do 4 test that and it is in our surveillance program and 5 that is performed every refueling outage. MEMBER SIEBER: Okay, thank you. 6 7 MR. POLASKI: Any other questions on the combustion turbines? 8 9 MR. BARTON: Yeah, one other thing. Do 10 you have the agreement that they can't take it out for maintenance, for instance, you can't take it out for 11 maintenance without getting your approval up front and 12 you can't -- they can't tag it out without going 13 14 through your control room or something like that? 15 MR. POLASKI: I'm going to let Rick discuss the details of that. 16 MR. SKELSKEY: Rick Skelskey again. 17 On the CT maintenance, for planned maintenance, we do get 18 19 buy-in ahead of time and for unplanned 20 maintenance, something happens to the CT, the unit 21 does not start, our control room operators do get a 22 call and we enter those into our corrective action 23 process to monitor that. And we also -- we do get 24 reports of their starting so start demands and when 25 they actually start. We get that on a monthly basis

1 from them and then --2 MR. BARTON: If you want to bring GE into 3 doing overhaul on one of the units, how do you know 4 that? 5 MR. SKELSKEY: We work with First Energy. We have regular meetings with them and they schedule 6 7 that through us when they want to do that maintenance. 8 MR. BARTON: Okay. 9 MR. SKELSKEY: So, like I said, for 10 planned maintenance, that is scheduled with us. 11 MR. BARTON: Thank you. 12 On Slide 25, discussed MR. POLASKI: briefly our commitment management process for license 13 14 renewal. There are 65 commitments that are listed in 15 Appendix A of the license renewal application which 16 will go into the FSAR. Fifty-seven of those are for 17 aging management programs and then there's eight stand-alone commitments. We have a -- generated a 18 19 passport commitment tracking number for 20 renewal commitments. Our passport system is a data 21 base system that we use at the plant at Oyster Creek 22 and also throughout Exelon for work management, 23 corrective action process, commitment tracking and 24 many other facets of things that go on at the plant

and so we've got a license renewal commitment number

you know, for license renewal commitments.

action that contains the details for each of the 65 commitments and each of the implementing procedures that we use to implement these aging management programs as annotated to provide the linkage back to the commitments and to preserve the details of the commitment. This process is controlled by the Exelon commitment management procedures and processes.

If there's no questions on that, I'm going to turn the presentation over to Tom Quintenz. He's going to provide a status on program implementation at the site.

MR. QUNITENZ: Thanks, Fred. We should be on Slide 26. Good afternoon, my name is Tom Quintenz. I'm the Oyster Creek Site License Renewal Engineer. I've been assigned to this project from the beginning to the present time. My responsibilities are to assure the proper level of site involvement throughout the project including input to the LRA and through implementation. I'm here today to tell you about the implementation of our aging management programs.

The programs have generated 368 activities to be performed prior to the period of extended operation; 257 of these are new activities and 111 are

1	enhancements to ongoing existing activities at the
2	site. Each of the activities have been assessed to
3	determine the appropriate time for implementation.
4	Each of the
5	MEMBER WALLACE: If you could just explain
6	this, these numbers don't mean much by themselves, but
7	257 new activities.
8	MR. QUNITENZ: That's correct.
9	MEMBER WALLACE: And the obvious question
10	is why weren't they done before? What's different now
11	than before? Why are they done now?
12	MR. QUNITENZ: These are new activities
13	that were generated as a result of our review of the
14	GALL and producing the aging management programs that
15	we have.
16	MR. BARTON: These are like one-time
17	inspections people say they have to do before an
18	extended period of I think that's the kind of thing
19	Tom's talking about.
20	MEMBER WALLACE: That's the kind of thing
21	he's talking about.
22	MR. QUNITENZ: The new activities, as John
23	indicated, were activities that come out of our one-
24	time and periodic inspections.
25	MEMBER WALLACE: You didn't look at the

1 buckets before and now you're going to look at the 2 It's not that kind of thing. buckets. 3 MR. QUNITENZ: No, no, it's not. 4 MEMBER WALLACE: Okay, it's inspections 5 that you have to do because of the aging. MR. QUNITENZ: Right, and this was a 6 7 result of also pulling in non-safety related systems that had the potential for interaction with safety 8 9 related systems in the plant that were not previously at this level of inspection. The following is a 10 breakdown of when we intend to implement each of these 11 12 Thirteen percent of the total will be activities. implemented in our upcoming refueling outage in 2006. 13 14 significant portion of these activities 15 associated with inspections that we will be doing with the drywell and --16 17 MEMBER WALLACE: I have no idea how to evaluate this. I mean, if I saw 500 up there, it 18 19 wouldn't make a difference to me. 20 MR. BARTON: Yeah, you probably couldn't 21 do them all. 22 I'd have to say that first MR. OUNITENZ: 23 of all, I'd have to talk about our work management 24 We've planned and schedule each year on the 25 order of 15,000 activities relative to operating the

1 station. So these numbers to us are well manageable. 2 MEMBER WALLACE: It's not a huge new 3 workload for you? I would say that, as I 4 MR. QUNITENZ: 5 indicated before, there are new activities in here and basically we have the capability to manage those. 6 7 know Tim Rausch is here and we've discussed that with him relative to that implementation as well. 8 9 ABDEL-KHALIK: Was there a MEMBER 10 prioritization process to decide which of these should be done now and which should be done two years later? 11 MR. QUNITENZ: Yeah, basically --12 MEMBER ABDEL-KHALIK: How was that done? 13 14 MR. QUNITENZ: Yes. Basically we took all 15 of the activities that we committed to that were implementing our commitments and we reviewed each of 16 them to determine what the appropriate time was to do. 17 Did we have to have the unit off-line in order to 18 19 implement the activity or could we do that while we 20 were operating? So we went through each activity to 21 make that determination. We also organized a team of 22 people to take a look at the activities to see which 23 ones would be more appropriately a fit into our 24 refueling outage in this October as opposed to next 25 October or next year and when to schedule.

MEMBER ABDEL-KHALIK: So it's a matter of convenience rather than a matter of significance?

MR. QUNITENZ: I think both weigh into that determination. For example, in terms of significance, we rolled all of the drywell inspection activities into this because we thought that that was a significant item that we needed to really take care of all the commitments relative to the drywell this outage rather than waiting till the next outage. So from a significance perspective, that did weigh into this also.

As indicated on the slide, 19 percent of the total will be implemented during our refueling outage in 2008. The remainder, 68 percent of the total, will be implemented during plant operation while we're online. A significant amount of these activities will be done between the two refueling The completion of this work effort will assure all required inspections have been completed prior to the period of extended operation. addition, all documents credited for implementing renewal commitments will license be annotated specifically with those commitments. And this assures continued implementation of our management programs through the period of extended

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	operation.
2	Are there any questions or comments? I'll
3	now turn it back over to Mike Gallagher.
4	MR. GALLAGHER: Okay, so just to
5	summarize, we Slide 27, we have established the
6	aging management programs to insure continued safe
7	operation for the period of extended operation. We've
8	also clearly identified and will implement all the
9	license renewal commitments as expected and we are on
10	track for completing the activities needed prior to
11	entering the period of extended operation. That
12	concludes our presentation and we're open to any other
13	questions.
14	CHAIRMAN MAYNARD: What I'd like to do at
15	this point is first go ahead and take a break. I'd
16	like to get the staff's presentation, public comments.
17	We may or may not call you back up at that time and
18	ask some additional questions at that time. So with
19	that, it's 20 till. Let's take a break and be back
20	here at five till.
21	(A brief recess was taken at 3:43 p.m.)
22	CHAIR MAYNARD: We will resume the
23	meeting. I'll turn it over to Mr. Ashley to present
24	the NRR.

MR. ASHLEY: Thank you, Mr. Chairman. My

1	name is Donnie Ashley. I am the Project Manager,
2	Staff Review of the Oyster Creek License Renewal
3	application. Joining me today is Steve Tenien who is
4	the Scoping and Screening Team Leader, Michael Modes
5	from Region I. He was our Inspection Team Leader on
6	the project. Michael and I will be presenting the
7	results of our staff's review. Roy Matthews is with
8	us. He's the Audit Team Leader and he's present to
9	respond to any question that you may have concerning
10	the audits.
11	MR. BARTON: You have three hours to
12	figure out what firebar D is taken. Can you tell us
13	that right up front?
14	(Laughter.)
15	MR. ASHLEY: I'm still worrying about the
16	phone. Hans Asher is also here and he is to brief the
17	Committee on a confirmatory analysis that we did and
18	that we're in the process of conducting now on the
19	drywell and supporting all of us are the technical
20	reviewers in the audits to answer the questions that
21	you're going to have.
22	Just a general overview, I won't repeat a
23	lot of the information other than to let you know that
24	there were the five items that the Applicant did

mention. There were 108 RAIs in this review and 366

audit questions and in all of those cases we got good responses back from the Applicant and they were all in a timely fashion. We had one major component that the Applicant talked about as far as the fork driven combustion turbine and if I go too fast, stop me and we'll talk.

CHAIR MAYNARD: No. I think the main

CHAIR MAYNARD: No. I think the main thing we want to be able to get into is the basis that the staff has used to draw conclusions on the acceptability of the drywell and some of the other technical issues.

MR. ASHLEY: Absolutely we'll do that. This is a listing again of our audits and inspections that we conducted. As far as the scoping and screening in the back of your package are extra slides that you can take a look at if you want to look at the specific mechanical systems, the containment systems and the electrical components and commodity groups. But the scoping and screening results included all the SSCs that were within the scope of license renewal and subject to aging management review. The one additional that we had was I believe on met tower equipment.

Michael Modes, if he's here, if he could discuss the inspection that was conducted.

1 (Discussion off the microphone.) 2 MR. MODES: So we did a few week inspection. Next slide. No, that one. 3 4 CHAIR MAYNARD: You're going to need to 5 make sure you use a microphone. MR. MODES: Yes, I'm sorry. We did a two-6 week onsite inspection March 13th to March 17th and 7 March 27th to March 31st. These were scheduled to 8 nominally support the NRR reviews. The schedule calls 9 for about an eight-month window. We tried to jump in 10 11 between the audits and the SER. 12 We had a team and this one was a large inspection because we thought we needed to cover an 13 14 awful lot of ground and we also needed to have 15 specialists paying attention to special areas. had eight inspectors covering all the disciplines and 16 17 one of those inspectors spent an entire one week period doing nothing but walking down the plants. 18 19 has about 30 experience in years 20 operationalization aspects. He did a 54-A2 nonsafety 21 effect safety inspection. 22 And one of the inspectors spent the entire 23 two weeks onsite plus the week in between doing 24 nothing but looking at the drywell data, all the

interviewing all the individuals,

videos,

through all the historical records and going through all the analysis that was performed. The inspection was performed in accordance with Procedure 71002. Next slide.

The scoping and screening portion as I said concentrated on the nonsafety systems whose failure would impact safety systems. The guy who did that emphasized physical walkdowns. He did over a He choose and did over a dozen dozen systems. but that means that he did way I don't think he spent more than an intersecting. hour each day with us debriefing when he was off running around the plant trying to figure out whether he could find weaknesses in their 54-A2 programs. concluded that the methodology was adequate and it was consistently applied. Next one.

Aging management program. We did 30 programs and you've heard me say it before from the bottom up starting with the implementing procedures, the work orders, all the information at the plant that gets you to understand what aging they're trying to deal with and whether or not the procedures and programs they're proposing will in fact manage what we see or what we think will occur. This time we did something a little creative and we took one risk

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

significant system, the isolation condenser, rather than grinding through all these programs again. we did was we took the isolation condenser which is risk significant but does not contribute to ECCS, so it's safety related but not safety and it gets very fuzzy but it's risk significant. It contributes substantially to the plant configuration post-accident and what we did there was we looked at the program applied to the aging of being that risk significant system and it was quite illustrative of trying to do this thing from the back forward using We concluded that the Applicant system. one implemented the existing aging management programs as they had described them in the application and that acceptable enhancements, etc. were made. Next one.

In response to NRC identified inconsistencies, the Applicant revised the application or entered those inconsistencies. We generated a lot of corrective actions as a consequence.

The Applicant provided assurance that properly updated its current licensing basis in accordance with 54.21b and the Applicant provided assurance that the systems, structures and components will perform the intended function, aging management programs are adequate for the period of extended

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

_	operation. Overall Oyster Creek's implementation of
2	aging management programs will be sufficient for the
3	extended period.
4	MR. BARTON: I got a question. You were
5	talking about iso-condenser and some of the exceptions
6	they took or whatever. They took exception to the use
7	of ASME Code Class I small bore piping program and
8	they proposed to inspect one small socket weld off the
9	iso-condenser and the NRC bought that as acceptable.
LO	Now I would like to understand why. Maybe you're not
L1	the guy to ask but I had that question.
L2	MR. MODES: I'm not the guy.
L3	MEMBER WALLIS: I picked that up as well.
L4	I wondered about that.
L5	MR. BARTON: Can anybody answer that?
L6	CHAIR MAYNARD: Donnie, do you have
L7	anybody in the staff?
L8	MR. ASHLEY: That did come up during the
L9	Roy, if you would come up to the microphone. Roy
20	Matthew, the Team Leader.
21	MEMBER WALLIS: The rationale was it's a
22	sampling process, but it's unusual that the sampling
23	of one is adequate.
24	MR. DAVIS: I'm Jim Davis on the Audit
25	Team. We've accepted this at other facilities doing

1	one socket weld as representative as under four inch
2	pipe and we've consistently used this because socket
3	welds are small enough that they're not normally
4	inspected.
5	MR. BARTON: I understand that. That's
6	why I wondered why one was acceptable as a sample. So
7	this is your standard. One is good enough.
8	MR. DAVIS: Yes, because they're not
9	normally even inspected other than by a system
LO	walkdown.
L1	MR. BARTON: Yes, but they do end up
L2	cracking.
L3	MR. DAVIS: Well, we're asking for a
L4	destructive examination of the socket weld to make
L5	sure that there's no degradation that's not visible.
L6	MR. BARTON: But it may or may not be in
L7	this one socket weld and you're happy.
L8	MR. DAVIS: With one we're happy because
L9	it's not normally included in the program. It's more
20	than is normally required. But we feel that they have
21	to look at least one socket weld to see if they're
22	okay.
23	MR. CHANG: Ken Chang, the Branch Chief -
24	MEMBER WALLIS: As long as they claim 95
25	percent confidence from one socket weld.

	MR. CHANG. Ken Chang, the Branch Chief
2	for the Audit branch License Renewal. We're not just
3	arbitrarily accepting the one socket weld. Although
4	it's difficult to inspect we want to inspect one of
5	the possible worst cases. In other words, you pick a
6	biased sample as one of the worst cases. You're not
7	picking along a continuous pipe. You're picking on a
8	fitting, on a reducer, on a socket weld, on something.
9	So that should represent a reasonably bad conditions.
10	If anything should happen, that should happen to that
11	component and also the welders went through the same
12	qualifications. So if you pick one of the worst cases
13	of socket welding inspected, it would give you a
14	reasonable assurance that it's done correctly.
15	MR. BARTON: I'm just not sure that one
16	welded at every socket weld at Oyster Creek.
17	MR. CHANG: But if you have 300 socket
18	welds, you cannot inspect all 300 socket welds.
19	MR. BARTON: I don't think 300, but I was
20	just wondering why one was enough.
21	MEMBER SIEBER: Well, the issue I think in
22	small bore piping, particularly socket welds, is they
23	do fail and they fail with greater frequency than
24	large bore pipe does.
25	MEMBER WALLIS: Right.

1	MEMBER SIEBER: And usually they fail
2	because of vibration. So how do you go and pick the
3	one that represents the worst case?
4	MR. BARTON: I'm not sure this one
5	vibrates very much.
6	MR. CHANG: No, this for vibration, this
7	socket weld you select on the basis of similar
8	fatigue. For vibration, there are other criteria to
9	evaluate the stresses and select the potential
LO	location of failure. It's like amplitude and
L1	frequency.
L2	MEMBER SIEBER: Yes.
L3	MR. CHANG: Now that's different. You do
L4	it by walkdown. You observe where you can see the
L5	vibration amplitude is bigger than in other places.
L6	There are typical examples, typical procedures, by
L7	every site to select the location and systems that are
L8	susceptible to vibration.
L9	MR. BARTON: I just don't see this one as
20	vibrating. I don't know.
21	PARTICIPANT: It's not a vibration
22	problem.
23	MR. BARTON: It sits at a dead lang off an
24	iso-condenser which only gets turned on if we really
25	need it during a event. Right?

1	MEMBER SIEBER: Right.
2	MR. BARTON: So that's why I wondered why.
3	MEMBER SIEBER: You can't also observe.
4	MR. BARTON: What are you going to
5	observe? You're going to be there when the event
6	happens and see if it shakes.
7	MEMBER SHACK: That's why he's inspecting
8	it because there is nothing to observe.
9	MR. BARTON: Ah, yes. Why couldn't I have
10	figured that out?
11	(Laughter.)
12	MEMBER SIEBER: You still have to pick the
13	one you're going to inspect.
14	MEMBER SHACK: He's tried to, I think,
15	pick one with a certain consideration critique
16	potential and
17	MEMBER SIEBER: Right. I got it.
18	CHAIR MAYNARD: Okay. Could we move on.
19	MR. ASHLEY: Moving right along.
20	MR. MODES: Any questions?
21	Okay. You guys are always interested in
22	the current performance of the facility. So the
23	licensee is in regulatory response column two. If you
24	note they have one white in emergency preparedness
25	because they failed to recognize they were in an usual

1 condition during а grassing event. We have subsequently done an inspection and did not fully 2 3 concur in their root cause analysis because it didn't 4 address fully the human performance element in the 5 white finding. So as a consequence, this remains 6 open. 7 In addition, they do have one crosscutting issue in the area of human performance which was 8 discussed at the midyear mid-cycle review with them 9 and it should surprise you absolutely not that the 10 crosscutting is failure to adhere to procedures. 11 Why shouldn't that surprise 12 MR. BARTON: 13 us? 14 MR. MODES: Well, you did ask a lot of 15 questions about how come they emptied the bottle and a matter of fact, you reflected exactly the 16 somewhat irritated remarks I had when I was told about 17 it. 18 Any questions? 19 MR. BARTON: Nothing. 20 Thank you, gentlemen. MR. MODES: Thank you, Michael. 21 MR. ASHLEY: 22 the aging management programs they happened to talk 23 about the 57 AMPs and again there are listings of the 24 amps that are in your package of slides if you'd like

to take a look at those.

1 This is an example of the aging management on protective coatings and monitoring and maintenance 2 program that was evaluated in Section 3. 3 This one 4 particularly has to do with the inspection of torus 5 bays and in subsection IWE of ASME Section 11. The structure's monitoring program is 17 6 7 commitments identified for that program. It also includes structures for the station blackout system. 8 Ten additional commitments for the station blackout 9 for the Forked River combustion turbines as the 10 Applicant discussed with you. 11 12 In the aging management review overview the soliciting of what the team looked at, the numbers 13 14 of systems, structures and components. The aging 15 management specifically on the drywell talks about --16 MEMBER WALLIS: So let me ask you 17 inspection of 100 percent of the sandbed region epoxy coating, is that just looking at it or is that 18 19 scratching it or pulling it? 20 MR. ASHLEY: Which slide are you on, sir? MEMBER WALLIS: Well, I think I'm -- Am I 21 22 ahead of you or something? 23 PARTICIPANT: Sixteen. 24 MEMBER WALLIS: Am I ahead of you? 25 BARTON: What number are you on, MR.

	134
1	Graham?
2	MR. CHANG: Sixteen.
3	MEMBER WALLIS: Sixteen. Aging management
4	example. Am I ahead of you?
5	MEMBER SIEBER: Yes.
6	MEMBER WALLIS: I'm ahead of you. I'm
7	sorry.
8	(Several speaking at once.)
9	MEMBER BONACA: You are behind because
10	you're only on three or four.
11	MEMBER WALLIS: You're ahead of us. It
12	says 100 What does that mean?
13	PARTICIPANT: It's a visual inspection.
14	MEMBER WALLIS: They do do it to inspect
15	samples.
16	MR. ASHLEY: Jim Davis on the Audit Team.
17	MR. DAVIS: It follows the ASTM
18	recommendations for inspecting coatings which is a
19	visual inspection. If you find something, then you
20	have to do something additional.
21	MEMBER WALLIS: So if it looks funny, it's
22	blistered or something.
23	MR. DAVIS: Blistered or cracked or
24	peeling.
25	MEMBER WALLIS: You don't have to scratch

	133
1	it or pull it.
2	MR. DAVIS: No.
3	MEMBER WALLIS: Or do anything to it
4	physically.
5	MR. DAVIS: No, that's not what the ASTM
6	recommends.
7	MEMBER WALLIS: If it's right, then it's
8	okay.
9	MR. DAVIS: Yes. That's the normal way.
10	I've talked to the industry expert, the Chairman of D-
11	33, the protective coating committee.
12	MEMBER WALLIS: If it's falling off it's
13	not okay, but if it's there, it's okay.
14	MR. DAVIS: If it's cracked or if it's
15	blistered or if it's
16	MEMBER WALLIS: Rust streaks or anything.
17	CHAIR MAYNARD: Isn't there a criteria or
18	a qualification for the individuals doing the visual
19	inspection on this?
20	MR. DAVIS: Yes, he's qualified.
21	CHAIR MAYNARD: It's not just anybody that
22	can walk in there and take a look and make a decision.
23	MR. DAVIS: Yes, you have to be a
24	certified coating inspector and they actually put them
25	upside-down in the sand bed region. It's 18 inches

1	wide. I don't think I'd fit in there, but they
2	actually do a very good visual inspection.
3	But having had some experience looking at
4	coatings, you can tell when they're going bad and then
5	there are other ASTM tests that can conduct such as a
6	cross hatch test or an adhesion test. So far to date,
7	they haven't had to do any of that.
8	MEMBER WALLIS: I'm just thinking about my
9	experience with my vehicles or my house or something.
10	Sometimes the paint looks fine, but it's rotting
11	underneath.
12	MR. DAVIS: That's not normally the case
13	with these epoxy type coatings on metal, on steel.
14	I'm a member I was a member of the ASTM D-33
15	Committee and we had tons of discussions on this and
16	actually Reg Guide 1.54 Rev 1 goes through the ASTM
17	requirements if you're interested.
18	MEMBER WALLIS: There's a lot of technical
19	evidence behind this.
20	MR. DAVIS: Yes.
21	MEMBER WALLIS: Okay. Thank you.
22	MR. ASHLEY: Slide 19. This is a listing
23	again of the systems that were subject to the aging
24	management review.
25	MEMBER WALLIS: All these numbers, what do

1	they mean? Does this mean this is typical plant or
2	it's exceptional or what?
3	MR. ASHLEY: It's fairly typical for this
4	kind of plant.
5	MEMBER SHACK: I think two of them.
6	MEMBER WALLIS: Of this type of plant?
7	It's typical of this type of result or license
8	renewal. You get this sort of numbers.
9	MR. ASHLEY: Yes, the other plants do have
10	similar numbers.
11	MEMBER WALLIS: It doesn't mean anything
12	to just have a list of numbers there.
13	MR. ASHLEY: It's just to tell you how
14	much this
15	(Several speaking at once.)
16	MEMBER WALLIS: in context or
17	something. It doesn't mean any
18	MR. ASHLEY: The aging management program
19	for the drywell shell as was discussed earlier as far
20	as the protective monitoring coating, excuse me, the
21	protective coating monitoring and the Magnets Program.
22	MEMBER BONACA: Again I have been
23	questioning this issue of preventative actions. Again
24	I mean everything stems from the fact that water is
25	leaking from that refueling cavity and there has to be

1	some design requirements there that are being violated
2	by the leakage and there has been some commitment to
3	use this steel tape, but it doesn't cure the whole
4	problem. I mean it has not cured it in the past. I
5	still wonder. To me it should be a central issue
6	regarding the leakage of the water.
7	MR. BARTON: I think what we heard was
8	that there were two outages in succession. When they
9	went through that decommissioning plan, they didn't do
10	that strippable coating and we all noticed cracks in
11	the liners.
12	MEMBER BONACA: Yes.
13	MR. BARTON: And the water in the bolus
14	was old. Is it that old?
15	MEMBER BONACA: Yes. If I have confidence
16	that if you really do apply that tape properly.
17	MR. BARTON: If you apply the strippable
18	coating, if coating has been applied in other outages
19	
20	MEMBER BONACA: And is effective.
21	MR. BARTON: I guess they haven't seen any
22	leakage, have they? I don't know. Ask the licensee.
23	Have you guys seen any leakage if you did put the
24	strippable coating on during a refuel outage?
25	MR. TAMBURNO: This is Pete Tamburno. In
J	I control of the cont

1	the past two outages where we've used the strippable
2	coatings, we haven't seen any leakage from above.
3	MEMBER BONACA: Then it should be part of
4	the commitment. Right? Do you have a commitment as
5	part of all this?
6	MR. TAMBURNO: Yes.
7	MR. ASHLEY: This is a listing of the
8	commitments that the Applicant had made in various
9	documents that had been sent to us and if you'll see
10	here, the strippable coating will be applied directly
11	to the line.
12	MEMBER BONACA: So that's a commitment.
13	MR. ASHLEY: And it is one of the
14	commitments.
15	MEMBER ARMIJO: Is it possible that you
16	could put a strippable coating on that was flawed and
17	you wouldn't know it or will you have some other
18	detector for water, either look at the drain lines to
19	see if this coating still is working?
20	MR. ASHLEY: They, in fact, have a
21	commitment here for monitoring daily those leakages
22	during the outages. Yes sir. It appears that that's
23	where the leakage was occurring during those periods
24	of times.
25	MEMBER ARMIJO: I thought that might.

1	CHAIR MAYNARD: One of the When they
2	had the leakage before, it wasn't going in the drain
3	like it was supposed to if it got passed that point
4	and from what the licensee said, it sounded like they
5	had changed that where it no longer has the low point
6	where it would drain down by the liner. It would go
7	down that drain so they could tell if they were
8	getting some leakage in that area.
9	MR. ASHLEY: They would be able to tell,
10	yes sir, at that point.
11	CHAIR MAYNARD: And my question is of the
12	staff the level of confidence that from what, you said
13	as an individual for at least three weeks going
14	through the data and talking to people about the
15	drywell and different things and other inspection team
16	members here, the confidence level that the strippable
17	tape and that the actions that they're taking will
18	prevent leakage and identify it if for any reason it
19	does occur?
20	MR. ASHLEY: Yes sir. With the look that
21	was given this entire system and the history of the
22	system, the inspections that were conducted, the
23	audits that were done, although we'll talk in just a
24	minute about TLAAs and all of the open items are
	II

linked to the TLAAs and that's in Section 4.7 of the

1 Safety Evaluation Report. 2 In addition to that, these other programs 3 on the monitoring, on the coatings programs, were also 4 reviewed by the audit teams in Section 3 as well. 5 it got a very, very exhaustive look and in a little while I'll bring Hans Asher and we'll talk to you 6 7 about where we're going from this point to further 8 verify. 9 It's also my understanding that 10 coatings inspections that are going to be done this outage in the U2 testing also figure in too. 11 12 the reason we have the open items. It's because we don't have complete information yet. So once we get 13 14 that information from the outage I think we'll be able 15 to say with confidence that we --Do you monitor the leakage 16 MEMBER WALLIS: 17 by having buckets at the end of the drains and the leakage only occurs during an outage when you're 18 19 refueling? 20 That's where the original MR. ASHLEY: 21 leakage was identified as --

didn't come down and evaporate on the way down or

NEAL R. GROSS

So you identify the

leakage by looking at the buckets at the end of the

That doesn't tell me whether the leakage

MEMBER WALLIS:

drains.

22

23

24

1	something. I mean it doesn't have to go all the way
2	down to the bucket, does it?
3	MR. ASHLEY: If it evaporates, it's gone.
4	MEMBER WALLIS: Yeah, but it still shows
5	there's been a leak.
6	MR. ASHLEY: It would be a very minor leak
7	at that point.
8	MEMBER WALLIS: I don't know because a
9	damp surface can corrode quite nicely.
10	MR. ASHLEY: But with the temperatures
11	that occur during normal operation
12	MEMBER WALLIS: It would evaporate.
13	MR. ASHLEY: the water doesn't have
14	time to
15	MEMBER WALLIS: or just
16	MR. BARTON: That's secondary normal
17	operation you're leaking when you shut down/cool down.
18	MEMBER WALLIS: That's when they leak.
19	Right.
20	MEMBER SIEBER: Yes.
21	MR. ASHLEY: We don't feel like there's a
22	leakage that we've seen -
23	MEMBER WALLIS: Don't feel like. That's
24	not good enough.
25	MR. ASHLEY: was not operation leak.
ļ	

1	MEMBER WALLIS: So you're assured from
2	some analysis that if there were a leak it would show
3	up in the bucket and not be evaporated somewhere or
4	just leave something else damp which might then do
5	something later on.
6	MR. ASHLEY: I don't know how to answer
7	your question.
8	MEMBER WALLIS: Or leave a puddle at the
9	bottom of the
10	MS. LUND: Hans Asher is going to address
11	that.
12	(Off the record comments.)
13	MR. BARTON: I don't know if it would
14	leave a puddle, Graham, because what they did when
15	they went in there and they sloped the floor and put
16	epoxy on it so it seals.
17	MEMBER WALLIS: It could be a damper.
18	MR. BARTON: There could be a damp spot,
19	yes.
20	(Off the record comments.)
21	MEMBER WALLIS: Certainly if there was
22	sand there, the sand could gather the water and
23	MEMBER SIEBER: Yes, there's more sand.
24	You're right.
25	MEMBER WALLIS: That's good then because

previous the sand could stay damp and that's what happened. That's how you got the corrosion without necessarily draining at all.

MEMBER SIEBER: That's right.

MR. ASHER: I will address your question about the operation of water. We've heard about this a long time back even during the Dresden containments and we asked the same questions that you are asking to the applicants. Okay. And the general answer was that it will operate and it won't corrode anything. I said no. I'm not ready to believe that. So what we resulted that did, the earlier one, and I saw a separate case too that we asked them to do the UT measurements from upper areas through which the water is continuing to the sand bed area. Okay. And a number of applicants said unless they see no activity of water at all during the entire life, then we will say that is not necessary. But that we have seen any water leakage from their refueling cavity or any other areas collected in the sand bed area, then the whole spherical area and cylindrical area are suspect. this case also, at Oyster Creek also, thev required to do the UT in the upper area of the shaft.

MEMBER WALLIS: So the UT is the real check rather than looking in the buckets.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. ASHER: Correct. UT is the real
2	check.
3	MR. ASHLEY: Thank you, Hans. This is a
4	slide that discusses the aging management, the in-
5	scope inaccessible concrete and that would be in the
6	structures system. The time limited aging analysis
7	sections 4. These are the TLAAs that were reviewed
8	and accepted by the teams.
9	And if I could, I would like to go ahead
10	onto the 4.72 and talk about drywell corrosion. I
11	know that's of interest to the subcommittee unless you
12	have specific questions about an item here that you
13	would like to talk about before I jump to the drywell.
14	CHAIR MAYNARD: Go ahead.
15	MR. ASHLEY: Give me just a second to get
16	there.
17	(Off the record comments.)
18	MR. ASHLEY: We also have with us
19	MR. ASHER: Jason Petty.
20	MR. ASHLEY: Jason Petty from Sandia
21	National Labs. So I'll turn it over to Hans to
22	discuss this.
23	MR. ASHER: In case you ask me very
24	difficult questions, he's here to help me.
25	MEMBER WALLIS: Okay.
ı	1

1 MR. ASHER: Well from this slide, the only 2 thing I want to point out are two things, the load 3 that we have considered which are -- Okay. Let me 4 first start with --5 CHAIR MAYNARD: Can we wait just a minute Do we have this slide? 6 here? 7 MR. ASHLEY: Yes sir. They should be in 8 the back of your handout. There should be several 9 slides there, the last four I think, the last four or 10 five. 11 (Off the record comments.) 12 CHAIR MAYNARD: Thank you. I have it. Do you have it everybody? 13 MR. ASHER: 14 first thing I want to explain, the reason why we 15 embarked on this particular plant for analysis purposes, we have not done this kind of analysis on 16 other plants, containments, because in all of them 17 they have certain corrosion but the corrosion was 18 19 within certain limits and it never compromised the 20 minimum required thickness from the design point of 21 In this particular case, the degradation is view. 22 quite severe in many ways of the same bucket area and 23 we wanted to comfort ourselves that is this degraded 24 containment be able to perform its function in the 25 next 20 years. This was our aim.

1 So though we are depending quite a bit on 2 the commitments that the Applicant has made, but this 3 is something that we want to make sure ourselves that 4 this particular degraded containment is able to 5 withstand the loads it is designed for. MEMBER WALLIS: Did they do a similar 6 7 analysis or did you do it? 8 MR. ASHER: Yes, in 1992-1993 time frame, 9 General Electric had done an analysis and that is what you were talking about before, 0.732 ages and all 10 that. 11 12 MEMBER WALLIS: Okay. That came from an General 13 MR. ASHER: 14 Electric analysis. Okay. On this slide, I want to 15 point out only two items. General loads, loads that 16 we have considered are the normal operating loads as well as the seismic load. Seismic load we have 17 considered the static coefficient from SFAR which I 18 19 think are bounding because subsequent to the basic 20 load that are used in the SFAR, Oyster Creek have done 21 other detailed analysis. But this load we consider 22 our bounding one. 23 MEMBER WALLIS: This is a dead load. 24 There are also pressure loads from --25 MR. ASHER: Yes. The next items,

1 controlling load pieces. There are controlling LOCAs 2 that we have considered and truly the LOCAs that we have considered are close to 10 to 12. Out of that, 3 4 we selected three of them which are going to control 5 certain aspects of the design. The first one is a refueling. Refueling 6 7 is basically during the shutdown. It is water in the refueling cavity that puts weight on the drywell shell 8 9 and the buckling is a possibility under that load and 10 particularly for the containment we ought to look for those things. 11 The second is a design basis accident with 12 earthquake which is a part of LOCA, normal LOCA 13 14 calculations. Post accident flooding with earthquake that is also part of our LOCA calculations in SRP and 15 16 everywhere else. So these are the three. 17 Now other two items, model geometry and modeling corrosion. I want to explain to you by 18 19 sketch rather than by speaking it out. Can you go to the first sketch? 20 21 (Off the record comments.) 22 Sandia National Lab has MR. ASHER: Okav. 23 done the full analysis. In the case of General 24 Electric, what General Electric had done was take a 36

degree splice which is one-tenth of the total.

here because we know have computer capabilities to completely do the final analysis of the entire shaft. So we used that particular technique and Sandia was also in earlier in the degraded containment research and they produced a couple of reports on this particular aspect. So we hope that Sandia will be able to do justice to this type of problem that we are encountering in Oyster Creek. And in my opinion when I read the draft report that they gave to me, it's like poetry to a structural engineer.

(Laughter.)

they modeled the personal equipment edge which I don't think were separately modeled in the case of General Electric. Then there are ten vents around here which are connected to the torus and generally in the vent header area, but in I just wanted to show the the second one -- Here. spring that we have attached to here just to be more realistic about the flexibility of the vent to move These two springs were attached, the Sandia separately from this particular model analysis and inserted those springs into the model. Apart from that, Sandia has considered the stiffeners and all the beams and all the details that necessary, Sandia National Lab has considered in this

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	particular model.
2	Second, I want to show you the degradation
3	that we used in our analysis. From cylindrical we
4	have used T equal to 85 is after the 0.406 is the as-
5	built thickness. Then 0.0075 is the one that
6	Applicant has computed from the 1980s to 2004 the kind
7	of readings that they have from the upper area.
8	MEMBER WALLIS: I'm sorry. I'm trying to
9	
10	MR. ASHER: These are corrosion rate.
11	MEMBER WALLIS: These thicknesses are
12	MR. ASHER: 0.406.
13	MEMBER WALLIS: measured values or
14	MR. ASHER: 0.604 is an as-built.
15	MEMBER WALLIS: No. It's ASME as-built
16	before corroded, before corrosion.
17	MEMBER ARMIJO: No, the nominal thickness
18	Well, we have a conflict with the Amergan
19	submittal and your name there. Their table shows a
20	nominal design thickness as 0.640 and the minimum
21	measured thickness as 0.604.
22	MR. ASHER: Okay. 0.604 minus we took the
23	25 years off extended period of operation.
24	CHAIR MAYNARD: The actual 0.604 is the
25	minimum measured.
J	I and the second

1 MR. ASHER: Yes, because we are to 2 extrapolate to 20 more years. So it's a hypothetical 3 in that sense. But that is what's likely to occur. 4 That's what we are considering. So we used 0.585 over 5 Then in the upper sphere there was no indication of any particular corrosion. The knuckle 6 7 area did not seem to be -- And even if there is slight closing, the knuckle area, it would not affect the 8 9 analysis too much and middle sphere, again we had corrosion rate available that we used, 0.678 minus 10 11 circular point. That's what we used as a thickness. 12 Now in the sand bed area, I think I would like to go to the next slide. No, let me go back to 13 14 explain something more. I want you to realize here 15 this is bay that we have considered, bay. It's the 16 red line here. There are one bay, two bays, three 17 bays are shown here. Each bay has an area of approximately 50 square feet and the corroded area 18 19 that we say we computed the amount of --20 MEMBER WALLIS: Can I go back? The reason 21 the steel is so much thicker down there is because of 22 these pipes coming in. Well, a number of things. 23 MR. ASHER: First thing, it is the bottom of the shell. So it 24

needs the more bearing.

1	MEMBER SIEBER: That's where all the
2	weight is.
3	MR. ASHER: So right from this area, it's
4	1.54 inches. Up above there, thinner.
5	MEMBER WALLIS: It's big jump from 0.65.
6	MR. ASHER: Yes, it is. And that is where
7	some of the disconnected stresses do build up too.
8	We'll talk about that a little later, but right now
9	what I want to consider is only the model of the
10	Okay. This one. Here if you see, these are the
11	thicknesses we Let me give you where we got these
12	readings from. We got these readings from the 1992,
13	I think, before Oyster Creek applied epoxy coating.
14	They took the readings in each and every bay to see
15	how much is corroded and where to grind it out and,
16	you know, you asked a number of questions on those
17	things. So you know that. So that time they had
18	taken the readings in a very detailed manner.
19	We had those tabulated everywhere and so
20	what we used was an average thickness of those
21	readings that came out of the 1992, I believe. Was it
22	1992?
23	PARTICIPANT: Yes, it was 1992 when it was
24	
25	MR. ASHER: Taken from outside.

1	MR. ASHLEY: I'm sorry. Ahmed, I'd like
2	you to use the mike.
3	MR. WO: Ahmed Wo with Exelon. In
4	response to your question, Hans, it's 1992 that we
5	took UT measurements from the outside.
6	MR. ASHER: Okay, and this is what we
7	MEMBER WALLIS: So it seems bigger than
8	the 0.8 to the 0.764 or whatever it was we talked
9	about earlier.
10	MR. ASHER: I will come to that. Just a
11	moment. I'm coming to that.
12	MEMBER WALLIS: Okay.
13	MR. ASHER: I want to emphasize one thing
14	that we tried to compute the corroded area versus the
15	bay area. The bay area is typically 50 square feet in
16	area, okay, one bay that I'm showing you here, this
17	bay, based on one bay, nine bay, that approximately 50
18	square feet in area. The most corroded areas are bays
19	13 and 1. Isn't it, Jason?
20	PARTICIPANT: Yes, at their center spot.
21	MR. ASHER: Bay one and bay 13 is the
22	worst case area. In that area, the square feet area
23	covered by the serious corrosion is close to about
24	four square feet or so. Okay. So what comes out is
25	the area corroded in the whole bay is 10 percent of

1	the total area.
2	MEMBER WALLIS: Why did it corrode in
3	those places?
4	MR. ASHER: Yeah.
5	MEMBER WALLIS: You have this leaking
6	water running down the side of this thing and certain
7	places it's very preferentially corroded.
8	MR. ASHER: Yes, the logical explanation
9	that I can figure out was that this is quite a steep
10	area. Let's go back to the earlier slide. Yes,
11	that's good enough. From here, this area is very easy
12	for water to pass through. When there is sand there,
13	it passes through the sand and accumulates at the
14	bottom area, but the bed of the sand bed area and that
15	is where it stays stagnant for a long period of time.
16	That is where most of the corrosion is located. In
17	each and every bay, that's the way what we noted.
18	MEMBER WALLIS: Why is bay one so much
19	worst than the other one?
20	MR. ASHER: Because my
21	MR. BARTON: Because that's where the
22	cracks are in the liner.
23	MEMBER SIEBER: That's where the leak was.
24	MR. ASHER: Where the leak concentrated.
25	The leak was not uniform all around this area.

1	MEMBER WALLIS: It was up above somewhere
2	and it ran down into the
3	MR. BARTON: The liner. It comes from the
4	top up in the cavity where the liner is.
5	MR. ASHER: From the fueling cavity.
6	Starts from the top.
7	MR. BARTON: And the liner has cracks and
8	the cracks are not in all one spot. They're around
9	the liner. So I guess where the biggest cracks in the
10	liner are is where the most water comes in.
11	MEMBER WALLIS: But cracks, this was
12	general corrosion right over the whole surface. It's
13	not
14	PARTICIPANT: No.
15	MEMBER WALLIS: From the top.
16	(Several speaking at once.)
17	MR. ASHER: There are no cracks. There
18	are no cracks anywhere. They found general corrosion.
19	I want to correct this.
20	(Several speaking at once.)
21	MEMBER WALLIS: Cracks in the liner.
0.0	MEMBER WADDIS. Clacks III clie IIIIel.
22	MR. BARTON: Cracks in the liner. The
23	
	MR. BARTON: Cracks in the liner. The
23	MR. BARTON: Cracks in the liner. The liner in the cavity.

1	liner cracks. I agree.
2	MEMBER SIEBER: There you go.
3	MR. ASHER: But the cracks in the drywell
4	are a different problem all together.
5	MEMBER WALLIS: That's why the bucket was
6	filling. The bucket was filling from bay one and not
7	from the other ones. You have five drains or
8	something here, don't you?
9	MR. ASHER: Yeah, there are ten drains and
10	the buckets were filling down even after the
11	MEMBER WALLIS: And there's a place where
12	the water was found.
13	MR. ASHER: After they put the epoxy
14	coating in.
15	MEMBER WALLIS: And the place where the
16	water was found is consistent with the place where the
17	corrosion was found.
18	MR. ASHER: Normally so but I have to ask
19	Applicant where it is, that particular question. The
20	question is whether the latter on whatever water
21	collection was found was in those particular bays or
22	they were normally in any bays. Any idea?
23	MR. TAMBURNO: This is Pete Tamburno. In
24	general we saw more water in bays one, 19 and 13.
25	MR. ASHER: One, 19 and 13.

1	MEMBER WALLIS: There was water elsewhere
2	too.
3	MR. TAMBURNO: Yes sir.
4	MR. ASHER: That could be. I mean that's
5	anybody's guess.
6	MEMBER SHACK: He has corrosion
7	everywhere.
8	MR. BARTON: Yes, you had corrosion.
9	MR. ASHER: Corrosion is in all bays to
10	some extent, but these two bays were serious corrosion
11	and that's why we took that slice we are showing.
12	This is the area where we took the lowest reading to
13	see the structure discontinuity effect of the thicker
14	part here with this thinner here.
15	MEMBER WALLIS: You took a certain amount
16	of square feet and said that's thinner than everything
17	else.
18	MR. ASHER: Yes. Exactly. And this is
19	the thinnest area, 0.705 which is the thickest and up
20	above we took 0.618 is the thinnest to see how it
21	behaves in analysis.
22	MEMBER ARMIJO: Now those are different
23	than the numbers presented in other submittals.
24	MR. ASHER: Yes.
25	MEMBER ARMIJO: They are actually less

1	than what seems to be later data. Am I confused?
2	MR. ASHER: No, this is really the earlier
3	data but why this? Because 0.998.
4	PARTICIPANT: Some of these averages
5	question how you've done the average here.
6	MEMBER ARMIJO: Just go ahead, but I don't
7	want to quibble. But there's an inconsistency between
8	this table and that chart and somewhere along the line
9	
LO	MR. BARTON: Were they done the same time?
L1	This is `92. What's that date?
L2	MEMBER ARMIJO: It doesn't say, but just
L3	somewhere along the line, sort that out. Your
L4	approach is what I'm interested in.
L5	CHAIR MAYNARD: But are these numbers
L6	though from a measured value and that you took off an
L7	estimated corrosion rate to get to these numbers or
L8	are these the actual measures?
L9	MR. ASHER: For the upper part of the
20	drywell, yes that's what we did. For the lower part
21	of the drywell, we used a measure. We did not
22	extrapolate them because the Applicant is insisting
23	that there's not going to be any more corrosion in
24	this area from now on. So we have not calculated any
25	corrosion rate at this time, but we have used what

1	they have given to us.
2	MEMBER WALLIS: The problem we have is
3	that the table in the supplemental gives numbers
4	different from the numbers you used.
5	MR. ASHER: Yes.
6	MEMBER WALLIS: We don't quite know what's
7	going on.
8	MR. GILLESPIE: Hans, let me. You
9	described it earlier and you just may need to step
LO	back and describe it again. These numbers are not the
L1	Applicant's numbers. These are numbers that the
L2	analysis, the analysts at Sandia, came up with given
L3	that the major corrosion area in each of the 50 square
L4	feet was actually only about four square feet and you
L5	said that.
L6	MR. ASHER: I said that.
L7	MR. GILLESPIE: And so these are numbers
L8	that came from the NRC supported analysis, not from
L9	the licensee.
20	MR. ASHLEY: Did the Sandia folks start
21	with a measured UT data and then treat them in some
22	way that converted them into these numbers?
23	MR. GILLESPIE: Yes and that's the key and
24	Hans and Jason can probably go through that if you
25	want to hear that detail.

	160
1	MEMBER WALLIS: They start with the UT
2	data.
3	MR. GILLESPIE: Yes, they started with the
4	UT data.
5	MEMBER WALLIS: Okay.
6	MR. GILLESPIE: But then they had to do
7	something with this four square feet over
8	MEMBER WALLIS: They made it thinner in
9	places.
10	MR. GILLESPIE: Yes, because they had to
11	average it over the 50 square foot pie-shaped segment
12	in order to get the analysis done.
13	MEMBER WALLIS: Got it.
14	MR. GILLESPIE: So it's an averaging
15	process they use in the analysis.
16	MEMBER WALLIS: But it would help. Sam
17	asked earlier for sort of a matrix of where the
18	measurements were so you could see what was actually
19	done and you could get some idea how it was averaged
20	and all that.
21	MR. GILLESPIE: Yes.
22	MEMBER WALLIS: That would be very helpful
23	if we're going to really dig into this.
24	MR. GILLESPIE: And this I think you'd
25	find We haven't distributed it because Hans has a

1	draft NUREG CR but I think we can share that later
2	with the Committee.
3	MR. ASHER: I will say when I come to the
4	results I want to emphasize the preliminary results.
5	We are still doing some studies and it might change
6	from what I said.
7	MEMBER WALLIS: So this is a draft NUREG
8	CR. Is the NUREG CR going to be available before we
9	look at the final SER on this thing?
10	MR. ASHER: We plan to I can provide
11	you with a copy of a draft report if you want to look
12	at it.
13	MEMBER WALLIS: But the final is going to
14	be available?
15	CHAIR MAYNARD: Aren't you waiting from
16	some of the inspection results from this outage to see
17	if there are any adjustments that are needed in this?
18	MR. ASHER: We are planning that. But in
19	case studies, if there are very large differences in
20	the thickness measurements that we see in the October
21	outage, then we will have to make adjustments and
22	recalculate the same stresses review. We are planning
23	that yes.
24	MR. GILLESPIE: But if the licensee As
25	Hans said, the ingoing assumption on the part of
l	I and the second

1	Oyster Creek was that the coating has arrested because
2	it eliminates the oxygen. So the expectation is that
3	the current measurements should be within some
4	uncertainty.
5	MEMBER WALLIS: Nothing has happened for
6	ten years.
7	MR. GILLESPIE: That nothing has happened
8	for ten years. Hans is only suggesting that if
9	there's a significant difference that we'd have to
10	eyeball it again.
11	MEMBER SHACK: Since you're doing a finite
12	element analysis, why do you have to do the averaging?
13	MR. ASHER: Well, because the rest, except
14	the thin area I'm showing you, in each bay the areas
15	are much thinner, much smaller, than this area that
16	I'm showing you here and the rest of the bay is
17	originally 1.152 inch more or less thickness. There
18	might be some isolated pits in one place or the other,
19	but as far as the very serious corrosion like this
20	MEMBER WALLIS: Only in a few places.
21	MR. ASHER: it's in those places. No,
22	in each and every base at the bottom, there is some
23	corrosion. But these are the controlling corrosions.
24	(Several speaking at once.)
25	MEMBER SHACK: But you're saying you're
	I and the second

1	averaging over the bay and I'm saying you have this
2	thing into umpty-dump finite elements. Why not each
3	finite element?
4	MR. ASHER: Jason, do you want to address
5	this question?
6	PARTICIPANT: For the analysis that we're
7	doing it's really not practical to build in that
8	topology of the point to point throughout space.
9	There needs to be some sort of an averaging process
10	for it to be practical. I don't have corrosion data
11	that specific to do that for one. Two, the elements
12	we're using
13	MEMBER SHACK: But I mean you can make it
14	as refined, obviously you can't as refined as your
15	corrosion data.
16	PARTICIPANT: Obviously with enough time
17	and enough data if it was specific enough, we could do
18	that. Yes. But it's really not practical.
19	CHAIR MAYNARD: From what you have seen,
20	do you think that would make any difference in your
21	results?
22	PARTICIPANT: What we do is we're trying
23	to have the numbers shaded on the conservative side
24	obviously so that we're covering any of those arms.
25	MEMBER SHACK: That's what I was losing

1 whether you were averaging the thin area over the 2 whole bay which didn't seem conservative or you made the whole bay correspond to the thin area. 3 PARTICIPANT: Now my understanding is that 4 5 the source that we've taken these values from were thinner points that were shown by visual inspection. 6

MEMBER SHACK: And then you assign that now to the whole bay.

They were visually inspected and then measured at the

There were points throughout PARTICIPANT: a certain region and then that was averaged and assigned uniformly to the whole bay. So, yes, within that bay there are thinner regions and thicker That's why those two smaller regions that regions. Hans had mentioned were added in for us to capture some of the effects of what if there's a smaller region that's much, much thinner that's not captured in this averaging process that we've done.

MEMBER WALLIS: I think it would be much clearer if all this were spelled out, you sort of showed there 150 measurements, this is how they scatter statistically and what did you do in terms of averaging, did you average the low ones, did you average the whole thing, were there lots of them

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

thin locations.

1	showing no corrosion at all and a few showing We
2	could see it. That would give a picture.
3	MR. ASHER: The report will explain those
4	things for sure.
5	MEMBER WALLIS: There is some work.
6	MR. ASHER: Yes.
7	MEMBER SHACK: Let me just see if I have
8	it in my mind though.
9	MR. ASHER: We will make sure that we
10	explain this a little more.
11	PARTICIPANT: Yes, we'll have to.
12	MEMBER SHACK: You have an average for the
13	bay now and then you put in a local average for these
14	low spots.
15	MR. ASHER: Low areas, yes.
16	MEMBER SHACK: Okay. Got it. So you're
17	probably conservative.
18	MR. ASHER: Because this is what we are
19	afraid of, the structure discontinuity and of course
20	because of the thickness differences. We wanted to
21	see what kind of effect it has.
22	MEMBER WALLIS: First it was the stuff
23	that shows the variation of the thicknesses and what
24	are the actual reportings in thickness?
25	(Off the record comments.)

1 MEMBER SIEBER: I guess I have a couple of 2 questions. When you consider the corrosion of the 3 drywell shells that changes the mass of the system and 4 your infinite element analysis takes into account the 5 fact that that mass is changed. From a seismic standpoint, it changes the vibration mode, frequencies 6 7 and response, amplitudes. (Two conversations going on at once.) 8 9 MEMBER SIEBER: And you also took that 10 into account. How did you take into account the fact that the sand pocket was removed because that also was 11 12 a cushioning effect and the support for the drywell. PARTICIPANT: It has no support. 13 14 MEMBER SIEBER: But it said in your 15 assumptions that you just used the coefficients from the FSAR which reflect the fact that the sand pocket 16 was there. Right? Go ahead. I just need for you to 17 clarify what's going on here. 18 19 Yes. Let me explain two ASHER: 20 things separately. Okay? For seismic loads, what we 21 have done is we have taken the upper bound values that 22 were being computed by the Applicant. That was done 23 during the construction. Since that time, the 24 Applicant had done a number of other analyses to

reduce the loads on certain supports and certain

piping supports and everything, the sophistical analysis in 1993 for example. And I had reviewed that in 1993. So I know that they had done that.

Now I asked them a question as to these values are bounding values or they are the one some other analysis were bounded and I was told that no they are the maximum that you can get out of -- these values are the ones that are good values.

Now how we have applied the seismic load here, that is important here from what you are telling me. The way we have applied seismic load here is at the bottom there is a static load. There is no dynamic analysis here. It's a moment. It does not have the dynamic seismic analysis where we would put damping and we take the -- We have not done that because we felt that we wanted to concentrate much more on the drywell corrosion. But at the same time, I agree that we ought to have a representative seismic load and --

MEMBER SIEBER: The degradation and the modifications that they made change the seismic response and I'm wondering did you take it into account, yes or no, and if you didn't, how do you know you're still conservative as far as overall strength of the drywell is concerned in these three cases?

1 MR. ASHER: Jason, do you want to say 2 anything? Okay. This is what we have used, but we 3 can --4 MEMBER WALLIS: I'm looking at the 5 original report and you have the measurements in higgly-piggly in fashion. 6 There isn't a pattern that 7 makes any sense and the numbers vary a lot. Rather 8 than use this average, you have to do some sensitivity 9 study where you say suppose we put in something like 10 my colleague Bill Shack suggests, some sort of a 11 distribution of thickness or something and does it 12 make a difference. Wait. We can't be trying 13 CHAIR MAYNARD: to answer three or four questions at once. We have 14 15 one question right now. MR. ASHER: And Mike Hessler from Sandia 16 17 wants to. MR. HESSLER: This is Mike Hessler from 18 19 I supervise the work, the analysis, that 20 The question as I understand it was that, Jason did. 21 and we agree with you, that the changes in the 22 geometry due to the degradation, due to the removal 23 from the sand from the sand pocket, would affect the 24 seismic loads. 25 For the analysis, the approach that we

took here, we knew we didn't have enough information to do the rigorous level of analysis that GE had done. We don't know what the piping is. We don't know all the equipment weights. So we had to utilize information that was published in the FSAR. I think the emphasis that we tried to do is to look at what, not so much the absolute values, but the changes due to the degradation. We were concerned early on that even if we did a detailed analysis of the undergraded shell we would not get exactly the same numbers that GE did just because of the difference in the modeling and the uncertainty in the loads.

So I think one critical aspect of the analysis that we did was to do an analysis initially with this three dimensional model with all the same assumptions of the undergraded drywell shell and then apply the degradation to that and see how that changed the factors of safety for both stresses and buckling for the three load cases that we had. So I wanted to emphasize that I think that's a critical element of this because we had to rely on incomplete information on all of the loads. We didn't go back and do a time history analysis to get the seismic response of the shell. Obviously, we could given the time and resources, but the emphasis as we understood it here

1	was to really understand what the effects of the
2	degradation are.
3	MEMBER SIEBER: Okay. What you did is
4	what I thought you did and probably what I would have
5	done. My follow-on question would be how do you know
6	that's conservative with regard to whether the
7	containment will fail or not under these cases up
8	there.
9	MR. HESSLER: How do I know it's
LO	conservative. I have to rely on the fact that the
L1	original design was reviewed and approved and
L2	reflected all of the loads. We used the same loading
L3	information that GE used in their analysis. We just
L4	applied it to this three dimensional model. Again, I
L5	
L6	MEMBER SIEBER: I'm really going to have
L7	to think about that.
L8	MR. HESSLER: But I just wanted to make
L9	sure you understood.
20	MEMBER SIEBER: I'm a slower thinker than
21	some people.
22	MR. HESSLER: I just wanted to make sure
23	you understood what we did and also
24	MEMBER SIEBER: Be patient. I think I do.
25	MR. HESSLER: the focus that we really
J	

thought we needed to look at was is the effect of the degradation significant rather than looking at the absolute numbers in all cases.

MEMBER WALLIS: And you found that they were.

MEMBER SIEBER: I'm interested in whether it fails or not. To me, that's specific.

MR. HESSLER: I understand. I'm just clarifying the scope of the work.

MR. GILLESPIE: I think -- Sandia only really did the tasks that we asked them to do and remember this is a confirmatory measurement. not designing a plant and we're confirming the projection made by the licensee and a 1991-1992 GE calculation. And the question on the table for us was because that calculation showed a very small margin existed given it's a small margin let's have independent group take the best data we have available limited data and do an independent was calculation to confirm the size of that margin. So I think they've done what we asked them to do. But this was not a de facto re-initial licensing review or design review. So there were limitations of what we asked them to do and I think they did exactly what we asked them to do and that's why it's by difference.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	MR. ABDEL-KALIK: The analysis assumes
2	that the locally-thinned areas are the same location
3	as the vent lines. In fact, they are right above the
4	midplane of the vent lines in bays one and 13. Is
5	this really the most limiting location for these
6	locally-thinned areas?
7	PARTICIPANT: That picture is a little
8	misleading. It's actually just below the vent lines.
9	MR. ABDEL-KALIK: Yes, but they have the
10	same azimuthal location angle wise. Is that the most
11	limiting azimuthal location for those locally-thinned
12	areas?
13	MR. ASHER: That is true. The early
14	question was asked as to why all the corrosion took
15	place at the bottom of the, at the sand bed area and
16	that is where the serious corrosion is concentrated.
17	MR. ABDEL-KHALIK: So you're saying that
18	the location was not selected based on where it would
19	be most limiting, but based on actual observation.
20	MR. ASHER: Actual observation.
21	MR. BARTON: Where it was, yes.
22	MR. ABDEL-KHALIK: Okay. Thank you.
23	MEMBER WALLIS: But you've said that this
24	is sensitive to modeling and this business of
25	averaging and putting things in certain places gives

you a result. If you put the thin areas somewhere else and you'd average in a different way, you'd get a different answer and Frank Gillespie just said that you're worried about having very low margin. So it seems to me that you have to pretty thorough about doing your sensitivity analysis. Saying suppose we did it a different way. What difference would it make?

MR. ABDEL-KHALIK: Intuitively this is not

MR. ABDEL-KHALIK: Intuitively this is not the most limiting location for the locally-thinned area.

MR. ASHER: Well for locally-thinned area what we did was we looked at the results of that 1992 observations that UT results were done because that time they truly went inside everywhere and took the UT results right from where the corrosion is occurring at that time and measured the metal thicknesses. To us it was very reliable measurements and based on that, we made certain assumptions and that's why we are saying the assumptions we made.

You are quite right. To somebody else, some other analysts can make some different assumptions. They come out with it different. But the way we have done it, we are going to the conservation site and wherever we had the readings,

1 where we had a particular doubt or something, we erred 2 on the conservative side. So that's the way we have 3 done the analysis considering the measurements that 4 were taken during that time. 5 CHAIR MAYNARD: I think it would be a different situation if you still had active corrosion 6 7 going on. 8 MR. ASHER: Right. CHAIR MAYNARD: And I think it would be 9 10 more important to go for the potentially worst case. Where you have a defined scope, you know what the 11 12 situation is and you have a mechanism in place that's supposed to stop additional corrosion, that's a little 13 14 different situation. 15 MR. ASHER: Yes. I mean that would be 16 MR. ABDEL-KHALIK: 17 true if we really knew the topology of the surface and knew exactly where the thinned areas are to a high 18 19 level of confidence. I'm not sure that we do. 20 I thought the question was MEMBER WALLIS: 21 even with no corrosion is it safe now, even with no 22 Isn't that the question we're asking more corrosion. 23 you? 24 MR. ASHER: Yes. Let's see the slide on 25 approximate safety factors. Again, I want to

1	emphasize these are the initial preliminary results.
2	So don't count on the numbers. But the degradation,
3	these are the values. You can see the difference on
4	the refueling load combination for example. The
5	safety factor again is buckling. If it is not
6	degraded with same taken out, the SF itself would be
7	3.85. Now with degradation, it comes out to be 2.15.
8	So you can see right away the impact of degradation
9	here.
10	MEMBER WALLIS: But that means that it's
11	twice as strong as it needs to be to avoid collapse.
12	Is that what a safety factor of two means?
13	MR. ASHER: Yes.
14	MEMBER SIEBER: That's the typical code
15	requirement.
16	MR. ASHER: There's a code requirement.
17	Two is the minimum code requirement. They are at
18	margin 2.15. Now sometimes you can have 1.5 safety
19	factor. It doesn't mean it's going to buckle right
20	away.
21	MEMBER WALLIS: Right.
22	MR. ASHER: But still it doesn't meet the
23	code requirement.
24	MEMBER WALLIS: The more confident you are
25	the less safety factor you need.

1	MR. ASHER: Absolutely yes.
2	MEMBER SIEBER: That's why it's two.
3	MR. ASHER: The accident condition, there
4	is no question of buckling there. It's mainly the
5	tension stresses and memory stresses and post accident
6	load case, all stresses are within level D
7	requirements and buckling you can see the safety
8	factor again 3.65, 2.74 with degradation. So you can
9	see the effect of degradation here.
10	MEMBER WALLIS: I think you have a kind of
11	engineering judgment and even if you fiddle around
12	with the way you put these various thin regions you
13	get a safety factor of around two.
14	MR. ASHER: Right. Two. Exactly. That's
14 15	MR. ASHER: Right. Two. Exactly. That's what we are looking at.
15	what we are looking at.
15 16	what we are looking at. MEMBER SHACK: Now did you take this all
15 16 17	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load
15 16 17 18	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was?
15 16 17 18 19	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was? MR. ASHER: No, I think because we were
15 16 17 18 19 20	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was? MR. ASHER: No, I think because we were working with the load combinations that are designed
15 16 17 18 19 20 21	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was? MR. ASHER: No, I think because we were working with the load combinations that are designed load combinations.
15 16 17 18 19 20 21 22	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was? MR. ASHER: No, I think because we were working with the load combinations that are designed load combinations. MEMBER SHACK: So you're only looking at
15 16 17 18 19 20 21 22 23	what we are looking at. MEMBER SHACK: Now did you take this all the way to failure to see just what the ultimate load was? MR. ASHER: No, I think because we were working with the load combinations that are designed load combinations. MEMBER SHACK: So you're only looking at design loads.

	1,
1	MEMBER SHACK: Not 67.06.
2	MR. ASHER: Internal pressure you are
3	thinking about. Right?
4	MEMBER SHACK: Yes.
5	MR. ASHER: No, we didn't do that.
6	MEMBER SHACK: Right.
7	MR. ASHER: We held on that for Peach
8	Bottom. Sandia National Lab has done that for Peach
9	Bottom all the way up to internal pressure going on to
10	collapse, not collapse, but up to certain staid limit.
11	PARTICIPANT: Predictively.
12	MR. ASHER: Predictively.
13	MEMBER SHACK: I mean you did for 67.06
14	you did ultimate loads.
15	MR. ASHER: Yes. And we've done that for
16	other plants, but not for Oyster Creek.
17	MEMBER WALLIS: It says in your figure
18	refueling buckling location. That seems to indicate
19	to me that you have buckling.
20	MR. ASHER: Well, again, I have to explain
21	this to you. Because of the stresses that are
22	developed, higher stresses in that area, so the
23	likelihood that the buckling will occur if surely the
24	loads are much more than this, they will buckle in
25	those areas. That's what we are showing. It's not

1	that it's a buckled area.
2	MEMBER WALLIS: If it fails by buckling by
3	the steel detaching itself from the concrete into the
4	well, is that what happens because you would think the
5	concrete would give it some stiffness if it tries to
6	buckle outwards?
7	MEMBER SIEBER: It's a weight load from
8	the refueling.
9	MEMBER WALLIS: Doesn't that buckle it
10	outwards?
11	MEMBER SIEBER: It can go either way. If
12	it's constrained by the concrete then it's going to go
13	in.
14	MR. ASHER: Yes, it can go in.
15	MEMBER SIEBER: It is stronger in that
16	configuration where it's forced to go in. But it can
17	still go in. There is a lot of weight there.
18	MR. BARTON: Damn right.
19	MR. ABDEL-KHALIK: So if the locally
20	thinned area is azimuthally shifted to that location,
21	would it be possible for the safety factor to be less
22	than the code requires it?
23	MR. ASHER: When we tried to locate this
24	locally thin area where several corrosion has been
25	recorded, why should I put it in a different place?

I have no reason to do that.

MEMBER ARMIJO: Well, you might if you hadn't sampled every area. So if your sampling skipped large areas and you have no data.

MR. ASHER: No, but in other bays, we had the other bays too. We took one and 13 bays because they had the worst corrosion. We could have taken the thin area in each and every bay and it would be much smaller than this. Okay. This was about four square feet or so. We could have taken two square feet, a small area, with thinning not as much as this, the other way, but that would not have made any difference in understanding the mechanism of buckling.

MEMBER WALLIS: Where's the thin area?

MR. GILLESPIE: Yes, I think again this is a confirmatory licensing calculation. This is not for us a research project where we're actually going to look at -- We are trying to confirm the licensee's assertion on their margin. We are actually not trying to independently establish the margin ourselves. So this whole analysis was done you might say on the asfound condition in 1992 of that shell as best we can judge from all the inspection information, etc. But I think structurally a small hole is not our interest here. It was broad degradation that would affect this

1 kind of safety margin. So a small thin spot wasn't 2 going to matter. Again we're confirming their 3 number. 4 We're not trying to independently calculate something 5 that's totally ours. 6 CHAIR MAYNARD: Can we go on? 7 MR. ASHER: Thank you very much. I want 8 to talk a little about commitment in the open items. 9 I want to just point out a few things in the open items. 10 (Off the record comments.) 11 12 CHAIR MAYNARD: Okay. Could we pay attention here? Okay. 13 Go ahead. 14 MR. ASHER: Yes. These are the five open 15 items we have right now and during the Applicant's presentation, it said that the first open item is the 16 17 one that they are working on and they are going to put in stove one, they are going to put four probes which 18 19 results in the area of the drywell shell and they say 20 that other four are accepted by NRCI. I disagree with 21 The OI on the embedded shell is not something that. 22 completely zeroed in on because that have 23 quantitatively the Applicant provided 24 convincing response qualitatively that is

concrete environment and it is a new chance of having

1 oxygen getting into that area and at the most what it 2 can do is not less than 0.732 or whatever they had 3 there. That was their argument and 4 qualitatively I tend to agree with that argument. 5 But I do feel that they should show some maybe chipping concrete in a particular area where the 6 7 damage had been the most, for example, in the sand bed area to show that there's no corrosion here or there's 8 9 a minimum corrosion. Something has to be done in that 10 area. We also provided an NXER report that the 11 12 Office of Research had developed earlier where they can really find the thickness of the matter between 13 14 the embedded shell. These are guided but they are 15 more experimental in nature. I did request the 16 Applicant to explore some of them to see if they can find something, to see if the metal thickness can be 17 measured somehow. 18 19 So embedded shell is still the annoying 20 It's very difficult to -- Qualitatively as I say one. 21 I agree with their arguments, but quantitatively I 22 don't have anything to go by. 23 The other three Ι agree with the 24 Applicant's conclusion that we have taken care of

through commitments and everything else.

1	MEMBER ARMIJO: I think I keep going
2	back to this one table in that June 20 $^{ m th}$ letter. I
3	think it was a response to a request for additional
4	information. The Applicant submitted data showing the
5	margin for the lower sphere which I presume is the
6	embedded part of the containment. Is that correct?
7	MR. ASHER: No, the lower sphere includes
8	the sand bed area.
9	MEMBER ARMIJO: They have a separate line
10	for sand bed than they have for the lower sphere. But
11	you're saying the lower sphere is let's say below the
12	equator. Is that
13	MEMBER SIEBER: Below the knuckle.
14	MEMBER ARMIJO: Below the knuckle. All
15	right. I understand now.
16	MR. ASHLEY: Thank you Hans. Which brings
17	up to our conclusion. The staff has concluded that
18	the depending resolution of the open items that there
19	is reasonable assurance that the activities authorized
20	by the renewed license will continue to be conducted
21	in accordance with the current licensing basis; that
22	any changes made to the Oyster Creek current licensing
23	basis in order to comply with 10 CFR 5429(a) or in
24	accordance with the Act and the Commission's
25	regulations.

CHAIR MAYNARD: Appreciate it. I would just like to make sure everybody realizes that that's the conclusion that you're presenting. That's not the ACRS conclusion at this point. The ACRS has not made any conclusion and still has quite a bit more to take a look at. So I want to make sure that people understand that's not an ACRS conclusion.

With that, I'd like to -- I believe that we have -- That does complete the NRC staff's presentation.

MR. GILLESPIE: Yes.

Can I say something about MEMBER WALLIS: I've been looking at the original data here from GPU and trying to figure it out and trying to see how on earth it's related to the stuff that was displayed in the Sandia study and it looks very interesting and I think they need to be put side by side so someone can explain to me how you go from the measurements and the places where it was measured to the actual numbers that were put into the computer program so we can understand that process and it's a Otherwise, there are just too many believable one. ifs and it may well be it's right. It looks to me looking at it superficially as if someone has made an effort to be conservative and take the lowest value

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	and all that but it needs to be clearly spelled out.
2	MR. ASHLEY: In the final SER.
3	MEMBER WALLIS: Yes, and in the
4	presentations I think too so that it's clear.
5	CHAIR MAYNARD: Yes, I think at some point
6	the ACRS is going to have to have that information.
7	That's something that we're going to have to be taking
8	a look at before we're going to be able to make a
9	determination and I don't think you're prepared to do
10	that today.
11	MR. ASHLEY: No sir. I don't think so.
12	CHAIR MAYNARD: So with that, we'll I'm
13	sorry. Did you want to make any concluding?
14	MR. GILLESPIE: No. I mean we'll make all
15	the reports and everything that we have available and
16	if there's a desire for us to come back or meet with
17	a couple of the members and go through the matching of
18	how we did the, how the Sandia staff did the Sandia
19	report, we'll be more than happy to do that.
20	CHAIR MAYNARD: Okay. With that, it
21	brings us to the next agenda item which is Public
22	Comments and first on the list here is Paul Gunter
23	from the Nuclear Information Resource Service. And
24	I'll apologize to you for running late, but we can
25	certainly give you your time here.

MR. GUNTER: Thank you. My name is Paul Gunter. I'm Director of the Reactor Watchdog Project for Nuclear Information and Resource Service. My remarks are going to be very brief, just opening and then an introduction to Richard Webster who will conduct the presentation.

Nuclear Information and Resource Service first got involved with this when we looked at the Applicant's application and we were surprised that so much credit was being taken for the epoxy coating on the severely coated region and began our investigation which led to the filing of the single contention on November 14, 2005 before the Atomic Safety and Licensing Board with regard to inadequate an application in addressing the age management review of the drywell age management review process.

So essentially, six groups, five from the state of New Jersey and ourselves, intervened on this single contention and Rutgers Environmental Law Clinic has reviewed the contention and the filings of our experts and took the challenge up. With that, I would like to turn what presentation we're going to make today over to Richard Webster who is a staff attorney with the Rutgers Environmental Law Clinic in Newark, New Jersey. He has a BA in Physics at Oxford

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 University, a Masters in Engineering in Hydrology from 2 Imperial College in London and a JD from Columbia Law 3 School. 4 MR. WEBSTER: Thank you Paul and first of 5 all, would like to thank the panel for the 6 opportunity to present here today. I don't see how I 7 I need to swallow the microphone here for a 8 second. 9 CHAIR MAYNARD: We make them short so you 10 have to lean in. MR. WEBSTER: It's hard to watch the 11 computer and do the microphone at the same time here. 12 But I can chew gum and rub my stomach at the same 13 14 time. So that's okay. 15 So what we've heard today has been very interesting and it's been very interesting to watch 16 17 your reaction because your reaction has mirrored our reaction over the time. 18 It's sort of this very slow 19 revealing of information and each bit of information 20 that you get actually adds to your concerns and the 21 conclusion that we've come to now is that there are 22 some very serious identified concerns. They cover both the current condition of the containment as well 23 24 as the whether the containment could go beyond safety

margins during any extended licensing period.

We characterize the process here as putting the cart before the horse because if you don't know what the current margins are it's pretty hard to design an adequate program to figure out whether those margins are being maintained and at the moment, all we've heard from the Applicant is what we already knew which is that the monitoring has not been a time sequence and it has not been adequate in terms of space to really allow you to draw any definitive conclusions about the current margins.

Now let me just come through in more detail and I'm going to start with the embedded region because that's simpler because simply there's really So we don't have to worry too much about the no data. data there because there is none. And again our concern is about the current state of the embedded region and it's about the potential state of the embedded region during any extended licensing period. And similar concerns for the sand bed region. whether it meets safety margins now and whether any significant degradation in the future would be detected before safety margins are violated and that's actually, that fourth item, is the subject of our contention as well. So there is a limited scope of litigation here and that's what we're litigating as

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

well.

So I think you've seen the diagrams. This is a bit of a bigger diagram of the containment and just to be clear then, this is the sand bed region.

CHAIR MAYNARD: I'm sorry.

MR. WEBSTER: Paul will point.

CHAIR MAYNARD: Stay at the microphone.

MR. MAYNARD: Paul will point to the sand bed region and then the embedded region is right below that. So we're talking about a small portion of a very large structure here, but a very significant portion.

Now normally our temporal look at this really starts and ends in 1992 because in 1992, they took the sand out. They couldn't look at the region very comprehensively before 1992 because the sand was there and there's that large concrete curb on the inside covering around two-thirds of the sand bed. So from the inside, all they really do is look at the top third and that led to the erroneous conclusion that this was called at the time a bathtub ring of corrosion. Actually, it wasn't a bathtub ring of corrosion. It was a bathtub ring of monitoring.

So then when they got in there in `92 and scrubbed it down, we did get a look at what was

1	happening in there and what was found was very
2	concerning. In terms of embedded region, the sand bed
3	floor was unfinished, water had ponded on the floor,
4	the floor had deep craters which is so far
5	unexplained, but we think they are potentially due at
6	least to corrosion or rebar in that concrete.
7	Until `92, there was no seal present
8	between the shell and the concrete to reduce
9	penetration of water in the gaps. Remember we have
10	ponded water in this area. The fact that there's a
11	seal there at all now tends to indicate there was a
12	gap. So it seems highly likely that that water has
13	penetrated into that gap and into the embedded region.
14	MEMBER WALLIS: Now this water that has
15	ponded on the floor, that's inside the containment.
16	MR. WEBSTER: No, that's outside.
17	MEMBER WALLIS: Outside. When you say
18	ponded, you mean outside.
19	MR. WEBSTER: I mean the outside floor by
20	the drain stem.
21	MEMBER ARMIJO: You mentioned deep crater.
22	Could you be more quantitative?
23	MR. WEBSTER: No, that's just taken from
24	documents that we've seen.
25	MEMBER ARMIJO: You don't have any
ļ	I

1	MR. WEBSTER: Paul, why don't you look up
2	those while I'll continue? I'll get back to you. I
3	think they're in terms of feet rather than inches.
4	MEMBER ARMIJO: In area?
5	MR. WEBSTER: In area.
6	MEMBER BONACA: And this is once you
7	remove the sand. Therefore, it's a surface.
8	MR. WEBSTER: Right. This is the surface
9	that's found once the Here we are. Here's the
10	quote. Once the sand is removed, it reveals the
11	concrete surface which has hitherto been covered up
12	and it says the floor was cratered with some craters
13	adjacent to the shell. A few craters were big, about
14	12 to 13 feet long and 12 to 20 inches deep and 8 to
15	10 inches wide.
16	MEMBER WALLIS: Twenty inches deep?
17	MR. WEBSTER: Yes.
18	MR. WEBSTER: And it says concrete
19	reinforcement bars could be seen bare in many bays. So
20	this certainly seems indicative that something's going
21	on in this embedded region.
22	Now the other thing thinking about the
23	sources of water, we've heard that there's quite a lot
24	of wet areas in this plant affecting the wires and so
25	forth. It hasn't been ruled out yet but some of this

water down at the bottom could be from groundwater and we think that's a potential source of water that so far needs to be eliminated and we haven't seen anything that eliminates that.

Now corrosion is possible contrary to what the Applicant would like to believe. Our expert has assessed what the Applicant has put forward. He states the statement that the concrete generates a high pH environment, a pH of 12 to 13, and thermodynamic calculations reveal no corrosion of iron above 10 room temperature.

The latter statement is patently wrong. Thermodynamics clearly demonstrate that iron can interact with water over the entire pH range even more in the presence of oxygen. The rate of the reaction is governed by the protectiveness of the corrosion product layer. So from what we've seen and we've been provided with absolutely no expert evidence whatsoever from the Applicant about this issue and I don't know if the NRC has had expert evidence on this issue, but from what absolutely we've seen there justification whatsoever for an assumption that no corrosion could occur in the embedded region. fact, the opposite it appears that it was wet, that there's at least some oxygen present at the top and

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 therefore also the visual observation which we didn't 2 know about until today is that the corrosion was just as bad at the bottom as it was at the top if not 3 4 worse. 5 MEMBER WALLIS: Are you saying partly that if there are these craters in the concrete then the 6 7 concrete will no longer protect the steel? Is that 8 part of your contention? 9 MR. WEBSTER: No, what we're really saying 10 is that the craters may have resulted from rebar corrosion and then once the rebar corrosion started to 11 happen, that provides a way for the water to seep down 12 into the --13 14 MEMBER WALLIS: It provides channels for 15 the water. 16 MR. WEBSTER: Right. 17 MEMBER WALLIS: Okay. WEBSTER: So the effects of sand MR. 18 19 removal ironically may have actually made this area 20 There's a phenomenon called differential aeration where actually in a crevice situation you 21 22 don't need oxygen present to have corrosion occurring 23 because electrons can be supplied through conductants actually you 24 of the surface and so can

preferential corrosion of oxygen starved areas under

1 certain circumstances. And it appears that that is 2 possible here, but of course, it's never 3 verified. 4 So we're not saying it's certainly 5 happening but it's certainly a possibility and it's a possibility that needs to be eliminated before any 6 7 conclusions can be drawn about what's happening in 8 this embedded region and what has happened in this 9 embedded region prior to 1992 and in the 14 years 10 since 1992. It actually astonishes us that this situation has gone unaddressed by the NRC for this 11 12 long. MEMBER WALLIS: Where does this 0.33 come 13 14 from? 15 MR. WEBSTER: 0.33 is what was measured in the sand bed region. You're skipping ahead. 16 what was measured in the sand bed region prior to the 17 sand being removed. There has been no corrosion rate 18 19 established. So we decided we would use that 20 corrosion rate. MEMBER WALLIS: For a year or just the 21 22 total? 23 This is per year. MR. WEBSTER: 24 MEMBER WALLIS: For a year? 25 MR. WEBSTER: Per year. That was the

1	maximum.
2	CHAIR MAYNARD: Did you get that from
3	taking what the original thickness was and what the
4	measured thickness was?
5	MR. WEBSTER: Right.
6	CHAIR MAYNARD: That's how you generated
7	your
8	MR. WEBSTER: Right.
9	MEMBER WALLIS: That happened in a year.
10	MR. WEBSTER: There were certain areas
11	over time that that happened. That's the worst case
12	and what we're saying is until a rate is established
13	let's assume the worst case. I mean the Applicant it
14	seems has the duty to establish a corrosion rate.
15	They haven't done that yet. They've had this problem
16	for They've known about this problem for at least
17	14 years and so far have done absolutely nothing about
18	it.
19	So the steel thickness in the very lower
20	region is 0.676 as we've seen. The thickness at the
21	top is higher. It's 1.154 and just to be clear the
22	corrosion rates in the sand bed region do not bound
23	the corrosion rates in the embedded region because of
24	this differential aeration phenomenon.
25	MEMBER SIEBER: Can I conclude from this

that in two years you are corroded all the way through?

MR. WEBSTER: If that corrosion rate applied. We're not saying that corrosion rate does apply. We're saying the corrosion rate is unknown.

So I don't think it surprises you that we think some action is required here. We think there needs to be a comprehensive check of current thickness of metal in the embedded region. I'm very happy to hear Hans Asher suggest that the analyses does want some measurement of that region because that's certainly news to us as of today. But we think that the analyses has to be comprehensive. Looking at this problem though a keyhole is not going to produce the answer.

Second, I think this is very obvious. They need to monitor for wet conditions in the embedded region using electronic detectors. From what our expert tells us, it's quite possible to insert electronic detectors down there that register spacial resistance and that would actually give you some idea about whether the area is wet or not and it would actually bolster up the Applicant's aging inspections of this seal. I mean it's one thing to look at the seal, but what the Applicant said with regard to the

1	component that was cracked is that visual inspection
2	identified one crack and then 100 percent UT
3	identified six cracks. That shows that visual
4	inspection doesn't give you the whole answer. It
5	gives you part of the answer. Once you see some
6	concerns, it's time to go and do some real
7	measurements and we have serious concerns already. So
8	we think it's time to go and do some real measurements
9	here. Let's just not sit around and argue about it on
10	an academic position when there's a real problem out
11	there and it needs to be solved and it needs to be
12	solved urgently.
13	And finally, the Applicant needs to
14	establish acceptance criteria for the measurements
15	that they're going to take.
16	MEMBER WALLIS: You'd be in trouble using
17	academic in a perjority.
18	MR. WEBSTER: I'm using it not in a
19	perjority sense but merely in the sense that it's
20	theoretical I should say. Remember I'm from Rutgers
21	Law School. So we do have some claims of academia
22	ourselves actually.
23	MEMBER WALLIS: Sometimes academic studies
24	are better.
25	MR. WEBSTER: Absolutely.

1	MEMBER WALLIS: Thank you.
2	MR. WEBSTER: But they're not known for
3	their urgency generally.
4	CHAIR MAYNARD: All right. Go ahead.
5	MR. WEBSTER: So now moving on to the sand
6	bed. So that was basically a quick overview. I'm
7	trying to move quickly here. So if you have
8	questions, I know it's been a long afternoon, so if
9	you have questions please stop me and ask me. But I
10	want to move through this fairly quickly because it's
11	getting to 5:00 p.m.
12	CHAIR MAYNARD: I think you've seen that
13	the Committee is not shy.
14	MR. WEBSTER: Okay. So as we've heard in
15	general in the sand bed, the most critical constraint
16	is buckling. The modeling actually established three
17	criteria and I was surprised to hear only two
18	mentioned. There's one on the uniform basis. There's
19	0.736 inches of wall thickness. Of course, that's not
20	very useful because the wall thickness isn't uniform.
21	So it's kind of hard to apply.
22	There's a single point criterion which is
23	no point should be less than 0.49 inches. Again, it
24	comes back to a point made. I think
25	MEMBER WALLIS: If it's seven inches
ļ	

buckling, it's not a point phenomenon.

MR. WEBSTER: That's right. That's actually a pressure bound phenomenon I think.

MEMBER WALLIS: Thank you.

MR. WEBSTER: But somebody made the point earlier that you can't just take the single worst measurement and say that's it. You have to do some extreme valuable statistics to actually figure out what the measurements are showing you. It could be the worst point value and actually we have done that for the Applicant because we're such nice guys. We decided to give them a little free work, a little free consulting work. So we've actually already done that for one small portion of the data just to illustrate the concept and show that it needs to be done more comprehensively.

And then originally this was all based on modeling of 36 degree slices of the shell. So there are ten bays, 36 degree slices and the problem with that is that there are two assumptions there. One is actual symmetry and the second was a spherical shape and it seems like now we have the Sandia study we've just heard about which is the first that we heard about it too has discarded the actual symmetry assumption to some extent but it does appear to retain

the spherical shape assumption.

MEMBER WALLIS: Your concern is that if it's slightly off spherical that makes a difference.

MR. WEBSTER: Yes. So as I said, these are the problems with the established criteria. The sand bed is far from uniform as I said. It's actually described, the surface was described in the report, reporting the 1992 results as a golfball with dimples going in and out.

According to our structural experts who have again done some good free work for the Applicant, the symmetry assumption prevents the simulating antisymmetric buckling. They actually said that it's possible that the bounding criteria is a combination of symmetric and anti-symmetric buckling, but a symmetric model can't model that. But I assume the Sandia model can. So I guess when we all hear all these caveats about what the Sandia model doesn't do I guess we're wondering which model does do what the Sandia model didn't do.

And finally the derivation of the small area criteria was not rigorous because, and I think the same problem actually applies to the Sandia study, you have to look at different geometries. Assuming a square area is not -- I mean it gives you some

information but it doesn't tell you what the smallest area below a certain thickness could be to define the safety criteria. It appears that a horizontal gash for instance could be smaller but lead to a more stringent criterion although that's really speculation. I mean nobody as far as I know has done any modeling to look at the effects of these geometries. But it just seems unlikely that a perfect square is the most bounding geometry. It seems much more likely that's been selected as a modeling assumption rather than based on some sort of review of what would be bounding.

Okay. So that's the first point then.

The first point is that the established criteria really aren't rigorous. So we don't have any rigorous criteria for this shell as of now. That's the first problem because you keep asking me about the margin.

I'm going to try and get to the margin but it's very hard to get to the margin when we don't even have acceptance criteria.

So the next problem is what about the measured results. The last measurements that were not in question were taken in `92. They were taken actually from the inside and from the outside. As we've seen, the inside results are very limited

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

because they're limited to the top one-third of the sand bed. The problem with the outside results --

Well, let me give you what the results are. The smallest measure of result was 0.603 inches from the inside and 0.618 from the outside. So it's why I have an issue with the Sandia results is they along extreme value statistics, don't even, let represent what was measured and the second issue that results with those that results is of course there are error bars in those results. I mean that's what the result is but that doesn't show you what the worst It's actually around five percent of all could be. thickness error bar. So it's 0.03 for each single measurement just straightforwardly but the extreme value analysis should pull that through. hasn't been done yet.

And now the GE study looked at how assuming a 0.736 thickness shell could certain areas be below 0.736? Obviously the way it worked really in history is that the Applicant thought there weren't any errors less than 0.736 initially. So they modeled 0.736. But then of course some monitoring showed up some measurements less than 0.736 and then they started to say what can we do about that. And what GE did was they cut a square foot and took it down to

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

0.576 I think and had a look at that and what they found was as long as the area below 0.736 was less than one square foot in each bay, you could maintain the safety criteria. But if it went above one square foot, well, I'm not sure they actually tested it above. That's basically the limit of their conclusion that provided the area less than 0.736 was less than one square foot you would be okay.

Now I wasn't quite sure when Hans said four square feet because the Applicant's number that they quoted for the area below 0.736 is 0.68 square feet. The problem with that number is they haven't really measured this parameter at all. The measurements from the outside as we've just heard just took the thinnest spot. They didn't make an attempt to measure the area below 0.736 and the measurements on the inside cover around three square feet. There are 12 6"X6" areas being measured. So that covers three square feet.

Now we've put out the numbers that the total area was 300 square feet. In fact, we've heard from Hans today that actually the total area is 500 square feet. So from the inside, they are measuring less than one percent of the area. So they simply don't have any measurement of the area below 0.736 and

1	that was something that was a bounding result in the
2	modeling. So somewhere along the line, this
3	acceptance criterion got lost and at the moment, I
4	would like to I don't want to mischaracterize what
5	Hans said, but it's startlingly worrying to me like
6	the NRC believes that the area below 0.736 in bays one
7	and 13 could be greater than one square foot. If
8	that's true, we would be beyond the safety margins
9	already.
10	MEMBER ARMIJO: I have a quick question
11	for you.
12	MR. WEBSTER: Sure.
13	MEMBER ARMIJO: You say the smallest
14	measured results was 0.603 from the inside and 0.618
15	from the outside. Now are those numbers that you took
16	for the sand bed region?
17	MR. WEBSTER: Yes, these are all
18	Everything relates to the sand bed region.
19	MEMBER ARMIJO: And this is an individual
20	measurement not an average.
21	MR. WEBSTER: This is an individual
22	measurement not an average. Just to take it up on the
23	averaging, if you look into the averaging you'll find
24	all sorts of problems there. I'll allude to them
25	later but the statistical treatment of these results

is a complete mess.

So the problem is each measurement is uncertain by about 0.03 inches and just to show you that the Applicant is fully aware of the extent of the error they actually accepted results that showed growth of, I said growth, in metal of 0.05 inches over two years. It was only when we analyzed the results and showed that that growth was systematic throughout the results and therefore could not be a result of random error but had to be the result of systematic, that the Applicant suddenly turned around and decided that there was an anomaly in those results. And actually the anomaly doesn't actually just extend 96. It also extends to 94 because that was done with the same methodology.

So these are quotes from Dr. Hausler who is our expert who you can imagine was kind of amazed to discover this. The general thickness for each grid decreases from 92 to 94. So you know first of all there's a claim that corrosion has been arrested. That wasn't what the 92 and 94 result showed. If those 94 results are valid, it actually shows some degree of corrosion even immediately after the coating was placed upon there.

The `96 results are the ones that

Applicant relied upon to draw a conclusion of no
corrosion. But those results systematically showed
metal growth and Dr. Hausler coins this was of course
physically impossible. Metal does not simply
spontaneously get thicker and the Applicant has now
agreed with him. But Amergan on June 20, 2006
admitted that the 1996 results were anomalous and as
I said, the 1994 results are still not validates. The
SER basically concludes that you can't rely on the `94
results either. As I say, if you could rely on the
`94 results, the conclusion would be the corrosion was
ongoing. So we really don't have any spatial tracking
here of what corrosion is doing in the sand bed
region. We might get some in October but at the moment
the proposal as I'll show you later is very limited.
I'm trying to stick right now to what we know about
this thing right now. Is within safety margins right
now?

so let's look at the margins that were established in 1992. Now remember this is 14 years ago. So we have serious concerns that you can't draw conclusions about the current situation based on these results. I mean it's been 14 years and we know that in 14 years at least over some periods of time water has been coming down this component. Again it's

something that we recently found out.

estimated at 0.11 inches by the operator. Reanalyzing using extreme value statistics, the margin has been estimated by Dr. Hausler and this is based on `02 data which is a limited dataset. So I'm not touting this as the be-all and end-all of analysis. I'm just touting this as a starting point where we need to go and again you see that it comes to around 0.26 inches significantly less than had been estimated by the Applicant.

The small areas margin was estimated at 0.07 inches by the operator. Again, the problem with that is that he didn't look at the area below 0.736. That area is very sensitive to corrosion because the slope between the thin area and the thick area is relatively small and so a small amount of corrosion at the edge can cause a considerable expansion in the area. So based on an assumption of linearity and the transition between the thin area and the thick area, Dr. Hausler comes up with a margin of around 0.03 inches.

MEMBER WALLIS: What is the transition like between the thin and the thick area?

MR. WEBSTER: Well, we don't have that

1	much information. I've seen a few very fuzzy photos
2	that look sort of like moon shot photos and they seem
3	to be sort of round, sort of like soup bowls they look
4	like on the photo, but maybe the Applicant can
5	elucidate on that a little more.
6	MR. ABDEL-KHALIK: What does this number
7	pertain to, 0.07 or 0.03? Is this the margin?
8	MR. WEBSTER: This is the margin between
9	In other words, this is an estimate of the amount
10	of corrosion that would be needed to push the
11	component beyond the code based on the current
12	acceptance criteria which remember we don't think are
13	actually correct. But they are the only criteria we
14	have so we might as well use them just to scope out
15	the problem and again I alluded to this before. The
16	inadequate spatial scope, basically the curbs on the
17	inside of
18	MEMBER WALLIS: The basis of these claims
19	he hasn't done a buckling analysis.
20	MR. WEBSTER: No, what he's doing is he's
21	looking at He's taking the buckling analysis that
22	GE did and he's looking at the criteria that they
23	generated.
24	MEMBER WALLIS: Uncertainties or something
25	and the statistics and all that stuff.

1 MR. WEBSTER: The statistics, he's looking at the measurements that Amergan have produced or at 2 3 least the ones that they've released to us and is then 4 running them through. 5 MEMBER WALLIS: But their analysis was 6 correct. 7 MR. WEBSTER: No. He's taking their raw results and then rerunning the statistics. 8 9 MEMBER WALLIS: But he's assuming that 10 they're mechanistic. Their stress analysis was 11 correct. 12 Yes. I mean we don't think MR. WEBSTER: all of it is correct. We dispute. In fact, we think 13 14 it is incorrect nonetheless because it fails to take 15 important phenomena. into account But some nonetheless in the absence of any other, unlike the 16 17 Applicant, we don't really have the funding to commission Sandia Labs to do a large study for us. 18 19 unlike the Applicant, we're just going to start with 20 looking at what they have said would meet the safety 21 requirements and then see how close they are and 22 they're very close, very, very close. Although let's 23 put it this way. They were very close in 1992. 24 don't know where they are now. 25 Remember each result has an uncertainty

around 0.03. So you can see it's very hard to design a program and this is why we say it's the cart before the horse because it's very hard to design a program to measure thicknesses to this kind of tolerance going forward. If you don't know that you need to do that, then it's very hard to know whether the program is acceptable and that's why we really can't understand at the moment how NRC staff are drawing their conclusions about the acceptability of the program in terms of aging management.

Let me go over this. Basically, we've had consulting from stress engineers. What they've said is and I think what's coming out of this Sandia study which is that there isn't enough UT data to really do a good model on what's going on in this sand bed What they've said to us is it's routine these days in the oil industry to do a comprehensive scan of the whole vessel. When you get to close to margin, you do a comprehensive scan of the whole vessel, have thickness measurements for the whole vessel, measure the shape of the vessel and then actually use the finite element model as you were suggesting over here, actually put the numbers that you measure into the finite element model and then actually model the real situation and then you can start to look at margin by

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 changing the amount, the thicknesses, of various areas 2 where you suspect or you have some concerns that 3 corrosion could occur and you see whether or how 4 robust the vessel is. When you get close to this 5 degree of margin, we fail to understand why do the most accurate techniques should not be used. 6 7 So here is the famous table. This is what I call the simplistic treatment of acceptance. 8 9 take all these results, you actually throw a few away 10 in the statistical analysis because they don't meet normal statistics, you sort of fudge it around a 11 little bit and then you compare what you label the 12 current thinnest is, but actually isn't the current 13 14 thinnest at all. It's some sort of average of thick 15 and thin over a quarter of a square foot area and you compare it with a uniform criteria when the service is 16 17 not uniform. This is absolutely not acceptable as a way to look at acceptance and this is what they're 18 19 still doing. 20 Let me hasten to add this was taken from 21 an old document, but this is still the process that 22 the Applicant is using. So --

MEMBER WALLIS: Does this chart go back to GPU?

MR. WEBSTER: It does but it's the same

23

24

2 been so much debated. ARMIJO: Actually they're 3 MEMBER 4 different, but not all that different. 5 MR. WEBSTER: They're similar. similar in the common sense of the word. 6 7 summary, we don't know what the current margins are. 8 In fact, we don't even know if there are current 9 The acceptance criteria has not been margins. 10 updated. We know now that water has been draining 11 from the sand bed at some time over the last eight 12 Of course, we don't know when because the years. Applicant didn't actually do his monitoring 13 14 required and we don't actually know where the water 15 came from because the Applicant threw it away before 16 they got the chance to sample it and there is some 17 suspicion that the water could be coming up from below. 18 19 MEMBER ARMIJO: I'd like to hear more why 20 you think that's possible. 21 MR. WEBSTER: Well, we don't have a lot of 22 data on that. I'm throwing that out as a possibility. 23 I'm really throwing it out to be refuted by the 24 Applicant. What we know is that the groundwater at 25 this site is high, that this is at the bottom of the

numbers that are in Table 1 of the response that has

1	site, but I don't have a good view of what the
2	relative elevations are between the wet areas and the
3	non-wet areas. I would be very interested In the
4	EPRI document that the Applicant has tried to rely
5	upon but it's not a gold document, I think it's a EPRI
6	document for their argument about the embedded region,
7	it says that you should eliminate groundwater as a
8	source of water and the Applicant actually hasn't done
9	that. So if they're attempting to rely upon that
10	document, they should at least do what it says in that
11	document.
12	MR. ABDEL-KHALIK: But the elevation at
13	that point is 8'11" or so.
14	MR. WEBSTER: Of the embedded region.
15	MR. ABDEL-KHALIK: Right.
16	MR. WEBSTER: I'm not quite sure what the
17	relative dating is on that. Is that
18	MR. ABDEL-KHALIK: Wouldn't that be sea
19	level?
20	MR. WEBSTER: I don't know. I mean I
21	don't know. I'm throwing that out as a possibility to
22	be refuted.
23	CHAIR MAYNARD: I think your point is that
24	you don't have evidence that it is groundwater, but
25	you haven't seen any analysis or enough information to

rule it out.

MR. WEBSTER: That's right. We're saying it's a cause that they should rule out. It's sort of illustrative that a root cause analysis is woefully inadequate or at least somebody should have looked at those elevations and figured it out.

Visual monitoring of the epoxy coat, again this is according to our expert the epoxy coat visual inspection is really not sufficient. He says that visual examination needs to be augmented by more quantitative assessment. Holidays and pinholes in the coatings cannot be addressed by visual examination. The coatings industry have developed methodology which can more accurately establish the integrity of coatings and he actually references four methodologies that are designed to analyze the integrity of coatings.

Of particular important is integrity of the putty. This is the seal in the embedded region. Water leakage in the crevice will further stimulate corrosion below the sand bed and floor. We think the coating should be inspected quarterly while wet conditions prevail and at the onset of moisture being detected.

Now I was astonished today to hear that

half of the bays haven't been inspected at all. When GPU Nuclear applied that coating they estimated its useful life was ten years. We're now 14 years later. So what that means is we're four years beyond the estimated life and half the bays are not being inspected at all. We've heard that the corrosion is quite heterogeneous, that what happens in one way doesn't tell you what's happening in another bay. So if that's the case I don't see any justification at all for the failure to monitor five bays to date.

And so finally -- Oh yes. The UT measured area was not adapted to thin areas at the edges. So in other words, when they did their 6"x6" area if the areas at the edges were thinner than 0.736 they didn't then expand the area and keep going to define the area that was thinner than 0.736. They just stopped there.

And as we know, they didn't measure known areas that are thinner than 0.736. That scatter plot that I think, Dr. Wallis, you were looking at from the 1992, I should have put that on my slides, assessment shows a scatter of thin areas all over the shell and there was no effort to measure the area of those thin areas. The only measurement was the thinnest spot on those areas which I think was -- I mean I don't know exactly the temporal sequence but certainly once the

GE modeling was available for those small areas, I think it behooved someone in either the NRC or the operator to go out and measure those areas because those could be absolutely critical.

My clients are amazed here of the oversight situation of this reactor. We have a situation and we really have no idea right now what the situation is, what the margins are and whether they're meeting the code or not. As far as my client is concerned, that's really not remotely acceptable.

So single UT measurement uncertainty is very close to the margin. So the operation fails to fully account for uncertainty and finally, there is insufficient data therefore to calculate the area below 0.736.

So that's what we don't know about the current situation really. So given what we don't know about the current situation it's pretty hard to predict what we're going to be able to do in the future. At best we can say that the predictions of the future are highly uncertain and that to determine the appropriate monitoring in terms of spatial scope and the required accuracy, we need to know the current margin to a high degree of certainty and the only way we're going to know is that we're going to use the

1 accurate techniques as proposed by Stress most 2 Consulting. 3 And to determine the monitoring frequency 4 we need to look in a very systematic way at corrosion 5 conditions. Let me come through these in more detail. We need to estimate the worst case corrosion rate 6 7 which we had some questions about before. We're using 8 a very high corrosion rate. I probably don't think 9 that's realistic. 10 MEMBER WALLIS: This is your 0.33 inches 11 per year. 12 Right. I don't think that's MR. WEBSTER: realistic but I don't think there's any other number 13 14 out there. So you want to take the biggest one and 15 again it's a question of should this be a process of elimination as far as we're concerned. Let's start 16 17 with the worst case assumption and work our way in; 18 whereas the Applicant has done absolutely the 19 They've started with the best case opposite. 20 assumption, zero corrosion, and said can we show zero 21 corrosion is okay. They're struggling to show that. 22 So the proposed program is inadequate. 23 What they proposes for the next outage is that they 24 will measure or at least what they proposed in writing

their June 20th commitment is that they will

measure the areas from the inside that they measured before. So it will twelve 6"X6" areas in the top area of the drywell, of the sand bed region of the drywell, totally inadequate to even compare to the current acceptance criteria.

The statistical techniques as I before using the data analysis are completely flawed and I will go into more detail on that. The coating integrity as I said hasn't been adequately maintained. There are tests out there. They should be done both immediately after it's applied. I was again interested to hear that again one reason that there an aging problem was because it was installment problem. For this coating, I mean we don't know whether it was an aging problem or an installation problem because they didn't properly measure it after they installed it and they haven't measured it since. So I don't know how splitting the hairs about which kind of problem it is doesn't mean it's not a problem. The fact is they haven't looked, they haven't made sure this installation was done properly and they haven't looked systematically at whether it continues to be functional. In fact they haven't looked at all in half the bays about whether it continues to be functional.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

And then finally, the initial UT
monitoring proves it every four years. I don't know
how anybody came up with four years. I mean if you're
going to have any kind of corrosion rate I don't
understand how you can calculate four years. The idea
that the upper region bounds the corrosion rate is
completely wrong. The temperatures are much higher in
the upper region. That means that it's less likely to
be wet or at least the moisture will evaporate more
quickly and then there's this firebard D stuff in the
upper region which isn't present in the sand bed
region. So I don't think the results in the upper
region, they are always much smaller in the sand bed
region, the corrosion rate there. So it's a datapoint
out there, but it certainly doesn't bound the sand bed
region in any way at all. And I'm amazed that that
would even be put forth as an idea. It doesn't seem
to make sense to me.

So finally, we must build in fail-safe checks. What we've seen from the Applicant's failure to meet its commitments is that when you just rely on one commitment for safety if they miss on that commitment, you have a safety problem or you potentially have a safety problem at least. We strongly believe that there have to be fail-safe

б

2 we have a margin on this drywell that it's 3 maintained. 4 Okay. I think I'll skip over that one. 5 Statistical techniques, there was some interest in The first problem is that the potential for 6 7 future corrosion is not estimated when no corrosion is 8 measured. It's just an assumption that we didn't see 9 any corrosion in the past. It won't happen in the 10 I've never seen any justification for that. So I'm sure now we know given the error bars that it 11 could be it's a sampling artifact that you see no 12 corrosion or it could be that the conditions could 13 14 change in the future. So the past conditions are not 15 indicative of future conditions necessarily. So you 16 have to really look at the propagating error bars 17 going forward to see what's happening even when you see no corrosion. 18 19 MEMBER WALLIS: These are two measurements 20 side by side. CHAIR MAYNARD: Wait. Listen to the 21 22 remarks here. 23 MEMBER WALLIS: I'll talk to him. 24 MR. WEBSTER: So secondly -- Do you want 25 Secondly there's an erroneous continue? me

checks, multiple systems in place, to make sure that

assumption of linearity over time. In fact, it's quite possible for pit corrosion to accelerate over time. So this projection of linearity again no justification again whatsoever for that.

Again there's an erroneously assumption of unchanged conditions. I mean if you're monitoring every ten years but the corrosion could happen in four years or three years or two years, then the monitoring every ten years is inadequate and at the moment, we think it's possible that the corrosion could happen very quickly especially in the crevice corrosion of the embedded region. And there is just absolutely no data out there on it. So we think you have to be conservative. Once every ten years doesn't seem very conservative to us.

This 95 percent confidence interval, this is again another mystery. I mean this means that basically there's a potential violation of the safety margin one and 20 times for this kind of confidence interval. Now we've seen no analysis of how that projects forward into a safety calculation and I think if you're going to accept that kind of low bound of certainty for a safety significant component, you really have to show rigorously that it doesn't translate into some kind of safety problem and that

just simply hasn't been done. As far as we can tell, somebody got their statistics textbook out, saw 95 percent as a standard interval and just started messing around with that.

Confirming that view, somebody tried to use normal statistics. The problem with normal statistics of course is it's generally two-sided and there are various assumptions built in. Here you really need a one-sided distribution and our expert has recommended a couple of distributions that might be more appropriate. The fact that the normal distribution is not appropriate was really found by They kept analyzing the results and the Applicant. checking that the normal distribution was right and finding it wasn't. So their response instead of saying we go the wrong distribution here was to discard data and to divide the data into different subsets in a desperate attempt to fit the data back to normal distribution. When any reasonable statistical view would have been this distribution is not working. Let's change distributions. You really can't -- You have to really see what the data is telling you and just cherry-picking the data to fit into a distribution doesn't seem as of our expert to be a very rigorous scientific approach.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	They failed to look systematically Yes,
2	I mentioned the data filtering. I want to emphasize
3	that again. In certain cases, we see data being
4	discarded, pits being taken out because they don't fit
5	normal. In fact our expert is saying that's precisely
6	what you expect to see when corrosion is happening.
7	Certain pits go very deep and they are way beyond
8	three standard deviations. But those pits are
9	precisely the ones you have to worry about most not
10	the ones you should throw away when you're doing your
11	data analysis.
12	MEMBER WALLIS: These are pits in the
13	shell.
14	MR. WEBSTER: Yes, they are pits in the
15	shell. Yes.
16	MEMBER WALLIS: Not pits in the
17	MR. WEBSTER: No, they are pits in the
18	shell.
19	So they fail to look systematically at
20	uncertainties in the measurements. When you see an
21	estimate about the square footage of area below 0.736,
22	you really have to ask yourself what is the
23	uncertainty. Given the uncertainty on each individual
24	measurement, the uncertainty on that is very likely to
25	be high and we think that the modeling needs to

reflect that worst case assumptions, i.e., what could be the case right now. We really think on a modeling study what you need to do is to look at what could be the case right now given the variation, given the uncertainty in the results and then what could be the case in the future given the time intervals and the potential corrosion rate. So far, nothing like that has been done.

And again, we keep coming back to this.

We were been unable to estimate a corrosion rate right now because we really have one datapoint in the sand bed region since the sand was removed. That's in 1992 It's very hard to get a rate out of one point. And the problem -- Well, when next results we'll have two points, but the problem is because there's been no monitoring conditions during the time that the two points have been occurring we really have no idea how the conditions will translate into a corrosion rate. And we would like to see a corrosion rate under wet conditions, a corrosion rate under coating failure conditions and so forth. We just don't have the data to even approach thinking about that kind of approach.

So here we are. This is an emphasis on maintaining coating integrity. I think I've said this. Basically, visual inspections as the Applicant

1 itself has admitted today misses a lot of details. 2 It's quite possible for pinholes and holidays to 3 Water gets in behind those. You get corrosion 4 happening behind those and actually then the coat can 5 mask that corrosion is occurring. And again because it's so close to margin 6 7 you don't need a whole lot of corrosion to get to be 8 on the margin. So we believe that visual inspection 9 must be augmented by the industry standard objective We believe that when wet conditions 10 measurements. prevail the monitoring frequency must increase to at 11 least quarterly until more certainty prevails. 12 believe that a response to coating failure must be a 13 14 complete renewal of the coating and comprehensive UT 15 measurements within a quarter. At the moment, they're proposing if they 16 see a small area of coating degradation they will 17 basically fix that area, but not fix the other areas 18 19 and it seems to us that once the coating starts to go 20 that's indicative of the whole coating needs to be 21 renewed. Just the statement was made 22 MEMBER SHACK: that the ASTM standard calls for visual examination. 23

MR. WEBSTER: Let me just check for you.

What industry standard are you referring to?

24

1	National Association of Corrosion Engineers
2	International Standard Test Method TM00384, Holiday
3	Detection of Internal Tubular Coatings of 2.5
4	micrometers film thickness. Again, National
5	Association of Corrosion Engineers Standard No
6	MEMBER SHACK: What was that standard
7	number again?
8	MR. WEBSTER: TM00384.
9	MEMBER WALLIS: Could you explain what a
10	holiday is?
11	MR. WEBSTER: A holiday, I don't think
12	it's used in the English sense. I think it's a small
13	hole. It's a place where the coating didn't apply in
14	other words. I think it's a place here the coating,
15	when you are brushing the coating on or however you're
16	applying it, you missed a spot. The brush sort of
17	took a holiday.
18	MEMBER WALLIS: It didn't stick.
19	MR. WEBSTER: It didn't stick. Your brush
20	was on holiday for that particular spot.
21	I can give you these codes later. They're
22	all in Dr. Hausler's
23	CHAIR MAYNARD: If you could give him
24	those codes later. I am giving you extra time.
25	MR. WEBSTER: Yes.

CHAIR MAYNARD: We do need to move along.

Let me wrap up then. MR. WEBSTER: monitoring for water, at the moment as we said, as Amergan said, you know they promise they're going to look at these drains in the future although they didn't the past and what we're saying is you know there are electronic water detection systems They would give you a lot more detail about where the water is, when it starts to happen and for how long it happens. You actually end up with an objective measure. You end up with a log and you get just a lot more information out of this. don't quite understand why this hasn't already been proposed. When you're this close to margin and with a component of this significance, it seems to us that you should do the best you can not just try and get away with the least and I'll let you slide by me.

Monitoring frequency basically at it's really very hard to know what monitoring frequency would be appropriate because the safety margins are not established and the worst case corrosion rates are not known. So as I said we And again we advocate conservative assumptions. strongly believe that we must have fail-safe We must have fail-safe systems all around intervals.

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 because we cannot just rely on this Applicant meeting 2 all of its commitments all the time. 3 Finally, and importantly, Dr. Hausler 4 raised another possible failure mechanism, chloride 5 induced fatigue cracking and suggested that that must be examined and ruled out and as far as we know, 6 7 nothing has become of this suggestion. Oh, I should mention. This information 8 9 Dr. Hausler provided was provided directly to the NRC. 10 It wasn't provided as part of the litigation. is -- Actually, strike that. I think that's 11 That was provided as part of litigation. 12 incorrect. ARMIJO: Do you have any 13 MEMBER 14 literature, documents, that cite chloride stress 15 corrosion cracking in carbon steels? 16 MR. WEBSTER: I haven't seen any. 17 certainly ask Dr. Hausler that question if you would like me to. 18 What's the pathway for the 19 MEMBER SIEBER: 20 introduction of chlorides? Where does it come from? MR. WEBSTER: I'm not sure at this point. 21 22 I can again check for you. So the Chairman will be 23 pleased to see that this slide is labeled conclusions. 24 MEMBER WALLIS: You keep referring to 25 Hausler's report. Has this been given to the NRC?

1	MR. WEBSTER: These have all been filed
2	with the Atomic Safety and Licensing Board.
3	MEMBER WALLIS: Has NRC seen this work
4	yet?
5	MR. WEBSTER: I believe they have.
6	MEMBER WALLIS: They have. Okay.
7	CHAIR MAYNARD: It was filed as part of
8	litigation.
9	MR. WEBSTER: Some of the memos have been
10	filed as litigation and some of the memos because we
11	were actually prevented from raising the issue of
12	embedded corrosion in the litigation we've actually
13	filed these separately to the staff just in order to
14	help their review.
15	MR. GUNTER: I just wanted to say that I
16	apologize but we did provide all of Hausler's memos
17	last week. So I don't know if you've actually had a
18	chance to review those materials yet. But the ACRS
19	does have them.
20	MEMBER WALLIS: No, absolutely not.
21	MEMBER SIEBER: Filled up a section of my
22	hard drive.
23	MEMBER WALLIS: We have a lot of other
24	things going on too.
25	MR. WEBSTER: I'm sure you do. My hard

drive has been filling up too. So in summary at the moment we don't have a current reasonable assurance of safety. I think that's hard to dispute. We know that the proposed monitoring program is inadequate. There are more measurements scheduled this month and if they were comprehensive they could answer many of the questions that have been raised here. The problems is at the moment they're not comprehensive.

At best the conclusions about future safety of the shell and the SER and the inspection I mean at a minimum we have to port are premature. wait for these results, but the problem with the results is that because they're not comprehensive, they really won't solve most of these problems. what we need to do here, what's happening really in this problem, when you look at it from stance of what's really happened is that a whole bunch of assumptions have accumulated over time, cluttered up the thinking on this program over time. People kept going back and saying the NRC accepted this before so it must be okay and then tried to use what has been accepted before as a quide to what will be done in the future.

And the reality is we have serious questions about what was acceptable before should have

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

been accepted before. What we know is it's certainly unacceptable going forward. Until we get a rigorous quantitative analysis based on comprehensive data and careful consideration on certainly, we strongly believe we encourage the ACRS to wait this application until you really see and are really satisfied that this problem has been addressed in a very rigorous manner. I think any careful analysis of the data will show you right now that the analysis that's been done is far from rigorous, is far from adequate and we end up in a situation now where elected officials have written to the NRC last week asking how the NRC can conclude that this reactor has a reasonable assurance of safety and that's all I have Thank you very much for your time. to say.

CHAIR MAYNARD: I really appreciate your comments and the ACRS I assure you has not come to I think you can tell from our conclusions on this. questions and we will be using your comments and information that you've provided here. We'll be factoring that into our future evaluation, deliberation, of this particular license renewal application and take that in conjunction with other information that we have and I'll assure you that the ACRS will not make a decision or recommendation until

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1 we have answers to the significant questions that we 2 still have outstanding too. I appreciate your 3 comments there. 4 MR. WEBSTER: Thank you very much. 5 MEMBER BONACA: I have a question that I would like to ask. 6 7 CHAIR MAYNARD: Okay. 8 MEMBER BONACA: It has to do with do you 9 know specific techniques that could be suggested to do 10 the direct measurements of the embedded thickness, metal thickness? 11 MR. WEBSTER: The short answer is no. 12 mean it seems that there are some research reports out 13 14 there that the NRC has cited and the other approaches 15 that chip out the concrete and get down there. Beyond that there's nothing really. There's no magic bullet 16 17 out there as far as we know. CHAIR MAYNARD: What I would like to 18 19 recommend to the subcommittee here if I could have 20 your attention here. It is getting late. I believe 21 that we still have a number of questions, a number of 22 unanswered questions. I'm not sure that it would do 23 any good to bring the licensee back up here and the 24 staff and reask a lot of the same questions. I think

we need to take a look.

1	I would recommend that tonight we give
2	this some thought. We have an open meeting session
3	tomorrow of subcommittee time and I think at that time
4	we can discuss what we believe our next step should
5	be. There are several options available, another
6	meeting, request additional information, define what
7	needs to be provided or whatever but unless somebody
8	objects to that I would recommend we give it some
9	thought overnight and discuss it in open meeting
10	tomorrow under subcommittee report as to what our next
11	step is.
12	I believe I'm safe in saying that we all
13	still have a number of questions that we don't have
14	answers to yet. Right?
15	MEMBER BONACA: I do.
16	CHAIR MAYNARD: Okay. With no objections,
17	that's it.
18	MEMBER WALLIS: That's the end. No more
19	presentations.
20	CHAIR MAYNARD: We have no more
21	presentations and we're out of time. So with that, I
22	would like to express my appreciation to all the
23	presenters and everybody that participated and I
24	appreciate your patience and we will conclude this
25	meeting. The meeting is adjourned. Off the record.

1 (Whereupon, at 6:11 p.m., the above-2 entitled matter was concluded.)