Official Transcript of Proceedings		
NU	JCLEAR REGULATORY COMMISSION	
Title:	Advisory Committee on Reactor Safeguards Subcommittee on Plant License Renewal	
Docket Number:	(not applicable)	
Location:	Rockville, Maryland	
Date:	Thursday, January 18, 2007	

Work Order No.: NRC-1398

Pages 1-371

NEAL R. GROSS AND CO., INC. Court Reporters and Transcribers 1323 Rhode Island Avenue, N.W. Washington, D.C. 20005 (202) 234-4433

	1
1	UNITED STATES OF AMERICA
2	NUCLEAR REGULATORY COMMISSION
3	+ + + + +
4	ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS)
5	SUBCOMMITTEE ON PLANT LICENSE RENEWAL
6	OYSTER CREEK GENERATING STATION
7	+ + + +
8	THURSDAY,
9	JANUARY 18, 2007
10	+ + + +
11	The meeting was convened in Room T-2B3 of
12	Two White Flint North, 11545 Rockville Pike,
13	Rockville, Maryland, at 8:30 a.m., DR. OTTO L.
14	MAYNARD, Chairman, presiding.
15	MEMBERS PRESENT:
16	OTTO L. MAYNARD
17	, Chairman
18	GRAHAM B. WALLIS, Vice-Chairman
19	WILLIAM J. SHACK, ACRS Member
20	MARIO V. BONACA, ACRS Member
21	DANA A. POWERS, ACRS Member
22	JOHN D. SIEBER, ACRS Member
23	SAID ABDEL-KHALIK, ACRS Member
24	J. SAM ARMIJO, ACRS Member
25	
	I

(202) 234-4433

2

	3
1	<u>NRC STAFF PRESENT</u> :
2	LOUISE LUND
3	DONNIE ASHLEY
4	MICHAEL JUNGE
5	BARRY GORDON
б	RICH CONTE
7	MICHAEL MODES
8	JIM DAVIS
9	NOEL DUDLEY
10	P. T. KUO
11	SUJIT SAMMADAR
12	
13	<u>ALSO PRESENT</u> :
14	MIKE GALLAGHER
15	PETE TAMBURRO
16	FRED POLASKI
17	AHMED OUAOU
18	HARDIYAL MEHTA
19	HOWIE RAY
20	TOM QUINTENZE
21	JOHN O'ROURKE
22	TIM O'HARA
23	JON CAVALLO
24	MARTY MCALLISTER
25	JASON PETTI
	1

		4
1	ALSO PRESENT (Continued):	
2	MIKE HESSHEIMER	
3	PAUL GUNTER	
4	RICHARD WEBSTER	
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
	1 Contraction of the second	

		5
1	I-N-D-E-X	
2	AGENDA ITEM	PAGE
3	Opening Remarks	6
4	O. Maynard, ACRS	
5	Staff Introduction	8
6	Louise Lund, NRR	
7	AmerGen - Oyster Creek Presentation	10
8	A. Drywell Shell Corrosion Overview	17
9	Fred Polaski	
10	B. Drywell Shell Thickness Analysis	53
11	Dr. Hardayal Mehta (GE),	
12	Ahmed Ouaou	
13	C. Drywell Sand Bed Region	120
14	John O'Rourke, Jon Cavallo,	
15	Pete Tamburro, Howie Ray	
16	D. Embedded Portions of the Drywell Shell	180
17	John O'Rourke, Barry Gordon,	
18	Howie Ray	
19	E. Upper Drywell Shell	235
20	John O'Rourke, Howie Ray	
21	NRC Staff Presentation	
22	A. Introduction/Overview	247
23	Donnie Ashley, NRR	
24		
25		

		6
1	I-N-D-E-X (Continued)	
2	AGENDA ITEM (Continued)	PAGE
3	NRC Staff Presentation (Continued)	
4	B. NRC inspection during 2006 outage	248
5	Richard Conte, Region I	
6	Tim O'Hara, Region I	
7	Michael Modes, Region I	
8	C. Status of Open Items/Licensee	260
9	Commitments	
10	Donnie Ashley, NRR	
11	Hans Ashar, NRR	
12	D. Confirmatory Analysis of Drywell -	266
13	Sandia Model	
14	Hans Ashar, NRR	
15	Jason Petti, SNL	
16	E. Socket Welds	305
17	Jim Davis, NRR	
18	Public Comment	308
19	Paul Gunter (NIRS)	
20	Richard Webster (RELC)	
21	Subcommittee Discussion	353
22	O. Maynard, ACRS	
23		
24		
25		

	7
1	P-R-O-C-E-E-D-I-N-G-S
2	(8:33 a.m.)
3	OPENING REMARKS
4	CHAIRMAN MAYNARD: This meeting will now
5	come to order. This is a meeting of the Plant License
6	Renewal Subcommittee. I am Otto Maynard, Chairman of
7	the Plant License Renewal Subcommittee for the Oyster
8	Creek license renewal application.
9	ACRS members in attendance are Jack
10	Sieber, Said Abdel-Khalik, Sam Armijo, Dana Powers,
11	Graham Wallis, Bill Shack, and Mario Bonaca. Michael
12	Junge of the ACRS staff is the designated federal
13	official for this meeting. He is to my right.
14	The purpose is this meeting is to review
15	the license renewal application for the Oyster Creek
16	generating station, the draft safety evaluation report
17	and associated documents with focus on questions that
18	were raised during the October 3rd, 2006 License
19	Renewal Subcommittee meeting.
20	We will hear presentations from
21	representatives of the Office of Nuclear Reactor
22	Regulation, Region I office, and AmerGen Energy
23	Company. The subcommittee will gather information,
24	analyze relevant issues and facts, and formulate
25	proposed positions and actions as appropriate for

(202) 234-4433

	8
1	deliberation by the full Committee.
2	The rules for participation in today's
3	meeting were announced as part of the notice for this
4	meeting previously published in the Federal Register
5	on January 25th, 2006. That's 71 FR 4177.
б	We have received requests for time to make
7	oral statements from Paul Gunter of Nuclear
8	Information Resource Service and from Richard Webster
9	of the Rutgers Environmental Law Clinic. These
10	statements will be considered as part of the
11	Committee's information-gathering process. We have
12	provided time on today's agenda for these oral
13	statements.
14	Comments should be limited to the issues
15	associated with the Oyster Creek generating station
16	license renewal application or draft safety evaluation
17	report with focus on questions that were raised during
18	the October 3rd, 2006 License Renewal Subcommittee
19	meeting.
20	We have received no written comments from
21	members of the public regarding today's meeting. I
22	will say that we did receive information from Mr.
23	Webster in response to some questions that were at the
24	last meeting and also copies of some of their proposed
25	presentation material.
	1

(202) 234-4433

1 A transcript of the meeting is being kept 2 and will be made available as stated in the Federal 3 Register notice. Therefore, we request that 4 participants in this meeting use the microphones 5 located throughout the meeting room when addressing the Subcommittee. Participants should first identify 6 7 themselves and speak with sufficient clarity and volume so that they can be readily heard. 8 9 It's going to be important to follow the I am sure we will deviate some, but we 10 agenda today. 11 do have important presentations from the license, from 12 the NRC staff, and from members of the public. So I will be watching the time. And we all need to be 13 14 paying attention to that, make sure we do focus on the right areas to get the right issues addressed in 15 16 today's meeting. I will now proceed with the meeting. 17 And I call on Ms. Louise Lund of the Office of Nuclear 18 19 Reactor Regulation to begin. 20 Well, thank you. MS. LUND: 21 STAFF INTRODUCTION 22 And good morning. MS. LUND: My name is Louise Lund. I am the Branch Chief of License Renewal 23 Branch A in the Division of License Renewal. Beside 24 25 me is Dr. P. T. Kuo, our Acting Director for the

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

(202) 234-4433

9

Division of License Renewal.

1

2

5

6

7

The staff has continued their review of 3 the Oyster Creek generating station license renewal 4 application, which was submitted in July of 2005. Mr. Donnie Ashley, here to my right, is the project manager for this review. He will lead the staff's presentation in the afternoon.

In addition, we have several NRC members 8 9 from Region I to discuss inspections that were held last October at Oyster Creek. We also have several 10 11 members of the NRC technical staff in the audience to 12 provide additional information and answer your questions. 13

14 As Dr. Maynard said at the last meeting in 15 October last year, the ACRS Subcommittee had a number of questions. As a result of the meeting, the 16 17 Committee requested additional information, specifically about the drywell shell, 18 from the applicant, which they provided and included historical 19 information and data as well as the results of the 20 21 inspections that were held in October of 2006. 22 AmerGen has put together a comprehensive

23 presentation to address the questions put forward by the Committee. In addition, the NRC staff provided a 24 25 draft and final report of the analysis of a drywell

> **NEAL R. GROSS** COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

Í	11
1	shell performed at Sandia to support the staff's
2	review. We have representatives of Sandia here to
3	answer any questions you may about their work.
4	Using insights from this work, the staff
5	issued an update to the safety evaluation in December,
6	which we provided to the Committee. You will be
7	hearing about this information in more detail during
8	the meeting today. In addition, you will be hearing
9	from the regional inspectors that were present during
10	the inspections in October 2006 and their observations
11	of AmerGen's inspections.
12	With that, I would like to turn this
13	presentation over to Mike Gallagher, who is the Vice
14	President of Exelon's license renewal group, to begin
15	the applicant's presentation.
16	<u>AMERGEN - OYSTER CREEK PRESENTATION</u>
17	MR. GALLAGHER: Good morning. My name is
18	Mike Gallagher. And I'm Vice President of License
19	Renewal Projects for AmerGen and Exelon. Also with me
20	here from our management team is Tim Rausch he's
21	our Site Vice President at Oyster Creek and Rich
22	Lopriore. He's our Senior Vice President for
23	Mid-Atlantic Operations.
24	On October 3rd, we last met and made a
25	summary presentation on our license renewal
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

12 1 application, including the drywell corrosion issue, at 2 Oyster Creek. 3 The feedback that we received from you was 4 that our presentation fell short of your expectations 5 because it did not provide a sufficient level of detail on the drywell corrosion issue. 6 7 I acknowledge the shortcoming. And we have taken action to provide you the information 8 9 necessary for your review. And in response to the questions from the last meeting, for instance, you 10 told us you wanted to see more details about the 11 12 drywell shell corrosion, including source documents and data that we previously shared with the NRC staff. 13 14 You also told us that you would like to see pictures of the drywell shell in the sand bed region before and 15 16 after the repair. On December 8th, we provided you with a 17 package of information in preparation for our meeting 18 in response to your request. 19 today and This 20 information package contained several white papers on 21 key areas of drywell corrosion issue as well as the 22 key source and reference documents. 23 We were also able to include inspection 24 information from our refueling outage, which was 25 completed since we last met. This refueling outage

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

13 1 inspection information demonstrates that the drywell shell continues to meet code safety margins and is 2 projected to do so through the period of extended 3 4 operation. 5 In addition, we put together this presentation to ensure that we clearly communicate our 6 7 conclusions and the detailed information upon which 8 our conclusions are based. There are two handouts for you today. 9 The 10 first is the presentation. That's the thicker 11 This is the presentation that we will be handout. 12 going over today. And the second is labeled "Reference Material." There are pictures. 13 There are 14 data graphs. And there is an integrated data sheet in 15 And so we will be referring to some of that there. 16 today. 17 CHAIRMAN MAYNARD: It will be important that we focus on the key areas. There's a lot of 18 19 material, and that is very helpful. But we're not 20 going to be able to spend a lot of time on every slide 21 in here. 22 MR. GALLAGHER: That's correct, Dr. 23 That's why we broke it up into the reference Mavnard. 24 material. If members have questions on some specific 25 things, we can go into that. We only have some

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	14
1	examples in the presentation. Okay?
2	Okay. We also included pictures of the
3	drywell shell in the sand bed region before and after
4	the repair. And we have also included the key data we
5	will be discussing throughout the presentation today.
6	We have experts here with us today to assist in our
7	presentation and answer any questions you may have.
8	The purpose of this presentation is to
9	communicate how we arrived at our overall conclusions,
10	which are the corrective actions to mitigate drywell
11	shell corrosion have been effective. Drywell shell
12	corrosion has been arrested in the sand bed region and
13	continues to be very low in the upper drywell
14	elevations. Service life of the drywell shell extends
15	beyond 2029 with margin. The corrosion on the
16	embedded portion of the drywell shell is not
17	significant due to environment of embedded steel and
18	concrete. The drywell shell meets code safety
19	margins. And we have an effective aging management
20	program to ensure continued safe operation of Oyster
21	Creek.
22	The way our presentation is organized
23	today, we do have some up-front background information
24	on the configuration and the cause and corrective
25	actions. The first main section is the GE analysis,
	I contraction of the second seco

(202) 234-4433

	15
1	which we will be getting into. So if we could get
2	through the background information, I would suggest we
3	get through that quickly so we can get to the meat of
4	the presentation, but we can get into any level of
5	detail you want to get in.
6	CHAIRMAN MAYNARD: I understand the
7	background. Basically we're going to focus on the
8	water
9	MR. GALLAGHER: The water leakage path.
10	CHAIRMAN MAYNARD: Yes.
11	MR. GALLAGHER: Yes. And so when we go
12	through the configuration, we have a model here.
13	We'll go through the water leakage path.
14	CHAIRMAN MAYNARD: Yes. So we don't need
15	to go through the background of everything we have
16	gone through before. But I do think it important to
17	go over the water path.
18	MR. GALLAGHER: That's correct. So I'll
19	turn it over now to Fred Polaski, who will lead us
20	through that background information.
21	MR. POLASKI: Thank you, Mike.
22	As Mike said, I'm Fred Polaski. I'm
23	Exelon's License Renewal Manager. I would like to
24	introduce today's presenters. At the front table with
25	me to my left is Mr. John O'Rourke. John is a member
	1

(202) 234-4433

	16
1	of the Oyster Creek license renewal team and formerly
2	was the Assistant Engineering Director at Oyster
3	Creek.
4	To my right is Mr. Ahmed Ouaou, who is a
5	civil engineer on the Oyster Creek license renewal
6	team.
7	To Ahmed's right is Howie Ray. He's a
8	mechanical/structural design branch manager at Oyster
9	Creek.
10	And to his right is Pete Tamburro, a
11	member of the Oyster Creek Engineering Department, who
12	has been involved with the drywell corrosion issue
13	since 1988.
14	Other presenters today will be Dr.
15	Hardiyal Mehta of General Electric; Mr. Barry Gordon,
16	Structural Integrity Associates; Mr. Jon Cavallo of
17	Corrosion Consultants and Laboratories.
18	Slide 3. This is our agenda for today.
19	We're going to focus on the corrosion of the drywell
20	shell at Oyster Creek. Mike said first we'll do a
21	brief overview of the physical configuration and the
22	leak path. And then we will discuss the drywell
23	thickness analysis conditions in the sand bed region;
24	embedded portions of the drywell shell; and, lastly,
25	the upper shell.
1	I Contraction of the second

(202) 234-4433

	17
1	If we go on to slide 5, this is a
2	cross-section of the reactor building at Oyster Creek.
3	In the middle is the reactor vessel shown in green
4	with the recirculation piping and pumps. Surrounding
5	that, the red is the drywell shell. This is shown in
6	the refueling condition.
7	So the reactor head and the drywell head
8	are removed. The reactor cavity is depicted as being
9	filled with water in the blue cross-hatch. And
10	surrounding the drywell is concrete shielding as part
11	of the reactor building.
12	VICE-CHAIRMAN WALLIS: In this
13	configuration is the pressure of two psi around the
14	drywell? Is that right?
15	MR. POLASKI: There is no
16	VICE-CHAIRMAN WALLIS: Where's the two?
17	Isn't the refueling where you have two psi around the
18	drywell?
19	MR. POLASKI: In the analysis that was
20	performed by General Electric, they assume two pounds
21	on the outside of the drywell.
22	VICE-CHAIRMAN WALLIS: I wondered where
23	that came from and how accurate it was.
24	MR. POLASKI: Well, we're going to
25	VICE-CHAIRMAN WALLIS: Are you going to
	1

(202) 234-4433

	18
1	get into that later on?
2	MR. POLASKI: We'll be getting into that
3	in
4	MR. GALLAGHER: Dr. Wallis, that's an
5	input to the analysis. It's from the standard review
6	plan.
7	VICE-CHAIRMAN WALLIS: How realistic is
8	it?
9	MR. GALLAGHER: It's not because the
10	you know, the equipment hatches are open during an
11	outage. So there is no
12	VICE-CHAIRMAN WALLIS: Are you going to
13	explain that later, are you?
14	MR. GALLAGHER: Yes. When we talk about
15	the GE analysis, we'll have that.
16	VICE-CHAIRMAN WALLIS: All right.
17	A. DRYWELL SHELL CORROSION OVERVIEW
18	MR. POLASKI: So our next three slides are
19	going to show details of the condition up here in the
20	liner and reactor cavity, detail around a leakage
21	path, around a bellows seal. And then we'll look at
22	the sand bed.
23	Go to slide 6. All right. This is a
24	detail of the reactor cavity liner. The cross-hatch
25	link here is the one-eighth thick stainless steel
1	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

19 1 liner for the reactor cavity that's constructed with 2 eighth-inch thick stainless steel plates that are 3 welded together in place during construction. And 4 then there's concrete behind it. The plates are 5 actually put in place first. And then the concrete is poured. And the plates are part of the form for 6 7 pouring the concrete. The blue depicts the leakage. The leakage 8 9 occurs through numerous very small cracks in this liner in the weld. 10 VICE-CHAIRMAN WALLIS: It's detail B. 11 MR. POLASKI: 12 Cause of the welds are the cracks, the stresses from welding, and fatigue on the 13 14 plates. The water leaks through numerous very small 15 cracks through the plate down between the plate and the concrete and then down into this bellows area. 16 Can we go to slide 7? This is the detail. 17 Here is the refueling bellows seal. Concrete is out 18 19 in this area. Below the seal is a concrete leakage 20 collection trough, which is designed to collect any 21 leakage from the bellows. 22 This is the drywell over here. And the 23 gap between the concrete and the drywell, the red cross-hatch is a fire bar D. I will note this is not 24 25 spelled correctly. It should be fire bar D and then

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	20
1	a one-inch gap.
2	The leakage comes up here at two, follows
3	the blue path down outside the stainless steel liner.
4	At three, it comes out from under the liner into the
5	trough. And it should all go down through this one
6	single drain line off of this trough. There's only
7	one drain line. It's two inches in diameter.
8	What happened was there was damage to this
9	lip on this drainage trough. And so the water that
10	was coming down here, remember, this was coming around
11	360 degrees around. We get into the trough and would
12	overflow this lip into the gap down into the sand bed
13	region.
14	This system, if the lip had not been
15	damaged and the leakage was not too great would have
16	been able to handle it. But because of the volume of
17	the leakage in this damage, you would overflow the
18	trough into that gap.
19	MEMBER SHACK: Now, did you say there's
20	only one of those drains? So it has to flow all the
21	way around to find the drain?
22	MR. POLASKI: Yes, yes. And here,
23	remember, there's one for the trough. When we later
24	talk about the sand bed region, there there are five.
25	Okay? And this is one, and it's only two-inch.
1	I contract of the second se

(202) 234-4433

	21
1	There were repairs made to this in 1988.
2	And then at that point, though, this was before we
3	applied strippable coating to the cavity liner. The
4	amount of leakage was such that the trough wasn't able
5	to handle it and the drain line would still continue
6	to overflow.
7	Go to slide 8, please.
8	MEMBER SIEBER: Well, before you move on,
9	is the reactor cavity stainless steel liner pinned in
10	any way to the concrete
11	MR. POLASKI: I am going to ask Mr. Ouaou
12	to answer.
13	MEMBER SIEBER: or is it free-standing?
14	MR. POLASKI: Ahmed?
15	CHAIRMAN MAYNARD: You need to use the
16	microphone.
17	MR. OUAOU: Ahmed Ouaou with AmerGen. The
18	liner has no such studs that are attached to the
19	concrete.
20	MEMBER SIEBER: Okay. I presume that each
21	time the cavity is filled and drained, there is
22	flexure, however, of the cavity wall. Is that where
23	the fatigue cracks are coming from or is that one
24	source?
25	MR. OUAOU: That's one source.
1	I contract of the second se

(202) 234-4433

	22
1	MEMBER SIEBER: Okay. Thank you.
2	MR. POLASKI: Go on to the next slide.
3	All right. This is a detail of the sand bed region.
4	And the dimensions are shown here. The leakage, you
5	know, we'll pick it up here at five. It comes down on
6	the outside of the drywell shell.
7	This green cross-hatch is the drywell vent
8	lines. The extent of these is about six and a
9	half-feet in diameter. So we either come in between
10	them or around them into the sand bed region.
11	And this was originally full of sand. It
12	was emptied in 1992. There are five drain lines out
13	of this region. These drain lines were clogged, and
14	the water would collect in this region.
15	Also depicted here, inside the drywell,
16	the red cross-hatch is the concrete floor inside the
17	drywell at an elevation of ten feet, three inches. It
18	has a curb on the inside at two different elevations.
19	Eleven foot is the lower part to the curb, and
20	12-foot-3 is the upper part. And I will show that in
21	our-three dimensional model.
22	So, with that, what I would like to do now
23	is I'm going to pass this around after I talk about
24	it. This is a three-dimensional model we have of the
25	lower part of the drywell, 90 degrees.

(202) 234-4433

	23
1	The main part here, this is the concrete
2	outside the drywell. The black here is the drywell
3	shell. The green circles here on the inside coming
4	out on the outside are the vent pipes that we showed
5	you that were going to the torus.
6	This is the floor. Inside the drywell you
7	will see a better one like this around. This is the
8	curb on the inside. You can see it's lower underneath
9	the vent headers and then higher in between.
10	This part of the structure here is the
11	reactor pedestal. And inside this area is what we
12	call the subflooring below the reactor and the control
13	rod drives.
14	This small area here and it goes around
15	from here and comes out on that side is the sand
16	bed region. This is where it was filled with sand
17	almost to the top. There was a small air gap. It's
18	been removed.
19	This slide shows a cross-section of one of
20	the drain lines that comes through the concrete. And
21	the pipe just ends right here at the edge of the
22	concrete. And I'll go into that in a little bit more
23	detail.
24	On the back side here, you can see some of
25	the other drain lines. And then these holes that are
l	1

(202) 234-4433

	24
1	right here in between are the ten man-ways that were
2	cut out through the concrete to gain access to the
3	sand bed region for removal of the sand. And we use
4	those for access to inspections during an outage.
5	Yes?
6	MEMBER SIEBER: The one purpose of the
7	sand bed region was to provide a cushion support for
8	the drywell base for seismic events. When you remove
9	the sand bed, does that change the inspectoral
10	response of the containment in the seismic event?
11	MR. POLASKI: The sand bed was there as a
12	transition from a part of the drywell that's embedded
13	in concrete to the free-standing pressure vessel.
14	MEMBER SIEBER: Right.
15	MR. POLASKI: And before it was removed,
16	there was analysis done to determine that removing
17	that sand would be acceptable and not having sand
18	there was included in the analysis that General
19	Electric did
20	MEMBER SIEBER: Yes. I got the feeling
21	from reading through that that the kinds of analysis
22	that were done were ones that would say that when you
23	refuel, there's downward pressure on the drywell and
24	that it would withstand that, that it would withstand
25	the hydrostatic pressure, but I don't recall seeing

(202) 234-4433

	25
1	anything about seismic response.
2	MR. POLASKI: The analysis that was done
3	for that condition for refueling included seismic.
4	MEMBER SIEBER: Okay.
5	MR. POLASKI: And we'll get through that
6	in detail when Dr. Mehta gives that presentation.
7	VICE-CHAIRMAN WALLIS: Now, you had
8	corrosion in the sand bed region. What did it look
9	like? Where did this half-inch of rust go in the
10	worst places? Was it still attached as a layer of
11	rust or was it diffused throughout the sand bed region
12	in some way? Was it washed away in some way or where
13	did the steel go if it disappeared?
14	MR. GALLAGHER: Well, I think, Dr. Wallis,
15	if you want to look at a picture pretty much right
16	away
17	VICE-CHAIRMAN WALLIS: Was it mostly rust
18	in the form of attached rust or was it
19	MR. GALLAGHER: Yes. We can show you a
20	picture on page of the presentation if we can skip
21	ahead to that
22	VICE-CHAIRMAN WALLIS: It was attached
23	rust.
24	MR. POLASKI: If you go to page 57 in the
25	first

(202) 234-4433

26 1 MR. GALLAGHER: Yes, page 57 in your 2 That's an as-found condition if we can presentation. 3 go to 57. 4 VICE-CHAIRMAN WALLIS: So there was not 5 much material in the sand that's dissolved and went into the sand or anything that was --6 7 MR. GALLAGHER: Well, this is with the 8 sand removed. So --9 VICE-CHAIRMAN WALLIS: Yes, I know. But 10 when you took the sand out, was it for the rust or was it just --11 12 MR. GALLAGHER: It was sand. And this is 13 the --VICE-CHAIRMAN WALLIS: Sand. It was sand. 14 15 Okay. MR. GALLAGHER: This is the loose --16 17 VICE-CHAIRMAN WALLIS: It was attached? 18 MR. GALLAGHER: It was attached. And then 19 it would be removed. 20 MR. POLASKI: You can actually see this 21 better on your picture, but this is the drywell shell. 22 This area to the left is the floor in the sand bed 23 region. 24 And you can see in the pictures -- it 25 actually shows up better in the pictures you have in

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

```
(202) 234-4433
```

27 1 here -- there are heavy layers of thick rust, if you 2 will, that were still attached. And this upper area 3 had already fallen off. 4 MR. GALLAGHER: Yes. And then, Dr. 5 Wallis, if you go to page 60 --VICE-CHAIRMAN WALLIS: It does look like 6 7 a real layer of rust? 8 MR. GALLAGHER: Yes. 9 MR. POLASKI: It was a real layer of rust. MR. GALLAGHER: And then if you go to page 10 60, you see it after we cleaned it. 11 12 VICE-CHAIRMAN WALLIS: I saw some of these last night, too. 13 14 MR. GALLAGHER: Yes. Okay. So did that 15 answer your question? VICE-CHAIRMAN WALLIS: Yes, it did. 16 Thank 17 you. 18 MEMBER SHACK: Just to come back to your 19 model there, those 19 grid locations that you make, 20 those are basically measured in the notches there of 21 the curb at the 11-3 level? 22 MR. POLASKI: Yes. The 19 are in this 23 area here. 24 MEMBER SHACK: In those notches? Okay. 25 MR. POLASKI: Yes. And the reason they

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	28
1	had to be taken here is the elevation of the sand was
2	12-foot-3, which corresponds to this top of the upper
3	curb. So that the only place that you could take the
4	measurements was in here.
5	MR. GALLAGHER: And, Fred, maybe we can
6	pass that around.
7	MR. POLASKI: Yes. I am going to. So now
8	if we go back to slide let's go back to 9. This is
9	a cross-section of the reactor building, the drywell
10	up here in the upper left-hand corner and the floor in
11	the sand bed, 20-inch man-ways that were bored in
12	there. This is one of the five drain lines out of the
13	sand bed region.
14	VICE-CHAIRMAN WALLIS: How many man-ways
15	did you have to make?
16	MR. POLASKI: Ten, one into each of the
17	ten bays. There are ten vent headers here. So you
18	had to put one in between each because you can't get
19	past the vent headers once you're in the sand bed.
20	What we have depicted here, this drain
21	pipe comes just to the edge or extends a short
22	distance beyond the concrete. We have installed at
23	the plant flexible plastic catch funnels that are used
24	underneath leaks in the plant to get a valve leaking
25	or something to use there.
1	I contraction of the second seco

(202) 234-4433

1 We installed on each of these drain lines 2 five-gallon tubing run down to one of five five-gallon poly bottles, which are in the porous room that we 3 4 would use to collect any water if there was still 5 water leaking that would get into the sand bed region 6 here. 7 I just want to note that here it is shown as a -- looks like an open bucket. This is really 8 about a five-gallon bottle with a closed neck. 9 Five-gallon tubing is in to connect it to and vent it 10 11 through a filter so it's not an open bottle. So these 12 are where any water leakage would be collected. During the recent outage, these were 13 checked daily. And there was no water found in any of 14 15 these poly bottles. And when we were in the bays -and we were in all ten this time -- no water was found 16 in any of those at all during the outage. 17 This is a picture of the 18 Next slide. 19 drywell. The red at the bottom is the sand bed 20 region. And the important thing to note here is it 21 shows the construction of the drywell is made out of 22 essentially square plates welded together, the lower 23 elevation, the thickness of 1.154 inches. 24 As you see, as you go further up, it gets 25 thinner in the spherical region. Then it gets very

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	30
1	thick in the transition between the spherical and the
2	cylinder. We call this the knuckle region there.
3	It's two and five-eighths inches thick and then 640
4	mls in the cylindrical region.
5	Also shown here are the elevations where
6	we take UT readings from the inside of the drywell in
7	the upper part of the drywell. And we'll discuss
8	those a lot more later.
9	MEMBER ARMIJO: How far does the fire bar
10	D extend around that shell?
11	MR. POLASKI: Ahmed, can you help me with
12	that?
13	CHAIRMAN MAYNARD: You need to talk into
14	the microphone.
15	MR. OUAOU: Ahmed Ouaou with Exelon. Fire
16	bar D starts at elevation where the personal air lock
17	is, 23, and it goes all the way up.
18	MEMBER ARMIJO: Okay.
19	MR. POLASKI: Any other questions on that?
20	(No response.)
21	MR. POLASKI: Slide 11.
22	VICE-CHAIRMAN WALLIS: So when you took
23	this rust off, your people went in there and chipped
24	it away or something? How did you get it out?
25	MR. POLASKI: They went in and physically
	1

(202) 234-4433

	31
1	removed it.
2	VICE-CHAIRMAN WALLIS: It looks pretty
3	claustrophobic in there, very tight.
4	MR. POLASKI: It's very tight. It is only
5	15 inches up 5 and a half feet.
6	VICE-CHAIRMAN WALLIS: Right.
7	MR. POLASKI: When we ran and graphed the
8	work in there, there are size restrictions on people
9	we can hire. So it's very close. They went in and
10	cleaned it with hand tools, power-operated rotary
11	brushes and needlepoint brushes, and removed all of
12	the loose rust down to the only thing left there was
13	any tightly adhered corrosion.
14	MEMBER ARMIJO: Did they sandblast or
15	anything like that to get it off?
16	MR. POLASKI: Oh, no.
17	MEMBER ARMIJO: Just manual?
18	MR. POLASKI: Manual, yes.
19	VICE-CHAIRMAN WALLIS: Did you have any
20	estimate of the amount of rust?
21	MR. GALLAGHER: The number of pounds of
22	rust or something like that?
23	VICE-CHAIRMAN WALLIS: It was tons in my
24	calculation. There was a lot of rust.
25	MR. GALLAGHER: Yes. I don't know. Pete,
	1

(202) 234-4433

	32
1	do you have anything on that?
2	MR. TAMBURRO: This is Pete Tamburro for
3	AmerGen. When we did go in in '92, we did do some
4	samples of the thickness and how much had built up.
5	And we did a correlation of how much rust products we
6	would have expected versus the amount of loss. And it
7	pretty well matched up.
8	VICE-CHAIRMAN WALLIS: So you actually
9	weighed how much you took away?
10	MR. TAMBURRO: We measured the volume of
11	how much was at a certain area.
12	VICE-CHAIRMAN WALLIS: Do you have a clue
13	as to how much that was, the total rust you took away?
14	MR. TAMBURRO: I don't recall offhand.
15	VICE-CHAIRMAN WALLIS: It's useful, sort
16	of the idea of how much there was, you know.
17	MR. TAMBURRO: I could get you that
18	information.
19	VICE-CHAIRMAN WALLIS: If you look at the
20	thicknesses, which are assumed in some of these
21	calculations, it's several tons of rust.
22	MR. TAMBURRO: I could get you that
23	information.
24	VICE-CHAIRMAN WALLIS: Okay. That would
25	be useful. Thank you.

```
(202) 234-4433
```

	33
1	MR. POLASKI: Going on to slide 11,
2	because of the corrosion, it's very simple: water
3	accumulation in the sand bed region, resulting in
4	corrosion in the exterior surface of the drywell
5	shell.
6	Corrective actions were completed in 1992.
7	The first one was that actions were taken to prevent
8	water intrusion into the sand bed region. The basic
9	way of doing this was application of metallic tape on
10	the larger cracks on the liner and then coating of the
11	entire reactor cavity liner prior to a slow-up in the
12	refueling outage with a strippable coating. And this
13	has been effective in reducing the leakage.
14	This last outage it was measured at about
15	a gallon a minute. And it was well within the
16	capacity of the leakage trough collection system and
17	prevent any water from getting onto the drywell shell.
18	A second corrective action was eliminating
19	the corrosive environments by removing the sand. And,
20	lastly, the drywell shell after it had been cleaned of
21	the corrosion products was coated with an epoxy
22	coating.
23	MEMBER ARMIJO: Before you go on, you
24	assert that the sand bed region that the water
25	accumulated there, stayed there for a long time?
	I contract of the second se

(202) 234-4433

	34
1	MR. POLASKI: Yes.
2	MEMBER ARMIJO: In the rusting
3	MR. POLASKI: Yes.
4	MEMBER ARMIJO: Now, in the upper regions,
5	you conclude that this fire bar D insulation retained
6	water so that the corrosion continued because
7	otherwise the water should have just run down the
8	sides and nothing should have happened? So it must be
9	porous or something that retains the water there in
10	contact with the steel.
11	MR. POLASKI: Well, in the upper portion,
12	you've got that fire bar D on there.
13	MEMBER ARMIJO: Yes.
14	MR. POLASKI: There were seven or nine
15	flow samples removed from the drywell to determine
16	what the corrosion mechanism was. And when they did
17	those, the fire bar D was still attached to the plugs.
18	And we are continuing to monitor the thickness in
19	those areas with UT readings.
20	We take them at the lead areas, the
21	thinnest areas, every other refueling outage. And as
22	we'll get into the details later, the corrosion in
23	that area is essentially zero except one location. I
24	think it was .66 mls per year.
25	MR. GALLAGHER: But I think, to answer

(202) 234-4433

	35
1	your question, Dr. Armijo, the material is like an
2	asbestos material. So it would retain water. The
3	other thing is, you know, what you said is correct.
4	The other thing is that we did investigate
5	early on whether the material within the fire bar D
6	would have had some, say, corrosive effect. And it
7	was concluded that it was not a contributor to the
8	corrosion.
9	MEMBER ARMIJO: Other than water
10	retention?
11	MR. GALLAGHER: Other than the water
12	retention.
13	MEMBER ARMIJO: Okay.
14	VICE-CHAIRMAN WALLIS: I'm surprised there
15	was enough oxygen. I mean, it's not water that
16	corrodes. You need air. Don't you need oxygen there
17	to make rust?
18	MR. GALLAGHER: There is an air gap.
19	VICE-CHAIRMAN WALLIS: Yes, but you could
20	have the air moving to put the oxygen in there. And
21	it's a pretty stagnant area. It's also surprising
22	there was enough oxygen to make all that rust.
23	MR. GALLAGHER: Do you mean in the sand
24	bed region?
25	VICE-CHAIRMAN WALLIS: Yes. And the

(202) 234-4433
	36
1	oxygen, you need a lot of air to make that oxygen,
2	make tons of oxygen.
3	MR. POLASKI: Well, the water that would
4	get in there during a refueling outage was oxygenated.
5	VICE-CHAIRMAN WALLIS: Yes, but you need
6	a huge amount of oxygen to make the volume.
7	MR. POLASKI: This went on for a number of
8	years, though.
9	MEMBER ARMIJO: This had gone on for a
10	number of years before it was discovered.
11	VICE-CHAIRMAN WALLIS: That's still an
12	awful lot of oxygen.
13	CHAIRMAN MAYNARD: Could we move on?
14	MR. POLASKI: Going to slide 12, we just
15	want to get through some information on what we are
16	doing to monitor the positions and verify that the
17	corrective actions have been effective. During our
18	refueling outage in October 2006, as I said before,
19	the linkage from the reactor cavity liner is collected
20	in a trough and out the trough drain line. It was all
21	captured there. It was estimated about a gallon a
22	minute. And it was captured through that drainage
23	system and routed throughout the rad waste system and
24	kept away from the drywell shell.
25	We took UT thickness measurements of the
	I contract of the second se

(202) 234-4433

	37
1	drywell at the 19 monitoring locations at elevation
2	11.3. This are the ones from inside the drywell down
3	between the upper and lower curve break load event
4	headers. And they showed no change in thickness from
5	previous readings.
6	We were in all ten of the bays and did 100
7	percent visual inspection of the epoxy coating in each
8	of the bays. And that was found to be in good
9	condition. And there was no water in the sand bed
10	region throughout the outage.
11	Slide 13. Outside, on the outside of the
12	drywell surface, in the sand bed region, there were
13	106 UT measurements taken. These were in locations
14	that had been last measured in 1992. Now, 1992 was
15	when the sand was removed and the rust and corrosion
16	was cleaned off.
17	At that time before they applied the epoxy
18	coating, they determined those locations that were the
19	thinnest regions and thinnest areas from looking at it
20	through micrometer readings to determine the locally
21	thinned areas. And then UT measurements were taken at
22	those locations after having prepared the surface.
23	As you will see in some of the pictures,
24	it's a very rough surface. You have to physically
25	grind off that roughness to make it smooth enough for
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	38
1	the UT.
2	VICE-CHAIRMAN WALLIS: These were taken
3	from inside?
4	MR. POLASKI: No. These are taken from
5	outside in the sand bed region.
б	VICE-CHAIRMAN WALLIS: And how did the
7	person decide where to put the measuring device when
8	
9	MR. POLASKI: Okay. In 1992, there was a
10	team of NDE technicians and engineers went in there
11	and did it, physically an examination of the surface.
12	They used gauges and determined the areas that had the
13	most corrosion on them, did UT measurements. They
14	prepped those areas. And we'll show you in some
15	pictures that it's very obvious where those are.
16	And so they took the measurements. And
17	they had dimensions of where those UT measurement
18	locations were. So when the technicians went in this
19	time, they were able to
20	VICE-CHAIRMAN WALLIS: When the
21	technicians made thee first measurements, someone
22	decided where to measure.
23	MR. POLASKI: Yes. And that was done in
24	1992.
25	VICE-CHAIRMAN WALLIS: And if you left it
	NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. (202) 234-4433 WASHINGTON, D.C. 20005-3701 (202) 234-4433

39 1 in the hands of the technician, then he can choose to 2 measure thin bits or fat bits or what depending on where he puts or she puts the device. 3 4 MR. GALLAGHER: Now, what was happening, 5 Dr. Wallis, is the purpose of that particular inspection was to find to thinned locations. 6 7 VICE-CHAIRMAN WALLIS: Did the person 8 deliberately --9 MR. GALLAGHER: Yes. 10 VICE-CHAIRMAN WALLIS: -- put the device on the thinner parts or --11 MR. GALLAGHER: So what was done was it 12 was -- let me just show you an example. 13 14 VICE-CHAIRMAN WALLIS: Instructions were 15 to put the device on the thinner parts --MR. GALLAGHER: Yes. The instructions --16 17 VICE-CHAIRMAN WALLIS: -- or did someone devise the grid ahead of time? 18 19 MR. GALLAGHER: Instructions were a 20 complete visual inspection of that surface before we 21 coated it. And the instructions were to identify 22 locations that were thinned. And this is relative to 23 _ _ 24 VICE-CHAIRMAN WALLIS: This is why the 25 measurements are in such strange places?

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	40
1	MR. GALLAGHER: That's correct. And, just
2	to pop you to a picture, Dr. Wallis, on page 91, if we
3	could put that up, page 91 shows an example of that.
4	That area that's circled. It looks like a divot.
5	That is one of the actual locations that are measured.
6	So that divot was intentionally put in place. So, in
7	other words, it was prepped so that you could have a
8	
9	VICE-CHAIRMAN WALLIS: Thinking you made
10	it thinner?
11	MR. GALLAGHER: In that particular case,
12	yes, you know, to get
13	VICE-CHAIRMAN WALLIS: Because they were
14	so rough that you wanted it to be smooth?
15	MR. GALLAGHER: Right.
16	CHAIRMAN MAYNARD: You wanted to get it
17	smooth enough for the UT.
18	MR. GALLAGHER: For the UT. Now, because
19	you remember on the inside of the drywell, when we
20	take the measurements there for the 19 grids, it's
21	smooth.
22	VICE-CHAIRMAN WALLIS: And you don't know
23	how thick it is. So there's no selectivity in where
24	you put the
25	MR. GALLAGHER: So you don't have to worry
	I

(202) 234-4433

	41
1	about where you put the probe. Here we were
2	identifying the thinnest locations. We identify them
3	and then we prep them. And then that would
4	VICE-CHAIRMAN WALLIS: Make them thinner?
5	MR. GALLAGHER: In that particular case.
6	And in 1992 we took the measurements. We took them
7	again in 2006. And we go into that, the sand bed
8	presentation. We have all that data in details.
9	VICE-CHAIRMAN WALLIS: Okay. So all of
10	these ringed places I see, those are places where you
11	measured, right?
12	MR. GALLAGHER: That's correct.
13	VICE-CHAIRMAN WALLIS: All right.
14	CHAIRMAN MAYNARD: Now, where that
15	transition is, is that where the sand had stopped? It
16	looks like it's pretty dramatic there.
17	MR. GALLAGHER: That's correct.
18	MR. POLASKI: On this picture, this area
19	down here is where the sand was and where it badly
20	pitted, corroded, and very rust surface.
21	Up here, this is the thicker part of the
22	drywell shell around the van header. So I guess one
23	thing you can say, this line that comes down here,
24	this is a device that they use, the NDE techs, for
25	locating where they are taking their measurements. So
	1

(202) 234-4433

	42
1	this is vertical. You are looking at an angle here.
2	So this sort of shows that at this elevation is where
3	the top of the sand was, heavy corrosion below it, no
4	corrosion above it.
5	MEMBER ARMIJO: It makes the point that if
б	water hadn't been retained, it would have just run off
7	and there would have been no problem.
8	MR. GALLAGHER: That's correct.
9	MEMBER ARMIJO: I take it
10	MEMBER SIEBER: You mentioned that in
11	order for a technician to find from the outside the
12	lowest or the deepest pit, they're going to use a
13	depth gauge of some sort?
14	MR. POLASKI: We did. We used
15	micrometers.
16	MEMBER SIEBER: And that means that it's
17	relative to the surrounding material. So there is a
18	chance that you didn't get to the thinnest part
19	because it's a relative measurement.
20	MR. POLASKI: Well, I think what we can
21	say on that is because they did in fact, inspection
22	was done over 100 percent of it. I mean, we're
23	looking for relative areas. Any of the thinned areas
24	that they found relative to the surrounding areas were
25	identified.
	1

(202) 234-4433

	43
1	And when you look at the thickness of
2	these UT readings that were taken, they range from
3	some of the most corroded areas to some areas that are
4	relatively thick and not much thinner than nominal.
5	MR. GALLAGHER: Yes. But you are right.
6	They are relative. And that's why in some of the
7	bays, that there's very little corrosion. The
8	thinnest points are pretty thick. You know, they are
9	nominal one inch. And then, you know, in the other
10	bays, where there was corrosion, they are thinner, but
11	they're the thinnest points.
12	MEMBER SIEBER: Well, when you think about
13	the technique, there probably isn't given this
14	geometry, there isn't any other way to do it. On the
15	other hand, there is a chance that there is a thin
16	point that you didn't get. That chance is probably
17	small.
18	MR. GALLAGHER: That's correct.
19	MEMBER SIEBER: But it is still there.
20	MEMBER ARMIJO: These readings in '92 were
21	taken before the epoxy paint was put on?
22	MR. POLASKI: That's correct.
23	MEMBER ARMIJO: So you prepped it either
24	grinding or water brushing or something to get down to
25	metal?
	1

(202) 234-4433

	44
1	MR. POLASKI: Yes.
2	MEMBER ARMIJO: And then what kind of
3	contact? Did you use a grease or water contact for
4	the UT probe or
5	MR. POLASKI: The UT measurements are with
6	a probe and uses a standard coupling that they use on
7	any kind of UT ratings.
8	MEMBER ARMIJO: Okay. But in 2006, when
9	you went back, it had been painted and
10	MR. POLASKI: Yes.
11	MEMBER ARMIJO: You'll account for that in
12	your measurement?
13	MR. POLASKI: Yes.
14	MEMBER SIEBER: You have to remove the
15	paint to do the
16	MR. POLASKI: No, you don't.
17	MEMBER SIEBER: grout right through the
18	paint?
19	MR. POLASKI: The UT techniques that are
20	available today could measure the thickness of the
21	metal and subtract out the thickness of the coating.
22	MEMBER ARMIJO: Okay. We'll get to that.
23	MR. GALLAGHER: Yes. We have a slide on
24	the
25	MEMBER SIEBER: Yes. We'll get to that in
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

ĺ	45
1	detail later when we get to the curvature issue.
2	MR. POLASKI: Yes. We will get to that
3	later.
4	MEMBER SIEBER: I've got a couple of
5	questions there.
6	MR. POLASKI: Okay.
7	MR. GALLAGHER: Yes. We do in the
8	presentation have a slide on that particular thing.
9	MEMBER SIEBER: All right.
10	MR. GALLAGHER: Okay.
11	MR. POLASKI: And the last point I would
12	like to make is that UT measurements on the inside of
13	the drywell in the upper elevations at the 13
14	locations that we have been monitoring since the early
15	1980s were performed, these we routinely do every
16	other refueling outage and have been doing every other
17	refueling outage. And all of these locations showed
18	there was only one location with a very small amount
19	of one showing corrosion.
20	Twelve of them showed no corrosion. And
21	the one that did have corrosion was very low, .66 mls
22	per year. And that location will meet its required
23	thickness through 2029 with margin.
24	Slide 14
25	CHAIRMAN MAYNARD: Just a head's up here.
l	1

(202) 234-4433

	46
1	We're going to be tieing into a phone bridge here.
2	And there may be some noise or whatever. So just to
3	give everybody a head's up.
4	MEMBER SHACK: Just to come back, I mean,
5	those locations are not that thinnest. So if you have
6	ongoing rate at that location, suppose you applied
7	that rate to another location that's thinner. Would
8	it make your
9	MR. POLASKI: Well, in the upper drywell,
10	those are the thinnest locations. There was extensive
11	and we're going to get into this detail later
12	extensive investigation going on at over 1,000
13	locations to find the thinnest areas.
14	MEMBER SHACK: But the grid locations
15	weren't necessarily the thinnest.
16	CHAIRMAN MAYNARD: Are you talking higher
17	or lower?
18	MR. GALLAGHER: Which bridge?
19	MEMBER SHACK: Upper and lower. I'm
20	sorry.
21	MR. GALLAGHER: In the sand bed region?
22	MEMBER SHACK: Yes. Okay. Right.
23	Different regions.
24	(Whereupon, the foregoing matter went off
25	the record briefly.)
	1

	47
1	CHAIRMAN MAYNARD: Go ahead.
2	MEMBER ABDEL-KHALIK: The first line of
3	this table presumably refers to the 87-foot, 5-inch
4	elevation. Is that correct?
5	MR. POLASKI: The cylindrical region here,
6	yes, that's in the upper part above the sphere. Yes.
7	MEMBER ABDEL-KHALIK: Do you have a
8	similar entry for the 71-foot, 6-inch elevation?
9	MR. POLASKI: I'll look at my drawing to
10	make sure I'm sure it's right.
11	MR. GALLAGHER: Are you talking about the
12	knuckle?
13	MEMBER ABDEL-KHALIK: Right above the
14	knuckle.
15	MR. GALLAGHER: Okay.
16	MEMBER ABDEL-KHALIK: Because on your
17	report, you indicate there was a measurement that was
18	done at the 71-foot, 6-inch elevation, where the
19	minimum thickness was actually .449 inches. And that
20	would tell me that the margin available at that
21	location would be considerably less than the margin
22	you indicate on this table for the cylindrical region
23	at the 87-foot, 5-inch elevation.
24	MR. POLASKI: So we're clear, what report
25	are you reading from so we can
I	I Contraction of the second

(202) 234-4433

	48
1	MEMBER ABDEL-KHALIK: Your report that was
2	submitted on December 8th.
3	MR. OUAOU: Ahmed Ouaou with AmerGen. I
4	believe you had referred to the transition between the
5	knuckle plate to the cylindrical portion.
6	MEMBER ABDEL-KHALIK: Correct.
7	MR. OUAOU: Yes. That was a measurement
8	that was taken for the first time in 2006. And the
9	point that you referred to is single point on that
10	area. In fact, that would be compared against local
11	criteria, as opposed to general criteria.
12	MEMBER ABDEL-KHALIK: So why is that not
13	included in any of your tables?
14	MR. GALLAGHER: If we could clarify that?
15	So what these tables are talking about is the average
16	thickness as measured in the grids? That individual
17	point, what you would do is compare that.
18	If you go to page 44, page 44 and we'll
19	get into this in detail when we get into analysis.
20	But page 44 shows the thicknesses for each location
21	based on membrane stresses. And so, as you can see in
22	the cylinder area, as long as it's greater than 301,
23	it's acceptable because that's a local thickness
24	criteria.
25	A single point that the thickness criteria
	1

(202) 234-4433

	49
1	we describe this to you later in the presentation.
2	It's basically a two and a half-inch diameter area.
3	The thickness could be as low as 301.
4	MEMBER ABDEL-KHALIK: Yes. But,
5	nevertheless, if you look at that spot, the margin
6	would be less than the margin that you indicate for
7	the higher elevation point, the 87
8	MR. GALLAGHER: Yes, for that specific
9	point.
10	MEMBER ABDEL-KHALIK: foot, 5-inch
11	elevation.
12	MR. GALLAGHER: Right.
13	MR. POLASKI: I think the major point we
14	need to make here is that on slide 14, we're looking
15	at average thicknesses. When we take these thickness
16	readings and keep them for and a later presentation
17	is going to go into this in great depth. It's a
18	6-by-6 grid, 49 individual readings that are taken.
19	Yes, Pete?
20	MR. TAMBURRO: Pete Tamburro. The
21	inspections we did at that elevation were one
22	6-by-6-inch area above the transition weld on the
23	plate that is nominally .66 inches and that one
24	6-by-6-inch area below the transition weld, which is
25	a plate nominally 2 and five-eighths inch, I think.
1	I Contraction of the second

(202) 234-4433

	50
1	The number that you are citing is for a
2	plate above the transition weld.
3	MEMBER ABDEL-KHALIK: Correct.
4	MR. TAMBURRO: And that local value would
5	be compared to the criteria for the thinner nominal
6	plates.
7	VICE-CHAIRMAN WALLIS: Would you explain
8	this difference between the required general thickness
9	and the required local thickness? And the required
10	local thickness would seem to depend on how big that
11	local area is.
12	MR. TAMBURRO: Right.
13	VICE-CHAIRMAN WALLIS: Thank you.
14	MR. POLASKI: That's correct. And they're
15	limited to a two-and-a-half-inch diameter area.
16	VICE-CHAIRMAN WALLIS: Very small area,
17	yes.
18	MR. GALLAGHER: What we do and we'll
19	get into this in the presentation is that for a
20	grid, the average thickness is calculated. And then
21	it's bounced off the criteria for this average
22	thickness. Each individual point that's measured is
23	also looked at compared to its local criteria. And
24	all the points lead to local criteria.
25	VICE-CHAIRMAN WALLIS: Then you look in
	1

(202) 234-4433

	51
1	adjacent points and see how big that area could be?
2	Is that what you do?
3	MR. GALLAGHER: If there are multiple ones
4	close by, that's looked at also.
5	VICE-CHAIRMAN WALLIS: If they're not, how
6	big do you decide the local area is around the
7	MR. GALLAGHER: The criteria for the local
8	would be two-and-a-half-inch diameter.
9	VICE-CHAIRMAN WALLIS: How do you
10	determine that two and a half is okay? Do you know
11	that it's not bigger than that?
12	MR. GALLAGHER: Well, you know the grid
13	size is a six by six.
14	VICE-CHAIRMAN WALLIS: If you have a fine
15	enough grid, you can do that.
16	MR. GALLAGHER: how many points you
17	VICE-CHAIRMAN WALLIS: If you don't have
18	a fine enough grid, then you may have a difficulty.
19	MR. GALLAGHER: Then you would have to
20	interrogate.
21	VICE-CHAIRMAN WALLIS: Yes.
22	MEMBER SIEBER: So you are treating this
23	as a memory?
24	MR. GALLAGHER: Yes. In the upper
25	drywell, we get into that. The upper drywell is
I	1 I I I I I I I I I I I I I I I I I I I

```
(202) 234-4433
```

52 1 controlled by membrane stresses. Buckling only 2 controls in the sand bed. 3 MEMBER SIEBER: So that applies to 4 hydrostatic forces. 5 PARTICIPANT: Pressure. The stresses, the membrane 6 MR. GALLAGHER: 7 stresses. 8 MEMBER SIEBER: Right. 9 ABDEL-KHALIK: So when that MEMBER 10 measurement at that location was made, it indicated a local fitting down to .449 inches at that location. 11 It was decided not to enlarge the area of measurement. 12 Why was that decision made? 13 14 MR. TAMBURRO: Again this is Pete Tamburro. 15 We did review the data points around that. 16 And that was a localized area. The other data points 17 around it were thicker. We did investigate the data around that one individual point. 18 19 MEMBER ABDEL-KHALIK: Within the six-inch 20 by six-inch area, but you didn't look at another 21 six-inch six-inch in the immediate by area 22 neighborhood? 23 MR. TAMBURRO: No. 24 MR. POLASKI: Any other questions? 25 (No response.)

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

MR. POLASKI: Okay. That concludes my portion of the presentation on the overview and the physical condition of the plant. We're now going to go onto the section on the drywell shell thickness analysis. And I would like to introduce Dr. Hardayal Mehta of General Electric.

7 Dr. Mehta received his Ph.D. from the 8 University of California at Berkeley. He's a 9 registered professional engineer in the State of 10 California and was elected an ASME fellow in 1999. He 11 is the author or co-author of over 35 ASME papers.

12 Mehta has been with GΕ Nuclear Dr Division since 1978 and currently holds the position 13 14 of chief engineer, mechanics. He has over 30 years of 15 experience in the areas of stress analysis, 16 linear-elastic, and elastic plastic fracture 17 mechanics, residual stress evaluation, and ASME code-related analyses for things with BWR components. 18

He has also participated as principal investigator or project manager for several BWR, VIP BWR owners' group, and EPRI-sponsored programs at General Electric.

23 Prior to joining General Electric, he was
24 with Intel Corporation, where he directed various
25 piping and structural analyses.

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

	54
1	Dr. Mehta?
2	DR. MEHTA: Thank you, Fred.
3	B. DRYWELL SHELL THICKNESS ANALYSIS
4	DR. MEHTA: Good morning. I'm going to
5	describe some of the structural analysis details of
6	the drywell that we did contract. Going to slide 16,
7	the analysis was completed in the early 1990s. And
8	definitely this one, the analysis was without sand in
9	the sand bed region.
10	I am going to provide some details on the
11	modeling of the drywell, which was finite element
12	model details; and the loads, load combinations that
13	we used; and followed by the buckling analysis
14	details, in which the sand bed region is controlled by
15	the thickness. And the analysis that we did, buckling
16	analysis, the sand bed thickness was assumed as
17	uniform value of 736 mls. You recall the original
18	thickness was 1.154 inches.
19	Again, in the ASME code analysis, which is
20	the section 8 analysis, we used 62 psi as the peak
21	pressure. And later on in the presentation, Mr. Ahmed
22	Ouaou will be presenting results where the 62 psi peak
23	pressure was reduced to 44 psi based on the peak
24	pressure calculations that were done separately.
25	Go on to the next slide. This now is the

(202) 234-4433

	55
1	modelling of the drywell in detail, slide 18. This,
2	the first bullet provides some of the details of the
3	general bulk of details in terms of height, diameter,
4	and so on.
5	At the bottom of this slide, I have the
6	material. The material that was ordered for the
7	drywell, which is the material for the sphere,
8	slender, dome, and transitions was SA-212, grade B
9	material, which was over to S-8 standard
10	specification.
11	Currently that material would be equal
12	into SA-516, grade 70, which has 38 ksi yield and 70
13	ksi ultimate stress, essentially equal into what we
14	will order the material today.
15	MEMBER ARMIJO: Were those properties,
16	mechanical properties, verified by independent testing
17	or was that just as specified?
18	DR. MEHTA: As the ASME 8 to the
19	quadrants, which are essentially equal into section 3
20	and also the environments, which were also verified.
21	We go on to slide 19, finite element
22	involving details. We used clean models,
23	axisymmetric, B model, and the pie slice model. The
24	axisymmetric model we'll use for the unflooded and
25	flooded seismic inertial loading and also for the
1	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	56
1	thermal loading during the postulated accident
2	condition.
3	The B model we used to come up with the
4	initial spectrum analysis and to also check the John
5	Blum original analysis. So that was used. And also
6	we developed the displacement for the displacement or
7	anchor displacement model.
8	The pie slice model was used for the
9	section 8 analysis and buckling analysis that had all
10	of the details essentially, like, for example, vent
11	lines, which in axisymmetric model is not possible to
12	present.
13	And, again, to emphasize, there was no
14	sand thickness used in the studies, essentially
15	assuming the sand had been taken out.
16	MEMBER SIEBER: So from the bottom of the
17	sand bed on up, it's all free-standing?
18	DR. MEHTA: Yes.
19	MEMBER SIEBER: Okay. Thank you.
20	DR. MEHTA: Next slide. In the pie slice
21	model, which is essentially where we transferred the
22	load from the axisymmetric model, like seismic inertia
23	and displacement were applied to the pie slide model.
24	In this case, given that there are ten
25	vent lines, we used one-tenth, which is one-tenth of

(202) 234-4433

57 1 360-degree would be 36-degree pie slice. And essentially at that time the capabilities, comparable 2 3 capabilities, that we're developing, that was 4 consistent with that. And the ANSIS model included from the 5 drywell shell from the base of the sand bed all the 6 7 way up to the top. And also the drywell thickness 8 that was used was assumed in this analysis at 736 mls 9 uniform throughout the sand bed region. The next slide shows a picture of this. 10 And what you will see, different colors here are 11 12 essentially the thickness differences. That is, each color represents a particular thickness. And the sand 13 14 bed region, which is at the bottom, has 736 loads 15 thickness. Move on to the next slide. 16 In terms of 17 the applied loads that we considered in the analysis, the gravity loads consisted of deadweight loads, 18 19 penetration loads, live loads, and also during the 20 refueling condition, the water load that is applied. 21 MEMBER ARMIJO: Does that include all the

22 water that's inside the torus hanging off the vents? 23 DR. MEHTA: I believe that is the water 24 that backs through the drywell dock head. And that --25 MR. POLASKI: No.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	58
1	MEMBER ARMIJO: No.
2	MR. POLASKI: I think that Dr. Armijo's
3	question was, does this analysis include the weight of
4	the water down in the torus at the end of the vent
5	line?
6	MEMBER SIEBER: The torus is reported
7	separately from the drywell.
8	MEMBER ARMIJO: It is reported separately.
9	So it's not transferring weight.
10	MEMBER SIEBER: There is some flexure in
11	this.
12	VICE-CHAIRMAN WALLIS: There is some sort,
13	yes. There is some sort of a bellows or something.
14	DR. MEHTA: That is how essentially we
15	only the torus is actually isolated.
16	MEMBER SIEBER: It's independent.
17	DR. MEHTA: And the only modeling in terms
18	of this thing we had was the vent line and then the
19	vent header to which it connects. So that's where we
20	have to
21	MEMBER ABDEL-KHALIK: So there is no load
22	transmission along the vent lines?
23	MEMBER SIEBER: Well, it's pressurable.
24	DR. MEHTA: It's only from just the edge,
25	whatever passes through the vent header and so on,

(202) 234-4433

	59
1	just connection, being connection. But basically that
2	didn't affect much of the analysis.
3	MEMBER ARMIJO: Okay.
4	DR. MEHTA: The accident pressure at that
5	time was 62 psi peak pressure. That was used in the
6	analysis. And you will also see later on that through
7	tech spec amendment, there was change of the peak
8	pressure to 44 psi.
9	And the test results are in the data
10	slides. At the end of this presentation, Mr. Ahmed
11	Ouaou will be presenting the results corresponding to
12	what we forecast.
13	There were accident condition temperature
14	stresses, which are thermal gradient stresses are
15	there. Those would be included as a part of the
16	accident condition analysis.
17	MEMBER ABDEL-KHALIK: Now, the mechanical
18	properties that you quoted earlier, the 38 ksi yield
19	stress and the 70 ksi ultimate strength, are those at
20	175 degrees F.?
21	DR. MEHTA: Those are up to about, I
22	believe, 200 degrees Fahrenheit. So that's
23	essentially consistent with the temperature with the
24	stress of the next model.
25	And it's the same way in the case where

(202) 234-4433

	60
1	the maximum stress is primary. Plus, secondary
2	stresses that we see are actually during the
3	post-accident condition. But the accident condition
4	where the primary stress is maximized, the temperature
5	is within the range of those properties.
6	The seismic loading we considered was
7	inertial loading, which is due to the spectrum
8	loading, and also the relative anchor displacement.
9	Essentially in this case the drywell is connected to
10	star truss. And that provides a later restraint. And
11	that was used in the analysis.
12	And also during seismic shaking, there
13	will be something that the reactor building will take
14	the drywell for a ride, certain displacement that
15	occurs. And that's 58 mls.
16	And that also produces seismic stresses in
17	the drywell, which was considered in this analysis.
18	In fact, that was about two-thirds of the
19	VICE-CHAIRMAN WALLIS: Now, in a seismic
20	event, does water slosh around inside this?
21	MEMBER SIEBER: Torus.
22	VICE-CHAIRMAN WALLIS: Well, also isn't
23	there water in the drywell, too, or there isn't a
24	combination of accident and seismic? So
25	MR. GALLAGHER: In the reactor cavity are

(202) 234-4433

	61
1	you talking about, Dr. Wallis?
2	VICE-CHAIRMAN WALLIS: Yes.
3	MR. GALLAGHER: For the refueling case,
4	there would be water in the
5	VICE-CHAIRMAN WALLIS: You don't have
6	seismic and refueling at that same time. So you don't
7	have water in there during the seismic event?
8	MR. GALLAGHER: Yes. The load combination
9	is seismic event, refueling with the two pounds
10	external.
11	VICE-CHAIRMAN WALLIS: So does the water
12	slosh around up there and
13	MR. GALLAGHER: I guess. I mean
14	VICE-CHAIRMAN WALLIS: Does that get
15	analyzed?
16	DR. MEHTA: It was indicated that the only
17	effect would be the weight of the water, which would
18	be, in fact, if you take into account the other
19	structures about 80 percent would be effective. So if
20	we took the 80 percent of the water during the
21	VICE-CHAIRMAN WALLIS: But does it move
22	around dynamically, this water in a seismic event?
23	And do you get extra loads because the water is
24	sloshing around?
25	DR. MEHTA: Based on our previous

(202) 234-4433

	62
1	experience, it was our engineering judgment that
2	because on what we would see, the sloshing would be
3	minimal and would not, in fact, be
4	VICE-CHAIRMAN WALLIS: It's so small, yes,
5	because
6	CHAIRMAN MAYNARD: That area would be
7	fairly full of water, correct? Any sloshing at all
8	would be spilling over the side, rather than sloshing.
9	VICE-CHAIRMAN WALLIS: Yes. As long as
10	it's full, as long as it's full, you might be okay.
11	MR. GALLAGHER: And the displacements, Dr.
12	Mehta, what's the displacement we're talking about?
13	VICE-CHAIRMAN WALLIS: It's very small.
14	DR. MEHTA: For example, anchor
15	displacement was 0.058 inch. So we are looking at a
16	very small displacement. And so it was our judgment
17	that the sloshing wouldn't be significant.
18	Going to the next slide.
19	VICE-CHAIRMAN WALLIS: Are you going to
20	explain to me now where the two psi comes from?
21	Sorry.
22	MEMBER SIEBER: Let me just ask a quick
23	question that will clarify something for me. On slide
24	23, you talk about the upper constraint. And if you
25	go back to slide 5, which is the drawing, could you
	I contraction of the second seco

(202) 234-4433

63 1 show me where the upper constraint is? Detail B. Is 2 that it? 3 PARTICIPANT: You'll need to talk into the 4 microphone. 5 CHAIRMAN MAYNARD: Yes. You'll need to talk into the microphone. 6 7 MR. POLASKI: Again, you have to talk into the microphone. 8 9 (Laughter.) 10 PARTICIPANT: It's a test. MR. GALLAGHER: Ahmed, why don't you point 11 12 And, Dr. Mehta, you can -to it? CHAIRMAN MAYNARD: Microphone. You need 13 14 to be talking into the microphone, please. 15 VICE-CHAIRMAN WALLIS: They're consulting. 16 DR. MEHTA: I believe it is at 74 feet, 17 3-inch or something. Again, microphone. 18 CHAIRMAN MAYNARD: 19 Somebody needs to be talking into the microphone while 20 somebody else is pointing. 21 MEMBER SIEBER: That's elevation 82 where 22 you're pointing. 23 MR. OUAOU: The elevation, as indicated on 24 the slide, is at 82, Dr. Mehta. 25 Now, what does that MEMBER SIEBER: Yes.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

```
(202) 234-4433
```

	64
1	consist of? Right now it looks like there's no
2	contact. So why is that an upper constraint?
3	MR. OUAOU: What it is Ahmed Ouaou with
4	AmerGen. What it is is a lug welded to the back of
5	the shell with an insert in the concrete.
6	MEMBER SIEBER: Okay.
7	MR. OUAOU: And that is a gap, a fairly
8	small gap, to allow for some movement, yet not
9	restrained in the containment.
10	MEMBER SIEBER: And then surrounding that
11	during construction was this insulating material?
12	MR. OUAOU: That's correct.
13	MEMBER SIEBER: Okay. Thank you.
14	Appreciate it.
15	CHAIRMAN MAYNARD: I believe Dr. Wallis
16	had a
17	VICE-CHAIRMAN WALLIS: While we're on the
18	he's going to get to the next slide.
19	MR. GALLAGHER: Yes, slide 24.
20	VICE-CHAIRMAN WALLIS: So when he puts up
21	24, we'll ask him that one.
22	DR. MEHTA: Slide 23. In the seismic load
23	definition, we use axisymmetric model. And, as the
24	earlier discussion indicated, we considered the
25	restraint at the star truss, which is 82 feet, 6
	1

```
(202) 234-4433
```

	65
1	inches.
2	And we had two spectra, one at the
3	foundation and the other one at the upper constraint.
4	We used the envelope of the two spectra to input into
5	the analysis, which was the axisymmetric model. From
6	that, we look at the expiration profile, which was
7	then put into the pie slice model.
8	The next slide shows the load combinations
9	and the constituent loads.
10	VICE-CHAIRMAN WALLIS: Where did this two
11	psi come from? Where did this two psi come from, this
12	two psi external? Is that a realistic number or is
13	that just some sort of conservative assumption or what
14	is it? Where did this two psi come from? And is it
15	realistic?
16	DR. MEHTA: This was in the specification.
17	VICE-CHAIRMAN WALLIS: Is it realistic?
18	Does it happen? I mean
19	MR. GALLAGHER: No, it does not.
20	VICE-CHAIRMAN WALLIS: Why do you put it
21	in there?
22	MR. GALLAGHER: It's a conservatism. I
23	think Dr. Mehta explained why that would be
24	conservative.
25	MR. POLASKI: Ahmed, do you want to do it?
	1

```
(202) 234-4433
```

	66
1	MR. OUAOU: Ahmed Ouaou with AmerGen.
2	That two psi was part of the original design basis of
3	the containment. It was in UFSAR. And it was felt
4	that we should maintain the original load combinations
5	that were in the UFSAR.
6	MR. POLASKI: This would imply that there
7	is some cause for this pressure difference and that
8	it's maintained in some way.
9	MR. OUAOU: Well, during normal operation
10	of the plant, you would have that external pressure of
11	two psi, but if
12	VICE-CHAIRMAN WALLIS: Because there's a
13	vacuum maintained inside?
14	MR. OUAOU: That's correct. But if the
15	hatches are open and so on, you shouldn't really
16	expect to see that, but for conservatism, to be
17	consistent with the CLB of
18	VICE-CHAIRMAN WALLIS: So you see the
19	normal operation, but you wouldn't see it in
20	refueling? Is that what it is?
21	MR. GALLAGHER: Dr. Wallis, just a
22	clarification. For normal operation, I mean, normally
23	you maintain the containments slightly pressurized.
24	VICE-CHAIRMAN WALLIS: You have two psi,
25	then?
	I

(202) 234-4433

	67
1	MR. GALLAGHER: No. Slightly pressurized,
2	one pound. So you would have one pound in containment
3	normally. And this is a two-pound external.
4	VICE-CHAIRMAN WALLIS: It's being
5	conservative.
6	MR. GALLAGHER: Right.
7	VICE-CHAIRMAN WALLIS: During refueling,
8	do you have that same thing?
9	MR. GALLAGHER: No. The refueling hatches
10	are open.
11	VICE-CHAIRMAN WALLIS: Right. And how
12	much of a contribution is this two psi to the
13	buckling? It is trying to collapse things, isn't it?
14	DR. MEHTA: Two psi produces about 600 or
15	700 psi compressive pressure
16	VICE-CHAIRMAN WALLIS: That's significant.
17	DR. MEHTA: stress in the sand bed
18	region.
19	VICE-CHAIRMAN WALLIS: Right. So you're
20	adding something which is not realistic?
21	DR. MEHTA: That is conservative.
22	VICE-CHAIRMAN WALLIS: And how much of a
23	contribution is this to the proportion of the stress?
24	It's a big contributor, isn't it?
25	MR. GALLAGHER: No.

(202) 234-4433

	68
1	VICE-CHAIRMAN WALLIS: You said 60,000 psi
2	produces
3	PARTICIPANT: Six hundred.
4	MR. GALLAGHER: Six hundred.
5	DR. MEHTA: Six hundred. Yes.
6	VICE-CHAIRMAN WALLIS: Oh, that's all?
7	MR. POLASKI: So I guess the question
8	would be, do you know? Did you do any studies? If
9	you did not include the two psi internal pressure, how
10	much difference would that have made in the results?
11	DR. MEHTA: It would be the compressive
12	loading, which produces buckling in the sand bed
13	region, would be lower by 600 psi.
14	VICE-CHAIRMAN WALLIS: Only 600 psi.
15	That's not a lot, no.
16	MEMBER SIEBER: That's not a lot.
17	VICE-CHAIRMAN WALLIS: Okay. Good.
18	DR. MEHTA: Overload, as I would explain
19	in the buckling case, is about 7.5 psi compressive
20	stress.
21	MEMBER ARMIJO: So you could look at that
22	two psi as really margined in your analysis that you
23	haven't taken credit for?
24	MR. POLASKI: Yes, you could.
25	MEMBER ARMIJO: I mean, it's small, but

(202) 234-4433

	69
1	it's not working in the wrong direction?
2	MR. GALLAGHER: Right. That's correct.
3	DR. MEHTA: In the load combinations,
4	again, the refueling condition was gravity loads;
5	pressure; water load; and the seismic, which was
б	actually two times the design basis earthquake, which
7	is the SSE condition. In effect, that is also
8	conservative in the sense that generally for refueling
9	and accident condition, it's the OBE, or operating
10	basis earthquake, is considered into the evaluation.
11	MEMBER ABDEL-KHALIK: So which mechanical
12	properties did you use for the 281 degrees F.
13	analysis?
14	DR. MEHTA: In that one, the temperature
15	gradient stress corresponding to that would be for the
16	SA-212, grade B we used corresponding to between 200
17	and 300 Fahrenheit "properties." From that, we used
18	the average value.
19	MEMBER ABDEL-KHALIK: And what were those
20	values compared to the room temperature values that
21	you quoted earlier?
22	DR. MEHTA: It's up to 200 I believe are
23	the same, no change.
24	MEMBER ABDEL-KHALIK: Okay.
25	DR. MEHTA: There is a slight change from

(202) 234-4433

	70
1	200 to 300 degrees Fahrenheit, but in this case, the
2	200, 175 degrees essentially
3	MEMBER ABDEL-KHALIK: I'm asking about the
4	281 degrees F. analysis.
5	DR. MEHTA: Yes. In that one, at that
6	point, we linearally interpolated the properties, like
7	E and alpha.
8	MR. GALLAGHER: Right. Do you recall the
9	number, Dr. Mehta? I think he's asking for a number.
10	Do you recall the number or do we have to get back to
11	him?
12	DR. MEHTA: Number? I'm sorry. I don't
13	have it, but for cog and steel, E would be like about
14	26 or 27 10^6 psi. And then the alpha would be about
15	6. or 7.0 times 10^{-6} inch per inch.
16	MR. GALLAGHER: Thank you.
17	CHAIRMAN MAYNARD: Said, is that something
18	you would like for them to get back to you on or
19	MEMBER ABDEL-KHALIK: I think it would be
20	a good idea to know the properties that were used in
21	these calculations just for the record.
22	MEMBER ARMIJO: But the point is you did
23	take into account the different mechanical properties
24	at the higher temperatures and you have that data
25	available for us?

(202) 234-4433

	71
1	DR. MEHTA: Yes.
2	MEMBER ARMIJO: Okay. Thank you.
3	VICE-CHAIRMAN WALLIS: Now, this 74-foot,
4	6 inches, is this vessel always filled so much during
5	a post-accident condition? This is almost filling the
6	whole thing, isn't it? This is an extreme case of
7	some sort or what you expect in a post-accident
8	condition?
9	MR. GALLAGHER: Yes. I think this goes
10	all the way up to the vent.
11	VICE-CHAIRMAN WALLIS: Yes. It goes all
12	the way up to almost fill the whole thing.
13	MR. POLASKI: These are the load cases
14	that we have to analyze.
15	VICE-CHAIRMAN WALLIS: This is some
16	conservative extreme assumption, is it, or something?
17	This is the most water you could possibly put in there
18	before it comes out?
19	PARTICIPANT: That's correct.
20	MR. GALLAGHER: Yes, this is conservative.
21	VICE-CHAIRMAN WALLIS: It just seems
22	unusual. Maybe I don't understand the post-accident
23	scenario.
24	MR. GALLAGHER: I mean, these are the load
25	combinations that we're required to analyze for.
	1

(202) 234-4433
	72
1	MR. POLASKI: These are the load
2	combinations. These are the ones that in the current
3	licensing basis before this analysis
4	VICE-CHAIRMAN WALLIS: This in the worst
5	that could possibly happen that you fill the whole
6	thing up to the vent.
7	MEMBER SIEBER: It's very conservative.
8	MR. GALLAGHER: And, Dr. Wallis, I mean,
9	you're hitting on some good points because if you even
10	think this whole refueling, the refueling is our
11	limiting case here for buckling. And so you think
12	about it.
13	What it is is during refueling, which only
14	occurs about 20 days out of every 2 years, that we
15	would have a seismic event twice the design basis and
16	we have this external pressure on the containment.
17	So probablistically it's pretty small, but
18	this is what we're required to analysis for.
19	CHAIRMAN MAYNARD: Yes. The requirements
20	for these types of analysis do require that level of
21	conservatism.
22	MR. GALLAGHER: That's correct. That's
23	correct.
24	CHAIRMAN MAYNARD: Yes.
25	DR. MEHTA: And these were also provided

(202) 234-4433

	73
1	in the design specification, which was the basis for
2	the analysis that
3	MEMBER SIEBER: Right. Okay.
4	VICE-CHAIRMAN WALLIS: But if we're trying
5	to look at what is the real risk of something, it is
6	nice to know what is the reality as well as what is
7	some design specification.
8	MR. GALLAGHER: Right. I understand.
9	VICE-CHAIRMAN WALLIS: Could someone
10	explain to me maybe later on about when, in ever, you
11	get this 74-foot, 6 inches occurring in reality?
12	MR. POLASKI: We probably don't have that
13	
14	MR. GALLAGHER: We will follow up. We can
15	follow up in a brief because what you would be into is
16	your trip, your emergency operating procedures.
17	VICE-CHAIRMAN WALLIS: Right.
18	MR. GALLAGHER: And so it would be way
19	beyond anything normal.
20	VICE-CHAIRMAN WALLIS: Okay.
21	MR. GALLAGHER: Yes.
22	DR. MEHTA: These load combinations that
23	were used, now moving on to buckling analysis, 26,
24	what I have provided here is first the basic summary
25	of the buckling analysis. This was conducted in the
	I contract of the second se

(202) 234-4433

uniform drywell shell thickness of some 36 mls in the sand bed region.

3 The stress limits and safety factors in 4 accordance with the code requirements, the analysis 5 showed that the code case and 284 requirements are met and considered the design basis load and 6 load 7 combinations which were consistent with that as a part of the sensitivity study, would that consider a local 8 area which is beyond the 736 ml thickness with a local 9 thickness reduction of 536 mls, which is when we found 10 that there was a more significant impact on the 11 buckling. 12

And the last one is, as you would see, some more details of how the 736 mls are being monitored against acceptance criteria, which --

16 VICE-CHAIRMAN WALLIS: All right. When 17 you do the buckling analysis, do you actually model the instability and its growth? Do you actually let 18 19 the thing proceed to buckle or is it some kind of 20 empirical method? Do you actually let the thing 21 crumple when you do your analysis? It begins to go 22 unstable and then presumably you stop or do you use 23 some ASME coefficients of some sort?

DR. MEHTA: We use first the ANSIS model,which gives us the theoretical buckling load. And

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

(202) 234-4433

74

ĺ	75
1	then we actually reduce that by the so-called capacity
2	reduction
3	VICE-CHAIRMAN WALLIS: But you have to
4	assume some sort of Eigen function or something. You
5	have to I'm trying to figure out how much of this
6	does ASME build some conservativeness or do you
7	actually analyze the thing to the point where it
8	collapses?
9	DR. MEHTA: The collapsed load was
10	calculated, but then we apply the code case in 284
11	has reduction in the theoretical calculated buckling
12	load corresponding to what the
13	VICE-CHAIRMAN WALLIS: How do you
14	calculate the buckling load, then?
15	MR. GALLAGHER: I think if I can just
16	interject here because I think Dr. Wallis is after
17	looking at what margins are available
18	VICE-CHAIRMAN WALLIS: No. Actually, does
19	it buckle?
20	MR. GALLAGHER: No.
21	VICE-CHAIRMAN WALLIS: Your analysis
22	doesn't go to a large deflection.
23	MR. GALLAGHER: You go to a stress value,
24	but there's a safety factor in there. And the safety
25	factor is dependent on your load combination either 2
1	

(202) 234-4433

	76
1	or 1.67. And Dr. Mehta will go through that, but so
2	you go to the stresses with safety factor.
3	VICE-CHAIRMAN WALLIS: The buckling
4	criteria and there is some ASME mixture of factors,
5	rather than actually calculating buckling happening.
6	Is that right?
7	MR. GALLAGHER: Yes.
8	DR. MEHTA: You're looking at buckling
9	load, which I think the next couple of slides
10	illustrate the process that you follow.
11	MEMBER ARMIJO: Basically you only get to
12	a stress level that's half of what's required to
13	buckle. You don't actually
14	MR. GALLAGHER: Right, because there's a
15	safety factor, too.
16	MEMBER ARMIJO: Yes.
17	MR. GALLAGHER: So you would get down to
18	there still should be
19	VICE-CHAIRMAN WALLIS: But you still have
20	these NIs and alpha I's and those things.
21	MR. GALLAGHER: Yes.
22	CHAIRMAN MAYNARD: I appreciate everyone's
23	patience here. We do have a number of people
24	listening on phone calls. And it's important that we
25	speak into the microphone and speak with a loud voice
	1

(202) 234-4433

	77
1	so that everybody can hear.
2	DR. MEHTA: In the next slide, I will have
3	some of the details of the
4	MEMBER ABDEL-KHALIK: Can we go back to
5	slide number 26? The locally thinned area, the
6	12-inch by 12-inch area, where was that located in the
7	36-degree pie slice?
8	DR. MEHTA: That was in between the for
9	the sand bed because we believe that's where we saw
10	buckling mode shape
11	MEMBER ABDEL-KHALIK: No. Azimuthally
12	where is it located? Around the angle within the
13	36-degree pie slice?
14	DR. MEHTA: The 36-degree
15	MR. GALLAGHER: It would be at the two
16	edges.
17	MEMBER ABDEL-KHALIK: At the two edges.
18	So half of it is located on one edge, and the other
19	half is located on the other edge of the
20	PARTICIPANT: So when you put the slice
21	together, it's a 12-by-12.
22	MEMBER ABDEL-KHALIK: In the middle,
23	between the two vent
24	PARTICIPANT: And that's where the most
25	stresses are

	78
1	MEMBER ABDEL-KHALIK: Thank you.
2	MEMBER ARMIJO: I have a question on that
3	I meant to ask earlier. You say the 12-by-12-inch
4	area, 536 would have no significant impact on
5	buckling. For that same thinning, how big an area
6	would have a significant effect?
7	In other words, if this were a 4-foot by
8	4-foot area at 536, would that make a difference?
9	Would it be you know, I would like to just know how
10	conservative or non-conservative is it, this
11	12-by-12-inch.
12	DR. MEHTA: In this 12-inch by 12-inch
13	area, where we put that in the worst location, we
14	found about approximately a 9 percent reduction in the
15	buckling load, which is kind of like considered like
16	plus/minus 10 percent in the ASME code in the
17	MEMBER ARMIJO: If you have made that area
18	twice as big, would it have been like an 18 percent
19	reduction in the buckling load or is it linear? I'm
20	just trying to get an idea of how much of a
21	DR. MEHTA: We only went up to 12-inch by
22	12-inch, but my guess is that there will be further
23	reduction. If it were a much larger area, then there
24	would be a somewhat larger reduction. But in this
25	case, we only considered 536.
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

1MR. POLASKI: So, Dr. Armijo, I t2answer to your question is that they only look	chink the
2 answer to your question is that they only loop	
	ked at a
3 12-by-12. And, actually, that 12-by-12 then	tapers
4 from 536 to 736. We did not investigate if t	here were
5 larger areas.	
6 And I don't believe that there was	s a need
7 to do that based on the information they had av	vailable
8 at the time. And we confirmed that later wi	th NT
9 measurements if there's no areas that come eve	en close
10 to this 536 on one-foot-square area.	
11 MEMBER ARMIJO: Right. Basically	y if you
12 conclude that where you have data it represent	nts a 12
13 by 12-inch region and the worst, if you measur	e a thin
14 area I guess I lost my train of thought.	I'm just
15 trying to find out what we have to worry abo	out here
16 and	
17 MR. POLASKI: Later in the presen	ntation
18 I would like to hold it until we get to it -	we've
19 got a diagram that shows all of the readings th	hat were
20 taken on the containment. I think that will	give you
21 a good picture to show you that no areas are a	anywhere
22 close to 536 in this kind of	
23 MEMBER ARMIJO: Of that much area	a?
24 MR. POLASKI: Yes, that much area	a, nothing
Ω	

(202) 234-4433

	80
1	VICE-CHAIRMAN WALLIS: I would like to ask
2	that this this is a GE analysis. Sandia also did
3	an analysis. Are we going to hear a presentation of
4	the Sandia? We are? Okay. Thank you.
5	MS. LUND: Yes. That will be later on
б	this afternoon.
7	VICE-CHAIRMAN WALLIS: Okay.
8	DR. MEHTA: In the next slide, this slide
9	illustrates the equation that was used for the log or
10	compressive stress or buckling stress. As you will
11	see, the first one on the numerator of this equation,
12	on the right-hand side is sigma IE.
13	That is the theoretical stress, which when
14	we do the modeling and just let it run, it will give
15	an item value which is how much is the what is the
16	theoretical buckling load for perfect shell as it is
17	modeled is the buckling load compared to the applied
18	load. If the item value is six, that means the
19	theoretical buckling load is six times the upper
20	VICE-CHAIRMAN WALLIS: Buckling is a
21	global phenomenon, isn't it? It's not a local
22	phenomenon?
23	DR. MEHTA: Right.
24	VICE-CHAIRMAN WALLIS: So how can there be
25	a stress?

(202) 234-4433

81 1 DR. MEHTA: In the ANSIS model, it starts 2 off with whatever is the lowest particular -- wherever 3 the buckling is happening first. And so we look for 4 the lowest item value. And that is the lowest 5 buckling load. And then there are higher item values, 6 which will show that some other locations may be 7 valued. 8 So in this case, we use the boundary 9 conditions in this one, symmetric-symmetric and so on, 10 just to make sure whichever gives us the lowest ideal value. 11 VICE-CHAIRMAN WALLIS: I understand that, 12 I mean, if you have a but where is this stress? 13 14 narrow region, the stress is bigger there. So 15 presumably the thinner region, the stress is bigger. So where is this allowable compressive stress? 16 Is it 17 the maximum one somewhere? We have a couple of --18 MR. GALLAGHER: 19 MR. POLASKI: We have some pictures that 20 we will show you --21 MR. GALLAGHER: Slide 31 and 32 I think 22 will hit that point. 23 VICE-CHAIRMAN WALLIS: But if you have a 24 stress distribution, buckling must be something to do 25 with the entire distribution, not just the local

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	82
1	stress.
2	MR. GALLAGHER: Dr. Wallis, if we could go
3	to slide 31?
4	VICE-CHAIRMAN WALLIS: Maybe it's too
5	complicated to explain.
6	PARTICIPANT: No, it isn't.
7	MR. POLASKI: Let's let Hardiyal go
8	through. And we'll get to that. I think we'll show
9	you the answer in a couple of slides.
10	VICE-CHAIRMAN WALLIS: Maybe Dr. Shack
11	understands it all and can explain it to me in the
12	break.
13	DR. MEHTA: So the sigma IE in this
14	equation is the theoretical buckling stress. And then
15	on the left of that is alpha I, which is the reduction
16	of the reduction
17	VICE-CHAIRMAN WALLIS: Is this an average
18	stress or something? Where do I get this sigma IE?
19	DR. MEHTA: It's the average in the sense
20	that the average in a stress in the sand bed region.
21	And if I use that as a number
22	VICE-CHAIRMAN WALLIS: Average stress?
23	DR. MEHTA: For the purposes of
24	multiplying to get a theoretical number. Otherwise
25	the stress distribution, we realize that it varies
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	83
1	through the sand bed region. But in order to apply
2	the item factor of like 6.141, whatever the stress is,
3	whatever the stress in the sand bed region, it is
4	6.141 times or the
5	VICE-CHAIRMAN WALLIS: Average stress?
6	Times the average stress?
7	DR. MEHTA: It is for the purposes, Dr.
8	Wallis, if we have to use a number, we use the average
9	stress, but that
10	VICE-CHAIRMAN WALLIS: Sigma IE is an
11	average stress?
12	DR. MEHTA: Average stress.
13	VICE-CHAIRMAN WALLIS: Thank you. That's
14	what I was trying to figure out.
15	MR. POLASKI: Dr. Mehta, just to be clear,
16	it's the average in that grid, right, because you're
17	on a
18	DR. MEHTA: Or it's to the section through
19	the sand bed region.
20	VICE-CHAIRMAN WALLIS: It's the whole
21	thing. Yes. That's what I'm trying to get. Okay.
22	And so a slightly thinner, narrower region wouldn't
23	affect that significantly, right?
24	DR. MEHTA: Right. We essentially
25	VICE-CHAIRMAN WALLIS: All right. That's
	1

(202) 234-4433

	84
1	what I'm trying to get at. Thank you.
2	DR. MEHTA: In the one key factor in the
3	analysis
4	VICE-CHAIRMAN WALLIS: I'm sorry. This
5	compressive stress, does it matter which direction
6	this stress is on? You have tangential, and you have
7	whatever you call the other ones, longitudinal or
8	something stresses. Which stress is it or is it some
9	combination of these stresses?
10	MR. POLASKI: So the question is, what
11	combination of stress
12	VICE-CHAIRMAN WALLIS: Yes. Stress is a
13	tensor, isn't it? Which stress are you looking at
14	here?
15	DR. MEHTA: There were all the applied
16	stresses to the model as they you know, like, for
17	example, the seismic stresses in the
18	VICE-CHAIRMAN WALLIS: Yes, but stress is
19	a tensor. So which stress is this stress?
20	DR. MEHTA: They were compressive in the
21	
22	VICE-CHAIRMAN WALLIS: In which direction?
23	In the longitudinal? In the vertical sort of
24	direction or the tangential? Does it matter which
25	one?
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	85
1	DR. MEHTA: In the vertical direction,
2	which is the meridional direction, they were
3	compressive.
4	VICE-CHAIRMAN WALLIS: That's the one you
5	look at, the meridional. So the tangential stress,
6	which we get in another mode somewhere here, doesn't
7	have any effect? The circumferential compression
8	doesn't tend to buckle it, like squeezing it a beer
9	can and buckling it? It doesn't
10	DR. MEHTA: The geometry of this is such
11	that that meridional with compressive stress along
12	with this thing produces tensile or hoop stress, which
13	is a circumferential direction, which it tends to
14	straighten out any imperfections, which may contribute
15	to buckling. So we did take that into account, effect
16	in order to modify the capacity reduction factor.
17	MR. POLASKI: Dr. Wallis, I think the next
18	couple of slides will show you diagrammatically that
19	the different
20	VICE-CHAIRMAN WALLIS: So this compressive
21	stress that's here, the sigma IE, is the meridional
22	stress? Yes, this one. It's this one. It's not the
23	circumference.
24	MR. POLASKI: It's this one, yes.
25	VICE-CHAIRMAN WALLIS: And the

(202) 234-4433

	86
1	circumferential one has no effect?
2	MEMBER ARMIJO: It looks like it must
3	because that's
4	VICE-CHAIRMAN WALLIS: Must.
5	CHAIRMAN MAYNARD: Why don't we move on to
6	a couple of slides? And then if it's not clear after
7	that
8	VICE-CHAIRMAN WALLIS: Maybe it will never
9	become clear.
10	MR. POLASKI: Let's go through the slides.
11	DR. MEHTA: The slides will show buckling
12	shape and the
13	VICE-CHAIRMAN WALLIS: That helps. That
14	helps, yes. That helps.
15	DR. MEHTA: And the third factor will be
16	the eta I in this equation, which is the plasticity.
17	If it turns out that the buckling, calculated
18	theoretical buckling stress, is quite a bit higher
19	than the proportional limit, then there will be some
20	plasticity. And there should be
21	VICE-CHAIRMAN WALLIS: Right.
22	DR. MEHTA: Correspondingly, the load
23	should be reduced. So we use that also as the factor
24	eta I. And so overall the allowable stress is
25	calculated firstly but from the theoretical buckling
	I

(202) 234-4433

	87
1	stress times the capacity reduction factor alpha I and
2	then the eta I, which is the plasticity reduction
3	factor, divided by safety factor.
4	And we use a safety factor of 2.0 for the
5	refueling condition and 1.67 for the post-accident
6	condition, which are consistent with the ASME code and
7	the code case and 280 code.
8	The boundary conditions for buckling
9	analysis for the pie slice model, essentially there
10	were only core combinations. So we use
11	symmetric-symmetric, asymmetric-symmetric. And I'm
12	going to on the next slide show how the
13	symmetric-symmetric boundary condition would be. What
14	you would see on this slide is the nearby bay has the
15	same symmetric displacement as the main bay.
16	VICE-CHAIRMAN WALLIS: I have a question
17	about this, too. You have a pie shape. You have a
18	pie shape. So it seems that your buckling shape of
19	the wavelengths are determined by this 36-degree
20	segment. It doesn't allow you to have one which is,
21	say, half goes around, includes two segments in a
22	wavelength, doesn't it?
23	The fact that you have a pie constrains
24	the kind of item values that you can pick up, does it?
25	You've got this boundary condition which is sort of
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	88
1	restricting the modes, isn't it?
2	Maybe Sandia can explain this to me later
3	on. The fact that you have a pie restricts the
4	buckling modes, doesn't it?
5	DR. MEHTA: Given this 36-degree segment,
6	we have geometry up to this. And we have taken the
7	worst bay in the sense that the
8	VICE-CHAIRMAN WALLIS: There is symmetry
9	around this pie. So it doesn't allow you to have
10	modes which would not have equal behavior on both
11	sides of the pie, right?
12	DR. MEHTA: Yes. In this case, it's equal
13	behavior, which is the symmetry boundary condition.
14	And the next slide, 29, shows where this could be one
15	direction here, the other direction there. And so
16	that is the asymmetric mode.
17	And so we did consider it
18	symmetric-symmetric, symmetric-asymmetric, and
19	asymmetric-asymmetric. And so the symmetric-symmetric
20	gives up the lowest item value. That is the lowest
21	buckling load.
22	MEMBER ABDEL-KHALIK: Are there any
23	buckling modes in which the span can be greater than
24	36 degrees?
25	DR. MEHTA: At least the way this is
	1

(202) 234-4433

	89
1	modeled?
2	MEMBER ABDEL-KHALIK: No. I mean, look at
3	the symmetric-symmetric, which gives you the largest
4	span, previous
5	DR. MEHTA: Previous slide?
6	MEMBER ABDEL-KHALIK: If you were to do a
7	full 360 degrees, are there any buckling modes in
8	which the span can be greater than one-tenth the
9	entire 360-degree?
10	DR. MEHTA: I believe in that case, those
11	kinds of modes, you would have a higher item value
12	because in this case, given that we have the
13	360-degree slice, the boundary conditions we could
14	supply were this. So I believe we are somewhat
15	conservative
16	VICE-CHAIRMAN WALLIS: If I crumple a beer
17	can, it doesn't crumple into 36-degree pies. It does
18	something else, right? So you're sort of forcing this
19	thing to crumple into 36-degree pieces symmetrically.
20	MEMBER SIEBER: Well, it's complicated
21	somewhat by the tank
22	CHAIRMAN MAYNARD: First of all, crumpled.
23	We probably should use a crumpled soft drink can, as
24	opposed to a crumpled but they don't have pipes
25	running out of them.

(202) 234-4433

	90
1	MEMBER SIEBER: The connection to the
2	MEMBER ARMIJO: The reason 36 degrees was
3	chosen, could you just address
4	DR. MEHTA: At that time this was done in
5	the '89-'90 time frame. The competent capability we
6	had was about two orders of magnitude smaller than
7	what we put on the program at that time we had. So
8	that's all we only
9	VICE-CHAIRMAN WALLIS: We'll ask Sandia if
10	they got 36-degree
11	CHAIRMAN MAYNARD: I understand that it
12	was your position or assumption or guess that larger
13	pie pieces would actually end up with a higher item
14	value, which would be less likely to buckle.
15	MEMBER SIEBER: I think this is a vertical
16	view. There are ten vents, which means the vents are
17	36 degrees apart. They represent constraints.
18	CHAIRMAN MAYNARD: Right.
19	MEMBER SIEBER: And so the buckling, the
20	big knee of the buckling, is going to be between the
21	vents.
22	VICE-CHAIRMAN WALLIS: Are they
23	constraints, though? They can move around.
24	PARTICIPANT: Not much according to this.
25	MR. GALLAGHER: Dr. Wallis?

(202) 234-4433

	91
1	MEMBER SIEBER: They do move around. They
2	are not solid, but they are there.
3	MR. GALLAGHER: Yes. Around the vents,
4	they are stiffened. So that the metal is much thicker
5	around the vents.
6	DR. MEHTA: And the next slide essentially
7	is
8	MEMBER ARMIJO: Dr. Mehta, before you
9	leave those, I still don't understand this. I see
10	like a big sphere, and you're squeezing down on it.
11	And I don't understand. These pictures show us
12	looking down from the top.
13	MEMBER SIEBER: Right.
14	MEMBER ARMIJO: If we look from the side,
15	what would it look like? I kind of thought it would
16	buckle in the vertical direction, not in the
17	circumferential direction.
18	MEMBER SIEBER: I did, too, initially.
19	DR. MEHTA: I do have one of the buckling
20	modes, which was the limiting one for the buckled
21	shape.
22	MR. GALLAGHER: Let's show them, Dr.
23	Mehta. Let's show them that. Go to slide 31.
24	DR. MEHTA: Thirty-one? Okay. This is
25	the buckling analysis. One of the modes for the
	1

(202) 234-4433

	92
1	refueling condition case. Up here the red area is
2	actually moving radially outward. And the new area is
3	moving inward.
4	VICE-CHAIRMAN WALLIS: So if you looked on
5	the vertical slides, it's buckling in that plane as
6	well?
7	DR. MEHTA: And also it's moving out here.
8	So it's symmetric with respect to the nearby bay. And
9	so this is what is the theoretical buckle shape, which
10	gives the least buckling load, which is this factor
11	called 6.141. What that says is whatever load we
12	applied for the refueling condition, the theoretical
13	buckling load for this mode is 6.141 times that value.
14	VICE-CHAIRMAN WALLIS: But the load again
15	you're having a stress only in one direction or
16	something. That's what puzzles me because there are
17	stresses in both directions here, which must both
18	influence the buckling surely.
19	DR. MEHTA: The model has all of the
20	loading applied to the appropriate nodal loading, so
21	on. So it has exactly
22	VICE-CHAIRMAN WALLIS: All the resources
23	are in there, including the tensile ones.
24	DR. MEHTA: And only for convenience of
25	calculation, what we did was we just calculated a
	I contraction of the second seco

(202) 234-4433

	93
1	single value of the average stress here just to show
2	that if you take that average stress, multiply by
3	this, that will be the total theoretical buckling
4	load. But we know that the stress here is distributed
5	in a way that it values.
6	MEMBER ARMIJO: Okay. I understand now.
7	DR. MEHTA: The next slide shows the
8	asymmetric buckling mode. And in that case, as you
9	will see here, the factor is 6.231, which is higher
10	than 6.14. So essentially that is saying the
11	symmetric-symmetric load would be the least buckling
12	load.
13	MEMBER ABDEL-KHALIK: So mode one is the
14	limiting one, where you have symmetric-symmetric?
15	Mode three is less high or restrictive?
16	DR. MEHTA: Right.
17	MEMBER ABDEL-KHALIK: So the question then
18	is if the span is longer, if you were to take two
19	36-degree pie shapes and apply a mode one analysis on
20	them with symmetry on both ends of the 72-degree
21	MEMBER SIEBER: Right.
22	MEMBER ABDEL-KHALIK: pie shape, would
23	you get a lower load?
24	DR. MEHTA: I believe you will get a
25	rather higher load than that because that again would
Į	I contraction of the second

(202) 234-4433

	94
1	capture if we include more of the material, then that
2	would contribute to
3	VICE-CHAIRMAN WALLIS: Now, the smaller
4	wavelengths are more unstable? The smaller
5	wavelengths are more unstable? So I could go to a
6	tiny, tiny one? And it would be most unstable? It
7	doesn't make sense somehow. I thought the biggest
8	wavelengths were most unstable.
9	DR. MEHTA: For example, the 360-degree
10	model would capture all of that. And there what I
11	have seen
12	VICE-CHAIRMAN WALLIS: We'll see that.
13	DR. MEHTA: And what I have seen, I
14	believe, in Sandia would prove that the factors are
15	higher than what we have here.
16	VICE-CHAIRMAN WALLIS: It would be
17	interesting to see if they get the same kind of
18	pattern that you get. Okay.
19	MR. OUAOU: Ahmed Ouaou. Dr. Mehta, would
20	you get more information if you described the boundary
21	condition you used for the models that could explain
22	the question whether the mode is going to be lower or
23	higher? The boundary condition you can save it for
24	the pie slice to conclude that the model represents
25	VICE-CHAIRMAN WALLIS: It's a symmetric
	1

(202) 234-4433

	95
1	boundary condition. You're not allowing it to be a
2	72-degree we'll move on. I'm sure it will become
3	clear at the end of the day.
4	DR. MEHTA: It's my engineering judgment
5	that I believe it would be higher.
6	Next slide. Here are the details of the
7	summary of the buckling radiation for the refueling
8	case. As you would see up here, the bottom is the
9	7.59 psi, which is the average value that we calculate
10	for the refueling condition when all the loads were
11	applied.
12	As you would see in what we saw, the 6.141
13	was the factor that we got. So if we multiply 7.59
14	psi by 6.14, this is the theoretical buckling stress
15	like we get. Again, it's a single number that we are
16	looking at.
17	VICE-CHAIRMAN WALLIS: So the two psi is
18	contributing, the .59 part of this? Yes. The bottom
19	line there, 7.59, you said earlier that the 2 psi
20	contributes about .6. So it's about ten percent of
21	it. It's the two psi.
22	DR. MEHTA: That's correct.
23	VICE-CHAIRMAN WALLIS: Okay.
24	DR. MEHTA: When the capacity reduction
25	factor is 0.207, that indicates that with the

(202) 234-4433

96 1 reduction by а factor of five for the radius 2 imperfections that could be there and the actual shells. 3 4 Now, then we looked at the fact that the 5 geometry of the spherical shell in the sand bed region is such that we applied compressive stress produces 6 7 hoop tension, which tends to actually straighten out 8 some of the imperfections. 9 And for that, we went to Dr. Clarence Miller, who was the author of food case and 284. 10 He also currently is the chief engineer at Chicago Bridge 11 And he concurred with this approach. 12 and Iron. He said this approach to take into account that the 13 14 tensile circumferential stress would raise this factor from above. 15 16 And we calculated this or this SO 17 circumferential stress that was produced in the sand bed region for the applied building. But was it equal 18 19 in pressure calculated as if what that tensile stress 20 is in terms of equal in pressure. VICE-CHAIRMAN WALLIS: Take that away. 21 22 That's uniform. Uniform spherical. 23 DR. MEHTA: 24 VICE-CHAIRMAN WALLIS: You subtracted 25 That was a later calculation? You subtracted that?

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	97
1	the uniform stress?
2	DR. MEHTA: This one was just in terms of
3	if I had a hoop stress
4	VICE-CHAIRMAN WALLIS: Right, right.
5	DR. MEHTA: in a sphere, then what the
6	value equal in pressure would be. And then there is
7	a parameter which we go through. And all that
8	indicates is essentially this, the modified capacity
9	reduction factor, is 0.3
10	VICE-CHAIRMAN WALLIS: That's modified by
11	the circumferential stress?
12	DR. MEHTA: Due to the circumferential.
13	VICE-CHAIRMAN WALLIS: Okay. Good. Thank
14	you. That's
15	DR. MEHTA: All that indicates is that due
16	to the tensile stress in the sand bed region, the
17	actual penalty factor, instead of .207, would be .326.
18	So then if we multiply this number by this number, we
19	get 15.18, I guess.
20	Since this stress is very small, it's way
21	below the proportion limit. There was the elasticity
22	reduction factor was essentially 1.0. So this when
23	you multiplied by 1.0, we get the inelastic buckling
24	stress, which is 15.18 psi.
25	And if you apply a factor of safety of
	I

(202) 234-4433

	98
1	two, then we get this number. It just turns out in
2	this case this number would just about be the value
3	that is required from what we calculated here.
4	Now, again, this is based on 736 mls of
5	uniform thickness assumed throughout the sand bed
6	region.
7	MEMBER ABDEL-KHALIK: So without taking
8	credit for the circumferential stress, what would the
9	code safety factor be?
10	DR. MEHTA: It would be considerably
11	lower. For example, it would be in the ratio of .207
12	divided by .326. So at least by about the value
13	increased from .207 to .326, which was about 60
14	percent increased.
15	And we had consulted Dr. Clarence Miller.
16	He had also written a report. He agreed with this
17	approach that we used. And also he had produced a
18	Welding Research Council bulletin number 406, which
19	came out in 1995, had the same formulas in there which
20	were used in this approach.
21	VICE-CHAIRMAN WALLIS: I think that's why
22	in the accident load case you're okay because there is
23	a compressive stress in the accident load case, but
24	there's also a significant tensile stress, which
25	probably means it doesn't seem to be a buckling
1	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

99 1 analysis for the accident load case, although there is 2 a compressive stress. 3 PARTICIPANT: We presented the core 4 accident. 5 MR. GALLAGHER: We presented the limiting case here, Dr. Wallis, which is --6 7 VICE-CHAIRMAN WALLIS: You did do an 8 accident load case? I don't think Sandia did. Maybe 9 I'm --10 MR. GALLAGHER: For the accident pressure load case, Har? Dr. Hardiyal Mehta? 11 12 I'm sorry? DR. MEHTA: MR. POLASKI: The question is, as part of 13 14 this analysis, did you do a buckling analysis for the other load conditions, for the accident condition? 15 16 Did you do that analysis? 17 DR. MEHTA: Yes. We -- oh, for buckling? MR. POLASKI: Yes, for buckling. 18 19 DR. MEHTA: For buckling, we realized that 20 either the refueling or the post-accident condition is 21 governing. We realized that with the large internal 22 pressure, the buckling would not be an issue during 23 the --24 VICE-CHAIRMAN WALLIS: That's right. So 25 it's the tensile stress that saves you in that case.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	100
1	Thank you.
2	DR. MEHTA: Going to slide 34, as I
3	mentioned earlier, a local area of 12-inch by 12-inch
4	was considered in the modeling to do the sensitivity
5	study. There we produce this 12-inch by 12-inch area
6	to the end of the model to be where you saw the
7	buckled shape, which would tend to produce the largest
8	change in the item value.
9	And then that was used as a criterion for
10	the locally reduced message, which may be measured
11	during the UT inspection.
12	VICE-CHAIRMAN WALLIS: And you put it in
13	the worst place, did you? You put it in the worst
14	place as well as having
15	DR. MEHTA: Exactly, from effect on the
16	buckling load point of view.
17	MEMBER SIEBER: Are we to conclude from
18	that that the min. wall thickness varies from point to
19	point as far as the examinations that the licensee is
20	to make and that you just aren't going to apply a
21	constant min. wall for a given elevation in the
22	vessel?
23	MR. POLASKI: The answer to that is the
24	analysis, as we saw with the colored pictures where
25	the coupling would occur
	I Contraction of the second

(202) 234-4433

	101
1	MEMBER SIEBER: Yes.
2	MR. POLASKI: those are the areas that
3	were most susceptible to buckling. It was done at a
4	736 ml uniform thickness. We applied a 736, as I
5	remember
6	MEMBER SIEBER: Everywhere?
7	MR. POLASKI: everywhere.
8	MEMBER SIEBER: Okay.
9	MR. POLASKI: So in areas other than the
10	limiting buckling areas, we actually had more
11	MEMBER SIEBER: You have more margin
12	MR. POLASKI: More margin.
13	MEMBER SIEBER: as opposed to allowing
14	a reduction in the required thickness?
15	MR. POLASKI: Yes.
16	MEMBER SIEBER: Thank you.
17	DR. MEHTA: Going on to the next slide,
18	essentially concluding the buckling analysis,
19	conclusions, which were essentially the same measure
20	presented earlier, we used 736 mls uniform cell
21	thickness.
22	CHAIRMAN MAYNARD: Again I would ask you
23	to speak up a little bit because people on the phones
24	are having a hard time hearing sometimes.
25	DR. MEHTA: Okay. Thanks.
	1

(202) 234-4433

	102
1	VICE-CHAIRMAN WALLIS: Can you tell me who
2	is on the phone, out of curiosity?
3	MR. JUNGE: The State of New Jersey. I
4	think one of the congressmen is listening, Region I,
5	and someone from Rutgers environmental law clinic.
б	VICE-CHAIRMAN WALLIS: Okay. Thank you.
7	DR. MEHTA: Essentially this slide
8	summarizes what I had presented for the document
9	evaluation. And next I will be moving on to the
10	asymmetrical section 8 stress analysis.
11	MEMBER ABDEL-KHALIK: Excuse me. Before
12	we move on, the fact that the locally thinned area
13	the placement of the locally thinned area along the
14	symmetry lines for mode one makes that the worst
15	condition. That is not necessarily the case for mode
16	three, is it?
17	DR. MEHTA: After putting that locally
18	thinned area, we again draw the analysis whatever the
19	lowest mode was. It turned out to be also
20	symmetric-symmetric. And so I'm assuming that there
21	will be higher modes later on.
22	MEMBER ABDEL-KHALIK: No. I mean, if you
23	were to do the analysis where the locally thinned area
24	is in the middle of one of the peaks for mode three,
25	would the minimum thickness be different than 536 mls?

(202) 234-4433

	103
1	DR. MEHTA: Well, the same item factor,
2	the minimum thickness, would be different and probably
3	would be even lower because what we had considered was
4	the worst location, the thickness we assumed was 536
5	mls.
6	Now, if we consider an area where it is
7	not associated from the worst type of mode shape
8	location point of view, then naturally the area would
9	be even thinner there. That's my
10	MEMBER ABDEL-KHALIK: Okay. Thank you.
11	MEMBER ARMIJO: I think I finally figured
12	out what I was trying to ask a while ago. For this
13	12-inch by 12-inch area, how thin would the steel have
14	to be in order to lose your factor to safety in this
15	12-by-12-inch when you have a 12-by-12-inch thinned
16	area?
17	You know, you say that it has no
18	significant impact of 536. What thickness does it
19	have a significant impact to the point where you would
20	lose your safety factor?
21	Do you see what I am trying to say? You
22	know, do you have more margin here or is this the very
23	edge or what?
24	MR. POLASKI: Is there any analysis going
25	to share that's thinner than 536? How thin do you
	1

(202) 234-4433

	104
1	have to go before buckling might actually occur?
2	MR. OUAOU: Ahmed Ouaou with AmerGen. We
3	do not have any analysis other than the 536 in the
4	12-by-12 area to demonstrate it.
5	MEMBER ARMIJO: A judgment question for
6	Dr. Mehta. Do you think it would be are you right
7	on the edge at 536 or 400 in a 400 mls 12-by-12-inch
8	area, still have no significant impact or would you
9	have crossed the line?
10	VICE-CHAIRMAN WALLIS: Of course, it's a
11	hole.
12	MEMBER ARMIJO: Yes. Well, a hole, you
13	know, for buckling, if it's just a small hole, it
14	won't make any difference. So at some point, so this
15	is an area thickness issue. And I'm just trying to
16	find out how far as we in the locally thinned area
17	VICE-CHAIRMAN WALLIS: Well, the vents
18	have been
19	MEMBER ARMIJO: But they are stiffened
20	with these giant
21	CHAIRMAN MAYNARD: Do you have that
22	information or is that something we need to go back
23	MR. GALLAGHER: We don't have a
24	calculation that the only thing we can say, as Dr.
25	Mehta mentioned earlier, is that this was about a 9

(202) 234-4433

105 1 percent reduction, you know, going to 536. So to get 2 to the safety factor, you have a 50 percent reduction. So you can go lower than 536. We just don't know how 3 4 much more. 5 MEMBER ARMIJO: That's what I'm trying to 6 get at. How far as we from --7 MR. GALLAGHER: We don't have that 8 analysis. 9 MEMBER ARMIJO: Okay. 10 DR. MEHTA: Going on to the ASME code section 8 stress analysis, slide 37. In this, the 11 stress analysis that we conducted according to the 12 ASME code quidelines, also we used one of 13 the 14 allowable stress limits from standard code section 3.8.2 because the ASME code did not have guideline for 15 the forced accident condition allowable stress limits. 16 The stress limits on safety factors were 17 according to the ASME code. The analysis showed that 18 19 the ASME code requirements were met. And also later 20 on in this slide, you will see the calculation of the 21 stresses based on the reduced pressure of 44 psi. 22 That reduction in pressure amounts to 23 about a maximum of 5,200 psi. And the minimum 24 required general and local drywell shell thicknesses, 25 those results are also presented later in this slide.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	106
1	And all of these are used for the acceptance criteria
2	in the inspection results.
3	We're going to now the details of this,
4	use the 1962 ASME code section 8 and also 3 code cases
5	which supplemented the requirements in the '62 edition
б	of the code.
7	The original code also didn't have certain
8	guidance in two areas. One area was whether local
9	areas increased membrane stress due to any thickness
10	reduction as to how far they could be or how the
11	extent of that area could be, which we have to use in
12	the case of '62 psi peak pressure, which was not
13	needed, actually, in the case of 44 psi peak pressure
14	because the stresses come out to be lower. And for
15	the, as I mentioned earlier, post-accident condition,
16	we used the limit from standard plan section 3.8.2.
17	This slide summarizes the allowable
18	stresses that we used in the code analysis. The three
19	categories are general primary membrane stress,
20	general primary membrane plus bending, and the primary
21	plus secondary.
22	In the all conditions except the
23	post-accident, the limits are again consistent with
24	what's in the ASME code for level C condition, which
25	is essentially for the accident condition.
	1

(202) 234-4433

107 1 And for the post-accident condition, these 2 limits are corresponding to the 38,000 psi general 3 primary membrane is the eave stress and 7,000 is for 4 the primary plus secondary stress. 5 Going on to the next slide, this slide, the table summarizes the radius calculated stresses 6 7 and the comparison with allowable values and the 8 percentage margin. 9 As you will see, they appear. The first column has the thicknesses that were used in the 10 analysis. These are uniform thicknesses in each of 11 12 the region. The 13 stress category and then the 14 calculated stress magnitudes are here. And these are 15 the allowable stresses. In this case, instead of 16 19,300 psi, we used to the extent that the ASME code 17 permits, that the local membrane stress is what's above 110 percent of the general membrane stress 18 19 limits. 20 The implication is if in an operating 21 structure you could have to some extent regions in 22 which the stresses between 100 and 110 percent of 23 allowable. So that was used here, which is not 24 necessarily in the case of 44 psi peak pressure, as 25 will be shown later.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433
	108
1	This, the last column shows the margins
2	that are with respect to the allowable stress. As you
3	could see, each of these meets the criteria.
4	VICE-CHAIRMAN WALLIS: Do you have any
5	comment on the size of the margin?
6	MR. POLASKI: We will address that in the
7	next section on the presentation. It's going to
8	discuss the change from 62 to 44 and how we gained
9	margin in that area.
10	VICE-CHAIRMAN WALLIS: You will tell us
11	why three percent was okay?
12	MR. POLASKI: Well, we're going to show
13	you that it's actually a lot more than three percent.
14	CHAIRMAN MAYNARD: Yes. This is based on
15	the 62 psi.
16	MR. POLASKI: This is 66.
17	CHAIRMAN MAYNARD: Okay. Okay. And that
18	extra two psi
19	MEMBER ARMIJO: And thank you.
20	VICE-CHAIRMAN WALLIS: Thank you, Dr.
21	Mehta.
22	MR. POLASKI: I would now like to
23	introduce Mr. Ahmed Ouaou. Mr. Ouaou was a member of
24	the Oyster Creek license renewal team. He has worked
25	on several license renewal projects, starting with the
	1

(202) 234-4433

	109
1	Peach Bottom license renewal project.
2	He holds a Bachelor's degree in civil
3	engineering from the University of Nevada and is a
4	registered professional engineer in California and
5	Pennsylvania. He has over 30 years experience in the
6	design and construction of nuclear power plants.
7	Mr. Ouaou will be presenting information
8	on the change that was made to the internal design
9	pressure of the drywell. The analysis that was
10	performed by General Electric was at 62 psi internal
11	pressure. And Mr. Ouaou will discuss the change to 44
12	psi design pressure.
13	Ahmed?
14	MR. OUAOU: Thank you, Fred. Good
15	morning.
16	CHAIRMAN MAYNARD: Good morning.
17	MR. OUAOU: The analysis that Dr. Mehta
18	described, again, is based on the two psi. And, as
19	Dr. Wallis pointed out, the margin is to be spread a
20	little in certain areas. And to address that
21	question, Oyster Creek investigated the potential of
22	evaluating de-establishing an Oyster Creek-specific
23	design pressure.
24	The 62 psi was based on generic tests at
25	the day-to-day. And the containment design is

(202) 234-4433

	110
1	somewhat different at Oyster Creek, particularly in
2	the venting from the drywell to the pressure chamber
3	or which decreases the pressure inside the drywell
4	considerably.
5	Slide 41, please. This slide, again, it
6	was recognized that the pressure is conservative and
7	analysis was conducted in early '90s to establish
8	unique design pressure. That analysis concluded that
9	the peak accident pressure inside the drywell is 38.1
10	psi. And it was increased by a 15 percent margin and,
11	thus, to 44 psi.
12	VICE-CHAIRMAN WALLIS: Now, in 1966, there
13	was an overload test of the drywell and vent system,
14	71.3 psi? You actually tested. It says, "Pneumatic,"
15	which seems to me strange. But, anyway, pneumatic
16	test? The whole thing was blown up to see if it would
17	pop. It's loaded inside with a pressure to see if it
18	would and so there was a test, which showed that it
19	was good for at least 71 psi.
20	Is there any kind of a test of this
21	damaged drywell in terms of hydraulic or pneumatic
22	testing?
23	MR. POLASKI: The only test that would
24	have been done would been the integrated leak rate
25	test. Howie, do you know when that was done last?
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	111
1	MR. RAY: That was done, I
2	MR. POLASKI: Introduce yourself.
3	MR. RAY: Oh. Howie Ray, AmerGen. The
4	next is coming up in 2008. The last one was 1990, I
5	believe, or no.
6	MR. GALLAGHER: No. Two thousand. We did
7	it in 2000.
8	MR. RAY: Two thousand, ten years, ten
9	years from 2010.
10	VICE-CHAIRMAN WALLIS: So you do actually
11	test the drywell under pressure?
12	MR. GALLAGHER: Right.
13	VICE-CHAIRMAN WALLIS: And what sort of
14	pressure did you test it at in the 1990-something?
15	MR. GALLAGHER: It's down to the 44
16	VICE-CHAIRMAN WALLIS: Oh, you tested it
17	at 44 or 44 is a design thing. You actually tested it
18	at 44?
19	MR. GALLAGHER: Yes. This is the
20	integrated leak break test that's done in accordance
21	with
22	VICE-CHAIRMAN WALLIS: Okay. So you did
23	test it. And that test was at 44 psi?
24	MR. GALLAGHER: Yes, that's correct.
25	VICE-CHAIRMAN WALLIS: Okay. Thank you.
I	1

(202) 234-4433

	112
1	MR. QUINTENZE: My name is Tom Quintenze.
2	I am the site lead for license renewal at Oyster
3	Creek. We do our integrative leak rate test per our
4	technical specifications. As indicated, it's done
5	periodically. The test pressure that we put that
6	under periodically is 35 pounds pressure. And that's
7	per our technical specifications.
8	VICE-CHAIRMAN WALLIS: You don't go up to
9	44, then?
10	MR. QUINTENZE: That is correct.
11	VICE-CHAIRMAN WALLIS: But in '66, you
12	went up to 71. It's called an overload test. You
13	don't do overload tests anymore.
14	MR. QUINTENZE: Okay. In 1966, when the
15	vessel was constructed, there was a test that was done
16	per the start-up testing requirements that were put
17	upon the vendors. And at that point in time, the
18	vessel would have put it into a test, which would have
19	been approximately 1.1 times the design pressure.
20	CHAIRMAN MAYNARD: I believe that all the
21	nuclear reactors initially built with containments,
22	you do an initial structural integrity test. And the
23	integrated leak rate test that we do every ten years
24	or so is primarily to identify leakage or
25	VICE-CHAIRMAN WALLIS: Right. It's a load

(202) 234-4433

	113
1	pressure.
2	MR. POLASKI: Correct.
3	MR. GALLAGHER: Tom, thanks for clarifying
4	these pressures. Thanks.
5	VICE-CHAIRMAN WALLIS: We don't have a
6	test at 44 psi, then?
7	MR. GALLAGHER: Tech specs at 35.
8	MEMBER SHACK: If you don't expect failure
9	at 44, there's no way to know what your margin is.
10	VICE-CHAIRMAN WALLIS: But if you had gone
11	above 44 and not failed, you would know something.
12	MEMBER SHACK: You still don't know what
13	your margin is.
14	VICE-CHAIRMAN WALLIS: No, no.
15	MEMBER SHACK: I mean, the whole question
16	here is to identify margin.
17	VICE-CHAIRMAN WALLIS: Yes.
18	MEMBER SIEBER: You only get to do that
19	once.
20	CHAIRMAN MAYNARD: Do you know, 44 psi, is
21	that what your current safety accident analysis would
22	show your peak pressure to be or is that just what you
23	are now using as your containment design pressure?
24	MR. OUAOU: The containment design
25	pressure is 38.1. The design pressure is 44. That's

(202) 234-4433

	114
1	in accordance with our current CLB and the approved
2	VICE-CHAIRMAN WALLIS: And in an accident,
3	you don't go above that, right, presumably?
4	MR. OUAOU: Accident, you should not go
5	above 38.1.
6	MEMBER SIEBER: Thirty-eight, yes.
7	VICE-CHAIRMAN WALLIS: 38.1.
8	MR. OUAOU: Right.
9	VICE-CHAIRMAN WALLIS: Okay.
10	MEMBER ABDEL-KHALIK: Just for
11	clarification, the integrated leak tests are done at
12	35 psi A or psi G?
13	MR. POLASKI: We'll ask Tom to clarify.
14	PARTICIPANT: G I would hope.
15	MR. QUINTENZE: I am Tom Quintenze,
16	AmerGen. That should be 35 psi G.
17	MEMBER ABDEL-KHALIK: Thank you.
18	MR. OUAOU: The reduction in pressure was
19	approved in a technical specification in 1993. And
20	the reduction resulted in approximately 200 psi and
21	VICE-CHAIRMAN WALLIS: Excuse me. When
22	you do these integrated leak tests, you don't put
23	strain gauges on the drywell?
24	MR. POLASKI: No.
25	VICE-CHAIRMAN WALLIS: You have no idea
	I

(202) 234-4433

	115
1	what the stresses are that you generate from this? It
2	would be sort of interesting.
3	MEMBER SIEBER: You are looking for leaks.
4	MR. POLASKI: It's a test to measure
5	leakage.
6	VICE-CHAIRMAN WALLIS: Yes, I know.
7	MR. POLASKI: You pressurize over time and
8	measure leakage.
9	MR. OUAOU: As a result of the reduction
10	of pressure, we recalculated the required thicknesses,
11	as I will show you, next slides.
12	MR. POLASKI: Slide 42, please.
13	MR. OUAOU: This slide was prepared, I
14	guess anticipating Dr. Wallis' question on the
15	margins, to compare the margin between the 62 psi and
16	the 44 psi. As you can note, there is a lot of
17	margin. The margin increase is significant.
18	And I would also like to note that the
19	2006 analysis we did was based on minimum measured
20	thicknesses and an average measure of thicknesses up
21	to the October 2006 refueling outage.
22	And if you compare the two, there are some
23	differences between what was used in the GE analysis
24	versus what it recorded for 2006 for the cylinder.
25	The original GE analysis, or 1993 analysis, used 619.
1	I contract of the second se

(202) 234-4433

	116
1	And what we used for 2006 is 604 mls thickness.
2	Next slide, please.
3	MEMBER SHACK: Just to clarify, so you
4	take the minimum average thickness you measure over
5	your six-by-six grids and you assume that is uniform
6	over the whole shell
7	MR. OUAOU: Exactly.
8	MEMBER SHACK: or that region of the
9	shell?
10	MR. OUAOU: The region, right.
11	The next slide, we talked earlier about
12	that summarizes the two required thicknesses: local
13	thickness and the general thickness and how they are
14	calculated.
15	The minimum required general thickness for
16	44 psi was calculated based on the previous analysis
17	that Dr. Mehta described adjusted for reduction in
18	pressure, from 62 to 44.
19	Minimum required thickness is based on the
20	ASME code provisions, which allow an increase of one
21	and a half times the allowable stress for local
22	membrane areas. And, as indicated in the bullet
23	there, the area that the minimum local thickness is
24	applied to is less than two-and-a-half-inch diameter.
25	And it also has other provisions in the code that
	1

(202) 234-4433

	117
1	provide you additional guidance.
2	What happens if you have more than one in
3	a particular area, two inches closer? And how do you
4	get them forced and so on? And we do use those
5	provisions to do the evaluation on a day-by-day basis.
6	Next slide, please. Forty-four. This
7	slide summarizes the various thicknesses that you use
8	as acceptance criteria. The first column, that's the
9	original nominal design thickness, second column is
10	the minimum measured general thickness 2000 through
11	2006. The third column is the minimum required
12	general thickness for the pressure for the membrane
13	stresses 452.
14	I would like to point out that in the sand
15	bed region, relatively required thickness is buckling.
16	And that's 47.36 mls. On the 479 is required for
17	pressure really does not enter into the picture
18	because the pressure
19	VICE-CHAIRMAN WALLIS: These figures are
20	based on the ASME allowable loads. They're not based
21	on a yield stress. So there's a big factor of safety
22	in here presumably.
23	MR. OUAOU: There is a factor of safety,
24	2 and 1.67
25	VICE-CHAIRMAN WALLIS: The actual
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	118
1	thickness before anything yields is considerably less
2	than we show here presumably.
3	MR. OUAOU: The last column is the minimum
4	required thickness.
5	VICE-CHAIRMAN WALLIS: By ASME, right.
6	MR. OUAOU: By ASME. Slide 45, please.
7	This slide summarizes the analysis that I just
8	described to you. The drywell shell, thin drywell
9	shell, was analyzed in accordance with ASME and the
10	requirements.
11	The stress limits are in accordance with
12	the code considering all load-to-load combinations.
13	To begin the margin, what we pursued, the change in
14	design basis was approved to reduce pressure from 44
15	psi to 62 psi.
16	That resulted in considerable margin that
17	I shared with you in the last slide. And those as a
18	result of you know, following the approval of the
19	reduction of pressure, we calculated the requirement
20	of thicknesses which will be used to monitor against
21	going forward.
22	MR. POLASKI: Thank you, Ahmed.
23	That completes our presentation on the
24	thickness that was performed on the drywell shell
25	thickness.

(202) 234-4433

	119
1	CHAIRMAN MAYNARD: I think before we go to
2	the next segment, we're at the point in the agenda for
3	a break. So we'll take a 15-minute break here and
4	then come back. We'll come back at five till.
5	(Whereupon, the foregoing matter went off
6	the record at 10:39 a.m. and went back on
7	the record at 10:57 a.m.)
8	CHAIRMAN MAYNARD: I would like to restart
9	the meeting here. So we'll turn it back over to you
10	for the next segment in the presentation.
11	MR. POLASKI: Thank you, Dr. Maynard.
12	The next part of our presentation, we've
13	got corrosion in the sand bed region. As I discussed
14	previously, the sand bed region is that part of the
15	drywell where corrosion is reduced to shell thickness
16	resulting in the smallest margin to the code-allowable
17	thickness.
18	As you heard in Dr. Mehta's and Mr.
19	Ouaou's presentation on the drywell thickness
20	analysis, AmerGen has established the thickness needed
21	for the drywell to meet the ASME code design thickness
22	with the safety factors required by the code.
23	This section of the presentation will
24	present information on the history of the corrosion
25	with drywell shell in the sand bed region, including
	1

(202) 234-4433

	120
1	corrective actions that have been taken in the current
2	condition of the drywell shell in the sand bed region.
3	We will provide information on the coding
4	that was applied to the exterior surface of the
5	drywell shell in the sand bed region. We also provide
6	information on the statistical analysis performed and
7	the UT thickness measurements that are made to
8	determine the thickness of the drywell shell.
9	Finally, we will provide the results of
10	inspections performed during the recent refueling
11	outage in October 2006. We believe that this
12	information will support AmerGen's position that the
13	Oyster Creek drywell shell meets its ASME code design
14	thickness and that AmerGen has the aging management
15	programs in place to ensure that the drywell shell
16	will continue to meet its design requirements.
17	We would now like to introduce Mr. John
18	O'Rourke, who will lead the presentation on the sand
19	bed region. Mr. O'Rourke holds both Bachelor's and
20	Master's degrees in mechanical engineering from Drexel
21	University. He is a registered professional engineer.
22	Prior to joining the Oyster Creek license
23	renewal project, Mr. O'Rourke was the Assistant
24	Engineering Director at Oyster Creek. He previously
25	held various engineering and management positions in
I	1

(202) 234-4433

(202) 234-4433

	121
1	Exelon's Nuclear Engineering Department. And he has
2	over 30 years' experience in nuclear power.
3	Mr. O'Rourke?
4	MR. O'ROURKE: Thanks, Fred.
5	C. DRYWELL SAND BED REGION
6	MR. O'ROURKE: This part of the
7	presentation will discuss the sand bed region and will
8	support the following conclusions. First, corrosion
9	on the outside of the drywell shell in the sand bed
10	region has been arrested.
11	Fred had previously discussed the cause of
12	the corrosion and the corrective actions taken. And
13	we will shortly show you the ultrasonic measurement
14	data and the train graphs that support this
15	conclusion.
16	Our second conclusion is that the coating
17	shows no degradation. And we have shown you one
18	photo. We'll show you some additional photos of the
19	coated shell to support this conclusion.
20	Thirdly, there is sufficient margin to the
21	minimum thickness requirements. Along with the
22	ultrasonic measurement data we will present the
23	available margins with the minimum margin being 64
24	mls.
25	After the corrosion problem was

(202) 234-4433

discovered, over 500 ultrasonic measurements were 2 taken from inside the drywell. Three hundred sixty degrees around the drywell had elevation 11-foot-3, 3 4 which is within the sand bed region on the outside and just above the floor and curb on the inside of the 6 drywell.

7 When thin locations were identified, 8 ultrasonic measurements were taken to locate the thinnest locations. We then did grid measurements at 9 the thinnest locations and selected 19 locations for 10 continued corrosion monitoring, with at least one of 11 12 those grids being in each of the 10 bays.

What is shown now is a plan view of the 13 14 drywell showing the locations of the 19 monitored 15 points shown as magenta squares. Also, note the trenches in bays 5 and 7 that I will later discuss in 16 17 a presentation. However, these were trenches that 18 were excavated in 1986 as part of the corrosion 19 investigation.

20 The next slide shows an elevation view 21 showing the typical qrid locations where the 22 ultrasonic measurements were taken from inside at 23 elevation 11-foot-3. This is the graphical response to Dr. Shack's question earlier about where we took 24 25 the measurements.

> **NEAL R. GROSS** COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

5

	123
1	The next slide, 51, this is a detailed
2	view of the bay 5 trench excavation. And it also
3	shows the additional excavation that we did in the
4	outage.
5	VICE-CHAIRMAN WALLIS: Can we go back to
6	the picture you just showed with the magentas and all
7	of that? You have taken these measurements under the
8	vent pipe because presumably the curve prevents you
9	from going in the other area.
10	MR. O'ROURKE: That is correct.
11	VICE-CHAIRMAN WALLIS: So we don't know
12	what is happening in the lowest region between the
13	vent pipes
14	MR. O'ROURKE: Only in the trenches. And
15	we'll
16	VICE-CHAIRMAN WALLIS: or didn't you
17	measure from the other side in that region?
18	MR. O'ROURKE: At this point, when we were
19	taking these measurements, the sand was still in the
20	sand bed region.
21	VICE-CHAIRMAN WALLIS: Okay. At this
22	point.
23	MR. O'ROURKE: Yes, yes.
24	VICE-CHAIRMAN WALLIS: But later on you
25	got measurements in the area between the vent pipes?
1	

(202) 234-4433

	124
1	MR. O'ROURKE: Yes, from the external.
2	VICE-CHAIRMAN WALLIS: The outside?
3	MR. O'ROURKE: That's correct. Back to
4	slide 51, showing the details of the excavation in bay
5	5; and slide 52, which shows the excavation in bay 17.
6	VICE-CHAIRMAN WALLIS: Do you see the ones
7	that later had water in them, these trenches?
8	MR. O'ROURKE: Yes. As I previously
9	noted, trenches in bays 5 and 17 were excavated in
10	1986 to determine the corrosion in the sand bed region
11	at elevation below the drywell interior floor. Bays
12	5 and 17 were selected because ultrasonic measurements
13	indicated that these bays had the least and the most
14	corrosion, respectively.
15	The trenches extend to about the elevation
16	of the bottom of the sand bed, as I showed in the
17	previous two slides. Ultrasonic measurements were
18	taken in the trenches, confirmed that the corrosion
19	below elevation 11-foot-3 was bounded by the
20	monitoring at elevation 11-foot-3. And in the next
21	slide, we'll show you the ultrasonic measurement data.
22	This slide summarizes the measurements
23	taken during the 2006 outage. And, as you can see,
24	the bay 17 trench data on the right is bounded by the
25	monitoring locations, particularly 17A, 17D, and the
	1

(202) 234-4433

	125
1	two to the right of those. You see that the 17A top
2	shows considerably more thickness. This is indicative
3	of the air-sand interface that we had shown on a
4	previous photograph.
5	Bay 5 did not exhibit as much wall loss.
6	The trench numbers represent some corrosion that
7	occurred prior to the coating of the external shell
8	and the refinishing of the floor in the sand bed
9	region. And ongoing corrosion is bounded by the
10	monitoring at elevation 11-foot-3.
11	Slide 55, to summarize the corrective
12	actions for the sand bed region, we removed the sand.
13	We cleaned the shell. We took ultrasonic measurements
14	externally. We coated the shell. And then we
15	performed ultrasonic measurements internally as the
16	baseline for future monitoring.
17	I would now like to show you a couple of
18	photographs of the condition of the drywell shell
19	after the sand removal. This photograph, which we had
20	shown earlier, indicates the condition of the shell
21	following sand removal and prior to cleaning of the
22	shell.
23	VICE-CHAIRMAN WALLIS: It looks to me as
24	if some of the rust has come off because there's a
25	sort of a cliff there where you see the rust.
	1

(202) 234-4433

	126
1	MR. O'ROURKE: Any of the rust that had
2	fallen off it was part of the
3	VICE-CHAIRMAN WALLIS: Almost fallen off
4	because there is a real layer of rust which suddenly
5	in the bottom right-hand there which
6	MR. POLASKI: I think what you have to
7	remember is this is a picture in the sand bed region
8	after the sand had been removed. So there had been
9	people in there working to remove the sand and clean
10	the
11	VICE-CHAIRMAN WALLIS: And after that,
12	they took some rust away as well.
13	MR. POLASKI: They could have knocked some
14	off and moved some of it because you will note on here
15	where it still shows against the drywell shell down at
16	the bottom, which is where you think it would
17	expect it to be retained the longest before you
18	actually went in to clean it off.
19	MR. O'ROURKE: Moving on to photo 58,
20	another photo of the shell in the sand bed floor prior
21	to the repairs. And you can see in the floor the
22	exposed rebar due to the finished condition of the
23	floor.
24	CHAIRMAN MAYNARD: Now, that was from
25	original construction or was that something that
	I

(202) 234-4433

	127
1	occurred after original construction?
2	MR. O'ROURKE: We believe that is from
3	original construction. Once the sand was in there,
4	there was no other access to that area.
5	MR. POLASKI: And the reports indicate
6	that from when they removed the sand, the floor in
7	some of the bays had been properly finished and were
8	in good condition. Other bays were six to eight
9	inches lower than they should have been, having never
10	been completely constructed.
11	MEMBER ARMIJO: The area where the rebar
12	was exposed, did that happen to be in a bay where
13	there was very little corrosion in the sand bed area
14	or where there was a lot of corrosion in the sand bed
15	area?
16	MR. O'ROURKE: It varied between bays.
17	Some bays showed damage, and some did not.
18	MEMBER ARMIJO: So what I'm trying to get
19	at is, if you saw exposed rebar, it had nothing to do
20	with the corrosion in the sand bed area because there
21	were some areas you know, if you had seen exposed
22	rebar in areas where there was no sand bed corrosion,
23	then you would say clearly that was there before
24	construction and it couldn't have been caused by the
25	water.

(202) 234-4433

	128
1	MR. GALLAGHER: Yes. Pete, do we have
2	that correlation?
3	MR. TAMBURRO: This is Pete Tamburro. It
4	varied. There was no relationship between the severe
5	corrosion on the vessel and the degradation of the
6	floor.
7	MEMBER ARMIJO: Did you see exposed rebar
8	in regions where there was no corrosion of the vessel?
9	MR. TAMBURRO: Yes.
10	VICE-CHAIRMAN WALLIS: What are we looking
11	at on the right of this picture here? It's
12	corrugated.
13	MR. TAMBURRO: That's the rebar.
14	VICE-CHAIRMAN WALLIS: On the right-hand
15	side is rebar?
16	MEMBER SIEBER: It's rebar.
17	MR. GALLAGHER: That's the frame. Ahmed,
18	please describe the frame.
19	MR. OUAOU: Ahmed Ouaou with AmerGen. On
20	the right-hand side, what we have is a conduit through
21	which rebar is the main reinforcement for structure
22	VICE-CHAIRMAN WALLIS: So we are looking
23	at, those ribs are rebar on the right-hand side?
24	MR. OUAOU: They're rebar. That's
25	correct. Yes.

(202) 234-4433

129 1 MEMBER SIEBER: What's the general scale 2 of this picture? Is that like six inches from the --MR. GALLAGHER: Yes. These pictures are 3 4 really hard to get perspective on, but, as we said, 5 the sand bed region was 15 inches wide, right? But there are a lot of optical illusions and things like 6 7 that --8 MEMBER SIEBER: Right. 9 MR. GALLAGHER: -- in these because the 10 shell curves, you know. That's about 15 inches, 11 MEMBER SIEBER: the dark area there. 12 MR. GALLAGHER: From left to right would 13 14 be about 15. 15 MEMBER SIEBER: Okay. Thanks. MEMBER ABDEL-KHALIK: Was the rebar itself 16 significantly corroded? 17 18 MR. POLASKI: Pete, can you address that? 19 TAMBURRO: No, the rebar was not MR. 20 significantly corroded. 21 VICE-CHAIRMAN WALLIS: It looks corroded, 22 though. 23 MR. TAMBURRO: This picture really is 24 tinted poorly. 25 MR. GALLAGHER: Now, for clarity, are you

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

	130
1	talking about the rebar in the floor?
2	MR. TAMBURRO: Yes.
3	VICE-CHAIRMAN WALLIS: The rebar on the
4	side looks really
5	MR. GALLAGHER: Now, there are two
б	different things here. The side if I can answer that
7	first, the side, those, the rebar is encased in pipe.
8	Okay. So you're
9	VICE-CHAIRMAN WALLIS: Actually, the
10	conduit, it's the conduit we see.
11	MR. GALLAGHER: You're looking at the
12	pipe. The rebar
13	VICE-CHAIRMAN WALLIS: The conduit has
14	disappeared in places.
15	MR. GALLAGHER: The rebar in the floor
16	well, no. There are individual pipes there, Dr.
17	Wallis, so that it looks like a ribbed configuration.
18	But there are individual pipes. The rebar in the
19	floor is not load-bearing structural rebar. So, you
20	know, it is not a significant
21	VICE-CHAIRMAN WALLIS: But if I look at
22	the pipes, the fifth one alone, it looks as if it's
23	disappeared. It looks very, very corroded in my
24	picture here.
25	MR. GALLAGHER: The fifth one?
1	

(202) 234-4433

	131
1	VICE-CHAIRMAN WALLIS: The fifth one in,
2	yes. You see there's an edge to it. The bottom of it
3	seems to have disappeared.
4	MR. GALLAGHER: I don't think we can
5	comment on that particular one at this point.
б	CHAIRMAN MAYNARD: Now, is that rebar or
7	is that actually like fidgeting cables that run
8	through those conduit?
9	MR. OUAOU: It is rebar. It's almost
10	treated like you suggested, with like a tendon, but
11	what really happened is that the main concrete was
12	much to provide the area. And, as a result, rebar was
13	exposed for the reason that it was encased in these
14	conduits that we're looking at, but it's actually
15	grouted inside. So if the conduit corrodes, the rebar
16	function is not going to be impacted.
17	MR. O'ROURKE: And, just to summarize,
18	this is the condition of the floor after the removal
19	of the sand. So we believe that these were unfinished
20	and not as a result of
21	VICE-CHAIRMAN WALLIS: Did the NRC go into
22	this space?
23	CHAIRMAN MAYNARD: It is my understanding
24	that during the inspection in 2006, an NRC inspector
25	did go into these areas.
	1

(202) 234-4433

	132
1	MR. ASHLEY: Yes, sir. He's here today.
2	VICE-CHAIRMAN WALLIS: Did he look at the
3	rebar and the conduit? And was it as corroded as it
4	appears to be here?
5	CHAIRMAN MAYNARD: Tim O'Hara?
6	MR. O'HARA: Good morning. My name is Tim
7	O'Hara from Region I. I was on site during the entire
8	inspection. I entered two of the sand bed bays, which
9	allowed me to look at approximately four total bays.
10	You can look to the side and see them. I
11	also reviewed all of the visual inspection records.
12	And the licensee did document all the conditions they
13	found in there, including the condition of the sand
14	bed floor and so forth.
15	VICE-CHAIRMAN WALLIS: And the rebar?
16	MR. O'HARA: And the rebar, yes.
17	VICE-CHAIRMAN WALLIS: And did you see the
18	extent of the corrosion of the rebar?
19	MR. O'HARA: I don't think it was
20	extensive.
21	VICE-CHAIRMAN WALLIS: The extent of it?
22	Because in this picture, it just looks
23	MR. O'HARA: That wasn't the intent of the
24	inspection.
25	VICE-CHAIRMAN WALLIS: Yes.
	I

(202) 234-4433

	133
1	MR. O'HARA: We were looking at the
2	coating on the drywell, but the general condition was
3	looked at and noted. Any conditions that the licensee
4	thought were not correct were put in their corrective
5	action process and analyzed.
6	MR. GALLAGHER: And, remember, this
7	picture is from 1992, Dr. Wallis.
8	MEMBER SHACK: I mean, I thought these
9	floors were finished up to make them smooth, to make
10	sure that you can drain the water. So, I mean, it
11	presumably doesn't look like this anymore.
12	MR. GALLAGHER: Yes. These pictures are
13	from 1992. That's correct.
14	MR. POLASKI: As we go on to the next
15	several slides, we will show you what it looks like
16	today or what it looked like in '92 after the
17	MR. O'ROURKE: And slide 59 leads us into
18	those photographs. We'll show you the condition of
19	the drywell shell as repairs were in progress.
20	Slide 60 shows the photograph of the shell
21	after cleaning and the corrosion products removed. It
22	also shows the sand bed floor after the coating was
23	applied. That's a partial answer to Dr. Shack's
24	question.
25	The next photograph shows
l	I

(202) 234-4433

	134
1	VICE-CHAIRMAN WALLIS: What's that thing
2	in the background? It looks like a sheet of plastic
3	or something. What is that?
4	MR. POLASKI: Yes. That very well could
5	be plastic. You remember these pictures were taken
6	during the actual application, repairs still in
7	launch. So you will see plastic in that area.
8	VICE-CHAIRMAN WALLIS: Well, the sand bed
9	floor needed quite a bit of repair it looks like.
10	MR. O'ROURKE: Slide 61 shows the shell as
11	it's being coated with the primer coat and also again
12	a view of the sand bed floor.
13	Slide 62 shows the shell after the epoxy
14	coating was applied. It also shows the caulk seal
15	that was applied to the interface between the external
16	shell and the sand bed floor.
17	And I will note that there are some
18	additional photos in your reference books.
19	MEMBER ARMIJO: Was that caulk sealing
20	kind of pressurized to kind of get it into the gap or
21	was it just kind of surface, like you do with a
22	bathtub or something?
23	MR. O'ROURKE: Pete, do you have an answer
24	to that question?
25	MR. TAMBURRO: The caulk ceiling was a
	1

(202) 234-4433

	135
1	fairly viscous epoxy caulking. And it was forced into
2	that gap with a trowel and pushed in there.
3	MR. GALLAGHER: Thanks, Pete.
4	VICE-CHAIRMAN WALLIS: So if there's no
5	water there, it doesn't matter, does it?
6	MR. O'ROURKE: That's correct.
7	I'm looking at slide 63.
8	VICE-CHAIRMAN WALLIS: How about the
9	draining of the sand bed floor? It presumably has to
10	run around circumferentially to find a drain. Did you
11	worry about leveling it off or putting a slope on it
12	or it slopes to the drain or what? How did you do
13	that?
14	MR. O'ROURKE: That is correct. The
15	directions were to slope. When the floors were
16	finished, the direction was to slope it away from the
17	drywell and toward the drain.
18	VICE-CHAIRMAN WALLIS: All right.
19	MR. O'ROURKE: And remember Fred's earlier
20	discussion that there are five sand bed drains,
21	VICE-CHAIRMAN WALLIS: Right.
22	MR. O'ROURKE: as opposed to the one on
23	the
24	VICE-CHAIRMAN WALLIS: The one on the top,
25	right.
	1 I I I I I I I I I I I I I I I I I I I

```
(202) 234-4433
```

	136
1	MR. O'ROURKE: the unique trough up
2	above. Continuing with the background and history for
3	the sand bed region, the epoxy coating applied to the
4	external shell was a three-part coating system
5	designed for applications on corroded surfaces.
б	The first coat that I showed in a previous
7	slide in the photograph was a rust-penetrating sealer
8	designed to penetrate rusty surfaces, reinforce the
9	rusty steel substrate, and ensure adhesion of the
10	epoxy coating.
11	Two coats of epoxy coating were then
12	applied. This coating is designed for more severe
13	surfaces than we expect at Oyster Creek, a couple of
14	which are noted on the slide.
15	Prior to application of the coating, it
16	was tested in a mock-up for coating thickness and
17	absence of holidays or pinholes. And we used two
18	coats to minimize any chance of pinholes or holidays.
19	And the coats are of a different color to facilitate
20	future inspections.
21	Fred?
22	MR. POLASKI: Thank you, John.
23	I would now like to you have heard from
24	Mr. O'Rourke about the corrective actions taken to
25	stop the corrosion of the drywell shell in the sand
	I contraction of the second

(202) 234-4433

	137
1	bed region. One of the key aspects of the corrective
2	action was application of the epoxy coating to the
3	exterior surface of the shell.
4	Our next presenter is Mr. Jon Cavallo, who
5	will speak about the coating on the drywell shell.
6	Mr. Cavallo is the Vice President of Corrosion Control
7	Consultants Alliance Incorporated. He's a registered
8	professional engineer in six states and holds a
9	Bachelor's degree from Northeastern University in
10	Boston, Massachusetts.
11	He also is a Certified society of
12	Protective Coatings protective coatings specialist and
13	holds registration as a certified protective coatings
14	engineer from the National Board of Registration for
15	Nuclear Safety-Related Coating Engineers and
16	Specialists.
17	He is active in a number of technical
18	societies, including ASTM, National Association of
19	Corrosion Engineers, National Society of Professional
20	Engineers, and the Society of Protective Coatings.
21	Mr. Cavallo served as the editor of the
22	EPRI report "Guideline on Nuclear Safety-related
23	Coatings Division I," assisted in development of and
24	teaches EPRI code in his training courses. He's also
25	the principal investigator of the EPRI report

(202) 234-4433

	138
1	"Analysis of Pressurized Water Reactor on Qualified
2	Original Equipment Manufacturer Buildings" and since
3	2000 has been a member of the NEI PWR containment sump
4	task force.
5	Mr. Cavallo?
б	MR. CAVALLO: Thanks, Fred. Good morning,
7	gentlemen.
8	I was asked to take an independent look at
9	the approach that Oyster Creek has taken to mitigating
10	the corrosion on the exterior shell of the drywell in
11	the sand bed region.
12	First off, I went back and looked at the
13	background and history from a regulatory standpoint of
14	good guidance that we received to approach this
15	project.
16	The Oyster Creek protective coatings
17	monitoring and maintenance program, aging management
18	is consistent with NUREG-1801, which is a GALL report
19	volume II, appendix XI.S8, which is the appendix
20	devoted to coatings condition assessment. However,
21	you should note that that appendix only covers coating
22	service level I coatings, which is coatings inside of
23	the primary pressure boundary inside the drywell.
24	Oyster Creek in my opinion wisely extended
25	that requirement to the service level II coating,

(202) 234-4433

	139
1	which they applied to the exterior of the drywell
2	using many of the same quality approaches that are
3	used in containment coatings.
4	Next slide, please. The coatings applied
5	to the exterior of the drywell, which we have seen
6	some photographs of in the previous presentation,
7	coating service level II, the evaluation and continued
8	monitoring of those coatings are conducted in
9	accordance with ASME section 11, subsection IWE by
10	qualified VT inspectors. In other words, they are
11	inspected the same way using the same techniques that
12	are used inside the containment, both BWRs and PWRs.
13	The coated areas are examined at a minimum
14	for visual anomalies, which includes flaking,
15	blistering, peeling, discoloration, and other signs of
16	distress. This approach is consistent again with the
17	NUREG-1801 and its attendant ASTM standards.
18	The whole premise of ASME section 11,
19	which is used for examination of the pressure
20	boundaries in PWRs and BWRs, is the degradation of a
21	vessel that's got a coating on it will be indicated by
22	a visual precursor defect in the coating.
23	And, again, the ASME section 11,
24	subsection IWE protocol is to remove that coating and
25	examine the substrate. That way we have a consistent

(202) 234-4433

	140
1	manner to look for any continuing corrosion of the
2	drywell shell on the exterior there, the sand bed
3	region.
4	Now, I wanted to spend a little time
5	discussing how barrier coatings such as the one that
6	John described prevent corrosion of the scale
7	substrates.
8	Basically we have four conditions
9	necessary for metallic corrosion: an anode; a
10	cathode; an electrical conductor; and some type of an
11	electrolyte, which is a liquid that conducts
12	electricity.
13	We as coatings engineers can only do one
14	thing. We can't control the anodes. We can't control
15	the cathodes. We can't control the electrical
16	conductors because they were already inherently in the
17	steel. So what we do is apply a barrier coating
18	system, which isolates the moisture, the electrolyte,
19	and breaks the corrosion cycle.
20	This is what has been done in the Oyster
21	Creek sand bed region. Repeating what John told you,
22	the Oyster Creek sand bed region coating system is
23	really a three-step process.
24	First off, the surface preparation was
25	done in accordance with SSPS SP2 hand tool cleaning,

(202) 234-4433

Í	141
1	which I think gets back to Dr. Wallis' question about
2	what was done. That removes loose rust, loose mill
3	scale, and loose coating. And loose is defined as
4	determined by moderate pressure with a dull putty
5	knife by code.
6	With that level of surface prep, which was
7	appropriate, they then applied a pre-prime, which is
8	an epoxy, which penetrates into the semi-irregular
9	shape of the substrate, and then applied two coats
10	VICE-CHAIRMAN WALLIS: About that
11	pre-prime, it is a very key thing, isn't it? I mean,
12	if you leave too much dry rust on, then it doesn't
13	really adhere to the steel.
14	MR. CAVALLO: Exactly. I am going to in
15	a little bit talk about how this was controlled as a
16	special process similar to welding.
17	VICE-CHAIRMAN WALLIS: Okay. Okay.
18	MR. CAVALLO: I didn't mean to cut you
19	off, sir.
20	VICE-CHAIRMAN WALLIS: No, no. I just
21	wanted to focus on that particular thing. The
22	pre-prime is an important step in this.
23	MR. CAVALLO: Yes, sir, it is, absolutely.
24	And, remember, our coating systems such as this one
25	are actually designed. I mean, people think anybody
	I

(202) 234-4433

	142
1	can paint. It's not true.
2	So we have selected a system with good
3	history in this type of application. Then we applied
4	two coats of the Devran 184 epoxy, which is a standard
5	epoxy phenolic, which is used a lot for this region,
6	which provides that barrier for moisture.
7	And, finally, we saw pictures of the
8	Devmat 124S caulking, which was applied by troweling
9	into the interface between the concrete floor and the
10	steel substrate, again another moisture barrier.
11	MEMBER ARMIJO: Just to understand, the
12	pre-prime, is it intended? Is it preferred that it be
13	in contact with the metal or is it okay that it's in
14	contact with a surface oxide that is adherent to the
15	metal?
16	MR. CAVALLO: Both, actually. It's
17	designed as an adhesion promoter. It soaks into any
18	crevices in that remaining corrosion. And, remember,
19	this is very tightly adherent corrosion and mill
20	scale.
21	MEMBER ARMIJO: Right.
22	MR. CAVALLO: And also it's an epoxy
23	polyamine. So it does bond to the steel substrate
24	that may be exposed. So you have a combination of
25	both conditions. And it is an adhesion promoter and
	1

(202) 234-4433

	143
1	gives something for the next two coats to stick to.
2	VICE-CHAIRMAN WALLIS: You mean if you
3	have a pit, it just bridges over the pit, does it?
4	MR. CAVALLO: No. It actually soaks in.
5	It's a fairly slow-drying material. And it acts a lot
6	like our old bridge paint did. It's to simulate that.
7	Now, my conclusion is in basically
8	reviewing the approach and the engineering involved is
9	that this coating system is appropriate for the
10	intended service, which is to prevent further
11	corrosion of the steel in the sand bed region drywell
12	shell.
13	Some of the reasons I came to that
14	conclusion are that we have created now a very benign
15	corrosion environment. Before the sand was removed,
16	we actually almost had an emergent condition. We had
17	moisture trapped in there held against the surface by
18	the sand. Now we have a dry
19	CHAIRMAN MAYNARD: I'm sorry. Can you
20	wait just a minute? We're trying to get this muted.
21	We are getting some noise from one of the lines. So
22	if the people on the telephone will be quiet, we'll go
23	ahead and continue with the discussion. Go ahead,
24	Jon.
25	MR. CAVALLO: All right. So, anyways, we

(202) 234-4433
	144
1	have removed all the sand. We removed the water. We
2	have a benign environment, a fairly low radiation dose
3	rate. So I don't worry about any sort of radiation
4	damage. This coating typically good to 1 times 10 9
5	rads or more total lifetime dose. And we're never
6	going to see anything like that.
7	Finally, it's an enclosed space. It's
8	shielded from atmospheric moisture, shielded from the
9	site environment. So we have now a very benign
10	environment.
11	The coating system is compatible with that
12	environment. Back to your question about the adhesion
13	promoter, that adhesion promoter which is your
14	penetrating sealer is designed to adhere to a
15	minimally prepared surface is what we're talking about
16	here, where we're leaving some corrosion product
17	behind. And also the two-coat applied over top of
18	that is used an awful lot in chemical tanks. So our
19	environment is far less severe than that.
20	And, then finally, this coating system can
21	be successfully applied by brush and roller. Because
22	of their very tight environment, we couldn't get into
23	very sophisticated spray equipment, such things like
24	that. So this is appropriate to be applied that way.
25	Now, Oyster Creek also did something which
	1

(202) 234-4433

	145
1	I think is quite noteworthy. They actually create a
2	mock-up of the sand bed region with the drywell shell
3	before they actually applied the coating in service.
4	And they did surface preparation and coasting
5	application using the same mechanics in this mock-up
6	area with the restricted access.
7	This was a proof of principle on the
8	coating system and also was used to train the
9	mechanics who did the surface prep and the coating
10	work. This includes the caulking also.
11	And then, finally, what they did was
12	actually do a holiday test, which was an electrical
13	test, to see whether or not they had pinholes on this
14	mock-up. So this was treated very similar to a
15	special process like we would have for welding. So it
16	was well over and above what you normally see in an
17	outside containment coating's work effort. So there
18	was quite a bit put into that.
19	MEMBER SIEBER: So a holiday as referred
20	to in your previous slide is a pinhole?
21	MR. CAVALLO: Yes, sir. And usually
22	holidays are not visible. They're solvent blistering.
23	Now, I am going with periodic condition
24	assessment maintenance if there is any required. And
25	I am not sure there ever will be any. In my opinion,
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	146
1	the Oyster Creek sand bed region shell coating will
2	continue to perform satisfactorily for the life of the
3	plant, very similar to our other coatings in the world
4	of nuclear reactors.
5	What Oyster Creek is going to do is
6	inspect or they have inspected 100 percent of the sand
7	bed region drywell shell coating during the 2006
8	outage. And they will continue to do this inspection
9	on a periodicity of three bays every other outage with
10	all ten bays inspected every ten years.
11	Now, this ten-year cycle is in accordance
12	with recommendations that industry has published,
13	including the EPRI guideline in protective coatings,
14	where for coating service level II coatings, these
15	coatings outside containment in a benign environment,
16	we recommend a periodicity of inspect them all every
17	ten years due
18	VICE-CHAIRMAN WALLIS: Can I ask, this is
19	presumably a tough ductile type of coating? It's not
20	brittle in any way?
21	MR. CAVALLO: Absolutely not. It's
22	VICE-CHAIRMAN WALLIS: As the steel moves
23	during pressurization and so on, it's not going to
24	crack?
25	MR. CAVALLO: No. Actually, the coatings
l	1

(202) 234-4433

	147
1	condition, if you think of a storage tank, we have
2	something called oil canning, where it actually moves
3	up and down quite a bit. So we've got to get very
4	little movement here. So yes, it is appropriate.
5	MEMBER ARMIJO: So this has been on for 14
6	years already, right, due to 2006 and are we going
7	to talk anymore about the inspection of the coating or
8	is this it?
9	MR. POLASKI: We are going to later
10	MEMBER ARMIJO: In 14 years, have you seen
11	the need to repair it or repaint it or whatever?
12	MR. POLASKI: No. We're going to I'll
13	let Mr. Howie Ray present that. Howie is going to
14	present information on inspection results.
15	MR. RAY: Yes. We've done visual
16	inspections on all ten bays in 2006 by qualified
17	individuals. And the coating was found to be
18	satisfactory. And we do it on a monitoring basis to
19	make sure that we're planning the recoating before
20	we're filled.
21	MEMBER ARMIJO: If you had found some
22	defects, it is repairable?
23	MR. CAVALLO: Yes, sir. Yes, sir. This
24	is a repairable coating.
25	MEMBER SIEBER: Let me ask another
	I

	148
1	question. In your professional opinion, is a ten-year
2	interval adequate for this application in these
3	conditions?
4	MR. CAVALLO: Yes, sir. Based on I
5	edited the document that the ten-year quote comes out
б	of. So that is my professional opinion.
7	MEMBER SIEBER: Okay.
8	MEMBER SHACK: You did see some
9	degradation in the coating on the floor, though,
10	right? Did I read that somewhere?
11	MR. GALLAGHER: No. What you might be
12	thinking about, Dr. Shack, is there was between the
13	floor and the wall, not the containment shell, the
14	back side wall, a gap in a couple of places. And that
15	was repaired
16	MR. POLASKI: Are there any other
17	questions on the coating system?
18	(No response.)
19	MR. POLASKI: Jon, thank you.
20	MR. CAVALLO: You are welcome.
21	MR. POLASKI: The next part of our
22	presentation is going to cover the methods that are
23	used to make UT thickness measurements drywell shell
24	and how this data is analyzed.
25	Presenting this information will be Mr.

(202) 234-4433

	149
1	Pete Tamburro. Mr. Tamburro holds a Bachelor of
2	Science degree in chemical engineering from Clarkson
3	University and a Master's degree in computer science
4	from Dickerson University.
5	He is a professional engineer who holds a
6	professional engineer's license from the State of New
7	Jersey. He has worked in the nuclear industry since
8	1980 and has 25 years experience at Oyster Creek and
9	Three Mile Island. He has worked on the drywell
10	corrosion issue since 1988, mostly dealing with data
11	collection analysis and documentation.
12	Mr. Tamburro?
13	MR. TAMBURRO: Thank you, Fred. I am here
14	to tell you what we did with the 2006 data.
15	This slide 72. First I would like to
16	present some background history. In 1992, the sand
17	was removed and the coating applied. We performed a
18	baseline inspection on the 19 monitor locations.
19	VICE-CHAIRMAN WALLIS: Can you go back
20	over how those locations were selected?
21	MR. TAMBURRO: Yes, sir. In the mid '80s,
22	when we recognized that there was a problem, we did an
23	extensive investigation from the inside and did over
24	500 UT inspections throughout the
25	VICE-CHAIRMAN WALLIS: Five hundred on
	1

(202) 234-4433

	150
1	that side?
2	MR. TAMBURRO: Yes, sir. Those 500
3	identified the thinnest areas. We then characterized
4	those areas and expanded those areas to a six-inch by
5	six-inch area, which we monitor now.
6	VICE-CHAIRMAN WALLIS: And do you monitor
7	it by monitoring all over it or one spot in it or
8	what?
9	MR. TAMBURRO: We monitor it by taking a
10	series of inspections
11	VICE-CHAIRMAN WALLIS: So it's not just
12	one reading?
13	MR. TAMBURRO: No, sir.
14	VICE-CHAIRMAN WALLIS: It's a whole lot of
15	readings at
16	MR. TAMBURRO: It's a lot. It's 49
17	readings.
18	VICE-CHAIRMAN WALLIS: Okay. That helps.
19	MR. TAMBURRO: And I will get into that in
20	
21	VICE-CHAIRMAN WALLIS: Why is it only at
22	one elevation? Why not at several elevations?
23	Because there is an area involved. Why is it all at
24	11-foot, 3 inches?
25	MR. TAMBURRO: The 11-foot, 3-inch area

```
(202) 234-4433
```

	151
1	was inspected because of the limited access due to the
2	concrete curb on the inside.
3	MR. GALLAGHER: Yes, Dr. Wallis
4	VICE-CHAIRMAN WALLIS: It's the lowest you
5	could get to. It's the lowest you could get to, isn't
6	it? Yes. It's the lowest you could get to in there.
7	But on the outside, you can get lower than that.
8	MR. TAMBURRO: Yes, sir. And we have
9	inspected externally lower than 11-foot, 3.
10	MR. O'ROURKE: And this is a graphical
11	representation we showed earlier.
12	VICE-CHAIRMAN WALLIS: Outside you can get
13	lower than that because
14	MR. GALLAGHER: Yes. Dr. Wallis?
15	VICE-CHAIRMAN WALLIS: generally the
16	corrosion might be worse lower down.
17	MR. O'ROURKE: That's correct, on the
18	outside.
19	VICE-CHAIRMAN WALLIS: On the outside.
20	And so you can get lower than that outside?
21	MR. TAMBURRO: Yes, sir.
22	MR. GALLAGHER: Yes. And, Dr. Wallis,
23	just
24	VICE-CHAIRMAN WALLIS: Just tell us about
25	that.
	1

(202) 234-4433

	152
1	MR. GALLAGHER: Yes. But visually if you
2	just want to look at it real quickly, on page 101
3	now, it's hard to see when it flips up here, but we
4	also included that chart in your handout book, the
5	last page of your reference material. There's an 11
6	by 17 depiction of this.
7	VICE-CHAIRMAN WALLIS: Whereabouts is
8	that?
9	MR. GALLAGHER: And we're going to go
10	through all of this.
11	VICE-CHAIRMAN WALLIS: You are going to go
12	through that later on?
13	MR. GALLAGHER: Yes. We're going to go
14	through all of this. But what this is is this is a
15	graphical representation of all the data in the sand
16	bed region in 2006. And you can see the coverage is
17	pretty wide. This includes the grids, the trenches,
18	and the individual points.
19	VICE-CHAIRMAN WALLIS: Okay.
20	MR. GALLAGHER: And we are going to
21	explain each one of these as we go through this
22	section right here.
23	VICE-CHAIRMAN WALLIS: Okay. Thank you.
24	MR. GALLAGHER: That summarizes that
25	VICE-CHAIRMAN WALLIS: I don't want to

(202) 234-4433

	153
1	hold you up. So we'll get to that, right?
2	MR. TAMBURRO: Okay. On slide 72, in
3	1992, we found that our thinnest average reading over
4	a 6-by-6-inch area was 800 mls. And our thinnest
5	individual reading, which was measured from the
6	outside, was 618 mls. Then when you compared them to
7	the appropriate acceptance criteria, they both met the
8	acceptance criteria.
9	Moving on to
10	VICE-CHAIRMAN WALLIS: That's over half an
11	inch less than it started out at or about a half an
12	inch less?
13	MR. TAMBURRO: Yes, sir, at the thinnest
14	areas. Yes, sir.
15	Slide 73. In 1994, we repeated the
16	inspections on the 19 grids. And in 1996, these
17	inspections showed no statistical changes in the means
18	and the thinnest area and the thinnest individual
19	points. This became the basis for the conclusion that
20	the corrosion had been arrested.
21	MEMBER ARMIJO: I guess I looked at a
22	different set of data. It looked to me like all your
23	1996 measurements were much higher than the previous
24	measurements.
25	MR. TAMBURRO: Yes, sir. There is an
	1

(202) 234-4433

	154
1	anomaly with the 1996 data in which they are higher.
2	Yes, sir.
3	MEMBER SIEBER: What do you think causes
4	that?
5	MEMBER ARMIJO: Yes. Right.
6	MR. TAMBURRO: We've taken some analysis.
7	And we have had our NDE folks look at what some of the
8	potential reasons were. They have indicated that a
9	couple of potential reasons were that the contractors
10	that did the '96 inspections did not remove the grease
11	that was on the locations that could attribute to it.
12	There are other factors, such as not
13	putting the machine, the UT machine, in the proper
14	setting. However, we cannot positively confirm why we
15	had this
16	MEMBER SIEBER: It's an epistemic error?
17	MR. TAMBURRO: Yes, sir.
18	MEMBER SIEBER: And it looks like a bad
19	calibration, wrong block, or perhaps a miscalibration?
20	MR. TAMBURRO: Yes, sir.
21	MEMBER SIEBER: But it's systematic across
22	all of the readings?
23	MR. TAMBURRO: However, the 2006 data has
24	come in line and is consistent with the 1992 and 1994
25	values.

(202) 234-4433

155 1 MEMBER SIEBER: Well, the '94 is the ones 2 that are off, right? 3 MR. TAMBURRO: No, sir. The '96 --4 MEMBER SIEBER: '96. MR. TAMBURRO: -- are the ones that are 5 off. 6 7 MEMBER SIEBER: Okay. Well, that's a 8 problem, I guess, as I see it, because somebody around the 1996 time frame should have caught that --9 10 MR. TAMBURRO: Right. MEMBER SIEBER: -- to figure out why that 11 12 was that way --PARTICIPANT: At the time, during the 13 14 inspection. 15 MEMBER SIEBER: -- and corrected it because if you do it again, that could give you --16 17 MR. TAMBURRO: Yes, sir. 18 MEMBER SIEBER: -- bad data. And you're 19 relying on that trend because of the smaller margin 20 that you have. You're relying on that trend to 21 predict when you need to do the next inspection or 22 whether you can run at all. 23 TAMBURRO: Yes, sir. And we've MR. 24 learned from that. Our new criteria requirements are 25 very clear and have eliminated what we think are the

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	156
1	potential causes of the problem in '96.
2	MEMBER SIEBER: Could you be more specific
3	in telling me what it is you do differently because of
4	that?
5	MR. TAMBURRO: Well, what we do
6	differently at this point is we require that the probe
7	be put in one orientation. Prior to that, there was
8	no requirement. And the inspector could have
9	literally rotated the probe, which would have given us
10	different readings.
11	We also instruct the operator to clean off
12	the grease and ensure that the surface condition of
13	that monitored location is free of the grease. We
14	also require the
15	MEMBER SIEBER: You need the grease in
16	there as a coupling?
17	MR. TAMBURRO: No, sir. No. The grease
18	is put on there between inspections to inspect the
19	surface from corrosion. We removed the grease and
20	then used a coupling as part of the UT process.
21	MEMBER SIEBER: But that is also a great
22	type
23	MR. TAMBURRO: It's more of a water
24	lubricant. It does have some viscous properties to
25	it, but it's not as thick as the grease we use to
1	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	157
1	protect it on the surface.
2	MEMBER SHACK: You are protecting the
3	surface because you haven't put the approximate
4	coating on the
5	MR. TAMBURRO: Yes, sir. It's bare metal,
6	and it's on the inside.
7	MR. GALLAGHER: On the inside.
8	MR. TAMBURRO: And we want to protect the
9	surface.
10	MR. GALLAGHER: Now, one thing on this
11	that I want to point out, the staff also had a concern
12	along your lines, Mr. Sieber, on this. And one of our
13	commitments that we have committed to is if we take
14	the data and the 19 grids and they are outside of our
15	expectations, we notify the NRC within 48 hours and
16	then enter into our corrective action system.
17	CHAIRMAN MAYNARD: That's what I was going
18	to I'm assuming that under your current program you
19	do take a look at your data compared to what you had
20	and look for anomalies before you just move on?
21	MR. GALLAGHER: That's correct.
22	MEMBER SIEBER: Does that cause you to
23	quarantine the inspection area until the NRC has an
24	opportunity to look at what it is you're doing or do
25	you just move on, close up shop, and send a notice in

(202) 234-4433

	158
1	
2	MR. POLASKI: You've got to remember that
3	these locations are inside the drywell. So you'll
4	take these during an outage.
5	MEMBER SIEBER: Right.
6	MR. POLASKI: And we have a requirement if
7	we find an anomaly or some problem with them to notify
8	the NRC within 48 hours for corrective action. We
9	need to get dialogue with the NRC and fulfill the
10	corrective action process, investigate the
11	MEMBER SIEBER: And right now there is no
12	quarantine requirement?
13	MR. GALLAGHER: Well, we would do an
14	investigation as part of our corrective actin. So
15	those types of things would be done to make sure we
16	understand the issue and can take additional
17	information or whatever.
18	But the key point was we would notify the
19	NRC. And we would go through our corrective action
20	process. And we would finish that before we come up
21	from that outage.
22	MEMBER SIEBER: Let me ask a couple of
23	other detailed questions. Do you use the same
24	instrument each time, probably not transducer?
25	MR. TAMBURRO: No, we do not. We use

(202) 234-4433

	159
1	qualified instrumentation to our procedures. We
2	calibrate them to cow blocks what are appropriate for
3	the thickness.
4	MR. GALLAGHER: Are you talking
5	MEMBER SIEBER: The reason for my question
6	is the footprint of the transducer is usually a
7	rectangle. And you're trying to measure something
8	that's spherical. And so you have a gap between the
9	top of the transducer and the material that you're
10	measuring due to the fact that you have a flat surface
11	against a spherical surface. And the footprint
12	determines how big that gap is.
13	And so I think you can calibrate that to
14	see both the inside wall and the outside wall. Is
15	that the way that it is done or can an error be made
16	where you are actually looking at the surface of the
17	transducer and the outside wall?
18	MR. TAMBURRO: The current technology
19	we're using measures the second bounce in the steel.
20	MEMBER SIEBER: Okay.
21	MR. TAMBURRO: And it eliminates any gaps
22	between the probe.
23	MEMBER SIEBER: Okay. So you're going
24	from the far wall back and taking both pulses?
25	MR. TAMBURRO: We're going from the far
ļ	1

(202) 234-4433

	160
1	wall back, back to the far wall, and measuring that
2	reflection.
3	MEMBER SIEBER: Okay. And that appears on
4	the scope?
5	MR. TAMBURRO: Yes, sir. And our ND
6	technician can give you more details.
7	MR. McALLISTER: Good morning. Marty
8	McAllister with AmerGen. The two different
9	techniques, one that is used on the outside surface,
10	where it's coated, is the echo-to-echo technique that
11	Pete described, where we're actually timing the second
12	round trip to measure the thickness.
13	For the readings that are taken on the
14	inside, that's the traditional technique, no
15	echo-to-echo, no curvature effects. Does that answer
16	your question?
17	MEMBER SIEBER: Yes.
18	VICE-CHAIRMAN WALLIS: You have also got
19	some indication of the condition of the coating, don't
20	you? It echoes from the coating into
21	MR. McALLISTER: If we are able to punch
22	the ultrasound through the coating, then yes, the
23	coating is tightly adhered from the exterior.
24	VICE-CHAIRMAN WALLIS: But you don't
25	measure anything.

	161
1	MEMBER SIEBER: You can
2	CHAIRMAN MAYNARD: Jack, you need to get
3	to a microphone.
4	MEMBER SIEBER: You can differentiate
5	between the coating and material.
6	MR. McALLISTER: That's correct. If we
7	did a traditional technique from the exterior, it
8	would include that coating thickness.
9	MEMBER SIEBER: Right.
10	MR. TAMBURRO: Okay. Continuing on, in
11	2006, we repeated the excuse me. The 19
12	inspections in '94 and '96 also became the basis for
13	an NRC SER that concluded that your key inspections
14	were no longer required and the coating inspections
15	were sufficient.
16	In 2006, we again repeated the inspections
17	of the 19 grids. The data was consistent with the
18	'94-'92 data and leads to the conclusion that the
19	corrosion has been arrested. When you
20	VICE-CHAIRMAN WALLIS: I would think you
21	would want to do some UT measurements anyway
22	MR. TAMBURRO: And we did in 2006.
23	VICE-CHAIRMAN WALLIS: or just say,
24	"We'll never do any again."
25	MR. TAMBURRO: No, sir.
	I

(202) 234-4433

	162
1	VICE-CHAIRMAN WALLIS: Just
2	defense-in-depth. And every two years, you do some UT
3	measurements.
4	MR. TAMBURRO: And in 2006, we did.
5	Moving on to slide 74, I would like to go over the
6	methodology in which we do these 19 inspections. Each
7	of the inspections are marked on the inside of the
8	drywell with a permanent marker.
9	We use a stainless steel grid, which has
10	mark slits on the grid, which line up with the
11	permanent marker on the drywell. We did insert a UT
12	probe through these holes. The diameter of these
13	holes is such that the probe fits snugly inside the
14	holes.
15	We take 49 readings at the critical
16	locations. Again, the probe is placed through the
17	holes. This is how we can ensure that we get to the
18	same location every inspection.
19	VICE-CHAIRMAN WALLIS: Is this where the
20	coverage I think comes in? I mean, that's a flat play
21	on a round
22	MR. TAMBURRO: If you'll notice, this has
23	a little bit of a curve to it.
24	VICE-CHAIRMAN WALLIS: I would think so.
25	I would think so, yes.
l	

	163
1	MR. TAMBURRO: The protective grease is
2	removed. We do our inspections, and then we reapply
3	the protective grease.
4	Slide 75 is a little schematic of this
5	grid. The data is then collected. We calculate the
6	mean of the data, the standard error of the mean. And
7	we look at the thinnest points.
8	VICE-CHAIRMAN WALLIS: Does it vary much
9	over this small area?
10	MR. TAMBURRO: Yes, it does.
11	VICE-CHAIRMAN WALLIS: It does?
12	MR. TAMBURRO: Yes. And, as you have seen
13	in the pictures, the back side is very rough.
14	MEMBER SIEBER: Yes. It looked pretty
15	lumpy.
16	MR. TAMBURRO: On to slide 76. And that
17	leads into my next slide. There is a fair amount of
18	uncertainty on the means and variance. And that's due
19	to the roughness.
20	If you go from one point to another, you
21	will see a fair amount of variation. That's why you
22	see some fairly large standard errors on these means.
23	That's the major contributor to the large standard
24	errors.
25	On to slide 77. The data, the means, and

(202) 234-4433

	164
1	the finished points of each grid are trended over
2	time. So this
3	MEMBER ARMIJO: I guess I wouldn't call
4	those errors. I think that's just variability.
5	MR. TAMBURRO: Variability, yes, sir.
6	MEMBER ARMIJO: In what you measure it?
7	MR. TAMBURRO: It's not experimental
8	error.
9	MEMBER ARMIJO: That same transducer on a
10	flat place, measure it over and over again. You would
11	get much
12	MR. TAMBURRO: Yes, sir. I'm not much of
13	a statistician. So I have been confusing error with
14	variance.
15	MEMBER ARMIJO: Okay.
16	VICE-CHAIRMAN WALLIS: It's surprising
17	that a mean could increase with time.
18	MR. TAMBURRO: The mean within that
19	standard error
20	VICE-CHAIRMAN WALLIS: That's not mood.
21	That's
22	MR. TAMBURRO: Within that variance.
23	Excuse me. You see fluctuations in the readings.
24	It's not a physical characteristic that the steel
25	grows. It's just that the numbers will change over
	1

(202) 234-4433

	165
1	time within a variance.
2	MEMBER ARMIJO: That variance, the
3	experimental variance, is very small compared to the
4	variability of the material you are measuring.
5	MR. TAMBURRO: Due to the roughness on the
6	back side.
7	MEMBER ARMIJO: Yes, right.
8	MR. POLASKI: And just to maybe explain a
9	little bit more, if you had shown me this and some
10	data and you hold this up and you're a technician,
11	you're in there, you put this in exactly the same
12	place, well, it's visually lined up.
13	If you walk just a little bit, 1/32 of an
14	inch, each of these readings will be different because
15	it's so rough on the other side. That's why you get
16	this difference in the mean because if you shifted one
17	way, some of them go up, some go down. It can affect
18	the average a little bit. It could be one way. It
19	could be the other.
20	MR. TAMBURRO: And then each point is
21	different.
22	VICE-CHAIRMAN WALLIS: What does an
23	ultrasonic measurement mean if there is a roughness
24	which is grainier than the size of the instrument?
25	MR. TAMBURRO: What we do is then we take
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	166
1	49 points and analyze it for
2	VICE-CHAIRMAN WALLIS: Don't you get a
3	fuzzy reflection or something or what do you get when
4	you have a waviness which is finer than the size of
5	the instrument?
6	MR. TAMBURRO: I'm going to ask Marty
7	McAllister to answer the question.
8	MR. MCALLISTER: Marty McAllister with
9	AmerGen. Yes. You will get less of a reflection back
10	from a rough surface. The machines that we use, the
11	data loggers, they're designed to trip at a certain
12	gate level, certain amount of sound that is being
13	echoed back.
14	VICE-CHAIRMAN WALLIS: Does it tend to
15	reflect from the troughs or the peaks if you get a
16	wiggly surface?
17	MR. MCALLISTER: It will trip off the
18	thinnest.
19	MEMBER SIEBER: It's a visual, right?
20	MR. MCALLISTER: That's correct.
21	VICE-CHAIRMAN WALLIS: It's surprising if
22	you have done all of this prep and you have cleaned it
23	and you almost you didn't grind it, but you
24	MEMBER ARMIJO: The diameter of the signal
25	that is going out, you could pick the size of your
	1

(202) 234-4433

	167
1	probe, right? So you can have a very tiny little
2	signal going to the sound.
3	MR. MCALLISTER: The probes are a pulse
4	echo. Half the probe is sending sound. The other
5	half is receiving it. They're kind of focused so it
6	will create more of a line of sound.
7	VICE-CHAIRMAN WALLIS: What's the diameter
8	of the signal? What's the diameter of the measuring
9	beam?
10	MR. McALLISTER: It would be a line that
11	would be the width of the transducer.
12	VICE-CHAIRMAN WALLIS: Which is?
13	MR. TAMBURRO: At the hole size.
14	VICE-CHAIRMAN WALLIS: Hole size.
15	MR. GALLAGHER: And, Dr. Wallis, I think
16	you got confused on the exterior and interior.
17	VICE-CHAIRMAN WALLIS: The exterior is
18	rough, right?
19	MR. GALLAGHER: We talked about the
20	VICE-CHAIRMAN WALLIS: You're measuring
21	from the inside?
22	MR. GALLAGHER: On the inside. When we
23	talked about the dish where we prepared the surface,
24	that's on the outside. And I hope to get to
25	VICE-CHAIRMAN WALLIS: That's right.

(202) 234-4433

	168
1	MEMBER ARMIJO: But literally from this
2	data, you could in principle drop contour maps of what
3	that surface looks like.
4	MR. GALLAGHER: That's correct, yes.
5	MEMBER ARMIJO: But you haven't needed to
6	do that or found trying to do that?
7	MR. TAMBURRO: No. We have data. We have
8	all 49 points.
9	VICE-CHAIRMAN WALLIS: Have you shown us
10	some of these grids of 49 points?
11	MR. GALLAGHER: In the calculations that
12	we submitted
13	VICE-CHAIRMAN WALLIS: We seem to presume,
14	but there isn't that much variability from one point
15	to the next over such a short distance or is there?
16	PARTICIPANT: I think there would be.
17	MR. TAMBURRO: There is a variability.
18	PARTICIPANT: We have a table.
19	VICE-CHAIRMAN WALLIS: You have a table?
20	PARTICIPANT: Yes.
21	VICE-CHAIRMAN WALLIS: From one point to
22	the next, just that short distance?
23	MR. TAMBURRO: Yes, sir.
24	MR. POLASKI: It's one inch.
25	VICE-CHAIRMAN WALLIS: One inch? It
	1

(202) 234-4433

169 1 doesn't vary by half an inch thickness. It varies by 2 3 MEMBER ARMIJO: It's small numbers. 4 VICE-CHAIRMAN WALLIS: Mls. It varies by 5 mls. MR. TAMBURRO: Okay. So moving on to 6 7 slide 77, we trend the data, both the means and the 8 thinness, over time. And the 77 is a schematic of 9 what this -- a representation. The thickness is the y-axis. And the time is the x-axis. 10 On 78, we then take that data. And we 11 12 develop a curve fit of that trend. That curve fit is based on least squares fit. 13 14 VICE-CHAIRMAN WALLIS: But since the 15 corrosion has been arrested in your view, there shouldn't be any. It should just be flat. 16 17 MR. TAMBURRO: Yes, sir. And it is flat. And I'll get into how we look at that in about four 18 slides. 19 20 VICE-CHAIRMAN WALLIS: Okay. 21 MR. TAMBURRO: We then test the curve fit 22 to the data and determine if it meets the curve with 23 95 percent confidence. If it does meet the curve with 24 95 percent confidence, then we use the curve for 25 The next slide shows how we do that projection.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	170
1	projection.
2	VICE-CHAIRMAN WALLIS: Does it usually
3	meet the curve with that confidence, then?
4	MR. TAMBURRO: Prior to
5	MEMBER POWERS: Can you go back to the
6	previous slide?
7	MR. TAMBURRO: Yes, sir. Could you repeat
8	the question, please?
9	MEMBER POWERS: I haven't asked it yet.
10	MR. TAMBURRO: Okay.
11	(Laughter.)
12	MEMBER POWERS: You are looking for a
13	curve with zero slope, is what you're looking for?
14	MR. TAMBURRO: No. At this point I'm
15	looking for a curve with a slope.
16	MEMBER POWERS: Are you doing an
17	CHAIRMAN MAYNARD: Dr. Powers, could you
18	get closer to the microphone?
19	MEMBER POWERS: You are doing an F test,
20	which is a test of variance?
21	MR. TAMBURRO: A test of variance to occur
22	with a slope. Yes, sir. At this point we're looking
23	for a slope.
24	MEMBER POWERS: I'm just not sure. You've
25	got to look at the ratio of the two variances. And I
I	I contraction of the second seco

(202) 234-4433

	171
1	don't know what the second variance is.
2	MR. TAMBURRO: The two variances we are
3	looking at are the ratio between the sum of the
4	squared error and the sum of the residual errors.
5	MEMBER POWERS: Okay. So you're just
6	looking at your inherent error versus your systematic
7	error?
8	MR. TAMBURRO: Yes, sir.
9	MEMBER POWERS: Okay.
10	MR. TAMBURRO: Again, if that curve fits
11	meets the data with 95 percent confidence, then we
12	will perform a projection using that curve fit.
13	Slide 79 provides a schematic of how we do
14	that. We calculate a lower 95 percent confidence
15	interval on that curve fit; again, if that curve fit
16	has satisfied a 95 percent confidence F test.
17	This schematic shows also the upper
18	confidence level, but we don't use that. The
19	intercept between the lower 95 percent confidence
20	intervals and 2029 is how we project our margin.
21	VICE-CHAIRMAN WALLIS: The upper 95
22	percent confidence looks nonphysical somehow.
23	MR. TAMBURRO: Yes, sir. Yes, sir.
24	MEMBER POWERS: So the statistics isn't
25	inherent here. Why 95 percent?

(202) 234-4433

	172
1	MR. TAMBURRO: Ninety-five percent is what
2	we typically have used with analysis and has been
3	generally accepted by the regulation.
4	MEMBER POWERS: Why does he accept 95
5	percent?
6	MR. TAMBURRO: I can't answer the
7	question.
8	MR. GALLAGHER: It is reasonable
9	assurance.
10	MR. TAMBURRO: It is a high confidence
11	level. I am sure on the upper drywell if we used 99
12	
13	MEMBER POWERS: There are multiple ways of
14	looking at it. You can say, "If I did this 20 times,
15	one out of those 20 times, you would violate this," in
16	which case you are dead meat, right?
17	MR. TAMBURRO: We've done sensitivity
18	studies. We have done
19	MR. GALLAGHER: In this one area.
20	MR. TAMBURRO: We've done sensitivity
21	studies on the upper drywell and have used 99 percent
22	confidence. We still meet margin. We still meet 2029
23	with margin.
24	CHAIRMAN MAYNARD: That might be a better
25	question to ask the staff when they're giving their

```
(202) 234-4433
```

	173
1	presentation this afternoon, too.
2	MEMBER SHACK: There is no answer to that
3	question.
4	(Laughter.)
5	CHAIRMAN MAYNARD: I am just trying to
6	move us along, Dana.
7	MR. TAMBURRO: So why did you ask it of
8	me?
9	(Laughter.)
10	MEMBER POWERS: Because I ask the staff
11	and I never get an answer. I thought maybe there was
12	some hope.
13	PARTICIPANT: What if you didn't meet your
14	F test?
15	MR. TAMBURRO: The next set of slides goes
16	into that.
17	MEMBER ARMIJO: Well, if you don't meet
18	the F test, that means that physically something is
19	changing and the data shouldn't be correlated with a
20	straight line.
21	MR. TAMBURRO: If I don't meet the F test,
22	I don't have high confidence that there is a straight
23	curve with a slope. This method worked well for the
24	sand bed prior to 1992.
25	We had rates between 10 and 20 mls per

(202) 234-4433

ĺ	174
1	year. It only took us 4 or 5 inspections to come up
2	with F tests that met 95 percent confidence. And we
3	did these projections.
4	It's also working in the upper regions,
5	where we have more than ten inspections over more than
6	ten years. And now we're in certain areas. We're
7	finding areas that are meeting the F test with 95
8	percent confidence. And we're finding rates of less
9	than that.
10	However, using the 2006 data for the sand
11	bed and moving on to slide 80, we only have four data
12	sets. And with very high variance, the data did not
13	meet the F test 95 percent confidence. So we had to
14	do more conservative analysis and simulation to show
15	that we would have seen high rates.
16	And I'm going to move on to slide 81.
17	MEMBER POWERS: Do you see evidence of
18	pitting in your corrosion at all?
19	MR. TAMBURRO: I'm sorry. I didn't hear
20	the question.
21	MEMBER POWERS: Do you see evidence of
22	pitting corrosion?
23	MR. TAMBURRO: We don't see evidence of
24	pitting. We do see evidence of local areas
25	progressing further than other areas, but those would
	I contract of the second se

(202) 234-4433

	175
1	not be characterized as pits. They would just be
2	characterized as areas that have progressed further.
3	CHAIRMAN MAYNARD: I do want to keep us
4	moving along here. I don't know how much more time
5	that you need, but I don't want to cut off the people
б	for their time this afternoon, too.
7	MR. TAMBURRO: I'll try and hurry it up.
8	So let's move on to slide 82. We performed
9	simulations based on Monte Carlo-type simulations.
10	And the simulations were intended to answer the
11	question, what's the minimum rate I would have
12	observed with 95 percent confidence given that I only
13	had 4 inspections and I had variances between 8 and 16
14	mils? This is not a rate we saw, but it is a rate we
15	should have seen given the number of inspections and
16	how much variance is.
17	Slide 83 provides a schematic of how the
18	random number generator was used. It took a mean, a
19	standard error, and 49. We got out of the random
20	number generator an array of 49 values, which is
21	normally distributed, with a mean and a standard
22	error, not necessarily the same as what was input
23	because of the random generator nature of
24	MEMBER POWERS: How do you know your
25	generator was not correlated?
l	1

(202) 234-4433

	176
1	MR. TAMBURRO: I don't know. We used the
2	standard random number generator from a standard
3	product.
4	MEMBER POWERS: Mr. Gnu's book on
5	semi-numerical algorithms goes at great lengths to
6	decry the use of standard numerical number generators.
7	He will regale you with stories of how correlated they
8	are.
9	MR. TAMBURRO: Thank you.
10	Moving on to slide 84, we then did this
11	slide is busy. I'm going to walk through it slowly.
12	We then simulated a series of inspections. So item 1
13	we simulated for our worst location, which was
14	location 19A. We input a value of 800 mls, which was
15	the reading in 1992. We inputted standard error. And
16	the generator gave us a 49-point array, which we then
17	calculated the mean and standard error. This is a
18	simulator standard error.
19	In 1994, for 1994, we inputted a value 2
20	mls less. In this case, we simulated a rate of one ml
21	per year, so two years differential, one ml a year,
22	two mls less.
23	For 1996, we did the same thing. And for
24	2006, again, we lowered the input mean by the
25	appropriate value for a one-year period, one ml PRA.
	1

(202) 234-4433

	177
1	With this simulation, we then performed a
2	curve fit. And then we performed the F test on this
3	value. If the F test was successful, we counted it
4	successful. We repeated this 100 times and counted
5	the number of successful tests.
6	On to the next slide. We then increased
7	the rates. So this slide is a schematic that shows
8	how we progressed at greater rates and the number of
9	times the F test was successful.
10	For example, for 2 mls per year, we passed
11	the F test 27 out of 100 times. At 8 mls per year, we
12	passed the F test 98 out of 100 times. We refined the
13	analysis. And at 6.9 mls per year, we passed the F
14	test 96.2 times. We did it ten times just to be sure.
15	VICE-CHAIRMAN WALLIS: This is a very
16	conservative
17	MR. TAMBURRO: Yes, sir. Yes, sir.
18	MEMBER ARMIJO: I don't believe it,
19	frankly, because it doesn't correlate at all with your
20	data.
21	MR. TAMBURRO: No, it doesn't.
22	MEMBER ARMIJO: And maybe it's telling me
23	that if it had been as much as 6 mls per year
24	corrosion rate, you would have had 96 percent
25	confidence of finding it, but you didn't.
1	I

(202) 234-4433

	178
1	MR. TAMBURRO: That's exactly the point,
2	sir.
3	MR. GALLAGHER: And one point we are
4	trying to make with this is that when you take a look
5	at the data, it's flat-lined. It's flat-lined. And
б	we're just using this to show that our inspection
7	frequencies are conservative.
8	So given this projection, people fast
9	forward given this projection. You know, it goes out
10	ten years. We're inspecting again in four years. So
11	we have a conservative inspection.
12	MR. TAMBURRO: Mike, you stole my next
13	slide.
14	MR. GALLAGHER: Sorry, sir.
15	MR. TAMBURRO: So that's what the next
16	slide says. 6.9 mls per year is the minimum rate we
17	did not observe. We should have observed it with high
18	confidence. So our next inspection is going to be
19	prior to when we project that rate into the future.
20	For the most limiting locations, 19A and
21	17D, if we did have a rate of 6.9 mls per year, which
22	we don't, we would reach our minimum value by 2016.
23	VICE-CHAIRMAN WALLIS: But you are
24	assuming that there is no change in the physical
25	situation in that period of time, that you can just
	I contract of the second s

(202) 234-4433

	179
1	extrapolate past experience. And caution would
2	indicate that you ought to do something sooner because
3	something may have happened. Epoxy may have changed
4	in some way unpredicted and so on.
5	MR. TAMBURRO: Yes, sir. And moving on to
6	the next slide
7	VICE-CHAIRMAN WALLIS: This is like
8	predicting the weather in New England 20 years from
9	now or something.
10	MR. TAMBURRO: And moving on to the next
11	slide
12	MEMBER POWERS: It would be just as bad 20
13	years from now as it is today.
14	CHAIRMAN MAYNARD: Let's move on. Next
15	slide.
16	MR. TAMBURRO: Even though the analysis
17	shows 2016, we will inspect in 2010. So that is much
18	sooner than this conservative analysis tells us we
19	should inspect. And further inspections, we'll use
20	the same methodology to establish required inspection
21	frequencies.
22	MR. POLASKI: So that completes Pete's
23	presentation. Are there any further questions on
24	that?
25	(No response.)
1	I contract of the second se

(202) 234-4433
	180
1	MR. GALLAGHER: Yes. Dr. Maynard, what we
2	have next is about the 2006 actual data. So we can
3	continue or
4	CHAIRMAN MAYNARD: I would like to go
5	ahead and continue just for a little while here. If
6	it runs too long, we may have to stop, but I would
7	like to get finished with your presentation before we
8	break for lunch.
9	MR. GALLAGHER: Okay.
10	PARTICIPANT: The entire thing?
11	CHAIRMAN MAYNARD: Yes, the licensee's
12	presentation.
13	VICE-CHAIRMAN WALLIS: The whole thing?
14	MR. POLASKI: It won't take us long to go
15	through the rest of this presentation on the sand bed
16	region. So Mr. Howie Ray is now going to make a
17	presentation on the results of the October 2006
18	refueling outage.
19	Mr. Ray is a design manager, has been a
20	design manager, at Oyster Creek for the last two years
21	and will
22	CHAIRMAN MAYNARD: I'm sorry. I didn't
23	mean to complete your entire presentation but the
24	section that we're in right now.
25	MR. POLASKI: Yes. We're going to do the
	I

(202) 234-4433

I	181
1	sand bed region now.
2	CHAIRMAN MAYNARD: Sorry.
3	MR. POLASKI: Thank you.
4	MR. RAY: Thank you, Fred.
5	My name is Howie Ray. I'm going to give
6	you the scope of the 2006 inspection that was
7	performed in the sand bed region. We did visual
8	inspection of the coating in all ten bays. That's
9	external to the drywell.
10	We did UT measurements in 19 grids at
11	elevation 11-foot, 3. That's internal to the drywell.
12	And we did UT measurements of the 106 locally thin
13	single point locations external in the sand bed
14	region.
15	The results of the visual inspection of
16	the external shell showed no degradation. This was
17	performed by qualified NDE personnel. And these were
18	all satisfactory.
19	Going on to the next slide, this shows you
20	pictures of the drywell shell. This is 2006 pictures.
21	You saw earlier the 1992 pictures. You can see the OD
22	surface of the shell is still in good condition. Just
23	to point out
24	VICE-CHAIRMAN WALLIS: What are those
25	stalic types at the bottom there that stick out from
l	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	182
1	the coating?
2	MR. RAY: I'm sorry? Could you repeat?
3	VICE-CHAIRMAN WALLIS: What are those
4	spiky things that stick out from the coating? What
5	are they? Does that have something to do with how the
6	coating was applied? That thing there, yes. What's
7	that?
8	PARTICIPANT: That's a good point.
9	MR. RAY: That's just the caulk. That's
10	a caulk between the shell and the
11	VICE-CHAIRMAN WALLIS: That's the caulk?
12	MR. RAY: Yes, probably just
13	MEMBER SIEBER: There's another one where
14	the
15	CHAIRMAN MAYNARD: Jack? Jack?
16	MEMBER SIEBER: There's another one where
17	the external UT inspection circle is to the left,
18	right above it.
19	MR. RAY: These surfaces were visually
20	inspected by qualified, and they were satisfactory.
21	So some of these pictures are deceiving.
22	VICE-CHAIRMAN WALLIS: There's some color.
23	You have some color in
24	MR. RAY: Yes. The other thing I wanted
25	to point out, too, is on the floor. That's a concrete
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	183
1	floor there on the left-hand side. Fred, do you want
2	to point that out, where the orange color is? I just
3	want to point out that the shell and the caulking
4	there were satisfactory. That is no indication of any
5	corrosion off of the shell.
6	MEMBER ABDEL-KHALIK: What is the cause of
7	the discoloration on the floor?
8	MR. RAY: If you recall the covers to the
9	rebar, right on this side is the biological concrete
10	wall. And there's a possibility of just some of that
11	discoloration coming off the surface rust on that
12	cover. But these were, there was no unsatisfactory
13	condition.
14	VICE-CHAIRMAN WALLIS: So those yellow
15	patches mean nothing or they're an illusion or
16	something?
17	MR. RAY: I think they're just shadows in
18	the
19	VICE-CHAIRMAN WALLIS: Yes?
20	MR. RAY: Going on to the next slide, if
21	there are no other questions on that one, this is
22	another picture. We have talked about this one. So
23	I won't spend too much time. But I did just want to
24	point out that the transition, it's obvious where the
25	top elevation of sand was prior to being removed.
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	184
1	Going on to the next slide, I wanted to
2	give you a picture of the bay 19 caulking conditions.
3	This is the bay with our minimum margin at this point
4	just to show you that the shell, caulking, and floor
5	are all in good condition.
6	MEMBER ARMIJO: Just for a scale, what is
7	the width of that caulking thing? Is that an inch or
8	two or
9	MR. TAMBURRO: This is Pete Tamburro.
10	It's approximately an inch.
11	MEMBER ARMIJO: It gives you an idea of
12	the granularity.
13	MR. RAY: Okay. The UT measurements at
14	the 19 internal grid locations were completed. And no
15	ongoing corrosion was identified, as Peter just went
16	through and described how we looked at those.
17	This next slide, this shows a table of the
18	UT measurements of the 19 grid locations that we have
19	taken since 1992. Just to highlight the yellow cells,
20	these are the minimum readings that have been taken
21	throughout the years. And these are the values used
22	to develop the margins for each bay. If you look on
23	bay 19A, you can see 62 mls there is our lowest margin
24	at this point.
25	The next slide shows a simplified
1	

(202) 234-4433

	185
1	tabulation of all the bays with their minimum margins.
2	And you could see bay 19 minimum with bay 3 having a
3	maximum of 439 mls.
4	The next slide, this is a trend graph. We
5	do have graphs of all of the 19 grid locations that
6	are in your reference book. We have included the
7	lowest margin and one of the more significant margins,
8	then, for your review.
9	Some keys to point out here are the top
10	horizontal line shows the original plate thickness of
11	1,154 mls. The bottom horizontal line shows the
12	minimum required shell thickness of 736. And the line
13	in between there you can see that has a slope, it's a
14	15 mls per year slope there on the left up to 1992.
15	That shows the significant corrosion that existed
16	before the sand was removed.
17	Also, just to note there that we're
18	showing the standard errors there, the 8.4 mls, the
19	9.9. And those are not corrosion rates. They're
20	standard deviations.
21	And then you can see from 1992, when we
22	removed the sand, it's fairly obvious that we did
23	correct the situation in that area.
24	And I just wanted to point out another
25	point of reference on here is between 1994 and 1996,
	1

(202) 234-4433

	186
1	those were two outages where we did not install these
2	triple coating. And you can see it did not have any
3	adverse effect on the
4	VICE-CHAIRMAN WALLIS: I'm surprised with
5	all these readings going down so rapidly that you
6	didn't do something before 1991-92. It's past
7	history, but it just seems strange that headed for
8	disaster in '94
9	MR. TAMBURRO: I think the answer would be
10	there was a lot being done. It was just very
11	difficult to get in there to the sand.
12	MR. POLASKI: There were things being
13	done. I mean, the drain lines were cleared to drain
14	water out. That wasn't successful. They then
15	installed a cathodic protection on two bays. And that
16	didn't solve the problem. And ultimately they decided
17	in 1992
18	PARTICIPANT: Get the sand out.
19	MR. POLASKI: they had to take the sand
20	out.
21	MR. RAY: Just quickly to show you we did
22	bay 1D in there also, which has 365 mls of margin.
23	Okay. So the 2006 UT readings, let's see. There were
24	106 individual UT measurements taken externally to the
25	sand bed region.
	1

(202) 234-4433

	187
1	It was verified that all 106 measurements
2	continue to meet the local thickness requirements.
3	That's both buckling and membrane stresses.
4	The 2006 measurements that were taken
5	external to the drywell, we've determined they are not
6	directly comparable to the 1992. We have talked a
7	little bit about it before with the difference in
8	technique that we have encountered there.
9	The next slide, we'll just go through and
10	highlight what the differences were from the UT
11	technique that we used in 1992 and that they were
12	using in 2006.
13	So in 1992, we did the readings on
14	uncoated surface. The surface had to be prepped
15	enough to get the transducer in there. It's obviously
16	a cupped surface. And traditional pulse, the echo
17	technique was used for that technique.
18	Today's technique, we are using the echo
19	technique. It does take the readings through the
20	coating. And it also allows the
21	VICE-CHAIRMAN WALLIS: The cup thing could
22	also make this cup
23	MR. RAY: between the transducer and
24	the
25	VICE-CHAIRMAN WALLIS: When you make a
	I contract of the second se

(202) 234-4433

	188
1	cup, the way we have been through this before, you are
2	actually making it a little bit thinner where you put
3	the transducer than it really is or than it was
4	before.
5	MR. RAY: That's absolutely right. You
6	would expect to have a little bit less just based on
7	that factor.
8	VICE-CHAIRMAN WALLIS: How big is that?
9	How much stuff do you take out to make that
10	MR. RAY: Actually, we have demonstrations
11	if you're really interested in this stuff, but I think
12	it was about 20 mls, Marty?
13	VICE-CHAIRMAN WALLIS: It's 20 mls. Okay.
14	So it's significant compared with the 60 mls you're
15	talking about for the margin.
16	MEMBER SIEBER: Well, you usually take it
17	down to where the lowest bid is.
18	MR. O'ROURKE: I don't think we're saying
19	we took off 20 mls. I think the variability between
20	the readings for 2000 to 2006 was 20 mls.
21	MR. RAY: Right. Yes. That's what we're
22	saying. So that way
23	CHAIRMAN MAYNARD: Keep it down to the
24	point where you've got it smooth enough to do that
25	MR. GALLAGHER: That's right.
	1

(202) 234-4433

	189
1	MR. RAY: So we did have to remove some
2	margin when we did that. And that's why we wanted to
3	minimize it as much as possible.
4	MR. GALLAGHER: I guess the point was,
5	Howie, from Dr. Wallis' question,
6	MR. RAY: I'm sorry.
7	MR. GALLAGHER: we took it down to the
8	lowest point. I mean, presumably we didn't go lower.
9	VICE-CHAIRMAN WALLIS: You might have
10	done, yes.
11	MR. GALLAGHER: But we tried not to.
12	VICE-CHAIRMAN WALLIS: Lower than the
13	average, certainly, yes.
14	MEMBER SIEBER: You actually can't help it
15	a little bit lower, but it's on the older of a couple
16	of mls.
17	MR. POLASKI: When we show you results,
18	things are not points that are showing that they're
19	the lead areas or the cleanest areas.
20	MR. RAY: Because of those differences,
21	we're going to treat the 2006. We used a much more
22	rigorous approach in going and doing these and
23	identifying the exact locations. So we're going to
24	these 2006s are baseline going forward. We will be
25	going back in 2008 and remeasuring these.
	1

(202) 234-4433

	190
1	The next slide, this gives the external
2	108 points inspection results. The key thing here,
3	this basically shows that there's very few points that
4	are less than the 736 criteria. In bay 13, the lowest
5	reading we have now is the 602 mls. And that still
6	satisfies the required local thickness of 536 mls.
7	The difference here between the 1992 total
8	and the 2006 total, we could not go back and duplicate
9	the 125 points. Some of the points they took in 1992
10	were the same in the areas that were cupped. And we
11	just went and got the finished reading, each one of
12	those cups. So we will be using 106 to clearly
13	identify as we should in the pictures, and we have a
14	good baseline to move forward.
15	Okay. This next picture, we did talk
16	about this a little bit before. But this schedule
17	illustrates all of the 19 grid internal UT readings
18	along with 106 external finished points that we took
19	in 2006. And we also have included the trench UT
20	readings, which adds up to kind of the numbers and
21	this also illustrates that right above the 11-foot-3
22	line, you can see that that is where most of our grids
23	are and that is where we are seeing the thinnest
24	readings. And that is where the points were picked.
25	The majority of the points that were thinnest were
	1

(202) 234-4433

(202) 234-4433

	191
1	picked in that area. So that helps demonstrate that
2	the 11-foot-3 elevation.
3	This sketch demonstrates the very few
4	measurements fall below the general required thickness
5	of 736 mls. We have yellow indicated there for
6	between 636 to 736 mls. We have one red spot there in
7	bay 13, which is the 602 mls that we measured. And
8	1992 was the thinnest reading of 618.
9	I guess an important point was in 1992,
10	they did do a full detailed round with micrometers to
11	make sure that that was, in fact, the thinnest area in
12	that area. They did a six-inch square.
13	PARTICIPANT: Characterization.
14	VICE-CHAIRMAN WALLIS: So there are quite
15	a few yellow regions. On the right there, there's
16	MR. RAY: Right. These are in the we
17	wanted to show you how many different points there
18	were. They're actually all in the six-by-six grids
19	there.
20	VICE-CHAIRMAN WALLIS: So the other ones
21	are actually mixed in with green ones
22	MR. RAY: That's correct.
23	VICE-CHAIRMAN WALLIS: in the same
24	region.
25	MR. RAY: That's correct. They go into
1	I contract of the second se

(202) 234-4433

	192
1	that calculation.
2	MR. POLASKI: One thing, just to be clear,
3	the triangles are the single points that were taken
4	from the outside.
5	VICE-CHAIRMAN WALLIS: Right.
6	MR. POLASKI: The rectangles, the square
7	boxes were the grids that were taken from the inside.
8	And it's in a particular grid. And I'll point this
9	one in bay 17. There were local points in the 49 that
10	were less than 736. We showed them as yellow just so
11	you can
12	VICE-CHAIRMAN WALLIS: It's one-seventh of
13	them, yes.
14	MR. POLASKI: Any small squares are part
15	of a larger square or rectangle.
16	MEMBER SHACK: Why do I have seven points
17	in some of the grids?
18	MR. POLASKI: I am going to ask Pete to
19	address that.
20	MR. TAMBURRO: During the characterization
21	in the mid '80s, some of the areas to the left showed
22	that they were nominal. So we did not go and do a
23	further characterization. So those areas with only
24	seven, even today, have thicknesses that are very
25	close to nominal.
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	193
1	MR. RAY: Okay. If there are no more
2	questions with that, we will move on to slide 102.
3	VICE-CHAIRMAN WALLIS: So let us see. The
4	7 are the ones which are the smaller green square, and
5	the 49 are the big green rectangle?
6	MR. POLASKI: That's correct.
7	MEMBER SHACK: Now, if you're coming down
8	in elevation, basically from the top of the sand bed
9	down towards that seam, is there a trend in the
10	thickness loss in places where you have enough
11	measurements?
12	MR. TAMBURRO: The trend is that the
13	majority of the loss is in the middle, where you see
14	the grids. The inspections of the external below
15	those grids and even in the trenches show that the
16	loss is not as severe.
17	MR. POLASKI: And I think the other thing
18	to remember on this picture is that where we show in
19	color. This is where we took measurements. The place
20	that's white was thicker than that. And sometimes
21	people tend to lose that that the white is showing a
22	lot of areas greater than 736.
23	VICE-CHAIRMAN WALLIS: Isn't corrosion
24	worse, sort of the interface between water and air so
25	that if the sand bed was partially flooded, it would
I	1

(202) 234-4433

	194
1	actually be protected by the water at the bottom?
2	MR. POLASKI: Well, there where the
3	interface is where it's at the worst, but if you see
4	from your pictures, there was corrosion on this whole
5	area.
6	VICE-CHAIRMAN WALLIS: Yes, but it's worst
7	somewhere partway up. It's not at the bottom.
8	MR. POLASKI: Yes, yes.
9	MR. RAY: We will be talking about that
10	later.
11	MR. POLASKI: Okay.
12	MR. O'ROURKE: Slide 102. To summarize,
13	we have shown you the ultrasonic measurement data that
14	supports our conclusion that the corrosion on the
15	outside of the drywell shell in the sand bed region
16	has been arrested.
17	Our direct visual examinations have
18	supported the conclusion that the coating shows no
19	degradation and, therefore, continues to protect the
20	external shell.
21	And based on the ultrasonic measurement
22	data and trend graphs, we supported the conclusion
23	that sufficient margin exists to the minimum thickness
24	requirements.
25	Going forward, we have defined an aging

(202) 234-4433

	195
1	management program that includes visual inspection of
2	the exterior coating in a minimum of three bays every
3	other outage and inspecting all ten bays once every
4	ten years.
5	VICE-CHAIRMAN WALLIS: Now, why is it
6	restricted to three bays? Is it very difficult to do
7	more?
8	MR. O'ROURKE: It's just distributing them
9	over the ten-year period?
10	VICE-CHAIRMAN WALLIS: Yes, but it just
11	seems a little risky to do a few bays and not look at
12	everything.
13	MR. POLASKI: Dr. Wallis, it is difficult
14	to get into this area. I mean, we showed you those
15	20-inch-diameter man-ways. Those have shielding
16	VICE-CHAIRMAN WALLIS: So you are telling
17	me that we have got a camera, a robot that runs all
18	the way around or something?
19	MR. POLASKI: No, no.
20	CHAIRMAN MAYNARD: And I would assume that
21	your program is set up that where if you started
22	seeing degradation, that the frequency would be
23	revisited to see if you need to go into all
24	MR. POLASKI: That's correct, yes.
25	MR. O'ROURKE: We will also be repeating

(202) 234-4433

the ultrasonic measurements at the 19 grid locations at elevation 11-foot-3 in 2010 and then every 10 years thereafter and will be repeating the ultrasonic measurements at the 106 locally thin locations from the exterior in the 2008 outage and then in 2 bays every outage thereafter.

7 VICE-CHAIRMAN WALLIS: Do you have any 8 measurement of humidity in this region ongoing? 9 Wouldn't it be useful just to have a humidity meter in 10 the sand bed region and see how wet it is?

MR. POLASKI: There have been some. 11 You 12 know, we have been asked that question. One of the concerns is any instrumentation will be exposed to a 13 14 reasonably high radiation field in there. I mean, this is inside the shield wall around the drywell. 15 We don't expect any instruments that would measured 16 humidity would survive. 17

But this was an area that once you close it off, you don't get any ventilation flow through here.

21 VICE-CHAIRMAN WALLIS: That's why I'm 22 surprised it rushed it so much because I calculated 23 you need several hundred thousand cubic feet of air to 24 get the oxygen to make all that rust.

MR. POLASKI: But then once the curb --

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

	197
1	PARTICIPANT: I mean, it's a conductor.
2	CHAIRMAN MAYNARD: We have got several
3	side conversations going on. Let's go ahead and move
4	on here.
5	MR. POLASKI: That completes our
6	presentation on the sand bed region.
7	CHAIRMAN MAYNARD: Yes. Before we go into
8	the next section, we're at the point in the agenda for
9	a lunch break. I would like to ask the members if 40
10	minutes would be enough for lunch. Is that
11	acceptable? That way we won't get too far behind.
12	Okay. We will
13	MEMBER BONACA: I have another question.
14	A question I have is more real to the MR scientists.
15	Since the leakage from the refueling liner happened so
16	early in the life of this plant, did you ever consider
17	replacement? Did you ever consider replacing the
18	liner?
19	MR. RAY: We've done extensive back in
20	1988 when we did put this in our non-conformance
21	system, we did an extensive review of it and
22	determined that because of the welding and I'm not
23	getting to your question. You are asking for a direct
24	liner replacement?
25	MEMBER BONACA: Yes. I mean, clearly a
	I contract of the second se

(202) 234-4433

198 1 list from your perspective that the water is for 2 refueling cavity and has been plaquing you. And I'm 3 sure this problem right now ends up being very 4 expensive. 5 MR. GALLAGHER: The only thing we have investigated was about repairs. We actually attempted 6 7 some repairs in 1983. And right now we feel that we are adequately controlling the leakage with the 8 metallic tape and the strippable coating and that we 9 can ensure that no water gets in the sand bed region. 10 And so that's what we have done. 11 12 CHAIRMAN MAYNARD: Mario, I've got some additional questions on that area, too. I think that 13 14 when we're finished with our presentation, maybe we'll 15 pursue that just a little bit. I would like to go ahead and break for 16 lunch now. 17 Licensee will come back up here after lunch. And we'll have a chance for more questions. 18 19 We'll break for lunch. And we'll come back at ten 20 after, ten after 1:00. 21 (Whereupon, a luncheon recess was taken 22 at 12:27 p.m.) 23 CHAIRMAN MAYNARD: Okay. I'd like to go 24 ahead and resume the meeting. So we'll turn it back 25 over to the next agenda item.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	199
1	MR. POLASKI: Thank you.
2	Mike Gallagher is going to start off with
3	some information about questions on some of the
4	conditions during the accident analysis.
5	MR. GALLAGHER: Mr. Chairman, we had to
6	follow up on three questions. I think they came from
7	Dr. Wallis. So do you want me to defer that?
8	CHAIRMAN MAYNARD: Yes. Why don't we wait
9	until he gets back? He should be back here.
10	MR. GALLAGHER: Okay. So we'll do that
11	after another break.
12	CHAIRMAN MAYNARD: Okay.
13	MR. POLASKI: Okay. Our next section of
14	the presentation is dealing with the imbedded portion
15	of the drywell shell. We'd like to discuss the
16	condition of the imbedded shell. We're talking about
17	the condition of the drywell shell in the sand bed
18	region.
19	If you'll remember, the sand bed region is
20	the portion of the drywell shell that transitions from
21	the lowest portion of the drywell shell, which is
22	fully imbedded in concrete both on the interior and
23	the exterior. The upper portions of the drywell,
24	which is a free standing pressure vessel. We will
25	discuss the condition of the imbedded section,

(202) 234-4433

	200
1	conditions that exist on the surface of the drywell
2	shell when water intrudes between the steel of the
3	shell and the concrete pour both on the inside and the
4	outside of the drywell during construction, and the
5	results of inspections that were performed in 2006.
6	When we were here in October of last year,
7	we only discussed potential corrosion on the exterior
8	surface of the imbedded section of the drywell shell.
9	During our refueling outage in October of '04, we
10	discovered water below the concrete floor on the
11	inside of the drywell. This was not expected, and is
12	a condition that was not covered in the Oyster Creek
13	licensure application.
14	We have supplemented our application to
15	include this environment and have modified our aging
16	management programs accordingly. So today we will be
17	discussing the impact of water on both the interior
18	and the exterior surfaces of the imbedded section of
19	the shell.
20	And Mr. John O'Rourke will lead our
21	presentation on this topic.
22	MR. O'ROURKE: Thanks, Fred.
23	The next part of this presentation focuses
24	on the imbedded shell and will support the following
25	conclusions.
	I contraction of the second seco

(202) 234-4433

	201
1	First, corrosion on the imbedded surfaces
2	of the drywell shell, both interior and exterior, is
3	not significant, and we will provide you with a
4	discussion of the environment of imbedded steel in
5	concrete and how it prevents significant corrosion.
б	Our second conclusion is that based on
7	recent ultrasonic inspections in the trench areas is
8	that if there is ongoing corrosion, it's estimated at
9	less than one mil per year.
10	And our final conclusion, again, based on
11	the ultrasonic inspections is that the drywell shell
12	meets design requirements with margin through the
13	period of extended operation.
14	First, let me briefly orient the
15	subcommittee with several physical sketches. This
16	sketch shows the elevation of the interior of the
17	drywell, and in particular, Fred is going to point out
18	several locations on the right and left side at the
19	drywell floor at elevation ten foot, three.
20	Also, on the left side is the concrete
21	that was removed from Bay 5 to form that trench. The
22	area under the reactor vessel, which we refer to as a
23	sub pile room, and the trough that's inside sub pile
24	room that is 360 degrees around the perimeter of the
25	room and directs any drywell leakage to the sump.
1	I contraction of the second

(202) 234-4433

	202
	Also of note on the right side where the
	curve exists, that joint between the concrete curve
	and the drywell shell, we added a caulk sealant to
	that during the last outage, and we will discuss that
	more.
	The next sketch that shows the drywell
	support structure, starting at the bottom, it consists
	of a ten foot thick concrete mat. On top of that is
	a concrete pedestal that is over 21 feet thick.
	Also of note is the sand bed region and
	the and the 20 inch manway that provides access to the
	region, and we have a torus room with an elevation of
	minus 19 foot, six that goes around the reactor
	building.
	Also of note is a waterproof membrane that
	was installed when the concrete was placed. You can
	see that that waterproof membrane goes underneath the
	concrete mat and up the outside of the concrete
	surfaces up to a level of plus five foot, zero.
	The next Slide 108 is a close-up of the
	drywell support skirt.
	CHAIRMAN MAYNARD: Just a quick question.
	Your elevations, are those from a reference point or
	is that from sea level?
11	

MR. O'ROURKE: Sea level.

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

б

Slide 108, this is a close-up of the drywell support skirt and the sand bed region and what illustrates one of the five drains that Fred had previously mentioned out of the sand bed region, but it also shows the plate thicknesses and the transition area in the imbedded shell where it transitions from the 1,154 mils to 676 mils.

Slide 109, again, this is a plan view of the drywell showing the trench locations, and I had previously shown you slides of the details of those trenches.

12 Continuing with the discussion of the imbedded external shell in Slide 110, any corrosion of 13 14 the drywell exterior imbedded surface occurred because 15 of water leakage into the sand bed region, and corrective actions that had been taken for the sand 16 bed region have arrested corrosion of the drywell 17 exterior imbedded shell, including preventing water 18 19 leakage from entering the sand bed region and sealing 20 the joint between the drywell shell and the floor of 21 the sand bed region to prevent water from contacting 22 the external shell, as I had noted in a previous 23 slide. 24

24 Slide 111. For the interior imbedded 25 shell the water that was identified in the trenches in

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

3

4

5

6

7

8

9

10

11

	204
1	Bays 5 and 17 inside the drywell when the foam filling
2	was removed during the 2006 refueling outage was
3	determined to have originated from equipment leakage
4	inside the drywell and not from external sources.
5	The investigations during the outage into
6	the source of the water indicate that there could have
7	been water below the drywell interior floor for an
8	extended period of time. To get more information
9	regarding the condition of the shell, concrete was
10	removed from the Bay 5 trench to expose an additional
11	six inches of drywell shell that had been imbedded on
12	both sides for ultrasonic thickness measurements in a
13	newly exposed area.
14	CHAIRMAN MAYNARD: I'm sorry. Can you
15	just again, I need to relate exactly where you're
16	looking at now. Maybe I have to go back to the slide
17	here.
18	MR. O'ROURKE: Okay. Let's go back to
19	Slide 108. First, on the external side, the seal, you
20	see the word "seal." That indicates where we put the
21	caulk seal and we showed the photographs of that seal
22	and the condition of that seal as we inspected it in
23	2006.
24	When we go to the interior, if you back up
25	to Slide 106, the curve on the right shows the

(202) 234-4433

	205
1	interface between the concrete inside the drywell and
2	the drywell shell.
3	CHAIRMAN MAYNARD: It's the trench on the
4	left that got full of water.
5	MR. O'ROURKE: The trench on the left that
б	got filled with water.
7	MR. POLASKI: This is the trench at Bay 5,
8	and you'll note that the bottom of that trench
9	corresponds to the bottom of the sand bed region. So
10	when we're talking imbedded region, we're talking from
11	here down, and when we move that additional concrete
12	from this region, the detail doesn't show here. This
13	is the first time we're able to give UT thickness
14	measurements on the drywell shell in a region that had
15	been imbedded both on the inside and the outside.
16	MR. O'ROURKE: Okay. This is the blow-up
17	that I showed previously of the Bay 5 trench, also
18	showing the additional concrete that we removed. When
19	we took the foam out of this trench, we had about five
20	inches of water in the bottom of the trench. We do
21	have a photograph of that coming up in a later slide.
22	MR. SHACK: This is an experiment to test
23	the corrosion environment.
24	MR. O'ROURKE: And back to Slide 112, we
25	did remove the additional six inches to interrogate

(202) 234-4433

ĺ	206
1	the area that had been imbedded on both sides sine the
2	original construction, and we will present the
3	ultrasonic measurement data for this inspection as
4	part of this presentation.
5	The corrective actions implemented during
6	the 2006 refueling outage included caulking the joint
7	between the drywell interior floor and the drywell
8	shell, and I pointed that location out in the
9	elevation view. We also made repairs to the
10	collection trough inside the sub pile room to prevent
11	any leakage into the concrete, both of which I had
12	shown on that previous slide.
13	Fred.
14	MR. POLASKI: Thank you, John.
15	Our next section is going to be a
16	presentation on corrosion of steel imbedded in
17	concrete. Making this part of the presentation will
18	be Mr. Barry Gordon. Mr. Gordon holds Bachelor's and
19	Master's degrees in material science engineering from
20	Carnegie Mellon University. He has been involved with
21	nuclear systems corrosion concerns for over 38 years
22	while working for Powell Laboratories, General
23	Electric Nuclear Energy, and Structural Integrity
24	Associates.
25	He is a member of the National Association
	I

(202) 234-4433

	207
1	of Corrosion Engineers for 34 years and has served as
2	unit committee chairman of corrosion and nuclear
3	energy systems and group committee chairman of energy
4	technology.
5	Mr. Gordon is an NACE certified corrosion
6	specialist and a registered professional engineer in
7	corrosion engineering. He has authored or co-authored
8	over 50 corrosion publications, including chairing the
9	2006 ASM Volume 13(c) section on corrosion in a
10	nuclear power industry.
11	Also, Mr. Gordon is currently preparing
12	the utility requirements document for materials for
13	advanced light water reactors for EPRI.
14	Mr. Gordon.
15	MR. GORDON: thank you very much, Fred.
16	I'm going to briefly discuss some of the
17	science involved, why carbon steel and concrete
18	environments work so well together. You know, any
19	construction site you'll see lots and lots of rebar
20	and the pouring of concrete onto the steel, bare
21	carbon steel, and why it's a satisfactory structural
22	system.
23	We've used, you know, tunnels and
24	concrete-like steel pipe, and there's a reason for
25	doing this.
	I

(202) 234-4433

	208
1	The first slide.
2	The drywell shell is constructed first,
3	and then on each side the interior and exterior
4	concrete was poured in. When you have wet concrete in
5	contact with steel, the concrete mixture is at very
6	high pH, and this forms a passive film on the surface
7	of the carbon steel, and it's a very resistent film.
8	And as the concrete hardens, even though
9	it becomes very hard, it still contains pores in the
10	concrete and the concrete contains it's called pour
11	water, and this pour water is, again, very high pH and
12	it mitigates corrosion.
13	So looking at the slide, again, the
14	concrete. The shell is constructed first, covered
15	both surfaces of the imbedded steel with concrete.
16	The high pH is like 12.5 to 14 during the hydration of
17	the cement, which is one of the mixtures in the
18	composite concrete material. It forms a passive film
19	on the surface which mitigates corrosion, and again,
20	that's why this system is used for constructing
21	buildings, tunnels, swimming pools, whatever.
22	Going to Slide 116, the reactor cavity
23	water, looking at the exterior environment now. The
24	reactor cavity water, which leaked down, went through
25	sand bed, was certainly affected by the sand bed
	I contract of the second se

(202) 234-4433

	209
1	region, and there may be some concern for that.
2	But a chemical analysis of this water,
3	again, it's reactor cavity water which is very high
4	purity to begin with, reveals that the pH is greater
5	than seven. The fluoride content was 0.045 parts per
6	million, and the sulfate concentration was 0.32 parts
7	per million. That's very high purity.
8	And the next line I have there is an
9	average of 3,600 waters, potable waters, natural
10	waters around the United States, and it shows that the
11	typical concentration is much higher, orders of
12	magnitude higher in chloride and orders of magnitude
13	higher in salts.
14	DR. WALLIS: So why was there so much
15	corrosion on the outside originally?
16	MR. GORDON: It doesn't take in that
17	particular area, in the sand region, there's no
18	concrete there to protect it.
19	DR. WALLIS: But still why is it
20	aggressive though? It should be neutral.
21	MR. GORDON: Oh, I mean, pure water will
22	certainly corrode steel, but I'm talking about in the
23	area where it is imbedded in concrete. It's a
24	different environment.
25	Again, the American Concrete Institute has
	1

(202) 234-4433

	210
1	rules on what kind of water is aggressive to concrete,
2	and the GALL report and the EPRI studies have all
3	supported the same level, and both these levels of the
4	water obtained from the sand bed region is high purity
5	and is not an aging concern.
6	Continuing with Slide 117, then the water
7	would have been the same high quality as we saw as
8	listed in the previous slide, but it would be
9	interacted with the high pH pour water, concrete pour
10	water, and it would provide a passive film for the
11	carbon steel.
12	Again, per the GALL report and for the
13	EPRI report, which is listed here, since the pH is
14	greater than 5.5 and the chloride content is way below
15	500 ppm and the sulfate is below 1,500 ppm, there is
16	not an aging concern for imbedded steel in concrete.
17	Now let's look at the surprise water that
18	was found during the last inspection on the interior
19	surface and see why that is also not a concern. A
20	chemical analysis was performed on this water, and the
21	next slide will actually show what this water looks
22	like. Again, the pH of this water was 8.4 to 10.2,
23	and this is even after it's exposed to the CO_2 in the
24	air, which would lower the pH. So the pH is probably
25	at least two points higher than this.
	•

(202) 234-4433

	211
1	High pH, and that's what you want to
2	maintain a passive film on carbon steel.
3	The chloride content, again, 13.6 to 14.6
4	ppm. It's way below the limit of 500 ppm.
5	Sulfate, again, 228 to 230, way below the
6	1,500.
7	The calcium content is just presented here
8	as a point of interest, and we'll discuss that in the
9	next slide. There's no GALL or EPRI concern with
10	that.
11	So this water that you have looked at in
12	the trench five is considered high purity concrete
13	pour water, which mitigates corrosion of carbon steel.
14	Again, this water that was found there complies with
15	the GALL and EPRI and ACI recommendations.
16	The next slide shows the trench five, the
17	water that was found in trench five, and the calcium
18	content, which I illustrated on the previous slide
19	indicates that the water was there for quite some
20	time. Water leaches out calcium hydroxide first from
21	concrete and it's an indication it took some time to
22	get there and, again, it mitigates corrosion.
23	Any subsequent water that may be found in
24	the interior of the drywell also will be affected by
25	this concrete pour water, have a high pH, and will be
	I

(202) 234-4433

	212
1	also high puree and will not lead to any degradation
2	of the carbon steel.
3	MR. ARMIJO: Where did this water come
4	from?
5	MR. GORDON: This is apparent during a
6	maintenance.
7	MR. ARMIJO: It was a spill.
8	MR. GORDON: Yes, spills and things like
9	that.
10	MR. GALLAGHER: As we mentioned in the
11	beginning, it's equipment leakage. So the design of
12	the drywell and the equipment leakage collection
13	system, and so any leakage would come down, go in the
14	sub pile room, go in a trough, and then goes into the
15	sump. So it's designed that way to collect any
16	leakage. That's where this leakage came from.
17	MR. ARMIJO: But did this water migrate
18	through the concrete or did it just kind of flow over
19	the top of something and just pour into this hole?
20	MR. POLASKI: It could have come from two
21	sources. The investigation showed that the trough
22	that we pointed out earlier in the sub pile room that
23	all of the leakage is supposed to flow into and then
24	drain to the sump did have some leakage in it. It was
25	not in the condition it should have been, and that

(202) 234-4433

	213
1	some of that water did migrate through the concrete
2	and showed up in these troughs.
3	The other thing is John mentioned earlier
4	that we have now installed caulking at the edge of the
5	curve, you know, against the scale of the drywell.
6	Most other BWRs have that caulked. Oyster Creek did
7	not. Oyster Creek is unique. It has a curve there,
8	but if there was any leakage that got on the shell of
9	the drywell and ran down, it could have gotten
10	directly below the concrete. Either of those ways
11	could have accounted for this.
12	MR. GORDON: And, again, this slide shows
13	the water, and you can see the carbon steel there, the
14	bare carbon steel. This has some superficial
15	corrosion on it.
16	What happens to the steel that's not
17	protected by the water, basically the side pH water.
18	MR. SHACK: Did you make inspections or,
19	okay, there is inspections later.
20	PARTICIPANTS: Yes.
21	MR. GORDON: What happens to the steel
22	that isn't protected by this high pH, high purity
23	water? When the drywell is inerted, the cathodic
24	reactant for the Trojan (phonetic) reaction oxygen is
25	depleted and corrosion would basically stop at that
1	I Contraction of the second

(202) 234-4433

	214
1	point.
2	Any possible subsequent steel corrosion
3	would occur only during the brief outages, which are
4	just a few, you know, ten days per year on average,
5	and you wouldn't expect to see much atmospheric
6	corrosion.
7	Finally, the transport of any oxygenated
8	water that may come in from equipment manipulation
9	would be affected by the high pH core water and also
10	it would have to displace the oxygen depleted water
11	before you'd see any corrosion.
12	So basically imbedded steel in concrete is
13	not a concern on either the interior or the exterior
14	of the drywell.
15	CHAIRMAN MAYNARD: Are you going to
16	provide more justification for the superficial
17	corrosion that you saw there or cover that in the
18	inspection? I mean, you made a statement that
19	there's some superficial rust there. I'd like to have
20	a little bit more to go on than just that. How do you
21	know it's superficial?
22	MR. GALLAGHER: Yes, Howie, answer that.
23	MR. RAY: Yes, so that's going to actually
24	lead into the infraction to be performed.
25	CHAIRMAN MAYNARD: As long as it gets

(202) 234-4433

	215
1	covered there
2	MR. POLASKI: We will cover it in a couple
3	of slides.
4	MR. GALLAGHER: And, Dr. Maynard,
5	basically the bottom line is on the interior when we
6	did UTs in the trench, and so you could easily wipe
7	off the corrosion, and then we UTed the whole trench
8	area and we have that data in here.
9	MR. POLASKI: So any other questions on
10	DR. ABDEL-KHALIK: How much farther do you
11	think beyond the trench that you dug in does the water
12	extend or is the concrete in intimate contact with the
13	steel along this entire bottom surface?
14	MR. POLASKI: The concrete that's on the
15	inside
16	DR. ABDEL-KHALIK: Right.
17	MR. POLASKI: as we said before, the
18	concrete or the drywell shell was welded together and
19	then the concrete was poured on the outside and then
20	on the inside. So it is in intimate contact.
21	DR. ABDEL-KHALIK: So if it is in intimate
22	contact, why is there water in the top part that you
23	dug out?
24	MR. POLASKI: Well, even though it's in
25	intimate contact, you can still get water into that.

(202) 234-4433
	216
1	There isn't really a gap there, but water can get in
2	between, you know, soaked into the concrete along the
3	steel.
4	MR. GALLAGHER: Yes, the concrete pour
5	water throughout the concrete slab, and you know, so
6	there's water there.
7	MR. RAY: Yes, the concrete is poured in
8	different sections. So there's actually a pass where
9	the water can get into the concrete or could migrate
10	through the different paths and seek its elevation, to
11	answer your question.
12	DR. ABDEL-KHALIK: Can you speak up a
13	little bit louder?
14	MR. RAY: Yes. The concrete was poured in
15	several different layers. So there are
16	DR. ABDEL-KHALIK: Horizontal halves?
17	MR. RAY: Horizontal, yes.
18	DR. ABDEL-KHALIK: So, I mean, if I look
19	at this picture, how much water is there and how much
20	water don't I see?
21	MR. POLASKI: We believe based on what we
22	found, when we found this water there was about five
23	inches in the bottom of Trench 5. It was pumped out
24	and then it filled back in again. So it was coming
25	from, you know, underneath the concrete and other
	1

(202) 234-4433

	217
1	areas.
2	We believe that the whole inside of the
3	drywell below the floor has water in there.
4	MR. ARMIJO: So you think there's water in
5	this lower part of the sphere
6	MR. POLASKI: Yes.
7	MR. ARMIJO: between the concrete and
8	the shell.
9	MR. POLASKI: Yes, that's correct.
10	MR. ARMIJO: And the source is the sump.
11	MR. POLASKI: Well, the source is
12	equipment leakage. It wasn't from the sump itself,
13	but from the troughs that then lead into the sump
14	indicated there was leakage out of that trough.
15	However, there would have been water in the past if
16	there was a leakage in the drywell, and again, there
17	was some small amount of leakage in the drywell; if it
18	got on the drywell shelf, could have run down and
19	gotten directly below. It could have been there for
20	years.
21	MR. GALLAGHER: Let's be clear. The
22	trough that we're talking about is this trough that
23	goes 360 degrees on the interior of the sub pile room.
24	That's designed to collect the water and then move it
25	to the sump.
	1

(202) 234-4433

	218
1	There were some defects in this trough so
2	that some water could have got into the concrete. We
3	don't know how far, you know, water is down there.
4	We're assuming it's down there and that we've taken
5	action to have an aging management program, assuming
6	it's there to check, and that's what we've done.
7	MR. ARMIJO: Well, the water level, you
8	know, if it's in direct contact, if it refills, the
9	water level is coming from somewhere. That's at least
10	that elevation or higher.
11	MR. GALLAGHER: Yes, and this elevation
12	here is the highest at that point. It's higher than
13	the bottom of the trench was. We've corrected this
14	trough. So we wouldn't expect anymore water to get in
15	there, but we added it to our aging management program
16	to verify that, to verify if there's any ongoing
17	effect.
18	But this trough elevation, see, right
19	here, if you look at the side, that's the bottom of
20	the trough, and then the bottom of the trench we're
21	talking about is at the bottom of the sand bed floor.
22	So any water you have coming down here
23	going into the trough, if the trough was not finished
24	correctly, would have gone into the concrete. So we
25	fixed that.
	1

(202) 234-4433

	219
1	MR. ARMIJO: But it's feasible the whole
2	bottom of that shell could have water in it.
3	MR. GALLAGHER: And that's what we're
4	presuming. We haven't verified it, you know, because
5	we only excavated down here.
6	MR. POLASKI: We're assuming there's water
7	there, but Mr. Gordon's presentation is just
8	addressing what would the conditions be, and once that
9	water gets in there
10	MR. GALLAGHER: It should be benign.
11	MR. POLASKI: it should be benign. A
12	passive layer was there when the concrete was
13	initially poured.
14	MR. SHACK: It would be better if it
15	wasn't there.
16	MR. GALLAGHER: That's correct.
17	MR. GORDON: But you know, concrete, even
18	if it's very well cured and very old, it still has
19	this moisture in it. It's like a very hard sponge
20	with this concrete pour with a high pH pure water. So
21	it really is basically a hard sponge, and it works
22	very successfully with steel.
23	DR. ABDEL-KHALIK: But that would not be
24	the source of the water you're seeing. I mean, you
25	pumped it out and the thing filled up again.
	1

(202) 234-4433

	220
1	MR. RAY: The source of the water was
2	coming through the trough. We paired a void there,
3	and we won't have that source of water.
4	DR. ABDEL-KHALIK: Okay. If you went and
5	looked at it today, it would be full of water again?
6	MR. RAY: We would not expect it. It
7	still had a little moisture in the bottom Trench 5
8	when we started back up. With the operating cycle, we
9	would expect that to evaporate off.
10	MR. SIEBER: Did you find cracks in the
11	concrete?
12	MR. RAY: No, we've done structural
13	monitoring, logged into the concrete, and had no
14	significant cracks. The only void we found was in
15	that trough, and we did verify there was leakage
16	through there with a leak test.
17	MR. POLASKI: Any other questions? Okay.
18	MR. SHACK: It just seems like 40 years of
19	operation to find a trough has a hole in it.
20	MR. POLASKI: Yes.
21	MR. ARMIJO: When the trough was first
22	excavated, was there any data that showed that there
23	was water in the trough when it was first built?
24	MR. GALLAGHER: The trench?
25	MR. ARMIJO: The trench, I mean, yeah, the
	I

(202) 234-4433

	221
1	trench. When that was opened up the first time, did
2	people find that full of water?
3	MR. GALLAGHER: When it was opened up the
4	first time, I don't think there was any water in
5	there, but we did find we did have some information
6	that there was water there at one point, and in
7	subsequent checks it wasn't there. So that's why we
8	thought there was not a water environment in the lower
9	elevation of the drywell, and that's why we hadn't
10	included that as an environment in our LRA.
11	One thing we did though. We said, well,
12	let's look at these trenches again, and that's when we
13	identify this and put it in our corrective action
14	system to update our LRA.
15	MR. ARMIJO: Have you ever experienced
16	recirc water pump seal leak?
17	MR. GALLAGHER: Plant Tom Quintenze.
18	MR. QUINTENZE: I'm Tom Quintenze,
19	AmerGen.
20	The question, I believe, was have you ever
21	experienced recirc pump seal leaks.
22	MR. ARMIJO: Yes.
23	MR. QUINTENZE: And the answer to that is
24	yes.
25	MR. ARMIJO: Would that be the source of

(202) 234-4433

	222
1	this water?
2	MR. QUINTENZE: It could be the source of
3	water. In earlier years we did have some significant
4	leak, but current history indicates that we've
5	maintained our unidentified leak rate, which would be
6	leakage from a recirc pump seal at a very low level,
7	on the order of .1 to .2 gallons per minute.
8	MR. GALLAGHER: We know that we do have
9	equipment leakage, like control rod drives. There's
10	some leakage from them typically. They're right above
11	the sub pile room, you know, right above this room
12	here, and water drips down in all BWRs, and that's the
13	case.
14	As Tom mentioned, there is an unidentified
15	leakage criteria, no more than five gallons a minute
16	unidentified leakage in your primary containment, and
17	you know, we meet the technical specification limits
18	by far. But this is designed to collect that leakage,
19	any leakage like that and then take it away to the
20	sump and then pump it out of containment.
21	MR. ARMIJO: Thank you.
22	MR. SIEBER: Given enough time though,
23	that's a lot of water.
24	MR. GALLAGHER: Yes.
25	MR. POLASKI: All right. We've now heard

(202) 234-4433

	223
1	about the effect of water on carbon steel imbedded in
2	concrete and how we expect minimal corrosion on the
3	imbedded part of the drywell shell. I'd now like to
4	have Mr. Howie Ray present the results of inspections
5	that were performed during October 2006 refueling
6	outage for the imbedded portion of the drywell shell.
7	MR. RAY: Thanks, Fred.
8	During the 2006 refuel outage, visual
9	inspections of the surface of the trenches did show
10	minor corrosion. It was easily removed with no
11	material loss of metal or degradation of the surface,
12	and the visual examinations were done satisfactorily
13	at those surfaces.
14	And as we just discussed, you know, that
15	superficial effect was what you would expect based on
16	the technical (speaking from an unmiked location).
17	The UT measurements taken in trenches were
18	used to compare the total corrosion on the inside and
19	outside between 1986 and 2006. It is known that there
20	was significant corrosion that was ongoing in the
21	exterior surface that was not imbedded up to 1992 when
22	the sand was removed.
23	The material loss identified was
24	consistent with the corrosion rates on the outside of
25	the drywell before the sand was removed in 1992.
	1

(202) 234-4433

So the next slide illustrates the 1986 readings versus the 2006 readings for both Trench 5 This did not include the additional and Trench 17. six inches of surface UTs that we exposed. 4 We'll discuss that later.

What's critical here is there 6 is а 7 difference of 38 mils for both of those trenches, but that we would note that that occurred between the 1986 8 9 and 1992 time frame, before the san was removed, and you had significant corrosion going. 10 So that would not be an unexpected corrosion rate. 11

12 CHAIRMAN MAYNARD: Okay. How do you know that that occurred over that time frame as opposed to 13 14 something that has recently started? It's kind of 15 hard to get a rate.

Well, we're assuming that, but 16 MR. RAY: 17 we know we had significant corrosion going on while 18 the sand was there. We've shown that on the graphs 19 with both of them. Bay 17 and Bay 5 both had 20 significant corrosion rates going on.

21 So if you took that across those years 22 that you had the sand installed with the water, we can 23 assume it. We can't verify that, but you do have 24 still good coating on the outside and you have a 25 technical justification that says that water in this

> **NEAL R. GROSS** COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

3

5

225 1 area would not cause significant corrosion inside the 2 drywell. 3 MR. GALLAGHER: And part of the basis is, 4 when we get to the next slide, when we interrogated 5 the six inches below the concrete floor, the corrosion rate -- Howie, why don't you go into that and you can 6 7 show him that -- the corrosion rate which is really 8 over the entire period of time since that shell was 9 imbedded in concrete. 10 MR. ARMIJO: Before you qo, did you find water to the same extent in Trench 17 as you did in 11 Trench 5? 12 No, we did not. The Trench 17 13 MR. RAY: 14 is about six inches shallower than the trench in Bay 5. 15 16 MR. GALLAGHER: So it's a higher 17 elevation. There was a little moisture in there, 18 but --19 ARMIJO: If there had been water MR. 20 there, it would have drained to a lower level? 21 MR. GALLAGHER: Yes. 22 MR. RAY: It was seeking its elevation. 23 It was voiced in Bay 17, but there's no standing 24 water. 25 DR. ABDEL-KHALIK: The statement that was

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	226
1	made earlier that the water from both the inside and
2	outside surface of the imbedded region is not
3	conducive to corrosion.
4	MR. POLASKI: That's correct.
5	DR. ABDEL-KHALIK: And that statement is
6	presumably applicable prior to 1992.
7	MR. POLASKI: That's correct.
8	DR. ABDEL-KHALIK: So how can you say that
9	38 mils of corrosion had occurred between 1986 and
10	1992? How are these two statements consistent?
11	MR. POLASKI: Between 1986 and 1992 there
12	was still sand in the sand bed region and there was
13	corrosion ongoing on the exterior of
14	MR. RAY: These are not imbedded. This is
15	actually in the above the floor.
16	DR. ABDEL-KHALIK: Yes, I understand, but
17	the statement was made that the leachate from the sand
18	region, the water that came out of that, which
19	presumably is the same as the water on the outside
20	surface of the imbedded region, is not conducive to
21	corrosion.
22	MR. GALLAGHER: For clarity, let's go to
23	Slide 51, which is the trench cross-section, and so
24	somebody can point with a pointer, but basically what
25	we're saying is you can see the curbs at the top here,
	1

(202) 234-4433

	227
1	the lower curb and the upper curb. So one side is
2	imbedded in concrete, on the interior. On the
3	exterior it is not in the sand bed region. So these
4	measurements that we're talking about here are in the
5	trench, which goes from, say, the sand bed floor, you
6	know, up to, I guess, where the lower curb is So
7	DR. ABDEL-KHALIK: So they're in opposite
8	below the sand bed
9	MR. GALLAGHER: Not below the sand bed
10	floor, right. So when the exterior side of that
11	Fred, point to that that's where the sand was. So
12	it corroded on the exterior side of that.
13	DR. ABDEL-KHALIK: Thank you.
14	MR. GALLAGHER: And then what we did is go
15	further down there in that six inches right there to
16	get concrete on both sides, to see what it looked like
17	on both sides.
18	And Howie is going to talk about that
19	next.
20	MR. RAY: Thank you.
21	So what we did do in Bay 5, we did
22	excavate an additional six inches of shell surface in
23	the bottom of the trench in Bay 5. That did give us
24	an area that was previously imbedded on both sides,
25	which now would give us some good data that would
	1

(202) 234-4433

	228
1	validate what you're trying to say.
2	We measure an average thickness of that
3	additional surface. It was 1,113 mils as compared to
4	a nominal of 1,154 mils, which would have been the
5	initial installed thickness in 1966. If you took that
6	time frame, that 41 mils relates to about a mil per
7	year, which is fairly insignificant. It would still
8	be bounded by anything that we have, you know, that
9	we're monitoring above.
10	There are 106 individual UT measurements
11	made from the exterior of the sand bed region. They
12	are baseline for monitoring corrosion of the interior
13	inbedded surface of the drywell for future outages,
14	and we basically believe that the coating on the
15	exterior shell remains in good condition, and the
16	changes are only expected at wetted surfaces inside
17	the drywell which would occur during refuel outages.
18	The joint sealant between the sand bed
19	floor and the exterior drywell shell was inspected and
20	found to be in good condition. No water was
21	identified in any of the sand bed regions. All ten
22	bays were inspected.
23	That's it for the imbedded. Back to John
24	for conclusions.
25	MR. O'ROURKE: Slide 127.
	1

(202) 234-4433

	229
1	To summarize our conclusions on the
2	imbedded shell, we discussed the ultrasonic
3	measurement data that demonstrates that corrosion on
4	the imbedded surfaces of the drywell shell, both
5	interior and exterior, is not significant, and we
6	discussed the environment of imbedded steel in
7	concrete and how it prevents significant corrosion.
8	We also demonstrated that if there is any
9	ongoing corrosion, it is estimated to be less than one
10	mil per year. And at less than one mil per year, the
11	drywell shell meets code thickness requirements with
12	margin through the period of extended operation.
13	MR. SHACK: You lost 41 mils. When did
14	you make the trench? We estimate there was no water
15	when you cut the trench, right?
16	MR. POLASKI: It was in 1986.
17	MR. SHACK: 1986, okay. So
18	MR. O'ROURKE: Well, the 41 mils though is
19	the portion that we newly excavated in the 2006 outage
20	that had been previously imbedded on both sides since
21	1966 when the
22	MR. SHACK: I'm trying to figure out how
23	long it was submerged in water though. In 1986 it
24	wasn't. So it's something less than
25	MR. POLASKI: Well, in 1986 there was no

(202) 234-4433

	230
1	standing water found in the sump or in the trench.
2	MR. O'ROURKE: Slide 128.
3	Our aging management program going forward
4	includes repeating the ultrasonic measurements in both
5	trenches, including the newly excavated six inches in
6	2008, and if those results indicate no significant
7	changes, we plan to fill the trenches with concrete
8	and restore the curb to its original configuration,
9	and we will repeat the ultrasonic measurements at the
10	106 external points in 2008, performing ultrasonic
11	measurements in two bays every refuel outage starting
12	in 2010 with all bays inspected every ten years.
13	Fred.
14	MR. POLASKI: Thank you, John.
15	Any other questions on the imbedded
16	portion of the drawing?
17	What we'd like to do now
18	CHAIRMAN MAYNARD: Excuse me. I think I
19	heard a question over here.
20	MR. POLASKI: Okay.
21	DR. ABDEL-KHALIK: If you were to actually
22	restore the curb to the original configuration, you
23	would have no way of knowing whether additional water
24	is seeping in the gap between the bottom and sperical
25	surface of the shell and the concrete.

(202) 234-4433

	231
1	MR. O'ROURKE: That is correct, but by
2	restoring the concrete to its original configuration,
3	we will re-put that passivating layer back in place.
4	So we will be protected as the rest of the imbedded
5	shell is currently protected.
6	DR. ABDEL-KHALIK: But you wouldn't know
7	that the state or whether or not there is any water
8	below the surface of where you're at now.
9	MR. O'ROURKE: That's correct. However,
10	our corrective actions that we implemented during this
11	outage intended to prevent any water from getting into
12	the space between the shell and the concrete, included
13	not only fixing the trough, but also the caulk that I
14	mentioned that was applied to the concrete shell
15	interface on the inside of the drywell to prevent any
16	leakage, potential leakage, down the shell from
17	getting into that area.
18	MR. SIEBER: And if it did, you would not
19	care, right?
20	MR. POLASKI: That's correct. If you
21	remember Mr. Gordon's presentation was that that
22	passive layer was formed with the concrete was poured.
23	Any water that would get in there because of being
24	with the concrete would have a high pH, was
25	nonaggressive, wouldn't impact that passive layer, and
	1

(202) 234-4433

	232
1	that passive layer will prevent any further corrosion
2	of the imbedded steel.
3	MR. ARMIJO: But that water really
4	shouldn't be there.
5	MR. O'ROURKE: And our current actions are
6	attempting to minimize that water from getting in
7	there.
8	MR. GALLAGHER: On thing for clarity. You
9	know, it's not that there's no monitoring even when we
10	fill these trenches back up because what we talked
11	about is the 106 points. The reason why we talked
12	about them in this section is because it does provide
13	some monitoring in the area behind the curb. So,
14	again, if you looked at the overall graph, the data
15	that's in your handout, a lot of the individual points
16	are behind the curb, and so we are monitoring, you
17	know, that area.
18	DR. ABDEL-KHALIK: What is the volume of
19	your sump?
20	MR. GALLAGHER: The sump volume? Tom,
21	anybody, the volume of the sump?
22	MR. RAY: I could guess. Do you remember,
23	Tom?
24	MR. POLASKI: Or do you remember what the
25	physical size of it is?
	1

	233
1	MR. QUINTENZE: Tom Quintenze, AmerGen.
2	I would estimate that the volume of the
3	sump is approximately 500 gallons.
4	DR. ABDEL-KHALIK: So at an unidentified
5	leak rate of five gallons per minute, you can actually
6	fill the sump in 100 minutes, correct?
7	MR. GALLAGHER: Right.
8	DR. ABDEL-KHALIK: So it is quite possible
9	that you can fill the sump and you will have water
10	standing on the floor, on the concrete floor.
11	MR. GALLAGHER: No, the sump is pumped
12	out.
13	DR. ABDEL-KHALIK: Is pumped out?
14	MR. GALLAGHER: Yes.
15	DR. ABDEL-KHALIK: At what
16	MR. GALLAGHER: Well, it's an automatic
17	pump.
18	MR. SIEBER: Now, any time you put drips
19	and drains onto the floor, you're going to find water
20	on the floor. I mean, some people are more careful
21	about how they pipe the drips and drains away, but
22	apparently yours just go to the floor, right?
23	MR. GALLAGHER: Yeah, the collection
24	system is the floor.
25	MR. SIEBER: I got it.
1	I

(202) 234-4433

	234
1	MR. POLASKI: Any other questions on the
2	imbedded section?
3	What we'd like to do now is there were
4	some questions we were asked this morning. We got
5	some answers and new information. So Mike Gallagher
6	has got some information about the conditions for the
7	analysis.
8	MR. GALLAGHER: Just a couple of final
9	questions. I think, Dr. Wallis, they were mostly from
10	you. The one on the two pound external pressure, yes,
11	physically that's not possible for the refueling
12	condition for the hatches are open. It is an accident
13	condition. The torus reactor building vacuum breakers
14	would limit the pressure inside the containment to
15	less than a negative two pounds, you know. So that's
16	why that two pounds was put in place, to envelope that
17	in the analysis.
18	DR. WALLIS: Maximum possible.
19	MR. GALLAGHER: Yes.
20	DR. WALLIS: Okay.
21	MR. GALLAGHER: And then the other
22	question was about the elevation 74.6 about flooding
23	up containment. In a DBA analysis, it does not go
24	anywhere near that high. It's really just for severe
25	accident management procedures. You could flood; if
	I contract of the second se

(202) 234-4433

	235
1	you don't have your ECCS and things like that, you
2	could flood up behind the top of the
3	DR. WALLIS: But to the vents.
4	MR. GALLAGHER: add the fuel, and then
5	not to
6	DR. WALLIS: So it's the maximum possible?
7	MR. GALLAGHER: It's the maximum possible.
8	And then the third question you had was
9	about how much rust did we measure, and Pete Tamburro
10	has the answer to that.
11	MR. TAMBURRO: The answer to that is
12	CHAIRMAN MAYNARD: Microphone, please.
13	MR. TAMBURRO: Thank you.
14	This is Pete Tamburro speaking.
15	We did not do a complete 100 percent
16	characterization of the rust. We did go into some of
17	the worst bays and look at a 12 by 12 inch area. The
18	thickness of the corrosion byproduct was an inch and
19	a quarter to an inch and a half in thickness.
20	DR. WALLIS: Inch and a half of rust?
21	MR. TAMBURRO: Yes, sir.
22	And we then did a calculation to determine
23	if that amount of rust was consistent with how much
24	material we had lost. The calculation showed that it
25	was consistent.
	I

(202) 234-4433

	236
1	We then took that corrosion byproduct and
2	sent it to our labs for further analysis.
3	DR. WALLIS: So you didn't do an
4	integrated measurement of how many truckloads of rust
5	you took away.
6	MR. TAMBURRO: No, sir.
7	DR. WALLIS: No. Okay.
8	CHAIRMAN MAYNARD: But you know it has got
9	to be a lot.
10	DR. WALLIS: Yeah.
11	DR. ABDEL-KHALIK: I have a follow-up
12	question. Is the status of the sump pump or the sump
13	level monitored in the control room?
14	MR. POLASKI: Yes, it is. There's
15	surveillance tests the operators perform when it's
16	pumped out, and they put it out to measure the leakage
17	and how much water is going into the sump.
18	CHAIRMAN MAYNARD: Isn't that one of the
19	input to your leak rate calculations?
20	MR. POLASKI: Well, that is the primary
21	for unidentified leakages, is the pump-out.
22	DR. ABDEL-KHALIK: Okay. Thank you.
23	MR. POLASKI: If there are no other
24	questions, we'll now go on to the final part of our
25	presentation on the upper drywell shell. We have

(202) 234-4433

presented information so far on both the sand bed and the imbedded regions of the drywell shell and why the drywell shell meets the code required thickness in these areas. The upper region as we define it in this presentation are those elevations of the drywell above the sand bed region.

7 Extensive ET measurements of the drywell 8 shell thickness have been performed in the upper 9 regions of the drywell shell. Corrosions in the upper 10 regions have been much less than in the sand bed 11 region, and there is more margin to code design 12 thickness requirements.

The UT thickness measurements are taken 13 14 and analyzed using the same methods as were previously 15 discussed by Mr. Tamburro for the sand bed region. We provided you with information and details from the 16 upper drywell shell in the package that we provided in 17 Because much of that information is the 18 December. 19 same as we have already present, we will be focusing 20 our presentation on the current condition in the upper 21 drywell shell and results of the 2006 refueling outage 22 inspection.

This will be a brief summary so we can answer any questions you may have. Mr. O'Rourke will be making this presentation.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	238
1	MR. O'ROURKE: Thanks, Fred.
2	This part of the presentation will discuss
3	the upper drywell area and will support the following
4	conclusions.
5	First, the areas we are monitoring are the
6	lead indicators of corrosion on the outside of the
7	shell. Recall from Fred's previous discussion if
8	water gets past the seal leakage trough, this is the
9	area of the shell that would be wetted first, and this
10	area does not have an epoxy coating as the sand bed
11	region. It was coated with a red lead primer only,
12	and I will show you the ultrasonic inspection data for
13	this area.
14	Our next conclusions are that the
15	corrosion of the upper shell is less than one mil per
16	year and upper drywell shell has a minimum of 137 mils
17	of margin, which is 25 percent of the minimum required
18	thickness of 541 mils. And we will discuss the
19	ultrasonic measurement data and trend graphs that
20	support this conclusion, all of which supports the
21	overall conclusion that based on current corrosion
22	rate, we had margin through the period of extended
23	operation.
24	DR. WALLIS: Now, this leakage by the
25	upper shell is presumably not everywhere. It's just
	1

(202) 234-4433

	239
1	in certain places, isn't it? I get the idea that the
2	rivulets run down rather than the stream that runs
3	down over the whole upper shell when there's a leak.
4	So you'd expect corrosion just in certain places where
5	these rivulets are?
6	MR. POLASKI: Today we don't expect any
7	leakage to get on
8	DR. WALLIS: No, but I just wonder how you
9	sample when you've got this very non-homogeneous
10	corrosion pattern.
11	MR. GALLAGHER: Yes, and I think John is
12	going to get into that next and who you where our
13	finished locations are.
14	DR. WALLIS: And down at the bottom where
15	you've got sand to sort of distribute the water, it's
16	different from at the top where you've got streams if
17	any is coming down in certain places.
18	MR. O'ROURKE: Right, and because of that,
19	starting in 1983
20	CHAIRMAN MAYNARD: Let's take just a
21	moment here.
22	There went an eardrum, I think. Are you
23	okay now?
24	All right. Let's try to resume.
25	MR. O'ROURKE: Thank you.

(202) 234-4433

So starting in 1983 over 1,000 ultrasonic measurements were taken around the circumference of the drywell at three elevations to locate those areas of corrosion on the external surface of the drywell shell.

addition, 6 Τn а random sampling of 7 additional locations in the upper drywell were measured to insure that the thinnest locations had 8 been identified. Thirteen grid locations have been 9 10 selected for ongoing monitoring.

DR. WALLIS: Do we have a picture of the pattern of those 1,000 measurements somewhere? MR. GALLAGHER: In the package of

14 information we sent in on December 8th, there were 15 some drawings in there from the clickable links and so 16 that there was the original drawings that we had that 17 information.

CHAIRMAN MAYNARD: Let's go ahead.

MR. O'ROURKE: Concluding with this slide, these locations are measured every other refueling outage, which is our ongoing aging management program for this area.

The next is planned view of the drywell, and what it does show here are the 13 locations that we monitor every other outage.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

18

	241
1	MR. GALLAGHER: But I think to get to Dr.
2	Wallis' original question, so you can see we
3	identified where the thinnest occasions were, and
4	yeah, they aren't like randomly they're not evenly
5	distributed throughout the drywell.
6	CHAIRMAN MAYNARD: Based on the original
7	of the thousands that you took before.
8	MR. GALLAGHER: Go around each area and
9	interrogate it.
10	DR. ABDEL-KHALIK: Now, this last outage
11	you identified another location at the 71 foot, six
12	inch elevation. Is that going to be added to this
13	collection of locations to be monitored?
14	MR. POLASKI: The measurements we did at
15	the 71.6 foot were at the transition from the knuckle
16	region to the thin above that. We did it in this
17	outage. We've got the next outage. We're taking
18	readings at four locations around the circumference of
19	the elevation. We did two on this outage, two the
20	next outage, and then four years later we're going to
21	repeat those to determine whether there's any
22	corrosion occurring in those areas or not. It says in
23	the future and beyond will depend on what we find
24	during these two sets of readings.
25	MR. O'ROURKE: So to summarize what Fred
	1

(202) 234-4433

	242
1	just said, we're going to take readings in those
2	locations twice, four years apart in the same
3	occasions.
4	CHAIRMAN MAYNARD: And I take it these are
5	included in your aging management program and your
6	commitments.
7	MR. O'ROURKE: Yes.
8	MR. GALLAGHER: Yes, they're commitments.
9	MR. O'ROURKE: Yes, they are.
10	MR. GALLAGHER: The comment is that if
11	they weren't bounded, we would continue, and that's
12	what John had said.
13	MR. O'ROURKE: Right. On Slide 133, this
14	slide and the next slide will show the ultrasonic
15	measurement data for the upper drywell. The third
16	column from the left shows the minimum required
17	thickness of 541 mils.
18	The next column show the actual
19	measurements taken between 1987 and 2006, and note
20	that in some columns there are multiple numbers.
21	These indicate separate readings taken in the same
22	year.
23	MR. ARMIJO: What was the nominal
24	thickness of the steel?
25	MR. O'ROURKE: Six, forty.

	243
1	MR. ARMIJO: No, no. It would have to be
2	higher.
3	DR. WALLIS: That's too much. It's more
4	than that.
5	MR. O'ROURKE: Oh, I'm sorry.
6	MR. GALLAGHER: We have a
7	MR. O'ROURKE: The way we define the upper
8	drywell shell, it's made up of several thicknesses of
9	plates. The 640 is the very upper cylindrical region.
10	MR. GALLAGHER: Yes, the summary that we
11	had kicked off at the beginning was on page 14. So it
12	shows what the nominals are, you know, for the
13	cylinder, which is 640, the upper sphere is 722.
14	MR. ARMIJO: There's no measurements for
15	what would correspond to Bay 19. Is there a reason
16	for that?
17	MR. GALLAGHER: Bay 19?
18	MR. ARMIJO: I mean, they all eventually
19	correspond to one of these bays in some way, don't
20	they?
21	I'm just trying to see if, you know, we
22	had in the sand bed region a lot of corrosion in Bay
23	19. Is there any correlation with the corrosion at
24	the higher elevation?
25	MR. POLASKI: We will let Mr. Tamburro
1	I contraction of the second

(202) 234-4433

respond to that.
MR. TAMBURRO: This is Pete Tamburro.
No, when we did the initial investigation
at the upper elevations with thousands of readings, we
did not find representative thin areas in Bay 19.
DR. WALLIS: It's Bay 13 that looks the
worst?
MR. TAMBURRO: Bay 13 looks the worst at
the upper elevations. So there's no direct
correlation between the worst areas and the sand bed
and the finished areas.
DR. WALLIS: It's all strange, all
strange. You'd expect the water runs down in one
place the worst.
CHAIRMAN MAYNARD: Apparently not.
MR. O'ROURKE: Continuing on Slide 133,
the final column to the right shows our projected
thicknesses in 2029, and you can note that most of the
locations show no ongoing corrosion.
The trend graphs, trend graphical
representations of this data are in your reference
books. So we do not show those in this presentation.
Slide 134 continues with the remainder of
the data for the locations that were monitored.
Slide 135 summarizes the previous two

(202) 234-4433

	245
1	slides, and as you saw, we have 12 of 13 locations
2	that show no statistically observable corrosion. The
3	location with a minimum margin, that is, the 137 mils,
4	has no ongoing corrosion, and we have one location
5	with a very low corrosion rate of 0.66 mils per year
6	with a projected thickness in 2029 of 720 mils
7	compared to a minimum required thickness of 541 mils.
8	Again, in summary, we discussed the
9	initial inspections followed by random sampling that
10	identified the areas of corrosion that are the lead
11	indicators of corrosion on the outside of the upper
12	drywell shell. The ultrasonic measurements indicate
13	no ongoing corrosion except at one location which is
14	less than one mil per year, giving the upper drywell
15	shell a minimum of 137 mils of margin, which is 25
16	percent of the minimum required thickness of 541 mils
17	and overall based on current corrosion rates, the
18	upper drywell shell will have margin through the
19	period of extended operation.
20	MR. POLASKI: Thank you, John.
21	That concludes our presentation on the
22	upper drywell shell. If there's no questions on that,
23	I'd like to summarize with our overall conclusions.
24	First, the corrective actions to mitigate
25	drywell shell corrosion have been effective.
	I

(202) 234-4433

(202) 234-4433

	246
1	Second, the drywell shell corrosion has
2	been arrested in the sand bed region and continues to
3	be very low on the upper drywell elevations.
4	Third, the corrosion on the imbedded
5	portion of the drywell shell is not significant.
6	Fourth, the drywell shell meets code
7	safety margins.
8	And finally, we have an effective aging
9	management program in place to insure continued safe
10	operation of the risk free drywell.
11	CHAIRMAN MAYNARD: At this point I'd like
12	to go back to the question Dr. Bonaca brought up a
13	little earlier, and that's relative to the leakage.
14	I know it's your position that the leakage is low
15	enough. It's manageable and will be diverted away.
16	I guess I'd like to have a little bit better
17	understanding of what it would take.
18	What are you doing to try to eliminate
19	water through the cracks, the small cracks in the
20	liner and stuff there?
21	MR. GALLAGHER: Yeah, I mean, the main
22	thing we're doing is the metallic tape and the
23	strippable coating. So, you know, we would continue
24	to look at improvements in that, better materials and
25	that type of thing. You know, we had already
l	1

(202) 234-4433

	247
1	attempted welding, and we don't think that's a right
2	repair. We had not looked at should we do an entire
3	replacement just because we can control what we have.
4	DR. BONACA: Well, one of the reasons why
5	I asked that question is that, you know, that
б	statement is made that one GMP leakage is
7	insignificant. Well, I mean, it may be insignificant,
8	but there are some operators that actually instrument
9	the drains, the alarm if there is any water coming
10	down, the painstaking action taken to prevent leakage.
11	Now, in all of the actions you have
12	described to us at this meeting and previously, all
13	you're doing is try to minimize the consequences of
14	water coming down, which is inconsistent with the GALL
15	approach to this issue, I mean, for the long run.
16	So that's why I was asking that question
17	because I sense that and I have no idea what the
18	cost will be but I don't think the cost will be,
19	but I don't think the cost will be so much more than
20	the money you're spending to do this kind of problem.
21	I mean, you've gone through a tremendous amount of
22	effort, and inspections also are costly, and I have no
23	appreciation for what the relative cost would be.
24	MR. GALLAGHER: We certainly haven't
25	evaluated that part of it. We could take a look at
	1

(202) 234-4433

	248
1	that. You know, the way we thought we were being
2	consistent with GALL was to have an aging management
3	program on the shell itself. So that's what we had.
4	That's what our aging management program is on, but I
5	understand your point.
6	DR. BONACA: Well, if I remember, I mean,
7	in GALL, you know, a key issue as a management program
8	is to prevent leakage, to monitor the bellows, and to
9	monitor the steels, and the intent and typically it
10	doesn't talk about the liner because it's not usual
11	that you have liner with cracks, and so that's
12	probably the reason why GALL doesn't speak about that.
13	But anyway, that's the question I had.
14	MR. GALLAGHER: Okay. We understand.
15	CHAIRMAN MAYNARD: Does anybody else have
16	any questions here for right now?
17	Okay. Thank you very much.
18	Our agenda next calls for a break, but
19	since we had a late lunch, I think what I'd like to do
20	is to go ahead with the first part of the staff's
21	presentation and maybe get through the Region 1
22	inspection part.
23	MR. ASHLEY: Can I have about two minutes
24	to set up?
25	CHAIRMAN MAYNARD: Okay. Very good.
	1

(202) 234-4433

	249
1	(Whereupon, the foregoing matter went off
2	the record at 2:14 p.m. and went back on
3	the record at 2:19 p.m.)
4	CHAIRMAN MAYNARD: All right. If everyone
5	will take their seats, I think we're ready to resume.
6	Mr. Ashley, whenever you're ready.
7	MR. ASHLEY: Thank you, Dr. Maynard.
8	My name is Donnie Ashley. I'm the project
9	manager for the Oyster Creek license renewal
10	application, and I will be doing the run through for
11	the committee this afternoon.
12	With us today we have Rich Conte, Mike
13	Modes, and Tim O'Hara, who are going to discuss the
14	NRC inspections during the fall of 2006. Hans Ashar
15	and I will discuss the status of the open items in the
16	licensee commitment from the last SER. And Hans Ashar
17	and Jason Petti from Sandia National Labs will take up
18	probably most of our agenda to discuss the Sandia
19	analysis. And then Jim Davis is going to take just a
20	couple of minutes to bring you back the answer that
21	you had on questioned socketed welds.
22	So with that, if we could, I'd like to
23	turn it over to Rich Conte.
24	MR. CONTE: Good afternoon. I'm Richard
25	Conte. I'm Chief of the Engineering Branch, number
I	1

(202) 234-4433

	250
1	one, in Region 1. I was the team manager for the 13th
2	inspection in 2006 of Oyster Creek.
3	With me I have Tim O'Hara, one of the team
4	members, who is an ISI specialist, and also I have
5	with me another specialist, Michael Modes. Michael
6	was an advisory member. He was off on another
7	project, but he was also the team leader for the
8	license renewal inspection earlier in 2006.
9	In the next three slides what I'd like to
10	briefly do is summarize the scope and results of the
11	fall outage. Yesterday we issued the report number
12	13. We have extra copies here on the table, and it is
13	publicly available as of today.
14	Prior to the outage, the NRC staff had
15	scheduled inspections for the outage, and in
16	particular, we noted that there were certain license
17	renewal commitments that the licensee or AmerGen was
18	going to perform. Most of the focus for us at least
19	was on the in service inspection, visual examination
20	of the drywell in the torus area.
21	The inspection also assessed an emergent
22	issue with the water in the trenches that came up.
23	The review is a multiple week inspection
24	with the assistance of experts not only in the Region
25	1 staff, but also NRR staff.
	1

(202) 234-4433

	251
1	The State of New Jersey representatives
2	also observed a number of activities, including
3	internal NRC staff conference calls during the course
4	of the inspection.
5	DR. WALLIS: Are you going to describe the
б	visual inspection results?
7	MR. CONTE: Yes.
8	DR. WALLIS: I mean separately. Okay.
9	I'll wait for that then.
10	MR. CONTE: Can I have Slide No. 4?
11	Basically the inspection looked at the
12	ultrasonic measurements and visual test results and
13	the related evaluations by AmerGen. We also observed
14	the epoxy coating in three of the ten bays. Two were
15	entered by Tim O'Hara and one was entered by the
16	senior resident, Marc Ferdas, who was also a member of
17	the team.
18	And when you went into the bays, you could
19	also see adjacent bays. So I would say about 40 or 50
20	percent of the area was reviewed.
21	And of course, we reviewed all of the
22	visual VT results that AmerGen documented on their
23	records.
24	We also reviewed AmerGen's efforts to
25	identify and mitigate the sources of water which
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433
252 1 accumulated in the trenches that were previously dug 2 out for the UT measurements on the drywell shell, and 3 we also reviewed the potential impact on structural 4 integrity on the concrete drywell floor and the 5 potential conditions in the imbedded portion of the drywell shell, and we insured that the repairs had no 6 7 impact on the design and licensing basis for 8 operations. 9 More specifically, at this point let's go on to Slide No. 4 or 5. 10 We verified that all of the ultrasonic 11 results, ultrasonic test measurements or results met 12 the calculated minimum code required thicknesses for 13 14 the area. 15 DR. WALLIS: As calculated by Sandia or by 16 whom? 17 MR. CONTE: These were calculated by This is based on their test records. 18 AmerGen. 19 DR. WALLIS: These are based on the minimum code required thickness as calculated by 20 21 AmerGen. 22 AmerGen's calculated. MR. CONTE: We 23 basically were in the field verifying the proper 24 implementation of their program. 25 We also found no adverse conditions with

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	253
1	respect to the epoxy coating on the outside of the
2	DR. WALLIS: Would you tell me about that
3	because I look at these pictures that you've seen, I'm
4	sure. There are sort of yellow and orange regions.
5	Is this an optical illusion, but in fact they really
6	looked white everywhere or did it have yellow
7	splotches on it?
8	MR. CONTE: I will let Tim O'Hara address
9	that, Doctor.
10	MR. O'HARA: We observed AmerGen
11	performing the visual inspections. The specification
12	or procedure that they used had criteria as to what
13	was to be reported. As part of the data sheets they
14	reported what they saw, what the inspector saw, and
15	they attached a picture to each one.
16	So the areas that we didn't physically
17	look at ourselves, we looked at their data sheets.
18	DR. WALLIS: But you did look at some,
19	physically looked at them.
20	MR. O'HARA: Yes, we looked at I looked
21	at
22	DR. WALLIS: And did they have these sorts
23	of yellow areas or they just looked white everywhere?
24	MR. O'HARA: They looked basically gray or
25	white.
	I contract of the second se

(202) 234-4433

	254
1	DR. WALLIS: Gray or what everywhere.
2	MR. O'HARA: The epoxy is more gray than
3	white.
4	DR. WALLIS: Did you touch these
5	protrusions and see if they were soft in any way?
6	MR. O'HARA: I did not.
7	MR. CONTE: Continuing with this
8	particular slide, we found no adverse conditions with
9	the repairs in and around the trough near the bottom
10	of the reactor vessel, and we also found acceptable
11	the structural integrity evaluations that AmerGen
12	developed.
13	Can I have Slide No. 6?
14	Overall we thought that AmerGen had a
15	technical basis for sufficient justification to
16	restart the unit. We found no safety significant
17	conditions with respect to primary containment
18	prohibiting restart, and there was reasonable
19	assurance that primary containment prohibited restart
20	and there was reasonable assurance that primary
21	containment is capable of performing its design
22	function throughout the next operating cycle.
23	With that I'd like to ask if there's any
24	questions.
25	DR. BONACA: The epoxy you just looked at,

(202) 234-4433

	255
1	the inspection is just visual.
2	MR. O'HARA: Yes.
3	DR. BONACA: And there was no I mean,
4	I was following up with the question of Dr. Wallis.
5	MR. O'HARA: I didn't memorize the
6	inspection criteria, but it was basically evaluate the
7	surface, look for any blistering, cracking, peeling or
8	anything like that, and report any of those conditions
9	throughout the specific entire area of that bay, and
10	that's what the inspector did.
11	DR. WALLIS: It's a bit hard to tell
12	blisters from the protrusions because it's a very
13	rough surface, isn't it?
14	MR. O'HARA: I don't think it would be.
15	I mean, if you saw blistering, you'd see
16	irregularities in even the rough surface, my opinion.
17	CHAIRMAN MAYNARD: Did you verify the
18	credentials of the inspectors, verify that the AmerGen
19	folks performing the inspections were qualified for
20	the inspection?
21	MR. O'HARA: We sampled both in the UT and
22	the VT qualification area to make sure that the folks
23	were qualified. We didn't check everyone.
24	CHAIRMAN MAYNARD: Okay.
25	DR. ABDEL-KHALIK: Your conclusions
	1

(202) 234-4433

	256
1	pertain only to the end of the upcoming operating
2	cycle. They do not go beyond that; is that correct?
3	MR. CONTE: That's correct. We're relying
4	on the current evaluation that will evaluate for the
5	period and the extended operations.
6	Are there any other questions on our
7	inspection?
8	MR. ARMIJO: What was your basis for
9	saying that the water in the trenches had no adverse
10	impact on structural integrity?
11	And then the second part is you mentioned
12	or reported this tracer dye testing to try and find
13	the source of that water.
14	MR. CONTE: That's correct.
15	MR. ARMIJO: Did you get any results? Did
16	you find out anything?
17	MR. CONTE: There were some flaws, and if
18	you remember, the 106 drawing from AmerGen or the
19	slide had the trough and the sump underneath it and
20	the trench. And when they did a good visual
21	inspection of that trough, they found imperfections,
22	including a bottle. We, at least AmerGen suspects
23	that it was probably new construction.
24	When they did do this dye penetrant, they
25	put the dye penetrant in the trough, and eventually
	I contraction of the second

(202) 234-4433

after a day or so the dye penetrant did who up in the trench, Bay 5, which is the one at the higher elevation.

4 That kind of confirmed that the water is 5 at least coming from the trench, but they couldn't rule out that water is also dripping down the sides of 6 7 the drywell from the CRD area going on the concrete floor and also going out to the trenches also. 8 At this point we believe they caught most of that water 9 They took the bottle 10 that was bypassing the sump. out, made repairs, and they did do a level test on the 11 12 trough to make sure that there wasn't any reduction in the level. So when they unplugged it to the sump, the 13 14 water was properly draining to a sump.

15 The basis for why there as no adverse impact is basically on the science that you heard, 16 that our expert in the region gave us basically the 17 same position that the water and concrete and steel 18 19 environment is a high pH and highly likely even 20 putting a protective coating on the drywell of that 21 area. 22 MR. ARMIJO: Thank you. 23 Are there any other questions MR. CONTE: 24 on the inspection? 25 I'm curious. DR. WALLIS: Maybe you're

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

1

2

3

(202) 234-4433

257

	258
1	not the right person. All of this thing here talkinga
2	bout high pH, how do they ever get a low pH in the
3	sand bed region to cause all of that corrosion?
4	MR. MODES: You're right. It's not the
5	right people.
6	MR. ARMIJO: There isn't a source of
7	DR. WALLIS: There's no source of acidity,
8	is there?
9	MR. ARMIJO: basic salt. Once the
10	corrosion occurs
11	CHAIRMAN MAYNARD: Sam, will you talk into
12	the microphone?
13	MR. ARMIJO: Well, I just think it's a
14	different environment.
15	DR. WALLIS: You think it's neutral water,
16	which is adequate to do it.
17	MR. ARMIJO: Yeah. It comes in as neutral
18	water and then it's in protection here.
19	DR. WALLIS: Okay.
20	DR. ABDEL-KHALIK: Is there any source of
21	biological growth between the bottom of the drywell
22	and the surface of the concrete in the imbedded
23	region?
24	MR. CONTE: I couldn't answer that
25	question right now. No one has seen that area. You'd

```
(202) 234-4433
```

	259
1	have to core bore in that area.
2	DR. ABDEL-KHALIK: Just by looking at the
3	small area that was excavated.
4	MR. CONTE: Well, you observed the
5	trenches.
6	MR. O'HARA: I didn't see any evidence,
7	you know, from looking at what I looked at.
8	MR. CONTE: And he did look at the
9	trenches inside.
10	DR. ABDEL-KHALIK: If there were
11	biological growth in areas that you could not see,
12	would that change the water chemistry and make it more
13	conducive to corrosion?
14	MR. MODES: You're barking up the flow
15	accelerated corrosion tree here.
16	DR. ABDEL-KHALIK: No, no, no, no, no.
17	MR. MODES: With a microbiological
18	accelerated corrosion environment, that's basically
19	what I'm saying, and the answer is obviously yes. If
20	it were present, it would change the chemistry, as it
21	does in flow assisted or accelerated, depending on the
22	political whim, accelerated or assisted corrosion,
23	yeah, absolutely.
24	MR. SIEBER: It would be rare in
25	containment.

(202) 234-4433

	260
1	MR. MODES: It would be extremely rare.
2	MR. DAVIS: This is Jim Davis from the
3	staff.
4	The way they made that containment was a
5	shell was built first and it was sitting right by the
6	ocean for several years, and then it was not cleaned
7	off, and the concrete was put around it. So that was
8	not very uncorrosive water that was down there in the
9	sand bed region.
10	DR. WALLIS: And it could be biological
11	spores coming in, too.
12	MR. DAVIS: There could be, but I believe
13	they checked, and they didn't find any evidence of
14	MIC.
15	MR. ASHLEY: Dr. Maynard, I think that's
16	it for this portion. I would ask Mr. Modes, Conte,
17	and Mr. O'Hara to stay with us in case you have
18	additional questions.
19	CHAIRMAN MAYNARD: Okay. I think what I'd
20	like to do right now is we'll take a break and then
21	we'll come back and do your open item status and then
22	go into Dr. Asher.
23	We'll take a 15 minute break. We'll come
24	back at 15 till.
25	(Whereupon, the foregoing matter went off
I	1

(202) 234-4433

	261
1	the record at 2:33 p.m. and went back on
2	the record at 2:47 p.m.)
3	CHAIRMAN MAYNARD: All right. Let's go
4	ahead and resume the meeting.
5	MR. ASHLEY: Thank you, Dr. Maynard.
6	As we identified in the original safety
7	evaluation report with open items that was issued in
8	August of this year, we had five open items
9	specifically related to the drywell. Some of those
10	items were originally identified in the audit report
11	that was conducted by Dr. Chang's team that did the
12	audits for those.
13	They were directly related to the work
14	that Mr. Ashar was doing in Section 4.7. So we put
15	all of the open items in the one section, but they
16	were identified throughout the evaluation, not just in
17	the TLAA.
18	The first open item on drywell corrosion
19	sampling in the transition area. The second had to do
20	with corrosion in the imbedded areas of the concrete.
21	Buckling analysis, the drywell shell thickness, and
22	the minimum available thickness margins, and also
23	questions on protective coatings.
24	As the applicant identified in their
25	presentation, the same areas that we were looking at
I	1

(202) 234-4433

	262
1	in their subsequent actions.
2	Following the inspections and the audits
3	that were conducted and in discussions with the
4	application, they made several new commitments that
5	were added to their aging management programs, and
6	those were identified in our SER that was published in
7	December 2006.
8	I won't read these to you, but I'll just
9	give you highlights from those new drywell
10	commitments. These commitments did not replace
11	commitments. They were additive in nature. They
12	increased the sample size in the transition area
13	originally. They had committed to doing one sample
14	during their inspections, and they have increased that
15	number to four.
16	They've also, as they discussed, talkinga
17	bout taking additional UT measurements in the drywell
18	during the 2008 outage, and also on the locally
19	thinned areas identified during the 2006 outage.
20	Then again in 2010 they had committed to
21	doing the UT thickness measurements on the outside of
22	the drywell in
23	DR. WALLIS: This sounds like more than
24	they mentioned in their presentation or have I got it
25	wrong.

(202) 234-4433

	263
1	MR. ASHLEY: No, sir. I think it's
2	exactly the same.
3	DR. WALLIS: It's supplementary to one.
4	MR. ASHLEY: Yes, sir.
5	DR. WALLIS: Okay.
6	MR. ASHLEY: They've also agreed and
7	committed to visual inspection of the drywell shell
8	inside the trenches. That was the last presentation
9	the applicant did in Bay 5 and Bay 17, and to repeat
10	those again in 2008.
11	They also have committed to performing
12	visual inspection of the moisture barrier between the
13	drywell shell and the concrete floor.
14	MR. SIEBER: Do you believe that if the
15	licensee performs these additional commitments along
16	with their other program that that represents an
17	adequate surveillance to assure containment integrity?
18	MR. ASHLEY: Yes, sir, we do.
19	MR. SIEBER: Okay. Thank you.
20	DR. WALLIS: Is there some basis for that
21	rationale? Is there some rationale for that
22	statement?
23	MR. ASHLEY: The ten elements that were
24	described in their aging management program meet the
25	requirements of the GALL.

(202) 234-4433

	264
1	DR. WALLIS: So you go back to GALL.
2	MR. ASHLEY: Yes, sir.
3	DR. WALLIS: There's no attempt to sort of
4	look at what's the risk that if they only look at a
5	few bays that they will miss something in the critical
6	period of time? There's no assessment of that?
7	MR. ASHLEY: It appears to us in the
8	information that the applicant has provided to us that
9	they've made a good effort to identify those areas
10	that need to be evaluated and that they're using
11	proper methods for identifying issues or addressing
12	the issues as they come up and putting it in the
13	corrective action program, which is the expectations
14	for the program.
15	MR. SIEBER: It actually seems to me that
16	what is important is the rate of corrosion or rate of
17	degradation. So I would think that if any of these
18	every other cycle examinations shows an increase in
19	corrosion rate or reduction in margin, that that would
20	constitute a basis for a reexamination of the whole
21	program to re-determine what the correct frequency of
22	inspection should be.
23	MR. ASHLEY: Yes, sir. Should they go
24	into a period of extended operations, that would
25	become their current licensing basis.
	I

(202) 234-4433

	265
1	MR. SIEBER: Right.
2	MR. ASHLEY: And part of that expectation
3	is for the applicant to make sure that their programs
4	get evaluated and they feed back into their programs
5	lessons that they're learning as they go through the
6	program and manage it with the corrective action
7	program. It's part of their license basis.
8	MR. SIEBER: See, right now the rate of
9	corrosion for the last few years has been pretty close
10	to zero, which provides some technical basis for the
11	frequency that they have established.
12	On the other hand, should that change for
13	any reason, that would prompt a reexamination of that
14	commitment, in my opinion.
15	MR. ASHLEY: Yes, sir, and as you look
16	through the commitments that have been made, they've
17	agreed to do those things as well.
18	MR. SIEBER: Okay. Thank you.
19	MR. ASHLEY: Yes, sir.
20	CHAIRMAN MAYNARD: Any other questions on
21	the open items?
22	MR. ASHLEY: If not, sir, I'd like to
23	introduce Hans Raj Ashar from HRR and Jason Petti, who
24	are going to discuss the structural integrity analysis
25	of the degraded drywell containment.
	I contract of the second se

(202) 234-4433

	266
1	Ashar.
2	MR. ASHAR: Can you hear me? Here. Plug
3	in this one. I want to make sure they can hear me.
4	I'm Hans Ashar with the Division of
5	Engineering in NRR. I'm not saying what branch I
6	belong to because the branches are changing every day.
7	The first thing I want to point out, the
8	intent of this analysis. Our intent of this study was
9	to assess the ability of the containment shell to
10	withstand the postulated loads.
11	Now, in doing so, we did look at the GE
12	analysis that was done in '92-'93 time frame, and you
13	heard something about it from Dr. Mehta and the
14	applicant. But took our own part as part of the
15	analysis methodology, and we did develop sampling and
16	everything else. We did different than what they had
17	done at that time.
18	We used 360 degree model of drywell to
19	study the special variation of that degradation.
20	Stress and stability analysis is a drive for as
21	designed and degraded shell conditions for postulated
22	loads.
23	So we tried to do both, first baseline
24	with undegraded shell, and then the degraded shell.
25	I will show you degraded shell picture a little later.
	1

(202) 234-4433

	267
1	DR. WALLIS: You say "we" did it. This is
2	Sandia.
3	MR. ASHAR: Sandia National Lab and NRC
4	together because NRC is the one who funded the study,
5	and what we wanted, we wanted to have Sandia know
6	about it so they can conduct particular analysis, you
7	know.
8	Now, I want to give you a little
9	background why I show Sandia National Lab, and I
10	requested my management to have this study done at
11	Sandia National Lab.
12	Now, I was quite aware of earlier studies
13	that Sandia had done on degraded containments in
14	general, and that was meant for the severe accident
15	studies and mainly for what is the effect of seven
16	degradations in PWR and BWR on capacity of those
17	containments.
18	Those studies were done in two negative
19	force. It was dug up in negative force. I was
20	heavily involved in that particular effort at that
21	time, but when I heard about the type of serious
22	degradation that we have seen in this particular
23	plant, I felt that we've got to do some kind of
24	confirmatory analysis to see that, hey, this degraded
25	containment or degraded drywell shell can withstand

(202) 234-4433

	268
1	those postulated loadings for which it is designed.
2	That was the main purpose of doing it, and
3	Sandia was chosen because of their experience, earlier
4	experience. They had the core ready for
5	implementation. So they used that core that they had
6	already developed before.
7	We did use wall thinning used to model
8	degradation. So what we did was, again, we divided
9	the spherical portion into ten bays just like what you
10	saw earlier, but instead of being one shell thickness
11	to all the bays, what we did was we took the average
12	of all the readings that we knew about from the UT
13	measurements, and we said with the average of those
14	things we are going to assign to each bay.
15	And each bay had their own radar
16	(phonetic) different from each other because most of
17	the serious degradation was in the lower ten percent
18	of the shell, the bay. Okay? So we took those worst
19	conditions that they had given to us on UT
20	measurements and we averaged them out and spread it to
21	the one bay.
22	We took the same from another bay, and we
23	studied to the other bays.
24	In addition to that distribution, we
25	included two slices, thin slices of strips (phonetic)
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

Í	269
1	into the model to see the inclusion of buckling due to
2	the cleanest area. We did not consider any statistic
3	research. We are going to take the longest result in
4	that particular bay and what was that? Point,
5	seventy, .76, .68 inches or whatever it was, we used
6	it in a slice of two and a half feet by one and a half
7	feet, and we put them into the model.
8	MR. ARMIJO: That was just an arbitrary
9	area selection, the two and a half
10	MR. ASHAR: It was arbitrary.
11	MR. PETTI: No, the UT measurements we
12	used were from in the sand bed region. They were from
13	one specific UT measurements in 1993 documented by GPU
14	Nuclear. Those readings were taken from the exterior,
15	I believe, before the coating was applied, after it
16	was clean, but then before the coating was applied.
17	I believe that that was the case.
18	In that case there was in two bays below
19	the vent line. In Bay 1 and Bay 13 there were these
20	patches of clustering of very low points that are able
21	to sort of carve out, and I believe in Bay 1 the
22	description in the document of the UT measurements, it
23	did give some approximate dimensions of the region
24	that was thinner than the surrounding, and that's what
25	that basis was for Bay 1.
	1

(202) 234-4433

	270
1	In the Bay 13, there were no specific
2	dimensions given. So I carried that over, the same
3	dimensions as Bay 1, just to kind of have the same
4	basic shape as I did in Bay 1.
5	MR. ASHAR: Yeah, this is general layout.
6	Now you know very well the use. So I'm not going to
7	spend too much time on this. Let's go to the next
8	one.
9	Yeah, this shows the various parts of the
10	drywell. Now I think you are quite familiar with
11	this, too.
12	This I think I should spend some time with
13	this.
14	DR. WALLIS: How many nodes did you have
15	or mesh
16	MR. PETTI: I believe the elements was
17	about a quarter of a million elements in the
18	DR. WALLIS: And they were denser in the
19	regions of interest.
20	MR. PETTI: The two local areas where we
21	had the thinnest spot under Bay 1 and Bay 13, they
22	were thinner. They were about one inch nominal
23	element size and about four inches throughout the rest
24	of the containment.
25	MR. ASHAR: Sandia, there are a number of
1	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	271
1	things that we put together. Develop appearances that
2	define an element model, baseline model and degraded
3	model, two models for there.
4	Degraded model, data came from the UT that
5	we knew about in 1993, and UT had other containment
6	issues, also are integrated into the degraded model.
7	LOCA formation and three LOCA formations
8	were analyzed here: accident, which is LOCA plus
9	temperature; temperature, pressure and seismic. All
10	three are in this one.
11	Post accident that you heard about, this
12	one totals one of the worst loading combinations for
13	the shell. So we tried to use that as one of the
14	refueling lowering, which happens to be critical for
15	the buckling of the shell point of view.
16	So these are three LOCA formations
17	considering the analysis. This stress analysis,
18	stability analysis, they
19	DR. WALLIS: Stability analysis, how was
20	that done?
21	MR. PETTI: That was the buckling
22	analysis.
23	MR. ASHAR: It is the buckling analysis.
24	MR. PETTI: It's the same as the
25	DR. WALLIS: Was this done by the finite

(202) 234-4433

	272
1	element analysis predicting a growing instability or
2	is it done by some kind of ASME factors?
3	MR. PETTI: A combination of the two. The
4	same finite element model that was used for the stress
5	analysis is used for the IGAN value (phonetic)
6	buckling analysis, but the numbers that come out of
7	that then need to be fed into the ASME N-284
8	procedures where there are the factors that are
9	applied to it, to the numbers you get out of the
10	computational analysis.
11	DR. WALLIS: And you're able to identify
12	the worst mode?
13	MR. PETTI: Correct. The analysis gives
14	the first mode.
15	MR. SHACK: Yeah, what did your worst mode
16	look like?
17	MR. PETTI: There's a slide near the back.
18	DR. WALLIS: It's a suspense item.
19	MR. ASHAR: Jump back to the stress, the
20	stress slide.
21	MR. PETTI: It's down here near the
22	bottom, that little black area there, near this bottom
23	picture where it says refueling buckling, right here.
24	MR. ARMIJO: Is that right under a vent?
25	MR. PETTI: No, it's between the two vent
	I

(202) 234-4433

	273
1	lines.
2	PARTICIPANT: You have the LOCA buckling
3	in the thin region there.
4	MR. PETTI: Well, actually we didn't send
5	from each, the typical bays. We went from center of
6	line to a bay to a center of line of bay. So the
7	region between the center of the vent line to the
8	center of the vent line had a uniform thickness
9	assigned to it. Plus you can see this real little
10	dark area that's where there's extra refinement, where
11	there was one of those local thinned areas as well.
12	So the first buckling we saw in the
13	analysis was in between the two bays that was just
14	adjacent to one of those thinned areas.
15	DR. WALLIS: There wasn't something that
16	repeated itself every 36 degrees
17	MR. PETTI: No, not on the lowest mode.
18	As you get up higher in modes they become a bit more
19	complex.
20	DR. WALLIS: So you weren't as artificial
21	as GE with their pie.
22	MR. PETTI: Correct.
23	DR. WALLIS: Of course, they had this
24	boundary condition that forced them to have some
25	MR. PETTI: Right. At least for the

(202) 234-4433

274
degraded case, we had the same type of behavior.
MR. ASHAR: We did this one. (Speaking
from unmiked location.)
MR. JUNGE: Hans, could you turn up the
mic? Is there a volume on that?
MR. ASHAR: Can you hear?
CHAIRMAN MAYNARD: I think when he turns
away from it, his voice
MR. ASHAR: Oh, okay.
MR. JUNGE: You're going to have to look
straight at it because when you turn your head away
from the mic
MR. ASHAR: Okay. Can you hear me now?
Okay.
CHAIRMAN MAYNARD: Turn your chair more.
MR. ASHAR: This are is shown as buckling.
It's a factor of safety here, for example, is 2.15.
PARTICIPANT: Three, point, eight, five.
MR. ASHAR: Three, point, eight, five?
PARTICIPANT: Yes, you said 2.15.
MR. ASHAR: Yes, 3.85. I'm sorry.
MR. SHACK: Two is required.
MR. ASHAR: Two is required. Three,
point, eight, five is what from the analysis. That's
for the undegraded case. These are 2.15; two is

```
(202) 234-4433
```

	275
1	required; 2.15.
2	Stress-wise, the stresses are computed
3	this way. We call it a stress ratio, but it's an
4	analysis test which we got from the analysis, divided
5	by the
6	DR. WALLIS: Can I ask you about that? On
7	page 54 you have these red numbers which would appear
8	to be bigger than the allowable stress.
9	MR. ASHAR: On the report, yes.
10	DR. WALLIS: Very little was said about
11	them in the report.
12	MR. PETTI: Which table number are you
13	specifically
14	DR. WALLIS: Well, any table. Each table
15	has a red
16	MR. PETTI: Right. The accident load
17	case.
18	DR. WALLIS: It would appear to exceed the
19	allowable stress. Is that
20	MR. PETTI: Right. The red numbers, the
21	one red number in Table 3-5, the way that we did the
22	stress assessment was the one stress limit was 29 KSI.
23	The general membrane stress was 29 KSI ASME limit. So
24	when I was assessing the results of the analysis, I
25	would go through and in each region, main region of

(202) 234-4433

	276
1	the drywell, I would pick out the maximum stress from
2	the analysis. If that then exceeded the 29, I would
3	go back into the analysis and look deeper into where
4	that stress was.
5	In the one case, in Table 3-5 in the upper
6	sphere, that happened to be at the junction between
7	two plates of differing thicknesses, which then
8	becomes an ASME code, a gross structural discontinuity
9	which has a higher limit.
10	So I just highlighted it in red to show
11	that I had
12	DR. WALLIS: Which is okay when you apply
13	the ASME.
14	MR. PETTI: Right, the ASME. In the other
15	cases where you're down at the lower sphere, in Tables
16	3-5 and I believe in 3-6, where you have a secondary
17	stress due to the thermal loading from the accident
18	condition, where we increased the temperature of the
19	shell from 70 degrees Fahrenheit to 292 degrees per
20	the load case, you do get these very large bending
21	stresses at the junction where the shell emerges from
22	the
23	DR. WALLIS: Are those the ones in
24	parentheses?
25	MR. PETTI: Those are the percentages. If

(202) 234-4433

	277
1	you applied the limits on the column on the right
2	DR. WALLIS: I remember.
3	MR. PETTI: but in the ASME code it
4	does state that for the accident load condition, which
5	is service level C, that there are no official checks
б	on those stresses.
7	DR. WALLIS: So which is 168 percent?
8	That seems like a large number.
9	MR. PETTI: Right. That's if you were
10	checking with that number, but if you do assess the
11	ASME code due to that thermal loading, it's not
12	required to be assessed in the code.
13	DR. WALLIS: So it's okay?
14	MR. PETTI: Yeah, based on the
15	interpretation.
16	MR. ASHAR: Under Level C currently it's
17	okay because the secondary effects of temperature are
18	not being considered.
19	DR. WALLIS: But they're real, aren't
20	they?
21	MR. ASHAR: Please?
22	DR. WALLIS: They exist.
23	MR. ASHAR: Not necessarily. ASME comes
24	out with this secondary stress kind of designation.
25	MR. HESSHEIMER: I'd like to just maybe
	1

(202) 234-4433

	278
1	offer a comment on the analysis. When those
2	CHAIRMAN MAYNARD: Could you identify
3	yourself, please?
4	MR. HESSHEIMER: Oh, I'm sorry. I'm Mike
5	Hessheimer from Sandia National Labs. I supervised
6	the work that Jason did on the analysis of the
7	structure. I'm also a member of the ASME boiler and
8	pressure vessel code committees.
9	The analysis that's done according to the
10	code uses the elastic analysis methods. There's no
11	relief due to plastic deformation. So the code
12	recognizes that there are local areas where local
13	yielding will occur and relieve the stresses, which is
14	why that's allowed for secondary stresses where there
15	are gross discontinuities. There are no stress limits
16	specified because the stresses that are calculated in
17	an elastic analysis are unrealistically high because
18	they don't allow local yielding of the material.
19	If we had done an inelastic analysis,
20	which normally is not done for design programs, those
21	stresses, you would have reached the yield limit in
22	those areas. You would have had plastic deformations,
23	and the stresses would have been self-limiting.
24	DR. WALLIS: That's allowed in the code?
25	MR. HESSHEIMER: It is allowed in the
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	279
1	code.
2	DR. WALLIS: Well, when I see the 168
3	percent of ASME limit, am I to be concerned?
4	MR. HESSHEIMER: I'm sorry?
5	DR. WALLIS: I should not be concerned
6	when I see that?
7	MR. HESSHEIMER: Based on an elastic
8	analysis that's correct. You should not be concerned
9	for secondary stress.
10	DR. WALLIS: But suppose it were 200
11	percent. How big does it have to be before I get
12	worried?
13	MR. HESSHEIMER: There are no strain
14	limits defined in the ASME code.
15	DR. WALLIS: Does plastic give foams
16	forever?
17	MR. HESSHEIMER: Essentially that's the
18	assumption inherent in the code. Now, you could argue
19	with the code committee, but that is
20	DR. WALLIS: What's the difference between
21	plastic deformation and a failure?
22	MR. HESSHEIMER: But you can get a lot of
23	plastic deformation and relieve the stresses in that
24	area. It's a result of performing an elastic analysis
25	in areas where local yielding can occur, and it's
	I contract of the second se

(202) 234-4433

	280
1	recognized by the code.
2	I guess I would want to make one point
3	about that, is that those high stresses occur both in
4	the analysis of the undegraded vessel and the degraded
5	vessel.
6	DR. WALLIS: Yes, I noticed that.
7	MR. HESSHEIMER: The effect of the
8	degradation does not cause much of a change there.
9	It's more of a function of how the analysis is done
10	and the local boundary conditions in that area. So
11	the code does recognize that at those levels when you
12	are using only elastic analysis methods, you will get
13	stresses that exceed
14	DR. WALLIS: But how do you decide when
15	those stresses are too big?
16	MR. HESSHEIMER: There probably should be
17	some strain limits that need to be evaluated, but I
18	think this is one of those things I think is just
19	and I don't want to speak on behalf of the entire code
20	committee but it's recognized as a practice that
21	works. There have not been problems with it.
22	DR. WALLIS: Well, I'm very puzzled
23	because suppose all the entries in this table were
24	red. Then it would still be okay?
25	MR. HESSHEIMER: No, because not all of

(202) 234-4433

	281
1	them are secondary stresses.
2	DR. WALLIS: How do I know which?
3	MR. SHACK: But, again, the idea is that
4	you can't get big plastic deformations unless the
5	primary stresses are clad.
6	DR. WALLIS: Yes, right, right.
7	MR. SHACK: You get very localized plastic
8	deformations in the secondary, and so
9	DR. WALLIS: Right, but it just says
10	primary plus secondary. There's no separation of the
11	two in the table. So I don't quite know what
12	MR. PETTI: The previous table has just
13	the primary. So Table 3-5 is just the primary
14	stresses.
15	DR. WALLIS: So you compare 3-5 with 3-6.
16	MR. PETTI: Correct, and that shows you
17	what the addition is to get the secondary stresses.
18	DR. WALLIS: Okay. So the local funnel
19	distributions, it relaxes uniplasty (phonetic).
20	MR. HESSHEIMER: That's correct.
21	DR. WALLIS: But the overall stressing of
22	the whole thing is okay.
23	MR. HESSHEIMER: That's correct.
24	MR. SHACK: Now, you sort of calculated
25	the buckling here for the best estimate that you've
l	I contract of the second se

(202) 234-4433

	282
1	shown here. Then you sort of go through the minimum
2	thickness study. You end up with a number that seems
3	significantly different than the GE analysis. Are you
4	going to talk about that at all?
5	MR. PETTI: We do have that one plot
6	that's in there that shows the different analyses I
7	ran and the different factors of safety that's kind of
8	in one of the back-up slides we have. We could put
9	that up and discuss that if you want to.
10	MR. SHACK: Yeah, why don't you put that
11	up and discuss it?
12	DR. WALLIS: So you have a different mode
13	of buckling, don't you, really? You have a different
14	shape to the as it begins to distort, it distorts
15	in a different mode from the GE mode. The GE mode is
16	a 36 segment.
17	MR. PETTI: Right.
18	DR. WALLIS: Thirty-six degree segment
19	repeated all the way around.
20	MR. PETTI: Right, right, and since we
21	have the full 360 degree model
22	DR. WALLIS: Well, I'm surprised that you
23	get a different number.
24	MR. PETTI: Correct. The models are
25	different. There are different assumptions.

(202) 234-4433

	283
1	DR. WALLIS: It's not realistic. Yours
2	should be more realistic.
3	MR. PETTI: More realistic in the sense
4	that we do have the full 360 degree model. We did
5	have to take since we didn't have the independent
6	data that GE had when they did their analysis, a lot
7	of the data, and it's documented in the report, was
8	taken directly from their analysis and then had to be
9	modified to fit my model, the new model that was
10	created.
11	So it's not surprising that the numbers
12	are not exact. It would be surprising if they were.
13	DR. ABDEL-KHALIK: But the loading is the
14	same in both analyses.
15	MR. PETTI: The loadings are the same.
16	The only difference was in the seismic loading
17	application. We used the static coefficients from the
18	FSAR, and they had actually based theirs on natural
19	dynamic analyses that we didn't have the data to do
20	that.
21	DR. WALLIS: Is that the same kind of
22	factors that they had? They had a factor of .2, which
23	turned into a factor of .34 when they took account of
24	tension and so on. Did you use that same approach?
25	MR. PETTI: For the refueling load case,
1	1

(202) 234-4433

	284
1	we did not increase the capacity factor. That's why
2	our minimum thickness is showing higher than theirs.
3	DR. WALLIS: Right.
4	MR. PETTI: From our reading of the N-284
5	ASME load case, it states that that is justified when
6	there's internal pressure, and in the refueling case
7	there is no internal pressure. So we did not feel
8	justified in applying that.
9	DR. WALLIS: Would you tell us about that?
10	I don't know the code. Which of these is the
11	appropriate way to proceed? I mean, should you
12	MR. PETTI: There's another slide that we
13	have.
14	MR. SHACK: That then is the fundamental
15	reason you're getting the different answers.
16	MR. PETTI: There are two reasons. One is
17	it's a different model. There's no way to compare
18	directly between ours and GE. That's why we did the
19	baseline analysis where we put the nominal original as
20	designed thicknesses. Our intent was to then compare
21	those to our degraded model to see really the relative
22	difference in the stresses, the relative difference in
23	the factors of safety from the buckling analyses, not
24	so much to compare directly with the GE, even though
25	we know that that will be done. We weren't trying to

(202) 234-4433

	285
1	tie that back.
2	Here is the section from the Article 1500
3	from the N-284 SME load case, which is what we used
4	for the buckling that GE had originally used, and this
5	quote just states that due to internal pressure
6	there's a smoothing of the initial imperfections; that
7	then you could, if justified, if you justify that, you
8	could increase the capacity reduction factor, and they
9	have applied that and GE provided justification. We
10	didn't feel that that was justified based on what we
11	knew of that.
12	MR. SHACK: If you applied that, what
13	would you get for your minimum uniform thickness?
14	MR. PETTI: We didn't do that analysis.
15	MR. SHACK: You didn't do that.
16	DR. WALLIS: Well, it's a big factor.
17	It's a factor of
18	MR. ASHAR: Yeah, 80 percent higher.
19	DR. WALLIS: So you would get a much
20	thinner, an even thinner value than GE if you applied
21	their factor.
22	MR. PETTI: It's possible, but we didn't
23	do that analysis.
24	DR. ABDEL-KHALIK: But based on your
25	interpretation of the code and based on the parametric

(202) 234-4433

	286
1	result that you showed in the graph before, you feel
2	that if a thickness were to drop below .844 inches,
3	the safety factor would decrease below two.
4	MR. PETTI: Uniformly.
5	DR. ABDEL-KHALIK: Yes.
6	MR. PETTI: Uniformly, but we do know from
7	the UT data that it is not uniformly degraded.
8	DR. ABDEL-KHALIK: Right. I understand.
9	MR. PETTI: That's why the first analysis
10	we did we did some spatial variation.
11	DR. ABDEL-KHALIK: I do understand that
12	there are differences between the two analyses, but I
13	want to sort of compare apples to apples between the
14	two analyses, recognizing the differences between the
15	two.
16	MR. PETTI: Sure.
17	DR. ABDEL-KHALIK: So the number that you
18	have here of .844 inches corresponds to the number
19	used in the GE analysis of .736 inches.
20	MR. PETTI: Given the differences and the
21	different assumptions and the different ways we apply
22	the buckling load case, correct.
23	DR. ABDEL-KHALIK: Now, all of the margins
24	reported by the applicant are based on this .736
25	MR. PETTI: Correct.

(202) 234-4433

	287
1	DR. ABDEL-KHALIK: inch uniform
2	thickness number. That minimum thickness is taken to
3	be the value that you calculate of .844. These
4	margins would be considerably lower than what's
5	reported by the applicant.
6	MR. ASHAR: That is correct. I think it
7	will come out about 1.67, something like that, a
8	buckling factor. Close to it. If you bring down the
9	4736
10	CHAIRMAN MAYNARD: You're facing away from
11	your microphone.
12	MR. ASHAR: I'm sorry. I am, yeah. I'm
13	sorry.
14	Jason, the question is regarding how much
15	safety we would have if he used .750.
16	MR. PETTI: Well, we haven't done that
17	analysis. So
18	MR. ASHAR: We haven't done the analysis.
19	That's true.
20	MR. PETTI: we can't make a statement.
21	DR. ABDEL-KHALIK: But if you were to
22	extrapolate that graph, I mean, it seems like a fairly
23	smoothly varying function. You would get down to that
24	safety factor of about 1.5, 1.6 versus two at the .736
25	inch thickness. Is that correct?

(202) 234-4433
	288
1	MR. PETTI: If we had done an analysis at
2	.736, the safety factor would be lower than two. I
3	can't tell you what it would be, but according
4	DR. ABDEL-KHALIK: Well, it's
5	extrapolating your
6	MR. PETTI: It would be lower than two.
7	I can't give you an exact number.
8	DR. ABDEL-KHALIK: You're not willing to
9	extrapolate.
10	MR. PETTI: No, I'm not willing to
11	extrapolate.
12	DR. WALLIS: This is the bottom line of
13	the whole study. You have a number and GE has a
14	number, and GE has used some modified capacity
15	reduction factor which we're not quite sure about.
16	You don't use that. You've got a different number
17	from GE. Who should I believe and what should I use?
18	MR. SHACK: They both predicted the number
19	is greater than two.
20	MR. ARMIJO: Not at 736.
21	MR. SHACK: But on the condition that it
22	is, it's 2.15. Now,
23	MR. ASHAR: Correct.
24	MR. SHACK: the argument here is that
25	you can't go and do this uniform thickness model and
	I

(202) 234-4433

	289
1	you have to do a more realistic calculation.
2	MR. PETTI: You're not giving enough
3	credit to the shell in its current condition by doing
4	the uniform thickness analysis, correct.
5	MR. SHACK: But it is acceptable from your
6	analysis in the condition that it's now in.
7	MR. PETTI: That's for NRC to make that
8	judgment, not me.
9	MR. ASHAR: Yeah, yes.
10	MR. SHACK: At least it meets the code
11	requirement.
12	MR. ASHAR: No, the reason we did not use
13	that increased capacity reduction factor can you
14	hear me all right? was that we did not have the
15	basis for doing it because ASME requires that if we
16	have justification to increase even in the loads under
17	pressure, you can do it. You go through some test
18	data, some kind of verification data. It is correct
19	to do so. We did not use that.
20	Now, if the applicant has those bases with
21	them, we did not have a chance to look at those
22	things. So we don't know about it. So we decided not
23	to use that.
24	DR. WALLIS: So you make your decision
25	MR. ASHAR: But still, but in spite of
	1

(202) 234-4433

	290
1	that, we did come out with a factor of safety for the
2	existing conditions.
3	DR. WALLIS: So you're making your
4	decision based on the Sandia analysis.
5	MR. ASHAR: Sandia.
6	DR. WALLIS: Which is your analysis, not
7	on the
8	MR. ASHAR: No, I want you to I want to
9	rephrase myself. We are not basing everything on
10	Sandia. This is one part in total judgment on our
11	part
12	DR. WALLIS: But the basic decision should
13	be based on what the applicant submits.
14	MR. ASHAR: The applicant submits
15	applicant's commitment for programmatic
16	DR. WALLIS: You base your decision on
17	what the applicant submits and then you do
18	confirmatory work.
19	MR. ASHAR: Confirmatory, right, exactly.
20	DR. WALLIS: And if it turns out that this
21	modified capacity reduction factor was misapplied in
22	some way, that might change your conclusion?
23	MR. ASHAR: I would say it would not
24	change your conclusion because still under existing
25	conditions it does satisfy the buckling factor.
	1

```
(202) 234-4433
```

	291
1	DR. WALLIS: If they can't use the
2	circumferential stress in the way that they did.
3	MR. ASHAR: Yeah, you see, that's the
4	reason we don't want to use hard and fast number from
5	Sandia analysis.
6	MR. DUDLEY: This is Noel Dudley, project
7	manager for license renewal.
8	What the process is is that we reviewed
9	the license renewal application. We asked questions
10	on the information in the license renewal application,
11	had responses. We had an open item, and we gathered
12	more commitment or different commitments from the
13	licensee and closed out the open item.
14	At that point the staff had made a
15	decision that the commitments were satisfactory for
16	maintaining public health and safety.
17	DR. WALLIS: I'm trying to determine if
18	you understand the ASME method and these modified
19	capacity reduction factors because surely part of your
20	decision has to be made based on what is submitted by
21	the applicant.
22	I don't understand that. Does somebody
23	here really understand these modified capacity
24	reduction factors.
25	MR. DUDLEY: And I don't think it's
1	1

(202) 234-4433

	292
1	necessary.
2	DR. WALLIS: It's not necessary?
3	MR. DUDLEY: It's not necessary because
4	there are commitments to do UTs every two years.
5	DR. WALLIS: But how do we know it's safe
6	now?
7	MR. DUDLEY: Because it met regulatory
8	requirements.
9	DR. WALLIS: How did it meet regulatory
10	requirements?
11	MR. DUDLEY: It was within the code.
12	DR. WALLIS: The code is based on this
13	modified capacity reduction factor, which we need to
14	understand, right?
15	MR. SHACK: Yeah, as I understand it, the
16	current Oyster Creek analysis is a claim to be a
17	bounding analysis with the minimum thickness of 736,
18	and that's acceptable if you accept that it's a
19	bounding analysis. They haven't attempted to do an
20	analysis of the current configuration.
21	DR. WALLIS: But their analysis is based
22	on this modified capacity reduction factor, which we
23	have to understand, I think. Somebody has to
24	understand it.
25	DR. ABDEL-KHALIK: Lets say you backtrack
	I

(202) 234-4433

and you haven't done the Sandia calculation yet, and 2 you're basing your decision on the applicant's 3 analysis. And you look at the analysis and you ask 4 your experts and they say, no, the ASME code does not allow this capacity reduction factor to be modified in this case because there is no internal pressure under 6 this loading condition.

And if that is the case, that would have 8 9 changed the safety factor from two to 1.27. What 10 would have been your response with regard to а communication for additional information from the 11 12 applicant?

I think that if we do have a 13 MS. LUND: 14 situation where and this does happen with _ _ 15 applications that we do receive where, you know, we have some questions about the conclusions or the data 16 or something that they've provided -- we would have to 17 look at the assumptions that were made. 18

19 But I think what Hans had done in this 20 case is to look at trying to evaluate it, and of 21 course, you're saying that if we didn't have the 22 Sandia report, but I think that it was part and parcel 23 of trying to look at what had been done and make sure. 24 I think one of the recognitions as well is 25 that the GE study that was done, it was an old study.

> **NEAL R. GROSS** COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

5

7

	294
1	Okay? There were limitations to doing it in a slice.
2	We did not try to just go through and do exactly the
3	same thing that GE had done just to confirm the
4	numbers for that. I think we were trying to do
5	something that at least in Hans' and Jason's mind was
6	more representative of what they needed to look at.
7	So I think that as far as the staff goes,
8	you know, that's the type of analysis, that's the kind
9	of thought process we tend to go through no matter
10	whether it's this or something else.
11	In addition to that, I think that the
12	point has been made both in the GE study and also in
13	this study, too, that the way it was modeled, you
14	know, the real situation I think you have to
15	remember that the real situation is not a uniformly
16	thinned shell. The real situation isn't the same as
17	modeled for both of them because I think that both of
18	them were trying to be modeled in a conservative
19	manner.
20	DR. WALLIS: The issue is what is the
21	decision going to be based on, and the Sandia model
22	may be fine, but it's NRC work. You base the
23	licensing decision on work done by NRC or by what's
24	submitted by the applicant?
25	And if the applicant's work has this

(202) 234-4433

(202) 234-4433

295 1 uncertainty about it and you're not quite sure that 2 it's appropriate to apply this modified reduction 3 factor, then maybe the GE work is not a basis for a 4 decision. 5 MS. LUND: Right. Then okay for you to make a 6 DR. WALLIS: 7 decision based on your work. I'm not quite sure. Ι think I'm always being told that it's up to the 8 9 applicant to submit a case. 10 DR. ABDEL-KHALIK: If I may expand on this, what in your view is the analysis of record? 11 12 The applicant's is the analysis MS. LUND: of record. 13 14 DR. ABDEL-KHALIK: Now, if the analysis of record is deficient, what would be your response? 15 LUND: Well, I think that the 16 MS. 17 discussion that has gone on here today has been there is a probably a difference of approach as far as 18 19 whether or not to consider this factor. I'm not sure 20 that we've decided that the applicant's study is 21 deficient in that particular manner. 22 CHAIRMAN MAYNARD: I think we've talked 23 I'm not sure we're going to get any better about. 24 answer. What I would propose is that this be a 25 specific agenda item for the full committee meeting

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

296 because I do think it needs to be better addressed 1 2 probably by the licensee in defending their 3 calculation and also by the NRC on what the acceptance 4 is. 5 So I would propose that we have this as an agenda item for that. I do think it's an important 6 7 issue and needs to be clarified. I don't think we're 8 going to get any further today. 9 MR. GALLAGHER: Mr. Chairman, it's Mike Gallagher, AmerGen. 10 I just wanted to make sure it was clear. 11 12 So we did specifically talk about this capacity factor reduction methodology. That's what Dr. Mehta was 13 14 talking about, that we consulted with the code case 15 That's the issue that we went through, and center. 16 the internal pressure was one way, but you know, there 17 were other ways where the hoop stresses could be distributed and it was appropriate. 18 19 MR. SHACK: Code interpretation then. 20 Dr. Mehta, can you come up MR. GALLAGHER: 21 and answer that question? 22 DR. MEHTA: Mehta with (unintelligible). 23 When we were doing this analysis, we 24 talked to Dr. Clarence Miller of Chicago Bridge and 25 Iron who is the author of the code case 284, and also

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	297
1	at the time when we did the analysis, the revision was
2	going on on 284, Revision 1.
3	And when we used this approach, we first
4	actually consulted him, and then we said, well, we
5	want to use this kind of approach and explained to him
6	how we were going to do that, and he wrote a technical
7	report that he agrees with this approach.
8	and so essentially our conclusion was that
9	the author who wrote this code case 284, if he agrees
10	with this approach, which would seem reasonable, and
11	our own technical justification was in effect the
12	internal pressure would not do much to straighten out
13	any imperfections. It's the internal pressure as it
14	manifests itself in tension which will pool these
15	imperfections and make them a little more straight,
16	thereby the reduction factor will be a little bit
17	lower.
18	And so that was our own technical
19	justification within ourselves, and then Dr. Clarence
20	Miller agreed, and he said that he agrees with this
21	interpretation.
22	MR. GALLAGHER: And just one other point
23	of clarity. So that was part of the original analysis
24	that was done in 1992 and is the current licensing
25	basis that was reviewed by the staff earlier. So, you
	1

(202) 234-4433

	298
1	know, it was reviewed by the staff.
2	CHAIRMAN MAYNARD: Well, again, I
3	appreciate your comments. I do think it would still
4	be a good agenda item for the full committee meeting,
5	give both the licensee and the staff a chance to
6	revisit this and make sure they're still consistent.
7	MR. ARMIJO: I just want to ask a question
8	for clarity. Did you use the internal pressure to
9	generate these capacity factors, reductions for the
10	refueling case when there no internal pressure.
11	MR. GALLAGHER: Dr. Har Mehta can explain
12	that.
13	DR. MEHTA: The question, whether the
14	refueling condition case we use
15	MR. ARMIJO: Yes. Can you use that?
16	DR. MEHTA: Yes, we used that.
17	MR. ARMIJO: And why?
18	MR. GALLAGHER: No, he said since there is
19	no internal pressure during refueling, what do we use
20	to justify the capacity reduction factor.
21	DR. MEHTA: We looked at the average of
22	the section in the sand bed region and determined what
23	is the circumferential tensile stress, and subsequent
24	to this code case and 284, Dr. Miller wrote a WRC
25	running research council bulletin 406 in which he had
	1

(202) 234-4433

	299
1	a procedure where from the circumferential tension he
2	calculates the coolant pressure and then puts into the
3	equation to raise the capacity factor.
4	MR. GALLAGHER: Right. So pressure is one
5	way. There's other stress. Other stresses command
6	DR. WALLIS: Well, I understand that
7	Sandia did not use the capacity reduction factor.
8	MR. PETTI: Right. As you can see in the
9	quote there it says justification can be provided. So
10	we just didn't have any justification to apply that,
11	and our
12	DR. WALLIS: But there is no internal
13	pressure really.
14	MR. PETTI: Correct.
15	DR. WALLIS: It's just sort of a surrogate
16	stress.
17	MR. PETTI: Correct. It's a matter of the
18	interpretation of the language there, and we
19	DR. WALLIS: Plus there must be some
20	physics behind this sort of thing.
21	MR. PETTI: did not have any other
22	documentation.
23	DR. WALLIS: There must be some real
24	physics which says if you have a circumferential
25	stress you can do something with it, not this

(202) 234-4433

	300
1	inventing an unreal pressure.
2	MR. PETTI: But that's why we did have
3	justification to do it. That's why we didn't apply
4	it. If they have justification, we weren't that
5	was not made available to us. So we didn't feel we
6	were justified in applying it.
7	MR. GALLAGHER: And Chairman Maynard, we
8	can definitely talk about it at the full committee if
9	you'd like. I just wanted to make sure it was clear
10	that this capacity factor reduction we did talk
11	specifically about and the justification was with the
12	author of the code case. So I just wanted to make
13	sure that was clear.
14	CHAIRMAN MAYNARD: And I acknowledge you
15	did discuss it and you did provide that information.
16	I think for the NRC staff probably more so than for
17	you, but part of this now becomes a legal question as
18	to what is the analysis of record. What can you and
19	can you not take credit for?
20	And I think it's probably more of
21	questions for the staff. I think it would be good for
22	the licensee to re-address that again back at the full
23	committee meeting, but for the staff to take a look.
24	MR. GALLAGHER: Okay. I understand.
25	Thank you.
1	

(202) 234-4433

DR. ABDEL-KHALIK: This opinion was sought and obtained in 1992 when the analysis was done, and perhaps it would be prudent for the applicant to seek an interpretation of the current interpretation of the ASME code.

CHAIRMAN MAYNARD: Sometimes there's a 6 7 difference between an opinion and official approval 8 letters. So, again, I think that both the applicant 9 and the NRC staff need to revisit this and come back and 10 to full committee meeting address the acceptability of it. 11

12 Yes, sir, and if I might add, MR. ASHLEY: from the safety valuation report standpoint, 13 the 14 commitments that the applicant has made to us is that 15 when they do these next outages and when they do these next testing, they will inform us of the results of 16 17 those tests, and if there is anything that we felt like would put them below the margin by their 18 19 definition or by this definition, we would take 20 appropriate action at that point, but it would be 21 monitored and it's not just to put the report out and 22 then be done with it because we felt like the 23 commitments that the applicant made we'll monitor 24 that.

CHAIRMAN MAYNARD: I want to make sure I

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

1

2

3

4

5

302
understand what I think I heard you say, is that when
you're informed of the results that if they were below
what the Sandia calculation is, you would be made
aware of that.
MR. ASHLEY: If they were different from
the numbers they got on this outage, any difference at
all, they would evaluate.
MR. SHACK: Yeah, I mean, I think if you
see significant thinning, you would have to come back
and look at it again because unless you accept this,
you can't accept the bounding analysis. Therefore you
have to analyze the as is case, which apparently has
been done.
DR. WALLIS: The question is will it
buckle now. That's the real question.
MR. SIEBER: Doesn't it stand to reason
that if you can't accept some analysis now, then you
can't draw a conclusion from today's data?
DR. WALLIS: So what's the basis for
drawing the conclusion?
MR. SIEBER: That's right.
DR. WALLIS: From any data.
MR. ARMIJO: Well, if you can't use the
Sandia analysis for drawing a conclusion, why are we
even talking about it? That's nonsense.

(202) 234-4433

CHAIRMAN MAYNARD: But from what I understand, both analyses show that it's okay today with a safety factor of two. So it really gets into what is the real margin there. Is it the licensee's calculation or is it the Sandia calculation, which could impact what the future inspections and stuff might have to be looking for.

Both of them showed that today it was okay.

Right, and I think that the 10 MR. ARMIJO: 11 GE calculations made in what, 1989-1990, used the 736 12 number when, in realty the number is much, much higher based on measurements in 2006. So in any future 13 14 discussion we should be talking with the realistic 15 dimensions of this containment because I think we're 16 just not using the margins which we've measured and 17 then using margins which you can argue whether they're They come from stress or pressure or 18 valid or not. 19 something else. So I think we should just update that 20 GE study to using current values might solve the 21 problem. Right. 22 This is P.T. Cu. MR. CU:

I just want to make a comment that we understand the members' concern, and I guess we don't have the ready answer to you. We'll come back to you.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

3

4

5

6

7

8

9

	304
1	CHAIRMAN MAYNARD: I do think it would be
2	best to address it at the next meeting and have
3	everybody a chance to be thinking, talking some
4	factual versus what they think may be the case.
5	MR. ASHLEY: Did you have anything
б	additional?
7	MR. ASHAR: This is the last slide. It
8	may be amazing or confusing.
9	MR. SHACK: It's hard to say we're not
10	counting on the same studies.
11	MR. ASHAR: We are, but to understand,
12	it's a three prong approach in decision making from a
13	regulatory point of view. The numbers are not
14	something that strictly we're going to adhere to. It
15	is the programmatic thing that we are working together
16	with because we knew that the real difference between
17	what they've done in 1993 and what we are doing right
18	now. So we expect the differences.
19	Now, this difference is a little critical.
20	I agree with you, and we have to come to some kind of
21	determination as to which way to go.
22	DR. WALLIS: Well, the Sandia study is
23	much more realistic than the GE one.
24	MR. ARMIJO: It's a modern analysis.
25	DR. WALLIS: It's 360 degrees, puts in

(202) 234-4433

	305
1	different thicknesses in different bays, and so on.
2	Now, the question is whether you can use it as the
3	basis for your decision.
4	MR. ARMIJO: That's for the lawyers.
5	MR. ASHAR: We were using the logic if we
6	are going to use this in one particular portion, but
7	you are quite right. There is going to be a problem,
8	and we have to work with it.
9	MR. SAMMADAR: This is Sujit Sammadar with
10	NRC.
11	Typically we never use NRC studies because
12	it's a back of the envelope to justify anything that
13	the applicant has. The applicant stands on their own
14	merit. So the Sandia study will not be a
15	justification for anything, but all it demonstrates to
16	us is given the current condition, what they have
17	concluded, we get the similar conclusions from the
18	Sandia study even though the two studies do not line
19	up.
20	There were differences in how the studies
21	were conducted and what they give us, but the bottom
22	line conclusion is about the same. They still
23	maintain that factor of
24	CHAIRMAN MAYNARD: I understand, and
25	again, I believe what the issue is is that the staff
	1

(202) 234-4433

	306
1	has taken credit for the applicant saying they meet
2	the code, and the real question is an issue has come
3	up as to what does the code require and does the
4	applicant's analysis meet the code, and so I guess
5	what we really need to do is the staff's position and
6	justification that the applicant's analysis meets the
7	code.
8	MR. CU: We will get back to the
9	committee.
10	MR. ASHLEY: Hans, did you have
11	additional?
12	MR. ASHAR: No, I don't think so.
13	MR. ASHLEY: With that
14	CHAIRMAN MAYNARD: Any other questions for
15	the staff?
16	MR. ASHLEY: We have one additional item.
17	CHAIRMAN MAYNARD: We have got the socket
18	welds. I'm sorry.
19	MR. ASHLEY: You had a question at your
20	previous meeting about socket welds, and Jim Davis is
21	going to give you some information.
22	Jim.
23	MR. DAVIS: I'm Jim Davis from the staff.
24	CHAIRMAN MAYNARD: Can you speak up a
25	little bit and can we hold down the side
	1

	307
1	conversations?
2	Thank you.
3	MR. DAVIS: We have gotten a commitment
4	from Oyster Creek to look at one socket weld
5	destructively, and we were questioned on the
6	reliability of that. So what I did was a lot more
7	research.
8	What the issue is is for Class 1 socket
9	welds, Class 1 and Class 2 socket welds, less than
10	four inch nominal pipe size, should they be included
11	in the one time inspection of small bore piping. The
12	GALL report does not include them.
13	I had extensive discussions with the
14	technical staff on this issue, and what we concluded
15	is currently IWB and IWC require a surface exam for
16	socket welds, between one and four inches. There's no
17	requirement for socket welds under one inch, and all
18	of Oyster Creek's socket welds are under one inch.
19	I looked at the literature and I found out
20	that most failures are vibrational fatigue, and they
21	initiate on the ID. So doing a surface exam doesn't
22	really help you much, and the NRC position is if it's
23	ID initiated doing a surface exam is not appropriate
24	even though it's in the code, and they've been
25	granting relief to use a VT-2 or visual exam.

(202) 234-4433

	308
1	So the conclusion we drew was that looking
2	at one or even several socket welds will not really
3	prove very much, and so that we're not going to
4	require socket welds be examined. So that's basically
5	the story. So there will be no additional
6	examinations of socket welds required.
7	CHAIRMAN MAYNARD: All right. Any
8	additional questions on socket welds?
9	MR. SIEBER: I think that was my issue.
10	I'm satisfied with that answer.
11	CHAIRMAN MAYNARD: Okay.
12	MR. ASHLEY: The conclusion will have to
13	await our next meeting.
14	(Laughter.)
15	CHAIRMAN MAYNARD: Okay. Any other
16	questions for the staff right now?
17	If not, I'd like to thank you for your
18	presentation, and I believe next we have Mr. Gunter
19	and Mr. Webster.
20	Take a moment or two here to transition
21	seats.
22	(Whereupon, the foregoing matter went off
23	the record at 3:46 p.m. and went back on
24	the record at 3:48 p.m.)
25	CHAIRMAN MAYNARD: I think if we can get

(202) 234-4433

	309
1	everybody to sit down and be quite, we'll go on with
2	the comments from the public.
3	And before you get started, I'd like to
4	say that I appreciated getting a copy of your slides.
5	I understand there may have been some changes since
6	then, but at least to get some prep work there done,
7	and so I really appreciate that and look forward to
8	hearing your comments.
9	So I think, Mr. Gunter, you're going to
10	lead it off.
11	MR. GUNTER: Thank you.
12	I'm going to offer just a very brief
13	introductory remark. My name is Paul Gunter. I'm
14	Director of the Reactor Watchdog Project for Nuclear
15	Information and Resource Service.
16	We are one of six intervenors before the
17	Atomic Safety and Licensing Board. We offered one, a
18	single contention.
19	Subsequent to our communications with
20	AmerGen on the drywell liner corrosion issue and
21	subsequent to our filing of the single contention, we
22	do recognize that AmerGen has offered a set of
23	commitment changes.
24	However, the commitment changes still
25	raise concerns, and we're here today to address some

(202) 234-4433

	310
1	of those concerns, and I will be turning it over to
2	our attorney in this proceeding, Mr. Richard Webster.
3	Mr. Webster's background is that he has a Bachelor's
4	degree in physics from Oxford University, a Master's
5	degree in engineering hydrology from Imperial College.
6	He has his law degree from Columbia Law School, and he
7	is currently the staff attorney for Rutgers
8	Environmental Law Clinic.
9	So Richard.
10	MR. WEBSTER: Thank you, Paul, and thank
11	you to all of the committee members here for inviting
12	us along, and thanks for the time last time. I'll try
13	not to overrun in the way that I did last time.
14	I'm presenting here on behalf of a
15	coalition of environmental groups and citizens groups
16	who are collectively known as the Coalition to Stop
17	the Relicensing of Oyster Creek.
18	So I just want to review what we did at
19	the previous meeting first and then move into what's
20	new. So the previous meeting I think we decided that
21	we should put the horse before the cart. That means
22	that we should first establish margin and then for
23	both the sand bed and the imbedded region, and then
24	we should determine whether that margin can be
25	maintained, and if so, how it can be maintained.
l	1

(202) 234-4433

	311
1	Now, at the last meeting we realized that
2	in terms of establishing margin there are significant
3	issues in terms of paucity of data, nonrigorous
4	statistics, large uncertainty, unrealistic modeling,
5	and many cumulative, unjustified assumptions.
6	In terms of whether the margin can be
7	maintained, we realize there are significant issues of
8	equipment failure leading to ongoing leakage, operator
9	failures, uncertainty in the measurements, lack of
10	data to predict the corrosion rate, and in the scope
11	and frequency of the monitoring.
12	So just to emphasize those are the key
13	issues, so far the applicant has measured less than
14	one percent of the sand bed area, and it says the last
15	measurements are in '94, where they have now done the
16	measurements in 2006. So we have a gap between '94
17	and 2006. I was kind of surprised that the applicant
18	used the '96 numbers in their simulations. I think
19	those numbers should be excluded. They've been shown
20	to be systematically in error, and therefore, I think
21	we really only have three valid measurements, not
22	four.
23	So when the applicant is doing its
24	statistical analysis, I really don't think they should
25	take credit for four measurements.
	I

(202) 234-4433

312
Again, last time we found that the
applicant had fitted the data to the normal
distribution by segmenting the data and editing out
pits that were beyond a certain number of standard
deviations. There seems to be no change in that and
no word from the applicant about that. I guess
they're still doing that.
The acceptance criteria are based on the
modeling and idealized geometries. I think the Sandia
report has addressed that to some extent.
The margin was not established, but there
was a .064 inches was claimed. That's still the same
now.
We had argued that the visual assessment
of the coating alone was inadequate, that we need
better detection of corrosive conditions and faster
response, and that there were no measurements in the
imbedded region.
Now, what's new so for the sand bed, we
had the historic results and we now have the results
in 2006. For the imbedded region we now have one 42
point grid taken in Trench 5 in 2006, and they found

the last outage.

So those are the primary new factors, and

water on the inside of the shell as we've heard during

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

	313
1	I guess the Sandia study is the other big factor. So
2	I'm going to start, first of all, while talking about
3	the sand bed. Then I'll just wrap up by talking about
4	the imbedded region.
5	And before I forget, I've also sent a
6	letter sweeping up a couple of questions that were
7	left over from last time, and actually raising a
8	couple other issues to do with the torus program, the
9	potential missed commitment in the torus program,
10	which I have been unable to resolve as of this point,
11	and summarizing a few of the items I'm going to
12	present here.
13	So I think we are fully familiar by now
14	with the schematics. We don't need to dwell too long
15	on those.
16	So the Sandia study, I mean, let's pick up
17	here. Obviously the Sandia study is a very serious
18	concern. We have a national laboratory where the
19	supervisor of the study apparently is ASME committee,
20	and they have decided that the modeling done by GE
21	basically got the wrong answer. There's an
22	assumption about the capacity reduction factor that
23	was unjustified.
24	So that was supposed to be a confirmatory
25	study, and Sandia did caution that it cannot be used
	1

(202) 234-4433

	314
1	as an absolute study. It can only be used as a
2	confirmatory study, and basically what we find is that
3	the confirmatory study has shown lack of confirmation.
4	The assumptions that went into the GE study, the
5	confirmatory study, are incorrect.
6	I mean, there are two big problems. One
7	is the capacity reduction factor, but the other, as
8	we've heard, is in the model because the GE study was
9	a 36 degree symmetric model. It couldn't predict the
10	lowest mode of buckling.
11	And so we think when you get that kind of
12	situation what's needed next at minimum is a more
13	refined approach to modeling. Just having two models
14	that don't agree with each other and then hoping for
15	the best we don't think is an adequate way to proceed.
16	I mean, the purpose of the Sandia study
17	was to see what the effects of the degradation were,
18	and what the Sandia study finds is that there has been
19	a 43 percent reduction in safety factor for buckling
20	the sand bed region under refueling conditions due to
21	the degradation.
22	As I said, it found that 8.44 inches
23	uniform thickness should be the is the number
24	Sandia can justify as opposed to .736 inches, which
25	both the applicant and GE want to adopt. And it has
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	315
1	found that the safety factors for buckling under
2	refueling conditions were actually they were
3	predicted at 1.95 in the upper drywell, which I was
4	kind of surprised that no one mentioned because that
5	is less than required, a factor of two, and they're
6	predicting 2.15 in the sand bed.
7	Now, the problem with this is I think, Dr.
8	Wallis, the last time you mentioned the sensitivity
9	analysis is going to be critical in this. You start
10	to change the assumptions a little bit and the outcome
11	could change a lot.
12	So what we have here is a model that's
13	based on some assumptions that are conservative and
14	some assumptions that are not conservative. If we
15	start to think about what the uncertainties in this
16	prediction, I think we see that there's an
17	uncertainty. We know somewhere the factor of safety
18	for the model actually or for the drywell overall has
19	existed in 1992, which is what the Sandia study
20	models, is somewhere on the order of two. It could be
21	more than that; it could be less than that. We know
22	it's on the order of two.
23	But I don't think that's enough to justify
24	relicensing. What that shows you is that we don't
25	really know whether it meets the code or not. We know
	1

(202) 234-4433

(202) 234-4433

316 1 that in fact what it shows you is we know there's a 2 slim chance probabilistically that it doesn't meet the code. 3 4 The problem with the Sandia study or the 5 lack of conservative assumptions are that actually there was some observed filling in the sand bed 6 7 exterior measurements in October 2006, and in fact, I've looked back at the tables, comparing the tables 8 9 presented by the applicant to you in the information 10 package they sent and the tables of degradation. Thev degraded modeling in the Sandia study, and actually 11 the two for Bay 1 don't reconcile. 12 The Bay 1 local region, Sandia used .705, 13 14 but according to the applicant on page 612, Table 2, 15 UT thickness measurements in '92, the thinnest measure So already the Sandia model looks 16 in Bay 1 was .68. 17 like it didn't take account of the thinnest measurement for '92. 18 19 Now, if we move on, look at the thinnest 20 measurement for 2006. It's actually .665. So already 21 there's a problem here. The Sandia model doesn't 22 predict what at the current state of the drywell is. 23 It predicts what -- well, actually it predicts what 24 Sandia thought it was, but what it doesn't look like 25 it really was back in '92.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

And the biggest one I've said before is that Sandia did not estimate the uncertainty of this prediction, didn't really do a lot of sensitivity. They did not move those degraded regions around to see how they would change it. They did not look at the uncertainty in the measurements themselves, and along the way you can point to various other assumptions which may not be conservative.

9 Now let's look. This is the applicant's 10 claims basically, and so you can see that what's happened over time here. In 1969, if we look on the 11 12 left-hand side at the small area thickness, this is what the applicant is running for single point 13 14 measurements, and so originally I'm just taking the 15 nominal, and then on a single point basis actually the applicant measured from the inside, .603, in 1992, but 16 17 subsequently they've sought to correct that measurement, and I'll go into this in more detail 18 19 later, but they're now saying that the thinnest 20 measurement actually measured from the interior is 21 .648.

And the thinnest measurement in 2006 measured from the exterior was .602. So from the applicant's basis they say, well, you know, based on the GE study, .536, we'll figure that is acceptable.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

3

4

5

6

7

8

	318
1	So that's fine.
2	The problem with that well, I'll go
3	into the problem with that later.
4	The way you see is at minimum we see a
5	dramatic reduction from 1969 to now, a huge reduction
6	in the margin, and the same thing for the mean
7	measured thicknesses. These are looking at the grids
8	that the applicant has used, not the exterior
9	measurements.
10	Again, taking the nominal 1969, it comes
11	down to .8. As we've said, if .736 is acceptable,
12	then you have a margin of .064. The question again is
13	uncertainty. What is the uncertainty of those
14	measurements? What's the uncertainty in the
15	acceptance criteria? Is there a possibility that
16	those two bars may overlap?
17	And, again, you see a dramatic reduction
18	in margin from 1969. This is simply not the same
19	plant that it was in 1969, and we see the same thing
20	with the pressure. I mean, what has happened over
21	time here is as the margins have gotten narrower and
22	narrower and narrower, the conservatism in the
23	analysis has gradually been eaten out of the analysis.
24	We saw with the pressure initially there was a
25	conservatism in the analysis. So the pressure was

(202) 234-4433

	319
1	going to be 66 psi.
2	Then because they didn't meet that, they
3	took that conservatism out, and so at minimum even by
4	the applicant's own admission, this plant has far
5	narrower margins than it had in 1969. I mean, based
6	on the modeling that we have actually it's our
7	contention that we don't know if there's any margin at
8	all right now, and the applicant certainly has not
9	demonstrated an ability to maintain even the margin
10	that they claim. So let's move forward in that.
11	I mean, I'm kind of attached to actually
12	looking at the data. So I decided to have the data
13	plotted out, and these are all based on the GE
14	acceptance criteria of .736. So I'll sort of go
15	through and then give some illustration if we change
16	that to the .844 that Sandia is predicting.
17	So this is Bay 1, and I think that's
18	interesting about this is that you see a pretty large
19	area in the middle here that's got thinness to it, and
20	then you see another area down here that's thin, too,
21	a separate area. So there's another nonconservative
22	part of the Sandia model. They have one degraded area
23	and actually have it directly underneath the vent
24	pipe.
25	Actually there are two I mean, look.
	1

(202) 234-4433

	320
1	These are the only numbers we have for this area or
2	that we have in the 2006 numbers, but I actually
3	haven't seen those. The only presentation of those
4	that I've seen is the ones given in Table 2 in your
5	packet. So this is the only drawing I'm able to
6	create from this.
7	And what it shows me is that we don't know
8	much about this area, but what we do know is there are
9	probably two scenarios, the local in 736 and they are
10	reasonably extensive, and they're probably not
11	centered around the vent pipe.
12	And if we were to up the required amounts
13	to .844, because remember the applicant's methodology
14	for those acceptance criteria is to take the uniform
15	thickness requirement and compare that to well,
16	actually let me backtrack. The applicant has a
17	strange approach to these numbers. Let me go on and
18	show you something here.
19	The applicant, obviously, if it decided
20	that each of these numbers represents an area, it
21	would have a problem because what it's doing for the
22	.25 square foot grids it compares them to the uniform
23	thickness, and so it says, well, are my grids less
24	than .736. If so, I have a problem.
25	The difficulty but then for these, the
	I

(202) 234-4433

1 applicant actually applies the individual measurement 2 amount and says, well, for these individual 3 measurements, are they less than .536 or whatever the 4 figure is, .5-something.

5 Now, the problem with that is each of these measurements could well represent an area that's 6 7 as big as or bigger than a quarter of a square foot. 8 Indeed, the report, for one, they actually -- and I'll 9 go through it -- actually tells you that the area 10 represented by the point is bigger than a quarter of a square foot. So the applicant's approach to 11 acceptance is completely inconsistent. 12

Sometimes they take the average of a quarter of square foot area and compare that to the uniform criteria, and sometimes they compare it to the individual point criteria, and sometimes they take the individual point which represents an area of over a quarter of a square foot, but then don't use the area account, the area acceptance criteria.

And I think earlier on you hit the nail on the head when you were asking about how do they come up with these areas that are thinner. As far as I can tell if the applicant measures on the edge of the grid a point that's less than .736 -- I'm talking about the results taken from the inside now -- if they measured

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	322
1	that, they don't then move the grid over and take
2	another grid and move the grid up and take another
3	grid and try to map out the area that's thinner than
4	.736. They just move on and then just average that
5	out.
6	And conceptually we think that's a
7	problem. They need to be measuring the areas.
8	However you cut off though, where you set the
9	criteria, which is obviously a matter of debate, but
10	minimally you have to measure these areas and figure
11	out how big they are, and then once you know how big
12	they are, you can actually, you know, think about
13	modeling.
14	For the moment we really have no idea how
15	big they are.
16	Now, this is just Bay 5, and the reason I
17	put this one up is to show you that if we compare Bay
18	1 with Bay 5, Bay 5 is the bay with pretty much the
19	least corrosion, and I think that I heard the
20	applicant say they selected Bay 5 for the trench
21	because it had the least corrosion.
22	And so it struck me as kind of strange
23	that they dug down and measured the corrosion in the
24	imbedded region in Bay 5 because you kind of
25	anticipate that Bay 5 would have the least corrosion

(202) 234-4433

	323
1	in the imbedded region, at least in terms of the
2	exterior imbedded region. But I'll come back to that
3	when I do my imbedded region point.
4	So this is Bay 9. Again, if we up the
5	criteria now to .844, you see that they have a large
б	area over here, which is thin.
7	This is Bay 11. Actually if you up the
8	criteria to .844, there are no measurements thicker
9	than .844 in Bay 11.
10	This is Bay 13. It's interesting. Sandia
11	said they weren't able to put an amount on this. I
12	actually found an E-mail from the applicant that
13	characterizes this area as 15 by 43, 15 inches by 43
14	inches, and then as I said before, this is .7 in Bay
15	13. If you go back to the original report, the report
16	says that .7 represents an area of a quarter of a
17	square foot. It says it's no more than that.
18	Of course, that was in 1992, and then
19	these are the actual measurements in Bay 13, and what
20	you see is that that's the .7 there. That came in as
21	.618. So there's a quarter of a square foot area at
22	least which is at a thickness of about .618.
23	Now, the applicant says, "Oh, that's okay
24	because, you know, there's that 536 criterion, and the
25	problem with that .536 criterion is there's actually
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433
	324
1	what GE showed was that a uniform thickness of 736
2	mils. This sand bed region exactly met the code.
3	What it actually showed when you go back
4	and look at the reports is that if there's a degraded
5	region that's thinner than .73, that's thinner than
6	.736 inside that uniform sand bed region, it's about
7	ten percent below the code.
8	So that GE report, even if it's right,
9	doesn't really tell you that you can allow areas of
10	more than one square foot to be thinner than .536. In
11	fact, what the applicant has said if you turn to my
12	letter, what the applicant has unequivocally said is
13	the areas corrode at less than .736 inches could be
14	contiguous provided their total area did not exceed
15	one square foot.
16	Now, the problem I have with this is it is
17	looking a lot like there's an area in the middle there
18	that's exceeding one square foot. It seemed like they
19	exceeded that in '92 as far as I can tell.
20	Now, I note what the response is. We
21	selected these thinnest points. So those are biased
22	towards the thin side. Well, yeah, that may be true,
23	but we don't have any other points. We really don't
24	have that much idea what's in between those points.
25	We know it's rough. I mean I question whether, you
	I contract of the second se

(202) 234-4433

	325
1	know these guys can really spot the thinnest. I think
2	somebody else was questioning that, whether they can
3	really spot the thinnest area.
4	What we do know is that this large area
5	here which is thinner than .736, or even if .736 is
6	right, which obviously Sandia doesn't think so, you
7	still have a problem or the applicant still has a
8	problem because they've said that it should be less
9	than one square foot, and it simply isn't.
10	So now we tried to come up with some
11	statistical approach. I mean the applicant's
12	statistics, as we heard earlier, were shaky, and so we
13	tried to help them out a little bit here by doing some
14	statistics.
15	Dr. Hausler actually ran this little
16	statistical analysis looking at extreme values. Very
17	simple, a reduced area on the bottom in terms of
18	ranking, and then the pit depth of the side, and so
19	you know, what you find is we extrapolate out, is that
20	there's obviously a chance they didn't find the finish
21	point. If these are randomly selected, which they're
22	not, if they were randomly selected, there's a 2.5
23	percent chance that the mission would give a thickness
24	less than .536, and at 99 percent certainty, the
25	thickness of each point is .449.

(202) 234-4433

	326
1	Now, as I said, we know they're not
2	randomly selected. I don't really know. We haven't
3	figured out how to do the statistical treatment for
4	non-random selected points, but somebody had better
5	figure this out because there is a chance when you get
6	these measurements that they miss the thinnest point
7	and, therefore, there's a chance that they're already
8	going below the acceptance criteria. You just can't
9	take the point you happen to measure, and so that
10	looks okay to me and so that's fine.
11	You really need to do some extreme values,
12	and I think we talked about this before, and the other
13	thing you really need to do is figure out what these
14	challenges are. Now, you know, we had a discussion
15	before about 95 percent. What's the basis of 95
16	percent, and it's an issue we rate. If one in 20
17	times you find your containment system isn't working
18	the way you like, is that acceptable?
19	It doesn't sound like it to me, but you
20	know, I don't really I haven't really gone through
21	all of the analysis to figure it out, but what I'm
22	hearing is nobody else has either, and that's what
23	worries me or worries us as a group, is that nobody
24	has really figured out what chance of this thing not
25	working is acceptable.
	1

(202) 234-4433

	327
1	We know there is a chance it doesn't work.
2	The question is how high can that chance be. The
3	applicant appears to be saying five percent chance is
4	okay. I don't know if that's the NRC position. I
5	certainly haven't seen the NRC position, the staff
6	position anywhere specifically addressed, but I think
7	that's something we really need to look at in this
8	case.
9	I want to get back to the errors. What
10	we've done here is actually just taken a very
11	simplistic just taken off that graph and I start if
12	you go back to the just come back. So here we are.
13	If you include those points, those higher points, then
14	I think the average comes out to just about exactly
15	736.
16	So I said, well, let's just fiddle around
17	with it and carve that end off and see what we get
18	then and let's cut this end off and see what we get
19	then. And then we know that this point is around a
20	fourth of a square foot, and let's put that on the
21	graph, and that's what we've done here.
22	So if your area, a quarter square foot,
23	you know is about .62 inches, it actually comes out to
24	about 2.5 square foot, that area that I indicated with
25	both sides cut off. That comes out to about .68
	1

(202) 234-4433

	328
1	inches, 3.75 square foot, to around .71 inches, and
2	then 4.4 each square foot, pick up 27 points.
3	So, again, you do have significant areas
4	that are thinner than .736, and it seems to me that
5	what the GE modeling even if the GE modeling is
6	right, what it's showing is that if it was uniform
7	with those indentations it wouldn't meet code case.
8	Now, we know its not uniform with those
9	indentations, but we really you know, we haven't
10	seen any modeling from the applicant on how to deal
11	with that. We've seen a lot of hand waving, but no
12	actual modeling, and the applicant has said,
13	remember you know, the applicant has stated let
14	me say it again areas corroded to less than .736 in
15	thickness could be contiguous= I'm quoting you from
16	here could be contiguous provided the total area
17	did not exceed one square foot.
18	Well, so it looks like what the applicant
19	is saying is that if this graph is right, there's
20	already a problem, and I just did a little look at the
21	sensitivity of thinning. I think no surprise that
22	thinning the areathe area that's thinner at a
23	certain point is actually in proportion to the square
24	of the thickness or the square of the thinness if you
25	want to look at it that way.
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	329
1	So, in other words, although the corrosion
2	goes linearally, the area will increase with the
3	square, and so what you end up with is a graph where
4	here I've taken obviously the cell is .736 inches
5	thick, then there's no area that's less than .736
6	inches, and here I've taken the known points as the
7	one that the applicant said was quarter of a square
8	foot, applied a cone shape, and then extrapolated it
9	if it was a cone shape just for that one point, that
10	.7.
11	What you see is that, you know, no
12	surprise, that the area goes up quite quickly with the
13	error and that the measurement error, which here I've
14	put in .02, which is the applicant's measurement
15	error, the measurement error makes it a parallel
16	difference to the well, let's put it this way.
17	There's more the error in the measurement magnifies
18	in terms of the area.
19	And so I think what that means is that
20	certainly for the Sandia study you need to be careful
21	about the sensitivity to the area, as well as the
22	sensitivity to the placement.
23	So now I'm going to more formally look at
24	these oh, before I finish up on that, I just want
25	to turn your attention to Slide 101 of the applicant's
	I Contraction of the second

(202) 234-4433

1 where they plot out all of their results. What it 2 really shows you is that at May 13 the thin area is 3 not directly under the downcomer at all. The thin 4 area that the applicant has documented is somewhere in 5 the middle of Bay -- oh, this is actually Bay 19. In Bay 19, the thin area they're done is actually similar 6 7 to Bay 17 and Bay 19. And again, you know, there's a thin area 8 That's not in the model. There's only two 9 there. thin areas in the model. So, you know, the claim that 10 this model is bounding I think is not. It just isn't 11 justified. I don't understand any justification why 12 the Sandia model would be bounding. 13 14 So moving on to the 2006 external results, 15 they're presented in a rather opaque way. I haven't got a slide, but they're on the Table 2 in page 612 of 16 17 your package. Basically it presents measurements from '92 and measurements from 2006, and I'll just show 18 19 some statistics on those, but the problem is we don't 20 know what points they were taking out. So it's very hard for us to do good statistics on those because 21 22 they obscure by the data presentation where the points 23 were. 24 What we do know is that the thinnest point 25 measured decrease from .618 to .602. The largest

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

(202) 234-4433

330

1 rupture we can see from that table was .039 inches. 2 I think the conclusion is that the shell is probably 3 thinner than it was in 1992. Well, there's a couple 4 of things we can conclude, but I'll go through those, 5 and I just want to note the .02 inches of corrosion doesn't sound like a lot, but even if you accept the 6 7 applicant's contention, which we don't, but even if 8 you did, the margin is .6 -- .064. 9 Point, zero, two is a lot. It's a third So here are some more detailed statistical 10 of that. treatment of the results that we have, which is not 11 that many, and what I want to point out here is that 12 in Bay 1 the number of areas thinner than .736 13 14 increases by one, but which is consistent with the idea there is thinning going on in Bay 1 because if 15 the thinning occurred, then an extra point could have 16 dropped below .736 in the intervening period. 17 Even though an extra point appears to come 18 19 into the analysis, the mean still drops by five mils. 20 Now, moving on to Bay 13, strangely the 21 applicant reported nine points that were less than 22 .736 in 1992 but is now reporting only six points. 23 So, again, we seem to have some magic metal going on 24 under here or something is going on because either 25 they can't find these points or something strange is

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

(202) 234-4433

331

	332
1	going on. I really don't know what it is.
2	DR. WALLIS: Let me try to explain. These
3	green things indicate a number of measurements in that
4	range.
5	MR. WEBSTER: That's right, a histogram of
6	the measurements
7	DR. WALLIS: And the scale is such that
8	there are it seems you should change the scale.
9	MR. WEBSTER: Yeah, the scales don't match
10	up, yes.
11	DR. WALLIS: The scales change.
12	MR. WEBSTER: My apologies for that.
13	DR. WALLIS: So I assume that on the left
14	there's the smallest square is one reading.
15	MR. WEBSTER: So, right, I think that's
16	one reading.
17	DR. WALLIS: And then one reading and
18	then the next one over is a skinnier thing. It's a
19	smaller yeah, okay, but the smallest thing we see
20	is one reading. Okay.
21	MR. WEBSTER: Yeah, there. That's the
22	DR. WALLIS: So it's one, one, two and
23	two.
24	MR. WEBSTER: Right, right. And then the
25	mean, the only results that I have or that we have as
1	1 I I I I I I I I I I I I I I I I I I I

```
(202) 234-4433
```

	333
1	a group are the ones the applicant reported, which are
2	the ones that were less than .736. There are other
3	measurements, but I haven't seen any data presented on
4	those. So I can't comment on those, but this is what
5	we have to analyze and so I know it's an imperfect
6	job, and I apologize for that, but that's the best we
7	can do, and we were rather hoping the applicant might
8	do a better job, but it seems like they decided not
9	to.
10	So what you say for Bay 13 is that there's
11	around 20 mils of thinning. Now, whether that's
12	statistically significant is a question because
13	there's a lot of variation. These results, obviously,
14	you'd have to match up the points to determine whether
15	it's statistically significant.
16	But at least what it means is that you're
17	shifting the center of the distribution around your
18	uncertainty. Let's put it that way.
19	So there's an apparent thinning observed,
20	and I think the applicant tried to deal with this by
21	saying that the two measurement techniques are
22	different. So they're not directly compared.
23	But you normally expect the applicant to
24	have employed a measurement technique which didn't
25	have a systematic error. I mean we already castigated
1	I Contraction of the second

(202) 234-4433

(202) 234-4433

334
the applicant for using the 1996 results which it did
turn out did have a systematic error. So it would be
very surprising if it turned out to be '92 results
taken on the exterior of the dry well also contained
a systematic error.
Normally you would expect a more up to
date technique would have smaller random error, but
you'd still be around the same actual physical, you
know, measurement. It's only if there's a systematic
error that it would make the two non-comparable.
And so the applicant appeared to say that
on this slide or maybe I'm misinterpreting what
he appeared to say was that there was such a
systematic error due to the curvature of the drywell.
Now, I didn't quite understand the slide
because the drywell is concave and there are convex
bits in it, and the probes seem to be pretty small.
So it's kind of hard to see how that's going to be
able to give you two mils, but it's possible, but even
if that's true, I think that's a serious concern. If

what we had here is an applicant that relied on

measurements that it knew had a systematic error, I

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

I think it more likely -- I mean, there's

two other possibilities. None of them are very

think there's a problem there.

(202) 234-4433

1 palatable. I mean, I think this is why the applicant 2 decided not to discuss this issue. The other 3 possibility is there's external corrosion occurring 4 despite all of the preventive measures take. Now, 5 because all of the coating came in as satisfactory, that would mean that the corrosion could occur when 6 7 the coating is visually intact. So that would be an 8 unpalatable finding. 9 The other possibility is that the internal corrosion, and you know, we have water inside the 10 drywells identified as normal operating commission in 11 So that's certainly seems to be a possibility. 12 2006. And I was thinking about this actually 13 14 while we're presenting. You know, you have an 15 interesting situation. It seems like the grids measure from the inside and not really showing 16 significant change. But the points from the outside 17 are showing some change, and I think what that tells 18 19 you is that once of the potential explanations is 20 corrosion from the inside. You wouldn't get the 21 corrosion on the inside where the concrete curve isn't 22 there, which is where the interior measurements are 23 taken, but you might get it where you're below that 24 curve.

And so the way to explain -- I think the

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

(202) 234-4433

335

	336
1	most logical way to explain the difference is to say
2	it's the most likely answer is that corrosion on the
3	inside is occurring, but I mean, that's by no means a
4	certain conclusion, but you have to pick one of these
5	three unpalatable explanations.
6	So I think I previewed this before, why
7	there's no margin left. The problem is even for the
8	points that represent an area of over a quarter of a
9	square foot, the applicants only applied the point
10	acceptance criteria. The .536 doesn't really work as
11	an explanation because you're getting below code in
12	that particular situation.
13	So the .736 if the model is right, you
14	know, you might be able to justify that, but the
15	problem is that you've got areas that are up to four
16	square foot that are thinner or were thinner than the
17	.736 even in '92, and sine then those areas have
18	probably expanded either because there was a
19	systematic measurement error in '92 or because there's
20	corrosion somewhere.
21	Now, the margin failure has obviously
22	increased a little bit by around .02 inches, and so
23	you know, at best it's the worst quarter of a square
24	foot is now around .6 inches thick, and obviously if
25	you adjust the criterion to 844 mils, then what you
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	337
1	find is that four of the 12 grids measured from the
2	interior fail significantly and that margin is
3	insignificant for two others.
4	And the big problem with Sandia are right
5	in terms of the uniform thicknesses, but the applicant
6	doesn't have any way to know when it takes the
7	measurements what's acceptable. The acceptance
8	criteria are all hooked around the GE model. So the
9	GE modeling Sandia are right in the GE modeling
10	used an overly optimistic factor. Then the applicant
11	has no way. I mean, you saw all of the graphs that
12	the applicant presented all had these lines for .736.
13	You know, on the lines they show would all have
14	negative margin.
15	So I think we know what the operator
16	approach to the margin was. I mean, the interesting
17	thing is when they took the external measurements in
18	'92, they actually took account of those measurements
19	and said that they assessed that the entire bay of Bay
20	13 had a average thickness around .8.
21	It's interesting now that we see now
22	assessment of the overall thickness even though the
23	measurements on the inside came in thinner, and you
24	know, the NRC really got this right in the past. They
25	were saying that in order to consider the corroded
	I Contraction of the second

(202) 234-4433

1 areas' discontinuity, the extent of the reduction in 2 thickness due to corrosion shall be known, and that's 3 really what you were saying. You don't need to just 4 track the minimum thickness here. You also have to 5 track the extent of the thinning, and then if you're going to justify safety or that it meets the code, you 6 7 really need to do an even more realistic model. Ιt takes the extents of the thinning, you know, which is 8 9 basically what stress consultants told us back some time ago when we hired them, is that until you have 10 measurements that tell you both the thicknesses and 11 12 the extent, and actually they said, you know, this capacity reduction factor is a big sort of fudge 13 14 factor in the analysis. So you're much better off 15 measuring the shape of the vessel. If you do that and then run a finite model 16

with realistic numbers, then you know, maybe there's margin there, but we're not going to know, and even if you run an analysis and you do find margin, the next thing to do is then reduce the numbers on a generalized basis by some amount to try to come up with an allowance for corrosion to the next outage.

I mean, it's not good to show that as of today this drywell meets the code. You want to say even if we assume a reasonable worst case corrosion

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

338

	339
1	rate, and we assume that they're not going to look at
2	it for another two years or four years or however long
3	they're going to look at it for, and it's still going
4	to meet margin during that period.
5	And actually Sandia, to be fair, did add
6	in that kind of margin for the upper areas, but not
7	for the sand bed.
8	So, you know, I guess I'm flogging a dead
9	horse here, but corrosion made one, nine, 11, and 13
10	is widespread, and there are many points that are
11	capable. Full grids show, in Bays 11, 17 and 19, show
12	an average thinner than 844. In Bay 13, the best
13	estimate of the area with an average thickness,
14	thinner than .736, is around four square foot. The
15	area thinner than .736 is probably expanded since
16	1992, and there's a high degree of uncertainty about
17	the nature of the corroded surface. What I mean is
18	the physical nature. How thick is it and what are the
19	extents of the thin areas?
20	So even if the margin is .04, which is
21	what you logically get from original plain thickness
22	of .064 minus .02, the operator can't maintain that
23	margin.
24	We don't have a worst case interior
25	corrosion rate. The worst case exterior sand bed
	1

(202) 234-4433

1 corrosion rate was .04 inches per year, and we know 2 that the individual measurements have at least .02 inches random error. 3 Some additional location error 4 and probe rotation error, all those kind of things, 5 and then there's possible additional systematic error which hasn't been well controlled for. I have to say 6 7 that before I got involved with this case, I would 8 have liked to have imagined that people who ran 9 nuclear power plants, you know, routinely control for systematic error in critical measurements. 10 I quess I've been disabused of that notion, but I think it's 11 something they should start doing. 12

So the sum total of that is if you have a 13 14 corrosion rate of -- if you combined interior-exterior corrosion rate of .04 inches a year, then you could 15 run through your margin in a year. So I don't quite 16 understand how the applicant -- you know, I've never 17 understood this. How do they come up with inspection? 18 19 If the coating fails and the commissions are wet, then 20 they can start to see corrosion happening quite 21 quickly, and the problem is that as we pointed out 22 before, the measures to analyze whether it's wet and 23 whether the coating fails are not very good. The 24 coating failure inspection is once every ten year. So 25 there's ten years there where, you know, you could

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

(202) 234-4433

340

	341
1	fail and you wouldn't know that.
2	The water commitments likewise are
3	unsatisfactory. We're talking about looking at the
4	drains. It turns out in August of last year, the
5	applicant tried to implement the commitment it had to
6	check the drains and still failed to properly note
7	what the content of the bottles was. They had to
8	check it again to find out that really there was
9	nothing in those bottles.
10	So we haven't seen an applicant that is
11	particularly dept at implementing these commitments,
12	and as I say, we've highlighted in our letter another
13	possible problem of another commitment in the torus
14	region. So we think it's a highly well, it's
15	dangerous to just rely on a single commitment like
16	whether somebody goes down there and looks for water.
17	They haven't done it in the past, and it would be much
18	better to have logging instruments that actually check
19	for water.
20	According to our expert such instruments
21	exist. We've seen no contrary claims that they don't
22	exist or that they couldn't work down there. So it's
23	hard for us to understand why they wouldn't want to do
24	that.
25	Likewise the source of the water, we know
	1

(202) 234-4433

	342
1	that. It's hard for us to understand why the
2	applicant hasn't looked to carry off the source of the
3	water. It seems to me an obvious idea.
4	Now, just to reinforce the point about
5	accuracy, here's an E-mail that we found. You know,
6	I have a hard time fully interpreting this language.
7	I guess I'll just read it. It says the equipment used
8	in the past to perform, quote, randomly selected
9	locations did not function worth a shit or it didn't
10	perform to expectation, but it says because the
11	locations were not stamped or date match marked. It
12	wouldn't be possible to provide accurate follow-up
13	inspections, and it ends by saying if you wanted to
14	perform baseline inspections now. This was on October
15	10th, 2006, Mr. Ryan to Mr. Polaski.
16	Now, I fully understand which occasions
17	they're talking about missing now, but what I do know
18	is that it tends to indicate to me that the random
19	error and even this systematic error may be somewhat
20	higher which the application is missing a little.
21	Okay. Let's move on to the imbedded
22	region. Now, what we know is is, as we said, the
23	floor I think we went over this the last time. The
24	floor had serious problems when they removed the sand.
25	I guess we'll never really know whether the floor
	1

(202) 234-4433

actually was constructed that way or whether it became that way due to corrosion.

3 What we do know is that with this plant we 4 keep seeing repeatedly problems where the plant wasn't 5 constructed according to specification. There's this problem, and apparently actually the stainless steel 6 7 liner of the pool, the cavity pool was likewise thinner than it was supposed to be which is maybe one 8 9 of the reasons why it has such extensive cracking, and 10 likewise apparently the construction of the spent fuel pool floor was supposed to be keyed in with L-shaped 11 rebar for the walls and wasn't. Where they had looked 12 at that it wasn't found that way. 13

So it is at least plausible or at least possible that, indeed, tit was constructed improperly, but I don't think that's a particularly comforting explanation because it just gives rise to the question of what else was not constructed improperly. Well, what else was constructed improperly?

And it certainly means that you can't look at these drawings and just say, oh, well, this is what the drawings say. So it must be okay. In this case it's really a question of trust, not verify. So as we know, that floor was repaired

with epoxy in '92. Now, what we know is that we know

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

1

2

	344
1	there's a document from AmerGen that says that since
2	1996 inspections have found indications that epoxy is
3	separating from the concrete, and the separate seams
4	could potentially louse up water to get under the
5	epoxy coating repair.
6	So I have a couple of questions about
7	that. One is, well, you know, you'd think if it was
8	important to stop water going down into the imbedded
9	region that you might want to repair the floor when
10	the inspections show that it's cracked.
11	Apparently that wasn't done. The next
12	part of the document says that the separation could be
13	caused by concrete swelling. Well, that's an
14	interesting notation. I mean there's obviously
15	something causing this cracking. If the concrete is
16	swelling, I mean, you'd rather like to know about it.
17	There must be something causing the concrete to swell.
18	Again, I don't know. I'm just quoting
19	these documents, but I think it's something that if I
20	was the applicant I might want to look into. We
21	actually now know the bottom of the drywell is below
22	the groundwater table which came up last time. Again,
23	this is an AmerGen assessment.
24	And now in terms of what can you do to
25	have a look at this region, which was a question that

(202) 234-4433

	345
1	came up last time, apparently at Dresden they drilled
2	holes in the concrete floor to take UT measurements,
3	and in the SER the staff said that you could get a
4	semi-quantitative assessment of this region using
5	guided way technology and then kind of using the sort
6	of logic which seems to pertain in these kind of
7	documents, they say, well, since this wouldn't be a
8	precisely quantitative estimate, it's hardly worth
9	doing at all.
10	Now, I suggest to you that where a precise
11	estimate is hard to make, it's at least a good idea to
12	make a semi-quantitative estimate. If that semi-
13	quantitative estimate comes up as a problem, then you
14	can move on and try to figure out how to do a more
15	quantitative estimate.
16	So the justification in the SER for not
17	using guided way technology I don't think is logical.
18	So I don't know if any of the NRC staff members want
19	to address why they decided that was a bad idea.
20	So the imbedded region measurements, I
21	said they were taken in Bay 5, and if you look at it,
22	Bay 5 was actually the bay with the least corrosion.
23	If you turn to Slide 54 of the AmerGen presentation
24	you see that actually, I mean, kind of surprisingly,
25	given the protestations of the consultant regarding
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

1 the noncorrosive qualities of the water, what you find 2 is that the corrosion in the san bed region in Bay 5 3 is not that different than the corrosion in the 4 imbedded region.

5 There seems to be some confusion about why I suspect Bay 5 was selected 6 was Bay 5 selected. 7 because it had the most water in it from the inside. 8 The problem is it's not the bounding. We don't really 9 know much about what water is in the other bay. So I think the idea of bounding on the inside is probably 10 not right. It seems to be rouse than Bay 17, but 11 that's as much as you can say, but from the outside, 12 Bay 5 is clearly the best bay. 13

So if you're trying to look for imbedded region corrosion, Bay 5 is absolutely the wrong place to look, and looking at this table you see that. I suggest, you know, Bay 1, Bay 13, Bay 11. All of those have serious corrosion in the san bed. Those are the regions you would want to look at.

20 We do know and the one thing we are 21 showing is that corrosion is occurring, and if you 22 look at the grid, I mean, it's hard to say how much 23 because the nominal is 1.154. You can see in the 24 grid above people give Slide 54. They make it 1.185. 25 so it's hard to say exactly how much it is, but it

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

ĺ	347
1	seems to be something, and I haven't really had time
2	to consult with my expert and trying to figure out
3	exactly how much and what significance that has, but
4	certainly these are issues that have to be fixed, have
5	to be resolved before this thing can move ahead.
6	I mean, it's kind of amazing to me that
7	we're in this position, that we're still debating
8	these fundamental things at this very late hour and
9	even when the staff I don't know how. This will be
10	a mystery to me I don't know how the staff has
11	signed off on this on the basis of this one
12	measurement because this one measurement is absolutely
13	not bounding.
14	Probably the best if you were trying to
15	find a measurement that might come out good, this
16	would be the one for you.
17	Conclusion. I mean, the basic
18	conclusions, there's a significant probability that
19	there's no margin in the sand bed region. We really
20	don't know what the margin is in the imbedded region.
21	Even if the margin is .04, which is pretty much what
22	you end up concluding is the best case, it's too small
23	to maintain the uncertainty in the measurements in the
24	corrosion rates.
25	And here we should err on the side of
	1

(202) 234-4433

	348
1	caution. Where does all of this uncertainty come
2	from? All of this uncertainty has come from the
3	applicant's inability to maintain a reasonable program
4	both in time and space measuring the thickness of this
5	vessel. You know, it was up to the applicant to make
6	the case. They had to figure this stuff out and take
7	enough measurements so that then uncertainties would
8	be small enough so that they could convince you that
9	they could have margin and they could maintain it.
10	So far I don't think they've done that.
11	I worked for one of you, and I don't think you've done
12	that. I'd like to ask or field questions now.
13	CHAIRMAN MAYNARD: Does anybody have any
14	questions for Mr. Webster?
15	DR. WALLIS: I'm wondering who should
16	respond to Mr. Webster. I mean, he has made a lot of
17	assertions, a lot of statements about what the staff
18	or AmerGen has done. I'm sure that we are the
19	appropriate people to respond to all of those
20	statements he has made.
21	CHAIRMAN MAYNARD: Okay. We're here to
22	gather information, not to answer questions.
23	DR. WALLIS: That's right.
24	CHAIRMAN MAYNARD: Mr. Webster or Mr.
25	Gunter's avenue to get questions answered would

(202) 234-4433

(202) 234-4433

	349
1	actually be through the NRC, through the staff, and
2	again, that's not ours to answer questions. I think
3	if they have specific questions, it's through the
4	staff because the licensee also does not have to
5	answer in this part of the regulatory process to them.
6	So their questions would be directed to
7	the staff to answer. What is important is for us to
8	get this information and for us to factor this in with
9	all the other information that we have in our overall
10	deliberations.
11	DR. WALLIS: Some of our deliberations
12	could be based on the staff's replies to Mr. Webster.
13	I mean, is the staff going to reply in some way to
14	this or just leave it the way it is.
15	MS. LUND: I guess my question would be
16	whether this is going to be submitted to us for
17	answers. I mean, it's similar to what has happened in
18	the past. We have a process for people to send, you
19	know, comments and also letters and we respond to
20	those all the time. So, I mean, I guess that would be
21	my question, is whether it would be put into the
22	process that we normally use to respond to questions.
23	MR. WEBSTER: Can I just make a couple of
24	remarks?
25	One is that actually after the last ACRS

(202) 234-4433

	350
1	meeting I made a specific query to the staff about a
2	particular issue and subsequently after the end of the
3	meeting I made a similar query to another member of
4	staff, and so far have no response from those queries.
5	So my ability to get answers from the staff is
6	somewhat limited.
7	Second of all, we have a transcript here.
8	I'd be more than happy to send the staff a transcript,
9	but I think you get a transcript already. So if you
10	could regard the transcript as a submission of those
11	questions, I'd be obliged.
12	DR. WALLIS: Maybe you should itemize your
13	questions. You have a question about what's the
14	appropriate area to use for the thinned region when
15	making a
16	MR. WEBSTER: Well, that is actually the
17	question I had asked.
18	DR. WALLIS: defined element study, and
19	this seems to be a very straightforward, technical
20	question, and if you're maintaining that the area
21	should be bigger than was used by somebody, then that
22	would seem to be a technical question that could be
23	answered. I don't think it's something that we can
24	answer.
25	MR. WEBSTER: That is the very question
1	

(202) 234-4433

	351
1	that I asked actually, is (a) what is the staff's
2	assessment of the current area that was thinner than
3	.736. What is the basis of that assessment and what
4	is the uncertainty of that assessment?
5	I'm still awaiting an answer to that
6	question. I think that has been about three months
7	I've been waiting for that answer.
8	MS. LUND: Yes, I think we'll take a look
9	at the transcript and reply to that. We'll do what we
10	do, send the answers similar to what we did I think it
11	was for Palisades, send the response back.
12	DR. WALLIS: How long will that take?
13	MS. LUND: I guess I'd have to look at the
14	number of questions and see, you know, how soon we can
15	get responses from the technical staff.
16	DR. WALLIS: Quite an awful lot of
17	questions.
18	MS. LUND: I guess that's my point, is
19	that, you know, we need to look at the amount of
20	questions from the transcript and also see how
21	CHAIRMAN MAYNARD: And, you know, you'll
22	have to take a look at the process and the right
23	process. I think that by the time the transcript gets
24	issued and we go through it, it may take longer than
25	what time is available. I'll leave that up to you
1	I Contraction of the second seco

(202) 234-4433

352 1 guys to address on how you submit or how you get the 2 answers here. 3 As far as for the members, we do have 4 access to the data. We have access to a lot of the 5 information that he has shown bits and pieces of. I think part of our job is to take a look at that and 6 7 take a look at the other data that we've got and see 8 what conclusions that we may draw from that, too. 9 MR. SIEBER: One of the things we don't 10 have is the slides from this section, or do we? CHAIRMAN MAYNARD: We do have the slides, 11 12 yes. 13 MR. SIEBER: Okay. CHAIRMAN MAYNARD: We do have that. 14 15 DR. WALLIS: Mr. Chairman, we're supposed 16 to analyze this. How much time do we have? 17 MR. WEBSTER: Well, there's also the letter that I sent as well, to add to your burden. 18 19 I'm sorry about that. 20 Two weeks. MR. SIEBER: CHAIRMAN MAYNARD: Yes, this is currently 21 22 scheduled for the February full committee meeting. 23 Also I believe that part of it is our obligation, too, 24 that having taking input from Mr. Webster, we've heard 25 from the licensee. We've heard from the staff. We've

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	353
1	got a lot of information. If we need more information
2	from the staff or somebody
3	MR. SIEBER: Good luck.
4	CHAIRMAN MAYNARD: we should be able to
5	question that.
6	DR. WALLIS: Well, we have other items to
7	consider for the next meeting, too which require due
8	consideration.
9	MS. LUND: And also we were just
10	mentioning that the staff I was just asking the
11	rest of the staff we don't have a copy of the
12	letter that he's speaking to. I think he gave it to
13	the ACRS members, but not to us.
14	MR. WEBSTER: I can certainly provide you
15	with a copy. You know, I remind you last time there
16	were serious questions outstanding and it was
17	postponed from the full committee meeting. I think
18	that's another cause for action from the members here.
19	CHAIRMAN MAYNARD: Okay. Are there any
20	other questions for Mr. Webster or Mr. Gunter?
21	Okay. What I'd like to do right now is to
22	exercise my privilege as Chairman. We're going to
23	take a short, ten minute break, and then we'll come
24	back and we'll have a round table discussion. I'll go
25	around and ask the members for any thoughts.

(202) 234-4433

	354
1	One of the things we need to be
2	identifying is what specific information may be needed
3	in the full committee presentation so that we can
4	provide guidance to the staff and licensee on things
5	that we want to specifically have in that.
6	We will not have as much time, and so we
7	will need to focus on key areas.
8	So with that, let's take a ten minute
9	break. Actually we'll come back at five o'clock and
10	we'll do our round table discussion. That's closer to
11	12 minutes.
12	(Whereupon, the foregoing matter went off
13	the record at 4:49 p.m. and went back on
14	the record at 5:04 p.m.)
15	CHAIRMAN MAYNARD: All right. I'd like to
16	bring the meeting back into session.
17	I'd like to just start briefly by saying
18	I appreciate everyone's participation. We've had a
19	lot of discussion today, had input from the licensee,
20	had it from the NRC staff, had it from members of the
21	public, and that's something for us to all take into
22	account, think about.
23	We'll have another meeting on this subject
24	at our full committee meeting, and so we'll have some
25	time to look over this and maybe I don't know
1	

(202) 234-4433

355 1 generate more questions of our own and we'll see where 2 things go. 3 What I'd like to do now is to go around 4 the table, get any thoughts that the members have and, 5 again, one of the things is if there's any specific areas that they think we need to cover in the full 6 7 committee meeting specifically, like the one that we 8 talked about, we need to identify that so that the 9 staff and the licensee can be prepared to address 10 that. So I'd like to start with Mario and just 11 what comments you may have or discussion items. 12 DR. BONACA: My first comment is that we 13 14 have a large amount of data. I certainly would want 15 to review them before the full meeting just to digest some of the information 16 17 A couple of general comments I have. One, clearly we have been presented with an assertion that 18 19 the corrosion has been stopped and then that the 20 drywell, therefore, can operate until 2029. I have 21 to reflect inspections more about the of the 22 monitoring program that they're proposing, whether or 23 not I think it's adequate. 24 At first glance I think that I would like 25 to see certainly a more aggressive inspection program

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	356
1	in the short term, and I'm not sure about looking at
2	it now and then in ten years doing inspections again.
3	So, I mean, the monitoring program is
4	something I'll pay attention to, and I would like to
5	see discussed definitely at the full committee
6	meeting.
7	I have raised a number of times the issue
8	of controlling sources of water. I mean, they may
9	have done as much as they can to do that, but still
10	during the refueling they have one gpm, water that
11	comes down and will go down to the trough, and I'm
12	sure of that.
13	But the question is have we done enough to
14	control sources of water to assure that there is no
15	further accumulation.
16	The other thing that, you know, is more
17	like the issue of how the epoxy is doing, I mean, is
18	there any corrosion taking place behind the epoxy? I
19	don't know if the UT they're planning to do is going
20	to tell us or is sufficient. I mean, maybe there
21	should be some poking in some location to see if there
22	is some weakness behind that.
23	But any, my attention is more focused on
24	these programs that will give us some more comfort
25	regarding the condition of the drywell and the ability

(202) 234-4433

	357
1	to go for additional 20 years.
2	Those are my comments.
3	CHAIRMAN MAYNARD: All right. Bill.
4	MR. SHACK: Well, the surprise for me
5	today was the notion that we have water in the
6	imbedded region. That concerns me a little bit. I
7	mean, I fully agree with the argument that it's a
8	fairly benign environment and the corrosion rates are
9	low, and in a containment that didn't have the already
10	substantial corrosion that this one does, I would sort
11	of agree that its probably not a problem.
12	But this is a containment where there
13	isn't a whole lot of margin, and you know, the
14	estimate was you had 41 mils lost and that was less
15	than one mil per year. Well, I do the arithmetic and
16	I get more like tow mils per year, and you do have
17	data on these 106 points.
18	Many of them are down in the region where
19	you are looking through the thing at the imbedded
20	region, and I think there's some data there that one
21	could look at to try to really see just what you
22	think the corrosion rates are in that imbedded area
23	and understand that a little better.
24	I'm fairly comfortable with the notion
25	that if the epoxy coating is in good condition, that
Į	I contraction of the second

(202) 234-4433

	358
1	the corrosion on the OD is arrested, and that the
2	visual examination is a good thing there. I'm a
3	little less convinced with the small margins that we
4	have that the corrosion in the imbedded region is as
5	negligible.
6	Again, the buckling analysis, again, I
7	think that we have to settle on both the legalistic
8	requirements of who's analysis that you can accept,
9	but it seems to me that perhaps it is time to take a
10	more realistic you know, you haven't got enough
11	margin to do the uniform thinning model anymore.
12	The Sandia one does seem to indicate that
13	you have enough left. It makes it more difficult to
14	assess just how much margin you have because it's
15	difficult, but again, I'd like to hear more discussion
16	over the kind of credit that should be given. Since
17	there is no internal pressure, you know, whether the
18	circumferential tension really does give you credit
19	that you can account for, whether it's already built
20	into the IGAN value analysis that you get out of the
21	finite element model. I'm not 100 percent convinced
22	that I'm not double counting here. You know, some
23	more discussion of that would be helpful to me.
24	DR. BONACA: Yes, I had another comment I

forgot to mention which was one of the assumed thinner

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

	359
1	areas of one square foot. It would have been
2	interesting to know how large an area you could
3	tolerate, but that's a question I believe Sam raised,
4	and I'm behind that.
5	CHAIRMAN MAYNARD: Okay. Dr. Wallis.
6	DR. WALLIS: Well, I think we got a lot
7	more information than we got last time. I think that
8	a lot of people made considerable effort to present
9	things professionally.
10	The question for me is this buckling
11	analysis and how good does it have to be. We got
12	close enough to it could be a condition where you
13	wouldn't accept the results. Do we have to I have
14	to look at these things again in some detail to see
15	whether I'm satisfied or whether I want to maybe even
16	ask for some more analysis.
17	I think the buckling analysis is the most
18	important issue here, and I'm not really sure whether
19	it's adequate or not yet.
20	CHAIRMAN MAYNARD: Sam.
21	MR. ARMIJO: Okay. I was impressed, and
22	I'd like to thank AmerGen and everybody who put this
23	package together. It was exactly what we asked for.
24	As far as the information, it was well presented, easy
25	to read and that was very good.
	I contraction of the second seco

(202) 234-4433
	360
1	I think the issue, first of all, from the
2	2006 inspection, I was impressed with the condition of
3	the epoxy. It has been on there for 16 years, and I
4	really was surprised what good shape it was in.
5	I think the issue of the UT measurements
б	and all of that controversy could be sorted out by
7	having a set of data, a curve, an analysis that shows
8	as a function of area, affected area, percent of the
9	sand bed region or some parameter that's area that
10	goes from zero to 100 percent and the 100 percent
11	thinning represents the general thinning issue, and at
12	some point there will be a thickness that's acceptable
13	at five percent of the area or square foot, you know,
14	some parameters.
15	Because if it's one square foot, it could
16	be paper thin. If it's four square feet it can be
17	.256 square feet, et cetera. So some parametric
18	analysis, I think that needs to be done.
19	DR. WALLIS: You're asking for more and
20	more and more
21	MR. ARMIJO: Yeah, I don't know if that's
22	legal.
23	DR. WALLIS: buckling analysis, which
24	I'm sort of tempted to do, too, but that's a lot more
25	work for somebody.
	I Contraction of the second

(202) 234-4433

1 MR. ARMIJO: Well, I don't know, but I 2 think it needs to sort it out because we know it's a 3 variable shell. There's a lot of variability, and so 4 somewhere we're going to have to use the data. The 5 licensee is going to have to use the data to describe that shell in a way that it can be analyzed and that 6 7 we can accept, if we can.

8 Ι think the GE analysis, there's 9 controversy about their capacity factor reduction. Ι think that should be reassessed by the licensee, 10 whether it's still valid. They still believe that 11 12 that's their submission. That's what they're going to stake their claim on. 13

14 My suspicion is that they haven't taken 15 full credit for the conservatisms that they do have and that if there is a reanalysis or an update of that 16 analysis, they should use the measured data, all the 17 date, not just some arbitrary .736, but all the shell 18 19 because that thing will not buckle if half of the 20 shell is at .8 and the other half is at .95. I mean, 21 you've got to use the entire thing.

And so I think there's some analysis that needs to be done. I'm not sure whether we need anymore data.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

The last thing is I don't like to se

(202) 234-4433

25

anymore water in or aroudn that containment that isn't there on purpose, and I would never cover up that trench personally. I'd monitor that. I don't know where that water is coming from. I think you've got to find it out and make that problem, that issue disappear.

7 And I share with Mario the concern that I 8 don't know why AmerGen wants to continue living with 9 a potential of having a leakage occur from that cavity 10 liner. I would think that there ought to be a 11 rethinking about fixing that, finding some practical 12 way to repair that so that leakage just stops.

To me that would be fix the source and then you don't have to worry about the containment. Those are the kinds of things that are bothering me. So I'd like those issue raised, really, the status of the GE thing, the issue of acceptable thickness versus affected area, some sort of a presentation like that.

19 CHAIRMAN MAYNARD: Okay. Some of this, 20 the analysis that you would like to see would not be 21 possible or practical to reanalyze before our meeting. 22 I think the may thing we probably need to do and maybe 23 they can -- I don't know -- but they need to address 24 these issues at the next meeting.

MR. ARMIJO: Right, and maybe they can't

NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

25

1

2

3

4

5

6

	363
1	analyze it, but I just think that's what needs to be
2	done.
3	CHAIRMAN MAYNARD: Okay. Said.
4	DR. ABDEL-KHALIK: I agree with all the
5	comments made by my colleagues. I would like to
6	reiterate that my primary concern pertains to the
7	analysis of record submitted by the applicant and
8	whether it conforms to ASME code requirements
9	specifically as it relates to the modification of the
10	capacity reduction factors and the buckling analysis
11	of the refueling case.
12	I'd like to point out that GE pie section,
13	36 degree analysis, Mode 1 buckling result corresponds
14	to a Mode 10 buckling result for a 360 degree
15	calculation, and therefore, one cannot expect that
16	result to adequately model the entire behavior of the
17	shell specifically if the lower modes are much more
18	limiting than the higher modes.
19	Again, like my colleagues, I was sort of
20	surprised about the discovery of water between the
21	concrete floor inside the drywell and the inside
22	surface of the drywell, and I agree with Sam that I
23	think it would be a good idea not to cover that trench
24	and just make sure we monitor that and find out where
25	that water is from and how much of it is there.
	1 I I I I I I I I I I I I I I I I I I I

(202) 234-4433

	364
1	MR. ARMIJO: I wanted to add one thing.
2	I'm not so worried about the imbedded region and
3	perhaps the licensee wants to think about a simple
4	analysis of the potential for buckling when you have
5	a highly constrained junk of metal between two big
6	concrete blocks. My guess is
7	MR. SHACK: No, no. But there's a portion
8	of that where you've got the imbedded region and the
9	free region. Once it's fully imbedded
10	MR. ARMIJO: At that interface between the
11	sand bed and the imbedded regions is probably the area
12	of concern, but once you get substantial concrete on
13	both sides, I don't know what the problem is. But you
14	know, there shouldn't be water on the inside of it.
15	CHAIRMAN MAYNARD: Anything else Said?
16	DR. ABDEL-KHALIK: That's it. Thank you.
17	CHAIRMAN MAYNARD: Jack.
18	MR. SIEBER: I differ with my colleagues
19	on what ought to be done with the little trench that
20	runs around on the inside. I would like to keep the
21	water away from the steel, and so I'd fill in the
22	trench and put the curb back because it's
23	inaccessible. You can't run in and out of there
24	during operations, and so the only time you get to
25	look at it is during refueling outages.
	1

(202) 234-4433

	365
1	MR. ARMIJO: If you dry it Jack and make
2	sure the water doesn't get there some other way, I
3	totally agree with you.
4	MR. SIEBER: Well, let me point out that
5	that plant like a lot of plants was built so that the
6	drips and drains go on the floor, and they did not put
7	drain lines in and all kinds of things that direct
8	them directly to the sump. It goes to the floor
9	first. And as the floor slopes or catches up against
10	the liner, I just don't think it's a good idea to have
11	water up against that liner. So I would protect it.
12	As my second comment I made a comment
13	during our last meeting about the seismic spectral
14	response of the containment with and without the sand
15	in the sand bed region, and how GE's analysis dealt
16	with that.
17	And I've learned during this meeting that
18	the constriction of the sand bed was not considered in
19	either analysis, and so the physical removal of the
20	sand bed makes no difference in the analysis. And so
21	as far as I'm concerned, that issue is resolved.
22	We had a fair amount of discussion, and I
23	think there is at least in my own mind some confusion
24	about the differences between the Sandia model and the
25	General Electric models. I think they use different
	1

(202) 234-4433

techniques with different scales. They ended up with different results, and one of the things when you look at a pressure vessel with a complex shape like the drywell is and it has different thicknesses, you've got different acceptance criteria depending on where you are.

7 That needs to be clearly defined and 8 justified and the basis provided for that based on one 9 model and not say, "Well, if I use this model, it's 10 this, and if I use that one it's that." To me that's 11 disturbing.

I come away with an element of confusion, 12 and I don't consider that resolved at all until we 13 14 come out with a definitive set of criteria that says 15 this is the analysis of record. These are the criteria that are used, and I would like to see a 16 later technique than the General Electric technique 17 because I think modeling the whole thing with a finer 18 19 mesh in a more modern computer is a better technique. 20 And then after that occurs, then I think

21 there has to be a reassemblage of the data in 22 consideration with some of the things the ASME code 23 says. The ASME code is not a simple code, and it 24 allows one to take certain exceptions at places where 25 the cross-sectional area of the member changes

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

1

2

3

4

5

6

	367
1	dimension, and so forth, and differences between
2	elastic and plastic deformation, and that needs to be
3	figured into the acceptance criteria so that even the
4	simple person like I am can interpret it and come out
5	with the same result every time and my brother can do
6	the same thing and come out with the same answer.
7	DR. WALLIS: Could I add to that?
8	I'm not sure that the ASME code really
9	covers this complicated a situation.
10	MR. SIEBER: I think it requires some
11	interpretation. On the other hand, the ASME code
12	refers to the governing authority. All of the codes
13	do, which happens to be this agency.
14	So the interpretation of the code and the
15	application of it to a specific example like this
16	situation is the agency's responsibility to make.
17	On the other hand, they just can't
18	flippantly do it. They have to write it down and
19	provide the basis for what it is they're doing and why
20	that's the way that it should be interpreted. I think
21	that those kinds of loose ends need to be tied up in
22	order for me to feel comfortable enough with all that
23	has happened here.
24	Other than the issues with this
25	containment, I don't see other issues in the plant

(202) 234-4433

368 1 that would prevent the license renewal, but I think 2 there's plenty to chew on here with the containment. 3 And I think answers can be found to the questions that 4 I have, and I think they are parallel to a lot of 5 other people's concerns. I think they ought to be I think mine can be addressed sine it's a 6 addressed. 7 matter of explanation by the full committee meeting. 8 CHAIRMAN MAYNARD: Okay. Thank you, Jack. 9 I'd to compliment all like of the 10 presenters. Again, I think it has been a long day, a lot of good information provided. I believe that the 11 12 licensee was very responsive to our questions from the last meeting and issues and concerns that we had with 13 14 their presentation provided use a lot of qood information with good additional information always 15 comes good additional questions on our part, but I 16 think that's healthy for the overall process. 17 The NRC staff, their inspections, I was 18 19 impressed that the inspectors actually went into some 20 of these areas so that they could see for themselves. 21 These are not easy areas to get into, and again, I

22 think that shows that the staff was wanting to see for 23 themselves what the condition of the epoxy and stuff 24 was.

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

And also the public comments, again, I

(202) 234-4433

25

	369
1	believe have raised a number of questions and gives me
2	something to look at and taking some additional looks
3	at the data and perhaps generate some additional
4	questions for the staff or for the licensee.
5	Again, I think everyone did a good job.
6	Personally, I'm not bothered by some of the
7	differences between the GE and the Sandia analysis.
8	I think it's good to approach some things from
9	different ways. I think they both show that there's
10	additional conservatisms that are still in both of the
11	analyses. They're still very conservative analyses.
12	I do think we still have a question to
13	resolve as everybody else. We need to resolve whether
14	the GE analysis that took the capacity adjustments
15	into account. Is that legal? Is that appropriate and
16	find out, you know, from the licensee and from the
17	staff as to whether that's acceptable because that
18	does make a difference in what you use as what your
19	base is for your margin and for measuring things.
20	So I think that that is something that
21	definitely needs to be addressed and taken care of.
22	My last area and probably one of my
23	primary ones, I am still concerned with continuing to
24	find water and living with some leakage there, and I
25	understand the discussions and the arguments on how it

(202) 234-4433

370 1 can be managed and everything, but the reality is 2 we're supposed to be keeping water out that we don't intend to get there, and I think there needs to be 3 4 some further discussion, and I still have some 5 questions and concerns as to whether enough is being done in that area with the water. 6 7 And as far as the trenches, I believe that the trenches should be left open until we are sure 8 9 that we don't have any water. I think it's good to I think the licensee committed to 10 have them open. make sure the water was gone before they filled it in, 11 but I do think that eventually it is the right thing 12 to do to fill those in, but I think initially they do 13 14 need to be kept open for the monitoring and they're 15 there to see that we're not getting any surprises and stuff there. 16 but I agree with Jack. 17 I think in the long term -- maybe Jack would do it quicker than I 18 19 would, but I think we both would like to see those 20 covered at some point and prevent water from getting 21 into there. 22 But anyway, those are my comments. I'd 23 like to thank everyone for their participation today.

24 I hope that the staff and the licensee have from our 25 comments some ideas of some of the things we will

> NEAL R. GROSS COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

	371
1	be
2	DR. WALLIS: Can I raise a question now?
3	CHAIRMAN MAYNARD: yes.
4	DR. WALLIS: I guess this has to go to the
5	full committee. Sometimes a subcommittee can say that
б	there are big enough doubts that something needs to be
7	worked out before we go to the full committee. We are
8	on schedule. We have to go to the full committee at
9	the next meeting. Is that the case?
10	DR. BONACA: My suggestion was that if we
11	go to the full committee meeting, I think that all the
12	other aspects of license renewal are pretty much in
13	line with other applications. I think I would focus
14	the whole meeting on the two analyses.
15	DR. WALLIS: I am just wondering can we
16	resolve some of these buckling questions by the time
17	of the full committee meeting. I'm not sure we can.
18	DR. BONACA: You may be right.
19	CHAIRMAN MAYNARD: I guess feedback from
20	the table as to whether and I haven't been involved
21	in some of these in the past. I don't know if it's
22	best to delay it until we get all of those questions
23	or is it best to take it to the full committee. If
24	the questions are still unresolved, do we have another
25	meeting there and do we write an I'm not exactly

(202) 234-4433

	372
1	sure what the process is at that point.
2	MR. SIEBER: Well, I don't think the
3	subcommittee can do that on its own.
4	DR. WALLIS: We have in the past
5	sometimes, but I think in this case
6	MR. SIEBER: I think it should go to the
7	PMP.
8	DR. WALLIS: There's enough meat here that
9	we probably should go to the full committee.
10	CHAIRMAN MAYNARD: I believe it's
11	important at this state. My opinion would be take it
12	to the full committee and then based on what
13	additional discussions there, based on the full
14	committee input, determine what our next step would
15	be.
16	MR. SIEBER: I think that's wise.
17	CHAIRMAN MAYNARD: Any other comments,
18	questions?
19	(No response.)
20	CHAIRMAN MAYNARD: All right. The meeting
21	is adjourned.
22	(Whereupon, at 5:31 p.m., the meeting in
23	the above-entitled matter was concluded.)
24	
25	

(202) 234-4433