0/24/2014 18:08:00 Page 1 of 2 Document Types: IR, LER From 01/01/2009 to 12/31/2009	U.S. Nuclear Regulatory Commission Human Factors Information System (HFIS) IR/LER Category Analysis by Docket Report		Total Number of Hits:21National Average:462x National Average:92National Median:23verage for Selected Dockets:21			
Facility Name: Robinson 2 Docket (050- 00261)						
Details Communication / IR	Department	Work Type	Docket/Report			
160 - No communication / information not communicated Number of Items for this Docket: 1 Percent of Total for this Docket: 5	E - Electrical	M - Maintenance / Repair	050-00261/2009-003			
Oversight / IR						
130 - Inadequate suprevision / command and control	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
131 - Management expectations or directions LTA Number of Items for this Docket: 2 Percent of Total for this Docket: 10	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
Procedures & Reference Document / IR						
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
Number of Items for this Docket: 1 Percent of Total for this Docket: 5						
Problem Identification & Resolution / IR						
 141 - Problem not properly classified or prioritized Number of Items for this Docket: 1 Percent of Total for this Docket: 5 	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
Work Planning & Practices / IR						
183 - Pre-job activities LTA	E - Electrical	M - Maintenance / Repair	050-00261/2009-003			
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00261/2009-003			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
187 - Action implementation LTA	M - Mechanical	G - Design	050-00261/2009-003			
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00261/2009-003			
190 - Failure to stop work / non-conservative decision making	E - Electrical	M - Maintenance / Repair	050-00261/2009-003			
Number of Items for this Docket: 8 Percent of Total for this Docket: 38						
Procedures & Reference Document / LER						
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00261/2009-002-00			
Number of Items for this Docket: 1 Percent of Total for this Docket: 5						

0/24/2014 18:08:00 age 2 of 2 locument Types: IR, LER rom 01/01/2009 to 12/31/2009	U.S. Nuclear Regulatory Co Human Factors Information S IR/LER Category Analysis by D	ystem (HFIS) ocket Report 2x	Total Number of Hits:21National Average:462x National Average:92National Median:23Average for Selected Dockets:21			
Facility Name: Robinson 2 Docket (050- 00261)						
Details	Department	Work Type	Docket/Report			
Problem Identification & Resolution / LER						
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00261/2009-002-00			
Number of Items for this Docket: 1						
Percent of Total for this Docket: 5						
Training / LER						
101 - Training process problem	O - Operations	O - Control Room Ops	050-00261/2009-002-00			
Number of Items for this Docket: 1						
Percent of Total for this Docket: 5						
Work Planning & Practices / LER						
182 - Work package quality LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00261/2009-002-00			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00261/2009-002-00			
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00261/2009-002-00			
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00261/2009-002-00			
196 - Independent verification / plant tours LTA	O - Operations	O - Control Room Ops	050-00261/2009-002-00			
Number of Items for this Docket: 5						
Percent of Total for this Docket: 24						