

---

## Issue 11: Turbine Disc Cracking

### DESCRIPTION

This issue which is identified in NUREG-0705<sup>1</sup> was raised because of the discovery of stress corrosion cracking in the low pressure discs of Westinghouse-designed turbines.

### CONCLUSION

This issue is not by itself a distinct generic issue but is part of a larger already existing issue, Task Action Plan Item A-37, Turbine Missiles. Therefore, this issue is covered in Item A-37, contained in Section 2 of this report.

---

<sup>1</sup> NUREG-0705, "Identification of New Unresolved Safety Issues Relating to Nuclear Power Plant Stations," U.S. Nuclear Regulatory Commission, March 1981.

