NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS2 (2) | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (7–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000247 (7) | 101780 (8) | 111480 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During full power operation, it was observed that power range nuclear
03 instrumentation channel N42 indication was drifting. A power reduction
04 was initiated in conjunction with continued monitoring, circuitry
05 testing and incore flux mapping. Incore flux data indicated normal
06 power distribution and verified a defective detector. The channel was
07 then placed in the trip condition in accordance with Tech. Spec. 3.5.
08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 013 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN C (18) | FUTURE ACTION E (19) | EFFECT ON PLANT B (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0003 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER W120

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A Westinghouse power range detector, Model No. WL-23686, became de-
11 fective due to moisture within its connector resulting from service
12 water leakage into containment. Following replacement, the new detector
13 and cables were satisfactorily tested for resistance to ground. Further
14 testing will be accomplished when the unit is returned to power.

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Control Room Instrumentation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY: ISSUED Y (44) | DESCRIPTION (45) Related press release dated 10-21-80 | NRC USE ONLY

8011180679

John M. Makepeace 914-739-8823