PALISADES

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | LICENSEE CODE: M I P A L 1 (2) | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) | LICENSE TYPE: 4 1 1 1 1 (4) | CAT (5)

CON'T 01 | REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 2 5 5 (7) | EVENT DATE: 1 0 2 0 7 8 (8) | REPORT DATE: 1 1 1 6 7 8 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine surveillance of PCS pressure channels, the channel D pressure
03 instrument (PT-0102D) was found to be out of calibration such that the
04 RPS channel D thermal margin/low pressure trip would have occurred at
05 1745 psia instead of at a minimum of 1750 psia as required by TS Table
06 2.3.1. Remaining three channels had satisfactory trip setpoints. Event
07 had no adverse effect on public health or safety. Instrument was adjus-
08 ted to bring it to within specifications.

09 | SYSTEM CODE: I A (11) | CAUSE CODE: D (12) | CAUSE SUBCODE: E (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: T (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR: 7 8 | – | SEQUENTIAL REPORT NO.: 0 3 5 | / | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | – | REVISION NO.: 0

ACTION TAKEN: E (18) | FUTURE ACTION: G (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: F 1 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Out of calibration condition caused by zero shift. The units (Foxboro
11 model 511GM) are very temperature sensitive. An increase in ambient
12 temp of 15 deg F since the previous calibration appears to have been
13 sufficient to have caused the observed drift. To minimize chances of
14 reoccurrence, calibration frequency was changed from annually to semi-annually.

15 | FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): N/A | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Calibration results

16 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

PERSONNEL EXPOSURES

17 | NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

PERSONNEL INJURIES

18 | NUMBER: 0 0 0 (40) | DESCRIPTION (41): N/A

LOSS OF OR DAMAGE TO FACILITY (43)

19 | TYPE: Z (42) | DESCRIPTION: N/A

7811210335 S

PUBLICITY

20 | ISSUED: N (44) | DESCRIPTION (45): N/A | NRC USE ONLY

45

PALISADES

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M I P A L 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)
LICENSEE CODE 9-14 | LICENSE NUMBER 15-25 | LICENSE TYPE 26-30 | CAT 57-58

CON'T
01 REPORT SOURCE L (6) | 0 5 0 0 0 2 5 5 (7) | 1 0 2 1 7 8 (8) | 1 1 1 6 7 8 (9)
DOCKET NUMBER 61-68 | EVENT DATE 69-74 | REPORT DATE 75-80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During monthly surveillance of fire hose stations, hose station No. 26
03 was found to have a 50 foot hose instead of the required 75 foot hose.
04 Refer to TS 3.22.4.1.B. A 25 foot hose was immediately added to the hose
05 station. Because another hose station in the same area contained a 75
06 foot hose, fire fighting capabilities in this area (viewing gallery)
07 were not impaired. No hazard to public health or safety existed.
08

| | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE |
|---|---|---|---|---|---|---|
| 09 | A B (11) | A (12) | X (13) | X X X X X X (14) | Z (15) | Z (16) |

| (17) LER/RO REPORT NUMBER | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | REPORT TYPE | | REVISION NO. |
|---|---|---|---|---|---|---|---|---|
| | 7 8 | — | 0 3 6 | / | 0 3 | L | — | 0 |

| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER |
|---|---|---|---|---|---|---|---|---|
| X (18) | X (19) | Z (20) | Z (21) | 0 0 0 0 | N (23) | N (24) | Z (25) | Z 9 9 9 (26) |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The hose normally stored in the cabinet had apparently been replaced
11 with a shorter hose. The two hose segments (50 foot plus 25 foot) will
12 be replaced with a single 75 foot hose.
13
14

| | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32) |
|---|---|---|---|---|---|
| 15 | E (28) | 1 0 0 (29) | N/A | B (31) | Visual inspection |

| | ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36) |
|---|---|---|---|---|
| 16 | Z (33) | Z (34) | N/A | N/A |

PERSONNEL EXPOSURES

| | NUMBER | TYPE | DESCRIPTION (39) |
|---|---|---|---|
| 17 | 0 0 0 (37) | (38) | N/A |

PERSONNEL INJURIES

| | NUMBER | DESCRIPTION (41) |
|---|---|---|
| 18 | 0 0 0 (40) | N/A |

LOSS OF OR DAMAGE TO FACILITY (43)

| | TYPE | DESCRIPTION |
|---|---|---|
| 19 | Z (42) | N/A |

PUBLICITY

| | ISSUED | DESCRIPTION (45) | NRC USE ONLY |
|---|---|---|---|
| 20 | N (44) | N/A | |