(7-77)

LICENSEE EVENT REPORT

UPDATE REPORT - Previous Report Date [illegible]/18/78

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQ[illegible]D INFORMATION)

01 | N J S G S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

01 REPORT SOURCE | L (6) | 0 5 0 0 0 2 7 2 (7) | 1 1 3 0 7 8 (8) | 0 1 2 2 8 0 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operations while a containment entry was in progress, the inner door
03 of air lock elev. 130' would not fully open. Maintenance Department was informed
04 and the LCO for T/S 3.6.1.3.a was implemented which requires repair within 24 hours.
05 The air lock was repaired, tested and returned to service within 8 hours. This is
06 the 13th occurrence of this type. (LER's 77-58, 77-70, 77-73, 78-3, 78-27, 78-28,
07 78-45, 78-56, 78-58, 78-60, 78-66, 78-68)
08

09 SYSTEM CODE S A (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE P E N E T R (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER RO REPORT NUMBER | EVENT YEAR 7 8 | — | SEQUENTIAL REPORT NO. 0 7 5 | / | OCCURRENCE CODE 0 3 | REPORT TYPE X | — | REVISION NO. 1
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER C 3 1 0 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this occurrence was a failed cam roller on the inner door operating
11 mechanism. The cam roller was replaced and the door closing mechanism was
12 adjusted for positive door seal. During the refueling outage, the inner and outer
13 door upper hinge shaft restraint bearing supports and worn internal door parts on
14 100 and 130' elevation air locks were replaced to improve air lock operation.
7 8 9 80

15 FACILITY STATUS E (28) | % POWER 0 4 6 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Containment Entry
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A
7 8 9 10 80

20 PUBLICITY ISSUED Z (44) | DESCRIPTION (45) N/A | NRC USE ONLY
7 8 9 10 68 69 80

NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628

8 0 0 1 2 8 0 357