Unit 2 LICENSEE EVENT REPORT Report No.

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | P A P B S 2 (2) | 0 0 -0 0 0 0 0 -0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

NPT
1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 7 7 (7) | 1 1 0 1 7 9 (8) | 1 1 1 6 7 9 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | As part of the inspection program being performed in response to IE Bul-
3 | letin 79-02, an engineering review of vendor design revealed that four
4 | seismic supports associated with the 1" control rod drive piping had
5 | anchor bolts with design safety factors less than 2. Four of the six
6 | anchor bolts on each support were found to have safety factors less than
7 | 2. Failure of the supported piping would not have prevented the control
8 | rods from scramming.
8 9 80

9 | SYSTEM CODE R B (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)
8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 4 9 (24 26) | / (27) | OCCURRENCE CODE 0 1 (28 29) | REPORT TYPE T (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN F (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER B 2 0 9 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 | This non-conservative condition was caused by an engineering design
1 | deficiency. A redesign was performed and corrective actions implemented
2 | within 7 days. The anchor bolt safety factors of the above supports now
3 | exceed 2. Future rework will be performed to bring the safety factors up
4 | to 5.
8 9 80

FACILITY STATUS E (28) | % POWER 0 9 9 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) Review of Vendor design.
8 9 10 12 13 44 45 46 80

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
8 9 10 11 44 45 80

PERSONNEL EXPOSURES
NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
8 9 11 12 13 80

PERSONNEL INJURIES
NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY
TYPE Z (42) | DESCRIPTION (43) NA
8 9 10 80

PUBLICITY
ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
8 9 10 68 69 80

POOR ORIGINAL

1399 062

7911270405

NAME OF PREPARER M. J. Cooney PHONE (215) 841-5020

GPO 791-024