LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E I H 2 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

NT 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 6 (7) | 0 6 0 9 7 9 (8) | 0 6 2 1 7 9 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 With the reactor in the startup and hot standby mode, while performing HNP-2-3302
3 (HPCI Valve Operability), the 2E41-F041 valve (pump suction from suppression chamber)
4 failed to open in the specified time of 60 seconds. Technical Specification 3.0.4
5 was complied with in that the facility remained in Condition II and did not enter
6 Condition I. Public health and safety were not affected by this incident.
7
8

9 | SYSTEM CODE C F (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE V A L V E X (14) | COMP. SUBCODE E (15) | VALVE SUBCODE D (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 5 0 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT C (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER P 3 0 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The 2E41-F041 valve failed due to a loose connection in the shunt field circuit,
11 which caused the motor winding to overheat and burn. The loose connection, located
12 at the internal side of the motor control center terminal block, was tightened and
13 the motor replaced. The valve was then tested and found satisfactory.
14

5 | FACILITY STATUS B (28) | % POWER 0 0 1 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

271 136

8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

7907020 308 S

9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER R. T. Nix, Supt. of Maintenance PHONE: 912-367-7781