NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | A L J M F 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 4 8 (7) | 0 2 2 2 7 9 (8) | 0 3 2 2 7 9 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1125 on 2/22/79, an Assistant Plant Operator discovered that the B1F sequencer was
0 3 | in the test mode thereby rendering the 1-2A D/G inoperable. (The B1F sequencer had
0 4 | been tested satisfactorily on 2/21/79.) The 1B D/G was out of service for preventative
0 5 | maintenance. Therefore, both sets of D/G required by Tech. Spec. 3.8.1.1b were not
0 6 | available. Tech. Spec. 3.8.1.1d action statement requirements were met. The 1-2A
0 7 | D/G and 1B D/G were returned to an operable status at 1200 and 2212 respectively on
0 8 | 2/22/79. The health and safety of the general public were not affected.
7 8 9 80

0 3 | SYSTEM CODE E E (11) | CAUSE CODE E (12) | CAUSE SUBCODE X (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER [EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 1 3 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0]
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN B (18) | FUTURE ACTION A (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER G 0 8 0 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The B1F sequencer being in the test mode is attributable to a faulty switch mechanism
1 1 | which would allow the sequencer to change modes when the sequencer cabinet was bumped.
1 2 | The B1F sequencer was returned to normal and repairs were made to prevent it from
1 3 | inadvertently going to the test mode.
1 4 |
7 8 9 80

1 5 | FACILITY STATUS F (28) | % POWER 0 9 4 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Assistant Plant Operator Observation
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA
7 8 9 10 80

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA
7 8 9 10 68 69 80

7903280318

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III PHONE: (205) 399-5156

GPO 814-7-926