UNIT 2 LICENSEE EVEN REPORT Report No. 2-80-8/1T

8005120452

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(1) PAPBS2 (2) 00-00000-00 (3) 4111111 (4) (5)
LICENSEE CODE (14) (15) LICENSE NUMBER (25) (26) LICENSE TYPE (30) (57) CAT (58)

ON'T
(1) REPORT SOURCE L (6) 050-027 (7) 041780 (8) 050180 (9)
(60) (61) DOCKET NUMBER (68) (69) EVENT DATE (74) (75) REPORT DATE (80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(2) Safety factor less than acceptable. As requested in IE Bulletin 79-01B,
(3) environmental conditions associated with high energy line breaks were
(4) made indicating that a guillotine failure of HPCI steam supply piping
(5) in outboard isolation valve room would result in pressure peaks that
(6) could affect the integrity of a concrete block wall (safety factor of
(7) approximately 1.4 as reanalyzed.). The block wall supports conduit
(8) containing some engineered safeguard cables.
(8) (9) 80

(9) SYSTEM CODE SF (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
(8) (9) (10) (11) (12) (13) (18) (19) (20)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 (21)(22) | — (23) | SEQUENTIAL REPORT NO. 008 (24)(25)(26) | / (27) | OCCURRENCE CODE 01 (28)(29) | REPORT TYPE T (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN F (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 (37)(38)(39)(40) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER Z999 (26)
(33) (34) (35) (36) (41) (42) (43) (44) (47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(10) Cause was a refined calculation. Immediate corrective action on
(11) Unit 3 consisted of throttling steam line isolation valves (75% closed),
(12) proving HPCI quick start capability and daily visual inspection of area
(13) for steam leaks. Further analysis allowed reopening of isolation valves -
(14) modifications will be made to achieve an acceptable safety factor.
(8) (9) 80

FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) U/3 - 100% Power | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) Notification from AE
(8) (10) (12) (13) (44) (45) (46) 80

ACTIVITY CONTENT
RELEASED OF RELEASE Z (33) | Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
(8) (9) (10) (11) (44) (45) 80

PERSONNEL EXPOSURES
NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
(8) (9) (11) (12) (13) 80

PERSONNEL INJURIES
NUMBER 000 (40) | DESCRIPTION (41) NA
(8) (9) (11) (12) 80

LOSS OF OR DAMAGE TO FACILITY (42)
TYPE Z (42) | DESCRIPTION NA
(8) (9) (10) 80

PUBLICITY
ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
(8) (9) (10) (68) (69) 80

NAME OF PREPARER M. J. Cooney PHONE: (215) 841-5020

GPO 917-826