(7-77)

UPDATE REPORT-PREVIOUS REPORT DATE: 01-22-79

LICENSEE EVENT REPORT

8004280 416

CONTROL BLOCK: [| | | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
0 1	LICENSEE CODE (2)	M D C C N 2
	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
	LICENSE TYPE (4)	4 1 1 1 1
	CAT (5)	
CON'T 0 1	REPORT SOURCE (6)	L
	DOCKET NUMBER (7)	0 5 0 0 0 3 1 8
	EVENT DATE (8)	0 1 2 0 7 9
	REPORT DATE (9)	0 4 2 5 8 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation 22A RCP lower seal temperature alarm was received at
0 3 0129. An approx. 2 gpm increase in RCS leak rate was also noted. The reactor
0 4 was manually tripped at 0143 when increasing lower seal temperature exceeded
0 5 195°F. An inspection of 22A RCP revealed a cracked weld on the pump's lower
0 6 seal pressure sensing line. Due to increased bleedoff flow and fluctuating
0 7 seal pressure the decision was made to replace seal assembly. LER's 77-15
0 8 (U-1) and 79-01 (U-2) describe similar events.

0 9	SYSTEM CODE (11)	CAUSE CODE (12)	CAUSE SUBCODE (13)	COMPONENT CODE (14)	COMP. SUBCODE (15)	VALVE SUBCODE (16)
	C B	B	A	P I P E X X	A	Z

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	7 9	—	0 0 3	/	0 1	X	—	2

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
F	Z	A	B	0 1 2 0	N	N	N	B 5 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The pump seal was replaced and the pump was returned to service. A complete
1 1 redesign of the RCP seal pressure sensing lines and their supports has been
1 2 done and the modifications have been completed. Observation of these lines
1 3 will continue, but the problem appears to have been corrected.
1 4

1 5	FACILITY STATUS (28)	% POWER (29)	OTHER STATUS (30)	METHOD OF DISCOVERY (31)	DISCOVERY DESCRIPTION (32)
	E	0 9 0	NA	A	Operator Observation

1 6	ACTIVITY RELEASED (33)	CONTENT OF RELEASE (34)	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
	Z	Z	NA	NA

PERSONNEL EXPOSURES

1 7	NUMBER (37)	TYPE (38)	DESCRIPTION (39)
	0 0 0	Z	NA

PERSONNEL INJURIES

1 8	NUMBER (40)	DESCRIPTION (41)
	0 0 0	NA

LOSS OF OR DAMAGE TO FACILITY (43)

1 9	TYPE (42)	DESCRIPTION
	Z	NA

PUBLICITY

2 0	ISSUED (44)	DESCRIPTION (45)	NRC USE ONLY
	N	NA	

NAME OF PREPARER J. T. Carroll/D. E. Huseby PHONE: (301)269-4738/4816

GPO 917-926