LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (PLEASE PRINT ALL REQUIRED INFORMATION)

7 8	LICENSEE NAME	LICENSE NUMBER	REPORT TYPE	EVENT TYPE
01	NJOCP	00-00000-0	11111	01

7 8	CONT	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01	CONT		L	L	050-021	040777	042977

EVENT DESCRIPTION

On April 7, 1977, at 1140 hours, a secondary containment capability test was performed following the installation of a penetration through the reactor building wall. The test results indicated a failure of the secondary containment to demonstrate the capability to maintain a .250 inches of water vacuum under calm wind conditions with a standby gas treatment system filter train flow of not more than 4,000 CFM. (50-219/77-7-3L)

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
SA	E	ZZZZZZ	N	Z999	Y

CAUSE DESCRIPTION

The cause of the low vacuum condition was traced to air in leakage through the reactor building roof manway which is an airlock with an inner and outer door. The inner door was found to be not fully closed and the outer door had excessive (SEE BELOW)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
E	073	N/A	C	Secondary Containment Tes

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	Z	N/A	N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z	N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION
000	N/A

Probable Consequences

N/A

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
	N/A

POOR ORIGINAL

PUBLICITY

N/A

8103040216

ADDITIONAL FACTORS - CAUSE DESCRIPTION (Continued)

leakage. This was attributed to the door gasket, which had deteriorated with age. An investigation is being made to improve seal gaskets. The latching mechanism will be locked.

NAME: Donald A. Ross, Manager-Gen.Sta.-Nuc. PHONE: 201-539-6111