NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

UPDATE REPORT-PREVIOUS REPORT DATE 04-24-79

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 1 | LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT |
|---|---|---|---|---|
| | M I D C C 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5) |

CON'T

| 0 1 | REPORT SOURCE | DOCKET NUMBER | EVENT DATE | REPORT DATE |
|---|---|---|---|---|
| | L (6) | 0 5 0 0 0 3 1 5 (7) | 0 3 2 6 7 9 (8) | 0 4 2 3 8 1 (9) |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE IN MODE 1, THE INDICATED POSITION OF ROD F-6 WAS DISCOVERED TO HAVE EXCEEDED
0 3 THE TWELVE STEP LIMIT IMPOSED BY T.S. 3.1.3.2. DURING THE TWO DAYS SUBSEQUENT TO
0 4 THE FIRST OCCURRENCE, THE PROBLEM RECURRED FOUR ADDITIONAL TIMES. THE ROD POSITION
0 5 INDICATION (RPI) FOR F-6 WAS DECLARED INOPERABLE ON 3-28-79 DUE TO A SUSPECTED
0 6 PROBLEM WITH THE CONNECTOR AT THE COIL STACK.
0 7
0 8

| 0 9 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE |
|---|---|---|---|---|---|---|
| | I E (11) | E (12) | A (13) | I N S T R U (14) | X (15) | Z (16) |

(17) LER/RO REPORT NUMBER

| EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | REPORT TYPE | | REVISION NO. |
|---|---|---|---|---|---|---|---|
| 7 9 | — | 0 2 4 | / | 0 3 | X | — | 1 |

| ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER |
|---|---|---|---|---|---|---|---|---|
| A (18) | Z (19) | Z (20) | Z (21) | 0 0 0 0 | N (23) | Y (24) | N (25) | W 1 2 0 (26) |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE INVESTIGATION REVEALED THAT ONE OF THE WIRES AT THE CONNECTOR TO THE COIL STACK
1 1 FOR ROD F-6 WAS BROKEN AND MAKING INTERMITTENT CONTACT. THE CONNECTOR WAS REPLACED
1 2 AND THE F-6 ROD POSITION INDICATION WAS CALIBRATED AND VERIFIED OPERABLE ON 4-13-79.
1 3 DURING THE INOPERABLE PERIODS THE ACTION REQUIREMENTS OF T.S. 3.1.3.2. WERE FULFILLED.
1 4

| 1 5 | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32) |
|---|---|---|---|---|---|
| | E (28) | 1 0 0 (29) | NA | A (31) | OPERATOR OBSERVATION |

| 1 6 | ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36) |
|---|---|---|---|---|
| | Z (33) | Z (34) | NA | NA |

PERSONNEL EXPOSURES

| 1 7 | NUMBER | TYPE | DESCRIPTION (39) |
|---|---|---|---|
| | 0 0 0 (37) | Z (38) | NA |

PERSONNEL INJURIES

| 1 8 | NUMBER | DESCRIPTION (41) |
|---|---|---|
| | 0 0 0 (40) | NA |

LOSS OF OR DAMAGE TO FACILITY (43)

| 1 9 | TYPE | DESCRIPTION |
|---|---|---|
| | Z (42) | NA |

POOR ORIGINAL

PUBLICITY

| 2 0 | ISSUED | DESCRIPTION (45) | NRC USE ONLY |
|---|---|---|---|
| | N (44) | NA | |

8104280441

NAME OF PREPARER S. D. DELONG PHONE: 616-465-5901