LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Field	Value
01 Licensee Code (2)	C A S O S 1
License Number (3)	0 0 - 0 0 0 0 0 - 0 0
License Type (4)	4 1 1 1 0
Cat (5)	
CON'T 01 Report Source (6)	L
Docket Number (7)	0 5 0 0 0 2 0 6
Event Date (8)	0 6 3 0 8 1
Report Date (9)	0 7 0 6 8 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 ERRONEOUS FEEDWATER FLOW INDICATIONS PRODUCED INDICATED POWER LEVELS BELOW
03 ACTUAL POWER LEVELS. HAD A POWER EXCURSION ACCIDENT OCCURRED DURING THIS PERIOD
04 THE REACTOR WOULD HAVE TRIPPED AT OR BELOW THE POWER ASSUMED IN THE FSA.

09	Value
System Code (11)	C M
Cause Code (12)	B
Cause Subcode (13)	C
Component Code (14)	I N S T R U
Comp. Subcode (15)	X
Valve Subcode (16)	Z

(17) LER/RO Report Number	Value
Event Year	8 1
	—
Sequential Report No.	0 1 4
	/
Occurrence Code	0 3
Report Type	L
	—
Revision No.	0

Field	Value
Action Taken (18)	G
Future Action (19)	E
Effect on Plant (20)	A
Shutdown Method (21)	A
Hours (22)	0 0 2 4
Attachment Submitted (23)	N
NPRD-4 Form Sub. (24)	N
Prime Comp. Supplier (25)	N
Component Manufacturer (26)	H 0 1 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A FEEDWATER FLOW ORIFICE WAS FOUND TO BE IN BACKWARDS. THE ORIFICE WAS REMOVED
11 INSPECTED, AND INSTALLED PROPERLY. ANOTHER FEEDWATER LINE WAS FOUND TO HAVE
12 EXCESSIVE VIBRATION WHICH CAUSED THE DIFFERENTIAL PRESSURE METER TO READ LOW. THE
13 VIBRATION WAS ELIMINATED BY PLACING THE FEEDWATER VALVE CONTROL IN MANUAL. FEEDWATER
14 CONTROL WAS RETURNED TO AUTO AFTER OPENING THE BYPASS VALVE. PERMANENT REPAIRS TO THE VALVES VIBRATION DAMPENER ARE PLANNED.

15	Value
Facility Status (28)	B
% Power (29)	0 9 1
Other Status (30)	NA
Method of Discovery (31)	B
Discovery Description (32)	CALIBRATION

16	Value
Activity Released (33)	
Content of Release (34)	Z
Amount of Activity (35)	NA
Location of Release (36)	NA

17 Personnel Exposures	Value
Number (37)	0 0 0
Type (38)	Z
Description (39)	NA

18 Personnel Injuries	Value
Number (40)	0 0 0
Description (41)	NA

19 Loss of or Damage to Facility	Value
Type (42)	Z
Description (43)	NA

20 Publicity	Value
Issued (44)	N
Description (45)	NA

NRC USE ONLY

8108050145 810706
PDR ADOCK 05000206
S PDR

NAME OF PREPARER J. M. CURRAN PHONE 714-492-7700

GPO 917-926