LICENSEE EVENT REPORT

Unit 1

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-000-00 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE (9–14) LICENSE NUMBER (15–25) LICENSE TYPE (26) CAT (57)

CON'T
01 | REPORT SOURCE L (6) | 05000327 (7) | 050282 (8) | 052882 (9)
DOCKET NUMBER (60–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 1 (100% power, 577 degrees F, 2240 psig) at 0100 CST on 05/02/82,
03 one auxiliary feedwater automatic control valve was declared inoperable due to
04 failure to meet surveillance requirements. This event placed the unit in action
05 statement (a) of LCO 3.7.1.2. There was no effect upon public health and safety.
06 Previous occurrences: none.
07
08

09 SYSTEM CODE WB (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 056 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER C753

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Control valve 1-LCV-3-175 failed to open on demand due to a faulty signal from the
11 pipe break detection pressure switch, 1-PS-3-165B. The pressure switch was found
12 to have a broken micro switch actuator. The cause for the defective dual snap
13 (custom components) model 604GCJR3-5405 pressure switch is unknown. The switch was
14 replaced and the valve returned to service at 1610 CST on 05/02/82. No additional
corrective action will be taken at this time.

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION NA

8206070188 820528
PDR ADOCK 05000327
S PDR

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

Name of Preparer H. R. Rogers./M. R. Harding Phone (615) 751-0349