NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CASO S2 (2) | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (14) | LICENSE NUMBER (25) | LICENSE TYPE (30) | CAT (58)

CON'T
01 | REPORT SOURCE L (6) | 05000361 (7) | 082682 (8) | 082782 (9)
DOCKET NUMBER (68) | EVENT DATE (74) | REPORT DATE (80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Review of Tech. Spec. tank levels resulted in the conclusion that the minimum allowable
03 RWST level is actually 87.5% rather than the 75% stated in procedures S023-3-3.25 and
04 S023-3-3.27. A review of records revealed that tank level had been reduced for
05 several periods below the 87.5% level to as low as 80%. This was not consistent with
06 the minimim water volume requirements established by the safety analysis and reflected
07 in Tech. Spec. 3.5.4. No events have occurred which called for substantial water use
from the RWST. Hence, plant operations were not affected and there was no effect on
08 the public health and safety.

09 | SYSTEM CODE SF (11) | CAUSE CODE D (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 073 | / | OCCURRENCE CODE 01 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN G (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Error in specification of the minimum level in procedures was the result of mis-
11 interpretation of the words "ECCS suction connection" and a failure to cross-check
12 the specified level against the applicable safety analysis. The surveillance Pro-
13 cedures S023-3-3.25 and S023-3-3.27 were changed to require the tank to be maintained
14 at least 88% full. Also, the water level was increased to meet this requirement.

15 | FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) Setpoint Review

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) N/A

8209080193 820827
PDR ADOCK 05000361
S PDR

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER H.B. RAY PHONE: 714-492-7700

GPO 917-926