LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CASO2 (2) | 00-0000-00 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T

01 | REPORT SOURCE L (6) | 05000361 (7) | 071782 (8) | 081882 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 3 during troubleshooting in cabinets to locate a Ground Pressurizer
03 Heater Control was lost for 2 - 3 minutes. The loss of Heater Control from the
04 Control Room has no significant consequence to the health and safety of the public
05 since local control was available.
06
07
08

09 | SYSTEM CODE IC (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE RELAYX (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 036 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 1

ACTION TAKEN F (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of failure was due to the fact that the High High trip relay was
11 wired such that it would have tripped the heaters when de-energized. A temporary
12 corrective measure was initiated promptly to disable this relay. A permanent change
13 will be implemented by rewiring within Cabinet RL071-IR to enable the operator to
override the high pressure control function contacts relay by placing Control Room
14 manual switches in the ON position.

15 | FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8209140231 820831
PDR ADOCK 05000361
S PDR

NRC USE ONLY

NAME OF PREPARER H. B. Ray HB Ray / M Murphy PHONE 714/492-7700