(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T
01 REPORT SOURCE: L (6) | 05000311 (7) | 082382 (8) | 091682 (9)
DOCKET NUMBER (61–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1400 hours, August 23, 1982, during surveillance testing, it was discovered that
03 the 130' Elevation Containment Air Lock inner door had excessive leakage past the
04 seals. The air lock was declared inoperable and Action Statement 3.6.1.3 was entered
05 at 1400 hours. The outer door was operable and maintained closed in compliance with
06 the Action Statement.
07
08

09 SYSTEM CODE: SA (11) | CAUSE CODE: A (12) | CAUSE SUBCODE: B (13) | COMPONENT CODE: PENETR (14) | COMP. SUBCODE: A (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | SEQUENTIAL REPORT NO. 102 | OCCURRENCE CODE 03 | REPORT TYPE L | REVISION NO. 0

ACTION TAKEN: H (18) | FUTURE ACTION: F (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: C130 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The seal was damaged by personnel closing the door with excessive force. The seal
11 was replaced and the door was satisfactorily tested. The air lock was declared
12 operable and Action Statement 3.6.1.3 was terminated at 1500 hours, August 23, 1982.
13 Personnel are being trained in proper operation of air lock doors.. Design Change
14 Requests have been submitted to install snubbers on the doors.

15 FACILITY STATUS: E (28) | % POWER: 081 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Surveillance Testing

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
17 NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES
18 NUMBER: 000 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY
20 ISSUED: N (44) | DESCRIPTION (45): NA

8210010461 820916
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER: R. Heller PHONE: 609/935-6000 Ext 3078