

General Information or Other (PAR)

Event # 44322

<b>Rep Org:</b> FISHER CONTROLS INTERNATIONAL, LLC	<b>Notification Date / Time:</b> 06/27/2008 16:51 (EDT)
<b>Supplier:</b> FISHER CONTROLS INTERNATIONAL, LLC	<b>Event Date / Time:</b> 06/27/2008 (CDT)
	<b>Last Modification:</b> 06/27/2008
<b>Region:</b> 3	<b>Docket #:</b>
<b>City:</b> MARSHALLTOWN	<b>Agreement State:</b> Yes
<b>County:</b>	<b>License #:</b>
<b>State:</b> IA	
<b>NRC Notified by:</b> BILL FITZGERALD	<b>Notifications:</b> CHRISTINE LIPA R3
<b>HQ Ops Officer:</b> JOHN KNOKE	KATHLEEN O'DONOHUE R2
<b>Emergency Class:</b> NON EMERGENCY	VERN HODGE NRR
<b>10 CFR Section:</b>	OMID TABATABAI NRO
21.21 UNSPECIFIED PARAGRAPH	MARK CUNNINGHAM NRR

PART 21 NOTIFICATION - PERFORMANCE AFFECTED ON 3" CL150 FISHER V150 VALVE ASSEMBLIES

"Purpose:

The purpose of this Fisher Information Notice (FIN) is to alert FPL that as of 20 June, 2008, Fisher Controls International LLC became aware of the possibility of a situation which may affect the performance of the applicable equipment.

"Equipment Affected by This Information Notice:

Items provided to FPL - Turkey Point per Fisher Order Number 010-A001017058, Item 0001, (FPL Order 00108848, Rev. 3). This equipment included 3" CL150 Fisher V150 valve assemblies (quantity 2). The equipment is identified by Fisher Serial Numbers 18497294 and 18497295 (FPL Tag Number 04224971).

"Applicability:

This notice applies only to the subject equipment supplied by Fisher Controls International LLC, identified above, that was provided to FPL-Turkey Point. Fisher Controls has determined that the subject items did not meet the material requirements specified by the FPL Order 00108848, Rev. 3. Specifically the discrepancies are:

- \* TFE packing was provided instead of graphite packing.
- \* TCM seal rings were provided instead of HD metal seal rings.

The difference in these parts will also require that a different seal protector ring be provided."

\*\*\*\*\*

IE19  
NRR



## Facsimile

301 South First Avet  
Marshalltown, IA 50158

T 641-754-2688  
F 641-754-2645

---

NRC

To: Vern Hodge

Fax: 301-816-5151

Trish Crosser (754-2688)

From: Executive Assistant for Quality

Date: 6/27/2008

Pages: 1  
(incl cover)

---

Attached is notification of a recent FIN Notice:

FIN 2008-01

Fisher Order 010-A001017058

For questions contact:

Matthew Farrell  
QA Manager  
Codes & Standards  
Fisher Valve Division  
Matthew.farrell@emerson.com  
Phone: (641) 754-3342



Fisher Controls International LLC  
301 South First Ave.  
P.O. Box 190  
Marshalltown, Iowa 50158-0190  
USA  
T (641) 754-3011  
F (641) 754-2830

**Fisher Information Notice: FIN 2008-01**

**June 26, 2008**

**Subject: Fisher Order 010-A001017058 for FPL-Turkey Point**

**From:**

Bill Fitzgerald  
Nuclear Business Unit Director and General Manager  
Fisher Controls International LLC  
205 South Center Street  
Marshalltown, IA 50158  
Fax: (641) 754-2854

**Equipment Affected By This Information Notice:**

***Items provided to FPL – Turkey Point per Fisher Order Number 010-A001017058, Item 0001, (FPL Order 00108848, Rev. 3). This equipment included 3" CL150 Fisher V150 valve assemblies (quantity 2). The equipment is identified by Fisher Serial Numbers 18497294 and 18497295 (FPL Tag Number 0422497 1).***

**Purpose:**

The purpose of this Fisher Information Notice (FIN) is to alert FPL that as of 20 June, 2008, Fisher Controls International LLC became aware of the possibility of a situation which may affect the performance of the applicable equipment.

We are informing you of this circumstance in accordance with Section 21.21 (b) of 10CFR21.

**Applicability:**

This notice applies only to the subject equipment supplied by Fisher Controls International LLC, identified above, that was provided to FPL-Turkey Point.



## **Fisher Information Notice: FIN 2008-01**

### **Discussion**

Fisher Controls has determined that the subject items did not meet the material requirements specified by the FPL Order 00108848, Rev. 3.

Specifically the discrepancies are:

- TFE packing was provided instead of graphite packing.
- TCM seal rings were provided instead of HD metal seal rings. The difference in these parts will also require that a different seal protector ring be provided.

We are reviewing the situation and will pursue a corrective action investigation to prevent problems like this in the future.

### **Action Required**

- Contact our Fisher Controls Local Business Partner to arrange for modification or replacement of these constructions.
- Contact Information is:  
Jim Fesl or Kevin Miller  
Key Controls Corporation  
Suite 1  
Lakeland, FL 33811  
863-583-0071 (Office)  
863-583-0273 (Fax)

### **10CFR21 Implications:**

Fisher Controls requests that the recipient of this notice review it and take appropriate action in accordance with 10CFR21.

If there are any technical questions or concerns, please contact:

Michael Wedemeyer  
Manager, Quality  
Fisher Controls International LLC  
205 South Center Street  
Marshalltown, IA 50158  
Fax: (641) 754-2854

