

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



Robert J. Barrett
Site Executive Officer

February 23, 2000
IPN-00-014

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
State Pollutant Discharge Elimination System (SPDES) Permit

Dear Sir:

Indian Point 3 Non-Radiological Environmental Protection Plan, Appendix B, Section 3.2 of the Technical Specifications requires that violations of the SPDES Permit be reported to the NRC by the submittal of a copy of the reports required by the SPDES Permit. The NRC staff requested notification of excursions from the SPDES Permit effluent limits, regardless of whether or not the excursion resulted in a Notice of Violation by the New York State Department of Environmental Conservation (NYSDEC). Accordingly, Attachment I to this letter provides a copy of the cover letters and Report of Noncompliance Event submitted to the NYSDEC for those months in 1999 in which there were reported excursions.

If you or your staff have any questions regarding this matter, please contact Mr. K. Peters (914) 736-8029.

The Authority is making no commitments in this letter.

Very truly yours,



Robert J. Barrett
Site Executive Officer
Indian Point 3 Nuclear Power Plant

Attachment

COO1

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

Mr. George F. Wunder, Project Manager
Project Directorate I-1
Division of Reactor Projects – I/II
U.S. Nuclear Regulatory Commission
Mail Stop 8 C4
Washington, DC 20555

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

February 22, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of January 1999. Two separate event reports are attached for noncompliances which occurred at the New York Power Authority Unit 3 Facility. One of the noncompliance reports documents an occurrence from November 1998 that was omitted from the November 1998 submittal.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,

Roger G. Keppel for
Christopher English
Christopher English
Env. Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

SECTION 1

*New York State Department of Environmental Conservation
Division of Water*



Report of Noncompliance Event

To: DEC Water Contact Cesare Manfredi DEC Region: 3

Report Type: 5 Day Permit Violation Order Violation Anticipated Noncompliance Bypass/Overflow

SECTION 2

SPDES #: NY-0004472 Facility: New York Power Authority - Indian Point 3

Date of Noncompliance: 11/19/98 Location (Outfall, Treatment Unit, or Pump Station): Outfall

Description of Noncompliance(s) and cause(s): Sewage line discovered overflowing into a storm drain which empties into the discharge canal. This was caused by blown fuses which tripped the lift station pumps, resulting in the wage sewage collecting in the lower lift station and then overflowing. There was also confusion regarding the repair of the fuses and restoring pump operation (on-coming shift believed the pumps were back in service).

Has event ceased? (Yes) (No) If so, when? 11/19/98 Was event due to plant upset? (Yes) (No) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: 11/19/98 ? (AM) (PM) End date, time of event 11/19/98 10:00 (AM) (PM)

Date, time oral notification made to DEC? 11/20/98 08:00 (AM) (PM) DEC Official contacted: Hotline

Immediate corrective actions: Fuses were replaced and the sewage pumps reset. Also any material which had not reached the drain was cleaned up.

Preventive (long term) corrective actions: Individuals involved in confusion about repair and restoration were counseled regarding the importance of turning over accurate information on equipment status.

SECTION 3

Complete this section if the event was a bypass:

Bypass Amount: _____ Was prior DEC authorization received for this event? (Yes) (No)
DEC Official contacted: _____ Date of DEC approval: _____

Describe event in "description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.


SECTION 4

Facility Representative: Ken Peters Title: Licensing Manager Date: 2/3/99

Phone #: (914) 736-8029 Fax #: (914) 736-8769

SECTION 1

*New York State Department of Environmental Conservation
Division of Water*



Report of Noncompliance Event

To: DEC Water Contact Cesare Manfredi DEC Region: 3

Report Type: 5 Day Permit Violation Order Violation Anticipated Noncompliance Bypass/Overflow

SECTION 2

SPDES #: NY-0004472 Facility: New York Power Authority – Indian Point 3

Date of Noncompliance: 1/15/99 Location (Outfall, Treatment Unit, or Pump Station): Outfall

Description of Noncompliance(s) and cause(s): On 1/15/99 a utility vehicle transmission leak was observed to be leaking To the ground. Due to adverse weather conditions (heavy rainfall) the transmission fluid was washed into the Storm darain system and subsequently the discharge canal. The volume leaked was approximately one quart.

Has event ceased? (Yes) (No) If so, when? 1/15/99 Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: 01/15/99 12:20 (AM) (PM) End date, time of event 01/15/99 12:30 (AM) (PM)

Date, time oral notification made to DEC? 01/15/99 13:50 (AM) (PM) DEC Official contacted: Helen Operator 322

Immediate corrective actions: The vehicle was removed from service and taken off-site for repairs. A clean up of the ground was conducted, and oil absorbent boom placed in the discharge canal.

Preventive (long term) corrective actions: No long term corrective actions are considered necessary due to the nature of this spill and the maintenance presently performed on the vehicle.

SECTION 3

Complete this section if the event was a bypass:

BypassAmount: _____ Was prior DEC authorization received for this event? (Yes) (No)
DEC Official contacted: _____ Date of DEC approval: _____

Describe event in "description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: Ken Peters Title: Licensing Manager Date: _____

Phone #: (914) 736-8029 Fax #: (914) 736-8769

March 15, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of February 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher English".

Christopher English
Env. Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa

April 19, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of March 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher English".

Christopher English
Env. Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa

May 26, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099.

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:


Enclosed are the Discharge Monitoring Reports (DMR) for the month of April 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

On April 7th at 9:16 a.m. the continuous temperature recorder measuring the total facility discharge canal was removed from service for Y2K testing and was returned to service 5 1/2 hours later. There was no indication that there was significant variation of discharge canal temperature during this time period based on the readings indicated prior to removal from service and the readings indicated following return to service.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,



Christopher English
Env. Manager
Indian Point Station

June 23, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: *Monthly Discharge Monitoring Report*
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of May 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher English", is written over a horizontal line.

Christopher English
Env. Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa

June 29, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

In March 1999 Outfall 001L exceeded the Action Level of 4 milligrams/liter for Iron. The reported value was 9.4 milligrams/liter. In response, a short-term, high-intensity monitoring program was implemented. The result of this program is enclosed.

If you have any questions regarding this submission, please contact Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,

A handwritten signature in black ink, appearing to read "Christopher English".

Christopher English
Env. Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

A. Alan Blind
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5718
blindaa@coned.com

July 27, 1999

NYSDEC - *Division of Water*
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: *Monthly Discharge Monitoring Report*
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of June 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,


A. Alan Blind

Enc.

A. Alan Blind
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5718
blindaa@coned.com

August 26, 1999

NYSDEC - *Division of Water*
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: *Monthly Discharge Monitoring Report*
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of July 1999. A Report of noncompliance Event is attached for a noncompliance which occurred at New York Power Authority Unit 3 facility.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns Manager of Chemistry at (914) 734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,



A. Alan Blind
Vice President
Nuclear Power

Enc.

SECTION 1

*New York State Department of Environmental Conservation
Division of Water*



Report of Noncompliance Event

To: DEC Water Contact Cesare Manfredi DEC Region: 3

Report Type: 5 Day Permit Violation Order Violation Anticipated Noncompliance Bypass/Overflow

SECTION 2

SPDES #: NY-0004472 Facility: New York Power Authority – Indian Point 3

Date of Noncompliance: 7/23/99 Location (Outfall, Treatment Unit, or Pump Station): Outfall 001

Description of Noncompliance(s) and cause(s): Overflow from the warehouse sewage holding pit entered a storm drain which empties into the discharge canal.

Has event ceased? (Yes) (No) If so, when? 11:30 Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: 7/23/99 11:30 (AM) (PM) End date, time of event 7/23/99 11:30 (AM) (PM)

Date, time oral notification made to DEC? 7/23/99 12:00 (AM) (PM) DEC Official contacted: Hotlines & C. Manfredi

Immediate corrective actions: Secured the source of the sewage and pumped out the holding pit.

Preventive (long term) corrective actions: Repaired the toilet causing the high flow condition (repair completed).
Evaluating additional protection options, such as high level alarm and piping this sewage holding pit into the site sewage system.

SECTION 3

Complete this section if the event was a bypass:

Bypass Amount: _____ Was prior DEC authorization received for this event? (Yes) (No) _____
DEC Official contacted: _____ Date of DEC approval: _____

Describe event in "description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: Ken Peters Title: Licensing Manager Date: 8/5/99

Phone #: (914) 736-8029 Fax #: (914) 736-8769

September 24, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of August 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,

A handwritten signature in black ink, appearing to read "Keith Barouch", written over a horizontal line.

Keith Barouch
Env., Health & Safety Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa

October 20, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of September 1999. A Report of noncompliance Event is attached for a noncompliance which occurred at New York Power Authority Unit 3 facility.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914)736-8452.

Very truly yours,

A handwritten signature in black ink, appearing to read "Keith Barouch".

Keith Barouch
Environmental Health & Safety Manager
Indian Point Station
Con Edison Units 1 & 2

Attachment

/paa

November 24, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of October 1999. A Report of Noncompliance Event is attached.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,

A handwritten signature in black ink that reads "Roger Keppel for K. Barouch". The signature is written in a cursive style and is positioned above a horizontal line.


Keith Barouch
Env., Health & Safety Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa

SECTION 1

New York State Department of Environmental Conservation
Division of Water



Report of Noncompliance Event

To: DEC Water Contact CESARE MANFREDI DEC Region: 3

Report Type: 5-Day Permit Violation Order Violation Anticipated Noncompliance Bypass/Overflow

SECTION 2

SPDES #: NY0004473 Facility: CON EDISON - IP2

Date of noncompliance: 10/20/99 Location (Outfall, Treatment Unit, or Pump Station): OUTFALL

Description of noncompliance(s) and cause(s): SEE ATTACHED

Has event ceased? Yes (No) If so, when? _____ Was event due to plant upset? (Yes) No SPDES limits violated? Yes (No)

Start date, time of event: 10/20/99, 00:00 (AM) (PM) End date, time of event: 10/20/99, 23:59 (AM) (PM)

Date, time oral notification made to DEC? / / (AM) (PM) DEC Official contacted: _____

Immediate corrective actions: NONE

Preventive (long term) corrective actions: SEE ATTACHED

SECTION 3

Complete this section if event was a bypass:

Bypass amount: _____ Was prior DEC authorization received for this event? (Yes) (No)

DEC Official contacted: _____ Date of DEC approval: / /

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: Keith Barouch Title: EH&S Section Manager Date: 11, 24, 99

Phone #: (914) 734-5674 Fax #: (914) 737-6045

**Attachment to Report of Noncompliance Event
October 20, 1999**

SPDES # NY-0004472

Description of noncompliance and cause:

The Sum 7 discharge (Outfalls 001B, 001C, 001D, 001E, 001G, 001K and 001L) exceeded the daily maximum discharge limitation of 50 mg/l for Total Suspended Solids (TSS). This was caused by a sample result which identified an elevated concentration of TSS in Outfall 001B during a plant startup. Short term flow transients, which can potentially cause an increase in TSS in Outfall 001B, are necessary in order to achieve proper plant chemical control. The Sum 7 TSS concentration dropped below 50 mg/l on 10/21/99.

Preventative (long term) corrective actions:

Revise sampling procedures to increase Outfall 001B sample frequency during plant startups to ensure a representative TSS determination is made when short term flow transients occur.

December 21, 1999



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of November 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452 .

Very truly yours,

Handwritten signature of Roger G. Keppel, with "for Keith Barouch" written below it.

Keith Barouch
Environmental, Health & Safety Manager
Indian Point Station
Con Edison Units 1 & 2

Attachment

/paa

January 24, 2000



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Watershed Compliance Programs
50 Wolf Road - Room 340
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #NY0004472
Con Edison - Indian Point Unit 1 and Unit 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of December 1999.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds J. Burns of Con Edison (914)734-5605 or Mr. Matthew Kerns of New York Power Authority at (914) 736-8452.

Very truly yours,

A handwritten signature in black ink, appearing to read "Keith Barouch", with a date "1/27/00" written to the right of the signature.

Keith Barouch
Environmental, Health & Safety Manager
Indian Point Station
Con Edison Units 1 & 2

Enc.

/paa