



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

July 31, 2000

MEMORANDUM TO: K. E. Brockman, Director, Division of Reactor Projects

FROM: P. H. Harrell, Chief, Project Branch D **/RA/**

SUBJECT: SECOND QUARTER 2000 REVIEW FOR PALO VERDE, UNITS 1, 2,  
AND 3

I have reviewed the 2Q/2000 performance indicators and inspection findings for Palo Verde, Units 1 and 2. All performance indicators and inspection findings were green. No adverse trends in the licensee's performance were noted for these units. Based on this review, additional inspections are not recommended.

The high pressure injection system unavailability performance indicator remained white. This performance indicator was identified as white during the first quarter by the licensee for Palo Verde, Unit 3. The followup inspection for this concern is scheduled to occur prior to August 29, 2000. The licensee was advised of this inspection in a separate letter on May 8, 2000, as required by IMC 0305.

cc via E-mail through ADAMS:

K. Kennedy **(KMK)**  
L. Willoughby **(LMW1)**  
J. Moorman **(JHM2)**  
N. Salgado **(NLS)**  
M. Fields **(MBF1)**