

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

**Nuclear Business Unit** 

AUG 1 1 2009

LRN-00-0307

U. S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

MONTHLY OPERATING REPORT SALEM GENERATING STATION UNIT 1 DOCKET NO. 50-272

In compliance with Section 6.9, Reporting Requirements for the Salem Unit 1 Technical Specifications, the operating statistics for **July 2000** are being forwarded. Also being forwarded, pursuant to the requirements of 10CFR50.59(b), is a summary of changes, tests, and experiments that were implemented in **July 2000**.

Sincerely,

Mark B. Bezilla

Vice President - Operations

RBK Attachments

C Distribution

JE24.

# **INDEX**

	NUMBER
SECTION	OF PAGES
Operating Data Report	1
Monthly Operating Summary	1
Summary of Changes, Tests, and Experiments	2

**DOCKET NO.: 50-272** 

UNIT: Salem 1 DATE: 8/15/00

COMPLETED BY: R. Knieriem

TELEPHONE: (856) 339-1782

Reporting Period July 2000

#### **OPERATING DATA REPORT**

**Design Electrical Rating (MWe-Net) Maximum Dependable Capacity (MWe-Net)** 

No. of hours reactor was critical No. of hours generator was on line (service hours) Unit reserve shutdown hours **Net Electrical Energy (MWH)** 

1115	Herida - 1921			
1106		360 <b>2600</b> 68		
Month	Year-to-date	Cumulative		
744	4862	123407		
744	4788	119040		
0 0		0		
801994	5150657	119771992		

#### **UNIT SHUTDOWNS**

NO.	DATE	TYPE F=FORCED S=SCHEDULED	DURATION (HOURS)	REASON (1)	METHOD OF SHUTTING DOWN THE REACTOR (2)	CORRECTIVE ACTION/ COMMENT

#### (1) Reason

- A Equipment Failure (Explain)
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training/License Examination
- F Administrative
- G Operational Error (Explain)
- H Other

#### (2) Method

- 1 Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)

DOCKET NO.: <u>50-272</u>

UNIT: Salem 1

DATE: 8/15/00

COMPLETED BY: R. Knieriem

TELEPHONE: (856) 339-1782

# **Summary Of Monthly Operating Experience**

- Salem Unit 1 began the month of July operating at full power.
- Power was reduced to 80% from July 15, until July 17 at the request of the load dispatcher in response to a solar magnetic disturbance.
- Salem Unit 1 operated at full power for the remainder of the month.

**DOCKET NO.: 50-272** 

UNIT: <u>Salem 1</u> DATE: 8/15/00

COMPLETED BY: R. Knieriem

TELEPHONE: (856) 339-1782

# SUMMARY OF CHANGES, TESTS, AND EXPERIMENTS FOR THE SALEM GENERATING STATION – UNIT 1

## MONTH July 2000

The following items completed during July 2000 have been evaluated to determine:

- 1. If the probability of occurrence or the consequences of an accident or malfunction of equipment important to safety previously evaluated in the safety analysis report may be increased; or
- 2. If a possibility for an accident or malfunction of a different type than any evaluated previously in the safety analysis report may be created; or
- 3. If the margin of safety as defined in the basis for any technical specification is reduced.

The 10CFR50.59 Safety Evaluations showed that these items did not create a new safety hazard to the plant nor did they affect the safe shutdown of the reactor. These items did not change the plant effluent releases and did not alter the existing environmental impact. The 10CFR50.59 Safety Evaluations determined that no unreviewed safety or environmental questions are involved.

## **Design Changes** Summary of Safety Evaluations

There were no reportable changes in this category implemented during July 2000.

# Temporary Modifications Summary of Safety Evaluations

There were no reportable changes in this category implemented during July 2000.

# **Procedures Summary of Safety Evaluations**

There were no reportable changes in this category implemented during July 2000.

# **UFSAR Change Notices** Summary of Safety Evaluations

There were no reportable changes in this category implemented during July 2000.

# SUMMARY OF CHANGES, TESTS, AND EXPERIMENTS FOR SALEM GENERATING STATION – UNIT 1 – Cont'd

### **Other - Summary of Safety Evaluations**

28VDC Distribution Calculations: Short Circuit and Voltage Drop, Battery and Battery Charger Sizing, and Component Study and Voltage Drop

This safety evaluation supported the revision of calculations related to the 28VDC Distribution system to increase the Loss of Coolant Accident/Loss of Offsite Power (LOCA/LOOP) design margin, to maximize future load growth margin, and to implement minor administrative improvements.

Evaluation of the 28VDC Distribution Calculations was required under 10CFR50.59 because these changes constituted a change to the facility as described in the SAR. The calculations considered in this safety evaluation revised battery load profiles to increase the LOCA/LOOP battery loading design margin from 5% to 7.5%. These revised load profiles will ensure that power is available for LOCA/LOOP loads when required. Therefore, the changes considered in this safety evaluation do not increase the probability or consequences of any accident or malfunction, do not reduce the margin of safety, and do not involve an Unreviewed Safety Question.