

August 31, 2000

Dear Sir:

During a routine review of our registration files, we found an error in NR-994-D-801-E. It lists the isotope amount for smoke detectors as 0.9 millicuries. It should read 0.9 microcuries. The error has been corrected and a copy of the corrected registration certificate is enclosed.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions.

If you have any questions, please contact me at (301) 415-8140 or Mr. John Jankovich at (301) 415-7904.

Sincerely,
/RA/

Traci Kime, Registration Specialist
Materials Safety and Inspection Branch
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Enclosure: NR-994-D-801-E
cc w/encl: SKimberley, LFDCB

Distribution:

SSD-00-40

SSD File # NR-994-D-801-E

DOCUMENT NAME: H:\Traci\994D801E.cmp

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	MSIB	E	MSIB	MSIB	E			
NAME	T. Kime <i>JK</i>		M. Burgess	JJankovich <i>JJ</i>				
DATE	8/29/2000		1/2000	8/29/2000				

OFFICIAL RECORD COPY