

Certified Mail - 7099 3220 0008 5206 2818 Return Receipt Requested

October 20, 2000

Mr. Steve Ingle WDEQ/LQD Herschler Building 122 West 25th Street Cheyenne, WY 82002

RE: Corrective Action Report, West Evaporation Pond Leak
Permit to Mine 633, License SUA-1548, Docket 40-8964

Dear Mr. ingle:

On September 14, 2000, during a routine inspection, it was discovered that the west evaporation pond sump contained greater than 6 inches of water. The water level in the pond, four feet six inches at the time of the discovery, was immediately lowered in order to stop the leak. The sump water was analyzed for chloride, specific conductance, bicarbonate, U_{nat} , and sulfate with the results shown below.

Rio Algom Mining Corp.

Glenrock, Wyoming 82637

Douglas, Wyoming 82633

307.358.3744 tel 307.266.2449 tel

307.358.9201 fax

P.O. Box 1390

762 Ross Road

Chemical	Concentration
Chloride	8,510 mg/l
Specific Conductance @ 25 °C	32.95 m Siemens
Bicarbonate	283.1 mg/l
U _{nat} as U ₃ O ₈	22.6 mg/l
Sulfate	7,429 mg/l

Upon receipt of the confirming analysis, both Steve Ingle of WDEQ and John Lusher of NRC were notified via telephone on September 22, 2000.

The holes have been patched and the water level is being slowly raised in order to confirm the patches. Currently, the water level is at four feet one inch with no water seeping into the sump. Additional monthly reports will be submitted until correction of the situation is confirmed.

If you have any questions or comments regarding the submittal, please feel free to contact me at (307) 358-3744, ext. 62.

MMSSOLPA

Sincerely

John W. Cash

Manager EHS & Regulatory

xc:

J. Lusher-U.S. NRC (Div. of Low Level Waste Mgt. & Dec.) Rockville, MD
Certified Mail - 7099 3220 0008 5206 2825

B. Ferdinand (RAMC-Smith Ranch Facility)

M. Freeman (RAMC-OKC Office)

P. Goranson (RAMC-OKC Office)

file