

601-1

(NO 21)

• gas/line failure of pressure tube
• rod bundle gas ejected

There is 1000 sec delay between the Cs release and the Ru release.

(Kermer plus x. NO 20)

Cs release, then Ru release

A couple of hours at temperature

L. Dickson

5/15/00