
Exelon Generation Company, LLC Byron Station 4450 North German Church Road Byron, IL 61010-9794 www.exeloncorp.com



LTR: BYRON 2001-0072 File: 2.07.0200

United States Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555-0001

> Byron Station, Units 1 and 2 Facility Operating License Nos. NPF-37 and NPF-66 NRC Docket Nos. STN 50-454 and STN 50-455

Subject: Monthly Operating Report

In accordance with Technical Specification 5.6.4, "Monthly Operating Reports," we are submitting the Monthly Operating Report for Byron Station, Units 1 and 2. This report covers the period April 1, 2001, through April 30, 2001.

During preparation and review of the station Monthly Operating Report a computer problem was identified that has changed the "Year to Date" and "Cumulative" Unit 1 and Unit 2 Net Electrical Energy (MWhrs). We are investigating this issue, and will provide any additional corrections to this data as the results are available.

If you have any questions regarding this report, please contact P. Reister, Regulatory Assurance Manager, at (815) 234-5441, extension 2280.

Respectfully,

Stephen Kurgenshi

Stephen E. Kuczynski ^{*} ^{*} Plant Manager Byron Nuclear Generating Station

SEK/DD/dpk

Attachment

cc: Regional Administrator – NRC Region III NRC Senior Resident Inspector – Byron Station NRC Project Manager – NRR – Byron Station Office of Nuclear Facility Safety – Illinois Department of Nuclear Safety

LEA

Exelon

Nuclear

ATTACHMENT

-

.

BYRON STATION, UNIT 1 AND UNIT 2 MONTHLY OPERATING REPORT

EXELON GENERATION COMPANY, LLC

FACILITY OPERATING LICENSE NOS. NPF-37 AND NPF-66 NRC DOCKET NOS. STN 50-454 AND STN 50-455

OPERATING DATA REPORT UNIT ONE

.

		<u></u>				
			DOCKET NO UNIT NAME DATE COMPLETEE TELEPHONE) BY	<u>50-454</u> <u>Byron One</u> <u>05/11/01</u> <u>D. Drawbauc</u> (815) 234-54	
	REPORTING PERIOD:	April, 2001 (Month/Year)				
			MONTH	<u>YEAR</u>	TO DATE	<u>CUMULATIVE</u>
1.	Design Electrical Rating (M The nominal net electrical o unit specified by the utility a the purpose of plant design	output of the and used for	1,120	N/A		N/A
2.	Maximum Dependable Cap The gross electrical output output terminals of the turb the most restrictive season the normal station service I	as measured at the ine-generator during al conditions minus	1,105	N/A		N/A
3.	Number of Hours the Reac The total number of hours of hours of the reporting perio was critical.	during the gross	719	2,879		115,074.57
4.	Number of Hours the Gener (also called Service Hours) of hours during the gross h period that the unit operate to the station bus. The sur generator was on line plus should equal the gross hou period.). The total number ours of the reporting ed with breakers closed n of the hours the the total outage hours	719	2,879		114,083.54
5.	Unit Reserve Shutdown Ho The total number of hours hours of the reporting perio removed from service for e reasons but was available	during the gross od that the unit was economic or similar	0	0		0
6.	Net Electrical Energy (MW The gross electrical output at the output terminals of the minus the normal station s the gross hours of the report expressed in megawatt ho quantities should not be us	of the unit measured he turbine-generator ervice loads during prting period, urs. Negative	821,875	3,340),303	116,388,984

DOCKET NO.	<u>50-454</u>
UNIT NAME	<u>Byron One</u>
DATE	05/11/01
COMPLETED BY	<u>D. Drawbaugh</u>
TELEPHONE	(815) 234-5441, X2402

-,

REPORTING PERIOD: April, 2001

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON (1)	METHOD OF SHUTTING DOWN (2)	CAUSE/CORRECTIVE ACTIONS COMMENTS
		None				

SUMMARY: Unit One On Line During the Month of April

- (1) Reason
 - A Equipment Failure (Explain) B Maintenance Test

 - C Refueling

 - D Regulatory Restriction
 E Operator Training/License Examination
 F Administrative

 - G Operational Error (Explain)
 - H Other (Explain)

- (2) Method
 - 1 Manual
 - 2 Manual Trip/Scram 3 Automatic Trip/Scram
 - 4 Continuation
 - 5 Other (Explain)

1. Safety/Relief valve operations for Unit One. This information is provided pursuant to the reporting requirements contained in Technical Specification 5.6.4, "Monthly Operating Report."

	VALVES	NO. & TYPE	PLANT	DESCRIPTION
<u>DATE</u>	<u>ACTUATED</u>	ACTUATION	CONDITION	OF EVENT

None

2. Licensee generated changes to ODCM.

None

3. Indications of failed fuel.

None. Fuel Reliability Indicator: (FRI) = $1.00 \text{ E}-06 \mu \text{Ci/cc.}$

4. Licensee Events Reports

The following is a tabular summary of all Licensee Event Reports for Byron Station, Unit One, occurring during the reporting period, April 1, 2001, through April 30, 2001. This information is provided pursuant to the reportable occurrence reporting requirements as set forth in 10 CFR 50.73, "Licensee Event Report System."

Licensee Event Report Number

Occurrence Date

Title of Occurrence

None

OPERATING DATA REPORT UNIT TWO

· · ·

			DOCKET NO. UNIT NAME DATE COMPLETED TELEPHONE	BY	50-455 Byron Two 05/11/01 D. Drawbaugh (815) 234-544	-
	REPORTING PERIOD:	<u>April, 2001</u> (Month/Year)				
			<u>MONTH</u>	YEAR	TO DATE	<u>CUMULATIVE</u>
1.	Design Electrical Rating (MW The nominal net electrical our unit specified by the utility an the purpose of plant design.	tput of the	1,120	N/A		N/A
2.	Maximum Dependable Capac The gross electrical output as output terminals of the turbing the most restrictive seasonal the normal station service loa	s measured at the e-generator during conditions minus	1,105	N/A		N/A
3.	Number of Hours the Reactor The total number of hours du hours of the reporting period was critical.	ring the gross	348.45	2,508.4	45	107,219.51
4.	Number of Hours the General (also called Service Hours). of hours during the gross hou period that the unit operated to the station bus. The sum of generator was on line plus th should equal the gross hours period.	The total number urs of the reporting with breakers closed of the hours the e total outage hours	340.4	2,500.4	4	106,455.45
5.	Unit Reserve Shutdown Hour The total number of hours du hours of the reporting period removed from service for eco reasons but was available for	ring the gross that the unit was pnomic or similar	0	0		0
6.	Net Electrical Energy (MWH) The gross electrical output of at the output terminals of the minus the normal station serv the gross hours of the reporti expressed in megawatt hours quantities should not be used	the unit measured turbine-generator vice loads during ng period, s. Negative	336,907	2,833,	464	109,000,728

<u>50-455</u>
<u>Byron Two</u>
<u>05/11/01</u>
D. Drawbaugh
(815) 234-5441, X2402

.

REPORTING PERIOD: April, 2001

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON (1)	METHOD OF SHUTTING DOWN (2)	CAUSE/CORRECTIVE ACTIONS COMMENTS
1	04/07/01	S	378.6	С	2	Entered Refueling Outage B2R09 per schedule.

SUMMARY: Unit Two entered and completed B2R09 per schedule.

- (1) Reason
 - A Equipment Failure (Explain)
 - B Maintenance Test
 - C Refueling

 - D Regulatory Restriction E Operator Training/License Examination
 - F Administrative
 - G Operational Error (Explain) H Other (Explain)

- (2) Method
 - 1 Manual
 - 2 Manual Trip/Scram 3 Automatic Trip/Scram
 - 4 Continuation
 - 5 Other (Explain)

1. Safety/Relief valve operations for Unit Two. This information is provided pursuant to the reporting requirements contained in Technical Specification 5.6.4, "Monthly Operating Report."

	VALVES	NO. & TYPE	PLANT	DESCRIPTION
DATE	<u>ACTUATED</u>	ACTUATION	<u>CONDITION</u>	OF EVENT

None

2. Licensee generated changes to ODCM.

None

3. Indications of failed fuel.

None. Fuel Reliability Indicator: (FRI) = $5.97 \text{ E}-06 \mu \text{Ci/cc.}$

4. Licensee Events Reports

The following is a tabular summary of all Licensee Event Reports for Byron Station, Unit Two, occurring during the reporting period, April 1, 2001, through April 30, 2001. This information is provided pursuant to the reportable occurrence reporting requirements as set forth in 10 CFR 50.73, "Licensee Event Report System."

Licensee Event Report Number	Occurrence Date	Title of Occurrence
455-2001-001-00	04/02/2001	Main Steam Safety Valve Relief Tests Exceeded Required Tolerance Due to Disk to Nozzle Metallic Bonding.